# Site Register



WASHINGTON STATE DEPARTMENT OF ECOLOGY TOXICS CLEANUP PROGRAM

#### DECEMBER 12, 2013

#### CONTENTS

Formal Cleanups	1
Site Hazard Assessments	8
Independent Cleanup Program	9
Voluntary Cleanup Program	12
News & Notes	15
Glossary	16
Site Information Online	17
Regional Office Addresses	17

Sign up to get the Site Register online:

www.ecy.wa.gov/maillist.html Under "Newsletters" click on Site Register. Under "Options" click on Join or Leave.

Looking for past issues? Check here: http://1.usa.gov/hAJyav.

Visit Ecology's Public Involvement Calendar for more information. Go to http://www.ecy.wa.gov/ and click on Public Calendar.

If you have questions, contact Seth Preston at 360/ 407-6848 or Seth.Preston@ecy.wa.gov. Specific contacts are listed after each entry.

To ask about the availability of this document in a format for the visually impaired, call 360/ 407-7170. Persons with hearing loss may call 711 for Washington Relay Service. Persons with a speech disability may call 877-833-6341.

#### FORMAL CLEANUPS

Ecology oversees complex cleanup sites to ensure that your health and that of the environment are protected.

#### **BENTON COUNTY**

Hicks Road Pit Site Hicks and Johnson roads, Prosser

Facility Site ID# 336

CSID# 4056

#### Public comment period: 11/27/13 – 12/27/13

#### Periodic Review Available for Public Comment

Ecology invites you to review and comment on a document called a periodic review for the Hicks Road Pit site. A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct questions and written comments to periodic review coordinator Jeff Newschwander.

Periodic Review Coordinator:

Jeff Newschwander Central Regional Office 509-454-7842 Jeff.Newschwander@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the document at the following locations:

• Hicks Road Pit site:

https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4056

• Ecology's Central Regional Office Toxics Cleanup Program – 15 W. Yakima Ave., Suite 200, Yakima, WA. (Please call 509/ 454-7658 for an appointment.)

#### **CHELAN COUNTY**

Chelan Chevron Site Facility Site ID# 77751227 232 East Woodin Avenue, Chelan CSID# 6660

#### Negotiations Extended for Agreed Order

Ecology and Chevron Products Company are negotiating an agreed order to conduct a supplemental remedial investigation at the Chelan Chevron site. Negotiations were scheduled to begin around September 25, 2013, and were anticipated to end around November 30, 2013. The anticipated date for negotiations has been extended to January 25, 2014.

Please direct questions to site manager Laura Klasner.



Site Manager:

Laura Klasner Central Regional Office 509/ 454-7833 Laura.Klasner@ecy.wa.gov

For more information:

Chelan Chevron site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=6660

### CLARK COUNTY

Turnbull Landfill Site 12001 NE Fourth Plain Boulevard, Orchards Facility Site ID# 51658363

CSID# 4677

#### Public comment period: 12/12/13 - 1/14/14

#### Periodic Review Available for Public Comment

Ecology invites you to review and comment on a periodic review of the Turnbull Landfill site in Orchards. Ecology reviews cleanup sites at least every five years to make sure the sites still protect human health and the environment.

Between 1970 and 1974, the Turnbull Landfill site was a solid waste disposal facility. Studies of the site found about 39,000 cubic yards of solid waste below ground. Studies also found manganese in groundwater slightly above the state drinking standard. However, nearby residents and businesses do not use groundwater for drinking. Studies found no detectable landfill gases.

The property owner cleaned up the site by removing some solid waste and placing a cap of clean fill over the remaining waste. Ecology determined that the site required no further cleanup. An environmental covenant is in place for the site.

Cleanup actions at this site appear to be protective. Ecology will respond to comments at the end of the comment period. Ecology will do a new periodic review after another five years.

Please direct questions and comments to site manager Panjini Balaraju.

Site Manager:

Panjini Balaraju Southwest Regional Office 360/ 407-6335 panjini.balaraju@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may view documents at the following locations:

• Turnbull Landfill site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4677

• Cascade Park Community Library - 600 NE 136th Ave., Vancouver, WA. Call 360/ 256-7782.

• Ecology's Southwest Regional Office Toxics Cleanup Program – 300 Desmond Drive SE, Lacey, WA. (Please contact Susie Baxter for an appointment at 360/ 407-6365 or Susan.Baxter@ecy.wa.gov.)

#### **KING COUNTY**

Boeing Fabrication Auburn Site Auburn Facility Site ID# 2018

CSID# 5049

Surface Water Sampling in Yards and Ditches to Begin

The Boeing Company will sample water in yards and ditches located in the northern area of the city of Algona. This sampling is part of a larger investigation associated with groundwater contamination from past releases of solvent chemicals on property Boeing owns in Auburn.

The groundwater table in Algona can be very high, especially during the winter months. The purpose of this sampling is to show whether chemicals in groundwater are entering surface water in ditches and yards during the wet season of the year.

Boeing will collect water samples from ditches and yards at various locations in northern Algona to determine if the solvent chemicals are present. Ecology will oversee the collection of these water samples by Boeing according to an Ecology-approved work plan. Boeing will pay all the costs for the sampling and analysis. Ecology will review all sampling results and decide if additional yard and ditch water sampling is needed.

The sampling data will be posted on the website once the data becomes available.

Please direct questions to site manager Robin Harrover with Ecology's Hazardous Waste & Toxics Reduction Program.

Contact:

Robin Harrover Northwest Regional Office 425/ 649-7232 robin.harrover@ecy.wa.gov

You may view documents at the following locations:

Boeing Auburn Fabrication site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=5049

• Ecology's Northwest Regional Office Toxics Cleanup Program – 3190 160th Avenue SE, Bellevue, WA. (Please contact Sally Perkins for an appointment at 425/ 649-7190 or Sally.Perkins@ecy.wa.gov.)

## North Boeing Field/Georgetown Steam Plant SiteFacility Site ID# 20507370 East Marginal Way South/6700 13th Avenue South, Seattle

CSID# 4765

#### Final Remedial Investigation/Feasibility Study Work Plan Completed

Ecology recently completed a remedial investigation/feasibility study final work plan for the North Boeing Field/Georgetown Steam Plant site. The plan proposes investigations of soil, groundwater, soil vapor, stormwater, and building materials at the site.

The final work plan summarizes the work of previous investigations and proposes additional work that is needed to meet the requirements of the agreed order for the site.

The North Boeing Field/Georgetown Steam Plant site is on the east side of the Lower Duwamish Waterway in Seattle. Industrial operations and maintenance caused contamination at the site.

Contaminants of concern are polychlorinated biphenyls (PCBs); total petroleum hydrocarbons (TPH); polynuclear aromatic hydrocarbons (PAHs); volatile and semi-volatile organic compounds (VOCs and SVOCs); and antimony, arsenic, cadmium, chromium, copper, lead, mercury, and zinc.

Please direct questions to site manager Mark Edens.

Site Manager:

Mark Edens Northwest Regional Office 425/ 649-7070 Mark.Edens@ecy.wa.gov

You may review documents at the following locations:

• North Boeing Field/Georgetown Steam Plant site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4765

• South Park Library - 8604 Eighth Ave. S., Seattle, WA. Call 206/ 615-1688.

• Ecology's Northwest Regional Office Toxics Cleanup Program – 3190 160th Avenue SE, Bellevue, WA. (Please contact Sally Perkins for an appointment at 425/ 649-7190 or Sally.Perkins@ecy.wa.gov.)



#### Facility Site ID# 23849623

CSID# 853

#### Northlake Shipyard Site 1441 North Northlake Way, Seattle

#### Cleanup Work in Progress at Northlake Shipyard

Ecology has started cleanup work at the Northlake Shipyard site at 1441 North Northlake Way, Seattle. Ecology's contractor, Redside Construction, will remove arsenic-contaminated sandblast grit from the sediments around the piers. The work began in early December and is expected to last for about three months.

The cleanup work will take place from 6 a.m. to 10 p.m. Monday through Friday and if needed on Saturday and Sunday between 9 a.m. to 10 p.m. The contractor will comply with the City of Seattle's noise ordinance.

**Traffic/Mariner advisory:** Expect traffic delays along North Northlake Way between 6 a.m. to 10 p.m. Monday through Friday and possibly on Saturday and Sunday between 9 a.m. to 10 p.m. Mariners are requested to use caution when motoring near the area.

This work is being done under a prospective purchaser consent decree between Ecology and Northlake Shipyard Inc. (Northlake) to clean up arsenic-contaminated sandblast grit that was at the site prior to Northlake purchasing the property.

The work will involve:

• Dredging abouty 8,000 cubic yards of sediment from around the western pier and beneath the dry docks. This will remove the top two feet of sediment.

• After dredging, six inches of clean sand will be placed over the area that was dredged.

• A silt curtain or sediment barrier (extending from the surface to the lake bottom) will be set up around the work area to contain sediment that is disturbed during the dredging. Water quality measurements will be taken outside of the silt curtain to confirm that the work does not result in excessive turbidity or cloudiness in the water.

• Every two to three days, trucks will remove the dredged material from the site and take it to a permitted landfill. This will result in an additional 20 to 30 trucks using North Northlake Way.

Please direct technical questions to site manager Libby Goldstein.

Site Manager:	Libby Goldstein
	Northwest Regional Office
	425/ 649-7242
	libby.goldstein@ecy.wa.gov

Please direct construction questions to Dave Berry, Redside Construction's on-site coordinator.

On-site coordinator: Dave Berry Redside Construction 206/940-2529 david@redside.biz

You may review related documents at the following locations:

- Northlake Shipyard site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=853
- Fremont Library 731 N 35th St., Seattle, WA. Call 206/ 684-4084.
- Wallingford Public Library 1501 N. 45th St., Seattle, WA Call 206/ 684-4088.

• Ecology's Northwest Regional Office Toxics Cleanup Program – 3190 160th Avenue SE, Bellevue, WA. (Please contact Sally Perkins for an appointment at 425/ 649-7190 or Sally.Perkins@ecy.wa.gov.)



## North Lot Development SiteFacility Site ID# 5378137South King Street and Occidental Avenue South, Seattle

CSID# 1966

#### Public comment period: 11/15/13 – 12/16/13

#### Proposed Consent Decree, Other Documents Available for Public Review and Comment

Ecology invites you to review and comment on a proposed consent decree with North Lot Development and 255 South King Street LP for the North Lot Development cleanup site north of CenturyLink Field at the southeast intersection of South King Street and Occidental Avenue South in Seattle.

The proposed consent decree will supersede a current prospective purchaser consent decree. The site is being developed as part of an inter-modal regional transit hub adjacent to King Street Station.

The site includes two parcels, west (North Lot Development) and east (255 South King Street LP). North Lot Development sold the east parcel to 255 South King Street LP and maintains ownership of the west parcel.

The new consent decree describes the work completed by North Lot Development on the west parcel and identifies the remaining remedial activities to be performed on the parcel.

Under the consent decree, North Lot Development will have no new or additional obligations regarding the west parcel, other than groundwater compliance monitoring and implementing institutional controls on it.

The consent decree will also obligate 255 South King Street LP to perform the cleanup at the east parcel. Work will include:

- Preparing an addendum to the original feasibility study report that incorporates the planned development of the east parcel.
- Preparing an addendum to the original cleanup action plan that incorporates the planned development of the east parcel.
- Implementing the cleanup action plan addendum for the east parcel.

Ecology invites comments on:

- The proposed consent decree.
- The feasibility study addendum.
- The cleanup action plan addendum.
- A revised public participation plan.

Please direct questions and comments to site manager Jing Liu.

Site Manager:

Jing Liu Northwest Regional Office 425/ 649-4310 jing.liu@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the documents at the following locations:

- North Lot Development site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=1966
- Seattle Public Library (Downtown Branch) 1000 4th Ave., Seattle, WA. Call 206/ 386-4636.
- Seattle Public Library (International District/Chinatown) 713 8th Ave. S, Seattle, WA. Call 206/ 386-1300.

• Ecology's Northwest Regional Office Toxics Cleanup Program – 3190 160th Avenue SE, Bellevue, WA. (Please contact Sally Perkins for an appointment at 425/ 649-7190 or Sally.Perkins@ecy.wa.gov.)

## Site Register

#### **KLICKITAT COUNTY**

Columbia Gorge Aluminum Site 85 John Day Dam Road, Goldendale Facility Site ID# 95415874

CSID# 11797

#### Negotiations in Progress for Agreed Order

Ecology is negotiating an agreed order with Lockheed Martin Corporation and NSC Smelter LLC, the potentially liable parties, to complete the remedial investigation and feasibility study for the Columbia Gorge Aluminum site.

The Columbia George Aluminum Smelter produced aluminum and aluminum products for nearly 30 years. The smelter is located in Goldendale on about 350 acres along the Columbia River. During the operation of the smelter, the various owners have managed hazardous and solid waste at several locations on the site.

Smelter operations contaminated soil and groundwater at the site with fluoride, PAHs, cyanide, and PCBs. The facility was added to the Hazardous Sites List in 1990.

Please direct questions to site manager James DeMay in Ecology's Industrial Section.

Site Manager:

James DeMay Ecology Industrial Section 360/ 407-6999 jade461@ecy.wa.gov

For more information:

Columbia Gorge Aluminum site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=11797

#### PEND OREILLE COUNTY

Airport Kwik Stop SiteFacility Site ID# 32584416CSID# 4203West of Highway 31 and north of Greenhouse Road, Ione

#### Public comment period: 11/27/13 – 12/30/13

Draft Remedial Investigation and Feasibility Study Reports Available for Public Review and Comment Ecology invites comments on the draft remedial investigation and feasibility study (RI/FS) reports conducted at t

Ecology invites comments on the draft remedial investigation and feasibility study (RI/FS) reports conducted at the Airport Kwik Stop site. These documents will help guide cleanup of site-related contamination. The site begins west of Highway 31 and north of Greenhouse Road and extends generally east and southeast toward the river in Ione.

Contamination is found in soil and groundwater at the Airport Kwik Stop, beneath the Cabin Grill, and on several private properties northeast and southeast of the Cabin Grill. The remedial investigation report provides information about the extent of contamination at the site.

Current contaminants of concern include volatile organic compounds (VOCs), benzene, toluene, ethylbenzene and xylenes (BTEX), and gasoline range petroleum hydrocarbons (GRPH) in soil and groundwater. The feasibility study report evaluates four options for cleanup at the site.

Monitoring showed contamination in groundwater that forms what is called a plume. Petroleum product is floating on the top 1 to 2 inches of the groundwater plume beneath the Cabin Grill.

The plume also contains petroleum product that has dissolved and become part of the groundwater that lies under the Airport Kwik Stop fuel dispensers and moves downgradient. The plume has migrated to the east-southeast at least 1,400 feet. Three domestic water wells have been impacted by the plume as well as the domestic water well at the Cabin Grill.

Potential impacts to humans and wildlife could occur if the contaminated groundwater plume rose to the surface in springs, seeps, or small ponds along the Pend Oreille River. Although Ecology has not found contamination in these areas, it is recommended that people avoid contact with these types of springs, seeps or ponds at this time.

Two treatment systems are in place to address the soil and groundwater contamination. Testing shows the soil vapor extraction system is working successfully to remove petroleum contaminants from soil. However, the air sparge system is not effective for removing contaminants from groundwater. The feasibility study evaluates four options to address remaining contaminants.

Please direct questions and written comments to site manager Doug Ladwig.

Site Manager:

Doug Ladwig Eastern Regional Office 509/ 329-3440 doug.ladwig@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the documents at the following locations:

Airport Kwik Stop site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4203

• Ione Public Library - Ione Community Center, 200 Blackwell, Ione, WA. Call 509/ 442-3030.

• Ecology's Eastern Regional Office Toxics Cleanup Program – 4601 N. Monroe, Spokane, WA. (Please call 509/ 329-3415 for an appointment.)

For ADA accommodations or documents in an alternate format, call Carol Bergin at 509/329-3546 (voice), 711 (relay service), or 877-833-6341 (TTY).

#### SKAGIT COUNTY

Former Shell	Oil	Tank	Farm	Site
Anacortes				

Facility Site ID# 4781157

CSID# 4846

#### Public comment period: 12/6/13 - 1/8/14

Draft Consent Decree, Other Draft Documents Available for Public Review and Comment

Ecology invites you to review and comment on the draft consent decree for the Former Shell Oil Tank Farm site cleanup in Skagit County. The consent decree is a legal document in which Ecology and the Potentially Liable Persons formalize agreement for the actions needed for cleanup of the site.

The decree includes a draft cleanup action plan that describes the particular actions to be taken, and is based off the findings of the draft remedial investigation and feasibility study. The public participation plan describes how the public can provide input on the cleanup of the site.

Please direct questions and comments to site manager Nick Acklam.

Site Manager: Nick Acklam Ecology Headquarters 360/ 407-6913 nicholas.acklam@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may view documents at the following locations:

• Former Shell Oil Tank Farm site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4846

• Anacortes Public Library - 1220 10th St., Anacortes, WA. Call 360/293-1910.

• Ecology's Headquarters Toxics Cleanup Program – 300 Desmond Drive SE, Lacey, WA. (Please contact Carol Dorn for an appointment at 360/ 407-7224 or Carol.Dorn@ecy.wa.gov.)



#### WHATCOM COUNTY

#### Whatcom Waterway Site West of Holly Street Bridge, Bellingham

Facility Site ID# 2899

CSID# 219

Responsiveness Summary Available for Public Review

Ecology requested review and comments from the public between February 26 and March 27, 2013, on a draft engineering design report (phase 1) for the Whatcom Waterway site in Bellingham. The comments received and Ecology's responses have been compiled in a responsiveness summary.

Please direct questions to site manager Lucy McInerney.

Site Manager:	Lucy McInerney
	Northwest Regional Office
	425/ 649-7272
	Lucy.McInerney@ecy.wa.gov

For more information: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=219

YAKIMA COUNTY			
Tidricks Quality Transmission Site	Facility Site ID# 534	CSID# 4944	
1802 South 1st Street, Yakima	-		

#### Public comment period: 11/22/13 - 12/23/13

Proposed Agreed Order Available for Public Review and Comment

Ecology proposes to enter into a legal agreement called an agreed order to conduct a remedial investigation/feasibility study (RI/FS) at the Tidricks Quality Transmission site. The RI/FS will gather information about the nature and extent of the site contamination and outline potential cleanup options.

Please direct questions and written comments to site manager John Mefford.

Site Manager: John Mefford Central Regional Office 509/ 454-7836 John.Mefford@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the document at the following locations:

Tidricks Quality Transmission site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4944

• Yakima Valley Regional Library, 102 N. 3rd St., Yakima, WA. Call 509/ 452-8541.

• Ecology's Central Regional Office Toxics Cleanup Program – 15 W. Yakima Ave., Suite 200, Yakima, WA. (Please call 509/454-7658 for an appointment.)

#### SITE HAZARD ASSESSMENTS

Date of report: 11/20/13

Publication #13-09-041	Y

#### **BENTON COUNTY**

#### Sun Mart 12 2105 West 4th Avenue, Kennewick

Independent Cleanup Action Report Received Date Report Received: 10/15/13 Name of report: Site Characterization Report Date of report: 10/10/13 Type of report: Site characterization Contaminants reported: Gasoline, diesel, VOCs Affected media: Soil Contact:

Facility Site ID# 32581878

A property owner may conduct an independent cleanup of contamination and submit reports to Ecology.

**Doug Ladwig** 

509/329-3440

Eastern Regional Office

doug.ladwig@ecy.wa.gov

#### INDEPENDENT CLEANUPS

Facility Site ID# 18591922

#### INDEPENDENT CLEANUP CONTACTS

Central Regional Office Contact: e-mail Roger.Johnson@ecy.wa.gov or call 509/ 575-2490 Eastern Regional Office Contact: Doug Ladwig, e-mail Doug.Ladwig@ecy.wa.gov or call 509/ 329-3440 Northwest Regional Office Contact: Donna Musa, e-mail Donna.Musa@ecy.wa.gov or 425/ 649-7136 Southwest Regional Office Contact: Kim Cross, e-mail Kim.Cross@ecy.wa.gov or call 360/ 407-6240

## Site Register

#### **SPOKANE COUNTY**

**Airway Heights Tire** 9028 West Sunset Highway, Spokane

Contact:

**Roger Johnson** Central Regional Office 509/454-7839 Roger.Johnson@ecy.wa.gov

#### Sun Mart 11 7707 West Deschutes Avenue, Kennewick

Date Report Received: 11/25/13

Type of report: Site characterization

Independent Cleanup Action Report Received

Name of report: Initial Site Characterization Report

Facility Site ID# 5574663

CSID# 12051

CSID# 12052

CSID# 8212



Contaminants reported: Petroleum Affected media: Soil, groundwater Contact:

Roger Johnson Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### USFW Whitcomb Island Farm Facilit 14 miles southwest of Paterson on Highway 14, Paterson

Independent Cleanup Action Report Received
Date Report Received: 11/27/13
Name of report: Second 2013 Semi-Annual Groundwater Monitoring Report
Date of report: 11/22/13
Type of report: Groundwater monitoring
Contaminants reported: Petroleum
Affected media: Groundwater
Contact:
Roger Johnson
Central Regional Office

509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### **CHELAN COUNTY**

#### Green Former Bulk Plant 1324 West Woodin Avenue, Chelan

Independent Cleanup Action Report Received Date Report Received: 12/2/13 (by email) Name of report: Spill Report Date of report: 10/15/13 Type of report: Spill report Contaminants reported: Gasoline, diesel Affected media: Soil Contact: Roger Job

Facility Site ID# 4086

iesel Roger Johnson Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### **KITTITAS COUNTY**

#### Summit Central Site HC 906, Snoqualmie Pass

Facility Site ID# 85448554

CSID# 12257

Independent Cleanup Action Report Received Date Report Received: 9/30/13 (by email)

Name of report: Site Characterization and Voluntary Cleanup Report Date of report: 8/28/13

## , Paterson

Facility Site ID# 88241112

CSID# 1681

CSID# 12258



Type of report: Site characterization, remedial action Contaminants reported: Petroleum Afttitasfected media: Soil Contact: Roger Johnson

Roger Johnson Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### Summit Central Site HC 906, Snoqualmie Pass

Facility Site ID# 85448554

CSID# 12257

#### Determination of No Further Action

Ecology has determined that no further action is necessary at the Summit Central site. The site had gasoline and diesel contamination in soil.

Contact:
----------

Frosti Smith Central Regional Office 509/ 454-7841 Frosti.Smith@ecy.wa.gov

For more information:

Summit Central site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=12257

#### YAKIMA COUNTY

Van Cleave Body Shop Site 305 Division Street, Yakima Facility Site ID# 478

CSID# 4196

#### Public comment period: 11/25/13 – 12/26/13

#### Site Proposed for Removal from Hazardous Sites List

Ecology proposes to remove the Van Cleave Body Shop site from the Hazardous Sites List (HSL). The site was ranked a 1 on the HSL (a rank of "1" represents the highest level of risk compared to other sites, and a rank of "5" represents the lowest). Ecology has determined that this site does not pose a threat to human health or the environment and recommends removing the site from the HSL.

Please direct questions and written comments to periodic review coordinator John Mefford.

Site Manager: John Mefford Central Regional Office 509/ 454-7836 John.Mefford@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the document at the following locations:

• Van Cleave Body Shop site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4196

• Ecology's Central Regional Office Toxics Cleanup Program – 15 W. Yakima Ave., Suite 200, Yakima, WA. (Please call 509/454-7658 for an appointment.)



#### Superior Asphalt E Beech St 2000 East Beech Street, Yakima

Facility Site ID# 488

CSID# 11394

Independent Cleanup Action Report Received Date Report Received: 11/21/13 Name of report: 2013 Groundwater Monitoring Report Date of report: 11/18/13 Type of report: Groundwater monitoring Contaminants reported: Diesel Affected media: Groundwater Contact: Roger Johnson

Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### **VOLUNTARY CLEANUP PROGRAM**

A property owner cleaning up a contaminated site may enter Ecology's Voluntary Cleanup Program (VCP).

#### VCP CONTACTS

Central Regional Office VCP Contact: Frosti Smith, e-mail Frosti.Smith@ecy.wa.gov or call 509/ 454-7841 Eastern Regional Office VCP Contact: Patti Carter, e-mail: Patti.Carter@ecy.wa.gov or call 509/ 329-3522 Northwest Regional Office VCP Contact: Donna Musa e-mail Donna.Musa@ecy.wa.gov or call 425/ 649-7136 Southwest Regional Office VCP Contact: Kim Cross, e-mail Kim.Cross@ecy.wa.gov or call 360/ 407-6240

#### **BENTON COUNTY**

7 Eleven Store 2306 25412 2411 George Washington Way, Richland Facility Site ID# 62328428

CSID# 11984

VCP/Independent Cleanup Action Report Received Date Report Received: 11/18/13 Name of report: Subsurface Investigation Report Date of report: 11/14/13 Type of report: Subsurface investigation Contaminants reported: Petroleum Affected media: Soil

Contact:

Roger Johnson Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

## Site Register

#### **KITTITAS COUNTY**

#### Pilot Travel Center 389 Facility Site ID# 18911356 CSID# 5649 1512 Highway 97, Ellensburg VCP/Independent Cleanup Action Report Received Date Report Received: 10/29/13 Name of report: Third Quarter 2013 Groundwater Monitoring Report Date of report: 10/25/13 Type of report: Groundwater monitoring Contaminants reported: Gasoline, diesel, benzene Affected media: Groundwater Contact: **Roger Johnson** Central Regional Office 509/454-7839 Roger.Johnson@ecy.wa.gov Dollar Way Mini Mart Facility Site ID# 38115463 CSID# 5990 1404 North Dolarway Road, Ellensburg VCP/Independent Cleanup Action Report Received Date Report Received: 11/18/13 Name of report: Quarterly Progress Report - July through September 2013 Date of report: 11/14/13 Type of report: Progress report Contaminants reported: Gasoline, BTEX Affected media: Soil, groundwater Contact: **Roger Johnson** Central Regional Office 509/454-7839 Roger.Johnson@ecy.wa.gov Facility Site ID# 48876329 CSID# 12244 VCP/Independent Cleanup Action Report Received Date Report Received: 10/30/13 Name of report: Proposal for Groundwater Investigation Date of report: 10/10/13 Type of report: Groundwater investigation proposal Contaminants reported: Ammonium hydroxide

Affected media: Groundwater

#### Contact.

**Roger Johnson** Central Regional Office 509/454-7839 Roger.Johnson@ecy.wa.gov

Publication #13-09-041 Y

#### **YAKIMA COUNTY**

#### **Darigold Sunnyside** 400 Alexander Road, Sunnyside



**Gailleon Park Site** 

Facility Site ID# 44832462

CSID# 2859

#### 101 North 65th Avenue, Yakima

#### Public comment period: 11/27/13 - 12/27/13

#### Second Periodic Review Available for Public Comment

Ecology invites you to review and comment on a document called a periodic review for the Gailleon Park site. A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA).

The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment.

Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct questions and written comments to periodic review coordinator Jeff Newschwander.

Periodic Review Coordinator:	Jeff Newschwander
	Central Regional Office
	509/ 454-7842
	Jeff.Newschwander@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the document at the following locations:

Gailleon Park site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=2859

• Ecology's Central Regional Office Toxics Cleanup Program – 15 W. Yakima Ave., Suite 200, Yakima, WA. (Please call 509/454-7658 for an appointment.)

#### Mabton Mini Mart Main & State Highway 22

Facility Site ID# 23115157

CSID# 5719

VCP/Independent Cleanup Action Report Received Date Report Received: 11/20/13 by email Name of report: Site Characterization and Remedial Action Report Date of report: November 2013 Type of report: Remedial action report Contaminants reported: Petroleum Affected media: Soil

Contact:

Roger Johnson Central Regional Office 509/ 454-7839 Roger.Johnson@ecy.wa.gov

#### Facility Site ID# 55484252

CSID# 4116

#### North Star Lodge Site 808 North 39th Avenue, Yakima

#### Public comment period: 11/27/13 - 12/27/13

#### Second Periodic Review Available for Public Comment

Ecology invites you to review and comment on a document called a periodic review for the North Star Lodge site. A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment.

Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made. Please direct questions and written comments to periodic review coordinator Jeff Newschwander.

Periodic Review Coordinator:	Jeff Newschwander
	Central Regional Office
	509/ 454-7842
	Jeff.Newschwander@ecy.wa.gov

More information may be found on Ecology's Public Events Calendar: http://www.ecy.wa.gov/; click on calendar.

You may review the document at the following locations:

• North Star Lodge site: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4116

• Ecology's Central Regional Office Toxics Cleanup Program – 15 W. Yakima Ave., Suite 200, Yakima, WA. (Please call 509/454-7658 for an appointment.)

#### NEWS & NOTES

## **Status Report on Pasco Landfill**

The Department of Ecology is working with several parties who are responsible for cleanup of contamination at the Pasco Landfill in Franklin County. The landfill is located on Dietrich Road north of the intersection of Kahlotus Road with U.S. Highway 12. Treatment systems are in place at the landfill to decrease contamination. These systems are showing positive improvements.

On Dec. 2, Ecology learned there is a fire under the ground in a small section of the landfill where old municipal wastes are buried. The area is approximately 25 feet in diameter. All parties involved are working to solve this situation quickly and keep the public informed as soon as information is received. The site is closed to the public and posted with no trespassing signs.

Currently, we know:

• There is no immediate threat to people living near the site or to workers and businesses in the area based on current knowledge.

• Actions are already being taken to evaluate and suppress the fire. Ecology is working closely with Pasco and Franklin County fire departments and other technical experts who know how to monitor and suppress these types of fires. Elected officials are also aware of the situation.

· Ecology will provide the community additional updates as more information is obtained.

If you have concerns or questions, please contact Ecology site manager Chuck Gruenenfelder at Ecology's Spokane office at 509/ 329-3429 or e-mail at chgr461@ecy.wa.gov. Para asistencia en español, comuníquese con Gregorio Bohn al 509/ 454-74174.

#### GLOSSARY

Agreed order - A legal agreement with Ecology to make sure the cleanup meets the standards of Washington State's cleanup law, the Model Toxics Control Act (MTCA).

**Cleanup action plan (CAP)** - A document that describes the selected cleanup method(s) and specifies cleanup standards and other requirements. It is based on information and technical analyses generated during the RI/FS and consideration of public comments and community concerns. A draft of the CAP (DCAP) is made available for public review and comment before finalizing.

**Comment period** - A time period during which the public can review and comment on various documents and Ecology or EPA actions. For example, a comment period is provided to allow community members to review and comment on proposed cleanup action alternatives and proposed plans. Also, a comment period is held to allow community members to review and comment on draft feasibility studies.

**Consent decree** - A formal legal agreement that is filed with a court. It describes studies and/or cleanup work to be done at a site and the terms under which that work is to be done.

**Engineering design report** - Engineering design reports outline the specific details for implementation and operation of the first phase of the cleanup actions.

ERTS - Environmental Report Tracking System

**Five-year periodic review** - A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment.

**Hazardous Sites List** - A statewide list of contaminated properties. Ecology may remove a site from the list only after determining that all remedial actions except confirmational monitoring have been completed and compliance with the cleanup standards has been achieved at the site, or the listing was erroneous.

Independent cleanup action - Any remedial action without department oversight or approval and not under an order or decree

LUST - Leaking Underground Storage Tank

NFA - No Further Action

**Public participation plan** - Outlines and describes the tools Ecology will use to inform the public about site activities, and it identifies opportunities for the community to become involved in this process.

**PSI** - Puget Sound Initiative

RCW - Revised Code of Washington

Remedial action - Construction work done to clean up a contaminated site.

**Remedial investigation/feasibility study** - Two distinct but related studies. They are usually performed at the same time, and together referred to as the "RI/FS."

**Responsiveness summary** - A summary of oral and/or written public comments received by Ecology during a comment period on key documents, and Ecology's responses to those comments.

RI/FS - See Remedial Investigation/Feasibility Study

SEPA - State Environmental Policy Act

**Site Hazard Assessment (SHA)** - An assessment to gather information about a site to confirm whether a release of hazardous substances has occurred and to enable Ecology to evaluate the relative potential hazard posed by the release.



UST - Underground Storage Tank

UXO - Unexploded Ordnance

**Voluntary Cleanup Program (VCP)** - The VCP is one of several options for cleaning up a hazardous waste site under the state's cleanup law. Under this option, property owners may perform a cleanup independently and request services from Ecology for a fee.

WAC - Washington Administrative Code

WARM, Washington Ranking Method - The method used to rank sites placed on the Hazardous Sites List.

Additional glossary terms may be found on the Ecology website at: http://www.ecy.wa.gov/programs/tcp/tcp\_acronym\_list.htm

#### SITE INFORMATION ONLINE

Visit this link to find info on all TCP sites: https://fortress.wa.gov/ecy/gsp.

To find out about Public Events related to the sites listed in this issue, go to http://apps.ecy.wa.gov/pubcalendar/calendar.asp

#### **REGIONAL OFFICES**

Ecology Central Regional Office 15 West Yakima Ave., Suite 200 Yakima, WA 98902-3452

Ecology Northwest Regional Office 3190 160th Ave. SE Bellevue, WA 98008-5482 Ecology Eastern Regional Office 4601 N. Monroe Spokane, WA 99205-1295

Ecology Southwest Regional Office 300 Desmond Drive Lacey, WA 98503

Ecology Headquarters Office 300 Desmond Drive Lacey, WA 98503