

Site Register

WASHINGTON STATE DEPARTMENT OF ECOLOGY—TOXICS CLEANUP PROGRAM



OCTOBER 27, 2016

CONTENTS

Formal Cleanups	1
Independent Cleanups	12
Glossary	14
Site Information Online	15
Regional Office Addresses	15

Sign up to receive the Site Register via email:

[http://listserv.wa.gov/cgi-bin/wa?](http://listserv.wa.gov/cgi-bin/wa?A0=SITEREGISTER)

[A0=SITEREGISTER](http://listserv.wa.gov/cgi-bin/wa?A0=SITEREGISTER)

Under “Options” click **Subscribe**.

Find past issues: <http://1.usa.gov/hAJyav>

For information about public comment periods, meetings and hearings, visit Ecology's Public Involvement Calendar at <https://fortress.wa.gov/ecy/publiccalendar/>.

Questions? Please contact Erika Bronson at 509-329-3546 or erika.bronson@ecy.wa.gov. Site contacts are found after each entry.

To request Americans with Disabilities Act accommodation including materials in a format for the visually impaired, please call 360-407-7170 or visit <http://www.ecy.wa.gov/accessibility.html>. Persons with impaired hearing may call Washington Relay Service at 711. Persons with a speech disability may call 877-833-6341.

FORMAL CLEANUPS

Ecology oversees complex cleanup sites to ensure that your health and that of the environment are protected.

CLARK COUNTY

Facility	Cleanup
Site ID#	Site ID#
7720 Northeast Highway 99, Vancouver	5686

7720 Northeast Highway 99, Vancouver

Public comment period: 10/13/16 – 11/14/16

Draft Periodic Review Report Available for Public Review and Comment

The former Totem Pole Restaurant site is now home to a framing store, cell phone store, coffee shop, and tanning salon.

From around 1930 and 1960, an auto service station was on the site. Its underground storage tank system released fuels into soil and groundwater. A cleanup in 2000 included digging up over 2,000 tons of contaminated soils and disposing of them at landfills. Some soil contamination remains on the site but is covered by an asphalt cap.

The periodic review finds that cleanup is still protective. Although contaminated soil remains on the site, the asphalt cap protects people from coming into contact with it. The contamination is not impacting groundwater. The property owner must continue to ensure the asphalt cap is in good shape. Ecology will review the site again in five years.

Please direct questions and comments to the periodic review coordinator:

Panjini Balaraju
Southwest Regional Office
360-407-6335
Panjini.Balaraju@ecy.wa.gov

Document review locations:

- Totem Pole Restaurant website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=5686>.
- Ecology's Southwest Regional Office – 300 Desmond Drive SE, Lacey. For an appointment, please contact Susie Baxter at 360-407-6365 or PublicDisclosureSWRO@ecy.wa.gov.

Site Register

KING COUNTY

3842 Interlake Avenue North Site

Facility Site ID# 5037427 Cleanup Site ID# 1512

3842 Interlake Avenue North, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Ecology invites you to review and comment on a document called a periodic review for a portion of the 3842 Interlake Avenue North site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by the Model Toxics Control Act (MTCA).

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Northwest Regional Office

425-649-7191

Eugene.Freeman@ecy.wa.gov

Document review locations:

- 3842 Interlake Avenue North website: **<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=1512>**.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at **425-649-7190** or **Sally.Perkins@ecy.wa.gov**.

Dexter Horton Building Site

Facility Site ID# 68766933 Cleanup Site ID# 3150

710 2nd Avenue, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Ecology invites you to review and comment on a document called a periodic review for a portion of the Dexter Horton Building site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by MTCA.

Site Register

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Northwest Regional Office

425-649-7191

Eugene.Freeman@ecy.wa.gov

Document review locations:

- Dexter Horton Building website: **<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=3150>**.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at **425-649-7190** or **Sally.Perkins@ecy.wa.gov**.

Greenwood Mixed Use Building Site

Facility Site ID# 5573744

Cleanup Site ID# 495

8214 Greenwood Avenue North, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Ecology invites you to review and comment on a document called a periodic review for a portion of the Greenwood Mixed Use Building site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by MTCA.

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Northwest Regional Office

425-649-7191

Eugene.Freeman@ecy.wa.gov

Site Register

Document review locations:

- Greenwood Mixed Use Building website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=495>.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at [425-649-7190](tel:425-649-7190) or Sally.Perkins@ecy.wa.gov.

Hines Interests 4th Avenue

Facility Site ID# 84854685 Cleanup Site ID# 7136

1001 4th Avenue, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Ecology invites you to review and comment on a document called a periodic review for a portion of the Hines Interests 4th Avenue site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by MTCA.

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Northwest Regional Office

[425-649-7191](tel:425-649-7191)

Eugene.Freeman@ecy.wa.gov

Document review locations:

- Hines Interests 4th Avenue website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=7136>.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at [425-649-7190](tel:425-649-7190) or Sally.Perkins@ecy.wa.gov.

Mt. Baker Properties Site

Facility Site ID# 96127971 Cleanup Site ID# 13054

2864 S McClellan Street, Seattle

Public comment period: 10/28/16 – 11/28/16

Draft Prospective Purchaser Consent Decree and Public Participation Plan Available for Public Review and Comment

Site Register

The Mt. Baker Housing Association (MBHA), a not-for-profit organization, is in the process of buying and redeveloping five properties within the Mt. Baker Properties Site for affordable housing:

- Four of the properties, one a former dry cleaning business, are located at the northeast corner of MLK Jr. Way South and South McClellan Street with addresses of 2802, 2806, 2810, and 2864 South McClellan Street (collectively referred to as the “McClellan Parcels”).
- The fifth property, a former gas station, is located southeast of the same intersection with an address of 2800 MLK Jr. Way South (referred to as the “Former Gas Service Station Parcel”).

Ecology invites you to review and comment on a proposed legal agreement called a Prospective Purchaser Consent Decree (PPCD) with MBHA. The PPCD identifies a framework for future environmental assessment and cleanup at the Site. Future assessment work will include completing a remedial investigation and feasibility study (RI/FS) to evaluate the extent of the contaminated area and develop preliminary cleanup options. Future cleanup work will be based on RI/FS results and may include completing a Cleanup Action Plan (CAP) and implementing the CAP either prior to or concurrent with the property’s redevelopment.

Future assessment and cleanup work depends on MBHA obtaining funding for the work. MBHA cannot redevelop the properties until it completes the assessment and cleanup work.

The draft Public Participation Plan, which describes how and when you can participate in cleanup decisions, is also available for review and comment.

Please direct comments and questions to the cleanup site manager:

Ching-Pi Wang
Northwest Regional Office
425-649-7134
ching-pi.wang@ecy.wa.gov

Document review locations:

- Mt. Baker Properties website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13054>.
- Beacon Hill Public Library – 2821 Beacon Avenue South, Seattle, **206-684-4711**.
- Downtown Public Library – 1000 4th Avenue, Seattle, **206-386-4636**.
- Ecology’s Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at **425-649-7190** or **Sally.Perkins@ecy.wa.gov**.

US West Airport Way SOC 070307 Site

Facility Site ID# 69857925 Cleanup Site ID# 7116

1709 Airport Way South, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Site Register

Ecology invites you to review and comment on a document called a periodic review for a portion of the US West (now Qwest) Airport Way SOC 070307 site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by MTCA.

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Northwest Regional Office

425-649-7191

Eugene.Freeman@ecy.wa.gov

Document review locations:

- US West (now Qwest) Airport Way SOC 070307 website: **<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=7116>**.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at **425-649-7190** or **Sally.Perkins@ecy.wa.gov**.

William C Smith Property Site

Facility Site ID# 91169457 Cleanup Site ID# 6841

12730 Lake City Way Northeast, Seattle

Public comment period: 10/27/16 – 11/28/16

Draft Periodic Review Available for Public Review and Comment

Ecology invites you to review and comment on a document called a periodic review for a portion of the William C Smith Property site. A periodic review is conducted at least every five years after beginning cleanup at a site or property, as required by MTCA.

The purposes of the review are to evaluate site conditions and to ensure continued protection of human health and the environment, when institutional controls are used as part of a remedy. Ecology will review comments received during the comment period and make recommendations for suggested changes. The periodic review will become final if no significant changes are made. An additional public comment period will be held if significant changes are made.

Please direct comments and questions to the periodic review coordinator:

Eugene Freeman

Site Register

Northwest Regional Office

425-649-7191

Eugene.Freeman@ecy.wa.gov

Document review locations:

- William C Smith Property website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=6841>.
- Ecology's Northwest Regional Office – 3190 160th Avenue Southeast, Bellevue. Please contact Sally Perkins for an appointment at **425-649-7190** or Sally.Perkins@ecy.wa.gov.

PIERCE COUNTY

**Louisiana Pacific Corp. Site
(Pony Lumber)**

Facility Site ID# 1209 Cleanup Site ID# 2317

3701 Taylor Way, Tacoma

Public comment period: 10/13/16 – 11/14/16

Draft Periodic Review Report Available for Public Review and Comment

Ecology invites you to review and provide comment on the five-year review of the Louisiana Pacific Corp. (also known as Pony Lumber) cleanup site.

Louisiana Pacific Corporation developed the property as a log yard and used contaminated Asarco slag as ballast. Investigations at the site found arsenic, copper, lead, and zinc at concentrations requiring cleanup. Louisiana Pacific investigated and cleaned up the site from 1983 to 1993.

While contaminated soil remains at the site under a concrete cap, Ecology staff found that the cleanup is still protective. An environmental covenant is in place to make any future owners aware of the contamination, and Ecology will review the site again in five years.

Please direct comments and questions to the periodic review coordinator:

Panjini Balaraju

Southwest Regional Office

360-407-6335

Panjini.Balaraju@ecy.wa.gov

Document review locations:

- Louisiana Pacific Corp. website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=2317>.
- Ecology's Southwest Regional Office – 300 Desmond Drive, Lacey. For an appointment, please contact Susie Baxter at PublicDisclosureSWRO@ecy.wa.gov or **360-407-6365**.

Site Register

**RW Investments Lincoln Avenue Site
(River Street Cardlock Facility)**

Facility Site ID# 1365

Cleanup Site ID# 164

2150 Taylor Way, Tacoma

Public comment period: 10/13/16 – 11/14/16

Draft Periodic Review Report Available for Public Review and Comment

Ecology invites you to review and comment on the five-year review of the RW Investments Lincoln Avenue cleanup site.

From 1992 to 1993, then-owner RW Investments found ethylbenzene, styrene, hexachlorobutadine, and total petroleum hydrocarbons at levels requiring cleanup in groundwater and soil. Storage sheds that housed liquid fiberglass resin and petroleum products contaminated soil.

The site was cleaned up under the **Voluntary Cleanup Program**. RW Investments' contractor removed the storage sheds and about 192 tons of contaminated soil from the property in December 1993.

While contaminated soil remains at the site under buildings and compacted gravel surfaces, Ecology staff found that the cleanup is still protective. An environmental covenant is in place to make any future owners aware of the contamination, and Ecology will review the site again in five years.

Please direct comments and questions to the periodic review coordinator:

Panjini Balaraju

Southwest Regional Office

360-407-6335

Panjini.Balaraju@ecy.wa.gov

Document review locations:

- RW Investments Lincoln Avenue website: **<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=164>**.
- Ecology's Southwest Regional Office – 300 Desmond Drive, Lacey. For an appointment, please contact Susie Baxter at **PublicDisclosureSWRO@ecy.wa.gov** or **360-407-6365**.

Xytec Clorox Lakewood Site

Facility Site ID# 1287

Cleanup Site ID# 3913

901 South 11th Street, Tacoma

Public comment period: 10/15/16 – 11/17/16

Draft Periodic Review Report Available for Public Review and Comment

Ecology invites you to review and comment on the five-year review of the Xytec Clorox Lakewood cleanup site.

Site Register

The Xytec Clorox Lakewood site is in the Lakewood/Tacoma Industrial Park. Starting in the late 1970s, several different companies made plastic products at the site.

A 1990 investigation found soils contaminated with petroleum chemicals. In 1993, Clorox dug up 1,550 tons of contaminated soil and sent them for thermal treatment. Clorox then filled in the area with clean soils and covered it with an asphalt cap.

The periodic review finds cleanup is still effective at protecting the environment and human health. Although contaminated soil remains on the site, the asphalt cap protects people from contacting it. The property owner must continue to ensure the asphalt cap is in good shape.

Please direct questions and comments to the periodic review coordinator:

Panjini Balaraju

Southwest Regional Office

360-407-6335

Panjini.Balaraju@ecy.wa.gov

Document review locations:

- Xytec Clorox Lakewood website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=3913>.
- Ecology's Southwest Regional Office – 300 Desmond Drive Lacey. For an appointment, please contact Susie Baxter at **360-407-6365** or **PublicDisclosureSWRO@ecy.wa.gov**.

SNOHOMISH COUNTY

Everett Shipyard Site

Facility Site ID# 2794

Cleanup Site ID# 3655

1016 14th Street, Everett

Public comment period: 10/14/16 – 11/12/16

Draft Amendments to the Cleanup Action Plan, Consent Decree, and Public Participation Plan

Ecology invites you to review and comment on draft amendments to the cleanup action plan, consent decree and public participation plan for the Everett Shipyard site.

The draft amendment to the cleanup action plan reflects changes identified and approved during cleanup. The plan describes the proposed cleanup action for the site and outlines requirements.

Because of the draft amendment to the cleanup action plan, the consent decree, the legal agreement requiring the responsible parties to cleanup the site, must also be amended.

The public participation plan describes how you can provide input on cleanup decisions about the site.

Site Register

Please direct comments and questions to the cleanup site manager:

Hun Seak Park
Headquarters Office
360-407-7189
hunseak.park@ecy.wa.gov

Document review locations:

- Everett Shipyard website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=3655>.
- Ecology's Headquarters Office – 300 Desmond Drive Southeast, Lacey. Please contact Carol Dorn for an appointment at **360-407-7224** or carol.dom@ecy.wa.gov.

THURSTON COUNTY

Budd Inlet Sediment Site

Facility Site ID# 3097108

Cleanup Site ID# 2245

Budd Inlet, Olympia

Reports Now Available for Budd Inlet Sediment Investigation

Two reports are available that discuss the Budd Inlet Sediment Investigation. The first is the Port of Olympia's Final Study Area Investigation Report. This report describes how the study was done and states the type and extent of the contamination in the Study Area.

The second study is Ecology's Budd Inlet Sediment Dioxin Source Study. This study details the types of dioxins found in the harbor, their potential sources, and where different types of dioxins are located.

This information will be used to:

- Identify potential sources of contamination in Budd Inlet
- Help evaluate cleanup actions for the study area
- Better understand contamination in Puget Sound.

Document review locations:

- Budd Inlet Sediment website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=2245>.
- Olympia Timberland Library – 313 8th Avenue SE, Olympia, **360-352-0595**.
- Ecology's Southwest Regional Office – 300 Desmond Drive SE, Lacey. Please call (360) 407-6365 for an appointment or email PublicDisclosureSWRO@ecy.wa.gov.

For questions, please contact Peter Striplin at peter.striplin@ecy.wa.gov or **360-407-6267**.

For public involvement information, please contact Stacy Galleher at **360-407-6255** or Stacy.Galleher@ecy.wa.gov.

Site Register

West Olympia Landfill Site

Facility Site ID# 1425

Cleanup Site ID# 4807

Highway 101 & Black Lake Boulevard, Olympia

Negotiations Underway for Agreed Order

Ecology has started discussions and is working with the City of Olympia to develop an agreed order (legal agreement) for the West Olympia Landfill. This agreed order requires the City of Olympia to conduct a remedial investigation, feasibility study, and draft cleanup action plan. This work will help define the types and extent of site contamination. We expect to have a public review draft of the agreed order and hold a public comment period in early 2017.

West Olympia Landfill website: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4807>

For public involvement information, please contact Stacy Galleher at **360-407-6255** or Stacy.Galleher@ecy.wa.gov.

Site Register

INDEPENDENT CLEANUPS

A property owner may conduct an independent cleanup of contamination and submit reports to Ecology.

Independent Cleanup Contacts

Central Regional Office: Public Records Coordinator at cropublicrequest@ecy.wa.gov or **509-454-7658**

Eastern Regional Office: Kathy Falconer at kathy.falconer@ecy.wa.gov or **509-329-3589**

Northwest Regional Office: Donna Musa at donna.musa@ecy.wa.gov or **425-649-7136**

Southwest Regional Office: Kim Cross at kim.cross@ecy.wa.gov or **360-407-6240**

YAKIMA COUNTY

Bleyhl Farm Service Sunnyside Site

Facility Site ID# 56531667

Cleanup Site ID# 6304

1720 Eastway Drive, Sunnyside

Groundwater Monitoring Report Received

Date report received: 10/17/2016

Name of report: August 2016 Groundwater Monitoring Report

Date of report: 10/11/2016

Type of report: Groundwater monitoring

Contaminants reported: Petroleum

Affected media: Groundwater

Contact:

Public Records Coordinator

Central Regional Office

509-454-7658

cropublicrequest@ecy.wa.gov

Site Register

Costco Yakima Call Center Site

Facility Site ID# 9240

Cleanup Site ID# 13130

1700 N 6th St, Yakima

No Further Action Required

Ecology has determined that no further action is necessary at the Costco Yakima Call Center site. The site had diesel contamination in soil and groundwater.

Cleanup site manager:

John Mefford

Central Regional Office

509-454-7836

john.mefford@ecy.wa.gov

Costco Yakima Call Center website: **<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13130>**

Site Register

GLOSSARY

Agreed order - A legal agreement with Ecology to make sure the cleanup meets the standards of Washington State's cleanup law, the Model Toxics Control Act (MTCA).

Cleanup action plan (CAP) - A document that describes the selected cleanup method(s) and specifies cleanup standards and other requirements. It is based on information and technical analyses generated during the RI/FS and consideration of public comments and community concerns. A draft of the CAP (DCAP) is made available for public review and comment before finalizing.

Comment period - A time period during which the public can review and comment on various documents and Ecology or EPA actions. For example, a comment period is provided to allow community members to review and comment on proposed cleanup action alternatives and proposed plans. Also, a comment period is held to allow community members to review and comment on draft feasibility studies.

Consent decree - A formal legal agreement that is filed with a court. It describes studies and/or cleanup work to be done at a site and the terms under which that work is to be done.

Engineering design report - Engineering design reports outline the specific details for implementation and operation of the first phase of the cleanup actions.

ERTS - Environmental Report Tracking System

Five-year periodic review - A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment.

Hazardous Sites List - A statewide list of contaminated properties. Ecology may remove a site from the list only after determining that all remedial actions except confirmatory monitoring have been completed and compliance with the cleanup standards has been achieved at the site, or the listing was erroneous.

Independent cleanup action - Any remedial action without department oversight or approval and not under an order or decree.

LUST - Leaking Underground Storage Tank

NFA - No Further Action

Public participation plan - Outlines and describes the tools Ecology will use to inform the public about site activities, and it identifies opportunities for the community to become involved in this process.

PSI - Puget Sound Initiative

RCW - Revised Code of Washington

Site Register

Remedial action - Construction work done to clean up a contaminated site.

Remedial investigation/feasibility study - Two distinct but related studies. They are usually performed at the same time, and together referred to as the "RI/FS."

RI/FS - See Remedial Investigation/Feasibility Study

SEPA - State Environmental Policy Act

Site Hazard Assessment (SHA) - An assessment to gather information about a site to confirm whether a release of hazardous substances has occurred and to enable Ecology to evaluate the relative potential hazard posed by the release.

TCP - Ecology's Toxics Cleanup Program

Total petroleum hydrocarbons (TPH) - A term used to describe a large family of several hundred chemical compounds that originally come from crude oil. TPH is a mixture of chemicals made mainly from hydrogen and carbon.

UXO - Unexploded Ordnance

Voluntary Cleanup Program (VCP) - The VCP is one of several options for cleaning up a hazardous waste site under the state's cleanup law. Under this option, property owners may perform a cleanup independently and request services from Ecology for a fee.

WAC - Washington Administrative Code

WARM, Washington Ranking Method - The method used to rank sites placed on the Hazardous Sites List.

Find more glossary terms on Ecology's website: www.ecy.wa.gov/programs/tcp/tcp_acronym_list.htm

SITE INFORMATION ONLINE

Information on all Toxics Cleanup Program sites: <https://fortress.wa.gov/ecy/gsp>

Public Events related to the sites in this issue: <https://fortress.wa.gov/ecy/publiccalendar/>

REGIONAL OFFICES

Ecology Central Regional Office
1250 W. Alder St.
Union Gap, WA 98903-0009

Ecology Eastern Regional Office
4601 N. Monroe
Spokane, WA 99205-1295

Ecology Southwest Regional Office
300 Desmond Drive SE
Lacey, WA 98503

Ecology Northwest Regional Office
3190 160th Ave. SE
Bellevue, WA 98008-5482

Ecology Headquarters Office
300 Desmond Drive SE
Lacey, WA 98503