February 28, 1973

Publication No. 73-e50

WA-22-4045

State of ashington of Ecology

MEMO TO	: Ron	Robinso	on a
		Devitt	Ω
FROM:	Ron	Devitt	RCX

SUBJECT: Dredging of Simpson's Pond on Wildcat Creek at McCleary

Objective: Determine effect of dredging activities on turbidity.

Simpson Timber Company has had a dam on Wildcat Creek at McCleary since the early 1900's. It is used to retain an emergency water supply in case of fire. Water is pumped to a reservoir to supplement the city water supply. Should a serious fire errupt, water would also be pumped from the creek itself.

Periodically, sediment builds up behind the dam and dredging is necessary. The last time dredging activities were conducted, a coincidental fish kill occurred. For this reason, and because the Department of Fisheries was concerned about sedimentation of fish rearing habitat, sequential samplers were set up above and below the dam to monitor the turbidity of the creek.

The upstream sampler (ISCO) was located at the residence about 20 yards west of the McCleary-Shelton highway bridge. The downstream (N-Con) was located at the residence at the end of Ash street. Distance between the two samplers was approximately three-eights of a mile. Both were programed to take 250 milliliters each hour. They were initiated on January 22, 1973, and terminated January 30, 1973.

Both samplers were powered by 12 volt DC batteries and I had not used them for such a prolonged time. Problems occurred and a continuous series of samples were not obtained. However, enough (241) samples were taken to effectively determine the effect of the dredging.

Heely and Tibbets hydraulic dredge, the "mud cat" operated sporatically throughout the sampling period. It is not known if they worked the weekend. Spoils were pumped northerly over a small rise to a swampy area and spilled on the forest floor. The pumping rate was 2,000 gpm while underway. Page Two

February 28, 1973 Ron Robinson

The operations were conducted very conscientiously because success in obtaining two other contracts depended on the results of this project.

The weather varied from light snow, rain, and fair. Because the natural conditions of the creek itself due to runoff, the turbidity failed to show any increase due to dredging activities.

:

1

RD/jsg 27/7:8

cc: Mike Moorehouse Department of Fisheries Mike Price - DOE

TURBIDITY (JTU) OF WILDCAT CREEK 1-22-73 - 1-30-73

	11-20	1 72	1_22	72	1-2	1.72	1_2	5 72	1-20	-72	1-22	1_72	1-20	2_72	1-20	-72	1-20	-721
m T 1/13			1-24-73 1-25-											1-30-73				
TIME	1				WED		THU		FRI		SAT		SUN		MON		TUE	
	<u> </u>	i D	U	D	U	D	<u> </u>	D	U	D	U		U	<u> </u>			U	<u>D</u>
0000	-	-	-	1	7	~	5	-	-	-	1	1	-	1	-	1	-	
0100	-				8	-	5	-	1		1	1		1	-	2	6	3
0200	-		-	2	5			-	-		1	1	-	1	-	2	9	4
0300	-	-	-	-	10	-	-	-	-	-	1	1	-	2	-	1	5	3
0400			-	1	7		-	-	-		1	l	-	1	-	2	9	3
050 0			-		5	-	-	-			1	1	-	2	-	2	6	3
0600	-	-			8		-	-		-	1	1		1	-	2	10	4
0700	-	-	-	1	3	-	-	-	-		1	1	-	1	-	2	5	-
0800	-		-		5		-				1	1	-	1	-	2	8	-
090 0	-		-	1	8	-	-	-		`	1	1		1	-			-
1000	-	willip		2	-	-	-	-	-	-	1	1	-	2	-	_	_	-
1100	2				9		-		_		2			2	4	2	-	
1200	2			2	7		1	1	1	1	2 ·		-	2	4	2	_	-
1300	2	2	1	7	9		1	1	1	1	2		2	2	5	4		
1400	2	1		5	8	-	ī	1	ī	ī	2	2	1	2	3	2	_	-
1500	4	ī	-	4	10		1	1	1	1	2	2	3	2	9	2	_	_
1600	2	2	3	6	5			า	î	î	2	ī	-	1	6	3		_
1700	3	2	4	5	3	~	_	î	1	1	2	ī		2	10	3	_	_
1800		7	7	5	3	-	_	i	1	ī	2	î	_	2	10	3	_	
1900		1	4	4	4		_	1	1	1	2	1	_	1	10	3		_
2000		1	4	5	5		_		· · 上 9	-	2	2	-	2	9	3	_	-
2000	-			3		-				- 7	2	2		1	9			
	-	2	6		4	-	-					2 1	-	1 2	9	4 3	-	-
2200	-		8	3	4	-				1	~		-				-	-
2300	-	2	3	5	4	-	-			Ţ	-	1	-	2	6	4		
2400		2	7	3	4			1	1			1		2	10	5		-

U = Upstream

D = Downstream