

## STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

## **Central Region Office**

1250 West Alder St., Union Gap, WA 98903-0009 • 509-575-2490

May 8, 2023

## Sent via email

Katie Krajicek HDR Engineering 412 East Parkcenter Blvd., Suite 100 Boise, ID 83706

RE: Ecology Comments on Phase 3 Remedial Investigation Report, dated March 2023

Site Name: Simplot Soilbuilders Sunnyside
 Site Address: 300 South First Street, Sunnyside

Facility Site ID No.: 76742139
 Cleanup Site ID No.: 2558
 Agreed Order No.: DE 16446

## Dear Katie Krajicek:

Thank you for submitting the above-referenced document. No revision or reissue of the Phase 3 Remedial Investigation Report is requested. Ecology agrees that Simplot should proceed to a Feasibility Study (FS).

Requirements of the FS are set forth in Agreed Order DE 16446, Exhibit B, Task 5, "Feasibility Study." This section indicates "Prior to beginning the FS, a Key Project Meeting will be held to review ARARs, potential remedial alternatives and establish points of compliance." Ecology will work with Simplot to set up a meeting to discuss these items and the schedule for the FS moving forward.

Please contact me at (509) 907-1353 or Rachel.Caron@ecy.wa.gov if you require any clarification of these comments or have further questions.

Sincerely,

Rachel Caron
Site Manager
Toxics Cleanup Program
Central Regional Office

cc: Molly Dimick, J.R. Simplot Company

<sup>&</sup>lt;sup>1</sup> https://apps.ecology.wa.gov/cleanupsearch/document/84140