

# Cleanup Site Details

Cleanup Site ID: 15139

**Cleanup Site ID:** 15139      **Facility/Site ID:** 49919      **UST ID:** N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Duwamish Waterway Park      [Glossary](#)  
**Alternate Names:** 1024 S Elmgrove St, Duwamish Waterway Park, Duwamish Waterway Park Addition, DWP, DWP Addition, United Site Services of Nevada Inc Sea

## LOCATION

**Address:** 7900 10TH AVE S      **City:** SEATTLE      **Zip Code:** 98108      **County:** King  
**Latitude:** 47.53104      **Longitude:** -122.31986      **WRIA:** 9      **Legislative District:** 11      **Congressional District:** 9      **TRS:** 24N 4E 32

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 2 - Moderate-High Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Butler, David      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duwamish Waterway Park	Upland	Cleanup Started	NW	Butler, David	Ecology-supervised or conducted
Duwamish Waterway Park Addition	Upland	Cleanup Started	NW	Butler, David	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	S	S			
Lead	C	S				
Mercury	C	S	S			
Metals - Other	C	S	S			
Other Halogenated Organics	C	S	S			
Other Non-Halogenated Organics	C	S	S			
Polychlorinated biPhenyls (PCB)	C	S	S			
Polycyclic Aromatic Hydrocarbons	C	S	S			

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		5/30/2019
Non-LUST Ind Report Received	Completed		5/30/2019

# Cleanup Site Details

Cleanup Site ID: 15139

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		5/30/2019
Non-LUST Ind Report Received	Completed		5/30/2019
Initial Investigation / Federal Preliminary Assessment	Completed		1/28/2020
Early Notice Letter(s)	Completed		2/5/2020
VCP Receipt of Plan or Report	Completed		7/1/2020
VCP Opinion on Remedial Investigation	Completed	7/15/2020	10/27/2021
VCP Receipt of Plan or Report	Completed		8/24/2021
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/2022	10/10/2022
Hazardous Sites Listing/NPL	Completed		10/28/2022
Order/Decree/Amendment	In Process	10/28/2022	