

Cleanup Site ID: 220

Cleanup Site Details

Facility/Site ID: 2913 UST ID: N/A Site Page Site Documents View Map

MEDIA

Cleanup Site ID: 220

Cleanup Site Name: Cornwall Avenue Landfill

Alternate Names: CORNWALL AV LANDFILL, CORNWALL AVENUE LANDFILL, GEORGIA PACIFIC DNR 22002353

LOCATION

Address: CORNWALL AVE City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.74083 Longitude: -122.49269 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 38N 2E 36

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: McInerney, Lucy Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CORNWALL AVENUE LANDFILL	Sediment	Cleanup Started	NW	McInerney, Lucy	Ecology-supervised or conducted
Cornwall Avenue Landfill	Upland	Cleanup Started	NW	Adams, Mark	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA							
Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
				С			
S	С	S		С			
			С				
				С			
				С			
S	С	S	С				
				S			
				С			
				С			
				С			
S							
S			С				
			С				
	S	S C	Soil Groundwater Surface Water S C S S C S S S S S	Soil Groundwater Surface Water Sediment S C S C S C S C S C S C S C S	Soil Groundwater Surface Water Sediment Air S C S C C C C C S C S C S C S C S C C C S C C C S C C C S C C C		

Toxics Cleanup Program Report Generated: 5/9/2024 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 220

Key:B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	6/1/1992	8/15/1992
Early Notice Letter(s)	Completed		7/16/1992
Hazardous Sites Listing/NPL	Completed		8/30/1992
Early Notice Letter(s)	Completed		1/12/1995
VCP Opinion on Remedial Investigation Work Plan	Completed	4/21/1998	
Remedial Investigation and/or Feasibility Study	Completed	6/1/1998	12/13/2013
VCP Status Request	Completed	11/13/2006	5/24/2007
Order/Decree/Amendment	Completed	1/1/2014	12/13/2013
Cleanup Action Plan	Completed	1/1/2014	10/10/2014
Order/Decree/Amendment	In Process	1/1/2014	
Cleanup Action - Engineering Design	In Process	10/11/2014	

Report Generated: 5/9/2024 **Toxics Cleanup Program** Page 2 of 2