

Cleanup Site Details

Cleanup Site ID: 2569

Cleanup Site ID: 2569 Facility/Site ID: 9 UST ID: 5351 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kimberly-Clark Worldwide [Glossary](#)

Alternate Names: KIMBERLY CLARK CORP, KIMBERLY CLARK CORPORATION, KIMBERLY CLARK TISSUE CO EVERETT, Kimberly Clark Worldwide, KIMBERLY CLARK WORLDWIDE INC, Kimberly-Clark Worldwide, SCOTT PAPER CO, SCOTT PAPER CO EVERETT, SCOTT PAPER CO UST 5351

LOCATION

Address: 2600 FEDERAL AVE **City:** EVERETT **Zip Code:** 98201 **County:** Snohomish
Latitude: 47.98572 **Longitude:** -122.21678 **WRIA:** 7 **Legislative District:** 38 **Congressional District:** 2 **TRS:** 29N 5E 19

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 4 - Low-Moderate Risk **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: Cook, Jason **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Scott Paper Co Everett	Upland	No Further Action Required	NW	Northwest Region	Independent Action
Kimberly-Clark Worldwide	Sediment	Awaiting Cleanup	HQ	Adolphson, Pete	Ecology-supervised or conducted
Kimberly-Clark Worldwide	Upland	Cleanup Started	HQ	Cook, Jason	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C		C		
Benzene	S					
Bioassay Failure				C		
Conventional Contaminants, Inorganic				C		
Dioxins/Furans	C			C		
Halogenated Solvents		S				
Lead	C	C				
Mercury		C		C		
Metals - Other	C	C		C		
Other Deleterious Substances				S		
Other Halogenated Organics	S	S		C		
Other Non-Halogenated Organics	S	C		C		

Cleanup Site Details

Cleanup Site ID: 2569

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C		S		
Petroleum-Gasoline	C	C				
Petroleum-Other	C	S		S		
Phenolic Compounds				C		
Polychlorinated biPhenyls (PCB)	C			C		
Polycyclic Aromatic Hydrocarbons	C	C		C		

Key:

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		11/21/1989
LUST - Report Received	Completed		12/27/1999
Order/Decree/Amendment	In Process	3/28/2012	
Early Notice Letter(s)	Completed		4/5/2012
Interim Action - Plan	Completed	7/2/2012	9/24/2012
Remedial Investigation and/or FS Work Plan	Completed	12/20/2012	11/26/2013
Interim Action - Construction	Completed	8/19/2013	5/30/2014
Remedial Investigation and/or Feasibility Study	In Process	10/1/2013	
Site Hazard Assessment/Federal Site Inspection	Completed	10/23/2013	12/24/2013
Hazardous Sites Listing/NPL	Completed		1/16/2014
Interim Action - Performance Monitoring	Completed	5/1/2014	8/20/2016
Order/Decree/Amendment	In Process	11/30/2017	
Interim Action - Plan	Completed	7/3/2018	12/13/2019
Early Notice Letter(s)	Completed		1/22/2020
Early Notice Letter(s)	Completed		1/29/2020
Interim Action - Construction	Completed	2/12/2020	3/3/2021
Non-LUST Ind Report Received	Completed		3/11/2020
Order/Decree/Amendment	In Process	5/29/2020	
Interim Action - Plan	Completed	4/12/2021	8/5/2021
Interim Action - Construction	In Process	9/1/2021	
Non-LUST Ind Report Received	Completed		3/10/2022
Cleanup Action Plan	Planned	6/30/2023	12/28/2023