

Cleanup Site ID: 3418

# Cleanup Site Details

Facility/Site ID: 2864 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3418

Cleanup Site Name: Central Waterfront

Alternate Names: CENTRAL WATERFRONT, Old City Dump, ROEDER AVE LANDFILL

LOCATION

Address: F ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75545 Longitude: -122.48999 WRIA: 1 Legislative District: 42 Congressional District: 2 TRS: 38N 2E 25

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Rapp, John Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Roeder Ave Landfill	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Chevron Bellingham Terminal 100- 1350	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Olivine Corp Hilton Ave Uplands	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Colony Wharf (BCI)	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

#### **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic		С					
Base/Neutral/Acid Organics	S	S	S				
Benzene	С	С					
Conventional Contaminants, Organic	С						
Halogenated Organics	S	S	S				
Lead	С	С					
Mercury		С					
Metals - Other		С					
Metals Priority Pollutants	С	С					
Non-Halogenated Solvents	С	С	С		S		
Other Halogenated Organics					S		
Other Non-Halogenated Organics		С					

Toxics Cleanup Program Report Generated: 5/12/2024 Page 1 of 2



Petroleum Products-Unspecified

Polycyclic Aromatic Hydrocarbons

Contaminant

Petroleum-Diesel

Petroleum-Other

Petroleum-Gasoline

Phenolic Compounds

# Cleanup Site Details

Groundwater

С

С

С

S

Soil

S

С

С

С

S

С

alis	CI	eanup Sit	e ID: 3418
Surface Water	Sediment	Air	Bedrock
S			
С		S	
S		S	

S

B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level

RA - Remediated-Above RB - Remediated-Below

R - Remediated

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Hazard Assessment/Federal Site Inspection	Completed	3/21/1995	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
VCP Opinion on Remedial Investigation Work Plan	Canceled	4/21/1998	
VCP Opinion on Remedial Investigation Work Plan	Completed	6/26/1998	10/15/1999
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	4/30/2009
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	3/30/2018
Interim Action - Plan	Completed	7/31/2012	9/30/2012
Interim Action - Construction	Completed	9/30/2012	5/31/2016
Cleanup Action Plan	In Process	11/13/2018	