

## INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1859	Э.		FS ID:	34542387		Site ID	: 685	
SITE NAME	Fire	stone 3193	3					
SITE LOCATION	IINF	ORMATION						
Contact Person Name Title					Phone Number			
Mailing Address					City		Zip + 4	
205 Kirkland Ave					Kirkland 9803			
Site Location					Closest City	C	ounty	
205 Kirkland Av	/e				Kirkland			
Quarter-Quarter			Section		Township	Rai	nge	
Latitude:			Degree		Minute	See	cand	
Longitude:			Degree		Minute	Se	cond	
INSPECTION IN	FOR	MATION						
Inspection Date		<u> </u>		Inspe	ection Time	Type of Entry N	lotice	
Photographs	Yes	No		Weat	her: Clear	Partly Cloudy	Overcast	
Videotape	Yes	No		Preci	pitation	Temperature		
Samples	Yes	No		Wind	Direction	Wind Speed		
RECOMMENDA	TION							
No Further Actior	:							
Yes								
Release or threatened release does not pose a threat					Site Hazard Assessment			
No release or threatened release					Interim Action			
Educational Mailing					Emergency Action Plan			
Refer to another program/agency				Inde	Independent Cleanup Action			
					In Prog	ress	Completed	
CONTAMINANT	(S)	(See Page	3 for details)					
Soil	Yes	- <u>-</u>		.:.				
Groundwater	No		Heavy c	וו				
DEPARTMENT	REVI	EW				· .		
Investigator					Date			
Approved by		4				. 1 . 1.		
Unit Supervisor Aun Cu-					Date [[1]][í			
Section Manager					Date			
COMMENTS								
Notice of Pena	ltv fo	r dumpina o	crank case oil int	o storm draii	n. File is inc	omplete.	and a state of the	