

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 497306		FS ID:	FS ID : 87214792		Site ID: 8241		
SITE NAME	Bremi	meyer Loເ	gging Co				
SITE LOCATION	INFOF	RMATION					
Contact Person Name Title					Phone Number		
Mailing Address				City		Zip + 4	
27204 Kent-Kangley Rd				Rave	ensdale	98051	
Site Location			Close	st City	County		
27204 Kent-Kangley Rd				Rave	Ravensdale		
Quarter-Quarter Section			Towns	:hip	Range		
Latitude:		Degree	Minute	,	Second		
Longitude:	ngitude:		Degree	Minute)	Second	
INSPECTION IN	FORMA	TION					
Inspection Date				Inspection 1	ime Type of	Entry Notice	
Photographs	Yes	No		Weather:	Clear Partly Clo	oudy Overcast	
Videotape	Yes	No	-	Precipitation	n Temp	erature	
Samples	Yes	N o		Wind Directi	ion Wind	Speed	
RECOMMENDA	TION			į			
No Further Action	1;					·	
Yes	•		•				
Release or thre	eatened	release do	es not pose a threat	Site Hazar	Site Hazard Assessment		
No release or threatened release				Interim Ad	tion		
Educational Mailing				Emergenc	Emergency Action Plan		
Refer to another program/agency				Independe	Independent Cleanup Action		
					In Progress	Completed	
CONTAMINANT	(S) (S	See Page 3	for details)	-		·	
Soil	Yes		Coc PTI	EX, diesel			
Groundwater	No		Gas, DTI	LA, diesei			
DEPARTMENT I	REVIEW	/					
Investigator Date							
Approved by		,	1 6 6				
Unit Supervisor Awnell & h					Date ≥ /16/11		
Section Manager					Date		
COMMENTS							

Two USTs (gas, diesel) associated product lines, and dispensers were removed from this property in 1999. Approximately 150 cy of PCS were overexcavated and landfarmed on-site. Confirmation soil samples collected from the excavation indicated that soils were ND or below MTCA for gas, BTEX, kerosene, diesel, oil, and lead. No GW was encountered during excavation. No additional info in file.