



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 551244

FS ID: 2124

Site ID: 5283

SITE NAME Valspar Coatings

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number
Mailing Address		City Zip + 4
13535 Monster Rd S		Seattle 98178
Site Location		Closest City County
13535 Monster Rd S		Seattle
Quarter-Quarter	Section	Township Range
Latitude:	Degree	Minute Second
Longitude:	Degree	Minute Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	Solvent and alcohols. MEK, Toluene, acetate, diacetone/xtasolve ethanol
Groundwater	No	

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>[Signature]</i>	Date 3/22/11
Section Manager	Date

COMMENTS

Six USTs containing solvents and /or alcohols were removed from one excavation at this facility in 1999. Approximately 389 tons of PCS were overexcavated and disposed off-site at a concrete plant to be incorporated in concrete. Confirmation soil samples collected from the excavation indicated remaining soils were below VOCs and ethanol. GW samples from wells throughout the site and collected before UST removal indicated that the potential of GW impacts from the UST release was low. No additional info in file.



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 551244

FS ID: 2124

Site ID: 5283

SITE NAME Valspar Coatings
