




Pictometry, King County

This Historical Site Map delineates the extent of the subsurface area of contamination prior to the BSB soil-bentonite containment wall installation in 2011.



File ID 273-008
Date 6/18/18

FIGURE 2a
Historical Site Map