




Pictometry, King County

2022 Site Map delineates the extent of the subsurface contamination after the BSB soil-bentonite containment wall installation in 2011.



CLEAR CREEK ASSOCIATES

File ID 273-008
Date 6/18/18

FIGURE 2b
2022 Site Map