



February 7, 2022

HWA Project Number: 2019-054-21

Aegis Living  
415 118th Avenue SE  
Bellevue, Washington 98005

**ATTENTION:** Mr. Walter Braun  
(425)861-9993  
Walter.Braun@aegisliving.com

**SUBJECT: Volclay Plate Installation  
Aegis Kirkland  
21 – 10<sup>th</sup> Avenue South  
Kirkland, Washington**

Dear Mr. Braun:

At your request HWA Geosciences (HWA) has reviewed to following documents.

- A letter entitled “Confirmation of Altered Engineered Controls at the Following Cleanup Site per conditions defined in Letter from Washington Department of Ecology dated March 12, 2019” by Aegis Living, dated January 28, 2022.
- A report entitled “Vapor Assessment Report, Aegis Senior Living – Kirkland, 6700 Lake Washington Boulevard, Kirkland Washington 98033 Ecology VCP No. NW2850” by TCR Environmental Corporation, dated September 13, 2021.
- A document with as built drawings and photos entitled “Exhibit A, As-Built Details, Aegis Kirkland Phase II 1002 Lake Street South, Kirkland, Washington 98033” by Compass General Construction, LLC., dated January 12, 2022.

HWA was not present during any of the volclay barrier wall construction. However, HWA has reviewed the above referenced documents and based on the photos, laboratory data, and testaments provided; the volclay barrier appears to have been completed in accordance with the provided as-built detail.

Sincerely,

**HWA GEOSCIENCES INC.**

Michael S. Place, P.E.  
Senior Geotechnical Engineer