



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1735

FS ID: 41573749

Site ID: 3417

SITE NAME Rental service Corporation

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number
<i>Mailing Address</i>		
	<i>City</i>	<i>Zip + 4</i>
3409 Everett Ave	Everett	98201
<i>Site Location</i>		
	<i>Closest City</i>	<i>County</i>
3409 Everett Ave	Everett	
<i>Quarter-Quarter</i>		<i>Section</i>
<i>Latitude:</i>		<i>Township</i>
	<i>Degree</i>	<i>Minute</i>
<i>Longitude:</i>		<i>Range</i>
	<i>Degree</i>	<i>Second</i>

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
<i>Photographs</i> Yes No	<i>Weather:</i> Clear Partly Cloudy Overcast	
<i>Videotape</i> Yes No	<i>Precipitation</i>	<i>Temperature</i>
<i>Samples</i> Yes No	<i>Wind Direction</i>	<i>Wind Speed</i>

RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

<i>Soil</i>	Yes	TPH-G, BTEX, diesel
<i>Groundwater</i>	Unknown	

DEPARTMENT REVIEW

<i>Investigator</i>	<i>Date</i>
<i>Approved by</i>	
<i>Unit Supervisor</i> <i>RFC</i>	<i>Date</i> <i>5/30/11</i>
<i>Section Manager</i>	<i>Date</i>

COMMENTS

Two USTs (gas and diesel) were removed in 1989. 45 cy was removed and stored on site for aeration treatment. Two confirmation soil samples were collected from composites of (1) west sidewall and bottom, and (2) east sidewall and bottom. Results were below MTCA for TPH and BTEX. Stockpile was re-sampled in 1990 and was below MTCA for TPH and BTEX. GW was not mentioned.