

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 5349 FS ID: 53	734972	Site ID: 9800
SITE NAME Safety-Kleen Corp		
SITE LOCATION INFORMATION		
Contact Person Name Title	Phone Number	
Mailing Address	City	Zip + 4
6303 212th St SW Ste C	Lynnwood	98036
Site Location	Closest City	County
6303 212th St SW Ste C	Lynnwood	
Quarter-Quarter Section	Township	Range
Latitude: Degree	Minute	Second
Longitude: Degree	Minute	Second
INSPECTION INFORMATION	A STATE OF THE STA	
Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed
RECOMMENDATION		
No Further Action:		
No, missing documentation.		
Release or threatened release does not pose a threat	Site Hazard Assessment	
No release or threatened release	Interim Action	
Educational Mailing	Emergency Action Plan	
Refer to another program/agency	Independent Cleanup	Action
	In Progress	s Completed
CONTAMINANT(S) (See Page 3 for details)		
Soil Yes TDU		
Groundwater Unknown		
DEPARTMENT REVIEW	,	
Investigator	Date	
Approved by		
Unit Supervisor REC	Date 5/30/11	
Section Manager	Date	
COMMENTS		

No reports were included in UST file. A letter from SECOR dated 1/8/03 states that Ecology sent an NFA letter dated 3/6/02 after reviewing their site closure report (2/19/02). Ecology notes (7/13/94) state RCRA clean up underway. See RCRA file for reports and closure plan.