



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710327

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/16/2021 Vehicle# 483613 Volume
Payment Type Credit Account Container 483613
Manual Ticket# 1025917 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105060 lb*
In 08/14/2021 15:56:23	Front Scale	jvaldez		Tare	55460 lb*
Out 08/16/2021 15:56:23		jvaldez		Net	49600 lb
Comments					24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Prefix: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver or RP: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good vehicle condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTL** Truck/Chassis: **443-707200 487391**

Driver Name: **JEFF THOMAS** Driver Signature: *[Signature]*

Remarks: **# WDL 7R79G013B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710328

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/16/2021 Vehicle# 483678 Volume
Payment Type Credit Account Container 483678
Manual Ticket# 1025918 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104000 lb*
In 08/14/2021 15:57:40	Front Scale	jvaldez		Tare	53900 lb*
Out 08/16/2021 15:57:40		jvaldez		Net	50100 lb
Comments					25.05

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.05	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.05	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Prefix: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver or RP: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good vehicle condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTL** Truck/Chassis: **444-743140**

Driver Name: **BRUCE BARNETT** Driver Signature: *[Signature]*

Remarks: **WDL 7R72A793B**

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-8512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH

Contact Person: _____
Telephone Number: _____

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Delivery to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-8512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Trailer # 441/107206/483-678-6

Driver Name: Arthur Egger Driver Signature: _____

Remarks: LF 49,620



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710329

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/16/2021 Vehicle# 483790 Volume
Payment Type Credit Account Container# 483790
Manual Ticket# 1025919 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101840 lb*
In 08/14/2021 15:58:48	Front Scale	jvaldez		Tare	54620 lb*
Out 08/16/2021 15:58:48		jvaldez		Net	47220 lb
Comments					23.61

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.61	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.61	Tons				WA-BELLEVUE

Driver's Signature _____

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-8512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH

Contact Person: _____
Telephone Number: _____

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Delivery to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-8512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Trailer # 443-702200-483790

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks: # WDL7R795013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710330

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/16/2021 Vehicle# 483187 Volume
Payment Type Credit Account Container# 483187
Manual Ticket# 1025772 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103080 lb*
In 08/13/2021 16:00:16	Front Scale	jvaldez		Tare	53280 lb*
Out 08/16/2021 16:00:16		jvaldez		Net	49800 lb
Comments					24.90

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.90	Tons				WA-BELLEVUE

Driver's Signature _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710506

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/17/2021 Vehicle# 480572 Volume
Payment Type Credit Account Container 480572
Manual Ticket# 1026111 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105380 lb*
In 08/14/2021 14:53:32	MANUAL WT	vmckinne		Tare	54560 lb*
Out 08/17/2021 14:53:32		vmckinne		Net	58220 lb
Comments				* Manual Weight	Tons 25.41

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.41	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		25.41	Tons				

Driver's Signature

DATE: 8/13/21 CONTAINER: 483187

SCD NE 8TH LLC

WASTE TYPE: CONTAMINATED SOIL

PROFILE: 115787WA EXP. DATE: 2/28/22

DAILY COVER: _____

CO-MINGLE: X

SEGREGATE: _____

NON FRIABLE CO-MINGLE: _____

FRIABLE GRID AREA: _____

RELEASE NAME: AE DATE: 8/13/21

COMMENTS:

sh
No bill of lading for this load
when paperwork was submitted



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710720

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483664 Volume
Payment Type Credit Account Container 483664
Manual Ticket# 1026020 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105840 lb*
In 08/16/2021 11:06:08	Front Scale	jvaldez		Tare	53980 lb*
Out 08/18/2021 11:06:08		jvaldez		Net	51860 lb
Comments				* Manual Weight	Tons 25.93

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		25.93	Tons				

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-137WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Keep in good vented condition Yes No
Container in good condition Yes No
No fire standing near Yes No
Container is empty and clean Yes No

TICKET ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTE Truck/Trailer # 44-743140

Driver Name: BURR BOWETT Driver Signature: [Signature]

Remarks: WM 27222793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710724

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483767 Volume
Payment Type Credit Account Container 483767
Manual Ticket# 1026021 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106240 lb*
In 08/16/2021 11:07:37	Front Scale	jvaldez		Tare	56500 lb*
Out 08/18/2021 11:07:37		jvaldez		Net	49740 lb
Comments					24.87
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.87	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.87	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup 8-18-2021
Time scheduled for pickup 8:00 AM

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition
Container in good condition
No floor standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # 583664 Lanes 0 1 2 Start Time _____
End Time _____ Box # 0 Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 4HS/WM 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: Devr Lic 3219 BJ 43 B -WA
exp 731.747



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710724

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483781 Volume
Payment Type Credit Account Container 483781
Manual Ticket# 1026022 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103640 lb*
In 08/16/2021 11:09:11	Front Scale	jvaldez		Tare	54180 lb*
Out 08/18/2021 11:09:11		jvaldez		Net	49460 lb
Comments					24.73
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition
Container in good condition
No floor standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 4HS/WM 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: Lt. 49,720



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710726

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483791 Volume
Payment Type Credit Account Container# 483791
Manual Ticket# 1026023 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105040 lb*
In 08/16/2021 11:10:12	Front Scale	jvaldez		Tare	54760 lb*
Out 08/18/2021 11:10:12		jvaldez		Net	50280 lb
Comments					25.14
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.14	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.14	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Fasteners in good condition: Yes No
No free standing water: Yes No
Container in proper and clean: Yes No

Units: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # to: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # of: _____ Lines 0 1 2 End Time: _____

Transporter Name: **CTI** Truck Class: **443-707200-483781**

Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks:
WDL 7R79G013B

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Fasteners in good condition: Yes No
No free standing water: Yes No
Container in proper and clean: Yes No

Units: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # to: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # of: _____ Lines 0 1 2 End Time: _____

Transporter Name: **CTI** Truck Class: **441/707200/483791**

Driver Name: **Arthur Egan** Driver Signature: *[Signature]*

Remarks:
L# 49, 5201120



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710728

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/18/2021 Vehicle# 480658 Volume
Payment Type Credit Account Container# 480658
Manual Ticket# 1026134 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105500 lb*
In 08/17/2021 11:12:57	Front Scale	jvaldez		Tare	54440 lb*
Out 08/18/2021 11:12:57		jvaldez		Net	51060 lb
Comments					25.53
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.53	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.53	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710729

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/18/2021 Vehicle# 480664 Volume
Payment Type Credit Account Container 480664
Manual Ticket# 1026135 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103600 lb*
In 08/17/2021 11:14:30	Front Scale	jvaldez		Tare	53760 lb*
Out 08/18/2021 11:14:30		jvaldez		Net	49840 lb
Comments				* Manual Weight	Tons 24.92

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.92	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Leading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 443-707200 480658

Driver Name: Jeff Thomas Driver Signature: _____

Remarks: 48240
WBL 7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710730

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483023 Volume
Payment Type Credit Account Container 483023
Manual Ticket# 1026135 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107700 lb*
In 08/17/2021 11:16:01	Front Scale	jvaldez		Tare	57220 lb*
Out 08/18/2021 11:16:01		jvaldez		Net	50480 lb
Comments				* Manual Weight	Tons 25.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.24	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.24	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 8-16-2021
Time scheduled for pickup 2:00 pm

Generator Name and Leading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 430664 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 445 / Wm 793136

Driver Name: John Michael Driver Signature: _____

Remarks: _____

Driver Lic: 3213 BT 43 B - WA
exp 7-1-2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710731

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483084 Volume
Payment Type Credit Account Container# 483084
Manual Ticket# 1026137 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107440 lb*
In 08/17/2021 11:18:07	Front Scale	jvaldez		Tare	57140 lb*
Out 08/18/2021 11:18:07		jvaldez		Net	50300 lb
Comments				* Manual Weight	Tons 25.15

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.15	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.15	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 8/16/2021
Time scheduled for pickup noon

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 483084

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In 483023 Lines # 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name CTI Truck/Trailer # 445 / WM 74316

Driver Name Jason Michaels Driver Signature [Signature]

Remarks:
Driver Note
3213 B-T 43.B - WA
exp 7/1/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710732

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483164 Volume
Payment Type Credit Account Container# 483164
Manual Ticket# 1026138 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103600 lb*
In 08/17/2021 11:19:56	Front Scale	jvaldez		Tare	53680 lb*
Out 08/18/2021 11:19:56		jvaldez		Net	49920 lb
Comments				* Manual Weight	Tons 24.96

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.96	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.96	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 8-16-21
Time scheduled for pickup

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lines # 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name CTI Truck/Trailer # 440-701287-483084

Driver Name Scott F Hogan Driver Signature [Signature]

Remarks:
WPL 71122138
GW: 50.060

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 8-16-21
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Front Park South International Facility - 18023 Van
412 South Bureau Lane
Beaverton, Oregon 97005
Phone: (503) 545-1200 or 503-274-7644

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading:
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 442-702887-483164
Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks:
LDL # 77122213B
LTWT 48.600



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710733

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 08/18/2021 Vehicle#: 483318 Volume:
Payment Type: Credit Account Container: 483318
Manual Ticket#: 1026139 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105680 lb*
In 08/17/2021 11:21:26	Front Scale	jvaldez		Tare	55300 lb*
Out 08/18/2021 11:21:26		jvaldez		Net	50380 lb
Comments: * Manual Weight					25.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.19	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.19	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Front Park South International Facility - 18023 Van
412 South Bureau Lane
Beaverton, Oregon 97005
Phone: (503) 545-1200 or 503-274-7644

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading:
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 443-2072 00 483318
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks:
* Hole BOTTOM CONTAINER *
WDL2R29G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710734

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 08/18/2021 Vehicle#: 483343 Volume:
Payment Type: Credit Account Container: 483343
Manual Ticket#: 1026140 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102340 lb*
In 08/17/2021 11:22:47	Front Scale	jvaldez		Tare	55400 lb*
Out 08/18/2021 11:22:47		jvaldez		Net	46940 lb
Comments: * Manual Weight					23.47

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.47	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	23.47	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: **LFO1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **444-743140**

Driver Name: **MIKE BARNETT** Driver Signature: *[Signature]*

Remarks: **WV 71122-593B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710735

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483359 Volume
Payment Type Credit Account Container 483359
Manual Ticket# 1026141 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107000 lb*
In 08/17/2021 11:24:18	Front Scale	jvaldez		Tare	54580 lb*
Out 08/18/2021 11:24:18		jvaldez		Net	52420 lb
Comments					26.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.21	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.21	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **8/16/2021**
Time scheduled for pickup **8:00 AM**

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: **LFO1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: **483359** Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **445 / WV 743136**

Driver Name: **Jason Michaels** Driver Signature: *[Signature]*

Remarks: **Driver Lic 3213 25 43 B -WA- Exp 7.31.2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 710735

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/18/2021 Vehicle# 483465 Volume
Payment Type Credit Account Container 483465
Manual Ticket# 1026142 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106180 lb*
In 08/17/2021 11:27:36	Front Scale	jvaldez		Tare	55340 lb*
Out 08/18/2021 11:27:36		jvaldez		Net	50840 lb
Comments					25.42

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.42	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.42	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 8/11/2021
Time scheduled for pickup: 8:00 AM

Customer Name and Loading Address: SCD NE 8TH
Waste Profile: LUS-7B7WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tap is good service condition	<input type="checkbox"/>	No	<input type="checkbox"/>
Container is in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 480438 Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 445/43136
Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____

Driver # 3213 BT 433 - 108
Exp 7/2/2027

WM
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint Ticket# 711155

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 480
Ticket Date: 08/20/2021 Vehicle#: 480549 Volume:
Payment Type: Credit Account Container: 480549
Manual Ticket#: 1025771 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time: In 08/13/2021 10:30:47 Scale: MANUAL WT Operator: vmckinne Inbound Gross: 102400 lb*
Out 08/20/2021 10:30:47 Tare: 53160 lb*
Net: 49240 lb*
Comments: * Manual Weight Tons: 24.62

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.62	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.62	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Customer Name and Loading Address: SCD NE 8TH
Waste Profile: LUS-7B7WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tap is good service condition	<input type="checkbox"/>	No	<input type="checkbox"/>
Container is in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 441/707206/480549
Driver Name: Arthur Pappalardo Driver Signature: _____

Remarks: Lt. 48, 920163

WM
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint Ticket# 711156

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 08/20/2021 Vehicle#: 483135 Volume:
Payment Type: Credit Account Container: 483135
Manual Ticket#: 1025771 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time: In 08/13/2021 10:32:26 Scale: MANUAL WT Operator: vmckinne Inbound Gross: 104200 lb*
Out 08/20/2021 10:32:26 Tare: 61320 lb*
Net: 42880 lb*
Comments: * Manual Weight Tons: 21.44

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		21.44	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	21.44	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711157

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/20/2021 Vehicle# 483337 Volume
Payment Type Credit Account Container 483337
Manual Ticket# 1025776 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105000 lb*
In 08/13/2021 10:33:12	MANUAL WT	vmckinne		Tare	59840 lb*
Out 08/20/2021 10:33:12		vmckinne		Net	45160 lb
Comments				* Manual Weight	Tons 22.58

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	22.58	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.58	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

DISPOSAL FACILITY: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container is empty and clean:

TRUCK ONLY: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Lines 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis: 442-707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 48 3135



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711158

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/20/2021 Vehicle# 483699 Volume
Payment Type Credit Account Container 483699
Manual Ticket# 1025776 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104800 lb*
In 08/13/2021 10:34:26	MANUAL WT	vmckinne		Tare	55780 lb*
Out 08/20/2021 10:34:26		vmckinne		Net	49020 lb
Comments				* Manual Weight	Tons 24.51

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.51	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.51	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

DISPOSAL FACILITY: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container is empty and clean:

TRUCK ONLY: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis: 443-707200-483377
Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks: LIGHT # 49700
WIL7R79G013B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Contact Person _____
Telephone Number _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading
 Company Name _____ Date _____
 Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Contents in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
 Start Time _____ Box # In _____ Unloading _____
 End Time _____ Box # Out _____ Lines 0 1 2 Start Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**

Driver Name: **Brendan Osborne** Driver Signature: *Brendan Osborne*

Remarks: **Can # 493699**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711159

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 08/20/2021 Vehicle# 483820 Volume
 Payment Type Credit Account Container 483820
 Manual Ticket# 1025779 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/13/2021 10:35:19 Scale Operator Inbound Gross 104140 lb*
 Out 08/20/2021 10:35:19 MANUAL WT vmckinne Tare 54400 lb*
 Comments * Manual Weight Net 49740 lb
 Tons 24.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.87	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.87	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **8-11-21**
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Contact Person _____
Telephone Number _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading
 Company Name _____ Date _____
 Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97112-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Contents in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
 Start Time _____ Box # In _____ Unloading _____
 End Time _____ Box # Out _____ Lines 0 1 2 Start Time _____

Transporter Name: **CTI** Truck/Trailer # **440-701387-493820**

Driver Name: **Scott F Hogan** Driver Signature: *Scott F Hogan*

Remarks: **WDL # TIT 22213 B Linc 49570**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711349

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
 Ticket Date 08/22/2021 Vehicle# 405008 Volume
 Payment Type Credit Account Container 405008
 Manual Ticket# 102637 Billing # 0002819
 Hauling Ticket# Manifest na
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/20/2021 09:04:24 Scale Operator Inbound Gross 89880 lb*
 Out 08/22/2021 09:04:24 Front Scale jvaldez Tare 50100 lb*
 Comments * Manual Weight Net 39780 lb
 Tons 19.89

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		19.89	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	19.89	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711350

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 08/22/2021 Vehicle# 400501 Volume
Payment Type Credit Account Container 400501
Manual Ticket# 1026333 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97120 lb*
In 08/20/2021 09:06:04	Front Scale	jvaldez		Tare	49460 lb*
Out 08/22/2021 09:06:04		jvaldez		Net	47660 lb
Comments				* Manual Weight	Tons 23.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.83	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.83	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-18-21
Time scheduled for pickup 7:25 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time: _____ Box # In: _____ Lines 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 440-707287-405008

Driver Name: Scott F Hoan Driver Signature: [Signature]

Remarks:
WDL 7T22213B LT.WT 45,660



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711351

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/22/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1026333 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103380 lb*
In 08/20/2021 09:07:49	Front Scale	jvaldez		Tare	53000 lb*
Out 08/22/2021 09:07:49		jvaldez		Net	50380 lb
Comments				* Manual Weight	Tons 25.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.19	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-19-2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time: _____ Box # In: 400501 Lines 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 245 + WA 743136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks:
Driver Lic # 3213 BJ 43 B-WA
WT 731 242 Tare 46380



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711582

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/23/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1026334 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98800 lb*
In 08/20/2021 10:00:43	MANUAL WT	jvaldez		Tare	53240 lb*
Out 08/23/2021 10:00:43		jvaldez		Net	45560 lb
Comments				* Manual Weight	Tons 22.78

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.78	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		22.78	Tons				

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane Columbia Ridge Landfill and Recycling Center
Arlington, Oregon 97812-6512 (541) 454-2030

Container Inspection Upon Pickup:
Empty in good sanitary condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis: 441-707206/4050110-1
Driver Name: Arthur Equino Driver Signature: _____

Remarks: LT 45,760



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711584

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/23/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1026335 Billing # 0002819
Hauling Ticket# Manifest na
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98160 lb*
In 08/20/2021 10:01:48	MANUAL WT	jvaldez		Tare	49840 lb*
Out 08/23/2021 10:01:48		jvaldez		Net	48320 lb
Comments				* Manual Weight	Tons 24.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.16	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-18-21
Time scheduled for pickup 100 PM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane Columbia Ridge Landfill and Recycling Center
Arlington, Oregon 97812-6512 (541) 454-2030

Container Inspection Upon Pickup:
Empty in good sanitary condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis: 440-707287-405004
Driver Name: SCOTT F HOGAN Driver Signature: _____

Remarks: WPL # TIT222130 LTWT. 45.720



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711585

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 08/23/2021 Vehicle# 484018 Volume
Payment Type Credit Account Container 484018
Manual Ticket# 1026346 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103760 lb*
In 08/20/2021 10:03:10	MANUAL WT	jvaldez		Tare	54440 lb*
Out 08/23/2021 10:03:10		jvaldez		Net	49320 lb
Comments				* Manual Weight	Tons 24.66

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.66	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.66	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **US-7B7WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Office: 18177 Cedar Springs Lane, Arlington, OR 97812-0512
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-0512

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container accepted and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Line: 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Classif: **442 / 707270**
Driver Name: **Brendan Osborne** Driver Signature: *Brendan Osborne*

Remarks:
CG# 405005



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711586

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/23/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container 405011
Manual Ticket# 1026339 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97660 lb*
In 08/20/2021 10:04:15	MANUAL WT	jvaldez		Tare	51300 lb*
Out 08/23/2021 10:04:15		jvaldez		Net	46360 lb
Comments				* Manual Weight	Tons 23.18

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.18	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.18	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **US-7B7WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Office: 18177 Cedar Springs Lane, Arlington, OR 97812-0512
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-0512

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container accepted and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Classif: **441 / 707206 / #441080**
Driver Name: **Anthony Egge** Driver Signature: *Anthony Egge*

Remarks:
49,300 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711587

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/23/2021 Vehicle# 405003 Volume
Payment Type Credit Account Container 405003
Manual Ticket# 1026450 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/20/2021 10:05:17 Scale MANUAL WT Operator jvaldez Inbound Gross 93620 lb*
Out 08/23/2021 10:05:17 jvaldez Tare 47940 lb*
Comments * Manual Weight Net 45680 lb
Tons 22.84

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.84	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.84	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-18-2021
Time scheduled for pickup 2:00 pm

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Inspection Upon Pickup:
Empty in good serviceable condition
Container in good condition
No fire standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Unloading
Start Time: 4:05:01 Box # In: 1 Lanes: 0 1 2 Start Time
End Time: 4:45 Box # Out: 1 Lanes: 0 1 2 End Time

Transporter Name: CTI Truck/Chassis # 445-WM 743136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Dry Lic
3213 3543 B - WM
08/23/21 4:27



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711588

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/23/2021 Vehicle# 480509 Volume
Payment Type Credit Account Container 480509
Manual Ticket# 1026467 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/21/2021 10:06:29 Scale MANUAL WT Operator jvaldez Inbound Gross 103320 lb*
Out 08/23/2021 10:06:29 jvaldez Tare 53840 lb*
Comments * Manual Weight Net 49480 lb
Tons 24.74

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.74	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Inspection Upon Pickup:
Empty in good serviceable condition
Container in good condition
No fire standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Unloading
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time

Transporter Name: CTI Truck/Chassis # 443-7072-00 405003

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: # WDL 7 R79013P



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711592

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/23/2021 Vehicle# 480561 Volume
Payment Type Credit Account Container 480561
Manual Ticket# 1026468 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104460 lb*
In 08/23/2021 10:07:31	MANUAL WT	jvaldez		Tare	54900 lb*
Out 08/23/2021 10:07:31		jvaldez		Net	49560 lb
Comments				* Manual Weight	Tons 24.78

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.78	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.78	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8/19/2021
Time scheduled for pickup noon

Generator Name and Loading Address: SCD NE 8TH
Waste Type: CDL Contaminated Soil Asbestos Other LF01
Waste Profile: US-787WA

Contact Person: _____ Telephone Number: _____

Acknowledgment of Loading: _____ Date: _____
Signature: _____ Name: _____

Customer Inspection Upon Pickup:
Eggs in good service condition: No Yes
Container in good condition: No Yes
No free standing water: No Yes
Container empty and clean: No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In 480509 Lanes 0/1 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
Transporter Name: CTI Truck Class: 4415 + w/m 743136
Driver Name: Jason Michaels Driver Signature: _____
Remarks: Driver Le 3213 BT 43 B -WA 11/7 B 2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711592

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/23/2021 Vehicle# 483125 Volume
Payment Type Credit Account Container 483125
Manual Ticket# 1026469 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100260 lb*
In 08/21/2021 10:08:32	MANUAL WT	jvaldez		Tare	50840 lb*
Out 08/23/2021 10:08:32		jvaldez		Net	49420 lb
Comments				* Manual Weight	Tons 24.71

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.71	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.71	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Type: CDL Contaminated Soil Asbestos Other LF01
Waste Profile: US-787WA

Contact Person: _____ Telephone Number: _____

Acknowledgment of Loading: _____ Date: _____
Signature: _____ Name: _____

Customer Inspection Upon Pickup:
Eggs in good service condition: No Yes
Container in good condition: No Yes
No free standing water: No Yes
Container empty and clean: No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
Transporter Name: CTI Truck Class: 44R 707270
Driver Name: Brendan Osborne Driver Signature: _____
Remarks: can # 480561



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711594

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/23/2021 Vehicle# 483849 Volume
Payment Type Credit Account Container 483849
Manual Ticket# 1026474 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104040 lb*
In 08/21/2021 10:09:37	MANUAL WT	jvaldez		Tare	54280 lb*
Out 08/23/2021 10:09:37		jvaldez		Net	49760 lb
Comments				* Manual Weight	Tons
					24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.88	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-19-21
Time scheduled for pickup 11:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Customer Inspection Upon Pickup:
Dry in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # H40-70187-483125

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: WDL # 71122213B WT 48,580

Need new tarp + stars



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711595

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 08/23/2021 Vehicle# 490019 Volume
Payment Type Credit Account Container 490019
Manual Ticket# 1026475 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103040 lb*
In 08/21/2021 10:11:01	MANUAL WT	jvaldez		Tare	52920 lb*
Out 08/23/2021 10:11:01		jvaldez		Net	50120 lb
Comments				* Manual Weight	Tons
					25.06

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.06	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.06	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Customer Inspection Upon Pickup:
Dry in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-707200 483849

Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: WDL # 71122213B WT 48,580



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711807

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483980 Volume
Payment Type Credit Account Container 483980
Manual Ticket# 1026145 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103060 lb*
In 08/17/2021 09:25:49	Front Scale	jvaldez		Tare	53460 lb*
Out 08/24/2021 09:25:49		jvaldez		Net	49600 lb
Comments					24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		24.80	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-24512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No
CONT 490019

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
Transporter Name: C.T.E. Truck Class: 444-743140
Driver Name: PAUL BARNETT Driver Signature: [Signature]
Remarks: WJL 071227193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711808

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/24/2021 Vehicle# 480524 Volume
Payment Type Credit Account Container 480524
Manual Ticket# 1026224 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102840 lb*
In 08/18/2021 09:27:09	Front Scale	jvaldez		Tare	53340 lb*
Out 08/24/2021 09:27:09		jvaldez		Net	49500 lb
Comments					24.75

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.75	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.75	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-24512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No
CONT 483820

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
Transporter Name: C.T.E. Truck Class: 444-743140
Driver Name: PAUL BARNETT Driver Signature: [Signature]
Remarks: WJL 071227193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711809

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 08/24/2021 Vehicle# 400159 Volume
Payment Type Credit Account Container 400159
Manual Ticket# 1026332 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96600 lb*
In 08/20/2021 09:28:27	Front Scale	jvaldez		Tare	49860 lb*
Out 08/24/2021 09:28:27		jvaldez		Net	46740 lb
Comments					23.37

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.37	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.37	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatch Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Empty in good condition	Yes	No
Container in good condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No Box standing water	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:

Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTE** Truck Chassis: **444-743140**

Driver Name: **EMIL BARNETT** Driver Signature: *[Signature]*

Remarks: **W1127111933**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711812

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container 405007
Manual Ticket# 1026336 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97340 lb*
In 08/20/2021 09:36:45	Back Scale	jvaldez		Tare	50800 lb*
Out 08/24/2021 09:36:45		jvaldez		Net	46540 lb
Comments					23.27

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.27	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.27	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatch Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Empty in good condition	Yes	No
Container in good condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No Box standing water	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:

Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: **CTE** Truck Chassis: **444-743140**

Driver Name: **EMIL BARNETT** Driver Signature: *[Signature]*

Remarks: **W1127111933**

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97102-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFOI

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Waste Profile #: _____

Container Inspection Upon Pickup:
Tarp is good serviceable condition: Yes No
Container is in good condition: Yes No
No fuel standing in tank: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 443-702200 405007

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: # WDL 7R 79408B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711813

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1026338 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LFOI - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 97700 lb*
In 08/20/2021 09:38:29 Front Scale jvaldez Tare 50540 lb*
Out 08/24/2021 09:38:29 jvaldez Net 47160 lb
Comments * Manual Weight Tons 23.58

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.58	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.58	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97102-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFOI

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Waste Profile #: _____

Container Inspection Upon Pickup:
Tarp is good serviceable condition: Yes No
Container is in good condition: Yes No
No fuel standing in tank: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 4111782204/405009-8

Driver Name: Arthur Egger Driver Signature: [Signature]

Remarks: LT 45,900lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711814

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405012 Volume
Payment Type Credit Account Container 405012
Manual Ticket# 1026340 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LFOI - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 97780 lb*
In 08/20/2021 09:39:35 Front Scale jvaldez Tare 51040 lb*
Out 08/24/2021 09:39:35 jvaldez Net 46740 lb
Comments * Manual Weight Tons 23.37

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.37	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.37	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711815

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container 405013
Manual Ticket# 1026341 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/20/2021 09:41:14 Scale Front Scale Operator Inbound Gross 93680 lb*
Out 08/24/2021 09:41:14 jvaldez jvaldez Tare 47820 lb*
Comments * Manual Weight Net 45860 lb
Tons 22.93

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.93	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Container Inspection Upon Pickup:
 Tap in good sanitary condition
 Container is in good condition
 No free standing water
 Container is empty and clean

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTF
 Truck/Chassis #: 440-707287-405013

Driver Name: SCOTT F HOGAN
 Driver Signature: [Signature]

Remarks: WDL JTJ2213B LT.Wt. 45,490



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711816

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405014 Volume
Payment Type Credit Account Container 405014
Manual Ticket# 1026342 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/20/2021 09:42:23 Scale Front Scale Operator Inbound Gross 96720 lb*
Out 08/24/2021 09:42:23 jvaldez jvaldez Tare 50060 lb*
Comments * Manual Weight Net 46660 lb
Tons 23.33

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.33	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.33	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup 8-14-21
Time scheduled for pickup 9:30

Customer Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Container Inspection Upon Pickup:
 Tap in good sanitary condition
 Container is in good condition
 No free standing water
 Container is empty and clean

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTF
 Truck/Chassis #: 440-707287-405013

Driver Name: SCOTT F HOGAN
 Driver Signature: [Signature]

Remarks: WDL JTJ2213B LT.Wt. 45,490



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711817

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/24/2021 Vehicle# 405019 Volume
Payment Type Credit Account Container 405019
Manual Ticket# 1026344 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98160 lb*
In 08/20/2021 09:43:29	Front Scale	jvaldez		Tare	50200 lb*
Out 08/24/2021 09:43:29		jvaldez		Net	47960 lb
Comments				* Manual Weight	Tons 23.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.98	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.98	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Concession Name and Loading Address: **SCD NE 8TH**
Waste Profile: **US-787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatcher: _____ Dispatch Facility: _____

Container Inspection Upon Pickup:

Easy to pull with a scale condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No feet standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: **CTI** Track Class: **444-743/140**

Driver Name: **BRUCE BARNETT** Driver Signature: *[Signature]*

Remarks: **WOL 21177493B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711818

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483191 Volume
Payment Type Credit Account Container 483191
Manual Ticket# 1026470 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102920 lb*
In 08/21/2021 09:47:08	Front Scale	jvaldez		Tare	53540 lb*
Out 08/24/2021 09:47:08		jvaldez		Net	49380 lb
Comments				* Manual Weight	Tons 24.69

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.69	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.69	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: **8/18/2021**
Time scheduled for pickup: **10:00 AM**

Concession Name and Loading Address: **SCD NE 8TH**
Waste Profile: **US-787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatcher: _____ Dispatch Facility: _____

Container Inspection Upon Pickup:

Easy to pull with a scale condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No feet standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: **405019** Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: **CTI** Track Class: **445 + Wm 743136**

Driver Name: **JOSEPH MICHAELS** Driver Signature: *[Signature]*

Remarks: **Dr Lic # 3213 BT 493B -WA**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711819

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483484 Volume
Payment Type Credit Account Container 483484
Manual Ticket# 1026471 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*
In 08/21/2021 09:48:24	Front Scale	jvaldez		Tare	55380 lb*
Out 08/24/2021 09:48:24		jvaldez		Net	49860 lb
Comments					24.93
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.93	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Delivery to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
 Easy to load/unload condition
 Container in good condition
 No fire standing water
 Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Track #/Chassis # **942/707270**

Driver Name: **Brandon Osborne** Driver Signature: *Brandon Osborne*

Remarks: **Can # 483191**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711820

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483697 Volume
Payment Type Credit Account Container 483697
Manual Ticket# 1026472 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103440 lb*
In 08/21/2021 09:49:51	Front Scale	jvaldez		Tare	54360 lb*
Out 08/24/2021 09:49:51		jvaldez		Net	49090 lb
Comments					24.54
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.54	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.54	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9-15-21**
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Delivery to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
 Easy to load/unload condition
 Container in good condition
 No fire standing water
 Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Track #/Chassis # **940-707837-483484**

Driver Name: **SCOTT F HIGGINS** Driver Signature: *Scott F Higgins*

Remarks: **WDL # 711222130 LWA**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711821

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483726 Volume
Payment Type Credit Account Container 483726
Manual Ticket# 1026473 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103240 lb*
In 08/21/2021 09:51:08	Front Scale	jvaldez		Tare	53540 lb*
Out 08/24/2021 09:51:08		jvaldez		Net	49700 lb
Comments					24.85

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.85	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.85	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115-787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good working condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: DTI Truck/Trailer # 444-707231/483697-6
Driver Name: ARTHUR EGRAK Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711822

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/24/2021 Vehicle# 480581 Volume
Payment Type Credit Account Container 480581
Manual Ticket# 1026654 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103900 lb*
In 08/21/2021 09:52:27	Front Scale	jvaldez		Tare	53580 lb*
Out 08/24/2021 09:52:27		jvaldez		Net	50320 lb
Comments					25.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.16	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.16	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115-787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good working condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: DTI Truck/Trailer # 444-743140
Driver Name: ALEX BARNETT Driver Signature: _____

Remarks: WH 772-7793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711823

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/24/2021 Vehicle# 480669 Volume
Payment Type Credit Account Container# 480669
Manual Ticket# 1026563 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102820 lb*
In 08/23/2021 09:59:10	Front Scale	jvaldez		Tare	53640 lb*
Out 08/24/2021 09:59:10		jvaldez		Net	49180 lb
Comments				* Manual Weight	Tons 24.59

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.59	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.59	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is tied with a ratchet condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWLP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 | 1 | 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 443-207200 460581

Driver Name: Jeff Thomas Driver Signature: _____

Remarks:
NDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711824

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483015 Volume
Payment Type Credit Account Container# 483015
Manual Ticket# 1026564 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106100 lb*
In 08/23/2021 10:00:18	Front Scale	jvaldez		Tare	56040 lb*
Out 08/24/2021 10:00:18		jvaldez		Net	50060 lb
Comments				* Manual Weight	Tons 25.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is tied with a ratchet condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWLP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 | 1 | 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 442-1707270

Driver Name: Brandon Osborne Driver Signature: _____

Remarks:
can # 480 669



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711825

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483441 Volume
Payment Type Credit Account Container 483441
Manual Ticket# 1026565 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104100 lb*
In 08/23/2021 10:01:18	Front Scale	jvaldez		Tare	54040 lb*
Out 08/24/2021 10:01:18		jvaldez		Net	50060 lb
Comments				* Manual Weight	Tons 25.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concrete Name and Loading Address: **SCD NE 8TH** Waste Profile #: **US7B7WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Debris or Oil: Yes No
Empty in good serviceable condition: Yes No
Container in good condition: Yes No
No floor standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis #: **444/702206/483015**
Driver Name: **Paula Barnett** Driver Signature: _____

Remarks: **Lt 50,540**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711829

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483885 Volume
Payment Type Credit Account Container 483885
Manual Ticket# 1026567 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106160 lb*
In 08/16/2021 10:15:41	Front Scale	jvaldez		Tare	54400 lb*
Out 08/24/2021 10:15:41		jvaldez		Net	51760 lb
Comments				* Manual Weight	Tons 25.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				
3 RAIL T SPW-RAIL BY 100		25.88	Tons				

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concrete Name and Loading Address: **SCD NE 8TH** Waste Profile #: **US7B7WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Debris or Oil: Yes No
Empty in good serviceable condition: Yes No
Container in good condition: Yes No
No floor standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis #: **444/743140**
Driver Name: **PAULA BARNETT** Driver Signature: _____

Remarks: **WDL 9167, 15933**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 711831

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/24/2021 Vehicle# 483725 Volume
Payment Type Credit Account Container 483725
Manual Ticket# 1026675 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104520 lb*
In 08/24/2021 10:24:59	Back Scale	jvaldez		Tare	54540 lb*
Out 08/24/2021 10:24:59	Front Scale	jvaldez		Net	49980 lb
Comments					24.99
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.99	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.99	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-19-2021
Time scheduled for pickup 10:10 AM

Concree Name and Loading Address: SCD NE 8TH Waste Profile: US-7B7WA

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: LF01

Customer Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483886 Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 445 + W/M 743136

Driver Name: Jason Mitchell Driver Signature: _____

Remarks:
Driver Lic
3213 BT 43 B -wt-
Exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712039

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/25/2021 Vehicle# 480626 Volume
Payment Type Credit Account Container 480626
Manual Ticket# 1026345 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105440 lb*
In 08/20/2021 09:32:03	Front Scale	jvaldez		Tare	54600 lb*
Out 08/25/2021 09:32:03	Front Scale	jvaldez		Net	50840 lb
Comments					25.42
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.42	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.42	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concree Name and Loading Address: SCD NE 8TH Waste Profile: US-7B7WA

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: LF01

Customer Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-707200 463785

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks:
WGTT
49900
WDL7R79G01BB

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address:
SCD NE 8TH

Waste Profile: **115-7874A**

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver's Signature: *Arthur Eggen*

Remarks: **49,200 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712042

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 08/25/2021 Vehicle# 483810 Volume
 Payment Type Credit Account Container 483810
 Manual Ticket# 1026455 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103760 lb*
In 08/20/2021 09:33:20	Front Scale	jvaldez		Tare	54000 lb*
Out 08/25/2021 09:33:20		jvaldez		Net	49760 lb
Comments					24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.88	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.88	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: **9-10-21**
Time scheduled for pickup: _____

Generator Name and Loading Address:
SCD NE 8TH

Waste Profile: **115-7874A**

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver's Signature: *Scott F Hogan*

Remarks: **WDL 771222138 340**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712043

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
 Ticket Date 08/25/2021 Vehicle# 405017 Volume
 Payment Type Credit Account Container 405017
 Manual Ticket# 1026669 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97000 lb*
In 08/24/2021 09:34:31	Front Scale	jvaldez		Tare	49600 lb*
Out 08/25/2021 09:34:31		jvaldez		Net	47400 lb
Comments					23.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.70	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	23.70	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712044

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/25/2021 Vehicle# 480603 Volume
Payment Type Credit Account Container# 480603
Manual Ticket# 1026670 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/24/2021 09:35:46 Scale Operator Inbound Gross
Out 08/25/2021 09:35:46 Front Scale jvaldez jvaldez Tare
25.38 Tons 52060 lb*
Comments * Manual Weight Net 50760 lb*
Tons 25.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.38	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup
Time scheduled for pickup

Consignee Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFD1**

Container Inspection Upon Pickup:
Ramp in good working condition: Yes No
Container in good condition: Yes No
No fuel standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY, PICK UP ONLY, **SWAP**, WTL

Leading:
Start Time: _____ Box # In: _____ Ltr# 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Ltr# 0 1 2 End Time: _____

Transporter Name: **CTJ** Truck/Chassis # **442/707270**

Driver Name: **Brendan Osborne** Driver Signature: **Brendan Osborne**

Remarks: **con # 405617**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712045

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/25/2021 Vehicle# 483464 Volume
Payment Type Credit Account Container# 483464
Manual Ticket# 1026672 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/24/2021 09:36:55 Scale Operator Inbound Gross
Out 08/25/2021 09:36:55 Front Scale jvaldez jvaldez Tare
26.21 Tons 54500 lb*
Comments * Manual Weight Net 52420 lb*
Tons 26.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		26.21	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup
Time scheduled for pickup

Consignee Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFD1**

Container Inspection Upon Pickup:
Ramp in good working condition: Yes No
Container in good condition: Yes No
No fuel standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY, PICK UP ONLY, **SWAP**, WTL

Leading:
Start Time: _____ Box # In: _____ Ltr# 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Ltr# 0 1 2 End Time: _____

Transporter Name: **CTJ** Truck/Chassis # **444-743140**

Driver Name: **BRUCE BARNETT** Driver Signature: **Bruce Barnett**

Remarks: **W/L Permit 1938**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712046

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 08/25/2021 Vehicle# 483718 Volume
 Payment Type Credit Account Container 483718
 Manual Ticket# 1026674 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross
 In 08/24/2021 09:38:24 Front Scale jvaldez 55500 lb*
 Out 08/25/2021 09:38:24 Front Scale jvaldez 50240 lb
 Comments * Manual Weight Tons 25.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.12	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.12	Tons				WA-BELLEVU

Driver's Signature

Columbia Ridge Landfill and Recycling Center
 a subsidiary of Waste Management
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-6512
 (541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
 Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person
 Telephone Number

Acknowledgment of Loading
 Company Name _____ Date _____
 Signature _____ Name _____

Dispatcher: [Blank] Dispatch Facility: [Blank]

Container Inspection Upon Pickup

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leads: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Ticket/Invoice # **491707206 / 483718-6**
 Driver Name: **Anthony Eggen** Driver Signature: _____

Remarks: **LF 41,720 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712047

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 08/25/2021 Vehicle# 483730 Volume
 Payment Type Credit Account Container 483730
 Manual Ticket# 1026674 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross
 In 08/24/2021 09:39:27 Front Scale jvaldez 104060 lb*
 Out 08/25/2021 09:39:27 Front Scale jvaldez 54740 lb*
 Comments * Manual Weight Tons 24.66

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.66	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.66	Tons				WA-BELLEVU

Driver's Signature

Columbia Ridge Landfill and Recycling Center
 a subsidiary of Waste Management
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-6512
 (541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
 Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person
 Telephone Number

Acknowledgment of Loading
 Company Name _____ Date _____
 Signature _____ Name _____

Dispatcher: [Blank] Dispatch Facility: [Blank]

Container Inspection Upon Pickup

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leads: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Ticket/Invoice # **491707206 / 483718-6**
 Driver Name: **Anthony Eggen** Driver Signature: _____

Remarks: **LF 49,840 lbs**

WM Columbia Ridge
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-2032
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 8-19-21
Time scheduled for pickup 9:30

Customer Name and Loading Address: SCD NE 8TH
Waste Profile: US 787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leaving: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: STI Truck/Chassis # 440-107287-484002
Driver Name: Scott F Hogan Driver Signature: _____

Remarks: WDL TIT22213B LTWR 49,630

WM Columbia Ridge
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint Ticket# 712060

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 08/25/2021 Vehicle# 484051 Volume
Payment Type Credit Account Container 484051
Manual Ticket# 1026680 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105480 lb*
In 08/24/2021 10:22:28	Front Scale	jvaldez		Tare	54100 lb*
Out 08/25/2021 10:22:28		jvaldez		Net	51380 lb
Comments					25.69

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.69	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.69	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-2032
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH
Waste Profile: US 787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leaving: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTC Truck/Chassis # 444-743140
Driver Name: Mike Bennett Driver Signature: _____

Remarks: WDL 27224093B

WM Columbia Ridge
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint Ticket# 712473

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/26/2021 Vehicle# 480420 Volume
Payment Type Credit Account Container 480420
Manual Ticket# 1026823 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102240 lb*
In 08/25/2021 10:48:06	MANUAL WT	vmckinne		Tare	52380 lb*
Out 08/26/2021 10:48:06		vmckinne		Net	49860 lb
Comments					24.93

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.93	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-5112
(541) 454-2030

Bill Of Lading Date scheduled for pickup: 8-25-21
Time scheduled for pickup: 10:15

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: US7B7WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contract Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit or Bill To: _____ Disposal Facility: _____
Location: _____ Facility Name: _____
North: _____ City: _____
Phone: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time: _____ Box # In: _____ Line 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Line 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 440-707287-480501
Driver Name: Scott F Hogano Driver Signature: _____

Remarks: WDL # 771222138 LT.Wt. 45490



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712578

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/28/2021 Vehicle# 405003 Volume
Payment Type Credit Account Container 405003
Manual Ticket# 1027087 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/28/2021 08:17:48 Scale MANUAL WT Operator jvaldez Inbound Gross 96620 lb*
Out 08/28/2021 08:17:48 jvaldez Tare 50380 lb*
Comments * Manual Weight Net 46240 lb
Tons 23.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.12	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.12	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-5112
(541) 454-2030

Bill Of Lading Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: US7B7WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contract Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit or Bill To: _____ Disposal Facility: _____
Location: _____ Facility Name: _____
North: _____ City: _____
Phone: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time: _____ Box # In: _____ Line 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Line 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 442/707270
Driver Name: Brandon Osborne Driver Signature: _____

Remarks: Can # 40 5003



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712587

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/28/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1027088 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/27/2021 08:21:45 Scale MANUAL WT Operator jvaldez Inbound Gross 96040 lb*
Out 08/28/2021 08:21:45 jvaldez Tare 49380 lb*
Comments * Manual Weight Net 46660 lb
Tons 23.33

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.33	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.33	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712594

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/28/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1027089 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96060 lb*
In 08/27/2021 08:24:31	MANUAL WT	jvaldez		Tare	50240 lb*
Out 08/28/2021 08:24:31		jvaldez		Net	45820 lb
Comments				* Manual Weight	Tons 22.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.91	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.91	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____

Container Inspection Upon Pickup:

Easy to read visible condition	Yes	No
Container not good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck Class # 111 / 707381 / 405004
Driver Name: Anthony Lopez Driver Signature: _____
Remarks: 45,640 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712594

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/28/2021 Vehicle# 405008 Volume
Payment Type Credit Account Container 405008
Manual Ticket# 1027090 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97800 lb*
In 08/27/2021 08:25:45	MANUAL WT	jvaldez		Tare	51300 lb*
Out 08/28/2021 08:25:45		jvaldez		Net	46500 lb
Comments				* Manual Weight	Tons 23.25

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.25	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.25	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-25-2021
Time scheduled for pickup 1:30 pm

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____

Container Inspection Upon Pickup:

Easy to read visible condition	Yes	No
Container not good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: W40508 Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck Class # 445 + WM 743136
Driver Name: Jason Michael Driver Signature: _____
Remarks: Driv Lic
3213 BJ 43 B -WA-
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712601

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/28/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container 405011
Manual Ticket# 1027091 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96120 lb*
In 08/27/2021 08:26:58	MANUAL WT	jvaldez		Tare	50160 lb*
Out 08/28/2021 08:26:58		jvaldez		Net	45960 lb
Comments				* Manual Weight	Tons 22.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		22.98	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.98	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:

Tarp secured over visible condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is on good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 441/707581/405003-2
Driver Name: Arthur Egan Driver Signature: _____

Remarks: LT 45780100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712601

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/28/2021 Vehicle# 480559 Volume
Payment Type Credit Account Container 480559
Manual Ticket# 1027092 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104120 lb*
In 08/27/2021 08:28:07	MANUAL WT	jvaldez		Tare	53580 lb*
Out 08/28/2021 08:28:07		jvaldez		Net	50540 lb
Comments				* Manual Weight	Tons 25.27

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.27	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.27	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8/25/21
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:

Tarp secured over visible condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is on good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Leading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 440-701287-905011
Driver Name: SCOTT F HOGAN Driver Signature: _____

Remarks: WDR 71722213B LT WI 45260



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712610

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/28/2021 Vehicle# 480587 Volume
Payment Type Credit Account Container 480587
Manual Ticket# 1027093 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106420 lb*
In 08/27/2021 08:29:13	MANUAL WT	jvaldez		Tare	54960 lb*
Out 08/28/2021 08:29:13		jvaldez		Net	51460 lb
Comments				* Manual Weight	Tons 25.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____ Telephone Number: _____

Acknowledgment of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Class # **4411 1601231/180559**
Driver Name: **Arthur Egard** Driver Signature: _____
Remarks: **1748,640 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712621

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483069 Volume
Payment Type Credit Account Container 483069
Manual Ticket# 1027094 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104560 lb*
In 08/27/2021 08:32:44	MANUAL WT	jvaldez		Tare	54960 lb*
Out 08/28/2021 08:32:44		jvaldez		Net	49600 lb
Comments				* Manual Weight	Tons 24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____ Telephone Number: _____

Acknowledgment of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Class # **443-707200 480587**
Driver Name: **Jeff Thomas** Driver Signature: _____
Remarks: **48420**
WJL7829GC13 B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712625

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483150 Volume
Payment Type Credit Account Contain# 483150
Manual Ticket# 1027095 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/27/2021 08:34:40 Scale MANUAL WT Operator jvaldez Inbound Gross 105580 lb*
Out 08/28/2021 08:34:40 jvaldez Tare 54640 lb*
Comments * Manual Weight Net 50940 lb
Tons 25.47

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.47	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.47	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4912
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # US-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery: 18177 Cedar Springs Lane, Arlington, OR 97812
Disposal Facility: 18177 Cedar Springs Lane, Arlington, OR 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container secure and closed:
Check ONE: DROP ONLY PICK UP ONLY SWAP WTL CONTAINER 3069

Loading: Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____
Transporter Name: CTE Truck/Chassis # 444-74340
Driver Name: DAVID BAUNE II Driver Signature: [Signature]
Remarks: WL 2722-7933



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712629

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483377 Volume
Payment Type Credit Account Contain# 483377
Manual Ticket# 1027095 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 08/27/2021 08:35:36 Scale MANUAL WT Operator jvaldez Inbound Gross 101060 lb*
Out 08/28/2021 08:35:36 jvaldez Tare 53120 lb*
Comments * Manual Weight Net 47940 lb
Tons 23.97

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.97	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.97	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4912
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8/26/2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # US-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery: 18177 Cedar Springs Lane, Arlington, OR 97812
Disposal Facility: 18177 Cedar Springs Lane, Arlington, OR 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container secure and closed:
Check ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Loading: Start Time: _____ Box # In: 483150 Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis # 4415 + WM 743136
Driver Name: Jaren M. Charles Driver Signature: [Signature]
Remarks: DRIV 212
3213 BOT 43-38
08/27/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712634

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483586 Volume
Payment Type Credit Account Container 483586
Manual Ticket# 1027097 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104980 lb*
In 08/27/2021 08:39:47	MANUAL WT	jvaldez		Tare	54020 lb*
Out 08/28/2021 08:39:47		jvaldez		Net	50960 lb
Comments				* Manual Weight	Tons 25.48

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.48	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.48	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 445-707220 483377

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: # WDL 7R794013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712636

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483598 Volume
Payment Type Credit Account Container 483598
Manual Ticket# 1027098 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98240 lb*
In 08/27/2021 08:43:22	MANUAL WT	jvaldez		Tare	54020 lb*
Out 08/28/2021 08:43:22		jvaldez		Net	44220 lb
Comments				* Manual Weight	Tons 22.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.11	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.11	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8/26/21
Time scheduled for pickup 7:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 440-707287-483586

Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks: WDL # TTR2213B LTDT: 49,500



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712639

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483651 Volume
Payment Type Credit Account Container 483651
Manual Ticket# 1027099 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105140 lb*
In 08/27/2021 08:44:27	MANUAL WT	jvaldez		Tare	54480 lb*
Out 08/28/2021 08:44:27		jvaldez		Net	50660 lb
Comments				* Manual Weight	Tons 25.33

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.33	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.33	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LEB1

Telephone Number: _____

Acceptance of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTT Truck/Chassis #: 442-787270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Co. # 483598



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712641

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/28/2021 Vehicle# 483690 Volume
Payment Type Credit Account Container 483690
Manual Ticket# 1027100 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103940 lb*
In 08/27/2021 08:45:38	MANUAL WT	jvaldez		Tare	53960 lb*
Out 08/28/2021 08:45:38		jvaldez		Net	49990 lb
Comments				* Manual Weight	Tons 24.99

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.99	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.99	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LEB1

Telephone Number: _____

Acceptance of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTT Truck/Chassis #: 444-783140

Driver Name: BRUCE BAILEY Driver Signature: Bruce Bailey

Remarks: W1147277793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712645

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/29/2021 Vehicle# 480407 Volume
Payment Type Credit Account Container 480407
Manual Ticket# 1026961 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101620 lb*
In 08/26/2021 08:47:16	MANUAL WT	jvaldez		Tare	53360 lb*
Out 08/29/2021 08:47:16		jvaldez		Net	48260 lb
Comments				* Manual Weight	Tons
					24.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442-767220 483690

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: # 10DL7R7G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712647

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/29/2021 Vehicle# 483193 Volume
Payment Type Credit Account Container 483193
Manual Ticket# 1026962 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104800 lb*
In 08/26/2021 08:48:55	MANUAL WT	jvaldez		Tare	54480 lb*
Out 08/29/2021 08:48:55		jvaldez		Net	50320 lb
Comments				* Manual Weight	Tons
					25.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.16	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442/707270

Driver Name: Brandon Osborne Driver Signature: [Signature]

Remarks: Can # 480407

350

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFD1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

DEIR of DE: _____
DEIR of DE: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Ticket # **441/707501483195**
Driver Name: **Arthur Eggel** Date of Signature: _____

Remarks: **Lt. 49,180 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712651

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/29/2021 Vehicle# 483237 Volume
Payment Type Credit Account Container 483237
Manual Ticket# 1026963 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104460 lb*
In 08/26/2021 08:50:01	MANUAL WT	jvaldez		Tare	53300 lb*
Out 08/29/2021 08:50:01		jvaldez		Net	51160 lb
Comments					25.58
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.58	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.58	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFD1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

DEIR of DE: _____
DEIR of DE: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Ticket # **441/7075014832074**
Driver Name: **Arthur Eggel** Date of Signature: _____

Remarks: **49,700 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712651

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/29/2021 Vehicle# 483264 Volume
Payment Type Credit Account Container 483264
Manual Ticket# 1026964 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104480 lb*
In 08/26/2021 08:51:17	MANUAL WT	jvaldez		Tare	54880 lb*
Out 08/29/2021 08:51:17		jvaldez		Net	49600 lb
Comments					24.80
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712655

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/29/2021 Vehicle# 483363 Volume
Payment Type Credit Account Container 483363
Manual Ticket# 1026965 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104880 lb*
In 08/26/2021 08:52:51	MANUAL WT	jvaldez		Tare	54480 lb*
Out 08/29/2021 08:52:51		jvaldez		Net	50400 lb
Comments				* Manual Weight	Tons 25.20

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.20	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.20	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LEF1

Company Name _____ Date _____
Signature _____ Name _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No floor standing water No
Container in proper and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Locality _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 444-703140

Driver Name: BLAKE BARNETT Driver Signature: [Signature]

Remarks: WDL 71222193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712670

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 08/29/2021 Vehicle# 484076 Volume
Payment Type Credit Account Container 484076
Manual Ticket# 1026967 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103780 lb*
In 08/26/2021 09:14:55	MANUAL WT	jvaldez		Tare	54180 lb*
Out 08/29/2021 09:14:55		jvaldez		Net	49600 lb
Comments				* Manual Weight	Tons 24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8:25:21
Time scheduled for pickup 7:15

Generator Name and Loading Address: SCD NE 8TH Waste Profile # US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LEF1

Company Name _____ Date _____
Signature _____ Name _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No floor standing water No
Container in proper and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Locality _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 440-707287-483363

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: WDL 71222130 LT WT 49700



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 712672

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/29/2021 Vehicle# 483989 Volume
Payment Type Credit Account Container 483989
Manual Ticket# 1026966 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103680 lb*
In 08/26/2021 09:16:03	MANUAL WT	jvaldez		Tare	54160 lb*
Out 08/29/2021 09:16:03		jvaldez		Net	49520 lb
Comments				* Manual Weight	Tons 24.76

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.76	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.76	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-25-2021
Time scheduled for pickup 3:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDI Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 484076 Liers 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-753136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____

Driver Log: 300 2213 BT 43 B WA- 01 711 2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713010

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 08/30/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1027187 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97480 lb*
In 08/28/2021 09:05:23	MANUAL WT	jvaldez		Tare	51040 lb*
Out 08/30/2021 09:05:23		jvaldez		Net	46440 lb
Comments				* Manual Weight	Tons 23.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.22	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDI Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-702220 469989

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks: LIGHT # 49440
WDL 2R77G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713025

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/30/2021 Vehicle# 480409 Volume
Payment Type Credit Account Container 480409
Manual Ticket# 1027189 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103060 lb*
In 08/28/2021 09:06:40	MANUAL WT	jvaldez		Tare	53960 lb*
Out 08/30/2021 09:06:40		jvaldez		Net	49100 lb
Comments				* Manual Weight	Tons
					24.55

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.55	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.55	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 8-25-2021
Time scheduled for pickup 10:00 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # US-7B7WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Dispose Facility: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Leakage in pipes and hoses

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
Loading: _____ Box # In _____ Litters 0 1 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis # 445 + wms 743216
Driver Name: Jason Michaels Driver Signature: _____
Remarks: Driv Lic
3213 BT 43 B WA
EXP 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713026

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 08/30/2021 Vehicle# 480650 Volume
Payment Type Credit Account Container 480650
Manual Ticket# 1027190 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105940 lb*
In 08/28/2021 09:21:56	MANUAL WT	jvaldez		Tare	54120 lb*
Out 08/30/2021 09:21:56		jvaldez		Net	51820 lb
Comments				* Manual Weight	Tons
					25.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.91	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.91	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # US-7B7WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Dispose Facility: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Leakage in pipes and hoses

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
Loading: _____ Box # In _____ Litters 0 1 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis # 444-743140
Driver Name: BRUCE BARNETT Driver Signature: _____
Remarks: WBL 217A 193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713027

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483085 Volume
Payment Type Credit Account Container 483085
Manual Ticket# 1027191 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106340 lb*
In 08/28/2021 09:23:22	MANUAL WT	jvaldez		Tare	55580 lb*
Out 08/30/2021 09:23:22		jvaldez		Net	50760 lb
Comments				* Manual Weight	Tons 25.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.38	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.38	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-707000 480650

Driver Name: Jeff Thomas Driver Signature: _____

Remarks: # WDL 7R794013



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713028

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483619 Volume
Payment Type Credit Account Container 483619
Manual Ticket# 1027196 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103020 lb*
In 08/28/2021 09:24:27	MANUAL WT	jvaldez		Tare	53780 lb*
Out 08/30/2021 09:24:27		jvaldez		Net	49240 lb
Comments				* Manual Weight	Tons 24.62

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.62	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.62	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8.26.21
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442-707287-413085

Driver Name: Scott F Hagan Driver Signature: _____

Remarks: WDL# 7T222136
LT.WT 50,230



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713029

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483831 Volume
Payment Type Credit Account Container 483831
Manual Ticket# 1027198 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104040 lb*
In 08/28/2021 09:25:31	MANUAL WT	jvaldez		Tare	53840 lb*
Out 08/30/2021 09:25:31		jvaldez		Net	50200 lb
Comments				* Manual Weight	Tons
					25.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.10	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.10	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: US-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CIT Truck/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
can # 483619



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713030

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483875 Volume
Payment Type Credit Account Container 483875
Manual Ticket# 1027198 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104540 lb*
In 08/28/2021 09:27:22	MANUAL WT	jvaldez		Tare	54320 lb*
Out 08/30/2021 09:27:22		jvaldez		Net	50220 lb
Comments				* Manual Weight	Tons
					25.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.11	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.11	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-26-2021
Time scheduled for pickup 10:00 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: US-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: 483831 Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: Jason Michaely Truck/Chassis # 4415 + WM 743136
Driver Name: Jason Michaely Driver Signature: Jason Michaely

Remarks:
Driver Lic
3213 3T 43 B -WA-
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713031

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 08/30/2021 Vehicle# 400159 Volume
Payment Type Credit Account Container# 400159
Manual Ticket# 1027286 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97680 lb*
In 08/30/2021 09:28:17	MANUAL WT	jvaldez		Tare	49180 lb*
Out 08/30/2021 09:28:17		jvaldez		Net	48500 lb
Comments				* Manual Weight	Tons 24.25

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.25	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.25	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing material Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: GTI Truck/Chassis # 4411707223/485875-2
Driver Name: Arthur Egan Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713033

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483258 Volume
Payment Type Credit Account Container# 483258
Manual Ticket# 1027293 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105800 lb*
In 08/30/2021 09:29:37	MANUAL WT	jvaldez		Tare	55500 lb*
Out 08/30/2021 09:29:37		jvaldez		Net	50300 lb
Comments				* Manual Weight	Tons 25.15

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.15	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.15	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing material Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: GTI Truck/Chassis # 442/207270
Driver Name: Brandon Osborne Driver Signature: _____

Remarks:
Can # 400 159



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713034

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 08/30/2021 Vehicle# 483975 Volume
Payment Type Credit Account Container 483975
Manual Ticket# 1027300 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104440 lb*
In 08/30/2021 09:30:50	MANUAL WT	jvaldez		Tare	53680 lb*
Out 08/30/2021 09:30:50		jvaldez		Net	50760 lb
Comments				* Manual Weight	Tons 25.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.38	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH Waste Profile # **115787WA**

Contact Person: _____ Waste Type CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver of us: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone #: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good workable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **444-746140**

Driver Name: **ELISE BARNETT** Driver Signature: **[Signature]**

Remarks: **WDL 97812-4512**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713349

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483599 Volume
Payment Type Credit Account Container 483599
Manual Ticket# 1026566 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104340 lb*
In 08/23/2021 10:32:04	Front Scale	jaday		Tare	54280 lb*
Out 09/01/2021 10:32:04		jaday		Net	50060 lb
Comments				* Manual Weight	Tons 25.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **8-27-2021**
Time scheduled for pickup **8:00 AM**

Generator Name and Loading Address
SCD NE 8TH Waste Profile # **115787WA**

Contact Person: _____ Waste Type CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver of us: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone #: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good workable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: **483775** Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **445 + 773136**

Driver Name: **Jason Michaels** Driver Signature: **[Signature]**

Remarks: **Driver Lic 3213 B-J 43 B-wid- exp 7/31/2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713350

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405012 Volume
Payment Type Credit Account Container 405012
Manual Ticket# 1027185 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	94080 lb*
In 08/28/2021 10:34:39	Front Scale	jaday		Tare	50960 lb*
Out 09/01/2021 10:34:39		jaday		Net	43120 lb
Comments					21.56
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	21.56	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	21.56	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**
Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: **CTI** Track/Class: **445/70720/483599-0**
Driver Name: **Arthur Egger** Driver Signature: _____

Remarks: **Gr. 49,900lbs**

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9/26/2021**
Time scheduled for pickup **15:00**

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile: **115787WA**
Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: **405012** Lanes: 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: **CTI** Track/Class: **445 + WM 743136**
Driver Name: **Jason Michaels** Driver Signature: _____

Remarks: **Driver Lic 3213 B 43 B -W48 - exp 7-31-2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713351

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405014 Volume
Payment Type Credit Account Container 405014
Manual Ticket# 1027186 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96160 lb*
In 08/28/2021 10:45:04	Front Scale	jaday		Tare	49640 lb*
Out 09/01/2021 10:45:04		jaday		Net	46520 lb
Comments					23.26
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.26	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.26	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713356

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405019 Volume
Payment Type Credit Account Container 405019
Manual Ticket# 1027188 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	97520 lb*
	08/28/2021 11:12:11	Front Scale	jaday		Tare	50460 lb*
	09/01/2021 11:12:11		jaday		Net	47060 lb
Comments						23.53
						* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.53	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.53	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-26-21
Time scheduled for pickup 1:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____
Richard Brown, Sr. Columbia Ridge Landfill and Recycling Center
North Manager 97812 18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Easy to load/unload condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No floor standing water	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck Class: 440-701A87-405019

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: WDL# 7TT22218 B ET WT 45,380



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713356

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483189 Volume
Payment Type Credit Account Container 483189
Manual Ticket# 1027192 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	101880 lb*
	08/28/2021 11:15:44	Front Scale	jaday		Tare	52780 lb*
	09/01/2021 11:15:44		jaday		Net	49100 lb
Comments						24.55
						* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.55	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.55	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-26-2021
Time scheduled for pickup NOON

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____
Richard Brown, Sr. Columbia Ridge Landfill and Recycling Center
North Manager 97812 18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Easy to load/unload condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No floor standing water	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____
Start Time: _____ Box # In: 405019 Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck Class: 445 + WA 743136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driver Lic 3213 3J 43 B -WA- exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713357

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483591 Volume
Payment Type Credit Account Container 483591
Manual Ticket# 1027194 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105540 lb*
In 08/28/2021 11:19:57	Front Scale	jaday		Tare	55600 lb*
Out 09/01/2021 11:19:57		jaday		Net	49940 lb

Comments
* Manual Weight
Tons 24.97

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		24.97	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a Subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH
Waste Profile # **115787WA**

Contact Person _____
Telephone Number _____
Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____
Title _____

Deliver to:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Dispose at:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
CONT 483189

Loading:
Start Time _____ Box # In _____ Unloading _____
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____
Liners 0 1 2 End Time _____

Transporter Name: **C.T.E.** Truck/Trailer # **444-743140**

Driver Name: **BRUCE BARNETT** Driver Signature: *[Signature]*

Remarks: **NOL 2727, 2732, 2733**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713358

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483615 Volume
Payment Type Credit Account Container 483615
Manual Ticket# 1027194 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105380 lb*
In 08/28/2021 11:21:17	Front Scale	jaday		Tare	55600 lb*
Out 09/01/2021 11:21:17		jaday		Net	49720 lb

Comments
* Manual Weight
Tons 24.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		24.86	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a Subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH
Waste Profile # **115787WA**

Contact Person _____
Telephone Number _____
Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____
Title _____

Deliver to:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Dispose at:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
SWAP

Loading:
Start Time _____ Box # In _____ Unloading _____
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____
Liners 0 1 2 End Time _____

Transporter Name: _____ Truck/Trailer # _____

Driver Name: _____ Driver Signature: _____

Remarks: **# WBL 27956213 B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713359

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483790 Volume
Payment Type Credit Account Container 483790
Manual Ticket# 1027197 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103640 lb*
In 08/28/2021 11:26:08	Front Scale	jaday		Tare	53940 lb*
Out 09/01/2021 11:26:08		jaday		Net	49700 lb
Comments					24.85
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.85	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.85	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
(541) 454-2030

Bill Of Lading

Concree Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 441707270/4836155
Driver Name: Andrew Egner Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713360

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483127 Volume
Payment Type Credit Account Container 483127
Manual Ticket# 1027250 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107060 lb*
In 08/27/2021 11:29:23	Front Scale	jaday		Tare	54340 lb*
Out 09/01/2021 11:29:23		jaday		Net	52720 lb
Comments					26.36
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.36	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	26.36	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
(541) 454-2030

Bill Of Lading

Concree Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: _____

Remarks:
can # 483790



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713361

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container 405007
Manual Ticket# 1027287 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98000 lb*
In 08/30/2021 11:30:49	Front Scale	jaday		Tare	50580 lb*
Out 09/01/2021 11:30:49		jaday		Net	47420 lb
Comments					23.71

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.71	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.71	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6312
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatcher: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
Case # 483 127



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713362

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1027288 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98180 lb*
In 08/30/2021 11:32:15	Front Scale	jaday		Tare	51060 lb*
Out 09/01/2021 11:32:15		jaday		Net	47120 lb
Comments					23.56

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.56	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.56	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6312
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-27-21
Time scheduled for pickup 7:25

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatcher: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis # 440-707287-405007
Driver Name: Scott F. Hogan Driver Signature: Scott F. Hogan

Remarks:
STRAPS MISSING
WDL # 77122213B KTZ 44,920



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713363

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container# 405013
Manual Ticket# 1027289 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98360 lb*
In 08/30/2021 11:35:07	Front Scale	jaday		Tare	51540 lb*
Out 09/01/2021 11:35:07		jaday		Net	46820 lb
Comments				* Manual Weight	Tons 23.41

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100					WA-BELLEVUE
2 EVF-P6-Environment	100	\$					WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.41	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Landing: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200/405009-8
Driver Name: Arthur Egger Driver Signature: _____

Remarks: ET 45,020 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713364

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405020 Volume
Payment Type Credit Account Container# 405020
Manual Ticket# 1027290 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96460 lb*
In 08/30/2021 11:36:27	Front Scale	jaday		Tare	50560 lb*
Out 09/01/2021 11:36:27		jaday		Net	45900 lb
Comments				* Manual Weight	Tons 22.95

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100					WA-BELLEVUE
2 EVF-P6-Environment	100	\$					WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.95	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Landing: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200/405013
Driver Name: Jeff Thomas Driver Signature: _____

Remarks: 44520
WDL 7R79013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713366

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/01/2021 Vehicle# 480634 Volume
Payment Type Credit Account Container 480634
Manual Ticket# 1027292 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 08/30/2021 12:19:13	Front Scale	jaday		104640 lb*
Out 09/01/2021 12:19:13		jaday		54680 lb*
		* Manual Weight		49960 lb
Comments				Tons 24.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.98	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.98	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
Phone: (541) 454-2030

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____

Start Time: _____ Box # In: _____ Licens 0 1 2 Start Time: _____ Unloading: _____
End Time: _____ Box # Out: _____ Licens 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 441-707381-405020-4
Driver Name: Arthur Egan Driver Signature: _____

Remarks: LT 46,060 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713367

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483266 Volume
Payment Type Credit Account Container 483266
Manual Ticket# 1027294 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 08/30/2021 12:27:52	Front Scale	jaday		103360 lb*
Out 09/01/2021 12:27:52		jaday		54360 lb*
		* Manual Weight		49000 lb
Comments				Tons 24.50

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.50	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-27-21
Time scheduled for pickup 9:50

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6612
Phone: (541) 454-2030

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____

Start Time: _____ Box # In: _____ Licens 0 1 2 Start Time: _____ Unloading: _____
End Time: _____ Box # Out: _____ Licens 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-490654
Driver Name: Scott F Hogan Driver Signature: _____

Remarks: WDL 7122213B LT WT 48,680

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-5112
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver Name: **PAUL BRINE II** Driver Signature: *[Signature]*

Remarks: **WDL 21277A95B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713368

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483325 Volume
Payment Type Credit Account Container 483325
Manual Ticket# 1027295 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104460 lb*
In 08/30/2021 12:29:49	Front Scale	jaday		Tare	54480 lb*
Out 09/01/2021 12:29:49		jaday		Net	49980 lb
Comments * Manual Weight					24.99

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.99	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.99	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks: **#1 WDL 7R79G013B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713369

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483768 Volume
Payment Type Credit Account Container 483768
Manual Ticket# 1027295 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103700 lb*
In 08/30/2021 12:32:35	Front Scale	jaday		Tare	53920 lb*
Out 09/01/2021 12:32:35		jaday		Net	49780 lb
Comments * Manual Weight					24.89

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.89	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.89	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Track/Chassis # **442/707270**

Driver Name: **Brandon Oble** Driver Signature: *Brandon Oble*

Remarks:
Con # 433768



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713370

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483876 Volume
Payment Type Credit Account Container 483876
Manual Ticket# 1027299 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104840 lb*
In 08/30/2021 12:33:57	Front Scale	jaday		Tare	55760 lb*
Out 09/01/2021 12:33:57		jaday		Net	49080 lb
Comments					24.54
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.54	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.54	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **8/27/2021**
Time scheduled for pickup **11:00 AM**

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **445787WA**

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In **483876** Liners 0 2 Start Time _____ Unloading _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Track/Chassis # **445 + WM 7473136**

Driver Name: **Jason Michael** Driver Signature: *Jason Michael*

Remarks:
Driver Lic 3213 BT 43 B -WA- exp 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713515

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/01/2021 Vehicle# 480437 Volume
Payment Type Credit Account Container 480437
Manual Ticket# 1027299 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102840 lb*
In 08/25/2021 10:07:08	MANUAL WT	jvaldez		Tare	53960 lb*
Out 09/01/2021 10:07:08		jvaldez		Net	48880 lb
Comments					24.44
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.44	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.44	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713516

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483523 Volume
Payment Type Credit Account Container 483523
Manual Ticket# 1027296 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103980 lb*
In 08/30/2021 10:08:32	MANUAL WT	jvaldez		Tare	54340 lb*
Out 09/01/2021 10:08:32		jvaldez		Net	49640 lb
Comments				* Manual Weight	Tons 24.82

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.82	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.82	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8/27/21
Time scheduled for pickup 1:40

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in its good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL
Front of Box bottom Broken Welds

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Lines 0 1 2 Start Time _____
End Time _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 440-707287-480437

Driver Name: Scott F. Hogan Driver Signature: Scott F. Hogan

Remarks: WDL # 71722213B LT-WJ 49640



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713517

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483631 Volume
Payment Type Credit Account Container 483631
Manual Ticket# 1027297 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	99140 lb*
In 08/30/2021 10:09:46	MANUAL WT	jvaldez		Tare	53160 lb*
Out 09/01/2021 10:09:46		jvaldez		Net	45990 lb
Comments				* Manual Weight	Tons 22.99

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.99	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.99	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in its good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Lines 0 1 2 Start Time _____
End Time _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 442/707270

Driver Name: Brandon Oster Driver Signature: Brandon Oster

Remarks: can # 483523



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713518

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 09/01/2021 Vehicle# 490012 Volume
Payment Type Credit Account Container 490012
Manual Ticket# 1027301 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104720 lb*
In 08/30/2021 10:11:16	MANUAL WT	jvaldez		Tare	54760 lb*
Out 09/01/2021 10:11:16		jvaldez		Net	49960 lb
Comments				* Manual Weight	Tons 24.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.98			WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		24.98			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Local Public Agency or High-Clearance or High-Clearance
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Unloading: _____

Transporter Name: CTI Truck/Chassis #: 443-207800 483631

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: WDL-2726-013 B
WTL 4900



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713519

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483937 Volume
Payment Type Credit Account Container 483937
Manual Ticket# 1027350 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102640 lb*
In 08/30/2021 10:12:29	MANUAL WT	jvaldez		Tare	52840 lb*
Out 09/01/2021 10:12:29		jvaldez		Net	49800 lb
Comments				* Manual Weight	Tons 24.90

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.90			WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		24.90			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-27-2021
Time scheduled for pickup 14:00

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Local Public Agency or High-Clearance or High-Clearance
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 490012 Unloading: _____
End Time _____ Box # Out _____ Unloading: _____

Transporter Name: CTI Truck/Chassis #: 4415 + WM 713136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driver Lic - 3213 BJ 43 B -WA-
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713520

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483410 Volume
Payment Type Credit Account Container 483410
Manual Ticket# 1027448 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/KK PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 08/30/2021 10:13:45	MANUAL WT	jvaldez		105320 lb*
Out 09/01/2021 10:13:45		jvaldez		57860 lb*
Comments * Manual Weight				Net 47460 lb
				Tons 23.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.73	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.73	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deficit to: _____ Disposal Facility: _____
EPA Permit: _____ EPA ID: _____
State: _____ City: _____
Phone: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTE** Truck/Chassis # **444-743140**
Driver Name: **BRUCE BARNETT** Driver Signature: *[Signature]*

Remarks: **WIL PIZZATTA**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713521

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405006 Volume
Payment Type Credit Account Container 405006
Manual Ticket# 1027464 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 09/01/2021 10:15:07	MANUAL WT	jvaldez		97320 lb*
Out 09/01/2021 10:15:07		jvaldez		50600 lb*
Comments * Manual Weight				Net 46720 lb
				Tons 23.36

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.36	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.36	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deficit to: _____ Disposal Facility: _____
EPA Permit: _____ EPA ID: _____
State: _____ City: _____
Phone: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTE** Truck/Chassis # **441/707381/4834105**
Driver Name: **ARTHUR EGAN** Driver Signature: *[Signature]*

Remarks: **LT 49-2001123**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713522

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/01/2021 Vehicle# 405017 Volume
Payment Type Credit Account Container# 405017
Manual Ticket# 1027465 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103520 lb*
In 09/01/2021 10:16:55	MANUAL WT	jvaldez		Tare	49180 lb*
Out 09/01/2021 10:16:55		jvaldez		Net	54340 lb
Comments				* Manual Weight	Tons 27.17

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	27.17	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	27.17	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 | 1 | 2 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 | 1 | 2 _____ End Time _____

Transporter Name: CTI Truck/Class # 413-702280 405017
Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: LT 45,820 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713522

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483151 Volume
Payment Type Credit Account Container# 483151
Manual Ticket# 1027469 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	110040 lb*
In 09/01/2021 10:18:12	MANUAL WT	jvaldez		Tare	50400 lb*
Out 09/01/2021 10:18:12		jvaldez		Net	59640 lb
Comments				* Manual Weight	Tons 29.82

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	29.82	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	29.82	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 | 1 | 2 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 | 1 | 2 _____ End Time _____

Transporter Name: CTI Truck/Class # 413-702280 405017
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: # WDL 7R795013B HWAT 45280



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713525

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483198 Volume
Payment Type Credit Account Container 483358
Manual Ticket# 1027470 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	84520 lb*
In 09/01/2021 10:19:39	MANUAL WT	jvaldez		Tare	49020 lb*
Out 09/01/2021 10:19:39		jvaldez		Net	35500 lb
Comments				* Manual Weight	Tons
					17.75

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		17.75			WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		17.75	Tons			WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Container Inspection Upon Pickup:
Empty in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Trailer # 4411702281/483151

Driver Name: William Eggel Driver Signature: _____

Remarks: H



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713526

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483358 Volume
Payment Type Credit Account Container 483358
Manual Ticket# 1027471 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104860 lb*
In 09/01/2021 10:20:49	MANUAL WT	jvaldez		Tare	54860 lb*
Out 09/01/2021 10:20:49		jvaldez		Net	50000 lb
Comments				* Manual Weight	Tons
					25.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.00			WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		25.00	Tons			WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Container Inspection Upon Pickup:
Empty in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Trailer # 444-743140

Driver Name: Bill Blaine II Driver Signature: _____

Remarks: WAL 27322793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713527

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483650 Volume
Payment Type Credit Account Container 483650
Manual Ticket# 1027473 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105360 lb*
In 09/01/2021 10:21:57	MANUAL WT	jvaldez		Tare	55140 lb*
Out 09/01/2021 10:21:57		jvaldez		Net	50220 lb
Comments				* Manual Weight	Tons 25.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.11	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.11	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-30-21
Time scheduled for pickup 7:35

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit or Bill: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Y N
Container in good condition Y N
Pro-free snagging wires Y N
Longman in cargo and clear Y N

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 440-707397-483358
Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks:
WDL # 711232130 LT.Wt. 50.160



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713528

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483668 Volume
Payment Type Credit Account Container 483668
Manual Ticket# 1027474 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96440 lb*
In 09/01/2021 10:23:01	MANUAL WT	jvaldez		Tare	49840 lb*
Out 09/01/2021 10:23:01		jvaldez		Net	46600 lb
Comments				* Manual Weight	Tons 23.30

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.30	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.30	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit or Bill: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Y N
Container in good condition Y N
Pro-free snagging wires Y N
Longman in cargo and clear Y N

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 444-743140
Driver Name: BRUCE BARNETT Driver Signature: [Signature]

Remarks: WDL 711232130

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-30-2021
Time scheduled for pickup 8:00 AM

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Definer to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483668 Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 445 WM 745136

Driver Name: Jason Michael Driver Signature: _____
Remarks: Driver Lic 3213 B 43 B -WA exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713529

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/01/2021 Vehicle# 483820 Volume
Payment Type Credit Account Container 483820
Manual Ticket# 1027475 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103960 lb*
In 09/01/2021 10:24:12	MANUAL WT	jvaldez		Tare	54140 lb*
Out 09/01/2021 10:24:12		jvaldez		Net	49820 lb
Comments					24.91
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.91	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.91	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Definer to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 442 707200 - 483820

Driver Name: Jeff Thomas Driver Signature: _____
Remarks: # WDL 7274013 B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713530

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/01/2021 Vehicle# 484065 Volume
Payment Type Credit Account Container 484065
Manual Ticket# 1027477 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104380 lb*
In 09/01/2021 10:25:47	MANUAL WT	jvaldez		Tare	54480 lb*
Out 09/01/2021 10:25:47		jvaldez		Net	49900 lb
Comments					24.95
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.95	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.95	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713953

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/02/2021 Vehicle# 483464 Volume
Payment Type Credit Account Container 483464
Manual Ticket# 1027121 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105540 lb*
In 09/02/2021 12:33:22	Front Scale	jaday		Tare	55840 lb*
Out 09/02/2021 12:33:22		jaday		Net	49700 lb
Comments					24.85
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.85	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.85	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
1 - Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 4421707270
Driver Name: Brian Osborne Driver Signature: Brian Osborne

Remarks:
Con # 494065



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713954

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/02/2021 Vehicle# 480537 Volume
Payment Type Credit Account Container 480537
Manual Ticket# 1027466 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103800 lb*
In 09/01/2021 12:35:05	Front Scale	jaday		Tare	53720 lb*
Out 09/02/2021 12:35:05		jaday		Net	50080 lb
Comments					25.04
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.04	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.04	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
1 - Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 4421707270
Driver Name: Brian Osborne Driver Signature: Brian Osborne

Remarks:
Con # 483464

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**

Driver Name: **Brendan Osborne** Driver Signature: *Brendan Osborne*

Remarks:
Can # 480537



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713956

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/02/2021 Vehicle# 483055 Volume
 Payment Type Credit Account Container 483055
 Manual Ticket# 1027467 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105580 lb*
In 09/01/2021 12:36:20	Front Scale	jaday		Tare	55320 lb*
Out 09/02/2021 12:36:20		jaday		Net	50260 lb
Comments					25.13
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.13	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.13	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **8-30-2021**
Time scheduled for pickup **11:50 AM**

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Trailer # **445 + WA-793136**

Driver Name: **Jason Michael** Driver Signature: *Jason Michael*

Remarks:
**Driver Lic
3213 BJ 43 B WA-
exp 7.31.2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713956

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/02/2021 Vehicle# 483507 Volume
 Payment Type Credit Account Container 483507
 Manual Ticket# 1027472 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104380 lb*
In 09/01/2021 12:37:38	Front Scale	jaday		Tare	54360 lb*
Out 09/02/2021 12:37:38		jaday		Net	50020 lb
Comments					25.01
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.01	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.01	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup: 2-30-21
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 11578746

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposition Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing liquid Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTE Truck/Chassis #: 440-707287-493507

Driver Name: SCOTT F. HAYAN Driver Signature: _____

Remarks: WDL # 71123313B
ATWC 5/1/12



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713957

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/02/2021 Vehicle# 483968 Volume
Payment Type Credit Account Container# 483968
Manual Ticket# 1027476 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105640 lb*
In 09/01/2021 12:38:52	Front Scale	jaday		Tare	55580 lb*
Out 09/02/2021 12:38:52		jaday		Net	50060 lb
Comments		* Manual Weight		Tons	25.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposition Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing liquid Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTE Truck/Chassis #: 441-743140

Driver Name: PAUL BARNETT Driver Signature: _____

Remarks: WDL # 711221793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713958

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/02/2021 Vehicle# 483660 Volume
Payment Type Credit Account Container# 483660
Manual Ticket# 1027500 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*
In 09/01/2021 12:41:41	Front Scale	jaday		Tare	54800 lb*
Out 09/02/2021 12:41:41		jaday		Net	50440 lb
Comments		* Manual Weight		Tons	25.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.22	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713959

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/02/2021 Vehicle# 480554 Volume
Payment Type Credit Account Container 480554
Manual Ticket# 1027612 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104120 lb*
In 09/02/2021 12:44:29	Front Scale	jaday		Tare	54060 lb*
Out 09/02/2021 12:44:29		jaday		Net	50060 lb
Comments					25.03
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading
Date scheduled for pickup 9-30-21
Time scheduled for pickup 3 pm

Generate Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
3877 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container in proper and safe

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483660 Line# 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 445 + WA-713136
Driver Name: Jason Michaels Driver Signature: _____
Remarks: _____
Driv Lic
3213 BT43 B-WA-
CP 7-31-2017



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713960

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/02/2021 Vehicle# 483096 Volume
Payment Type Credit Account Container 483096
Manual Ticket# 1027614 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105380 lb*
In 09/02/2021 12:45:46	Front Scale	jaday		Tare	54920 lb*
Out 09/02/2021 12:45:46		jaday		Net	50460 lb
Comments					25.23
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.23	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.23	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading
Date scheduled for pickup 9-31-21
Time scheduled for pickup 10:45 am

Generate Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
3877 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container in proper and safe

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Line# 0 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 440-70287-480554
Driver Name: Scott F Hogan Driver Signature: _____
Remarks: _____
WDL 7122213B
LWT 49.500

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97112-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI
Driver Name: Arthur Eggen Driver Signature: _____

Remarks: LT 50,180 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 713961

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/02/2021 Vehicle# 483361 Volume
Payment Type Credit Account Container 483361
Manual Ticket# 1027614 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105540 lb*
In 09/02/2021 12:47:16	Front Scale	jaday		Tare	55340 lb*
Out 09/02/2021 12:47:16		jaday		Net	50200 lb
Comments		* Manual Weight		Tons	25.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.10	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.10	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97112-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97112-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI
Driver Name: Jeff Tibbets Driver Signature: _____

Remarks: #1 WDL 787940130



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714135

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/03/2021 Vehicle# 480552 Volume
Payment Type Credit Account Container 480552
Manual Ticket# 1027611 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104460 lb*
In 09/02/2021 13:42:39	MANUAL WT	vmckinne		Tare	54180 lb*
Out 09/03/2021 13:42:39		vmckinne		Net	50280 lb
Comments		* Manual Weight		Tons	25.14

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.14	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.14	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714136

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483039 Volume
Payment Type Credit Account Container 483039
Manual Ticket# 1027613 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/02/2021 13:43:22 Scale MANUAL WT Operator vmckinne Inbound Gross 105920 lb*
Out 09/03/2021 13:43:22 vmckinne Tare 55540 lb*
Comments * Manual Weight Net 50380 lb
Tons 25.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.19	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-3-2021
Time scheduled for pickup 2:00 PM

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in its good condition No
No free standing water No
Customer is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Box # In 18052 Unloading: _____
Start Time: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Lanes 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 445 + WJM 743136

Driver Name: JOHN MICHAELS Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714139

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483293 Volume
Payment Type Credit Account Container 483293
Manual Ticket# 1027615 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/02/2021 13:44:06 Scale MANUAL WT Operator vmckinne Inbound Gross 106520 lb*
Out 09/03/2021 13:44:06 vmckinne Tare 56380 lb*
Comments * Manual Weight Net 50140 lb
Tons 25.07

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.07	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.07	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-3-21
Time scheduled for pickup 7:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in its good condition Yes
No free standing water No
Customer is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Box # In _____ Unloading: _____
Start Time: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Lanes 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-10787-483039

Driver Name: SCOTT F HOYAN Driver Signature: _____

Remarks: _____

WDL# TTI22213B LFWT 49.040



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714140

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483359 Volume
Payment Type Credit Account Container 483359
Manual Ticket# 1027616 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	99960 lb*
In 09/02/2021 13:44:49	MANUAL WT	vmckinne		Tare	54300 lb*
Out 09/03/2021 13:44:49		vmckinne		Net	45660 lb
Comments				* Manual Weight	Tons 22.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.83	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.83	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 5.31.2021
Time scheduled for pickup: 11:00 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading: _____
Start Time: _____ Box # to: 483293 Litter: 1 2 Unloading Start Time: _____
End Time: _____ Box # On: _____ Litter: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 445 * WM 74336

Driver Name: Jason Michael Driver Signature: [Signature]

Remarks: drive license 3213 BJ 43 B

CP 7.31.2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714142

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483359 Volume
Payment Type Credit Account Container 483359
Manual Ticket# 1027618 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104360 lb*
In 09/02/2021 13:45:32	MANUAL WT	vmckinne		Tare	54920 lb*
Out 09/03/2021 13:45:32		vmckinne		Net	49440 lb
Comments				* Manual Weight	Tons 24.72

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.72	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.72	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 8.31.2021
Time scheduled for pickup: 3:00 pm

Generate Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading: _____
Start Time: _____ Box # to: 483364 Litter: 1 2 Unloading Start Time: _____
End Time: _____ Box # On: _____ Litter: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 445 * WM 74336

Driver Name: Jason Michael Driver Signature: [Signature]

Remarks: Drive Lic

WOL 3213 BJ 43 B - WA -

CP 7.31.2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714144

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483635 Volume
Payment Type Credit Account Container 483635
Manual Ticket# 1027620 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104640 lb*
In 09/02/2021 13:46:23	MANUAL WT	vmckinne		Tare	54220 lb*
Out 09/03/2021 13:46:23		vmckinne		Net	50420 lb
Comments				* Manual Weight	Tons 25.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.21	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.21	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 - New Pacific Bulk Terminal Facility (3000) Road
P.O. Box 20000
Seattle, Washington 98108
Phone (206) 744-2200 or 1-800-274-7424

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Chassis # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 483459



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714145

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483657 Volume
Payment Type Credit Account Container 483657
Manual Ticket# 1027621 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104340 lb*
In 09/02/2021 13:47:06	MANUAL WT	vmckinne		Tare	54600 lb*
Out 09/03/2021 13:47:06		vmckinne		Net	49740 lb
Comments				* Manual Weight	Tons 24.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.87	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.87	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 - New Pacific Bulk Terminal Facility (3000) Road
P.O. Box 20000
Seattle, Washington 98108
Phone (206) 744-2200 or 1-800-274-7424

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Chassis # 443-707202 483635

Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks: # WDL 7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714146

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483716 Volume
Payment Type Credit Account Container 483716
Manual Ticket# 1027622 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104880 lb*
In 09/02/2021 13:47:57	MANUAL WT	vmckinne		Tare	54020 lb*
Out 09/03/2021 13:47:57		vmckinne		Net	50860 lb
Comments				* Manual Weight	Tons 25.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.43	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.43	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - to Back Bay Transfer Facility (LH01) (LH02)
45 South Bayshore
North, Vancouver, BC V7P 2G6
Phone (604) 681-2222 or (604) 291-7444 (24)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (503) 625-3200

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Unloading
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ End Time _____
Liners 0 1 2

Transporter Name: **CTI** Truck/Trailer # **44117073281/483659-2**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
LA 49.640120



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714147

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483827 Volume
Payment Type Credit Account Container 483827
Manual Ticket# 1027623 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103780 lb*
In 09/02/2021 13:48:41	MANUAL WT	vmckinne		Tare	53960 lb*
Out 09/03/2021 13:48:41		vmckinne		Net	49820 lb
Comments				* Manual Weight	Tons 24.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.91	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.91	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **8:31:20 AM**
Time scheduled for pickup **8:00 AM**

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - to Back Bay Transfer Facility (LH01) (LH02)
45 South Bayshore
North, Vancouver, BC V7P 2G6
Phone (604) 681-2222 or (604) 291-7444 (24)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (503) 625-3200

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In **W/MX 4 283716** Unloading
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ End Time _____
Liners 0 1 2

Transporter Name: **CTI** Truck/Trailer # **445 + van 743136**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
**WA Driv Lic
3A13 BJ 43 B
09/07/2017**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714148

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/03/2021 Vehicle# 483926 Volume
Payment Type Credit Account Container 483926
Manual Ticket# 1027624 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104300 lb*
In 09/02/2021 13:49:29	MANUAL WT	vmckinne		Tare	54040 lb*
Out 09/03/2021 13:49:29		vmckinne		Net	50260 lb
Comments				* Manual Weight	Tons 25.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-30-21
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____
Telephone Number: _____

Acceptance of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1-Local Public Health Department (LPHD) only
2-Local Business Owner
3-Local Municipality
4-Other (Specify) _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Licens 0 1 2 Start Time _____
End Time _____ Licens 0 1 2 End Time _____

Transporter Name: RTI Truck/Trailer # 440-707287-483887
Driver Name: STEEVE F. HOGAN Driver Signature: [Signature]

Remarks: WDL 771222135 LTWT 49,560



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714150

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/03/2021 Vehicle# 484024 Volume
Payment Type Credit Account Container 484024
Manual Ticket# 1027625 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104540 lb*
In 09/02/2021 13:50:09	MANUAL WT	vmckinne		Tare	54340 lb*
Out 09/03/2021 13:50:09		vmckinne		Net	50200 lb
Comments				* Manual Weight	Tons 25.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.10	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.10	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____
Telephone Number: _____

Acceptance of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1-Local Public Health Department (LPHD) only
2-Local Business Owner
3-Local Municipality
4-Other (Specify) _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Licens 0 1 2 Start Time _____
End Time _____ Licens 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442/707270
Driver Name: Brandon Osborne Driver Signature: [Signature]

Remarks: can # 483926



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714151

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/03/2021 Vehicle# 484069 Volume
Payment Type Credit Account Container 484069
Manual Ticket# 1027626 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	104360 lb*
09/02/2021 13:51:03	MANUAL WT	vmckinne			Tare	54740 lb*
09/03/2021 13:51:03		vmckinne			Net	49620 lb
Comments				* Manual Weight	Tons	24.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Columbia Ridge Landfill and Recycling Center, 484069, 18177 Cedar Springs Lane, Arlington, Oregon 97812-4512. Phone: (541) 454-2030.
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-4512. Phone: (541) 454-2030.

Container Inspection Upon Pickup:
Tary in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: LTC Truck/Trailer # 444-745140

Driver Name: BIGGIE BARRETT Driver Signature: [Signature]

Remarks: WLD 1122-195B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714153

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/04/2021 Vehicle# 480547 Volume
Payment Type Credit Account Container 480547
Manual Ticket# 1027737 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	104680 lb*
09/03/2021 13:51:50	MANUAL WT	vmckinne			Tare	54240 lb*
09/04/2021 13:51:50		vmckinne			Net	50440 lb
Comments				* Manual Weight	Tons	25.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.22	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Columbia Ridge Landfill and Recycling Center, 484069, 18177 Cedar Springs Lane, Arlington, Oregon 97812-4512. Phone: (541) 454-2030.
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-4512. Phone: (541) 454-2030.

Container Inspection Upon Pickup:
Tary in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck/Trailer # 411/2073581/3840699

Driver Name: Adam Eggel Driver Signature: [Signature]

Remarks: LT 48040100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714154

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/04/2021 Vehicle# 483132 Volume
Payment Type Credit Account Container 483132
Manual Ticket# 1027738 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/03/2021 13:52:31 Scale MANUAL WT Operator vmckinne Inbound Gross 104120 lb*
Out 09/04/2021 13:52:31 Tare 51120 lb*
Net 53000 lb
Comments * Manual Weight Tons 26.50

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	Tons				WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
11577 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing ropes: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: CTI Truck/Trailer # 441-707381 / 420547
Driver Name: Scott F Hogan Driver Signature: _____

Remarks: LT 49,180100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714320

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/06/2021 Vehicle# 483244 Volume
Payment Type Credit Account Container 483244
Manual Ticket# 1027874 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/04/2021 07:47:53 Scale Front Scale Operator jaday Inbound Gross 103780 lb*
Out 09/06/2021 07:47:53 Tare 54860 lb*
Net 48920 lb
Comments * Manual Weight Tons 24.46

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	Tons				WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-3-21
Time scheduled for pickup 12-40

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
11577 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing ropes: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707297-483123
Driver Name: Scott F Hogan Driver Signature: _____

Remarks: WDL ITT 2213B
LT WT 49,740

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 9-2-
Time scheduled for pickup: 11:30

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115707WA

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Company Name: _____ Date: _____
 Signature: _____ Name: _____

Deliver to:
 1 - New Pacific Tank (removal) facility (800) 460-1400
 4 - Columbia Ridge Landfill and Recycling Center
 4 - North, Washington St
 4 - River Street (503) 251-1200 or High Street (503) 241-1200

Disposal Facility:
 Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-6512
 Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time: _____ Box # In: _____ Unloading Start Time: _____
 End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-443244
 Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks:
WDL 7IT22213B
LTWT 48,700



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714321

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/06/2021 Vehicle# 483245 Volume
 Payment Type Credit Account Container# 483245
 Manual Ticket# 1027875 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103880 lb*
In 09/04/2021 07:49:49	Front Scale	jaday		Tare	54360 lb*
Out 09/06/2021 07:49:49		jaday		Net	49520 lb
Comments					24.76

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.76	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.76	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 9-2-2021
Time scheduled for pickup: 11:00

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115707WA

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Company Name: _____ Date: _____
 Signature: _____ Name: _____

Deliver to:
 1 - New Pacific Tank (removal) facility (800) 460-1400
 4 - Columbia Ridge Landfill and Recycling Center
 4 - North, Washington St
 4 - River Street (503) 251-1200 or High Street (503) 241-1200

Disposal Facility:
 Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-6512
 Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time: _____ Box # In: WM 483245 Unloading Start Time: _____
 End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: CTI Truck/Trailer # 445 + WM 743136
 Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks:
Driver Lic
WDL 3A13 3J 43 B
09 7-31-2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714322

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/06/2021 Vehicle# 483972 Volume
 Payment Type Credit Account Container# 483972
 Manual Ticket# 1027880 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103540 lb*
In 09/04/2021 07:51:15	Front Scale	jaday		Tare	53860 lb*
Out 09/06/2021 07:51:15		jaday		Net	49600 lb
Comments					24.84

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.84	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.84	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714323

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/06/2021 Vehicle# 483002 Volume
Payment Type Credit Account Container 483002
Manual Ticket# 1027991 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105120 lb*
In 09/06/2021 07:56:13	Front Scale	jaday		Tare	55540 lb*
Out 09/06/2021 07:56:13		jaday		Net	49580 lb
Comments					24.79
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.79	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.79	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - New Pacific Waste Materials Facility (5801 10th St)
2 - Old Pacific Waste Materials Facility (5801 10th St)
3 - South, Washington St (5th)
Phone: (541) 454-2030 or (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **PICK UP ONLY** WTL

Loading
 Start Time _____ Box # In _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Chassis # **442/707220**

Driver Name: **Brandon Osborne** Driver Signature: **Brandon Osborne**

Remarks:
can # 483972



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714577

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/07/2021 Vehicle# 483810 Volume
Payment Type Credit Account Container 483810
Manual Ticket# 1027739 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100240 lb*
In 09/03/2021 09:33:15	MANUAL WT	vmckinne		Tare	54280 lb*
Out 09/07/2021 09:33:15		vmckinne		Net	45960 lb
Comments					22.98
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.98	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		22.98	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9-11-21**
Time scheduled for pickup **7:30**

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - New Pacific Waste Materials Facility (5801 10th St)
2 - Old Pacific Waste Materials Facility (5801 10th St)
3 - South, Washington St (5th)
Phone: (541) 454-2030 or (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **PICK UP ONLY** WTL

Loading
 Start Time _____ Box # In _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Chassis # **444-707287-493602**

Driver Name: **Scott Hogan** Driver Signature: **Scott Hogan**

Remarks:
WDL # 71122213B **LTWT: 80,580**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714578

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/07/2021 Vehicle# 480601 Volume
Payment Type Credit Account Container 480601
Manual Ticket# 1027990 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	103200 lb*
09/06/2021	09:35:52	MANUAL WT	vmckinne		Tare	53540 lb*
09/07/2021	09:35:52		vmckinne		Net	49660 lb
Comments						24.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.83	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.83	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Depot Facility: _____

Container Inspection Upon Package:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Class # 443-707220 483810

Driver Name: Jeff Thomas Driver Signature: _____

Remarks:
WDL 7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714580

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/07/2021 Vehicle# 483339 Volume
Payment Type Credit Account Container 483339
Manual Ticket# 1027992 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	104120 lb*
09/06/2021	09:37:15	MANUAL WT	vmckinne		Tare	50120 lb*
09/07/2021	09:37:15		vmckinne		Net	54000 lb
Comments						27.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	27.00	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	27.00	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Depot Facility: _____

Container Inspection Upon Package:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Class # 443-707220 480601

Driver Name: Jeff Thomas Driver Signature: _____

Remarks:
WDL 7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714581

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/07/2021 Vehicle# 483430 Volume
Payment Type Credit Account Container 483430
Manual Ticket# 1027993 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104300 lb*
In 09/06/2021 09:38:09 MANUAL WT vmckinne Tare 54500 lb*
Out 09/07/2021 09:38:09 vmckinne Net 49800 lb
Comments * Manual Weight Tons 24.90

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.90		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100			24.90		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 483539



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714582

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/07/2021 Vehicle# 483603 Volume
Payment Type Credit Account Container 483603
Manual ticket# 1027994 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104840 lb*
In 09/06/2021 09:39:04 MANUAL WT vmckinne Tare 54560 lb*
Out 09/07/2021 09:39:04 vmckinne Net 50280 lb
Comments * Manual Weight Tons 25.14

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.14		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100			25.14		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 441/707581/483430-9
Driver Name: Anthony Eggen Driver Signature: Anthony Eggen

Remarks: ET. 49,600 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714583

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/07/2021 Vehicle# 480605 Volume
Payment Type Credit Account Container 480605
Manual Ticket# 1028115 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105300 lb*
In 09/07/2021 09:45:25 MANUAL WT vmckinne Tare 53700 lb*
Out 09/07/2021 09:45:25 vmckinne Net 51600 lb
Comments * Manual Weight Tons 25.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.80	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-11-2021
Time scheduled for pickup 12:00

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 183603 Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck Class # 495 / W.M. 74 3136

Driver Name: Jason Michaels Driver Signature: _____

Remarks:
Den Lic
3213 B J 43 B WA
Op + p 2427



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714584

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/07/2021 Vehicle# 483233 Volume
Payment Type Credit Account Container 483233
Manual ticket# 1028116 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105480 lb*
In 09/07/2021 09:46:23 MANUAL WT vmckinne Tare 53120 lb*
Out 09/07/2021 09:46:23 vmckinne Net 52360 lb
Comments * Manual Weight Tons 26.18

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.18	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.18	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-2-21
Time scheduled for pickup 9:00

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115707WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck Class # 440-707287-480665

Driver Name: Scott F Hogan Driver Signature: _____

Remarks:
WDL 71122213B
LT WTL
48340



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714585

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/07/2021 Vehicle# 484015 Volume
Payment Type Credit Account Container 484015
Manual Ticket# 1028123 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 09:47:07 Scale MANUAL WT Operator vmckinne Inbound Gross 104460 lb*
Out 09/07/2021 09:47:07 vmckinne Tare 54220 lb*
Comments * Manual Weight Net 50240 lb
Tons 25.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.12	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.12	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9/2/2021
Time scheduled for pickup 9 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: No
Container in good condition: No
No free standing water: No
Customer is empty and clean: No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483233 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 415 + WM 743136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: DRIVER LIC
WDL 3213 BF-43 B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 714586

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 09/07/2021 Vehicle# 490002 Volume
Payment Type Credit Account Container 490002
Manual Ticket# 1028125 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 09:48:05 Scale MANUAL WT Operator vmckinne Inbound Gross 101300 lb*
Out 09/07/2021 09:48:05 vmckinne Tare 60880 lb*
Comments * Manual Weight Net 40420 lb
Tons 20.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		20.21	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	20.21	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: No
Container in good condition: No
No free standing water: No
Customer is empty and clean: No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 414-745140

Driver Name: BLAKE BARNETT Driver Signature: [Signature]

Remarks: WPL 2722793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715154

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/09/2021 Vehicle# 483722 Volume
Payment Type Credit Account Container 483722
Manual Ticket# 1027879 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 103780 lb*
In 09/04/2021 10:43:42 MANUAL WT vmckinne Tare 54920 lb*
Out 09/09/2021 10:43:42 vmckinne Net 48860 lb
Comments * Manual Weight Tons 24.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.43	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				
3 RAIL T SPW-RAIL BY 100		24.43	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer #: 4421707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: _____
can # 490002



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715155

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/08/2021 Vehicle# 480592 Volume
Payment Type Credit Account Container 480592
Manual ticket# 1028114 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 102880 lb*
In 09/07/2021 10:45:05 MANUAL WT vmckinne Tare 53640 lb*
Out 09/08/2021 10:45:05 vmckinne Net 49240 lb
Comments * Manual Weight Tons 24.62

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.62	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.62	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer #: 4421707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: _____
can # 435722



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715156

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483450 Volume
Payment Type Credit Account Container 483450
Manual Ticket# 1028117 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 10:45:48 Scale MANUAL WT Operator vmckinne Inbound Gross 100100 lb*
Out 09/08/2021 10:45:48 Tare vmckinne Net 54220 lb*
Comments * Manual Weight Tons 22.94

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.94	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.94	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Prefix: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Drop Off: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tare in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Line: 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 485450



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715157

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483475 Volume
Payment Type Credit Account Container 483475
Manual Ticket# 1028118 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 10:46:37 Scale MANUAL WT Operator vmckinne Inbound Gross 104240 lb*
Out 09/08/2021 10:46:37 Tare vmckinne Net 54380 lb*
Comments * Manual Weight Tons 24.93

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.93	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Prefix: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Drop Off: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tare in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Line: 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 1 2 End Time: _____

Transporter Name: _____ Truck/Chassis #: 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: 485450



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715158

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483485 Volume
Payment Type Credit Account Container 483485
Manual Ticket# 1028119 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 10:47:20 Scale Operator Inbound Gross 102880 lb*
Out 09/08/2021 10:47:20 MANUAL WT vmckinne Tare 51340 lb*
vmckinne Net 51540 lb
* Manual Weight Tons 25.77

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.77	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.77	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-202200-483475

Driver Name: Jeff Thomas Driver Signature: _____

Remarks: # WDL 7F79G-0170



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715159

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483531 Volume
Payment Type Credit Account Container 483531
Manual Ticket# 1028120 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/07/2021 10:48:03 Scale Operator Inbound Gross 103860 lb*
Out 09/08/2021 10:48:03 MANUAL WT vmckinne Tare 54480 lb*
vmckinne Net 49380 lb
* Manual Weight Tons 24.69

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.69	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.69	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-202200-483475

Driver Name: Jeff Thomas Driver Signature: _____

Remarks: # WDL 7F79G-013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715161

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483537 Volume
Payment Type Credit Account Container 483537
Manual Ticket# 1028121 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104260 lb*
In 09/07/2021 10:48:54	MANUAL WT	vmckinne		Tare	54240 lb*
Out 09/08/2021 10:48:54		vmckinne		Net	50020 lb
Comments					25.01
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.01	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.01	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4912
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name _____ Date _____ Signature _____ Name _____

Customer Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No other loading notes Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONT 483531

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTE Truck/Chassis #: 444-743140
Driver Name: BLAKE BOWEN Driver Signature: [Signature]

Remarks: WPL 0722LT93B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715161

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/08/2021 Vehicle# 484055 Volume
Payment Type Credit Account Container 484055
Manual Ticket# 1028124 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105520 lb*
In 09/07/2021 10:49:35	MANUAL WT	vmckinne		Tare	54480 lb*
Out 09/08/2021 10:49:35		vmckinne		Net	51040 lb
Comments					25.52
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.52	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.52	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4912
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name _____ Date _____ Signature _____ Name _____

Customer Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No other loading notes Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 443-702000-483537
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: # WDL 7R79G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715163

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/09/2021 Vehicle# 480514 Volume
Payment Type Credit Account Container 480514
Manual Ticket# 1027872 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	100340 lb*
09/09/2021	10:50:18	MANUAL WT	vmckinne		Tare	52240 lb*
09/09/2021	10:50:18		vmckinne		Net	48100 lb
Comments						24.05

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		24.05	Tons				WA-BELLEVUE
2				\$			WA-BELLEVUE
3		24.05	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: Start Time _____
End Time _____ Box # Out _____ Liers @ 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441 / 707381 / 424055-4

Driver Name: Michael Eggen Driver Signature: _____

Remarks: LT 49,580



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715164

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/09/2021 Vehicle# 480595 Volume
Payment Type Credit Account Container 480595
Manual Ticket# 1027873 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	103540 lb*
09/09/2021	10:51:07	MANUAL WT	vmckinne		Tare	54380 lb*
09/09/2021	10:51:07		vmckinne		Net	49160 lb
Comments						24.58

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		24.58	Tons				WA-BELLEVUE
2				\$			WA-BELLEVUE
3		24.58	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-2-2021
Time scheduled for pickup 2:00 pm

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 480514 Unloading: Start Time _____
End Time _____ Box # Out _____ Liers @ 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 + WM 742136

Driver Name: Jason Michael Driver Signature: _____

Remarks: Driver Lic WDL 3213 BT 43 B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715308

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483966 Volume
Payment Type Credit Account Container 483966
Manual Ticket# 1028250 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104660 lb*
In 09/08/2021 09:00:19	Front Scale	jaday		Tare	53820 lb*
Out 09/10/2021 09:00:19		jaday		Net	50840 lb
Comments				* Manual Weight	Tons 25.42

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.42	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.42	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONF 480595

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTC Truck/Chassis #: 444-745140

Driver Name: BRUCE BANETT Driver Signature: [Signature]

Remarks: WV 97812-6512



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715309

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 09/10/2021 Vehicle# 400501 Volume
Payment Type Credit Account Container 400501
Manual Ticket# 1028355 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96720 lb*
In 09/09/2021 09:06:17	Front Scale	jaday		Tare	50280 lb*
Out 09/10/2021 09:06:17		jaday		Net	46440 lb
Comments				* Manual Weight	Tons 23.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.22	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/16/2021
Time scheduled for pickup 10:40 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONF 483966

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 445 / JM 743136

Driver Name: Jason Michael Driver Signature: [Signature]

Remarks: dry Lic
2213 87 43 B - WA-
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715310

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container# 405004
Manual Ticket# 1028356 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97340 lb*
In 09/09/2021 09:07:52	Front Scale	jaday		Tare	51240 lb*
Out 09/10/2021 09:07:52		jaday		Net	46100 lb
Comments					23.05

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.05	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.05	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **443-702200** **40B501**

Driver Name: **Jesse Thomas** Driver Signature: _____

Remarks:
WDL 7R796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715311

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container# 405005
Manual Ticket# 1028357 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97260 lb*
In 09/09/2021 09:09:20	Front Scale	jaday		Tare	50940 lb*
Out 09/10/2021 09:09:20		jaday		Net	46320 lb
Comments					23.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.16	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9-9-21**
Time scheduled for pickup **9:40**

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **440-701287-406004**

Driver Name: **SCOTT F HOGAN** Driver Signature: _____

Remarks:
WDL # 7R22213B
LT Wt 45,800



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715312

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1028358 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	95400 lb*
In 09/09/2021 09:23:42	Front Scale	jaday		Tare	50540 lb*
Out 09/10/2021 09:23:42		jaday		Net	44860 lb
Comments					22.43
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.43	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.43	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck License: 94117075381/405 005-6
Driver Name: Arthur Egger Driver Signature: _____

Remarks: LT 45,780 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715313

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container 405011
Manual ticket# 1028359 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96960 lb*
In 09/09/2021 09:34:45	Front Scale	jaday		Tare	50540 lb*
Out 09/10/2021 09:34:45		jaday		Net	46420 lb
Comments					23.21
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.21	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.21	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck License: 94117075381/405 009-8
Driver Name: Arthur Egger Driver Signature: _____

Remarks: 45,780 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715314

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container 405013
Manual Ticket# 1028360 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96780 lb*
In 09/09/2021 09:36:29	Front Scale	jaday		Tare	50640 lb*
Out 09/10/2021 09:36:29		jaday		Net	46140 lb
Comments				* Manual Weight	Tons 23.07

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.07	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.07	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-21
Time scheduled for pickup 7:30

Waste Profile # 115787WA

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Inspection Upon Pickup
 Easy to load/unload condition:
 Container in good condition:
 No floor standing water:
 Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 440-707287-405011

Driver Name Scott F Hogan Driver Signature Scott F Hogan

Remarks
WDL # 71122213B
Gr
LT. 45660



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715315

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/10/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1028361 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96820 lb*
In 09/09/2021 09:38:07	Front Scale	jaday		Tare	49680 lb*
Out 09/10/2021 09:38:07		jaday		Net	47140 lb
Comments				* Manual Weight	Tons 23.57

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.57	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.57	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-8-2021
Time scheduled for pickup 8:00 AM

Waste Profile # 115787WA

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Inspection Upon Pickup
 Easy to load/unload condition:
 Container in good condition:
 No floor standing water:
 Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In 705013 Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 445 + vehicle 743136

Driver Name Jason Michaels Driver Signature _____

Remarks
Driver Lic
3213 B543B
exp 7-31-2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715316

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483088 Volume
Payment Type Credit Account Container 483088
Manual Ticket# 1028365 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104120 lb*
In 09/09/2021 09:40:41	Front Scale	jaday		Tare	54560 lb*
Out 09/10/2021 09:40:41		jaday		Net	49560 lb
Comments				* Manual Weight	Tons 24.78

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.78	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.78	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Water Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Disposed Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
can # 405016



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715317

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483210 Volume
Payment Type Credit Account Container 483210
Manual Ticket# 1028367 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106920 lb*
In 09/09/2021 09:42:01	Front Scale	jaday		Tare	56080 lb*
Out 09/10/2021 09:42:01		jaday		Net	50840 lb
Comments				* Manual Weight	Tons 25.42

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.42	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.42	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Water Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Disposed Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/707381/403-0838

Driver Name: Andrew Eggen Driver Signature: Andrew Eggen

Remarks:
IT 501620



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715318

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483353 Volume
Payment Type Credit Account Container 483353
Manual Ticket# 1028368 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 09/09/2021 09:49:54	Front Scale	jaday		103280 lb*
Out 09/10/2021 09:49:54		jaday		54460 lb*
		* Manual Weight		48820 lb
				Net Tons 24.41

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.41	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.41	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 444-743140

Driver Name: BLAKE BARKETT Driver Signature: [Signature]

Remarks: WDL 27221193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715319

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483557 Volume
Payment Type Credit Account Container 483557
Manual Ticket# 1028369 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 09/09/2021 09:53:57	Front Scale	jaday		103680 lb*
Out 09/10/2021 09:53:57		jaday		54120 lb*
		* Manual Weight		49560 lb
				Net Tons 24.78

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.78	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.78	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-8-21
Time scheduled for pickup 12:55

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707287-483353

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: WDL 71122213B Cr. LT.Wt 49,880



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715320

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483643 Volume
Payment Type Credit Account Container 483643
Manual Ticket# 1028370 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103140 lb*
In 09/09/2021 09:56:59	Front Scale	jaday		Tare	53640 lb*
Out 09/10/2021 09:56:59		jaday		Net	49500 lb
Comments					24.75
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.75	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.75	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 4421/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can #493557



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715321

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/10/2021 Vehicle# 483065 Volume
Payment Type Credit Account Container 483065
Manual Ticket# 1026671 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103820 lb*
In 09/08/2021 10:01:50	Front Scale	jaday		Tare	55360 lb*
Out 09/10/2021 10:01:50		jaday		Net	48460 lb
Comments					24.23
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.23	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.23	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-8-2021
Time scheduled for pickup 10:00 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483065 Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 + WM 743736

Driver Name: Jason Richards Driver Signature: Jason Richards

Remarks: Driver Lic WDL 3213 BJ 43 B exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715369

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/11/2021 Vehicle# 483622 Volume
Payment Type Credit Account Container 483622
Manual Ticket# 1026673 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106920 lb*
In 08/24/2021 08:54:54	Front Scale	jaday		Tare	57400 lb*
Out 09/11/2021 08:54:54		jaday		Net	49520 lb
Comments		* Manual Weight		Tons	24.76

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.76		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		24.76		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442 / 707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 493065



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715370

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/11/2021 Vehicle# 480619 Volume
Payment Type Credit Account Container 480619
Manual Ticket# 1028363 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	109140 lb*
In 09/09/2021 08:56:37	Front Scale	jaday		Tare	55820 lb*
Out 09/11/2021 08:56:37		jaday		Net	53320 lb
Comments		* Manual Weight		Tons	26.66

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		26.66		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		26.66		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 1 2 End Time _____

Transporter Name: _____ Truck/Trailer # 442 / 707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 483622



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715371

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/11/2021 Vehicle# 483047 Volume
Payment Type Credit Account Container 483047
Manual Ticket# 1028364 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105360 lb*
In 09/09/2021 08:58:41	Front Scale	jaday		Tare	55740 lb*
Out 09/11/2021 08:58:41		jaday		Net	49620 lb
Comments				* Manual Weight	Tons 24.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Phone: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONT 480619

Lading:
Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: CTE Truck/Chassis # 444-743140
Driver Name: BRUCE BARNETT Driver Signature: [Signature]
Remarks: WDL 2722 AT 930



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715372

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/12/2021 Vehicle# 483296 Volume
Payment Type Credit Account Container 483296
Manual Ticket# 1028510 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106300 lb*
In 09/10/2021 09:02:56	Front Scale	jaday		Tare	56640 lb*
Out 09/12/2021 09:02:56		jaday		Net	49660 lb
Comments				* Manual Weight	Tons 24.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.83	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.83	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Phone: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONT 483047

Lading:
Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: CTE Truck/Chassis # 444-743140
Driver Name: BRUCE BARNETT Driver Signature: [Signature]
Remarks: WDL 2722 AT 930

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **441-767381/483296**
Driver Name: **Adam Eggen** Driver Signature: _____

Remarks: **LT 49,820 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715373

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483692 Volume
Payment Type Credit Account Container# 483692
Manual Ticket# 1028513 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/10/2021 09:04:08 Scale Operator Inbound Gross 105360 lb*
Out 09/13/2021 09:04:08 Front Scale jaday jaday Tare 54980 lb*
Comments * Manual Weight Net 50380 lb
Tons 25.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.19	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9/9/21**
Time scheduled for pickup **8:50**

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115767WA**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **440-767387-1833492**
Driver Name: **Scott F Hagan** Driver Signature: _____

Remarks: **WTL # 71122213B LTWT 49740**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715607

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483189 Volume
Payment Type Credit Account Container# 483189
Manual Ticket# 1028245 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/08/2021 11:04:05 Scale Operator Inbound Gross 104420 lb*
Out 09/13/2021 11:04:05 MANUAL WT JVALDEZ JVALDEZ Tare 54220 lb*
Comments * Manual Weight Net 50200 lb
Tons 25.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.10	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.10	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-2021
Time scheduled for pickup 8:30 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LFO1

Acknowledgment of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483/89 Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 445 + W 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: Driver hic
WDL 3213 BJ 43 B

WP T-31-2121



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715608

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483616 Volume
Payment Type Credit Account Container 483616
Manual Ticket# 1028248 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101120 lb*
In 09/08/2021 11:06:04	MANUAL WT	JVALDEZ		Tare	53550 lb*
Out 09/13/2021 11:06:04		JVALDEZ		Net	47570 lb
Comments					23.79

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.79	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.79	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-21
Time scheduled for pickup 7:35

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LFO1

Acknowledgment of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 440-707297-483116

Driver Name: SCOTT F HOGAN Driver Signature: _____

Remarks: WDL# 71122213B
Gross Wt. 47,440
LT Wt.



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715609

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/13/2021 Vehicle# 480409 Volume
Payment Type Credit Account Container 480409
Manual Ticket# 1028505 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102300 lb*
In 09/10/2021 11:07:17	MANUAL WT	JVALDEZ		Tare	52540 lb*
Out 09/13/2021 11:07:17		JVALDEZ		Net	49760 lb
Comments					24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.88	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715610

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/13/2021 Vehicle# 480627 Volume
Payment Type Credit Account Container 480627
Manual Ticket# 1028507 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103700 lb*
In 09/08/2021 11:08:20	MANUAL WT	JVALDEZ		Tare	53920 lb*
Out 09/13/2021 11:08:20		JVALDEZ		Net	49780 lb
Comments				* Manual Weight	Tons 24.89

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.89	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.89	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-8-2021
Time scheduled for pickup 12:30 PM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container as empty and clean:

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Lading: WALWA
Start Time: _____ Box # In: 480409 Liters 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Liters 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis # 445 + WDL 74336

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driver Lic. WDL 3213 BJ 43 B exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715612

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483303 Volume
Payment Type Credit Account Container 483303
Manual Ticket# 1028511 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105060 lb*
In 09/10/2021 11:09:19	MANUAL WT	JVALDEZ		Tare	55640 lb*
Out 09/13/2021 11:09:19		JVALDEZ		Net	49420 lb
Comments				* Manual Weight	Tons 24.71

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.71	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.71	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition:
Container in good condition:
No free standing water:
Container as empty and clean:

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Lading: CONT#80627
Start Time: _____ Box # In: _____ Liters 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Liters 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis # 444-743140

Driver Name: BRUCE BARNETT Driver Signature: [Signature]

Remarks: WDL 74336 BJ 43 B exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715614

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483419 Volume
Payment Type Credit Account Container# 483419
Manual Ticket# 1028512 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105520 lb*
In 09/10/2021 11:10:35	MANUAL WT	JVALDEZ		Tare	55100 lb*
Out 09/13/2021 11:10:35		JVALDEZ		Net	50420 lb
Comments				* Manual Weight	Tons 25.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.21	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.21	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512) Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512) Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 4311/707381/485505
Driver Name: ANTHONY EPIFANIO Driver Signature: _____

Remarks: LT 499410 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715617

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483742 Volume
Payment Type Credit Account Container# 483742
Manual Ticket# 1028514 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103980 lb*
In 09/10/2021 11:11:40	MANUAL WT	JVALDEZ		Tare	53660 lb*
Out 09/13/2021 11:11:40		JVALDEZ		Net	50320 lb
Comments				* Manual Weight	Tons 25.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.16	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512) Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512) Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483419 Liers: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 445 + W4743136
Driver Name: ANTHONY MICHAEL Driver Signature: _____

Remarks: Driver lie
WDL 3213 BJ 43 B
09 13 2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715619

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483930 Volume
Payment Type Credit Account Container 483930
Manual Ticket# 1028515 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102520 lb*
In 09/03/2021 11:12:59	MANUAL WT	JVALDEZ		Tare	52680 lb*
Out 09/13/2021 11:12:59		JVALDEZ		Net	49840 lb
Comments				* Manual Weight	Tons 24.92

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.92	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-13-21
Time scheduled for pickup 11:47

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL Tarp Bar Report

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707387-483242

Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks: WDL # 71122138 LWT 49960



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715621

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483157 Volume
Payment Type Credit Account Container 483157
Manual Ticket# 1028623 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104480 lb*
In 09/11/2021 11:14:03	MANUAL WT	JVALDEZ		Tare	54300 lb*
Out 09/13/2021 11:14:03		JVALDEZ		Net	50180 lb
Comments				* Manual Weight	Tons 25.09

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.09	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.09	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200 483930

Driver Name: [Signature] Driver Signature: [Signature]

Remarks: # WDL 7R7940138



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715623

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/13/2021 Vehicle# 483258 Volume
 Payment Type Credit Account Container 483258
 Manual Ticket# 1028624 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 100360 lb*
 In 09/11/2021 11:15:05 MANUAL WT JVALDEZ Tare 56500 lb*
 Out 09/13/2021 11:15:05 JVALDEZ Net 43860 lb
 Comments * Manual Weight Tons 21.93

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		21.93	Tons				WA-BELLEVU
2 EVF-P6-Environment		100	\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY		100	21.93 Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
 Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
 18177 Cedar Springs Lane
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-4512
 Phone # (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
 Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
 End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 444-745140

Driver Name: LUKE BARNETT Driver Signature: LUKE BARNETT

Remarks: WHL 07222793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715623

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/13/2021 Vehicle# 483370 Volume
 Payment Type Credit Account Container 483370
 Manual Ticket# 1028625 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105120 lb*
 In 09/11/2021 11:16:11 MANUAL WT JVALDEZ Tare 55520 lb*
 Out 09/13/2021 11:16:11 JVALDEZ Net 49600 lb
 Comments * Manual Weight Tons 24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.80	Tons				WA-BELLEVU
2 EVF-P6-Environment		100	\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY		100	24.80 Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
 Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
 18177 Cedar Springs Lane
 18177 Cedar Springs Lane
 Arlington, Oregon 97812-4512
 Phone # (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
 Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
 End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: con # 493258



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715625

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483521 Volume
Payment Type Credit Account Container 483521
Manual Ticket# 1028627 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105120 lb*
In 09/11/2021 11:17:18	MANUAL WT	JVALDEZ		Tare	55360 lb*
Out 09/13/2021 11:17:18		JVALDEZ		Net	49760 lb
Comments				* Manual Weight	Tons 24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.88	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition No
Container in its good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 444-743140

Driver Name: PAUL BARNETT Driver Signature: [Signature]

Remarks: WDL 24221993B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715627

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483608 Volume
Payment Type Credit Account Container 483608
Manual Ticket# 1028629 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104960 lb*
In 09/11/2021 11:19:04	MANUAL WT	JVALDEZ		Tare	54980 lb*
Out 09/13/2021 11:19:04		JVALDEZ		Net	49980 lb
Comments				* Manual Weight	Tons 24.99

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.99	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.99	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition No
Container in its good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 443-702200 483521

Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: WDL 24221993B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715631

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483632 Volume
Payment Type Credit Account Container 483632
Manual Ticket# 1028630 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross
09/11/2021	11:33:32	MANUAL WT	JVALDEZ		105760 lb*
09/13/2021	11:33:32		JVALDEZ		55300 lb*
			* Manual Weight		Net 50460 lb
					Tons 25.23

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.23	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.23	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good working condition:
Container in good condition:
No free standing water:
Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 483608



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715632

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483838 Volume
Payment Type Credit Account Container 483838
Manual Ticket# 1028631 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross
09/11/2021	11:34:48	MANUAL WT	JVALDEZ		104080 lb*
09/13/2021	11:34:48		JVALDEZ		54480 lb*
			* Manual Weight		Net 49600 lb
					Tons 24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-8-21
Time scheduled for pickup 9:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good working condition:
Container in good condition:
No free standing water:
Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 442/707270-483632
Driver Name: Scott F Hogan Driver Signature: Scott F Hogan

Remarks: WPL# TJE2213B
or
LT 49,740



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715641

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/13/2021 Vehicle# 483104 Volume
Payment Type Credit Account Container 483104
Manual Ticket# 1028726 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105540 lb*
In 09/11/2021 12:08:41	MANUAL WT	JVALDEZ		Tare	55780 lb*
Out 09/13/2021 12:08:41		JVALDEZ		Net	49760 lb
Comments				* Manual Weight	Tons 24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.88	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Waste Type: CUL Contaminated Soil Asbestos Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WYL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **443-702202** **489876**

Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks: *** NEEDS NEW TARP!!**
WJL7R79G012B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 715642

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/08/2021 Vehicle# 483713 Volume
Payment Type Credit Account Container 483713
Manual Ticket# 1027878 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103440 lb*
In 09/04/2021 12:10:22	MANUAL WT	JVALDEZ		Tare	53440 lb*
Out 09/08/2021 12:10:22		JVALDEZ		Net	50000 lb
Comments				* Manual Weight	Tons 25.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.00	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.00	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9/10/2021**
Time scheduled for pickup **10:00 AM**

Customer Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Waste Type: CUL Contaminated Soil Asbestos Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WYL

Loading: Start Time _____ Box # In **WJL 483104** Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **443** + **WJL 743130**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks: **Driver Lic**
WJL 3213 BT 43 B
Cap 721 2427



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716111

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483580 Volume
Payment Type Credit Account Container 483580
Manual Ticket# 1028247 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105400 lb*
In 09/08/2021 13:31:41	Front Scale	jvaldez		Tare	55040 lb*
Out 09/14/2021 13:31:41		jvaldez		Net	50360 lb
		* Manual Weight		Tons	25.18

Comments REPLACEMENT TICKET FOR TICKET # 716000

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.18	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				
3 RAIL T SPW-RAIL BY 100		25.18	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Customer is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading:
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Vehicle # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
Can # 483713



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716112

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483747 Volume
Payment Type Credit Account Container 483747
Manual Ticket# 1028249 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106480 lb*
In 09/08/2021 13:44:53	Front Scale	jvaldez		Tare	55800 lb*
Out 09/14/2021 13:44:53		jvaldez		Net	50680 lb
		* Manual Weight		Tons	25.34

Comments REPLACEMENT TICKET FOR TICKET # 716003

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.34	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.34	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Customer is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____ Unloading:
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Vehicle # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
Can # 483540



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716113

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/14/2021 Vehicle# 484045 Volume
Payment Type Credit Account Container 484045
Manual Ticket# 1028371 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106120 lb*
In 09/09/2021 13:46:07	Front Scale	jvaldez		Tare	55440 lb*
Out 09/14/2021 13:46:07		jvaldez		Net	50680 lb
				* Manual Weight	Tons 25.34

Comments REPLACEMENT TICKET FOR TICKET # 716004

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.34	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.34	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name _____ Date _____
Signature _____ Name _____

Dispatcher: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Empty in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
Unloading: End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck # 495011702331/4857473
Driver Name: Jason Lopez Driver Signature: _____

Remarks: LT 49,500 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716114

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483563 Volume
Payment Type Credit Account Container 483563
Manual Ticket# 1028628 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106820 lb*
In 09/11/2021 13:47:22	Front Scale	jvaldez		Tare	55580 lb*
Out 09/14/2021 13:47:22		jvaldez		Net	51240 lb
				* Manual Weight	Tons 25.62

Comments REPLACEMENT TICKET FOR TICKET # 716005

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.62	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.62	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/14/21
Time scheduled for pickup 10:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name _____ Date _____
Signature _____ Name _____

Dispatcher: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Empty in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 484045 Lines 0 1 2 Start Time _____
Unloading: End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck # 495011702331/4857473
Driver Name: Jason Michaels Driver Signature: _____

Remarks: Drive Lic 3213 BT 43 B -04-

49 7-3 2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716115

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483994 Volume
Payment Type Credit Account Container 483994
Manual Ticket# 1028632 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*
In 09/11/2021 13:52:07	Front Scale	jvaldez		Tare	55520 lb*
Out 09/14/2021 13:52:07		jvaldez		Net	49720 lb
				* Manual Weight	24.86

Comments REPLACEMENT TICKET FOR TICKET # 716006

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.86	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-9-21
Time scheduled for pickup 7:50

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 New Pacific South International Facility (1807) Wash
42500 Stevens Road
North, Washington 98153
Phone: (206) 761-1100 or (206) 761-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck Chassis # 440-307287-1485563

Driver Name: Scott F Hager Driver Signature: _____

Remarks:
WDL 7162218B
KT 6549, 540



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716117

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/14/2021 Vehicle# 484000 Volume
Payment Type Credit Account Container 484000
Manual Ticket# 1028632 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105320 lb*
In 09/11/2021 13:53:51	Front Scale	jvaldez		Tare	55240 lb*
Out 09/14/2021 13:53:51		jvaldez		Net	50080 lb
				* Manual Weight	25.04

Comments REPLACEMENT TICKET FOR TICKET # 716007

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.04	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.04	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 New Pacific South International Facility (1807) Wash
42500 Stevens Road
North, Washington 98153
Phone: (206) 761-1100 or (206) 761-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck Chassis # 4417075301/4839949

Driver Name: Anthony Equik Driver Signature: _____

Remarks:
ET 49,620160



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716118

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483089 Volume
Payment Type Credit Account Container 483089
Manual Ticket# 1028725 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104760 lb*
In 09/12/2021 13:55:44	Front Scale	jvaldez		Tare	55860 lb*
Out 09/14/2021 13:55:44		jvaldez		Net	48900 lb
				* Manual Weight	24.45

Comments REPLACEMENT TICKET FOR TICKET # 716008

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.45	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.45	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9/10/2021
Time scheduled for pickup 8:00 AM

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
483 Cedar Springs Lane
Arlington, Oregon 97812
Phone (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In **484000** Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name **CTI** Truck Basis # **445** **WM 743136**

Driver Name **Jason Michaels** Driver Signature _____
Remarks
**Driver Lic
WDL 3213 BT 43 B
exp 7/31/2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716120

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483215 Volume
Payment Type Credit Account Container 483215
Manual Ticket# 1028727 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105640 lb*
In 09/12/2021 13:56:57	Front Scale	jvaldez		Tare	56100 lb*
Out 09/14/2021 13:56:57		jvaldez		Net	49540 lb
				* Manual Weight	24.77

Comments REPLACEMENT TICKET FOR TICKET # 716009

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.77	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.77	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
483 Cedar Springs Lane
Arlington, Oregon 97812
Phone (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name **CTI** Truck Basis # **441/707581/483089**

Driver Name **Adrian Egan** Driver Signature _____
Remarks
H 50,401lb



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716122

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483374 Volume
Payment Type Credit Account Container 483374
Manual Ticket# 1027876 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106140 lb*
In 09/04/2021 13:58:12	Front Scale	jvaldez		Tare	55580 lb*
Out 09/14/2021 13:58:12		jvaldez		Net	50560 lb
		* Manual Weight		Tons	25.28

Comments REPLACEMENT TICKET FOR TICKET # 716101

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.28	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.28	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-18-21
Time scheduled for pickup 10:00

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name: _____ Date: _____ Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in proper and closed: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: STI Truck/Chassis # 440-701297-483215
Driver Name: Scott Hogan Driver Signature: [Signature]

Remarks: L.T.Wt. 49,749
WDL# TTT22213B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716126

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483522 Volume
Payment Type Credit Account Container 483522
Manual Ticket# 1028730 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104660 lb*
In 09/12/2021 13:59:25	Front Scale	jvaldez		Tare	55300 lb*
Out 09/14/2021 13:59:25		jvaldez		Net	49360 lb
		* Manual Weight		Tons	24.68

Comments REPLACEMENT TICKET FOR TICKET # 716011

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.68	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.68	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: Company Name: _____ Date: _____ Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Ramp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in proper and closed: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: STI Truck/Chassis # 440-701297-483215
Driver Name: Arthur Engel Driver Signature: [Signature]

Remarks: 49,260 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716127

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483473 Volume
Payment Type Credit Account Container 483473
Manual Ticket# 1027877 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103580 lb*
In 09/04/2021 14:00:45	Front Scale	jvaldez		Tare	53800 lb*
Out 09/14/2021 14:00:45		jvaldez		Net	49780 lb
		* Manual Weight		Tons	24.89

Comments REPLACEMENT TICKET FOR TICKET # 716012

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.89	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.89	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
SWAP

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____
Transporter Name: CTC Truck/Chassis #: 444-743140
Driver Name: PAUL ROBERT Driver Signature: [Signature]
Remarks: WOL 97812-6512



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716131

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/14/2021 Vehicle# 405014 Volume
Payment Type Credit Account Container 405014
Manual ticket# 1028722 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97080 lb*
In 09/12/2021 14:03:00	Front Scale	jvaldez		Tare	51240 lb*
Out 09/14/2021 14:03:00		jvaldez		Net	45840 lb
		* Manual Weight		Tons	22.92

Comments REPLACEMENT TICKET FOR TICKET # 716013

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	22.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.92	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL
SWAP

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 443-702200 483473
Driver Name: JEFF THOMAS Driver Signature: [Signature]
Remarks: # WOL 7R-796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716133

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/14/2021 Vehicle# 405017 Volume
Payment Type Credit Account Container 405017
Manual Ticket# 1028723 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98640 lb*
In 09/12/2021 14:04:36	Front Scale	jvaldez		Tare	51360 lb*
Out 09/14/2021 14:04:36		jvaldez		Net	47280 lb
		* Manual Weight		Tons	23.64

Comments REPLACEMENT TICKET FOR TICKET # 716014

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.64	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.64	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Libers 0 1 2 Start Time _____
End Time _____ Libers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 40504



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716134

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/14/2021 Vehicle# 480446 Volume
Payment Type Credit Account Container 480446
Manual Ticket# 1028822 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102480 lb*
In 09/14/2021 14:06:21	Front Scale	jvaldez		Tare	51440 lb*
Out 09/14/2021 14:06:21		jvaldez		Net	51040 lb
		* Manual Weight		Tons	25.52

Comments REPLACEMENT TICKET FOR TICKET # 716015

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.52	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.52	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: _____
End Time _____ Box # Out _____ Libers 0 1 2 Start Time _____
End Time _____ Libers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 441/707281/405017-0
Driver Name: Arthur Egger Driver Signature: Arthur Egger

Remarks: LT 45,580



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716135

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/14/2021 Vehicle# 483672 Volume
Payment Type Credit Account Container 483672
Manual Ticket# 1028825 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104480 lb*
In 09/14/2021 14:07:30	Front Scale	jvaldez		Tare	55000 lb*
Out 09/14/2021 14:07:30		jvaldez		Net	49480 lb
		* Manual Weight		Tons	24.74

Comments REPLACEMENT TICKET FOR TICKET # 716016

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.74	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-9-2021
Time scheduled for pickup 14:07:30

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane, Suite 1000, Arlington, OR 97812
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Box # In WMXL Unloading: _____
Start Time _____ Box # Out _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Track # 445 * WM 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks: Driver Lic
WDL 3213 BT 43 B
sep 9 2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716136

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 09/14/2021 Vehicle# 490003 Volume
Payment Type Credit Account Container 490003
Manual Ticket# 1028828 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103980 lb*
In 09/14/2021 14:08:39	Front Scale	jvaldez		Tare	54120 lb*
Out 09/14/2021 14:08:39		jvaldez		Net	49860 lb
		* Manual Weight		Tons	24.93

Comments REPLACEMENT TICKET FOR TICKET # 716017

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.93	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane, Suite 1000, Arlington, OR 97812
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Box # In _____ Unloading: _____
Start Time _____ Box # Out _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Track # 443-702200 483672

Driver Name: Jeff Thomas Driver Signature: _____
Remarks: # WDL 7R79G 013 B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716164

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483084 Volume
Payment Type Credit Account Container 483084
Manual Ticket# 1027468 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101720 lb*
In 09/01/2021 12:15:27	Front Scale	jvaldez		Tare	54980 lb*
Out 09/15/2021 12:15:27		jvaldez		Net	46740 lb
Comments				* Manual Weight	Tons
					23.37

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.37	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				
3 RAIL T SPW-RAIL BY	100	23.37	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone #: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck #/Trailer # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 490003



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716165

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483538 Volume
Payment Type Credit Account Container 483538
Manual Ticket# 1028246 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104180 lb*
In 09/08/2021 12:17:00	Front Scale	jvaldez		Tare	56740 lb*
Out 09/15/2021 12:17:00		jvaldez		Net	47440 lb
Comments				* Manual Weight	Tons
					23.72

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.72	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.72	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone #: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck #/Trailer # 441/7073231/4835054

Driver Name: William Egge Driver Signature: William Egge

Remarks: LT 50,200120



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716166

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/15/2021 Vehicle# 480519 Volume
Payment Type Credit Account Container 480519
Manual Ticket# 1028362 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105300 lb*
In 09/09/2021 12:18:20	Front Scale	jvaldez		Tare	54820 lb*
Out 09/15/2021 12:18:20		jvaldez		Net	5480 lb
Comments					25.24
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.24	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.24	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concrete Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-707206 / 4835658-9**
Driver Name: **Thomas** Driver Signature: _____

Remarks: **Lt. 49, 820103**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716167

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/15/2021 Vehicle# 480415 Volume
Payment Type Credit Account Container 480415
Manual ticket# 1028506 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96680 lb*
In 09/10/2021 12:19:40	Front Scale	jvaldez		Tare	52560 lb*
Out 09/15/2021 12:19:40		jvaldez		Net	44120 lb
Comments					22.06
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.06	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.06	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concrete Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-707206 / 480519**
Driver Name: **Thomas** Driver Signature: _____

Remarks: **# WDL 7A79G013D**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716171

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483117 Volume
Payment Type Credit Account Container 483117
Manual Ticket# 1028508 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105260 lb*
In 09/10/2021 12:43:37	MANUAL WT	jvaldez		Tare	55080 lb*
Out 09/15/2021 12:43:37		jvaldez		Net	50180 lb
Comments				* Manual Weight	Tons 25.09

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.09	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				
3 RAIL T SPW-RAIL BY 100		25.09	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 ton Bulk, Single itemized footer (3000) load
PCE Bulk Storage Bin
North, Washington #111
Phone: (509) 325-7410

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liers # 1 2 Start Time _____
End Time _____ Box # Out _____ Liers # 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 430415



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716172

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483240 Volume
Payment Type Credit Account Container 483240
Manual Ticket# 1028509 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104880 lb*
In 09/10/2021 12:45:22	MANUAL WT	jvaldez		Tare	55400 lb*
Out 09/15/2021 12:45:22		jvaldez		Net	49480 lb
Comments				* Manual Weight	Tons 24.74

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.74	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 ton Bulk, Single itemized footer (3000) load
PCE Bulk Storage Bin
North, Washington #111
Phone: (509) 325-7410

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liers # 1 2 Start Time _____
End Time _____ Box # Out _____ Liers # 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/757206/483117

Driver Name: Arthur Eggen Driver Signature: Arthur Eggen

Remarks: LA 10/30



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716173

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483009 Volume
Payment Type Credit Account Container 483009
Manual Ticket# 1028925 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106240 lb*
In 09/11/2021 12:46:34	MANUAL WT	jvaldez		Tare	56420 lb*
Out 09/15/2021 12:46:34		jvaldez		Net	49820 lb
Comments				* Manual Weight	Tons 24.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.91	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.91	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____ Date: _____
Company Name: _____ Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing waste Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442/707 270
Driver Name: Brendan Osborne Driver Signature: Brendan Osborne

Remarks: can # 240 493 420



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716175

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483421 Volume
Payment Type Credit Account Container 483421
Manual Ticket# 1028626 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104860 lb*
In 09/11/2021 13:06:15	MANUAL WT	jvaldez		Tare	55400 lb*
Out 09/15/2021 13:06:15		jvaldez		Net	49460 lb
Comments				* Manual Weight	Tons 24.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____ Date: _____
Company Name: _____ Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing waste Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442/707 270/483009
Driver Name: Arnell Egan Driver Signature: Arnell Egan

Remarks: 51,200 lbs

32021

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-10-2021
Time scheduled for pickup 1:00 pm

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115707WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Columbia Ridge Landfill and Recycling Center
825 Oak Street
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading: WAX4
Start Time: _____ Box # In: 483421 Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 4415 + WA 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____
Driver Lic
WDL 3213 BJ 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716176

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/15/2021 Vehicle# 405003 Volume
Payment Type Credit Account Container 405003
Manual Ticket# 1028719 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97080 lb*
In 09/12/2021 13:07:52	MANUAL WT	jvaldez		Tare	51260 lb*
Out 09/15/2021 13:07:52		jvaldez		Net	45720 lb
Comments				* Manual Weight	Tons 22.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		22.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.86	Tons				WA-BELLEVUE

Driver's Signature

32021

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-2021
Time scheduled for pickup 2:00 pm

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115707WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Columbia Ridge Landfill and Recycling Center
825 Oak Street
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading: WAX4
Start Time: _____ Box # In: 405003 Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 4415 + WA 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____
Driver Lic
WDL 3213 BJ 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716177

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/15/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container 405007
Manual Ticket# 1028720 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97320 lb*
In 09/12/2021 13:10:21	MANUAL WT	jvaldez		Tare	51060 lb*
Out 09/15/2021 13:10:21		jvaldez		Net	46260 lb
Comments				* Manual Weight	Tons 23.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.13	Tons				WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-21
Time scheduled for pickup 2:40

Generate Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 440-107267-405007

Driver Name: Scott F Hogan Driver Signature: Scott F Hogan

Remarks: # WDL 7112213B cr LT 45700



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716178

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/15/2021 Vehicle# 405012 Volume
Payment Type Credit Account Container# 405012
Manual Ticket# 1028721 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96780 lb*
In 09/12/2021 13:12:29	MANUAL WT	jvaldez		Tare	50960 lb*
Out 09/15/2021 13:12:29		jvaldez		Net	45820 lb
Comments				* Manual Weight	Tons
					22.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		22.91			WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		22.91			WA-BELLEVUE

Driver's Signature

WM Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 443-707200 40501Y

Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks: # WDL 7R796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716179

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/15/2021 Vehicle# 480631 Volume
Payment Type Credit Account Container# 480631
Manual Ticket# 1028724 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102620 lb*
In 09/12/2021 13:14:22	MANUAL WT	jvaldez		Tare	54180 lb*
Out 09/15/2021 13:14:22		jvaldez		Net	48440 lb
Comments				* Manual Weight	Tons
					24.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.22			WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		24.22			WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716180

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483406 Volume
Payment Type Credit Account Container# 483406
Manual Ticket# 1028729 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104560 lb*
In 09/12/2021 13:17:35	MANUAL WT	jvaldez		Tare	55100 lb*
Out 09/15/2021 13:17:35		jvaldez		Net	49460 lb
Comments				* Manual Weight	Tons 24.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.73	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-10-2021
Time scheduled for pickup 3:00 p.m.

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Leaving: _____ Unloading: _____
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Class # 445-UM 743136
Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____
Driver Lic: 3213 BT 43 B WA
Exp: 7-1-2017



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716181

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483532 Volume
Payment Type Credit Account Container# 483532
Manual Ticket# 1028731 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103860 lb*
In 09/12/2021 13:19:21	MANUAL WT	jvaldez		Tare	54480 lb*
Out 09/15/2021 13:19:21		jvaldez		Net	49380 lb
Comments				* Manual Weight	Tons 24.69

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.69	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.69	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Leaving: _____ Unloading: _____
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Class # 444-743140
Driver Name: BAILE BARNETT Driver Signature: ALC. B

Remarks: WDL 07221793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716182

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483854 Volume
Payment Type Credit Account Container 483854
Manual Ticket# 1028732 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107360 lb*
In 09/12/2021 13:21:20	MANUAL WT	jvaldez		Tare	55280 lb*
Out 09/15/2021 13:21:20		jvaldez		Net	52080 lb
Comments				* Manual Weight	Tons 26.04

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.04	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.04	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-9-21
Time scheduled for pickup 2:45

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707287-483532

Driver Name: SCOTT F Hagan Driver Signature: [Signature]

Remarks: WDL 71722213B LTWT 50,070



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716183

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/15/2021 Vehicle# 484001 Volume
Payment Type Credit Account Container 484001
Manual Ticket# 1028733 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104780 lb*
In 09/12/2021 13:24:35	MANUAL WT	jvaldez		Tare	55380 lb*
Out 09/15/2021 13:24:35		jvaldez		Net	49400 lb
Comments				* Manual Weight	Tons 24.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.70	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.70	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____ Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441-707381/483854

Driver Name: Arthur Equil Driver Signature: [Signature]

Remarks: LT 49,560 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716184

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483271 Volume
Payment Type Credit Account Container 483271
Manual Ticket# 1028823 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104120 lb*
In 09/14/2021 13:26:21	MANUAL WT	jvaldez		Tare	55860 lb*
Out 09/15/2021 13:26:21		jvaldez		Net	48260 lb
Comments				* Manual Weight	Tons 24.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.13	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.13	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CT1 Truck # 443-707200 4/8406
Driver Name: Jesse Thomas Driver Signature: _____

Remarks: # WDL 7R79G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716185

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483530 Volume
Payment Type Credit Account Container 483530
Manual Ticket# 1028824 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103980 lb*
In 09/14/2021 13:28:07	MANUAL WT	jvaldez		Tare	55520 lb*
Out 09/15/2021 13:28:07		jvaldez		Net	48460 lb
Comments				* Manual Weight	Tons 24.23

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.23	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.23	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CT1 Truck # 441/707206/4835071
Driver Name: Arthur Egger Driver Signature: _____

Remarks: Net Weight 50,040 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716186

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483991 Volume
Payment Type Credit Account Container 483991
Manual Ticket# 1028827 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104640 lb*
In 09/14/2021 13:34:35	MANUAL WT	jvaldez		Tare	54060 lb*
Out 09/15/2021 13:34:35		jvaldez		Net	50580 lb
Comments				* Manual Weight	Tons 25.29

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.29	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.29	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liers 1 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-707200-483590

Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks:
#WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716187

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483227 Volume
Payment Type Credit Account Container 483227
Manual Ticket# 1028923 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105300 lb*
In 09/12/2021 13:36:13	MANUAL WT	jvaldez		Tare	55120 lb*
Out 09/15/2021 13:36:13		jvaldez		Net	50180 lb
Comments				* Manual Weight	Tons 25.09

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.09	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.09	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 7-27-21
Time scheduled for pickup 10:05

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liers 0 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 44070722-483991

Driver Name: SEAN F HOGAN Driver Signature: [Signature]

Remarks:
WT 49740
WDL 7T-22213B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716188

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/15/2021 Vehicle# 405006 Volume
Payment Type Credit Account Container# 405006
Manual Ticket# 1028913 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98260 lb*
In 09/14/2021 13:38:12	MANUAL WT	jvaldez		Tare	51780 lb*
Out 09/15/2021 13:38:12		jvaldez		Net	46480 lb
Comments				* Manual Weight	Tons
					23.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.24	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.24	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Drop off to: _____ Disposal Facility: _____
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512 Arlington, Oregon 97812-4512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Easy to load/unload condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # M2 1707270
Driver Name: Randa Osborne Driver Signature: Randa Osborne

Remarks: can # 483 227



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716189

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/15/2021 Vehicle# 405008 Volume
Payment Type Credit Account Container# 405008
Manual ticket# 1028919 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96140 lb*
In 09/14/2021 13:40:06	MANUAL WT	jvaldez		Tare	50100 lb*
Out 09/15/2021 13:40:06		jvaldez		Net	46040 lb
Comments				* Manual Weight	Tons
					23.02

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.02	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.02	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-21
Time scheduled for pickup 12:30

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Drop off to: _____ Disposal Facility: _____
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512 Arlington, Oregon 97812-4512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Easy to load/unload condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 440-707287-405006
Driver Name: SCOTT F HOGAN Driver Signature: Scott F Hogan

Remarks: WDE # 77122213 B
Cr
LT.45.42d



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716190

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/15/2021 Vehicle# 484008 Volume
Payment Type Credit Account Container 484008
Manual Ticket# 1028921 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100100 lb*
In 09/15/2021 13:42:25	MANUAL WT	jvaldez		Tare	54260 lb*
Out 09/15/2021 13:42:25		jvaldez		Net	45840 lb
Comments				* Manual Weight	Tons
					22.92

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.92	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-2021
Time scheduled for pickup 11:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Local Public Solid Waste Dept (SWM) Unit
 AC/Local Business House
 Retail, Wholesale, etc.
 Private (Other than AC/Local Business House)

Disposal Facility: Columbia Ridge Landfill and Recycling Center
 WTL (Other than AC/Local Business House)
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free-standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 405008 Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck #/Plate: 4455 + WM 743136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driv Lic
WDL 3213 BT 433
exp 7-31-2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716191

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/15/2021 Vehicle# 483684 Volume
Payment Type Credit Account Container 483684
Manual Ticket# 1028826 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104560 lb*
In 09/14/2021 13:43:45	MANUAL WT	jvaldez		Tare	55340 lb*
Out 09/15/2021 13:43:45		jvaldez		Net	49220 lb
Comments				* Manual Weight	Tons
					24.61

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.61	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.61	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Local Public Solid Waste Dept (SWM) Unit
 AC/Local Business House
 Retail, Wholesale, etc.
 Private (Other than AC/Local Business House)

Disposal Facility: Columbia Ridge Landfill and Recycling Center
 WTL (Other than AC/Local Business House)
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free-standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck #/Plate: 4411/702331/484008-7

Driver Name: Arturo Egoz Driver Signature: [Signature]

Remarks: Dr. 49,8401100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716489

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405019 Volume
Payment Type Credit Account Container 405019
Manual Ticket# 1028820 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98900 lb*
In 09/14/2021 12:40:01	MANUAL WT	jvaldez		Tare	51700 lb*
Out 09/16/2021 12:40:01		jvaldez		Net	47200 lb
Comments				* Manual Weight	Tons 23.60

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.60	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				
3 RAIL T SPW-RAIL BY	100	23.60	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Unloading: Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: **CTI** Truck/Trailer #: **443-707200 483684**

Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks: **# WDL 7F794213B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716491

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1028931 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97560 lb*
In 09/15/2021 12:42:26	MANUAL WT	jvaldez		Tare	50480 lb*
Out 09/16/2021 12:42:26		jvaldez		Net	47080 lb
Comments				* Manual Weight	Tons 23.54

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.54	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.54	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Customer is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Unloading: Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: **CTI** Truck/Trailer #: **441707381/405019-0**

Driver Name: **Anthony Egger** Driver Signature: _____

Remarks: **LT 451520110 45200**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716493

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1028933 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97680 lb*
In 09/15/2021 12:44:15	MANUAL WT	jvaldez		Tare	50760 lb*
Out 09/16/2021 12:44:15		jvaldez		Net	46920 lb
Comments				* Manual Weight	Tons 23.46

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.46	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.46	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 401/707 270
Driver Name: Brendan Osborne Driver Signature: Brendan Osborne

Remarks: can # 405009



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716494

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1028934 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	99020 lb*
In 09/08/2021 12:45:57	MANUAL WT	jvaldez		Tare	50480 lb*
Out 09/16/2021 12:45:57		jvaldez		Net	48540 lb
Comments				* Manual Weight	Tons 24.27

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.27	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.27	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-13-2021
Time scheduled for pickup 10:00 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 405013 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 445 WM 743130
Driver Name: Jason Michaels Driver Signature: Jason Michaels

Remarks: Driver Lic
WDL 3213 B5 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717241

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483291 Volume
Payment Type Credit Account Container 483291
Manual Ticket# 1028728 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	111460 lb*
In 09/21/2021 10:34:36	MANUAL WT	vmckinne		Tare	54640 lb*
Out 09/21/2021 10:34:36		vmckinne		Net	56820 lb
Comments				* Manual Weight	Tons 28.41

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		28.41	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				
3 RAIL T SPW-RAIL BY	100	28.41	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-14-21
Time scheduled for pickup 9:25

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading: Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: CTI Truck/Trailer # 440-70287-405016

Driver Name: SCOTT HOGAN Driver Signature: [Signature]

Remarks: WDL # 711222133 LFW 45,480



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717242

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483265 Volume
Payment Type Credit Account Container 483265
Manual ticket# 1024757 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100000 lb*
In 08/02/2021 10:35:16	MANUAL WT	vmckinne		Tare	47000 lb*
Out 09/21/2021 10:35:16		vmckinne		Net	53000 lb
Comments				* Manual Weight	Tons 26.50

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	26.50	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-2021
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: Core Transport Inc. Date: 9-7-2021
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483291 Unloading: Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: _____ Truck/Trailer # _____

Driver Name: _____ Driver Signature: [Signature]

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717245

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/21/2021 Vehicle# 405020 Volume
Payment Type Credit Account Container 405020
Manual Ticket# 1028821 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	95880 lb*
In 09/14/2021 10:37:03	MANUAL WT	vmckinne		Tare	50040 lb*
Out 09/21/2021 10:37:03		vmckinne		Net	45840 lb
Comments					22.92
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.92	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 7-27-2021
Time scheduled for pickup 12:149

Customer Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Contract Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: CITY TRANSFER INC. Date: 7-27-2021
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good accessible condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No fire hazard noted	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483265 Lines # 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines # 1 2 End Time: _____

Transporter Name: CITY TRANSFER INC. Truck/Trailer # 743136
Driver Name: Jason Matthews Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717573

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/22/2021 Vehicle# 405015 Volume
Payment Type Credit Account Container 405015
Manual Ticket# 1029491 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97320 lb*
In 09/21/2021 13:51:12	MANUAL WT	vmckinne		Tare	50620 lb*
Out 09/22/2021 13:51:12		vmckinne		Net	46700 lb
Comments					23.35
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.35	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.35	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-7-2021
Time scheduled for pickup 11:54

Customer Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Contract Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: CITY TRANSFER INC. Date: 9-7-2021
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good accessible condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No fire hazard noted	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 405020 Lines # 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines # 1 2 End Time: _____

Transporter Name: _____ Truck/Trailer # 707210
Driver Name: _____ Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717574

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/22/2021 Vehicle# 483979 Volume
Payment Type Credit Account Container 483979
Manual Ticket# 1029493 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101960 lb*
In 09/21/2021 13:52:18	MANUAL WT	vmckinne		Tare	54940 lb*
Out 09/22/2021 13:52:18		vmckinne		Net	47020 lb
Comments				* Manual Weight	Tons
					23.51

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.51	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.51	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 7-27-2021
Time scheduled for pickup 8:00 a.m.

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tary in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time 4:50:15 Box # 1 Unloading Start Time _____
End Time _____ Box # 1 End Time _____
Transporter Name: CTI Truck/Trailer # 415 / WA 713136

Driver Name: _____ Driver Signature: _____

Remarks: _____

WA Driver Lic # 3213 BT43B WA



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717575

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/22/2021 Vehicle# 483980 Volume
Payment Type Credit Account Container 483980
Manual Ticket# 1029494 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106620 lb*
In 09/21/2021 13:58:10	MANUAL WT	vmckinne		Tare	54940 lb*
Out 09/22/2021 13:58:10		vmckinne		Net	51680 lb
Comments				* Manual Weight	Tons
					25.84

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.84	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.84	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tary in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time 8:15 Box # 1 Unloading Start Time _____
End Time 8:25 Box # 483979 End Time _____
Transporter Name: CTI Truck/Trailer # 444-743271

Driver Name: BLAKE BRUNETT Driver Signature: Mc B

Remarks: _____

WDL# 27222793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717576

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/22/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container# 405016
Manual Ticket# 1029620 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103480 lb*
In 09/22/2021 13:58:50	MANUAL WT	vmckinne		Tare	53720 lb*
Out 09/22/2021 13:58:50		vmckinne		Net	49760 lb
Comments				* Manual Weight	Tons 24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.88	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-25-2021
Time scheduled for pickup 1:00 pm
Waste Profile # 115787WA

Generate Name and Loading Address
SCD NE 8TH
Waste Type CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In 453980 Liers 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck # Basis # 4415 WM 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks:
Driver Lic
WDL 3213 BT 43 B
cap 7.21.2017



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717577

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/22/2021 Vehicle# 483208 Volume
Payment Type Credit Account Container# 483208
Manual Ticket# 1029622 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96200 lb*
In 09/22/2021 13:59:40	MANUAL WT	vmckinne		Tare	49440 lb*
Out 09/22/2021 13:59:40		vmckinne		Net	46760 lb
Comments				* Manual Weight	Tons 23.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.38	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____
Waste Profile # 115787WA

Generate Name and Loading Address
SCD NE 8TH
Waste Type CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In _____ Liers 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: CTI Truck # Basis # 441707270

Driver Name: Brandon Osborne Driver Signature: _____
Remarks:
can # 405016



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717579

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/22/2021 Vehicle# 483350 Volume
Payment Type Credit Account Container 483350
Manual Ticket# 1029625 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105080 lb*
In 09/22/2021 14:00:16	MANUAL WT	vmckinne		Tare	55680 lb*
Out 09/22/2021 14:00:16		vmckinne		Net	49400 lb
Comments				* Manual Weight	Tons
					24.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.70	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.70	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/21/2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone # (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483208 Lines # 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 with 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: Driver Lic
WDL 3213 BT 43 B
cap 7/31/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717580

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/22/2021 Vehicle# 483909 Volume
Payment Type Credit Account Container 483909
Manual Ticket# 1029628 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105260 lb*
In 09/22/2021 14:01:07	MANUAL WT	vmckinne		Tare	54500 lb*
Out 09/22/2021 14:01:07		vmckinne		Net	50760 lb
Comments				* Manual Weight	Tons
					25.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.38	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone # (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines # 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 with 743136

Driver Name: Arthur Lopez Driver Signature: _____

Remarks: ET



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717845

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/23/2021 Vehicle# 480401 Volume
Payment Type Credit Account Container 480401
Manual Ticket# 1029624 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107640 lb*
In 09/22/2021 10:12:29	Front Scale	jaday		Tare	55640 lb*
Out 09/23/2021 10:12:29		jaday		Net	52000 lb
Comments				* Manual Weight	Tons 26.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.00	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.00	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1-800-Pacific South America facility (800) 401-1000
451 South Service Street
South, Portland, OR 97208
Phone: (503) 241-1111 or (503) 241-1112

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No flow standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____

Transporter Name: **CTC** Truck/Trailer # **441/707331/435909-1**

Driver Name: **Anthony Caputo** Driver Signature: *[Signature]*

Remarks: **LT 49,680 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717846

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/23/2021 Vehicle# 483346 Volume
Payment Type Credit Account Container 483346
Manual Ticket# 1029624 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	109180 lb*
In 09/22/2021 10:15:23	Front Scale	jaday		Tare	56580 lb*
Out 09/23/2021 10:15:23		jaday		Net	52600 lb
Comments				* Manual Weight	Tons 26.30

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.30	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.30	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1-800-Pacific South America facility (800) 401-1000
451 South Service Street
South, Portland, OR 97208
Phone: (503) 241-1111 or (503) 241-1112

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No flow standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____

Transporter Name: **CTC** Truck/Trailer # **444-745130**

Driver Name: **PAUL BARNETT** Driver Signature: *[Signature]*

Remarks: **CONTR 480401**
MPV 2722793B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717847

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/23/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1029735 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97260 lb*
In 09/22/2021 10:17:44	Front Scale	jaday		Tare	51160 lb*
Out 09/23/2021 10:17:44		jaday		Net	46100 lb
Comments				* Manual Weight	Tons 23.05

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		23.05		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		23.05		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Contract Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 405 Pacific South International Facility (40503) 405 South Street North, Multnomah, OR 97131 Phone: (503) 251-1111 or 1-800-271-5444

Dispose Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition Yes No Contaminated in its good condition Yes No No free standing water Yes No Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200 483346

Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: 101420 50060
WDL# 7R794013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717849

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/23/2021 Vehicle# 483701 Volume
Payment Type Credit Account Container 483701
Manual Ticket# 1029492 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105400 lb*
In 09/21/2021 10:20:30	Front Scale	jaday		Tare	58200 lb*
Out 09/23/2021 10:20:30		jaday		Net	47200 lb
Comments				* Manual Weight	Tons 23.60

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		23.60		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		23.60		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-21-21
Time scheduled for pickup 9:30

Contract Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 405 Pacific South International Facility (40503) 405 South Street North, Multnomah, OR 97131 Phone: (503) 251-1111 or 1-800-271-5444

Dispose Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition Yes No Contaminated in its good condition Yes No No free standing water Yes No Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707207 405024

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: WDL# 7TT22213B
LTOT. 46.04D



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717851

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/23/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container# 405009
Manual Ticket# 1029618 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97180 lb*
In 09/22/2021 10:29:23	Front Scale	jaday		Tare	51180 lb*
Out 09/23/2021 10:29:23		jaday		Net	46000 lb
Comments				* Manual Weight	Tons
					23.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	23.00	Tons			WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		23.00	Tons			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **441/107328/485101-5**
Driver Name: **Anthony Eggen** Driver Signature: _____

Remarks:
LT 49, 0301100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717852

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/23/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container# 405011
Manual Ticket# 1029619 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103480 lb*
In 09/22/2021 10:33:25	Front Scale	jaday		Tare	57840 lb*
Out 09/23/2021 10:33:25		jaday		Net	45640 lb
Comments				* Manual Weight	Tons
					22.82

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	22.82	Tons			WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		22.82	Tons			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup **9-21-2021**
Time scheduled for pickup **10:00 AM**

Generate Name and Loading Address
SCD NE 8TH Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **405009** Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **445** * **WM 743126**
Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
**Driver Lic
WDL 3213 BT 43 B
09 11 2017**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717853

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/23/2021 Vehicle# 483299 Volume
Payment Type Credit Account Container 483299
Manual Ticket# 1029623 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104340 lb*
In 09/22/2021 10:35:11	Front Scale	jaday		Tare	70980 lb*
Out 09/23/2021 10:35:11		jaday		Net	33360 lb
Comments					16.68
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		16.68	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	16.68	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
11577 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup
 Tarp in good serviceable condition Yes No
 Contents in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWP** WTL

Loading
 Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **442-7070-2-405011**

Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks:
405011 vs 46040
WDL 7A95013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717854

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/23/2021 Vehicle# 483653 Volume
Payment Type Credit Account Container 483653
Manual Ticket# 1029626 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104220 lb*
In 09/22/2021 10:36:25	Front Scale	jaday		Tare	57300 lb*
Out 09/23/2021 10:36:25		jaday		Net	46920 lb
Comments					23.46
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.46	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	23.46	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
11577 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup
 Tarp in good serviceable condition Yes No
 Contents in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWP** WTL

Loading
 Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Liers 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**

Driver Name: **Brandon Osborne** Driver Signature: *[Signature]*

Remarks:
can # 483299



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717855

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/23/2021 Vehicle# 483901 Volume
Payment Type Credit Account Container 483901
Manual Ticket# 1029627 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103620 lb*
In 09/22/2021 10:37:48	Front Scale	jaday		Tare	53900 lb*
Out 09/23/2021 10:37:48		jaday		Net	49720 lb
Comments					24.86
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.86	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-21-21
Time scheduled for pickup 7:20 AM

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
11500 Pacific South International Facility (SR02) Unit
452 South Business Center
Banks, Washington OR 97138
Phone (509) 465-2000 or (509) 465-2001

Dispose of Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:

Try to good serviceable condition	Yes	No
Container is in good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707287-483653

Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks:
WDL # 71122213B
LT Wt. 49,620



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717856

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 09/23/2021 Vehicle# 490006 Volume
Payment Type Credit Account Container 490006
Manual Ticket# 1029629 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103420 lb*
In 09/22/2021 10:39:39	Front Scale	jaday		Tare	53620 lb*
Out 09/23/2021 10:39:39		jaday		Net	49800 lb
Comments					24.90
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.90	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
11500 Pacific South International Facility (SR02) Unit
452 South Business Center
Banks, Washington OR 97138
Phone (509) 465-2000 or (509) 465-2001

Dispose of Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:

Try to good serviceable condition	Yes	No
Container is in good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 444-743140

Driver Name: BUCK BARNETT Driver Signature: [Signature]

Remarks:
WDL # 711222193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718352

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/24/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1029768 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96540 lb*
In 09/23/2021 09:27:31	Front Scale	jaday		Tare	49780 lb*
Out 09/24/2021 09:27:31		jaday		Net	46760 lb
Comments					23.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.38	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	23.38	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone # (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-707200 490006**

Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks:
1/8/20
WDL70720015



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718353

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/24/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container 405007
Manual Ticket# 1029769 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97860 lb*
In 09/23/2021 09:28:47	Front Scale	jaday		Tare	50800 lb*
Out 09/24/2021 09:28:47		jaday		Net	47060 lb
Comments					23.53

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.53	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	23.53	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone # (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **441/707361/405005-6**

Driver Name: **Andrew Egner** Driver Signature: *[Signature]*

Remarks:
45600125



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718354

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/24/2021 Vehicle# 405008 Volume
Payment Type Credit Account Container 405008
Manual Ticket# 1029770 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	95480 lb*
In 09/23/2021 09:32:34	Front Scale	jaday		Tare	49520 lb*
Out 09/24/2021 09:32:34		jaday		Net	45960 lb
Comments					22.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	22.98	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.98	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-22-21
Time scheduled for pickup 7:15

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707237-405007

Driver Name: SCOTT Hagan Driver Signature: [Signature]

Remarks: WDL 71122213B Ls WT 46500



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718356

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/24/2021 Vehicle# 480516 Volume
Payment Type Credit Account Container 480516
Manual Ticket# 1029771 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103540 lb*
In 09/23/2021 09:35:31	Front Scale	jaday		Tare	54080 lb*
Out 09/24/2021 09:35:31		jaday		Net	49460 lb
Comments					24.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: US-787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFE1

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/7072361/405008-2

Driver Name: Arthur Egner Driver Signature: [Signature]

Remarks: _____

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97122-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-22-21
Time scheduled for pickup 9:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97122-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707887-480516

Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks: _____

WDL # 7T22213B LT 48,960



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718357

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/24/2021 Vehicle# 483218 Volume
Payment Type Credit Account Container 483218
Manual Ticket# 1029772 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104740 lb*
In 09/23/2021 09:37:11	Front Scale	jaday		Tare	55000 lb*
Out 09/24/2021 09:37:11		jaday		Net	49740 lb
Comments					24.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.87	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.87	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97122-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Deposit Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97122-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/707331/4852134

Driver Name: ARTHUR EGGER Driver Signature: [Signature]

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716496

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483251 Volume
Payment Type Credit Account Container 483251
Manual Ticket# 1028936 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105020 lb*
In 09/15/2021 12:46:50	MANUAL WT	jvaldez		Tare	55120 lb*
Out 09/16/2021 12:46:50		jvaldez		Net	49900 lb
Comments					24.95

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.95	Tons				WA-BELLEVU
2 EVF-P6-Environment	100			\$			WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.95	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716497

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483341 Volume
Payment Type Credit Account Container 483341
Manual Ticket# 1028937 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105220 lb*
In 09/15/2021 12:47:51	MANUAL WT	jvaldez		Tare	54540 lb*
Out 09/16/2021 12:47:51		jvaldez		Net	50680 lb
Comments				* Manual Weight	Tons 25.34

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.34	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.34	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1600 Pacific South International Facility (LRO) Unit
425 South Street
North, Portland, OR 97208
Phone: (503) 744-1111 or (503) 744-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Unloading
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **443-707200** **0183251**

Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks:
49680
WDL 78796013



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716499

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483383 Volume
Payment Type Credit Account Container 483383
Manual Ticket# 1028938 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105620 lb*
In 09/15/2021 12:49:04	MANUAL WT	jvaldez		Tare	55320 lb*
Out 09/16/2021 12:49:04		jvaldez		Net	50300 lb
Comments				* Manual Weight	Tons 25.15

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.15	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.15	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1600 Pacific South International Facility (LRO) Unit
425 South Street
North, Portland, OR 97208
Phone: (503) 744-1111 or (503) 744-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In **483341** Unloading
Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **4415** **WM 743136**

Driver Name: **Jason Michael** Driver Signature: _____

Remarks:
Driver Lic
WDL 3213 BT 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716500

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483628 Volume
Payment Type Credit Account Container 483628
Manual Ticket# 1028941 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104100 lb*
In 09/15/2021 12:50:01	MANUAL WT	jvaldez		Tare	54380 lb*
Out 09/16/2021 12:50:01		jvaldez		Net	49720 lb
Comments				* Manual Weight	Tons 24.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.86	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 9-13-21
Time scheduled for pickup 2:30 PM

Waste Profile # 115787WA

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
11500 North Salem Road (1000) Unit
400 North Salem Road
North, Washington 97131
Phone: (503) 744-1111 or (503) 744-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 4HD-107A7-43383

Driver Name: SCOTT HOGAN Driver Signature: [Signature]

Remarks:
WDL 7122215B
6/4 49,400

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Waste Profile # 115787WA

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
11500 North Salem Road (1000) Unit
400 North Salem Road
North, Washington 97131
Phone: (503) 744-1111 or (503) 744-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 444-743140

Driver Name: BRUCE BONNETT Driver Signature: [Signature]

Remarks: WDL 917211730



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716501

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483650 Volume
Payment Type Credit Account Container 483650
Manual Ticket# 1028943 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104640 lb*
In 09/15/2021 12:51:02	MANUAL WT	jvaldez		Tare	54420 lb*
Out 09/16/2021 12:51:02		jvaldez		Net	50220 lb
Comments				* Manual Weight	Tons 25.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.11	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.11	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716502

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483655 Volume
Payment Type Credit Account Container 483655
Manual Ticket# 1028944 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	94920 lb*
In 09/15/2021 12:52:10	MANUAL WT	jvaldez		Tare	55100 lb*
Out 09/16/2021 12:52:10		jvaldez		Net	39820 lb
Comments				* Manual Weight	Tons 19.91

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	19.91 Tons				WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	19.91 Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707 WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liers: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Vehicle #: 444-743140

Driver Name: BRUCE BRADITT Driver Signature: MB

Remarks: WOL 97812-6512



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716503

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483859 Volume
Payment Type Credit Account Container 483859
Manual Ticket# 1028944 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105120 lb*
In 09/15/2021 12:53:10	MANUAL WT	jvaldez		Tare	55360 lb*
Out 09/16/2021 12:53:10		jvaldez		Net	49760 lb
Comments				* Manual Weight	Tons 24.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	24.88 Tons				WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	24.88 Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115707 WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liers: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Vehicle #: 4421701270

Driver Name: BRANDON OSBORNE Driver Signature: BRANDON OSBORNE

Remarks: can # 483655



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716504

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483966 Volume
Payment Type Credit Account Container 483966
Manual Ticket# 1028950 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105340 lb*
In 09/15/2021 12:54:10	MANUAL WT	jvaldez		Tare	54860 lb*
Out 09/16/2021 12:54:10		jvaldez		Net	54860 lb
Comments				* Manual Weight	Tons 25.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.24		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		25.24		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
Estate Public Waste Services Inc. 483966 Unit
400 East Street West
Arlington, Oregon 97812
Phone: (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-702200** **483859**

Driver Name: **JEFF THOMAS** Other Signature: _____

Remarks:
49560
WDL 78796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716505

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/16/2021 Vehicle# 484019 Volume
Payment Type Credit Account Container 484019
Manual Ticket# 1028951 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105260 lb*
In 09/15/2021 12:56:12	MANUAL WT	jvaldez		Tare	54560 lb*
Out 09/16/2021 12:56:12		jvaldez		Net	50700 lb
Comments				* Manual Weight	Tons 25.35

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.35		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		25.35		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup **9-13**
Time scheduled for pickup **11:20**

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
Estate Public Waste Services Inc. 483966 Unit
400 East Street West
Arlington, Oregon 97812
Phone: (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-702207-4838166**

Driver Name: **Scott F Hogan** Other Signature: _____

Remarks:
WDL # 78796013B
50,023



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716506

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/16/2021 Vehicle# 484021 Volume
Payment Type Credit Account Container 484021
Manual Ticket# 1028952 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105880 lb*
In 09/15/2021 12:57:14	MANUAL WT	jvaldez		Tare	55620 lb*
Out 09/16/2021 12:57:14		jvaldez		Net	50260 lb
Comments				* Manual Weight	Tons 25.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1680 Pacific South Industrial Facility 18001 South
Arlington, Oregon 97812
Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good workable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
Unloading: End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck #/Basin #: **441/7072361/484019-5**
Driver Name: **Arthur Eugene** Driver Signature: _____

Remarks: **LT 477001123**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716507

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 09/16/2021 Vehicle# 400501 Volume
Payment Type Credit Account Container 400501
Manual Ticket# 1029055 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98020 lb*
In 09/15/2021 12:58:04	MANUAL WT	jvaldez		Tare	49680 lb*
Out 09/16/2021 12:58:04		jvaldez		Net	48340 lb
Comments				* Manual Weight	Tons 24.17

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.17	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.17	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1680 Pacific South Industrial Facility 18001 South
Arlington, Oregon 97812
Phone: (541) 454-2030
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good workable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
Unloading: End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck #/Basin #: **441/707270**
Driver Name: **Brandon Osborne** Driver Signature: _____

Remarks: **can # 484021**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716508

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container 405011
Manual Ticket# 1028932 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96460 lb*
In 09/15/2021 12:59:15	MANUAL WT	jvaldez		Tare	49660 lb*
Out 09/16/2021 12:59:15		jvaldez		Net	46800 lb
Comments				* Manual Weight	Tons
					23.40

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		23.40	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck Number: 4411/707381/405011
Driver Name: Arthur Egger Driver Signature: [Signature]

Remarks: LT 34, 9601100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716509

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1028930 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96460 lb*
In 09/15/2021 13:00:32	MANUAL WT	jvaldez		Tare	50040 lb*
Out 09/16/2021 13:00:32		jvaldez		Net	46420 lb
Comments				* Manual Weight	Tons
					23.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		23.21	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck Number: 4411/707381/405011-7
Driver Name: Arthur Egger Driver Signature: [Signature]

Remarks: LT 45, 6601100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716510

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/16/2021 Vehicle# 483786 Volume
 Payment Type Credit Account Container 483786
 Manual Ticket# 1028946 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105540 lb*
In 09/15/2021 13:01:43	MANUAL WT	jvaldez		Tare	54880 lb*
Out 09/16/2021 13:01:43		jvaldez		Net	50660 lb
Comments				* Manual Weight	Tons 25.33

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.33	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.33	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA Disposal Facility: Columbia Ridge Landfill and Recycling Center
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTC Truck #/axis: 444-743140

Driver Name: BOUCE BELLEVUE Driver Signature: [Signature]

Remarks: WUL 716510 49513



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716511

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
 Ticket Date 09/16/2021 Vehicle# 490016 Volume
 Payment Type Credit Account Container 490016
 Manual Ticket# 1028953 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104140 lb*
In 09/15/2021 13:02:40	MANUAL WT	jvaldez		Tare	52840 lb*
Out 09/16/2021 13:02:40		jvaldez		Net	51300 lb
Comments				* Manual Weight	Tons 25.65

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.65	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.65	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA Disposal Facility: Columbia Ridge Landfill and Recycling Center
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Loading: Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck #/axis: 443-707200 483786

Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: 49510
WUL 716510 49513



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716512

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483643 Volume
Payment Type Credit Account Container 483643
Manual Ticket# 1028942 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/15/2021 13:03:40 Scale Operator Inbound Gross 104580 lb*
Out 09/16/2021 13:03:40 MANUAL WT jvaldez jvaldez Tare 55260 lb*
Comments * Manual Weight Net 49320 lb
Tons 24.66

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.66	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.66	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-13-2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading: W.M.X.L Unloading _____
Start Time _____ Box # In 480016 Litter # 1 2 Start Time _____
End Time _____ Box # Out _____ Litter # 1 2 End Time _____

Transporter Name: CTI Truck/Classif: 445 * WM 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks: _____
Driver Lic
WDL 3213 BT 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716513

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483582 Volume
Payment Type Credit Account Container 483582
Manual ticket# 1028939 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/15/2021 13:04:43 Scale Operator Inbound Gross 106740 lb*
Out 09/16/2021 13:04:43 MANUAL WT jvaldez jvaldez Tare 54180 lb*
Comments * Manual Weight Net 52560 lb
Tons 26.28

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.28	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.28	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-13-2021
Time scheduled for pickup 11:00 AM

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading: W.M.X.L Unloading _____
Start Time _____ Box # In 483643 Litter # 1 2 Start Time _____
End Time _____ Box # Out _____ Litter # 1 2 End Time _____

Transporter Name: CTI Truck/Classif: 445 * WM 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks: _____
Driver Lic
WDL 3213 BT 43 B
cap 7.31.2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716514

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483035 Volume
Payment Type Credit Account Container 483035
Manual Ticket# 1028935 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106240 lb*
In 09/15/2021 13:07:15	MANUAL WT	jvaldez		Tare	54480 lb*
Out 09/16/2021 13:07:15		jvaldez		Net	51760 lb
Comments				* Manual Weight	Tons 25.88

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.88	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.88	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Arlington, Oregon 97812-6512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-483582

Driver Name: Scott F HOGAN Driver Signature: Scott F Hogan

Remarks: WDL 7TT22213B LTW 49240



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716515

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483902 Volume
Payment Type Credit Account Container 483902
Manual Ticket# 1028949 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105980 lb*
In 09/15/2021 13:09:00	MANUAL WT	jvaldez		Tare	54560 lb*
Out 09/16/2021 13:09:00		jvaldez		Net	51420 lb
Comments				* Manual Weight	Tons 25.71

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.71	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.71	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Arlington, Oregon 97812-6512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 4411/707381/483035

Driver Name: Arthur Egger Driver Signature: Arthur Egger

Remarks: LT 50,366lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716516

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483613 Volume
Payment Type Credit Account Container 483613
Manual Ticket# 1028940 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105180 lb*
In 09/08/2021 13:11:08	MANUAL WT	jvaldez		Tare	54220 lb*
Out 09/16/2021 13:11:08		jvaldez		Net	50960 lb
Comments				* Manual Weight	Tons 25.48

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.48		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		25.48		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane (18177 Cedar Springs Lane)
Arlington, Oregon 97812
Phone: (541) 454-2030
Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 444-707-881/4839023
Driver Name: John Egger Driver Signature: _____

Remarks: # 49,840 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716518

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483675 Volume
Payment Type Credit Account Container 483675
Manual Ticket# 1028945 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108140 lb*
In 09/15/2021 13:16:40	MANUAL WT	jvaldez		Tare	55320 lb*
Out 09/16/2021 13:16:40		jvaldez		Net	52820 lb
Comments				* Manual Weight	Tons 26.41

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		26.41		Tons	WA-BELLEVUE
2 EVF-P6-Environment		100		\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100		26.41		Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 18177 Cedar Springs Lane (18177 Cedar Springs Lane)
Arlington, Oregon 97812
Phone: (541) 454-2030
Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Litters 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 443-707200 483613
Driver Name: Jeff Thomas Driver Signature: _____

Remarks: # WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716520

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/16/2021 Vehicle# 483826 Volume
Payment Type Credit Account Container 483826
Manual Ticket# 1028947 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105480 lb*
In 09/15/2021 13:19:42	MANUAL WT	jvaldez		Tare	54780 lb*
Out 09/16/2021 13:19:42		jvaldez		Net	50700 lb
Comments				* Manual Weight	Tons 25.35

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.35	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.35	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Definition:
Left Side: Pacific South International Facility (LF01) load
Right Side: Waste Transfer
Please Check "WTL" if applicable to this load

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 707/270
Driver Name: Brendan Osborne Driver Signature: Brendan Osborne

Remarks: Can # 493675



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716521

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/16/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1028929 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	99240 lb*
In 09/15/2021 13:21:00	MANUAL WT	jvaldez		Tare	52560 lb*
Out 09/16/2021 13:21:00		jvaldez		Net	46680 lb
Comments				* Manual Weight	Tons 23.34

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.34	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100			\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.34	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Definition:
Left Side: Pacific South International Facility (LF01) load
Right Side: Waste Transfer
Please Check "WTL" if applicable to this load

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 444-743140
Driver Name: BLAKE BARNETT Driver Signature: Blake Barnett

Remarks: WV 2722693B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716543

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483080 Volume
Payment Type Credit Account Container 483080
Manual Ticket# 1028622 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*
In 09/11/2021 08:31:24	Front Scale	jvaldez		Tare	55520 lb*
Out 09/17/2021 08:31:24		jvaldez		Net	49720 lb
Comments					24.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.86	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 9-15-21
Time scheduled for pickup: 9:55 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
483080 (Vehicle #)
1028622 (Manual Ticket #)
0002819 (Billing #)
10630, 10660, 10680 (Generator #s)

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-40504
Driver Name: SCOTT F. HOGAN Driver Signature: [Signature]

Remarks: WDL # 71122213B
LT WT 45,846



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716544

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483350 Volume
Payment Type Credit Account Container 483350
Manual Ticket# 1029065 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105720 lb*
In 09/16/2021 08:33:01	Front Scale	jvaldez		Tare	55180 lb*
Out 09/17/2021 08:33:01		jvaldez		Net	50540 lb
Comments					25.27

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.27	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.27	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 9-10-21
Time scheduled for pickup: 12:30

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
483350 (Vehicle #)
1029065 (Manual Ticket #)
0002819 (Billing #)
10630, 10660, 10680 (Generator #s)

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-483030
Driver Name: SCOTT F. HOGAN Driver Signature: [Signature]

Remarks: WDL # 71122213B
NEED Repair
LT WT 50,100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716545

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483396 Volume
Payment Type Credit Account Container 483396
Manual Ticket# 1029066 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105880 lb*
In 09/16/2021 08:34:56	Front Scale	jvaldez		Tare	54980 lb*
Out 09/17/2021 08:34:56		jvaldez		Net	50900 lb
Comments				* Manual Weight	Tons 25.45

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.45	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.45	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
Low Profile Loads (Standard Forklift - 1800) Lash
4x2 Load Secure Restraint
Secure, N/A, and 100%
Phone Call 761-1721 or 1-800-275-7612

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in its good condition Yes No
 No fire loading notes Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **441/707201/483350-8**

Driver Name: **Howard Egard** Driver Signature: *Howard Egard*

Remarks:
#49,980160



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716546

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483660 Volume
Payment Type Credit Account Container 483660
Manual Ticket# 1029066 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105720 lb*
In 09/16/2021 08:36:07	Front Scale	jvaldez		Tare	55460 lb*
Out 09/17/2021 08:36:07		jvaldez		Net	50260 lb
Comments				* Manual Weight	Tons 25.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.13	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.13	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
Low Profile Loads (Standard Forklift - 1800) Lash
4x2 Load Secure Restraint
Secure, N/A, and 100%
Phone Call 761-1721 or 1-800-275-7612

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in its good condition Yes No
 No fire loading notes Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**

Driver Name: **Brandon Osborne** Driver Signature: *Brandon Osborne*

Remarks:
can # 493396



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716547

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483715 Volume
Payment Type Credit Account Container 483715
Manual Ticket# 1029070 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104840 lb*
In 09/16/2021 08:37:17	Front Scale	jvaldez		Tare	54880 lb*
Out 09/17/2021 08:37:17		jvaldez		Net	49960 lb
Comments				* Manual Weight	Tons 24.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.98	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.98	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil) Deposit Facility: Columbia Ridge Landfill and Recycling Center
425 East Street Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition No Yes
Container is in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: car # 483660



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716548

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483928 Volume
Payment Type Credit Account Container 483928
Manual Ticket# 1029071 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106780 lb*
In 09/16/2021 08:38:23	Front Scale	jvaldez		Tare	55240 lb*
Out 09/17/2021 08:38:23		jvaldez		Net	51540 lb
Comments				* Manual Weight	Tons 25.77

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.77	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.77	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil) Deposit Facility: Columbia Ridge Landfill and Recycling Center
425 East Street Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition No Yes
Container is in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 441/7075301/483715-0
Driver Name: Andrew Fogel Driver Signature: Andrew Fogel

Remarks: LT



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716549

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/17/2021 Vehicle# 483933 Volume
Payment Type Credit Account Container 483933
Manual Ticket# 1029072 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105920 lb*
In 09/16/2021 08:39:26	Front Scale	jvaldez		Tare	55340 lb*
Out 09/17/2021 08:39:26		jvaldez		Net	50580 lb
Comments				* Manual Weight	Tons 25.29

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.29	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.29	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-15-2021
Time scheduled for pickup 8:30 AM

Water Profile # 115787WA

Customer Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483925 Lites # 1 2 Start Time _____
End Time _____ Box # Out _____ Lites # 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 445 WILSON T-43136

Driver Name: Jason Michael Driver Signature: _____
Remarks: _____
Driver Lic
WDL 3213 BJ 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716869

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/18/2021 Vehicle# 480437 Volume
Payment Type Credit Account Container 480437
Manual Ticket# 1029061 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103700 lb*
In 09/16/2021 14:42:55	MANUAL WT	jvaldez		Tare	53640 lb*
Out 09/18/2021 14:42:55		jvaldez		Net	50060 lb
Comments				* Manual Weight	Tons 25.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.03	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.03	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-15-21
Time scheduled for pickup 7:25

Water Profile # 115787WA

Customer Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lites # 2 Start Time _____
End Time _____ Box # Out _____ Lites # 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 449-762287-483933

Driver Name: Scott F. Hagan Driver Signature: _____
Remarks: _____
WDL 2722213B LTWJ 49566



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716870

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/18/2021 Vehicle# 480552 Volume
Payment Type Credit Account Container 480552
Manual Ticket# 1029062 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105640 lb*
In 09/16/2021 14:44:48	MANUAL WT	jvaldez		Tare	55920 lb*
Out 09/18/2021 14:44:48	MANUAL WT	jvaldez		Net	49720 lb
Comments				* Manual Weight	Tons
					24.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.86	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
2 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
3 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Ltr: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Ltr: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 443-707280 480497

Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks: WDL TR AGC13B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716871

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/18/2021 Vehicle# 483164 Volume
Payment Type Credit Account Container 483164
Manual Ticket# 1029063 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104880 lb*
In 09/16/2021 14:45:50	MANUAL WT	jvaldez		Tare	53420 lb*
Out 09/18/2021 14:45:50	MANUAL WT	jvaldez		Net	51460 lb
Comments				* Manual Weight	Tons
					25.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/18/2021
Time scheduled for pickup NOON

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
2 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
3 from Pacific States (Inland) Facility (AR01) Unit 402-3400 Service Area
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 480552 Ltr: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Ltr: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer #: 445 773136

Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driver Lic
WDL 3113 BT 43 B
CP T 31-2027

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-18-2021
Time scheduled for pickup 2:00 pm

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483164 Liers: 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 End Time: _____

Transporter Name: CTI Truck/Trailer # 445 743136

Driver Name: Jason Michaels Driver Signature: _____

Remarks: _____
Driver Lic
WDL 3213 BT 43 B
09-18-2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716873

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/18/2021 Vehicle# 483328 Volume
Payment Type Credit Account Container 483328
Manual Ticket# 1029064 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104980 lb*
In 09/16/2021 14:47:39	MANUAL WT	jvaldez		Tare	55260 lb*
Out 09/18/2021 14:47:39		jvaldez		Net	49720 lb
Comments				* Manual Weight	Tons
					24.86

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.86	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.86	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-18-21
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Liers: 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers: 0 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-483328

Driver Name: Scott F Hogan Driver Signature: _____

Remarks: _____
WDL # 71122213B WDL 49760



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716874

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/19/2021 Vehicle# 483422 Volume
Payment Type Credit Account Container 483422
Manual Ticket# 1029067 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101840 lb*
In 09/16/2021 14:48:45	MANUAL WT	jvaldez		Tare	54980 lb*
Out 09/19/2021 14:48:45		jvaldez		Net	46860 lb
Comments				* Manual Weight	Tons
					23.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	23.43	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.43	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716876

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/18/2021 Vehicle# 483601 Volume
Payment Type Credit Account Container 483601
Manual Ticket# 1029068 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107940 lb*
In 09/16/2021 14:50:12	MANUAL WT	jvaldez		Tare	56320 lb*
Out 09/18/2021 14:50:12		jvaldez		Net	51620 lb
Comments				* Manual Weight	Tons 25.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 7/27/2021
Time scheduled for pickup 16:00:00

Waste Profile # 115787WA

Generate Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 Line North South Street (3000) East
4200 South Street
North, Washington 97116
Phone: (503) 251-1111 x 4200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition No
Container is in good condition No
No fuel standing inside No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In 483422 Lanes 0 0 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck #/Axis # 445 / 743/36

Driver Name: Jason M. Harkis Driver Signature: _____

Remarks:
LIC # WDL 3213 BT 43 B exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 716876

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 09/18/2021 Vehicle# 490014 Volume
Payment Type Credit Account Container 490014
Manual Ticket# 1029073 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106560 lb*
In 09/16/2021 14:51:46	MANUAL WT	jvaldez		Tare	56860 lb*
Out 09/18/2021 14:51:46		jvaldez		Net	49700 lb
Comments				* Manual Weight	Tons 24.85

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.85	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.85	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Waste Profile # 115787WA

Generate Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 Line North South Street (3000) East
4200 South Street
North, Washington 97116
Phone: (503) 251-1111 x 4200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition No
Container is in good condition No
No fuel standing inside No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading
Start Time _____ Box # In _____ Lanes 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck #/Axis # 444-743/100

Driver Name: Blake Bennett Driver Signature: _____

Remarks: WDL 27227-193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717076

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/20/2021 Vehicle# 483199 Volume
Payment Type Credit Account Container# 483199
Manual Ticket# 1029203 Billing # 0002819
Hauling Ticket# Manifest# 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 96100 lb*
In 09/17/2021 09:43:36 MANUAL WT vmckinne Tare 47940 lb*
Out 09/20/2021 09:43:36 vmckinne Net 48160 lb
Comments * Manual Weight Tons 24.08

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.08	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.08	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-15-2021
Time scheduled for pickup 3:00 pm

Concrete Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC (Internal Facility 10630) (ash) Disposal Facility: Columbia Ridge Landfill and Recycling Center
A/C# of Facility: 483199 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in its good condition No
No free standing water No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading: W M X U Unloading
Start Time _____ Box # In 483199 Litter# 1 2 Start Time _____
End Time _____ Box # Out _____ Litter# 6 1 2 End Time _____
Truck/Trailer # CTI Truck/Trailer # 445 w/m 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks: Driver Lic
WDL 3213 BT 43 B
cap 7-11-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717077

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/20/2021 Vehicle# 483239 Volume
Payment Type Credit Account Container# 483239
Manual Ticket# 1029204 Billing # 0002819
Hauling Ticket# Manifest# 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104380 lb*
In 09/17/2021 09:45:01 MANUAL WT vmckinne Tare 54060 lb*
Out 09/20/2021 09:45:01 vmckinne Net 50320 lb
Comments * Manual Weight Tons 25.16

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.16	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-15-2021
Time scheduled for pickup 10:00 AM

Concrete Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC (Internal Facility 10630) (ash) Disposal Facility: Columbia Ridge Landfill and Recycling Center
A/C# of Facility: 483239 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in its good condition No
No free standing water No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading: W M X U Unloading
Start Time _____ Box # In 483239 Litter# 1 2 Start Time _____
End Time _____ Box # Out _____ Litter# 6 1 2 End Time _____
Truck/Trailer # CTI Truck/Trailer # 445 w/m 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks: Driver Lic
WDL 3213 BT 43 B
cap 7-11-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717078

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/20/2021 Vehicle# 483578 Volume
Payment Type Credit Account Contain# 483578
Manual Ticket# 1029205 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/17/2021 09:45:52 Scale MANUAL WT Operator vmckinne Inbound Gross 105060 lb*
Out 09/20/2021 09:45:52 Tare 54500 lb*
Net 50560 lb
Tons 25.28
Comments * Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	25.28	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.28	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-15-21
Time scheduled for pickup 9:30

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC Disposal Facility: Columbia Ridge Landfill and Recycling Center
402 South Service Street 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512 Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707287-483578
Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks:
WDL # 71722213B
WT 49.740



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717079

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/20/2021 Vehicle# 480403 Volume
Payment Type Credit Account Contain# 480403
Manual Ticket# 1029412 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/16/2021 09:46:35 Scale MANUAL WT Operator vmckinne Inbound Gross 99500 lb*
Out 09/20/2021 09:46:35 Tare 46000 lb*
Net 53500 lb
Tons 26.75
Comments * Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	26.75	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	26.75	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC Disposal Facility: Columbia Ridge Landfill and Recycling Center
402 South Service Street 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512 Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 444/743130
Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks:
WDL # 71722213B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717080

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/20/2021 Vehicle# 483638 Volume
Payment Type Credit Account Container 483638
Manual Ticket# 1029207 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 106380 lb*
In 09/17/2021 09:47:14 MANUAL WT vmckinne Tare 55540 lb*
Out 09/20/2021 09:47:14 vmckinne Net 50840 lb
* Manual Weight Tons 25.42

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	25.42	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.42	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil) Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary is good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck #/Taxis # 441-702381/483638-5
Driver Name: Arthur Equil Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717223

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483068 Volume
Payment Type Credit Account Container 483068
Manual Ticket# 1029316 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105820 lb*
In 09/18/2021 10:24:22 MANUAL WT vmckinne Tare 55400 lb*
Out 09/21/2021 10:24:22 vmckinne Net 50420 lb
* Manual Weight Tons 25.21

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	25.21	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.21	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil) Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary is good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: CTI Truck #/Taxis # 443-702381 483068
Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks:
91860
WDL 7R796C13B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717224

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483678 Volume
Payment Type Credit Account Container 483678
Manual Ticket# 1029317 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/18/2021 10:25:06 MANUAL WT Operator vmckinne Inbound Gross 107160 lb*
Out 09/21/2021 10:25:06 vmckinne Tare 55540 lb*
Net 51620 lb
* Manual Weight Tons 25.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.81	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.81	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC (LF01 - Contained-In PCE Contaminated Soil)
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 444-743440

Driver Name: BRUCE BARNETT Driver Signature: BA

Remarks: WDL7422193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717225

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483716 Volume
Payment Type Credit Account Container 483716
Manual Ticket# 1029318 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/18/2021 10:25:44 MANUAL WT Operator vmckinne Inbound Gross 104300 lb*
Out 09/21/2021 10:25:44 vmckinne Tare 53860 lb*
Net 50440 lb
* Manual Weight Tons 25.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.22	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.22	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC (LF01 - Contained-In PCE Contaminated Soil)
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition Yes No
Container is in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 443-707020 493716

Driver Name: JEFF HARRIS Driver Signature: Jeff Harris

Remarks: 49640
WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717226

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483792 Volume
Payment Type Credit Account Contain# 483792
Manual Ticket# 1029319 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 106780 lb*
In 09/18/2021 10:26:20 MANUAL WT vmckinne Tare 54700 lb*
Out 09/21/2021 10:26:20 vmckinne Net 52080 lb
* Manual Weight Tons 26.04

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.04	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.04	Tons				WA-BELLEVU

Driver's Signature

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Purpose: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: From Public Waste Transfer Facility (WTF) Unit 412 South Service Road South, Tualuma, OR 97143 Phone: (503) 682-1101 x 412 or 413 Disposal Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (503) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/702381/183792-5
Driver Name: Arthur Eggert Driver Signature: _____

Remarks: ET 49,160 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717228

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483877 Volume
Payment Type Credit Account Contain# 483877
Manual Ticket# 1029320 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 106140 lb*
In 09/18/2021 10:27:00 MANUAL WT vmckinne Tare 54520 lb*
Out 09/21/2021 10:27:00 vmckinne Net 51620 lb
* Manual Weight Tons 25.81

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.81	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.81	Tons				WA-BELLEVU

Driver's Signature

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Container Purpose: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: From Public Waste Transfer Facility (WTF) Unit 412 South Service Road South, Tualuma, OR 97143 Phone: (503) 682-1101 x 412 or 413 Disposal Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (503) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 444/443130
Driver Name: BLAKE BANNETT Driver Signature: _____

Remarks: WDL 872,727,933



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717232

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/21/2021 Vehicle# 484076 Volume
Payment Type Credit Account Container 484076
Manual Ticket# 1029321 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 107840 lb*
In 09/18/2021 10:27:40 MANUAL WT vmckinne Tare 55980 lb*
Out 09/21/2021 10:27:40 vmckinne Net 51860 lb
* Manual Weight Tons 25.93

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.93	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.93	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-14-21
Time scheduled for pickup 11:30 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Container Types: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	<input type="checkbox"/>
Container in its good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: RTI Truck/Trailer # 440-767287-484076

Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks: WDL 7TH 22213B
LT 67,49,640



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717235

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/21/2021 Vehicle# 484069 Volume
Payment Type Credit Account Container 484069
Manual Ticket# 1028251 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 100000 lb*
In 09/08/2021 10:29:39 MANUAL WT vmckinne Tare 47000 lb*
Out 09/21/2021 10:29:39 vmckinne Net 53000 lb
* Manual Weight Tons 26.50

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.50	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 8-31-2021
Time scheduled for pickup 8:00 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Container Types: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: City Transfer Inc. Date: 8-31-2021
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	<input type="checkbox"/>
Container in its good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 484069 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: City Transfer Inc. Truck/Trailer # 707381

Driver Name: Amelia Foster Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 717240

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/21/2021 Vehicle# 483170 Volume
Payment Type Credit Account Container 483170
Manual Ticket# 1028366 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 99340 lb*
In 09/09/2021 10:33:11 MANUAL WT vmckinne Tare 47940 lb*
Out 09/21/2021 10:33:11 vmckinne Net 51400 lb
* Manual Weight Tons 25.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	25.70	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.70	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup 8/12-2021
Time scheduled for pickup 10:30 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE
Disposal Facility: 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483170 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 443-707000 483408
Driver Name: Jason Michael Driver Signature: _____
Remarks: Driver Lic 3213 B-J 43 B WA exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718358

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/24/2021 Vehicle# 483408 Volume
Payment Type Credit Account Container 483408
Manual Ticket# 1029773 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104540 lb*
In 09/23/2021 09:38:22 Front Scale jaday Tare 55040 lb*
Out 09/24/2021 09:38:22 jaday Net 49500 lb
* Manual Weight Tons 24.75

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	24.75	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.75	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE
Disposal Facility: 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp is good serviceable condition: Yes No
Container is in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 443-707000 483408
Driver Name: JEFF THOMAS Driver Signature: _____
Remarks: 50020 WDL 7 R79013D



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718359

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/24/2021 Vehicle# 483422 Volume
Payment Type Credit Account Container 483422
Manual Ticket# 1029774 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104660 lb*
In 09/23/2021 09:39:24 Front Scale jaday Tare 54820 lb*
Out 09/24/2021 09:39:24 jaday Net 49840 lb
* Manual Weight Tons 24.92

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.92	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.92	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
E-Flow Pacific Waste Services Inc. (OR01) Unit
453 South River Street
Beaverton, Oregon 97005
Phone: (503) 638-7200 x7200 Fax: (503) 638-7200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTE** Truck/Trailer # **444-745140**

Driver Name: **BLAKE BARNETT** Driver Signature: *[Signature]*

Remarks: **WL 27227493B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718360

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/24/2021 Vehicle# 483671 Volume
Payment Type Credit Account Container 483671
Manual Ticket# 1029774 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105680 lb*
In 09/23/2021 09:40:29 Front Scale jaday Tare 56140 lb*
Out 09/24/2021 09:40:29 jaday Net 49540 lb
* Manual Weight Tons 24.77

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.77	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.77	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
E-Flow Pacific Waste Services Inc. (OR01) Unit
453 South River Street
Beaverton, Oregon 97005
Phone: (503) 638-7200 x7200 Fax: (503) 638-7200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTE** Truck/Trailer # **444-745140**

Driver Name: **BLAKE BARNETT** Driver Signature: *[Signature]*

Remarks: **WL 27227493B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718361

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/24/2021 Vehicle# 484067 Volume
Payment Type Credit Account Container 484067
Manual Ticket# 1029882 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/23/2021 09:42:27 Scale Operator Inbound Gross 102720 lb*
Out 09/24/2021 09:42:27 Front Scale jaday Tare 53520 lb*
Net 49200 lb
* Manual Weight Tons 24.60

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.60	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.60	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Container Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 - use Pacific States International for city - (800) 456-4566
484 South Ocean Street
Beaverton, Oregon 97005
Phone: (503) 638-7100, High-Low: 704-5000

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-702200 484067
Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks: WDL 7R79G012B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718362

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/24/2021 Vehicle# 484077 Volume
Payment Type Credit Account Container 484077
Manual Ticket# 1029884 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/23/2021 09:44:29 Scale Operator Inbound Gross 101480 lb*
Out 09/24/2021 09:44:29 Front Scale jaday Tare 49980 lb*
Net 51500 lb
* Manual Weight Tons 25.75

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.75	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.75	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Container Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 - use Pacific States International for city - (800) 456-4566
484 South Ocean Street
Beaverton, Oregon 97005
Phone: (503) 638-7100, High-Low: 704-5000

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 484077 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 + wdl 7H3136
Driver Name: Jason Michaels Driver Signature: [Signature]

Remarks: Driver Lic
WDL 3213 BJ 43 B
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718370

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/27/2021 Vehicle# 480412 Volume
Payment Type Credit Account Container 480412
Manual Ticket# 1029856 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/23/2021 10:24:27 MANUAL WT Operator Inbound Gross 103820 lb*
Out 09/27/2021 10:24:27 jaday Tare 53540 lb*
Net 50280 lb
* Manual Weight Tons 25.14

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.14	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.14	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-22-21
Time scheduled for pickup 10:20 AM

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
1-1000 Pallets, 2000-3000 lbs per pallet (10000 lbs total)
400 Bulk Bins (40000 lbs total)
South, Washington 97136
Phone (509) 748-1200 or (509) 748-1200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name CTI Truck/Trailer # 446 * WMT 743136

Driver Name Jasen Michaels Driver Signature _____

Remarks:
Driver Lic
WDL # 2113 BT 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718371

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483062 Volume
Payment Type Credit Account Container 483062
Manual Ticket# 1029865 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/24/2021 10:37:22 MANUAL WT Operator Inbound Gross 103600 lb*
Out 09/27/2021 10:37:22 jaday Tare 53940 lb*
Net 49660 lb
* Manual Weight Tons 24.83

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.83	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.83	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-22-21
Time scheduled for pickup 10:30

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
1-1000 Pallets, 2000-3000 lbs per pallet (10000 lbs total)
400 Bulk Bins (40000 lbs total)
South, Washington 97136
Phone (509) 748-1200 or (509) 748-1200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name CTI Truck/Trailer # 440-701287-483062

Driver Name Scott F Hogan Driver Signature _____

Remarks:
10' Hole IN Bottom of Bay
WDL # 2113 BT 2213 B
WMT



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718372


Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483523 Volume
Payment Type Credit Account Container# 483523
Manual Ticket# 1029870 Billing # 0002819
Hauling Ticket# Manifest# 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104180 lb*	
In 09/24/2021 10:46:22	MANUAL WT	jaday		Tare	54700 lb*	
Out 09/27/2021 10:46:22		jaday		Net	49480 lb	
* Manual Weight					Tons	24.74

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.74	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH	Waste Profile # <u>US 787WA</u> Waste Type: <input type="checkbox"/> CDL <input type="checkbox"/> Contaminated Soil <input type="checkbox"/> Asbestos <input type="checkbox"/> Other: <u>LF01</u>
Contact Person: Telephone Number:	

Acknowledgment of Loading:

Company Name _____ Date _____
 Signature _____ Name _____

Details of Rec: 4 from Pacific States Interstate Facility (18001) and 4 from South Dakota State
 Disposal Facility: Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>
Container in good condition	<input type="checkbox"/>	No	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>		<input type="checkbox"/>
Container empty and clean	<input type="checkbox"/>		<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name CTI Truck # 441/707381/483523-9
 Driver Name Arthur Egger Driver Signature _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718373


Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483677 Volume
Payment Type Credit Account Container# 483677
Manual Ticket# 1029872 Billing # 0002819
Hauling Ticket# Manifest# 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103000 lb*	
In 09/24/2021 10:50:00	MANUAL WT	jaday		Tare	54000 lb*	
Out 09/27/2021 10:50:00		jaday		Net	49000 lb	
* Manual Weight					Tons	24.50

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.50	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH	Waste Profile # <u>US 787WA</u> Waste Type: <input type="checkbox"/> CDL <input type="checkbox"/> Contaminated Soil <input type="checkbox"/> Asbestos <input type="checkbox"/> Other: <u>LF01</u>
Contact Person: Telephone Number:	

Acknowledgment of Loading:

Company Name _____ Date _____
 Signature _____ Name _____

Details of Rec: 4 from Pacific States Interstate Facility (18001) and 4 from South Dakota State
 Disposal Facility: Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>
Container in good condition	<input type="checkbox"/>	No	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>		<input type="checkbox"/>
Container empty and clean	<input type="checkbox"/>		<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name CTI Truck # 441/707381/483677-0
 Driver Name Arthur Egger Driver Signature _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718377

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483815 Volume
Payment Type Credit Account Container# 483815
Manual Ticket# 1029874 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105320 lb*
In 09/24/2021 11:02:40	MANUAL WT	jaday		Tare	54460 lb*
Out 09/27/2021 11:02:40		jaday		Net	50860 lb
* Manual Weight					Tons 25.43

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.43	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		25.43	Tons				

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718382

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483537 Volume
Payment Type Credit Account Container# 483537
Manual Ticket# 1029990 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	111000 lb*
In 09/25/2021 11:20:31	MANUAL WT	jaday		Tare	55260 lb*
Out 09/27/2021 11:20:31		jaday		Net	55740 lb
* Manual Weight					Tons 27.87

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		27.87	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		27.87	Tons				

Driver's Signature

1.

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-24-21
Time scheduled for pickup 7:40

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____
Telephone Number: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Open Pickup:
Tarp in good service condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTX Truck/Container # 440-707887-433537

Driver Name: Scott F Hogan Driver Signature: [Signature]

Remarks:
WDL # 71122213B 17WT 49466



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718385

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/27/2021 Vehicle# 484069 Volume
Payment Type Credit Account Container# 484069
Manual Ticket# 1029996 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	110340 lb*
In 09/25/2021 11:26:29	MANUAL WT	jaday		Tare	54320 lb*
Out 09/27/2021 11:26:29		jaday		Net	56020 lb
* Manual Weight					Tons 28.01

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		28.01	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		28.01	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: **LFO1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Origin of Site: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Trailer #: **411/707281/784069-9**

Driver Name: **Harold Engel** Driver Signature: _____

Remarks: **LT 496401105**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718387

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483032 Volume
Payment Type Credit Account Container# 483032
Manual Ticket# 1030103 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103840 lb*
In 09/27/2021 11:30:38	MANUAL WT	jaday		Tare	53820 lb*
Out 09/27/2021 11:30:38		jaday		Net	50020 lb
Comments					25.01
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.01	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.01	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9/21/21**
Time scheduled for pickup **2:00 PM**

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____ Waste Type: CDL
Telephone Number: _____ Contaminated Soil
 Asbestos
 Other: **LFO1**

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Origin of Site: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: **183032** Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Trailer #: **445 + Wm 743136**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks: **Driver Lic**
WDL 5213 BT 43 B
xp 731-2227



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718389

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/27/2021 Vehicle# 484071 Volume
Payment Type Credit Account Container# 484071
Manual Ticket# 1030106 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107400 lb*
In 09/26/2021 11:33:40	MANUAL WT	jaday		Tare	55600 lb*
Out 09/27/2021 11:33:40		jaday		Net	51800 lb
Comments					25.90
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.90	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718392

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483574 Volume
Payment Type Credit Account Container 483574
Manual Ticket# 1029992 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	10660 lb*
In 09/25/2021 11:23:32	MANUAL WT	jaday		Tare	55040 lb*
Out 09/27/2021 11:23:32		jaday		Net	51560 lb
		* Manual Weight		Tons	25.78

Comments REPLACEMENT TICKET FOR TICKET # 718383

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.78	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3		25.78	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/27/2021
Time scheduled for pickup 10:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Container Inspection Upon Pickup: _____
Click ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 42401 Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____
Transporter Name: CT1 Truck/Trailer # 445 * WM 74316
Driver Name: Jason Michaels Driver Signature: _____
Remarks: _____
Driver Lic
WDL 3213 BJ 43 B
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718599

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/27/2021 Vehicle# 483885 Volume
Payment Type Credit Account Container 483885
Manual Ticket# 1029780 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106480 lb*
In 09/27/2021 11:03:28	MANUAL WT	Jaday		Tare	56220 lb*
Out 09/27/2021 11:03:28		Jaday		Net	50260 lb
		* Manual Weight		Tons	25.13

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.13	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3		25.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/24/2021
Time scheduled for pickup 9:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Container Inspection Upon Pickup: _____
Click ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: 483574 Liers 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liers 0 1 2 End Time: _____
Transporter Name: CT1 Truck/Trailer # 445 * WM 74316
Driver Name: Jason Michaels Driver Signature: _____
Remarks: _____
Driver Lic
WDL 3213 BJ 43 B
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718601

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483904 Volume
Payment Type Credit Account Container 483904
Manual Ticket# 1029875 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106480 lb*
In 09/27/2021 11:10:59	MANUAL WT	Jaday		Tare	56220 lb*
Out 09/28/2021 11:10:59		Jaday		Net	50260 lb
Comments				* Manual Weight	Tons 25.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-22-21
Time scheduled for pickup 2:46

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
 Tarp in good serviceable condition
 Container in good condition
 No bar standing water
 Container is empty and closed

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-701287-483825

Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks: WDL # 7122213B LT WT 49,180



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718602

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483311 Volume
Payment Type Credit Account Container 483311
Manual Ticket# 1029867 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106760 lb*
In 09/27/2021 11:13:54	MANUAL WT	Jaday		Tare	56760 lb*
Out 09/28/2021 11:13:54		Jaday		Net	50000 lb
Comments				* Manual Weight	Tons 25.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.00	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.00	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-23-21
Time scheduled for pickup 1:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Container Inspection Upon Pickup:
 Tarp in good serviceable condition
 Container in good condition
 No bar standing water
 Container is empty and closed

Click ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-701287-483924

Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks: WDL # 7122213B LT WT 49,720



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718603

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483692 Volume
Payment Type Credit Account Container 483692
Manual Ticket# 1029777 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	112480 lb*
In 09/27/2021 11:16:49	MANUAL WT	Jaday		Tare	56880 lb*
Out 09/28/2021 11:16:49		Jaday		Net	56600 lb
Comments				* Manual Weight	Tons 27.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	27.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	27.80	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup 9-23-2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # US787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Details of Use
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup
 Tarp in good serviceable condition
 Container in good condition
 No free standing water
 Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In 483311 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 445 + WVA 743136

Driver Name Jason Michaels Driver Signature [Signature]

Remarks
Driver hic
WDL 3213 BJ 43 B
09/23/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718604

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483971 Volume
Payment Type Credit Account Container 483971
Manual Ticket# 1029781 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107480 lb*
In 09/27/2021 11:18:41	MANUAL WT	Jaday		Tare	57860 lb*
Out 09/28/2021 11:18:41		Jaday		Net	49620 lb
Comments				* Manual Weight	Tons 24.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # US787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Details of Use
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup
 Tarp in good serviceable condition
 Container in good condition
 No free standing water
 Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 443-707200 483692

Driver Name Jeff Thomas Driver Signature [Signature]

Remarks
49600
WDL 7R79G 0130



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718607

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/28/2021 Vehicle# 480659 Volume
Payment Type Credit Account Container 480659
Manual Ticket# 1029864 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103240 lb*
In 09/27/2021 11:20:24	MANUAL WT	Jaday		Tare	59700 lb*
Out 09/28/2021 11:20:24		Jaday		Net	43540 lb
Comments					Tons
					21.77

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		21.77	Tons				WA-BELLEVUE
2		EVF-P6-Environment 100	\$				WA-BELLEVUE
3		RAIL T SPW-RAIL BY 100	21.77 Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup 9-22-2021
Time scheduled for pickup noon

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Site:
 1. How Pallets, Boxes, Bundles, etc. are stacked (1800) (max)
 2. How Bundles are stacked
 3. How Pallets are stacked
 4. How Bundles are stacked
 5. How Pallets are stacked
 6. How Bundles are stacked
 7. How Pallets are stacked
 8. How Bundles are stacked
 9. How Pallets are stacked
 10. How Bundles are stacked
 11. How Pallets are stacked
 12. How Bundles are stacked
 13. How Pallets are stacked
 14. How Bundles are stacked
 15. How Pallets are stacked
 16. How Bundles are stacked
 17. How Pallets are stacked
 18. How Bundles are stacked
 19. How Pallets are stacked
 20. How Bundles are stacked
 21. How Pallets are stacked
 22. How Bundles are stacked
 23. How Pallets are stacked
 24. How Bundles are stacked
 25. How Pallets are stacked
 26. How Bundles are stacked
 27. How Pallets are stacked
 28. How Bundles are stacked
 29. How Pallets are stacked
 30. How Bundles are stacked
 31. How Pallets are stacked
 32. How Bundles are stacked
 33. How Pallets are stacked
 34. How Bundles are stacked
 35. How Pallets are stacked
 36. How Bundles are stacked
 37. How Pallets are stacked
 38. How Bundles are stacked
 39. How Pallets are stacked
 40. How Bundles are stacked
 41. How Pallets are stacked
 42. How Bundles are stacked
 43. How Pallets are stacked
 44. How Bundles are stacked
 45. How Pallets are stacked
 46. How Bundles are stacked
 47. How Pallets are stacked
 48. How Bundles are stacked
 49. How Pallets are stacked
 50. How Bundles are stacked
 51. How Pallets are stacked
 52. How Bundles are stacked
 53. How Pallets are stacked
 54. How Bundles are stacked
 55. How Pallets are stacked
 56. How Bundles are stacked
 57. How Pallets are stacked
 58. How Bundles are stacked
 59. How Pallets are stacked
 60. How Bundles are stacked
 61. How Pallets are stacked
 62. How Bundles are stacked
 63. How Pallets are stacked
 64. How Bundles are stacked
 65. How Pallets are stacked
 66. How Bundles are stacked
 67. How Pallets are stacked
 68. How Bundles are stacked
 69. How Pallets are stacked
 70. How Bundles are stacked
 71. How Pallets are stacked
 72. How Bundles are stacked
 73. How Pallets are stacked
 74. How Bundles are stacked
 75. How Pallets are stacked
 76. How Bundles are stacked
 77. How Pallets are stacked
 78. How Bundles are stacked
 79. How Pallets are stacked
 80. How Bundles are stacked
 81. How Pallets are stacked
 82. How Bundles are stacked
 83. How Pallets are stacked
 84. How Bundles are stacked
 85. How Pallets are stacked
 86. How Bundles are stacked
 87. How Pallets are stacked
 88. How Bundles are stacked
 89. How Pallets are stacked
 90. How Bundles are stacked
 91. How Pallets are stacked
 92. How Bundles are stacked
 93. How Pallets are stacked
 94. How Bundles are stacked
 95. How Pallets are stacked
 96. How Bundles are stacked
 97. How Pallets are stacked
 98. How Bundles are stacked
 99. How Pallets are stacked
 100. How Bundles are stacked

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No fire standing in area Yes No
 Container in proper and clear Yes No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading:
 Start Time _____ Box # In 483971 Liters 0 1 2 _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Liters 0 1 2 _____ End Time _____

Transporter Name: CTI Truck/Chassis # 445 + WM

Driver Name: JASON MICHAELS Driver Signature: [Signature]

Results:
Driver Lic
WDL 3213 BJ 43 B
Cap 7.31.2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718609

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483377 Volume
Payment Type Credit Account Container 483377
Manual Ticket# 1029864 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105620 lb*
In 09/27/2021 11:23:07	MANUAL WT	Jaday		Tare	55340 lb*
Out 09/28/2021 11:23:07		Jaday		Net	50280 lb
Comments					Tons
					25.14

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.14	Tons				WA-BELLEVUE
2		EVF-P6-Environment 100	\$				WA-BELLEVUE
3		RAIL T SPW-RAIL BY 100	25.14 Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Site:
 1. How Pallets, Boxes, Bundles, etc. are stacked (1800) (max)
 2. How Bundles are stacked
 3. How Pallets are stacked
 4. How Bundles are stacked
 5. How Pallets are stacked
 6. How Bundles are stacked
 7. How Pallets are stacked
 8. How Bundles are stacked
 9. How Pallets are stacked
 10. How Bundles are stacked
 11. How Pallets are stacked
 12. How Bundles are stacked
 13. How Pallets are stacked
 14. How Bundles are stacked
 15. How Pallets are stacked
 16. How Bundles are stacked
 17. How Pallets are stacked
 18. How Bundles are stacked
 19. How Pallets are stacked
 20. How Bundles are stacked
 21. How Pallets are stacked
 22. How Bundles are stacked
 23. How Pallets are stacked
 24. How Bundles are stacked
 25. How Pallets are stacked
 26. How Bundles are stacked
 27. How Pallets are stacked
 28. How Bundles are stacked
 29. How Pallets are stacked
 30. How Bundles are stacked
 31. How Pallets are stacked
 32. How Bundles are stacked
 33. How Pallets are stacked
 34. How Bundles are stacked
 35. How Pallets are stacked
 36. How Bundles are stacked
 37. How Pallets are stacked
 38. How Bundles are stacked
 39. How Pallets are stacked
 40. How Bundles are stacked
 41. How Pallets are stacked
 42. How Bundles are stacked
 43. How Pallets are stacked
 44. How Bundles are stacked
 45. How Pallets are stacked
 46. How Bundles are stacked
 47. How Pallets are stacked
 48. How Bundles are stacked
 49. How Pallets are stacked
 50. How Bundles are stacked
 51. How Pallets are stacked
 52. How Bundles are stacked
 53. How Pallets are stacked
 54. How Bundles are stacked
 55. How Pallets are stacked
 56. How Bundles are stacked
 57. How Pallets are stacked
 58. How Bundles are stacked
 59. How Pallets are stacked
 60. How Bundles are stacked
 61. How Pallets are stacked
 62. How Bundles are stacked
 63. How Pallets are stacked
 64. How Bundles are stacked
 65. How Pallets are stacked
 66. How Bundles are stacked
 67. How Pallets are stacked
 68. How Bundles are stacked
 69. How Pallets are stacked
 70. How Bundles are stacked
 71. How Pallets are stacked
 72. How Bundles are stacked
 73. How Pallets are stacked
 74. How Bundles are stacked
 75. How Pallets are stacked
 76. How Bundles are stacked
 77. How Pallets are stacked
 78. How Bundles are stacked
 79. How Pallets are stacked
 80. How Bundles are stacked
 81. How Pallets are stacked
 82. How Bundles are stacked
 83. How Pallets are stacked
 84. How Bundles are stacked
 85. How Pallets are stacked
 86. How Bundles are stacked
 87. How Pallets are stacked
 88. How Bundles are stacked
 89. How Pallets are stacked
 90. How Bundles are stacked
 91. How Pallets are stacked
 92. How Bundles are stacked
 93. How Pallets are stacked
 94. How Bundles are stacked
 95. How Pallets are stacked
 96. How Bundles are stacked
 97. How Pallets are stacked
 98. How Bundles are stacked
 99. How Pallets are stacked
 100. How Bundles are stacked

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No fire standing in area Yes No
 Container in proper and clear Yes No

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading:
 Start Time _____ Box # In _____ Liters 0 1 2 _____ Unloading Start Time _____
 End Time _____ Box # Out _____ Liters 0 1 2 _____ End Time _____

Transporter Name: CTI Truck/Chassis # 443-7072 W-480659

Driver Name: Jeff Thomas Driver Signature: [Signature]

Results:
48680
WDL 787960DD



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718611

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483618 Volume
Payment Type Credit Account Contain# 483618
Manual Ticket# 1029871 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106760 lb*
In 09/27/2021 11:25:35	MANUAL WT	Jaday		Tare	56540 lb*
Out 09/28/2021 11:25:35		Jaday		Net	50220 lb
Comments				* Manual Weight	Tons 25.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.11	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.11	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442-707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Tarp needs a new roll-up bar
can # 483377



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718613

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/28/2021 Vehicle# 405020 Volume
Payment Type Credit Account Contain# 405020
Manual Ticket# 1029984 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102800 lb*
In 09/27/2021 11:27:39	MANUAL WT	Jaday		Tare	52460 lb*
Out 09/28/2021 11:27:39		Jaday		Net	50340 lb
Comments				* Manual Weight	Tons 25.17

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.17	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.17	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200 483618

Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks: 49480
WIL 7R79G013B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LFC1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition
 Container in good condition
 No free standing water
 Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
 Transporter Name: **CTI** Track/Chassis # **441707381/405020-1**

Driver Name: _____ Driver Signature: _____
BT 45,580 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718615

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/28/2021 Vehicle# 483313 Volume
 Payment Type Credit Account Container 483313
 Manual Ticket# 1029987 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/27/2021 11:29:55 Scale MANUAL WT Operator Jaday Inbound Gross 111620 lb*
 Out 09/28/2021 11:29:55 Jaday Tare 56740 lb*
 Net 54880 lb
 Comments * Manual Weight Tons 27.44

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		27.44	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	27.44	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LFC1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition
 Container in good condition
 No free standing water
 Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____
 Transporter Name: **CTI** Track/Chassis # **442/707270**

Driver Name: **Brandon Osborne** Driver Signature: **Brandon Osborne**

Remarks
can * 483313



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718617

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 09/28/2021 Vehicle# 483404 Volume
 Payment Type Credit Account Container 483404
 Manual Ticket# 1029987 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/27/2021 11:31:41 Scale MANUAL WT Operator Jaday Inbound Gross 109140 lb*
 Out 09/28/2021 11:31:41 Jaday Tare 57740 lb*
 Net 51400 lb
 Comments * Manual Weight Tons 25.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.70	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.70	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718619

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/28/2021 Vehicle# 480548 Volume
Payment Type Credit Account Container# 480548
Manual Ticket# 1030207 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	10280 lb*	
In 09/27/2021 11:33:33	MANUAL WT	Jaday		Tare	53320 lb*	
Out 09/28/2021 11:33:33		Jaday		Net	49480 lb	
Comments				* Manual Weight	Tons	24.74

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100					WA-BELLEVU
2 EVF-P6-Environment	100	24.74	Tons				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.74	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-28-2021
Time scheduled for pickup 11:20 AM

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
112 South Davis Street Columbia Ridge Landfill and Recycling Center
Beagle, Oregon 97812 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030 Fax: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In 483464 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 + 480548
Driver Name: JASON MICHAELS Driver Signature: _____

Remarks: _____
Driver License
WDL 3213 3743 B
exp 7-31-2027

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
112 South Davis Street Columbia Ridge Landfill and Recycling Center
Beagle, Oregon 97812 18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030 Fax: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 441/782331/480548
Driver Name: Matthew Eggert Driver Signature: _____

Remarks: _____

WM Oregon Waste Systems
A Waste Management Company
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

DATE/TIME: _____
LOAD DATE: _____
CUSTOMER NAME: mystery
PROFILE NUMBER: _____
TRUCK NUMBER: _____
TRAILER/CONTAINER NUMBER: 480548
SEAL NUMBER: _____
CUSTOMER INVOICE NO.: _____

GROSS WEIGHT: _____
TARE WEIGHT-TRACTOR: _____
TARE WGT.-TRAILER/CONTAINER: _____
NET WEIGHT: _____

GATEHOUSE: _____
DRIVER: _____
TRAIN ID: DSEGL 22 ORIGIN: _____
WASTE TYPE: _____
DISPOSAL: CM DC BU GRID SEGREGATE
REMARKS: NO PWR

HALLER



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718621

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483275 Volume
Payment Type Credit Account Container 483275
Manual Ticket# 1029866 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 107860 lb*
In 09/27/2021 11:35:56 MANUAL WT Jaday Tare 57380 lb*
Out 09/28/2021 11:35:56 Jaday Net 50480 lb
* Manual Weight Tons 25.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.24	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.24	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Container Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US-787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver of Rig: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading
End Time _____ Box # Out _____ Liters 0 1 2 Start Time _____

Transporter Name: **CTI** Truck/Trailer # **444/702331/483275**
Driver Name: **Arthur Engel** Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718623

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483714 Volume
Payment Type Credit Account Container 483714
Manual Ticket# 1029873 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 106440 lb*
In 09/27/2021 11:37:47 MANUAL WT Jaday Tare 56940 lb*
Out 09/28/2021 11:37:47 Jaday Net 49500 lb
* Manual Weight Tons 24.75

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.75	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.75	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9/23/2021**
Time scheduled for pickup **10:00 AM**

Container Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US-787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver of Rig: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **483714** Unloading
End Time _____ Box # Out _____ Liters 0 1 2 Start Time _____

Transporter Name: **CTI** Truck/Trailer # **445 + WTL 743136**
Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
**Driver Lic
WDL 3213 BJ 43 B
exp 7 31 2021**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718624

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483988 Volume
Payment Type Credit Account Container# 483988
Manual Ticket# 1029877 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 103900 lb*
In 09/27/2021 11:40:37 MANUAL WT Jaday Tare 55140 lb*
Out 09/28/2021 11:40:37 Jaday Net 48760 lb
* Manual Weight Tons 24.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.38	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-3030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to:
115787WA (LF01 - Contained-In PCE Contaminated Soil)
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-3030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-3030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-707280-483988**

Driver Name: **JEFF THOMAS** Driver Signature: _____

Remarks:
WDL 7R796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718625

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/28/2021 Vehicle# 484047 Volume
Payment Type Credit Account Container# 484047
Manual Ticket# 1029877 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104580 lb*
In 09/27/2021 11:42:58 MANUAL WT Jaday Tare 50640 lb*
Out 09/28/2021 11:42:58 Jaday Net 53940 lb
* Manual Weight Tons 26.97

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.97	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.97	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-3030

Bill Of Lading

Date scheduled for pickup **9/23/2021**
Time scheduled for pickup **12:15 PM**

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to:
115787WA (LF01 - Contained-In PCE Contaminated Soil)
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-3030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-3030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In **WALK UP 484047** Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443 + WA 743136**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
**Driver Lic
WDL 3213 35413 B
exp 7.31.2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718627

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/28/2021 Vehicle# 484051 Volume
Payment Type Credit Account Container 484051
Manual Ticket# 1029879 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105220 lb*
In 09/27/2021 11:45:04 MANUAL WT Jaday Tare 57780 lb*
Out 09/28/2021 11:45:04 Jaday Net 47440 lb
* Manual Weight Tons 23.72

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.72	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.72	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA, Route 10630, Box 10630, Bellevue, Oregon 97812
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 142/9707970

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 484051



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718628

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 09/28/2021 Vehicle# 484052 Volume
Payment Type Credit Account Container 484052
Manual Ticket# 1029880 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105900 lb*
In 09/27/2021 11:46:44 MANUAL WT Jaday Tare 56006 lb*
Out 09/28/2021 11:46:44 Jaday Net 49894 lb
* Manual Weight Tons 24.95

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.95	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.95	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA, Route 10630, Box 10630, Bellevue, Oregon 97812
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 944-74440707994

Driver Name: BRUCE BARNETT Driver Signature: M. B

Remarks: WTL 0722117938



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718629

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483387 Volume
Payment Type Credit Account Container 483387
Manual Ticket# 1029988 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103360 lb*
In 09/27/2021 11:49:07	MANUAL WT	Jaday		Tare	56900 lb*
Out 09/28/2021 11:49:07		Jaday		Net	46460 lb
Comments		* Manual Weight		Tons	23.23

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.23	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.23	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718631

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483814 Volume
Payment Type Credit Account Container 483814
Manual Ticket# 103140 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103140 lb*
In 09/27/2021 11:54:50	MANUAL WT	Jaday		Tare	54180 lb*
Out 09/28/2021 11:54:50		Jaday		Net	48960 lb
Comments		* Manual Weight		Tons	24.48

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.48	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.48	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718632

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483785 Volume
Payment Type Credit Account Container 483785
Manual Ticket# 1029778 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105040 lb*
In 09/27/2021 11:56:42	MANUAL WT	Jaday		Tare	56240 lb*
Out 09/28/2021 11:56:42		Jaday		Net	48800 lb
Comments		* Manual Weight		Tons	24.40

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.40	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.40	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup 9-28-21
Time scheduled for pickup 11:35

Customer Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDI Contaminated Soil Asbestos Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: _____
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Arlington, Oregon 97812-6512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good waterproof condition No YES NEEDS A NEW BAR
Container in good condition No YES
No free standing water No YES
Container is empty and clean No YES

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading _____ Unloading _____
Start Time _____ Box # In _____ Ltrsv # 1 2 Start Time _____
End Time _____ Box # Out _____ Ltrsv # 1 2 End Time _____

Transporter Name: CTI Truck # 446-707287-483814

Driver Name: Scott F Higgins Driver Signature: Scott F Higgins

Remarks:
W.D. # 71122213B 4.6T. 49600



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718633

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483563 Volume
Payment Type Credit Account Container 483563
Manual Ticket# 1029991 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	110840 lb*
In 09/27/2021 11:58:49	MANUAL WT	Jaday		Tare	56500 lb*
Out 09/28/2021 11:58:49		Jaday		Net	54340 lb
Comments				* Manual Weight	Tons 27.17

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		27.17	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	27.17	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Water Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 443-707200 483785

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks: 49660
WDL 7R79G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718634

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483598 Volume
Payment Type Credit Account Container 483598
Manual Ticket# 1029993 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104860 lb*
In 09/27/2021 12:01:42	MANUAL WT	Jaday		Tare	57780 lb*
Out 09/28/2021 12:01:42		Jaday		Net	47080 lb
Comments				* Manual Weight	Tons 23.54

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		23.54	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	23.54	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9/24/21
Time scheduled for pickup 12:00

Generator Name and Loading Address: SCD NE 8TH Water Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Delivery to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition: Yes No
Container in its good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Trailer # 440-707287-483563

Driver Name: SCOTT F. HOGAN Driver Signature: _____

Remarks: WDL # 7IT22313B
LCW 49,660



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718635

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483639 Volume
Payment Type Credit Account Container 483639
Manual Ticket# 1029994 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	111140 lb*
09/27/2021	12:04:17	MANUAL WT	Jaday		Tare	58060 lb*
09/28/2021	12:04:17		Jaday		Net	53080 lb
Comments				* Manual Weight	Tons	26.54

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		26.54	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Admission of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
11577 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Deposit Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp is good and in service condition Yes No
 Container is in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**

Driver Name: **Brendan Osborne** Driver Signature: **Brendan Osborne**

Remarks:
Can # 493598



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718636

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483414 Volume
Payment Type Credit Account Container 483414
Manual Ticket# 1029869 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	106580 lb*
09/27/2021	12:06:25	MANUAL WT	Jaday		Tare	56840 lb*
09/28/2021	12:06:25		Jaday		Net	49740 lb
Comments				* Manual Weight	Tons	24.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		24.87	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Admission of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
11577 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Deposit Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp is good and in service condition Yes No
 Container is in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **443-7072 00-483639**

Driver Name: **Jeff Thomas** Driver Signature: **Jeff Thomas**

Remarks:
99100 49580
WDL 7R799013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718637

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483927 Volume
Payment Type Credit Account Container 483927
Manual Ticket# 1029876 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106340 lb*
In 09/27/2021 12:08:28	MANUAL WT	Jaday		Tare	56740 lb*
Out 09/28/2021 12:08:28		Jaday		Net	49600 lb
Comments				* Manual Weight	Tons 24.80

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.80	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.80	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-28-2021
Time scheduled for pickup 7:30

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

DEPT OF RE: _____ DEPOSIT FACILITY: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL Bar crushed & Bent
RATCHETS NEEDED REPAIR

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck #/Chassis: 440-707287-483414

Driver Name: Scott F Haggard Driver Signature: Scott F Haggard

Remarks: WDL # 71122213B 49,580



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718638

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/28/2021 Vehicle# 480526 Volume
Payment Type Credit Account Container 480526
Manual Ticket# 1030102 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103240 lb*
In 09/27/2021 12:10:53	MANUAL WT	Jaday		Tare	53060 lb*
Out 09/28/2021 12:10:53		Jaday		Net	50190 lb
Comments				* Manual Weight	Tons 25.09

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.09	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.09	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____

Signature: _____ Name: _____

DEPT OF RE: _____ DEPOSIT FACILITY: _____

Container Inspection Upon Pickup: Tarp in good serviceable condition Container in good condition No free standing water Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck #/Chassis: 440-707287-483414

Driver Name: Arthur Eggen Driver Signature: Arthur Eggen

Remarks: ET 49,630 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718639

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483615 Volume
Payment Type Credit Account Container 483615
Manual Ticket# 1030105 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108780 lb*
In 09/27/2021 12:12:39	MANUAL WT	Jaday		Tare	57920 lb*
Out 09/28/2021 12:12:39		Jaday		Net	50860 lb
Comments				* Manual Weight	Tons 25.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.43	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.43	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

BHI Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific South International Parkway - 48303 Tualatin, OR 97146
442 South Division Street - 97130 Beaverton, OR 97005
Phone (503) 766-1200 or (503) 238-7660

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container in proper and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL
CONT# 480526

Loading
Start Time _____ Box # In _____ Lines # 1 2 Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name: **CTC** Truck #/Chassis # **444-743140**

Driver Name: **Bruce Bennett** Driver Signature: *[Signature]*

Remarks: **WDL 7122-1193B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718640

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483050 Volume
Payment Type Credit Account Container 483050
Manual Ticket# 1029986 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	109000 lb*
In 09/27/2021 12:14:15	MANUAL WT	Jaday		Tare	56620 lb*
Out 09/28/2021 12:14:15		Jaday		Net	52380 lb
Comments				* Manual Weight	Tons 26.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.19	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	26.19	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

BHI Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific South International Parkway - 48303 Tualatin, OR 97146
442 South Division Street - 97130 Beaverton, OR 97005
Phone (503) 766-1200 or (503) 238-7660

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container in proper and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL
CONT# 483615

Loading
Start Time _____ Box # In _____ Lines # 1 2 Start Time _____
End Time _____ Box # Out _____ Lines # 1 2 End Time _____

Transporter Name: **CTC** Truck #/Chassis # **444-743130**

Driver Name: **Bruce Bennett** Driver Signature: *[Signature]*

Remarks: **WDL 7122-1193B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718801

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/28/2021 Vehicle# 483588 Volume
Payment Type Credit Account Container 483588
Manual Ticket# 1027193 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/27/2021 07:56:58 Scale MANUAL WT Operator Jaday Inbound Gross 98620 lb*
Out 09/28/2021 07:56:58 Jaday Tare 54240 lb*
Comments * Manual Weight Net 44380 lb
Tons 22.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.19	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-27-2021
Time scheduled for pickup 12:30 PM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: WMX4
Start Time _____ Box # In 183050 Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 445 WM 74336

Driver Name: JASON MICHAELS Driver Signature: _____
Remarks: Driver's Lic
WDL 3213 BT 43 B
09/27/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718802

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/29/2021 Vehicle# 480446 Volume
Payment Type Credit Account Container 480446
Manual Ticket# 1029985 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/28/2021 07:59:51 Scale MANUAL WT Operator Jaday Inbound Gross 108460 lb*
Out 09/29/2021 07:59:51 Jaday Tare 54840 lb*
Comments * Manual Weight Net 53620 lb
Tons 26.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: 0011483588
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: _____ Truck/Chassis # 444-743201

Driver Name: BRUCE PALNETT Driver Signature: _____
Remarks: WDL 3922A 95B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718803

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483678 Volume
Payment Type Credit Account Contain# 483678
Manual Ticket# 1029995 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	109260 lb*
In 09/28/2021 08:02:40	MANUAL WT	Jaday		Tare	55280 lb*
Out 09/29/2021 08:02:40		Jaday		Net	53980 lb
Comments				* Manual Weight	Tons 26.99

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.99	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.99	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container in proper and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Track/Class # 443-707200 480146
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks:
48740
WDL 7R799 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718805

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/29/2021 Vehicle# 480557 Volume
Payment Type Credit Account Contain# 480557
Manual Ticket# 1030215 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*
In 09/28/2021 08:04:31	MANUAL WT	Jaday		Tare	54280 lb*
Out 09/29/2021 08:04:31		Jaday		Net	50960 lb
Comments				* Manual Weight	Tons 25.48

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.48	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.48	Tons				WA-BELLEVU

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container in proper and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Track/Class # 442170720
Driver Name: Brandon Osborne Driver Signature: [Signature]

Remarks:
Can # 483678



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718806

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/29/2021 Vehicle# 480588 Volume
Payment Type Credit Account Container 480588
Manual Ticket# 1030216 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106360 lb*
In 09/28/2021 08:06:00	MANUAL WT	Jaday		Tare	55580 lb*
Out 09/29/2021 08:06:00		Jaday		Net	5780 lb
Comments				* Manual Weight	Tons 25.39

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.39		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		25.39	Tons			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container in empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Container Number: **CONT 480587**

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTE** Truck/Trailer # **444/743130**

Driver Name: **BRUCE BAILEY** Driver Signature: *[Signature]*

Remarks: **WDL # 7722793B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718807

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/29/2021 Vehicle# 480641 Volume
Payment Type Credit Account Container 480641
Manual Ticket# 1030217 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104860 lb*
In 09/28/2021 08:07:24	MANUAL WT	Jaday		Tare	53560 lb*
Out 09/29/2021 08:07:24		Jaday		Net	51300 lb
Comments				* Manual Weight	Tons 25.65

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.65		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		25.65	Tons			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container in empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Container Number: **CONT 480588**

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTE** Truck/Trailer # **440-71837-480588**

Driver Name: **STEVE F. HOGAN** Driver Signature: *[Signature]*

Remarks: **WDL # 7722313B**

LT WT: 48586



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718808

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483149 Volume
Payment Type Credit Account Container 483149
Manual Ticket# 1030218 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107300 lb*
In 09/28/2021 08:09:01	MANUAL WT	Jaday		Tare	54220 lb*
Out 09/29/2021 08:09:01		Jaday		Net	53080 lb
Comments				* Manual Weight	Tons 26.54

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.54	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.54	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200 490641

Driver Name: Jeff Thomas Driver Signature: _____

Remarks:
48360
WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718809

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483400 Volume
Payment Type Credit Account Container 483400
Manual Ticket# 1030219 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108940 lb*
In 09/28/2021 08:10:34	MANUAL WT	Jaday		Tare	55680 lb*
Out 09/29/2021 08:10:34		Jaday		Net	53260 lb
Comments				* Manual Weight	Tons 26.63

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.63	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.63	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 443-707200 483149

Driver Name: Jeff Thomas Driver Signature: _____

Remarks:
49280
WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718812

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483931 Volume
Payment Type Credit Account Container 483931
Manual Ticket# 1030220 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106960 lb*
In 09/28/2021 08:12:01	MANUAL WT	Jaday		Tare	54480 lb*
Out 09/29/2021 08:12:01		Jaday		Net	52480 lb
Comments				* Manual Weight	Tons 26.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		26.24		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		26.24			Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane (LF01) 10660
483 South Street Lane
South, Washington 97136
Phone (509) 746-1200 or (509) 746-1200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition No Yes
 Container in good condition No Yes
 No free standing water No Yes
 Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name **CTI** Truck #/Chassis # **441/702331/483400-0**

Driver Name **Anthony Egger** Driver Signature _____

Remarks:
LT 49,740



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718813

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483432 Volume
Payment Type Credit Account Container 483432
Manual Ticket# 1030038 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98640 lb*
In 09/28/2021 08:13:39	MANUAL WT	Jaday		Tare	53280 lb*
Out 09/29/2021 08:13:39		Jaday		Net	45360 lb
Comments				* Manual Weight	Tons 22.68

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		22.68		Tons	WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100		22.68			Tons	WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **9/24/2021**
Time scheduled for pickup **8:00 AM**

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane (LF01) 10660
483 South Street Lane
South, Washington 97136
Phone (509) 746-1200 or (509) 746-1200

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition No Yes
 Container in good condition No Yes
 No free standing water No Yes
 Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In **483931** Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name **CTI** Truck #/Chassis # **445** W.M. # **743126**

Driver Name **Jason Michaels** Driver Signature _____

Remarks:
**Driver Lic
WDL 3213 BJ 43 B
cap 731 0127**

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **US-787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: **DROP ONLY** PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Truck Class # **4411/7075381/485452-0**
Driver Name: **Admir Ege** Driver Signature: _____

Remarks:
49,760 lbs

WM
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718814

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/29/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1030348 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98240 lb*
In 09/28/2021 08:15:16	MANUAL WT	Jaday		Tare	53680 lb*
Out 09/29/2021 08:15:16		Jaday		Net	44560 lb
Comments					22.28
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.28	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.28	Tons				WA-BELLEVUE

Driver's Signature _____

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **US-787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: **DROP ONLY** PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Truck Class # **4411/7075381/405009-8**
Driver Name: **Admir Ege** Driver Signature: _____

Remarks:

WM
WASTE MANAGEMENT

Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718815

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 09/29/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405016
Manual Ticket# 1030348 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	92300 lb*
In 09/28/2021 08:16:43	MANUAL WT	Jaday		Tare	29580 lb*
Out 09/29/2021 08:16:43		Jaday		Net	62720 lb
Comments					31.36
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		31.36	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		31.36	Tons				WA-BELLEVUE

Driver's Signature _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718817

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 09/29/2021 Vehicle# 480627 Volume
Payment Type Credit Account Container 480627
Manual Ticket# 1030349 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107800 lb*
In 09/28/2021 08:18:17	MANUAL WT	Jaday		Tare	55840 lb*
Out 09/29/2021 08:18:17		Jaday		Net	51960 lb
Comments				* Manual Weight	Tons 25.98

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.98	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.98	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Contract Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: **DROP ONLY** PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: **CTE** Track/Chassis #: **444/707294/405016**

Driver Name: **James Phillips** Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718820

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483121 Volume
Payment Type Credit Account Container 483121
Manual Ticket# 1030352 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108320 lb*
In 09/28/2021 08:19:42	MANUAL WT	Jaday		Tare	64320 lb*
Out 09/29/2021 08:19:42		Jaday		Net	44000 lb
Comments				* Manual Weight	Tons 22.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	22.00	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	22.00	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Contract Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: **DROP ONLY** PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: **CTI** Track/Chassis #: **443-707200/480627**

Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks: **48460**

WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718824

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483880 Volume
Payment Type Credit Account Container 483880
Manual Ticket# 1030354 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107220 lb*
In 09/28/2021 08:20:57	MANUAL WT	Jaday		Tare	70120 lb*
Out 09/29/2021 08:20:57		Jaday		Net	37100 lb
Comments				* Manual Weight	Tons 18.55

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		18.55	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		18.55	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Remarks:
STAIRS MISSING
WDL # 7122213B
LTWG 49,400



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718828

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 09/29/2021 Vehicle# 483956 Volume
Payment Type Credit Account Container 483956
Manual Ticket# 106120 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106120 lb*
In 09/28/2021 08:22:22	MANUAL WT	Jaday		Tare	67340 lb*
Out 09/29/2021 08:22:22		Jaday		Net	38780 lb
Comments				* Manual Weight	Tons 19.39

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		19.39	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		19.39	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person
Telephone Number

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Remarks:
can # 433890

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8th

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LFE1**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - Waste Transfer Station (WTS) Facility (MRF) Unit
455 South Service Road
Beaverton, Oregon 97005
Phone: (503) 638-1111 or (503) 271-7444

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI**
Driver Name: **Arthur Eggert** Driver Signature: _____
Remarks: **ET.Wt. 49,880 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 718833

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
 Ticket Date 09/29/2021 Vehicle# 484000 Volume
 Payment Type Credit Account Container 484000
 Manual Ticket# 1030356 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106340 lb*
In 09/28/2021 08:23:51	MANUAL WT	Jaday		Tare	55720 lb*
Out 09/29/2021 08:23:51		Jaday		Net	56620 lb
Comments		* Manual Weight		Tons	25.31

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.31	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.31	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9-28-2021**
Time scheduled for pickup **2:30 AM**

Generator Name and Loading Address
SCD NE 8th

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LFE1**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
1 - Waste Transfer Station (WTS) Facility (MRF) Unit
455 South Service Road
Beaverton, Oregon 97005
Phone: (503) 638-1111 or (503) 271-7444

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **W/MX L** Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI**
Driver Name: **JOSEPH MICHAELS** Driver Signature: _____
Remarks: **WDL 3213 BF 453**
09/23/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719315

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 10/01/2021 Vehicle# 483627 Volume
 Payment Type Credit Account Container 483627
 Manual Ticket# 1029206 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105820 lb*
In 09/17/2021 13:07:40	Front Scale	jaday		Tare	55620 lb*
Out 10/01/2021 13:07:40		jaday		Net	50200 lb
Comments	NO BOL	* Manual Weight		Tons	25.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.10	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.10	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719316

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483090 Volume
Payment Type Credit Account Container# 483090
Manual Ticket# 1030351 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105260 lb*
In 09/29/2021 13:13:15 Scale jaday Tare 55360 lb*
Out 10/01/2021 13:13:15 Front Scale jaday Net 49900 lb
* Manual Weight Tons 24.95

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.95	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.95	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-15-21
Time scheduled for pickup 12:50

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
115787WA (LF01 - Contained-In PCE Contaminated Soil)
483090 (Vehicle #)
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707281-483090
Driver Name: Scott F. Heard Driver Signature: [Signature]

Remarks:
W.D.L. # 71122213 B LT Wt. 50,000



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719317

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
Ticket Date 10/01/2021 Vehicle# 490019 Volume
Payment Type Credit Account Container# 490019
Manual Ticket# 1030357 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105480 lb*
In 09/29/2021 13:18:58 Scale jaday Tare 53840 lb*
Out 10/01/2021 13:18:58 Front Scale jaday Net 51640 lb
* Manual Weight Tons 25.82

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.82	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.82	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Container Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
115787WA (LF01 - Contained-In PCE Contaminated Soil)
490019 (Vehicle #)
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in its good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707281-490019
Driver Name: Army Egan Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719318

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483221 Volume
Payment Type Credit Account Container 483221
Manual Ticket# 1030353 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 106600 lb*
In 09/29/2021 13:21:54 Front Scale jaday Tare 54280 lb*
Out 10/01/2021 13:21:54 jaday Net 52320 lb
* Manual Weight Tons 26.16

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.16	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.16	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Res. # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Res. # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **447-207294/WB14443021**

Driver Name: **James Phillips** Driver Signature: *[Signature]*

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719378

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483306 Volume
Payment Type Credit Account Container 483306
Manual Ticket# 1030622 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 100480 lb*
In 10/01/2021 08:02:01 MANUAL WT jaday Tare 54680 lb*
Out 10/04/2021 08:02:01 jaday Net 45800 lb
* Manual Weight Tons 22.90

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		22.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.90	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Res. # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Res. # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **447-207200-413306**

Driver Name: **LEFF THOMAS** Driver Signature: *[Signature]*

Remarks:
49900
WDL 7R79G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719380

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483868 Volume
Payment Type Credit Account Container 483868
Manual Ticket# 1030626 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/04/2021 08:06:48 Scale Operator Inbound Gross 104580 lb*
Out 10/04/2021 08:06:48 MANUAL WT jaday Tare 54480 lb*
Net 50100 lb
* Manual Weight Tons 25.05

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.05	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.05	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis #: **441 / 201205 / 185368-0**

Driver Name: **Anthony Egan** Driver Signature: _____

Remarks:
LT 50,120103



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719394

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/03/2021 Vehicle# 483677 Volume
Payment Type Credit Account Container 483677
Manual Ticket# 1030624 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 08:12:11 Scale Operator Inbound Gross 106760 lb*
Out 10/03/2021 08:12:11 MANUAL WT jaday Tare 55110 lb*
Net 51650 lb
* Manual Weight Tons 25.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.83	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.83	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9-30-2021**
Time scheduled for pickup **10:00 AM**

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **483677** Lines **0 1 2** Start Time _____
End Time _____ Box # Out _____ Lines **0 1 2** End Time _____

Transporter Name: **CTI** Truck/Chassis #: **445 / 174636 / 707381**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks:
**Driver Lic
WDL 3213 BT 43 B**

Exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719396

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 10/03/2021 Vehicle# 484062 Volume
Payment Type Credit Account Container 484062
Manual Ticket# 1030628 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 103780 lb*
In 10/01/2021 08:14:07 MANUAL WT jaday Tare 54300 lb*
Out 10/03/2021 08:14:07 jaday Net 49480 lb
* Manual Weight Tons 24.74

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.74	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
412 South Division Street
Beaverton, Oregon 97008
Phone: (503) 646-7471 or 1-800-276-7444 ext 400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAY WTL

Loading: Start Time _____ Box # In _____ Line# 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 484062



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719399

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/01/2021 Vehicle# 480674 Volume
Payment Type Credit Account Container 480674
Manual Ticket# 1030487 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 103780 lb*
In 10/01/2021 08:15:50 MANUAL WT jaday Tare 54160 lb*
Out 10/01/2021 08:15:50 jaday Net 49620 lb
* Manual Weight Tons 24.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.81	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9.29.2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: LF01

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
412 South Division Street
Beaverton, Oregon 97008
Phone: (503) 646-7471 or 1-800-276-7444 ext 400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAY WTL

Loading: Start Time _____ Box # In _____ Line# 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 445 + 743136
Driver Name: Jason Michaels Driver Signature: Jason Michaels

Remarks: Driver lic
WDL 3213 8J 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719400

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483770 Volume
Payment Type Credit Account Container 483770
Manual Ticket# 1030493 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 08:17:18 Scale Operator Inbound Gross 111820 lb*
Out 10/01/2021 08:17:18 MANUAL WT jaday Tare 54480 lb*
Net 57340 lb
* Manual Weight Tons 26.67

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		28.67	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		28.67	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Low-Poll Bulk Transfer Facility (BMTF) at 42340 Pacific Street, South, Multnomah Co, OR 97148
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Ltr# 0 1 2 Start Time _____
End Time _____ Box # Out _____ Ltr# 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **440-707387**
Driver Name: **Scott F Hogan** Driver Signature: *Scott F Hogan* 483770

Remarks: _____

49/16



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719404

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/01/2021 Vehicle# 480567 Volume
Payment Type Credit Account Container 480567
Manual Ticket# 1030486 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 08:19:06 Scale Operator Inbound Gross 109820 lb*
Out 10/01/2021 08:19:06 MANUAL WT jaday Tare 56480 lb*
Net 53340 lb
* Manual Weight Tons 26.67

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.67	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.67	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Low-Poll Bulk Transfer Facility (BMTF) at 42340 Pacific Street, South, Multnomah Co, OR 97148
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No free standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container is empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Ltr# 0 1 2 Start Time _____
End Time _____ Box # Out _____ Ltr# 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **442/707270**
Driver Name: **Brandon Osborne** Driver Signature: *Brandon Osborne*

Remarks: _____

can # 48 05 67



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719406

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483001 Volume
Payment Type Credit Account Container 483001
Manual Ticket# 1030488 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 08:20:32 Scale Operator Inbound Gross 107120 lb*
Out 10/01/2021 08:20:32 MANUAL WT jaday Tare 55960 lb*
Net 51160 lb
* Manual Weight Tons 25.58

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.58	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.58	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-29-2021
Time scheduled for pickup 10:00 AM

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # US-787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person
Telephone Number

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Date of Use
1-Load/Full, 2-Load/Intermediate/Full, 3-Empty/Full
4-2-Load/Empty/Full
5-Empty/Intermediate/Full
6-Empty/Empty/Full
Please Circle One (1) or Two (2) or Three (3)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483001 Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 445 WM # 745156

Driver Name Jason Michaels Driver Signature _____

Remarks:
Driver Lic
WDL 3213 BJ 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719409

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483251 Volume
Payment Type Credit Account Container 483251
Manual Ticket# 1030789 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 08:22:02 Scale Operator Inbound Gross 110480 lb*
Out 10/01/2021 08:22:02 MANUAL WT jaday Tare 55140 lb*
Net 55140 lb
* Manual Weight Tons 27.57

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		27.57	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		27.57	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-28-21
Time scheduled for pickup 2:00

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # US-787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person
Telephone Number

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Date of Use
1-Load/Full, 2-Load/Intermediate/Full, 3-Empty/Full
4-2-Load/Empty/Full
5-Empty/Intermediate/Full
6-Empty/Empty/Full
Please Circle One (1) or Two (2) or Three (3)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 440-707287-493261

Driver Name Scott F Hegar Driver Signature _____

Remarks:
WDL 71122213B LT W. 49 808



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719412

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483252 Volume
Payment Type Credit Account Container 483252
Manual Ticket# 1030490 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108000 lb*
In 10/01/2021 08:23:21	MANUAL WT	jaday		Tare	54760 lb*
Out 10/01/2021 08:23:21		jaday		Net	53240 lb
		* Manual Weight		Tons	26.62

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	26.62	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	26.62	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-29-21
Time scheduled for pickup 9:40

Concrete Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site:
Location: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Class # AHD-707897-483252
Driver Name: SCOTT F HOGAN Driver Signature: [Signature]

Remarks:
WDL # 2122213B 11 Wt. 50.580



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719415

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483284 Volume
Payment Type Credit Account Container 483284
Manual Ticket# 1030491 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106760 lb*
In 10/01/2021 08:24:40	MANUAL WT	jaday		Tare	56720 lb*
Out 10/01/2021 08:24:40		jaday		Net	50040 lb
		* Manual Weight		Tons	25.02

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	25.02	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	25.02	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Concrete Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site:
Location: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: CTI Truck/Class # 443-707000-483284
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks:
50000
WDL 7R796013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719419

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/01/2021 Vehicle# 483723 Volume
Payment Type Credit Account Container 483723
Manual Ticket# 1030492 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 107760 lb*
In 10/01/2021 08:25:56 MANUAL WT jaday 54860 lb*
Out 10/01/2021 08:25:56 jaday 52900 lb*
* Manual Weight Tons 26.45

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.45	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.45	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: **GTI** Truck # **441/207381/485723**
Driver Name: **Arthur Eggen** Driver Signature: _____

Remarks: **LT 50,060lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719612

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1030480 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 99380 lb*
In 10/01/2021 06:41:58 MANUAL WT jaday 51720 lb*
Out 10/04/2021 06:41:58 jaday 47660 lb*
* Manual Weight Tons 23.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.83	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.83	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: **GTI** Truck # **441/207381/405004-0**
Driver Name: **Arthur Eggen** Driver Signature: _____

Remarks: **45,900lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719614

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container 405011
Manual Ticket# 1030482 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/01/2021 06:44:06 MANUAL WT Operator jaday Inbound Gross 98640 lb*
Out 10/04/2021 06:44:06 jaday Tare 50980 lb*
Net 47660 lb
* Manual Weight Tons 23.83

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.83	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.83	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-28-21
Time scheduled for pickup 16:35

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Bill: Full Truck, Partial Truck, Transfer Station
North Management Office: _____
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 440-767281-405011
Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks:
WDL TIT2225B AJWA 45 920



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719621

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405012 Volume
Payment Type Credit Account Container 405012
Manual Ticket# 1030482 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/28/2021 06:45:38 MANUAL WT Operator jaday Inbound Gross 98960 lb*
Out 10/04/2021 06:45:38 jaday Tare 56360 lb*
Net 42600 lb
* Manual Weight Tons 21.30

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		21.30	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		21.30	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115-787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Bill: Full Truck, Partial Truck, Transfer Station
North Management Office: _____
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 440-767281-405012
Driver Name: Arthur Cooper Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719622

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405017 Volume
Payment Type Credit Account Container 405017
Manual Ticket# 1030485 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	Net	Manual Weight
In 09/28/2021 06:53:38	MANUAL WT	jaday		98460 lb*	51780 lb*	
Out 10/04/2021 06:53:38		jaday			46680 lb	
		* Manual Weight				23.34

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.34	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		23.34	Tons				

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Container Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines @ 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines @ 1 2 End Time: _____

Transporter Name: **CTI** Truck/Trailer #: **443-707200-405017**
Driver Name: **Jeff Thomas** Driver Signature: _____
Remarks: **45300**
WDL 7R799 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719624

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483620 Volume
Payment Type Credit Account Container 483620
Manual Ticket# 1030623 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	Net	Manual Weight
In 10/01/2021 06:55:42	MANUAL WT	jaday		104280 lb*	54180 lb*	
Out 10/04/2021 06:55:42		jaday			50100 lb	
		* Manual Weight				25.05

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.05	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.05	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9/30/2021**
Time scheduled for pickup **8:00 AM**

Generate Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Container Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: **483620** Lines @ 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines @ 1 2 End Time: _____

Transporter Name: **CTI** Truck/Trailer #: **445**
Driver Name: **Jason Michaels** Driver Signature: _____
Remarks: **Driver pic**
WDL 3213 BJ-43 B
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719625

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483856 Volume
Payment Type Credit Account Container 483856
Manual Ticket# 1030625 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 107680 lb*
In 10/01/2021 06:57:47 MANUAL WT jaday Tare 55560 lb*
Out 10/04/2021 06:57:47 jaday Net 52120 lb
* Manual Weight Tons 26.06

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.06	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.06	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Bill: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **441-707205-1483856-2**
Driver Name: **Anthony Eggen** Driver Signature: _____
Remarks: **LT 51,200 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719626

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483959 Volume
Payment Type Credit Account Container 483959
Manual Ticket# 1030627 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105380 lb*
In 10/01/2021 07:00:23 MANUAL WT jaday Tare 54540 lb*
Out 10/04/2021 07:00:23 jaday Net 50840 lb
* Manual Weight Tons 25.42

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.42	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.42	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **9:30**
Time scheduled for pickup **7:15**

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Bill: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 3 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **440-707287-483959**
Driver Name: **SCOTT F. HOGAN** Driver Signature: _____
Remarks: **WDL 71122213B LT.Wt. 50,230**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719628

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483383 Volume
Payment Type Credit Account Container# 483383
Manual Ticket# 1030747 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 107060 lb*
In 10/02/2021 07:02:34 MANUAL WT jaday Tare 56820 lb*
Out 10/04/2021 07:02:34 jaday Net 50240 lb
* Manual Weight Tons 25.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.12	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.12	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Contract Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: Columbia Ridge Landfill and Recycling Center
412 South River Street
North, Washington 97149
Phone: (509) 749-7100 or 1-800-235-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	No	Yes
Container in good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Class # **443-707205 / 4833832**
Driver Name: **Amiel Equid** Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719630

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483392 Volume
Payment Type Credit Account Container# 483392
Manual Ticket# 1030748 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 105200 lb*
In 10/02/2021 07:04:08 MANUAL WT jaday Tare 54140 lb*
Out 10/04/2021 07:04:08 jaday Net 51060 lb
* Manual Weight Tons 25.53

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.53	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.53	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Contract Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: Columbia Ridge Landfill and Recycling Center
412 South River Street
North, Washington 97149
Phone: (509) 749-7100 or 1-800-235-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	No	Yes
Container in good condition	<input type="checkbox"/>	<input type="checkbox"/>
No free standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lanes 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CTI** Truck/Class # **443-707200 / 483392**
Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks: **49760**
WDL 787G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719632

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483412 Volume
Payment Type Credit Account Container 483412
Manual Ticket# 1030749 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107060 lb*
In 10/02/2021 07:05:47	MANUAL WT	jaday		Tare	55900 lb*
Out 10/04/2021 07:05:47		jaday		Net	51160 lb
		* Manual Weight		Tons	25.58

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.58	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.58	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 9-30-21
Time scheduled for pickup 1:00 PM

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
18177 Cedar Springs Lane
North, Washington 97149
Phone (509) 748-1100 or (509) 748-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In 48-3412 Liers # 1 2 Start Time _____
End Time _____ Box # Out _____ Liers # 1 2 End Time _____
Transporter Name CTI Truck/Chassis # 445 +
Driver Name Jason Michaels Driver Signature _____ 941397

Remarks:
Driver Lic
WDL 3213 BJ 43 B
09/30/21



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719634

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483493 Volume
Payment Type Credit Account Container 483493
Manual Ticket# 1030750 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100540 lb*
In 10/02/2021 07:07:14	MANUAL WT	jaday		Tare	55560 lb*
Out 10/04/2021 07:07:14		jaday		Net	44990 lb
		* Manual Weight		Tons	22.49

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		22.49	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.49	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 9-30-21
Time scheduled for pickup 12:30

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
18177 Cedar Springs Lane
North, Washington 97149
Phone (509) 748-1100 or (509) 748-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading:
Start Time _____ Box # In _____ Liers # 1 2 Start Time _____
End Time _____ Box # Out _____ Liers # 1 2 End Time _____
Transporter Name CTI Truck/Chassis # 440-707287-483493
Driver Name Scott F Hynd Driver Signature _____

Remarks:
WDL 71122213B
LT WT 49,860



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719635

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483561 Volume
Payment Type Credit Account Container 483561
Manual Ticket# 1030751 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105480 lb*
In 10/02/2021 07:09:00	MANUAL WT	jaday		Tare	54180 lb*
Out 10/04/2021 07:09:00		jaday		Net	51300 lb
		* Manual Weight		Tons	25.65

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.65	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.65	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **443-707202 483561**

Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks:
49980
WDL 7R79G 013D



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719635

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483639 Volume
Payment Type Credit Account Container 483639
Manual Ticket# 1030752 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105180 lb*
In 10/02/2021 07:10:21	MANUAL WT	jaday		Tare	51120 lb*
Out 10/04/2021 07:10:21		jaday		Net	54060 lb
		* Manual Weight		Tons	27.03

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		27.03	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		27.03	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US 787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **44D-707287-418364**

Driver Name: **Scott F. Ryan** Driver Signature: *[Signature]*

Remarks:
WDL 7TE2213B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719638

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 10/04/2021 Vehicle# 400501 Volume
Payment Type Credit Account Container 400501
Manual Ticket# 1030859 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/04/2021 07:11:39 Scale Operator Inbound Gross 96760 lb*
Out 10/04/2021 07:11:39 MANUAL WT jaday Tare 49960 lb*
Net 46800 lb
* Manual Weight Tons 23.40

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.40	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.40	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-21-2021
Time scheduled for pickup 12:00

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDI
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Delivery to:
400501-Scrub (Removal) Facility (L002) (L001)
400501-Scrub (Removal) Facility (L002) (L001)
Banks, Multiquip # 010
Pallets (See Manifest for High/Low/No/None)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In W-544 400501 Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis # 445 * W.M. 743136
Driver Name: Jason Michaels Driver Signature _____
Remarks:
Driver Lic
WDL 3213 BT 43 B
exp 7/31/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719639

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405006 Volume
Payment Type Credit Account Container 405006
Manual Ticket# 1030860 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/04/2021 07:13:05 Scale Operator Inbound Gross 97500 lb*
Out 10/04/2021 07:13:05 MANUAL WT jaday Tare 50500 lb*
Net 47000 lb
* Manual Weight Tons 23.50

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.50	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-21-21
Time scheduled for pickup 11:45

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # 115787WA

Waste Type
 CDI
 Contaminated Soil
 Asbestos
 Other: LF01

Company Name _____ Date _____
Signature _____ Name _____

Delivery to:
400501-Scrub (Removal) Facility (L002) (L001)
400501-Scrub (Removal) Facility (L002) (L001)
Banks, Multiquip # 010
Pallets (See Manifest for High/Low/No/None)

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Chassis # 440-707287-405006
Driver Name: SCOTT F HOGAN Driver Signature _____
Remarks:
WDL # TT22213B
L/W 460088



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719640

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/04/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container 405013
Manual Ticket# 1030863 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96200 lb*
In 10/04/2021 07:14:43	MANUAL WT	jaday		Tare	49960 lb*
Out 10/04/2021 07:14:43		jaday		Net	46240 lb
		* Manual Weight		Tons	23.12

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.12	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.12	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal or Use: _____ Disposal Facility: _____
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 4911/7075231/405013-8
Driver Name: Arthur Lopez Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719641

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483005 Volume
Payment Type Credit Account Container 483005
Manual Ticket# 1030866 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	109260 lb*
In 10/04/2021 07:16:04	MANUAL WT	jaday		Tare	55380 lb*
Out 10/04/2021 07:16:04		jaday		Net	53890 lb
		* Manual Weight		Tons	26.94

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.94	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.94	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 9-30-21
Time scheduled for pickup 9:20

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: US-787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal or Use: _____ Disposal Facility: _____
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South
1500 Park, South, Interstate 5 (1000) South

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 440-707287-483005
Driver Name: Scott F Hogan Driver Signature: _____

Remarks:
DDL # 71122213B LT WT



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719642

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/04/2021 Vehicle# 483291 Volume
Payment Type Credit Account Container 483291
Manual Ticket# 1030975 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 104680 lb*
In 10/02/2021 07:17:21 MANUAL WT jaday 53640 lb*
Out 10/04/2021 07:17:21 jaday 51040 lb
* Manual Weight Tons 25.52

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.52	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.52	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115-787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
A-2 Bulk Debris Area
North Thompson Office
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Line# 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 1 2 End Time _____

Transporter Name: **CTJ** Truck/Chassis # **4A2 / 707270**

Driver Name: **Brendan Osborne** Driver Signature: **Brendan Osborne**

Remarks: **Can # 433291**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719889

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/06/2021 Vehicle# 483738 Volume
Payment Type Credit Account Container 483738
Manual Ticket# 1028122 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 103980 lb*
In 10/06/2021 07:18:37 MANUAL WT jaday 54180 lb*
Out 10/06/2021 07:18:37 jaday 49800 lb
* Manual Weight Tons 24.90

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.90	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **7-28-2021**
Time scheduled for pickup **2:30 PM**

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115-787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: **CITY TRANSPORT INC** Date: **7-28-2021**
Signature: **[Signature]** Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
A-2 Bulk Debris Area
North Thompson Office
Phone: (541) 454-2030

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In **WHSX483738** Line# 0 1 2 Start Time _____
End Time _____ Box # Out _____ Line# 0 1 2 End Time _____

Transporter Name: **CITY TRANSPORT INC** Truck/Chassis # _____

Driver Name: **[Name]** Driver Signature: **[Signature]**

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719892

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405003 Volume
Payment Type Credit Account Container 405003
Manual Ticket# 1030479 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/30/2021 07:21:30 Scale Operator Inbound Gross 97060 lb*
Out 10/05/2021 07:21:30 MANUAL WT jaday Tare 52200 lb*
Net 44860 lb
* Manual Weight Tons 22.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.43	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.43	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 - one Pacific Waste Materials facility (WMO) each
2 - 2 East Bellevue Street
Arlington, Oregon 97812
Phone: (541) 454-2030 or (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Litters # 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters # 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **443-707200-405003**
Driver Name: **Jeff Thomas** Driver Signature: *[Signature]*

Remarks: **45720**
WTL 7R79F013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719893

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1030481 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 09/30/2021 07:23:05 Scale Operator Inbound Gross 98360 lb*
Out 10/05/2021 07:23:05 MANUAL WT jaday Tare 50620 lb*
Net 47740 lb
* Manual Weight Tons 23.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.87	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.87	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile # **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: **LF01**

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
1 - one Pacific Waste Materials facility (WMO) each
2 - 2 East Bellevue Street
Arlington, Oregon 97812
Phone: (541) 454-2030 or (541) 454-2030

Dispose Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Litters # 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Litters # 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis # **444/707204/405005**
Driver Name: **James Phillips** Driver Signature: *[Signature]*

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719894

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405014 Volume
Payment Type Credit Account Container# 405014
Manual Ticket# 1030484 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 97480 lb*
In 09/30/2021 07:24:39 MANUAL WT jaday Tare 51320 lb*
Out 10/05/2021 07:24:39 jaday Net 46160 lb*
* Manual Weight Tons 23.08

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.08	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.08	Tons				WA-BELLEVU

Driver's Signature

Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
405 South Street
Arlington, Oregon 97812
Phone: (541) 454-2030

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time

Transporter Name: CTI Truck/Trailer # 442/707270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
Can # 405014



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719895

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container# 405007
Manual Ticket# 1030861 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 98240 lb*
In 10/04/2021 07:26:22 MANUAL WT jaday Tare 51200 lb*
Out 10/05/2021 07:26:22 jaday Net 47040 lb*
* Manual Weight Tons 23.52

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.52	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.52	Tons				WA-BELLEVU

Driver's Signature

Waste Management
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
405 South Street
Arlington, Oregon 97812
Phone: (541) 454-2030

Dispose Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time

Transporter Name: CTI Truck/Trailer # 443-707900-405007
Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks:
45980
WDL 7A79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719896

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/05/2021 Vehicle# 483244 Volume
Payment Type Credit Account Container 483244
Manual Ticket# 1030868 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/03/2021 07:31:04 Scale Operator Inbound Gross 100680 lb*
Out 10/05/2021 07:31:04 MANUAL WT jaday Tare 52280 lb*
Net 48400 lb
* Manual Weight Tons 24.20

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.20	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.20	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-29-2021
Time scheduled for pickup 12:25 pm

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Ashes
 Other **LF01**

Waste Profile # **US-787WA**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of use:
1. How Pallets, Bundles, Intermediate Containers, etc. are used
2. How Bundles, Bundles, etc. are used
3. How Bundles, Bundles, etc. are used
4. How Bundles, Bundles, etc. are used

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: **W/M/X/L**
Start Time _____ Box # In **425214** Liters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis # **445 WA 742136**
Driver Name: **Jason Michels** Driver Signature: _____
Remarks:
**Driver Lic
WDL 3213 BJ 413 B
cap 7-31-2027**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719897

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/05/2021 Vehicle# 483273 Volume
Payment Type Credit Account Container 483273
Manual Ticket# 1030868 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/03/2021 07:32:47 Scale Operator Inbound Gross 107140 lb*
Out 10/05/2021 07:32:47 MANUAL WT jaday Tare 55360 lb*
Net 51780 lb
* Manual Weight Tons 25.89

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.89	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.89	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading
Date scheduled for pickup 9-29-21
Time scheduled for pickup 12:20 pm

Generator Name and Loading Address
SCD NE 8TH

Waste Type
 CDL
 Contaminated Soil
 Ashes
 Other **LF01**

Waste Profile # **US-787WA**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of use:
1. How Pallets, Bundles, Intermediate Containers, etc. are used
2. How Bundles, Bundles, etc. are used
3. How Bundles, Bundles, etc. are used
4. How Bundles, Bundles, etc. are used

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: **BENT BAR + STRAPS MISSING**
Start Time _____ Box # In _____ Liters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis # **H40-707287-483273**
Driver Name: **Scott F Hogan** Driver Signature: _____
Remarks:
**WDL # 71122213B
LTIW: 50.560**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719899

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/05/2021 Vehicle# 483583 Volume
Payment Type Credit Account Container 483583
Manual Ticket# 1030871 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/03/2021 07:34:12 Scale Operator Inbound Gross 106420 lb*
Out 10/05/2021 07:34:12 MANUAL WT jaday Tare 55400 lb*
Net 51020 lb
* Manual Weight Tons 25.51

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.51	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.51	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Origin: _____ Disposal Facility: _____
115787WA (LF01 - Contained-In PCE Contaminated Soil)

Container Inspection Upon Pickup:
Tary in good serviceable condition No Yes
Container is in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck # 4811/107205/485583-5
Driver Name: Brandon Osburne Driver Signature: Brandon Osburne

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719899

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405015 Volume
Payment Type Credit Account Container 405015
Manual Ticket# 1030864 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/03/2021 07:35:25 Scale Operator Inbound Gross 98400 lb*
Out 10/05/2021 07:35:25 MANUAL WT jaday Tare 49600 lb*
Net 48800 lb
* Manual Weight Tons 24.40

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.40	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.40	Tons				WA-BELLEVU

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile #: 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Origin: _____ Disposal Facility: _____
115787WA (LF01 - Contained-In PCE Contaminated Soil)

Container Inspection Upon Pickup:
Tary in good serviceable condition No Yes
Container is in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck # _____
Driver Name: Brandon Osburne Driver Signature: Brandon Osburne

Remarks: _____

can # 405015



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 719900

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/05/2021 Vehicle# 405008 Volume
Payment Type Credit Account Container 405008
Manual Ticket# 1030862 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 99120 lb*
In 10/03/2021 07:36:44 MANUAL WT jaday Tare 50720 lb*
Out 10/05/2021 07:36:44 jaday Net 48400 lb
* Manual Weight Tons 24.20

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.20	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.20	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-28-2021
Time scheduled for pickup 11:00 AM

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 405 Park Blvd, Beaverton, OR 97005
405 Back Street Lane
Beaverton, Oregon 97005
Phone: (503) 638-7400 or 1-800-451-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container is in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 405008 Lines 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 445 WMA 743136

Driver Name: Jason Michaels Driver Signature: _____
Remarks:
Driver Lic
WDL 3215 BJ 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720092

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/05/2021 Vehicle# 483010 Volume
Payment Type Credit Account Container 483010
Manual Ticket# 1030746 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time Scale Operator Inbound Gross 92900 lb*
In 10/02/2021 07:17:27 MANUAL WT jaday Tare 54860 lb*
Out 10/05/2021 07:17:27 jaday Net 38040 lb
* Manual Weight Tons 19.02

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		19.02	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		19.02	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH Waste Profile # 115787WA

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 405 Park Blvd, Beaverton, OR 97005
405 Back Street Lane
Beaverton, Oregon 97005
Phone: (503) 638-7400 or 1-800-451-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No
Container is in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In 483010 Lines 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____
Transporter Name: CTI Truck/Trailer # 445 WMA 743136

Driver Name: JASON MICHAELS Driver Signature: _____
Remarks:
Driver Lic
WDL 3215 BJ 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720096

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/05/2021 Vehicle# 483966 Volume
Payment Type Credit Account Container 483966
Manual Ticket# 1030999 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/05/2021 07:19:21 Scale Operator Inbound Gross 105620 lb*
Out 10/05/2021 07:19:21 MANUAL WT jaday Tare 60920 lb*
Net 44700 lb
* Manual Weight Tons 22.35

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		22.35	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.35	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115 South Street (Industrial Facility - 1000) South
415 South Bureau Road
South, Washington 97137
Phone: (509) 748-1100 or (509) 748-1108

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CT Truck/Chassis # 444-743110

Driver Name: BRUCE BAUGHN Driver Signature: [Signature]

Remarks: WVL 272 ZT 193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720100

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/06/2021 Vehicle# 483889 Volume
Payment Type Credit Account Container 483889
Manual Ticket# 1030753 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/02/2021 07:20:50 Scale Operator Inbound Gross 108320 lb*
Out 10/06/2021 07:20:50 MANUAL WT jaday Tare 60840 lb*
Net 47480 lb
* Manual Weight Tons 23.74

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.74	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.74	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 115 South Street (Industrial Facility - 1000) South
415 South Bureau Road
South, Washington 97137
Phone: (509) 748-1100 or (509) 748-1108

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 442 / 707270

Driver Name: Brandon Osborne Driver Signature: [Signature]

Remarks: can # 483889



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720103

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/06/2021 Vehicle# 405019 Volume
Payment Type Credit Account Container# 405019
Manual Ticket# 1030865 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96660 lb*
In 10/04/2021 07:22:21	MANUAL WT	jaday		Tare	50760 lb*
Out 10/06/2021 07:22:21		jaday		Net	45900 lb
		* Manual Weight		Tons	22.95

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	22.95	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	22.95	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 44213707210
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
Can # 405019



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720104

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/06/2021 Vehicle# 483044 Volume
Payment Type Credit Account Container# 483044
Manual Ticket# 1030867 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106020 lb*
In 10/04/2021 07:24:05	MANUAL WT	jaday		Tare	57320 lb*
Out 10/06/2021 07:24:05		jaday		Net	48700 lb
		* Manual Weight		Tons	24.35

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T	100	24.35	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.35	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 443-702200-483044
Driver Name: Jeff Thomas Driver Signature: Jeff Thomas

Remarks:
CAT WALK MISSING BOLTS & NUTS
50880
WDL7R99013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720105

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/06/2021 Vehicle# 483487 Volume
Payment Type Credit Account Container 483487
Manual Ticket# 1030870 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/04/2021 07:25:22 MANUAL WT Operator jaday Inbound Gross 107840 lb*
Out 10/06/2021 07:25:22 jaday Tare 57680 lb*
Net 50160 lb
* Manual Weight Tons 25.08

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.08	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.08	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: U5787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROPP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 4821707205/483487-0
Driver Name: Arthur Egner Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720106

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/06/2021 Vehicle# 483305 Volume
Payment Type Credit Account Container 483305
Manual Ticket# 1030996 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/05/2021 07:26:47 MANUAL WT Operator jaday Inbound Gross 103860 lb*
Out 10/06/2021 07:26:47 jaday Tare 54560 lb*
Net 49300 lb
* Manual Weight Tons 24.65

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.65	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.65	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: U5787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROPP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 4821707270
Driver Name: Brandon Osborne Driver Signature: _____

Remarks:

Can # 483305



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720107

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/06/2021 Vehicle# 480615 Volume
Payment Type Credit Account Container 480615
Manual Ticket# 1031011 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/05/2021 07:28:04 MANUAL WT Operator Inbound Gross 67800 lb*
Out 10/06/2021 07:28:04 jaday Tare 14160 lb*
jaday Net 53640 lb*
* Manual Weight Tons 26.82

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		26.82	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		26.82	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup
Time scheduled for pickup

Generator Name and Loading Address: Seattle Iron & Metals Corp., 801 S. Myrtle St., Seattle, WA 98108
Contact Person: Ed Armstrong
Telephone Number: 206 3960569

Waste Profile #: 129577-OR
Waste Type: CDL, Contaminated Soil, Asbestos, Other

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Union Pacific North Intermodal Facility (4800 Yard), 402 South Duane Street, Seattle, Washington 98108, Phone (206) 744-2300 or (800) 326-7444
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: 480615 Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: 48324A Liners 0 1 2 End Time: _____

Transporter Name: _____ Truck/Chassis #: 63743210
Driver Name: Jim Ackor Driver Signature: [Signature]

Remarks: Driver License # AKERKT



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720480

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/07/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container 405009
Manual Ticket# 1031105 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/06/2021 09:04:44 MANUAL WT Operator Inbound Gross 99260 lb*
Out 10/07/2021 09:04:44 jaday Tare 53820 lb*
jaday Net 45440 lb*
* Manual Weight Tons 22.72

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		22.72	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.72	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup
Time scheduled for pickup

Generator Name and Loading Address: SCD NE 8TH
Contact Person:
Telephone Number:

Waste Profile #: 115787WA
Waste Type: CDL, Contaminated Soil, Asbestos, Other: LF01

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Union Pacific North Intermodal Facility (4800 Yard), 402 South Duane Street, Seattle, Washington 98108, Phone (206) 744-2300 or (800) 326-7444
Disposal Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812-6512, Phone (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: OTE Truck/Chassis #: 405/70122/405009
Driver Name: James Phillips Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720484

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/07/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container 405015
Manual Ticket# 1031106 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/06/2021 09:06:03 Scale Operator Inbound Gross 98040 lb*
Out 10/07/2021 09:06:03 MANUAL WT jaday Tare 51080 lb*
Net 46960 lb
* Manual Weight Tons 23.48

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.48	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.48	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Job: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONT 405016

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____

Transporter Name: CTE Truck/Trailer # 444-701294
Driver Name: PHILIP PHILLIPS Driver Signature: [Signature]
Remarks: WPL 277221938



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720488

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/07/2021 Vehicle# 483249 Volume
Payment Type Credit Account Container 483249
Manual Ticket# 1031107 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In 10/06/2021 09:07:29 Scale Operator Inbound Gross 105900 lb*
Out 10/07/2021 09:07:29 MANUAL WT jaday Tare 55340 lb*
Net 50560 lb
* Manual Weight Tons 25.28

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.28	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.28	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Job: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tary in good serviceable condition No
Container in good condition No
No free standing water No
Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time _____ Box # In _____ Liters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liters 0 1 2 End Time _____

Transporter Name: CTE Truck/Trailer # 482/207220/483249
Driver Name: JAMES PHILLIPS Driver Signature: [Signature]
Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720489

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/07/2021 Vehicle# 483382 Volume
Payment Type Credit Account Container 483382
Manual Ticket# 1031108 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

In 10/06/2021 09:08:48 MANUAL WT Operator Inbound Gross 106960 lb*
Out 10/07/2021 09:08:48 jaday Tare 57760 lb*
Net 49200 lb
* Manual Weight Tons 24.60

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.60	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.60	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit to: _____
1-800-Pace, North International Facility (800) 543-6434
12-04-04
South, Northgate 9714
Phone: (503) 261-5500 or (503) 276-7448

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing material Yes No
 Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **PTC** Truck/Trailer # **444-707294**

Driver Name: **BRUCE BUNNETT** Driver Signature: *[Signature]*

Remarks: **WPL 27227793B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720490

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/07/2021 Vehicle# 483505 Volume
Payment Type Credit Account Container 483505
Manual Ticket# 1031109 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10660 NE 8TH STREET BELLEVUE

In 10/06/2021 09:10:12 MANUAL WT Operator Inbound Gross 103064 lb*
Out 10/07/2021 09:10:12 jaday Tare 54656 lb*
Net 48408 lb
* Manual Weight Tons 24.20

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.20	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.20	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Debit to: _____
1-800-Pace, North International Facility (800) 543-6434
12-04-04
South, Northgate 9714
Phone: (503) 261-5500 or (503) 276-7448

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing material Yes No
 Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
 End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **PTC** Truck/Trailer # **444 707225/483505-4**

Driver Name: **Arturo Equino** Driver Signature: *[Signature]*

Remarks: **LT. 49, 360113**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720491

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 10/07/2021 Vehicle# 484004 Volume
Payment Type Credit Account Container 484004
Manual Ticket# 1031111 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105160 lb*
In 10/06/2021 09:11:47	MANUAL WT	jaday		Tare	55280 lb*
Out 10/07/2021 09:11:47		jaday		Net	49880 lb
		* Manual Weight		Tons	24.94

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		24.94	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		24.94	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 10-6-2021
Time scheduled for pickup 8 AM

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # US787WA

Waste Type
 CDL
 Contaminated Soil
 Adhesives
 Other LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Date of Bill: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tare in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Circle ONE: DROP ONLY PICK UP ONLY WSP WTL

Loading:
Start Time _____ Box # In 487004 Litter 1 2 Start Time _____
End Time _____ Box # Out _____ Litter 0 1 2 End Time _____
Transporter Name CTI Truck/Chassis # 4415 # 745-34
Driver Name JASON MICHAELS Driver Signature _____ # 707581

Remarks:
Driver Lic
WDL 3213 BT 43 B
09/7/2021
Tare 49820



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720663

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/06/2021 Vehicle# 480552 Volume
Payment Type Credit Account Container 480552
Manual Ticket# 1031094 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105080 lb*
In 09/30/2021 06:38:56	MANUAL WT	jaday		Tare	54840 lb*
Out 10/06/2021 06:38:56		jaday		Net	50240 lb
		* Manual Weight		Tons	25.12

Comments No Bill of Lading attached. Just an email.

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		25.12	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.12	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720664

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/08/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1031252 Billing # 0002819
Hauling Ticket# Manifest 3535035-200
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98740 lb*
In 10/07/2021 06:41:23	MANUAL WT	jaday		Tare	51220 lb*
Out 10/08/2021 06:41:23		jaday		Net	47520 lb
		* Manual Weight		Tons	23.76

Comments

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont. Soil Sp. W.-T 100		23.76	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		23.76	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720666

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/08/2021 Vehicle# 483295 Volume
Payment Type Credit Account Container 483295
Manual Ticket# 1031254 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105480 lb*
In 10/07/2021 06:43:05	MANUAL WT	jaday		Tare	55640 lb*
Out 10/08/2021 06:43:05		jaday		Net	49840 lb
Comments				* Manual Weight	Tons 24.92

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.92	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.92	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup 10-6-21
Time scheduled for pickup 11:50

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 440-701297-403004
Driver Name: Scott F. Haggard Driver Signature: [Signature]

Remarks: WD # 71722130 ATWT 46,040



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720667

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/08/2021 Vehicle# 483381 Volume
Payment Type Credit Account Container 483381
Manual Ticket# 1031254 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105080 lb*
In 10/07/2021 06:44:18	MANUAL WT	jaday		Tare	54840 lb*
Out 10/08/2021 06:44:18		jaday		Net	50240 lb
Comments				* Manual Weight	Tons 25.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.12	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.12	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis # 444-701294
Driver Name: BLAKE BARNETT Driver Signature: [Signature]

Remarks: HWL 07221793B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Concree Name and Loading Address
SCD NE 8TH

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Site:
4000 Pacific Street, Industrial Facility - 18000 Tons
4000 Pacific Street
Seattle, Washington 98105
Phone: (206) 360-0100 or (206) 360-0101

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Check ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **AA2 1707270**

Driver Name: **Brandon Osborne** Driver Signature: **Brandon Osborne**

Remarks:
Can # 483381



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720668

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/08/2021 Vehicle# 483412 Volume
Payment Type Credit Account Container 483412
Manual Ticket# 1031257 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107260 lb*
In 10/07/2021 06:45:39	MANUAL WT	jaday		Tare	56660 lb*
Out 10/08/2021 06:45:39		jaday		Net	50600 lb
Comments					25.30
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.30	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.30	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **11-6-2021**
Time scheduled for pickup **10:00 AM**

Concree Name and Loading Address
SCD NE 8TH

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Ashes
 Other: **LF01**

Acknowledgment of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Site:
4000 Pacific Street, Industrial Facility - 18000 Tons
4000 Pacific Street
Seattle, Washington 98105
Phone: (206) 360-0100 or (206) 360-0101

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good service condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Check ONE: DROP ONLY PICK UP ONLY SWP WTL

Loading:
Start Time _____ Box # In **WML 483412** Lines 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **445 WML 707381**

Driver Name: **JASON MICHAELS** Driver Signature: **Jason Michaels**

Remarks:
Driver Lic WDL 3213 BJ 43 B
09/23/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720669

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/08/2021 Vehicle# 483510 Volume
Payment Type Credit Account Container 483510
Manual Ticket# 1031258 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105480 lb*
In 10/07/2021 06:47:01	MANUAL WT	jaday		Tare	54260 lb*
Out 10/08/2021 06:47:01		jaday		Net	51220 lb
Comments					25.61
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.61	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.61	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720671

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/11/2021 Vehicle# 480593 Volume
Payment Type Credit Account Container 480593
Manual Ticket# 1031253 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105700 lb*
In 10/07/2021 06:48:18	MANUAL WT	jaday		Tare	54400 lb*
Out 10/11/2021 06:48:18		jaday		Net	51300 lb
Comments				* Manual Weight	Tons 25.65

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.65	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.65	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading _____
Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: CTI Truck/Class # 443-743267-483510

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks:
49560
WDL 7K79G 013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720673

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 10/11/2021 Vehicle# 484078 Volume
Payment Type Credit Account Container 484078
Manual Ticket# 1031253 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106500 lb*
In 10/07/2021 06:49:46	MANUAL WT	jaday		Tare	55620 lb*
Out 10/11/2021 06:49:46		jaday		Net	50880 lb
Comments				* Manual Weight	Tons 25.44

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.44	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.44	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading _____
Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ End Time _____

Transporter Name: CTI Truck/Class # 443-743267-480593

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks:
49380
WDL 7K79G 013B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8th

Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site:
Location: _____
Access: _____
Hazardous Materials: _____
Phone: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck Class # 442/207270
Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks:
can # [redacted]
434078



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720674

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483085 Volume
Payment Type Credit Account Container 483085
Manual Ticket# 1031368 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106400 lb*
In 10/08/2021 06:51:25	MANUAL WT	jaday		Tare	56100 lb*
Out 10/11/2021 06:51:25		jaday		Net	50300 lb
Comments					Tons
* Manual Weight					25.15

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.15	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.15	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address: SCD NE 8th

Waste Profile # 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site:
Location: _____
Access: _____
Hazardous Materials: _____
Phone: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck Class # 441/207205/483085
Driver Name: Arthur Egge Driver Signature: Arthur Egge

Remarks:
50,620 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720980

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 10/11/2021 Vehicle# 405017 Volume
Payment Type Credit Account Container 405017
Manual Ticket# 1031368 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	100140 lb*
In 10/08/2021 07:14:05	MANUAL WT	jaday		Tare	55360 lb*
Out 10/11/2021 07:14:05		jaday		Net	44780 lb
Comments					Tons
* Manual Weight					22.39

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.39	Tons				WA-BELLEVU
2 EVF-P6-Environment 100							WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		22.39	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720983

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/11/2021 Vehicle# 480509 Volume
Payment Type Credit Account Container 480509
Manual Ticket# 1031366 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107620 lb*
In 10/08/2021 07:17:29	MANUAL WT	jaday		Tare	56260 lb*
Out 10/11/2021 07:17:29		jaday		Net	51360 lb
Comments					25.68
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.68	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.68	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 10-10-21
Time scheduled for pickup: 9:30

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTS Truck/Chassis #: 440-701287-405017
Driver Name: SCD NE 8TH 46400 Driver Signature: [Signature]

Remarks:
W.D.L # 7111222138
46400



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720985

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/11/2021 Vehicle# 480529 Volume
Payment Type Credit Account Container 480529
Manual Ticket# 1031366 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104100 lb*
In 10/08/2021 07:19:01	MANUAL WT	jaday		Tare	55120 lb*
Out 10/11/2021 07:19:01		jaday		Net	48980 lb
Comments					24.49
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.49	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.49	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 443-743267 ~~443-743267~~
Driver Name: LEFF THOMAS Driver Signature: [Signature] 480509

Remarks:
FRONT LADDER (BROKEN)
48540
WDL 7R79G 413B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720986

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483310 Volume
Payment Type Credit Account Container 483310
Manual Ticket# 1031369 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107020 lb*
In 10/08/2021 07:20:35	MANUAL WT	jaday		Tare	56140 lb*
Out 10/11/2021 07:20:35		jaday		Net	50880 lb
Comments				* Manual Weight	Tons
					25.44

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		25.44		Tons	WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100		25.44	Tons			WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Consignee Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific Beach, Seaside, OR 97138
4500 Pacific Beach, Seaside, OR 97138
Seaside, Washington 97138
Phone: (503) 738-1111 or (503) 738-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition No
 Container in good condition No
 No free standing water No
 Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **440-707287-483310**

Driver Name: **Scott F Hagan** Driver Signature: _____

Remarks:
49,160 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720987

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483672 Volume
Payment Type Credit Account Container 483672
Manual Ticket# 1031370 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104180 lb*
In 10/08/2021 07:21:50	MANUAL WT	jaday		Tare	55460 lb*
Out 10/11/2021 07:21:50		jaday		Net	48720 lb
Comments				* Manual Weight	Tons
					24.36

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100		24.36		Tons	WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100		24.36	Tons			WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **10-6-21**
Time scheduled for pickup **3:00**

Consignee Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific Beach, Seaside, OR 97138
4500 Pacific Beach, Seaside, OR 97138
Seaside, Washington 97138
Phone: (503) 738-1111 or (503) 738-1112

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition No
 Container in good condition No
 No free standing water No
 Container is empty and clean No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **440-707287-483310**

Driver Name: **Scott F Hagan** Driver Signature: _____

Remarks:
#
WDL 7772213B 50.020



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720988

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483934 Volume
Payment Type Credit Account Container 483934
Manual Ticket# 1031371 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104220 lb*
In 10/08/2021 07:23:16	MANUAL WT	jaday		Tare	54540 lb*
Out 10/11/2021 07:23:16		jaday		Net	49680 lb
Comments				* Manual Weight	Tons 24.84

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.84	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.84	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-7B7WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: _____ Truck/Chassis # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 48 36 72



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720988

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483986 Volume
Payment Type Credit Account Container 483986
Manual Ticket# 1031372 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10660, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105500 lb*
In 10/08/2021 07:24:28	MANUAL WT	jaday		Tare	55140 lb*
Out 10/11/2021 07:24:28		jaday		Net	50360 lb
Comments				* Manual Weight	Tons 25.18

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.18	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.18	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading Date scheduled for pickup 10-6-2021
Time scheduled for pickup 3:00 PM

Generator Name and Loading Address: SCD NE 8TH Waste Profile: US-7B7WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFO1

Telephone Number: _____

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In WA X 61 Liners 0 1 2 Start Time _____
783934
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CT1 Truck/Chassis # 445 WA 707381

Driver Name: JASON MICHAELS Driver Signature: [Signature]

Remarks: Driver Lic
WDL 5213 BT 43 B
exp 7-31-2027

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 10/5/2021
Time scheduled for pickup: 4:00 PM

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Deposit Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition:
 Container in its good condition:
 No free standing water:
 Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: **783986** Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: **CTI** Truck/Trailer #: **445** **W707381**
Driver Name: **JASON MICHAELS** Driver Signature: _____
Remarks: **Driver Lic**
WDL 3213 BJ 43 B
09/23/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 720990

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 484
 Ticket Date: 10/11/2021 Vehicle#: 484021 Volume:
 Payment Type: Credit Account Container: 484021
 Manual Ticket#: 1031373 Billing #: 0002819
 Hauling Ticket#: _____ Manifest:
 Destination: UP/CUST PO: 3535035-200
 Profile: 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
 Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105680 lb*
In 10/08/2021 07:25:36	MANUAL WT	jaday		Tare	54920 lb*
Out 10/11/2021 07:25:36		jaday		Net	50760 lb
Comments: * Manual Weight				Tons	25.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		25.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.38	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person:
Telephone Number:

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Deposit Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition:
 Container in its good condition:
 No free standing water:
 Container is empty and clean:

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: **CTI** Truck/Trailer #: **444-707294**
Driver Name: **BRUCE BARKER II** Driver Signature: _____
Remarks: **WDL 27727A93B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721217

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
 Ticket Date: 10/12/2021 Vehicle#: 483613 Volume:
 Payment Type: Credit Account Container: 483613
 Manual Ticket#: 1029775 Billing #: 0002819
 Hauling Ticket#: _____ Manifest:
 Destination: UP/CUST PO: 3535035-200
 Profile: 115787WA (LFO1 - Contained-In PCE Contaminated Soil)
 Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103200 lb*
In 09/23/2021 09:19:24	MANUAL WT	jaday		Tare	54460 lb*
Out 10/12/2021 09:19:24		jaday		Net	48740 lb
Comments: Replacement BOL No J-1				Tons	24.37

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.37	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.37	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721218

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483374 Volume
Payment Type Credit Account Container# 483374
Manual Ticket# 1031255 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104240 lb*
In 10/07/2021 09:21:31	MANUAL WT	jaday		Tare	54080 lb*
Out 10/12/2021 09:21:31		jaday		Net	50160 lb
Comments					25.08
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.08	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-22-2021
Time scheduled for pickup 5:40

Generator Name and Loading Address: SCD NE 8TH
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name: City Transfer Inc Date: 9-22-2021
Signature: [Signature] Name: _____
Title: _____

Deliver to:
1800 Park South Industrial Parkway, Clatskanie
400 East Service Road
Salem, Oregon 97301
Phone: (503) 325-2100 or (503) 325-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483374 Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: City Transfer Inc Truck/Trailer # _____
Driver Name: [Signature] Driver Signature _____ Other Signature _____
Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721220

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483531 Volume
Payment Type Credit Account Container# 483531
Manual Ticket# 1031259 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	108220 lb*
In 10/07/2021 09:22:49	MANUAL WT	jaday		Tare	55680 lb*
Out 10/12/2021 09:22:49		jaday		Net	52540 lb
Comments					26.27
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		26.27	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3							WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 10-6-2021
Time scheduled for pickup 8:45 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____
Title: _____

Deliver to:
1800 Park South Industrial Parkway, Clatskanie
400 East Service Road
Salem, Oregon 97301
Phone: (503) 325-2100 or (503) 325-1100

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Container in good condition No Yes
No free standing water No Yes
Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483374 Lines 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 445 WA 767381
Driver Name: JOHN MICHAELS Driver Signature _____ Other Signature _____
Remarks:
Driver Lic
WDL 3213 BJ 43 B
09/7/31/2027

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 10-6
Time scheduled for pickup: 7:40

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
 Company Name: _____ Date: _____
 Signature: _____ Name: _____

Details of Site:
 422 South River Street
 Beaverton, Oregon 97005
 Phone: (503) 768-1000

Disposal Facility:
 Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane
 Arlington, Oregon 9712-6512
 Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in its good condition: Yes No
 No free standing water: Yes No
 Container is empty and closed: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time: _____ Box # In: _____ Litter: 1 2 Start Time: _____
 End Time: _____ Box # Out: _____ Litter: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 440-707287-483565
 Driver Name: SCOTT F MAGAN Driver Signature: _____

Remarks:
WDL 7TI 222138 49,760



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721221

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 10/12/2021 Vehicle# 483565 Volume
 Payment Type Credit Account Container 483565
 Manual Ticket# 1031260 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104240 lb*
In 10/07/2021 09:23:59	MANUAL WT	jaday		Tare	54400 lb*
Out 10/12/2021 09:23:59		jaday		Net	49840 lb
Comments					24.92
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.92	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.92	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type:
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading:
 Company Name: _____ Date: _____
 Signature: _____ Name: _____

Details of Site:
 422 South River Street
 Beaverton, Oregon 97005
 Phone: (503) 768-1000

Disposal Facility:
 Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane
 Arlington, Oregon 9712-6512
 Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container in its good condition: Yes No
 No free standing water: Yes No
 Container is empty and closed: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
 Start Time: _____ Box # In: _____ Litter: 1 2 Start Time: _____
 End Time: _____ Box # Out: _____ Litter: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 441-707205/483565-0
 Driver Name: APRIL EMMETT Driver Signature: _____

Remarks:
49,760lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721222

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 10/12/2021 Vehicle# 483811 Volume
 Payment Type Credit Account Container 483811
 Manual Ticket# 1031261 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107640 lb*
In 10/07/2021 09:25:11	MANUAL WT	jaday		Tare	55620 lb*
Out 10/12/2021 09:25:11		jaday		Net	52020 lb
Comments					26.01
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.01	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	26.01	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific South International Parkway - 48001 South
4500 South Business Street
Seattle, Washington 98148
Phone: (206) 765-1211 or 1-800-270-7262

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container is in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No
CONT# 483511

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Trailer # **444-707894**

Driver Name: **PAUL BAUMIT** Driver Signature: *[Signature]*

Remarks: **WDL 21221935**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721224

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 490
 Ticket Date 10/12/2021 Vehicle# 490019 Volume
 Payment Type Credit Account Container 490019
 Manual Ticket# 1031264 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106940 lb*
In 10/07/2021 09:26:20	MANUAL WT	jaday		Tare	52720 lb*
Out 10/12/2021 09:26:20		jaday		Net	54220 lb
Comments					Tons
					27.11

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		27.11	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	27.11	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFO1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to:
4500 Pacific South International Parkway - 48001 South
4500 South Business Street
Seattle, Washington 98148
Phone: (206) 765-1211 or 1-800-270-7262

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition: Yes No
 Container is in good condition: Yes No
 No free standing water: Yes No
 Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Trailer # **444-707205/490019**

Driver Name: **PAUL BAUMIT** Driver Signature: *[Signature]*

Remarks: **WDL 21221935**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721227

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
 Ticket Date 10/12/2021 Vehicle# 480503 Volume
 Payment Type Credit Account Container 480503
 Manual Ticket# 1031572 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	102220 lb*
In 10/11/2021 09:27:29	MANUAL WT	jaday		Tare	53440 lb*
Out 10/12/2021 09:27:29		jaday		Net	48780 lb
Comments					Tons
					24.39

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.39	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.39	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721230

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/12/2021 Vehicle# 480513 Volume
Payment Type Credit Account Container 480513
Manual Ticket# 1031573 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104080 lb*
In 10/11/2021 09:28:44	MANUAL WT	jaday		Tare	54200 lb*
Out 10/12/2021 09:28:44		jaday		Net	49880 lb
Comments				* Manual Weight	Tons 24.94

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	Tons	24.94			WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	Tons	24.94			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Arlington, Oregon 97812-6512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: _____ Unloading End Time: _____

Transporter Name: CTI Truck Class # 444 17072205 / 480583
Driver Name: Arthur Lopez Driver Signature: [Signature]

Remarks: 49,380 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721230

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 480
Ticket Date 10/12/2021 Vehicle# 480594 Volume
Payment Type Credit Account Container 480594
Manual Ticket# 1031574 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104700 lb*
In 10/11/2021 09:29:56	MANUAL WT	jaday		Tare	54900 lb*
Out 10/12/2021 09:29:56		jaday		Net	49800 lb
Comments				* Manual Weight	Tons 24.90

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		100	Tons	24.90			WA-BELLEVUE
2 EVF-P6-Environment		100	\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY		100	Tons	24.90			WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane 18177 Cedar Springs Lane
Arlington, Oregon 97812-6512 Arlington, Oregon 97812-6512
Phone: (541) 454-2030 Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Unloading Start Time: _____
End Time: _____ Box # Out: 480513 Unloading End Time: _____

Transporter Name: CTI Truck Class # 444-707294
Driver Name: BLAKE BARNETT Driver Signature: [Signature]

Remarks: WUL 2722-2936

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 10-5-21
Time scheduled for pickup: 5:30

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: LS-787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512)
Depot Facility: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512)

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: SWAP DROP ONLY PICK UP ONLY WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: STI Truck Class: 480-107837-48054H
Driver Name: F. Hagan Driver Signature: _____
Remarks: _____

WTL 7722218B LTV 48840



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721236

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 480
Ticket Date: 10/12/2021 Vehicle#: 480608 Volume:
Payment Type: Credit Account Container: 480608
Manual Ticket#: 1031575 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105240 lb*	
In 10/11/2021 09:30:59	MANUAL WT	jaday		Tare	54100 lb*	
Out 10/12/2021 09:30:59		jaday		Net	51140 lb	
Comments: * Manual Weight					Tons	25.57

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.57	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.57	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512)
Depot Facility: Columbia Ridge Landfill and Recycling Center (18177 Cedar Springs Lane, Arlington, Oregon 97812-6512)

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: _____ DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____

Transporter Name: STI Truck Class: 480-107837-480608
Driver Name: Arthur Eggen Driver Signature: _____
Remarks: 4-81780103



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721239

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 10/12/2021 Vehicle#: 483033 Volume:
Payment Type: Credit Account Container: 483033
Manual Ticket#: 1031575 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106920 lb*	
In 10/11/2021 09:32:07	MANUAL WT	jaday		Tare	55800 lb*	
Out 10/12/2021 09:32:07		jaday		Net	51120 lb	
Comments: * Manual Weight					Tons	25.56

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.56	Tons				WA-BELLEVU
2 EVF-P6-Environment 100			\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY 100		25.56	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721241

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483126 Volume
Payment Type Credit Account Container 483126
Manual Ticket# 1031577 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105760 lb*
In 10/11/2021 09:33:13	MANUAL WT	jaday		Tare	55400 lb*
Out 10/12/2021 09:33:13		jaday		Net	50360 lb
Comments				* Manual Weight	Tons 25.18

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		25.18	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		25.18	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading
Date scheduled for pickup 10-6-2021
Time scheduled for pickup 1:00 PM

Generator Name and Loading Address
SCD NE 8TH
Waste Profile # **115-787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In **483033** Liers 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis # **445 WMA 707381**

Driver Name **JASON MICHAELS** Driver Signature _____
Remarks:
Driver Lic
WDL 3213 BJ 43 B
exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721245

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483261 Volume
Payment Type Credit Account Container 483261
Manual Ticket# 1031578 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	112120 lb*
In 10/11/2021 09:34:20	MANUAL WT	jaday		Tare	64680 lb*
Out 10/12/2021 09:34:20		jaday		Net	47440 lb
Comments				* Manual Weight	Tons 23.72

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.72	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100				\$			WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.72	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading
Date scheduled for pickup 10-6-2021
Time scheduled for pickup 11:00 AM

Generator Name and Loading Address
SCD NE 8TH
Waste Profile # **115-787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Container Inspection Upon Pickup:
Tarp in good serviceable condition
Container in good condition
No free standing water
Container is empty and clean

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading
Start Time _____ Box # In **483126** Liers 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis # **445 WMA 707381**

Driver Name **JASON MICHAELS** Driver Signature _____
Remarks:
Driver Lic
WDL 3213 BJ 43 B
exp 7-31-2027

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-8512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Contact Person: _____
Telephone Number: _____

Waste Profile #: **L15787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFE1**

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver or Rec: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 9712-8512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:

Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis #: **443-743267 489221**

Driver Name: **Leaf Thomas** Driver Signature: _____

Remarks: **56100**

WDL 7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721247

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483309 Volume
Payment Type Credit Account Container 483309
Manual Ticket# 1031579 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	10590 lb*
In 10/11/2021 09:35:34	MANUAL WT	jaday		Tare	56080 lb*
Out 10/12/2021 09:35:34		jaday		Net	49820 lb
Comments					24.91
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.91	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.91	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 9712-8512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Contact Person: _____
Telephone Number: _____

Waste Profile #: **L15787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LFE1**

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver or Rec: _____
Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 9712-8512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:

Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis #: **443/30722/483309**

Driver Name: **James Phillips** Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721250

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483324 Volume
Payment Type Credit Account Container 483324
Manual Ticket# 1031580 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104580 lb*
In 10/11/2021 09:36:41	MANUAL WT	jaday		Tare	55340 lb*
Out 10/12/2021 09:36:41		jaday		Net	49240 lb
Comments					24.62
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.62	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.62	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 10-5-21
Time scheduled for pickup: 2:40

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: US787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LEF1

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI
Truck/Chassis #: 440-707297-783227

Driver Name: Scott F Hogan Driver Signature: _____

Remarks:
WDL # 7TT 22213B WT 50,180



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721253

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 10/12/2021 Vehicle#: 483427 Volume:
Payment Type: Credit Account Container: 483427
Manual Ticket#: 1031581 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103560 lb*	
In 10/11/2021 09:37:41	MANUAL WT	jaday		Tare	54200 lb*	
Out 10/12/2021 09:37:41		jaday		Net	49360 lb	
Comments: * Manual Weight					Tons	24.68

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.68	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.68	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: US787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LEF1

Acknowledgment of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97124-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI
Truck/Chassis #: 441 707223/483427-1

Driver Name: Arthur Eggen Driver Signature: _____

Remarks:
56,040 lbs



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721253

Customer Name: SCD NE 8TH LLC SCD NE 8TH LLC Carrier: 483
Ticket Date: 10/12/2021 Vehicle#: 483586 Volume:
Payment Type: Credit Account Container: 483586
Manual Ticket#: 1031582 Billing #: 0002819
Hauling Ticket#: _____ Manifest:
Destination: UP/CUST PO: 3535035-200
Profile: 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator: 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107360 lb*	
In 10/11/2021 09:38:47	MANUAL WT	jaday		Tare	54860 lb*	
Out 10/12/2021 09:38:47		jaday		Net	52500 lb	
Comments: * Manual Weight					Tons	26.25

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.25	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	26.25	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 10-5-21
Time scheduled for pickup: 10:30

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: _____ Litter # 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Litter # 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis #: **440-707387-483586**

Driver Name: **Scott P. Logan** Driver Signature: _____

Remarks: **711 22213B** **60,420**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721257

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483604 Volume
Payment Type Credit Account Container# 483604
Manual Ticket# 1031583 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105180 lb*
In 10/11/2021 09:39:51	MANUAL WT	jaday		Tare	55300 lb*
Out 10/12/2021 09:39:51		jaday		Net	49880 lb
Comments					24.94
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.94	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.94	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup: 10-5-20-21
Time scheduled for pickup: 1:00 PM

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115787WA**

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading:
Start Time: _____ Box # In: **W/MX14 483604** Litter # 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Litter # 1 2 End Time: _____

Transporter Name: **CTI** Truck/Chassis #: **445 + W/M 707381**

Driver Name: **Jason Michaels** Driver Signature: _____

Remarks: **Driver Lic**
WDL 3213 BT 43 B
Exp 7-31-2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721258

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483638 Volume
Payment Type Credit Account Container# 483638
Manual Ticket# 1031584 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104180 lb*
In 10/11/2021 09:40:54	MANUAL WT	jaday		Tare	55000 lb*
Out 10/12/2021 09:40:54		jaday		Net	49180 lb
Comments					24.59
* Manual Weight					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.59	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.59	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721259

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/11/2021 Vehicle# 483849 Volume
Payment Type Credit Account Container 483849
Manual Ticket# 1031585 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105520 lb*
In 10/11/2021 09:41:51	MANUAL WT	jaday		Tare	55780 lb*
Out 10/11/2021 09:41:51	MANUAL WT	jaday		Net	49740 lb
Comments				* Manual Weight	Tons 24.87

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.87	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.87	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFC1

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No
CONTAMINATED

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTE Truck/Chassis #: 444-707294
Driver Name: PAUCE BARNETT Driver Signature: [Signature]
Remarks: IND. P 77272193B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721260

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/12/2021 Vehicle# 483891 Volume
Payment Type Credit Account Container 483891
Manual Ticket# 1031586 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	104980 lb*
In 10/11/2021 09:43:14	MANUAL WT	jaday		Tare	56740 lb*
Out 10/12/2021 09:43:14		jaday		Net	48240 lb
Comments				* Manual Weight	Tons 24.12

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.12	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.12	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LFC1

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No
SWAP

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 443-743267-483849
Driver Name: JEFF THOMAS Driver Signature: [Signature]
Remarks: 49100
WIX 767PAU3B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFC1**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
 Container in good condition No Yes
 No free standing water No Yes
 Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL
CONT483891

Loading:
Start Time _____ Box # In _____ Licens 0 1 2 Start Time _____
End Time _____ Box # Out _____ Licens 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **444-707294**

Driver Name: **BLAKE BANETT** Driver Signature: *[Signature]*

Remarks: **WDL P72277938**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721261

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
 Ticket Date 10/12/2021 Vehicle# 483667 Volume
 Payment Type Credit Account Container 483667
 Manual Ticket# 1031652 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103260 lb*
In 10/11/2021 09:44:33	MANUAL WT	jaday		Tare	55080 lb*
Out 10/12/2021 09:44:33		jaday		Net	48180 lb
Comments					24.09
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		24.09	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	24.09	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Customer Name and Loading Address
SCD NE 8TH

Waste Profile # **115707WA**

Contact Person: _____
Telephone Number: _____

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LFC1**

Acknowledgement of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
 Container in good condition No Yes
 No free standing water No Yes
 Container is empty and clean No Yes

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Licens 0 1 2 Start Time _____
End Time _____ Box # Out _____ Licens 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Chassis # **442/207220/483667**

Driver Name: **JAMES PHILLIP** Driver Signature: *[Signature]*

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721262

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
 Ticket Date 10/12/2021 Vehicle# 405020 Volume
 Payment Type Credit Account Container 405020
 Manual Ticket# 1031758 Billing # 0002819
 Hauling Ticket# Manifest
 Destination UP/CUST PO 3535035-200
 Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
 Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98380 lb*
In 10/12/2021 09:45:40	MANUAL WT	jaday		Tare	53360 lb*
Out 10/12/2021 09:45:40		jaday		Net	45020 lb
Comments					22.51
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		22.51	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	22.51	Tons				WA-BELLEVU

Driver's Signature



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721263

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 10/12/2021 Vehicle# 484063 Volume
Payment Type Credit Account Container 484063
Manual Ticket# 1031587 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103640 lb*
In 10/11/2021 09:46:42	MANUAL WT	jaday		Tare	54780 lb*
Out 10/12/2021 09:46:42		jaday		Net	48860 lb
Comments				* Manual Weight	Tons 24.43

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.43	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.43	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Adhesion
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 442-787206-74367-405020

Driver Name: JEFF THOMAS Driver Signature: _____

Remarks: 45540

WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721418

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 10/13/2021 Vehicle# 483662 Volume
Payment Type Credit Account Container 483662
Manual Ticket# 1031110 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107620 lb*
In 10/06/2021 07:57:22	MANUAL WT	jaday		Tare	59440 lb*
Out 10/13/2021 07:57:22		jaday		Net	48180 lb
Comments				* Manual Weight	Tons 24.09

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.09	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.09	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Adhesion
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Top in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____
Start Time: _____ Box # In: _____ Liners 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis #: 442/207270

Driver Name: Brandon Osborne Driver Signature: _____

Remarks: Can # 48 46 63



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 721420

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 484
Ticket Date 10/13/2021 Vehicle# 484046 Volume
Payment Type Credit Account Container 484046
Manual Ticket# 1031262 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	105820 lb*
10/07/2021	07:59:06	MANUAL WT	jaday		Tare	55140 lb*
10/13/2021	07:59:06		jaday		Net	50680 lb
Comments						25.34
						Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		25.34	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3		25.34	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 10-5-21
Time scheduled for pickup 8:30

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Love Pacific Truck Transfer Facility (4800) 1800
4200 Shaver Lane
North, Washington 9713
Phone: (509) 251-1111 or 1-800-235-7424

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Customer to empty and close: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 440-78287-433662
Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks:
WDL 71122213D
LT 125-48,560



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725025

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/01/2021 Vehicle# 405020 Volume
Payment Type Credit Account Container 405020
Manual Ticket# 1033159 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross	98040 lb*
10/28/2021	11:25:16	Front Scale	jaday		Tare	53440 lb*
11/01/2021	11:25:16	Front Scale	jaday		Net	44600 lb
Comments						22.30
						Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1		22.30	Tons				WA-BELLEVUE
2							WA-BELLEVUE
3		22.30	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 1 Love Pacific Truck Transfer Facility (4800) 1800
4200 Shaver Lane
North, Washington 9713
Phone: (509) 251-1111 or 1-800-235-7424

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Customer to empty and close: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Litters 0 1 2 Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: CTI Truck/Chassis #: 443-743267-484046
Driver Name: Jeff Thomas Driver Signature: [Signature]

Remarks:
49840
WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725026

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/01/2021 Vehicle# 405009 Volume
Payment Type Credit Account Container# 405009
Manual Ticket# 1033321 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	95120 lb*
In 10/29/2021 11:27:26	Front Scale	jaday		Tare	51660 lb*
Out 11/01/2021 11:27:26	Front Scale	jaday		Net	43460 lb
Comments					21.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		21.73	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	21.73	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: 10-27-21
Time scheduled for pickup: 1:50

Consignee Name and Loading Address: SCD NE 8TH
Waste Profile #: 45787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners: 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 440-701287-465020
Driver Name: Scott F. Hogan Driver Signature: [Signature]

Remarks: 77A2213B LS WT 46,860



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725027

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/01/2021 Vehicle# 405017 Volume
Payment Type Credit Account Container# 405017
Manual Ticket# 1033323 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	93700 lb*
In 10/29/2021 11:28:58	Front Scale	jaday		Tare	51680 lb*
Out 11/01/2021 11:28:58	Front Scale	jaday		Net	42020 lb
Comments					21.01

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		21.01	Tons				WA-BELLEVU
2 EVF-P6-Environment	100		\$				WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	21.01	Tons				WA-BELLEVU

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup: _____
Time scheduled for pickup: _____

Consignee Name and Loading Address: SCD NE 8TH
Waste Profile #: 115787WA

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Liners: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Liners: 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 442/7079270
Driver Name: Brandon Osborne Driver Signature: [Signature]

Remarks: can # 405009



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725028

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/01/2021 Vehicle# 405004 Volume
Payment Type Credit Account Container 405004
Manual Ticket# 1033320 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	97080 lb*
In 10/29/2021 11:30:28	Front Scale	jaday		Tare	55080 lb*
Out 11/01/2021 11:30:28	Front Scale	jaday		Net	42000 lb
Comments					21.00

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	21.00	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	21.00	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 10-28-21
Time scheduled for pickup 10:45

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # US-78746

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
From Park Waste Transfer Facility (LF01) to: 405 Back Bay Area
South, Washington 97812
Phone (541) 454-2030 or (541) 234-7444

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 440-707387-405017

Driver Name Scott F Hyman Driver Signature Scott F Hyman

Remarks:
100 TIL222138
620
47 67 45,780



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725030

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8612 Volume
Payment Type Credit Account Container 8612
Manual Ticket# 1033447 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	71240 lb*
In 10/30/2021 11:38:02	Front Scale	jaday		Tare	47080 lb*
Out 11/01/2021 11:38:02	Front Scale	jaday		Net	24160 lb
Comments					12.08

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	12.08	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100						WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	12.08	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup 10-28-21
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # US-78746

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person:
Telephone Number:

Acknowledgement of Loading:
Company Name _____ Date _____
Signature _____ Name _____

Details of Job:
From Park Waste Transfer Facility (LF01) to: 405 Back Bay Area
South, Washington 97812
Phone (541) 454-2030 or (541) 234-7444

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 405004 Lanes 0 1 2 Start Time _____ Unloading
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name CTI Truck/Chassis # 445-707381

Driver Name Jason MICHAELS Driver Signature Jason Michaels

Remarks:
Driver Lic
WDL 3213 BJ 43 B
09 7 31 2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725031

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8568 Volume
Payment Type Credit Account Container 8568
Manual Ticket# 1033446 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	73360 lb*
In 10/30/2021 11:40:17	Front Scale	jaday		Tare	46980 lb*
Out 11/01/2021 11:40:17	Front Scale	jaday		Net	26380 lb
Comments					13.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		13.19	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	13.19	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **US-78746**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name _____ Date: **10-29-21**
Signature: _____ Name: _____

Details of Site:
1500 South, South Mountain Facility (SR03) Tech
1500 South Mountain
North Mountain 97812
Phone (541) 454-2030 or (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: **DROP ONLY** PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **08612** Lanes 0 1 2 Start Time _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: _____ Track/Chassis # **444 707294**

Driver Name **Michael FROES** Other Signature: **WJF Fields**

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725032

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8648 Volume
Payment Type Credit Account Container 8648
Manual Ticket# 1033446 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	71680 lb*
In 10/30/2021 11:42:16	Front Scale	jaday		Tare	48060 lb*
Out 11/01/2021 11:42:16	Front Scale	jaday		Net	23620 lb
Comments					11.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		11.81	Tons				WA-BELLEVU
2 EVF-P6-Environment	100						WA-BELLEVU
3 RAIL T SPW-RAIL BY	100	11.81	Tons				WA-BELLEVU

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **10-27-2021**
Time scheduled for pickup **11:40 AM**

Generate Name and Loading Address
SCD NE 8TH

Waste Profile # **US-78746**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name _____ Date: _____
Signature: _____ Name: _____

Details of Site:
1500 South, South Mountain Facility (SR03) Tech
1500 South Mountain
North Mountain 97812
Phone (541) 454-2030 or (541) 454-2030

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: **DROP ONLY** PICK UP ONLY WTL

Loading:
Start Time _____ Box # In **WMA X 6 8568** Lanes 0 1 2 Start Time _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: **CTI** Track/Chassis # **445 WMA 707381**

Driver Name **JASON MICHAELS** Other Signature: _____

Remarks:
Driver Lic
WDL 8213 BJ 43 B
op 731 2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725033

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8853 Volume
Payment Type Credit Account Container# 8853
Manual Ticket# 1033454 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	71000 lb*
In 10/30/2021 11:44:53	Front Scale	jaday		Tare	48560 lb*
Out 11/01/2021 11:44:53	Front Scale	jaday		Net	22440 lb
Comments					11.22
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	11.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	11.22	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Ramp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No floor standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:

Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 442 / 707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 008648



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725034

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8673 Volume
Payment Type Credit Account Container# 8673
Manual Ticket# 1033449 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	71400 lb*
In 10/30/2021 11:49:23	Front Scale	jaday		Tare	47600 lb*
Out 11/01/2021 11:49:23	Front Scale	jaday		Net	23800 lb
Comments					11.90
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	11.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	11.90	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Ramp in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in good condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
No floor standing water	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container empty and clean	Yes <input type="checkbox"/>	No <input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:

Start Time: _____ Box # In: _____ Lanes: 0 1 2 Start Time: _____ Unloading
End Time: _____ Box # Out: _____ Lanes: 0 1 2 End Time: _____

Transporter Name: CTI Track/Chassis #: 442 / 707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: Can # 008353



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725035

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8805 Volume
Payment Type Credit Account Container 8805
Manual Ticket# 1033451 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	69060 lb*
In 10/30/2021 11:51:47	Front Scale	jaday		Tare	48760 lb*
Out 11/01/2021 11:51:47	Front Scale	jaday		Net	20300 lb
Comments				* Manual Weight	Tons 10.15

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		10.15	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		10.15	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 443-743267-8673
Driver Name: Jeff Thomas Driver Signature: _____

Remarks: _____
WOL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725038

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8807 Volume
Payment Type Credit Account Container 8807
Manual Ticket# 1033452 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103680 lb*
In 10/30/2021 12:03:28	Front Scale	jaday		Tare	49300 lb*
Out 11/01/2021 12:03:28	Front Scale	jaday		Net	54380 lb
Comments				* Manual Weight	Tons 27.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		27.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		27.19	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
Telephone Number: _____ Asbestos
 Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: _____ Unloading: _____
Start Time: _____ Box # In: _____ Lines: 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines: 0 1 2 End Time: _____

Transporter Name: CTI Truck/Chassis # 443-743267-8673
Driver Name: Arthur Eggen Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725264

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/01/2021 Vehicle# 405016 Volume
Payment Type Credit Account Container# 405016
Manual Ticket# 1033322 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	95500 lb*
In 10/29/2021 11:27:59	Front Scale	jaday		Tare	52740 lb*
Out 11/01/2021 11:27:59		jaday		Net	42760 lb
Comments				* Manual Weight	Tons 21.38

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		21.38	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		21.38	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis #: **443-743267-8807**
Driver Name: **Jeff Thomas** Driver Signature: _____
Remarks: **NDL 7R 79G 03B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725292

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/02/2021 Vehicle# 405015 Volume
Payment Type Credit Account Container# 405015
Manual Ticket# 1033545 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103020 lb*
In 11/01/2021 13:10:45	Front Scale	jaday		Tare	55080 lb*
Out 11/02/2021 13:10:45		jaday		Net	47940 lb
Comments				* Manual Weight	Tons 23.97

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		23.97	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		23.97	Tons				WA-BELLEVUE

Driver's Signature

WM Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____
Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Liers 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liers 0 1 2 End Time _____
Transporter Name: **CTI** Truck/Chassis #: **443-743267-8807**
Driver Name: **Henry Engel** Driver Signature: _____
Remarks: **Empty Wt 46,660 lbs**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725293

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 400
Ticket Date 11/02/2021 Vehicle# 400501 Volume
Payment Type Credit Account Container 400501
Manual Ticket# 1033536 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103480 lb*
In 11/01/2021 13:16:32	Front Scale	jaday		Tare	59860 lb*
Out 11/02/2021 13:16:32		jaday		Net	43620 lb
Comments				* Manual Weight	Tons 21.81

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		21.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		21.81	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL CONT405015

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 444-701244

Driver Name: BRUCE BARNETT Driver Signature: Mr. B

Remarks: WV 776625966



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725294

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/02/2021 Vehicle# 405012 Volume
Payment Type Credit Account Container 405012
Manual Ticket# 1033542 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	111040 lb*
In 11/01/2021 13:18:02	Front Scale	jaday		Tare	56140 lb*
Out 11/02/2021 13:18:02		jaday		Net	54900 lb
Comments				* Manual Weight	Tons 27.45

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		27.45	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		27.45	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Acknowledgement of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:

Tarp in good serviceable condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container in good condition	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
No free standing water	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No
Container is empty and clean	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL SWAP

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Truck/Trailer # 442/707270

Driver Name: Brandon Osborne Driver Signature: Brandon Osborne

Remarks: can # 400501



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725295

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/02/2021 Vehicle# 8808 Volume
Payment Type Credit Account Container# 8808
Manual Ticket# 1033453 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	73960 lb*
In 10/30/2021 13:34:34	Front Scale	jaday		Tare	48380 lb*
Out 11/02/2021 13:34:34		jaday		Net	25580 lb
Comments					12.79
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		12.79	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	12.79	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US-727WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Company Name: **CTC** Date: **10-29-21**
Signature: **Michael Sporel** Name: **Michael Sporel**

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Containment in good condition No Yes
No free standing water No Yes
Container in proper and close No Yes **Cont 405012**

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 _____ End Time _____
Transporter Name: **CTC** Truck/Chassis #: **444-707994**
Driver Name: **HALE BARNETT** Driver Signature: **HALE BARNETT**
Remarks: **WMP 2722, 1930**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725295

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/02/2021 Vehicle# 405011 Volume
Payment Type Credit Account Container# 405011
Manual Ticket# 1033456 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	106480 lb*
In 10/30/2021 13:39:59	Front Scale	jaday		Tare	52680 lb*
Out 11/02/2021 13:39:59		jaday		Net	53800 lb
Comments					26.90
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		26.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	26.90	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **US-727WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Company Name: **CTC** Date: **10-29-21**
Signature: **Michael Sporel** Name: **Michael Sporel**

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition No Yes
Containment in good condition No Yes
No free standing water No Yes
Container in proper and close No Yes **Cont 405012**

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 _____ End Time _____
Transporter Name: **CTC** Truck/Chassis #: **444-707994**
Driver Name: **HALE BARNETT** Driver Signature: **HALE BARNETT**
Remarks: **WMP 2722, 1930**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725297

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/02/2021 Vehicle# 405006 Volume
Payment Type Credit Account Container 405006
Manual Ticket# 1033539 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	105220 lb*
In 11/01/2021 13:41:36	Front Scale	jaday		Tare	52320 lb*
Out 11/02/2021 13:41:36		jaday		Net	52900 lb
Comments					26.45
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		26.45	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		26.45	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 10-29-2021
Time scheduled for pickup 8:00 AM

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: UIS 787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: 405011 Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 445 WMA 707381

Driver Name: JOHN MICHAELS Driver Signature: _____
Remarks:
Driver Lic
WDL 3213 BJ 43 B
09/29/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725298

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/02/2021 Vehicle# 405013 Volume
Payment Type Credit Account Container 405013
Manual Ticket# 1033543 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	107640 lb*
In 11/01/2021 13:42:50	Front Scale	jaday		Tare	52980 lb*
Out 11/02/2021 13:42:50		jaday		Net	54660 lb
Comments					27.33
					* Manual Weight

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		27.33	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		27.33	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: UIS 787WA
Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time: _____ Box # In: _____ Lines 0 1 2 Start Time: _____
End Time: _____ Box # Out: _____ Lines 0 1 2 End Time: _____
Transporter Name: CTI Truck/Chassis #: 403-743267-405005

Driver Name: JEFF THOMAS Driver Signature: _____
Remarks:
46040
WDL 78794013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725495

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8549 Volume
Payment Type Credit Account Container# 8549
Manual Ticket# 1033445 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	75240 lb*
In 10/30/2021 09:35:31	MANUAL WT	cwalsh3		Tare	48420 lb*
Out 11/03/2021 09:35:31		cwalsh3		Net	26820 lb
Comments					13.41
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		13.41	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							
3 RAIL T SPW-RAIL BY 100		13.41	Tons				

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US787WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LEF1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:

Tary in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in its good condition	<input type="checkbox"/>	<input type="checkbox"/>
No fire standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Track/Chassis # **443-743267-405113**

Driver Name: **Jeff Thomas** Driver Signature: _____

Remarks: **WDL 7R79G013B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725496

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8773 Volume
Payment Type Credit Account Container# 8773
Manual Ticket# 1033450 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	68200 lb*
In 10/30/2021 09:37:10	MANUAL WT	cwalsh3		Tare	48780 lb*
Out 11/03/2021 09:37:10		cwalsh3		Net	19420 lb
Comments					9.71
* Manual Weight					

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		9.71	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		9.71	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **10-29-21**
Time scheduled for pickup **12:15**

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile: **US787WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LEF1**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-0512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:

Tary in good serviceable condition	Yes <input type="checkbox"/>	No <input type="checkbox"/>
Container in its good condition	<input type="checkbox"/>	<input type="checkbox"/>
No fire standing water	<input type="checkbox"/>	<input type="checkbox"/>
Container is empty and clean	<input type="checkbox"/>	<input type="checkbox"/>

Check ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: **CTI** Track/Chassis # **440-707287-8549**

Driver Name: **SC611 HIGGINS** Driver Signature: _____

Remarks: **WDL 02TT22213B**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725497

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8510 Volume
Payment Type Credit Account Container# 8510
Manual Ticket# 1033527 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	70000 lb*
In 11/01/2021 09:38:55	MANUAL WT	cwalsh3		Tare	47520 lb*
Out 11/03/2021 09:38:55		cwalsh3		Net	22480 lb
Comments				* Manual Weight	Tons 11.24

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		11.24	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		11.24	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 10-29-21
Time scheduled for pickup 12:15

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____ Signature: _____ Name: _____

Deliver to: 4500 Pacific South International Facility (SR03) Truck 4500 South Business Center Banks, Washington 97106 Phone: (509) 746-1101 or (509) 241-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition Yes No No No No No No No No No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: GFI Truck/Chassis # 44D-707287-8713

Driver Name: Scott F. Hagan Driver Signature: Scott F. Hagan

Remarks: WDL # 7122213B GR LT



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725498

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8686 Volume
Payment Type Credit Account Container# 8686
Manual Ticket# 1033528 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	75480 lb*
In 11/01/2021 09:40:16	MANUAL WT	cwalsh3		Tare	47040 lb*
Out 11/03/2021 09:40:16		cwalsh3		Net	28440 lb
Comments				* Manual Weight	Tons 14.22

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		14.22	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		14.22	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgement of Loading: Company Name: _____ Date: _____ Signature: _____ Name: _____

Deliver to: 4500 Pacific South International Facility (SR03) Truck 4500 South Business Center Banks, Washington 97106 Phone: (509) 746-1101 or (509) 241-7400

Disposal Facility: Columbia Ridge Landfill and Recycling Center 18177 Cedar Springs Lane Arlington, Oregon 97812-6512 Phone: (541) 454-2030

Container Inspection Upon Pickup: Tarp in good serviceable condition Yes No No No No No No No No No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Lines 0 1 2 Start Time _____ End Time _____ Box # Out _____ Lines 0 1 2 End Time _____

Transporter Name: GFI Truck/Chassis # 44D 707203/8510

Driver Name: Matthew Feagin Driver Signature: Matthew Feagin

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725499

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8702 Volume
Payment Type Credit Account Container# 8702
Manual Ticket# 1033529 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	73000 lb*
In 11/01/2021 09:42:02	MANUAL WT	cwalsh3		Tare	46080 lb*
Out 11/03/2021 09:42:02		cwalsh3		Net	26920 lb
Comments				* Manual Weight	Tons 13.46

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	13.46	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	13.46	Tons				WA-BELLEVUE

Driver's Signature

WM WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup: 10-29-21
Time scheduled for pickup: 7:20

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115-787WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:

Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in proper and clean: Yes No

Ways ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Boxes In _____ Liners 0 1 2 Start Time _____
End Time _____ Boxes Out _____ Liners 0 1 2 End Time _____

Transporter Name: **RTI** Truck/Chassis #: **440-767287-8086**

Driver Name: **Scott F. Hagan** Driver Signature: _____

Remarks: **WDL # 7IT22213B Cr. 76380 LTR 48380 14T**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725500

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8711 Volume
Payment Type Credit Account Container# 8711
Manual Ticket# 1033530 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	72780 lb*
In 11/01/2021 09:43:31	MANUAL WT	cwalsh3		Tare	51680 lb*
Out 11/03/2021 09:43:31		cwalsh3		Net	21100 lb
Comments				* Manual Weight	Tons 10.55

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	10.55	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	10.55	Tons				WA-BELLEVUE

Driver's Signature

WM WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup: 10-29-21
Time scheduled for pickup: 9:45

Generator Name and Loading Address: **SCD NE 8TH**

Waste Profile #: **115-787WA**

Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Company Name: _____ Date: _____
Signature: _____ Name: _____

Driver Name: _____ Date: _____
Signature: _____ Name: _____

Container Inspection Upon Pickup:

Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container in proper and clean: Yes No

Ways ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Boxes In _____ Liners 0 1 2 Start Time _____
End Time _____ Boxes Out _____ Liners 0 1 2 End Time _____

Transporter Name: **RTI** Truck/Chassis #: **440-767287-8702**

Driver Name: **Scott F. Hagan** Driver Signature: _____

Remarks: **WDL # 7IT22213B Cr. 76220 LTR 49880**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725501

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8727 Volume
Payment Type Credit Account Container# 8727
Manual Ticket# 1033531 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross
11/01/2021	09:45:05	MANUAL WT	cwalsh3		70340 lb*
11/03/2021	09:45:05		cwalsh3		47560 lb*
			* Manual Weight		22780 lb
					Net Tons 11.39

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		11.39	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	11.39	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 11577 Cedar Springs Lane, Arlington, Oregon 97812
Dispose Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time: _____ Box # In: _____ Lanes 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CCI** Track/Chassis #: **443-793267-8673**
Driver Name: **JEFF THOMAS** Dir. or Signature: *[Signature]* **8711 full**

Remarks: **49240**
WDL7R79G013B



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725502

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8746 Volume
Payment Type Credit Account Container# 8746
Manual Ticket# 1033532 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

In	Time	Scale	Operator	Inbound	Gross
11/01/2021	09:46:07	MANUAL WT	cwalsh3		71800 lb*
11/03/2021	09:46:07		cwalsh3		46780 lb*
			* Manual Weight		25020 lb
					Net Tons 12.51

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T		12.51	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	12.51	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH**
Waste Profile #: **115787WA**
Waste Type: CDL Contaminated Soil Asbestos Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgement of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: 11577 Cedar Springs Lane, Arlington, Oregon 97812
Dispose Facility: Columbia Ridge Landfill and Recycling Center, 18177 Cedar Springs Lane, Arlington, Oregon 97812

Container Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading: Start Time: _____ Box # In: _____ Lanes 0 1 2 Unloading Start Time: _____
End Time: _____ Box # Out: _____ Lanes 0 1 2 End Time: _____

Transporter Name: **CCI** Track/Chassis #: **441/707205/6087073**
Driver Name: **Jeffrey Egan** Dir. or Signature: *[Signature]*

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725504

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8787 Volume
Payment Type Credit Account Container# 8787
Manual Ticket# 1033533 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	9960 lb*
In 11/01/2021 09:47:21	MANUAL WT	cwalsh3		Tare	47820 lb*
Out 11/03/2021 09:47:21		cwalsh3		Net	31800 lb
Comments				* Manual Weight	Tons 15.90

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		15.90	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		15.90	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person _____
Telephone Number _____

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
4500 Pacific South International Parkway (SR207) South
4500 South International Parkway, Suite 100
North, Vancouver, WA 98684
Phone: (360) 535-1200 or (360) 535-1201

Dispose of Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Track/Class # **442/707270**
Driver Name: **Brandon Osborne** Driver Signature: **Brandon Osborne**

Remarks:
Can # ~~1009746~~ / 1009746



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725504

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8794 Volume
Payment Type Credit Account Container# 8794
Manual Ticket# 1033534 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	73140 lb*
In 11/01/2021 09:48:28	MANUAL WT	cwalsh3		Tare	47460 lb*
Out 11/03/2021 09:48:28		cwalsh3		Net	25690 lb
Comments				* Manual Weight	Tons 12.84

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		12.84	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		12.84	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person _____
Telephone Number _____

Acknowledgment of Loading
Company Name _____ Date _____
Signature _____ Name _____

Deliver to:
4500 Pacific South International Parkway (SR207) South
4500 South International Parkway, Suite 100
North, Vancouver, WA 98684
Phone: (360) 535-1200 or (360) 535-1201

Dispose of Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No free standing water Yes No
 Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY **SWAP** WTL

Loading
Start Time _____ Box # In _____ Litters 0 1 2 Unloading Start Time _____
End Time _____ Box # Out _____ Litters 0 1 2 End Time _____

Transporter Name: **CTI** Track/Class # **442/707270/10087870**
Driver Name: **William Lopez** Driver Signature: **William Lopez**

Remarks:
8500 20000
437200100



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725505

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/03/2021 Vehicle# 8846 Volume
Payment Type Credit Account Container 8846
Manual Ticket# 1033535 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 11/01/2021 09:49:32	MANUAL WT	cwalsh3		69380 lb*
Out 11/03/2021 09:49:32		cwalsh3		47480 lb*
Comments				Net 21900 lb
* Manual Weight				Tons 10.95

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	10.95	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	10.95	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Track/Chassis # 4411702205/0087946
Driver Name: Harvey Equi Driver Signature: _____

Remarks: _____



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725506

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405003 Volume
Payment Type Credit Account Container 405003
Manual Ticket# 1033537 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross
In 11/01/2021 09:51:07	MANUAL WT	cwalsh3		105480 lb*
Out 11/03/2021 09:51:07		cwalsh3		51100 lb*
Comments				Net 54380 lb
* Manual Weight				Tons 27.19

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	27.19	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	27.19	Tons				WA-BELLEVUE

Driver's Signature

WM
Waste Management

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 10.29.21
Time scheduled for pickup 9.45

Generator Name and Loading Address: SCD NE 8TH Waste Profile # 115787WA

Contact Person: _____ Telephone Number: _____

Waste Type: CDL Contaminated Soil Asbestos Other: LF01

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Deliver to: _____ Disposal Facility: _____

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: CTI Track/Chassis # 440-767237-3346
Driver Name: Scott F Hayne Driver Signature: _____

Remarks: _____

ki DL # 11222135 Cr. 96,920
Gr. 47,980



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725507

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405007 Volume
Payment Type Credit Account Container 405007
Manual Ticket# 1033540 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	103040 lb*
In 11/01/2021 09:52:09	MANUAL WT	cwalsh3		Tare	51580 lb*
Out 11/03/2021 09:52:09		cwalsh3		Net	51460 lb
Comments				* Manual Weight	Tons 25.73

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	25.73	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	25.73	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Waste Profile #: 115787WA

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Use:
From Public Access Restricted Facility (LAR01) Item
Address: _____
County: _____
Phone: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Trailer # 405003

Loading:
Start Time _____ Box # In _____ Lines 0 1 2 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 2 _____ End Time _____

Transporter Name: CTI Truck/Class # 444-107294

Driver Name: Paul Bennett Driver Signature: [Signature]

Remarks: WDL 2712241933



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725509

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405008 Volume
Payment Type Credit Account Container 405008
Manual Ticket# 1033541 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101820 lb*
In 11/01/2021 09:53:38	MANUAL WT	cwalsh3		Tare	53360 lb*
Out 11/03/2021 09:53:38		cwalsh3		Net	48460 lb
Comments				* Manual Weight	Tons 24.23

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	24.23	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	24.23	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill of Lading

Date scheduled for pickup 11 26 2021
Time scheduled for pickup 12 45 PM

Generator Name and Loading Address: SCD NE 8TH

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Waste Profile #: 115787WA

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Use:
From Public Access Restricted Facility (LAR01) Item
Address: _____
County: _____
Phone: _____

Disposal Facility:
Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup:
Tarp in good serviceable condition Yes No
Container in good condition Yes No
No free standing water Yes No
Container is empty and clean Yes No

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Trailer # 465007

Loading:
Start Time _____ Box # In _____ Lines 0 1 3 _____ Unloading Start Time _____
End Time _____ Box # Out _____ Lines 0 1 3 _____ End Time _____

Transporter Name: CTI Truck/Class # 445 W 707381

Driver Name: JASON MICHAELS Driver Signature: _____

Remarks: Driver Lic
WDL 3213 BT 43 3
09 23 2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725513

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405014 Volume
Payment Type Credit Account Container 405014
Manual Ticket# 1033544 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	98840 lb*
In 11/01/2021 09:54:54	MANUAL WT	cwalsh3		Tare	54800 lb*
Out 11/03/2021 09:54:54		cwalsh3		Net	44040 lb
Comments				* Manual Weight	Tons 22.02

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.02	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.02	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Carrier Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No fire handling error Yes No
 Container in empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **445** / **707205/4050028-2**

Driver Name: **Arthur Eggers** Driver Signature: _____

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 725515

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405019 Volume
Payment Type Credit Account Container 405019
Manual Ticket# 1033544 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101880 lb*
In 11/01/2021 09:56:47	MANUAL WT	cwalsh3		Tare	52480 lb*
Out 11/03/2021 09:56:47		cwalsh3		Net	49400 lb
Comments				* Manual Weight	Tons 24.70

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		24.70	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100			\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		24.70	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-4512
(541) 454-2030

Bill Of Lading

Date scheduled for pickup **12-28-2021**
Time scheduled for pickup **12-22 AM**

Generator Name and Loading Address
SCD NE 8TH

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Contact Person: _____
Telephone Number: _____

Acknowledgment of Loading:
Company Name: _____ Date: _____
Signature: _____ Name: _____

Carrier Inspection Upon Pickup:
 Tarp in good serviceable condition Yes No
 Container in good condition Yes No
 No fire handling error Yes No
 Container in empty and clean Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In **405019** Liners 0 1 2 Start Time _____
End Time _____ Box # Out _____ Liners 0 1 2 End Time _____

Transporter Name: **CTI** Truck/Trailer # **445** / **707381**

Driver Name: **JASON MICHAELS** Driver Signature: _____

Remarks:
Driver Lic
WDL 3213 BJ 43 B
09/23/2027



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 726064

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 8000
Ticket Date 11/01/2021 Vehicle# 8858 Volume
Payment Type Credit Account Container 8858
Manual Ticket# 1033455 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	71100 lb*
In 10/30/2021 06:53:13	MANUAL WT	cwalsh3		Tare	34840 lb*
Out 11/01/2021 06:53:13		cwalsh3		Net	36260 lb
Comments				* Manual Weight	Tons 18.13

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	18.13	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	18.13	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading: Start Time _____ Box # In _____ Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Chassis #: **1117070005/105019-0**

Driver Name: **Michael Egger** Driver Signature: _____

Remarks: **Empty wt 116,200 lb**



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 726472

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 405
Ticket Date 11/03/2021 Vehicle# 405005 Volume
Payment Type Credit Account Container 405005
Manual Ticket# 1033538 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	96300 lb*
In 11/01/2021 15:21:07	Front Scale	jaday		Tare	54100 lb*
Out 11/03/2021 15:21:07		jaday		Net	42200 lb
Comments				* Manual Weight	Tons 21.10

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T	100	21.10	Tons				WA-BELLEVUE
2 EVF-P6-Environment	100		\$				WA-BELLEVUE
3 RAIL T SPW-RAIL BY	100	21.10	Tons				WA-BELLEVUE

Driver's Signature

WM
Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup **11-03-2021**
Time scheduled for pickup **10:40 AM**

Generator Name and Loading Address: **SCD NE 8TH** Waste Profile #: **115787WA**

Contact Person: _____ Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: **LF01**

Telephone Number: _____

Acknowledgment of Loading: _____

Company Name: _____ Date: _____
Signature: _____ Name: _____

Details of Site: _____ Disposal Facility: Columbia Ridge Landfill and Recycling Center
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Container Inspection Upon Pickup: _____

Check ONE: DROP ONLY PICK UP ONLY WTL

Loading: Start Time _____ Box # In **8858** Unloading Start Time _____
End Time _____ Box # Out _____ Unloading End Time _____

Transporter Name: **CTI** Truck/Chassis #: **445 WM 707381**

Driver Name: **Michael** Driver Signature: _____

Remarks: **Driver Lic WDL 3213 75 43 B**

11/03/2021



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 727234

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 11/11/2021 Vehicle# 483030 Volume
Payment Type Credit Account Container 483030
Manual Ticket# 1030350 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	84000 lb*
In 10/29/2021 10:23:11	Front Scale	jaday		Tare	49000 lb*
Out 11/11/2021 10:23:11		jaday		Net	35000 lb
Comments					17.50
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		17.50	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		17.50	Tons				WA-BELLEVUE

Driver's Signature

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup _____
Time scheduled for pickup _____

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Address/Department of Loading: _____
Company Name: _____ Date: _____
Signature: _____ Name: _____

Dispatcher: _____ Dispatch Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In _____ Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CTI Track/Chassis # 403-743267-405005
Driver Name: JEFF THOMAS Driver Signature: [Signature]

Remarks:
46040
WDL 78794013B

WM
WASTE MANAGEMENT

Columbia Ridge Landfill and Recycling Center
a subsidiary of Waste Management
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
(541) 454-2030

Bill Of Lading Date scheduled for pickup 9-10-2021
Time scheduled for pickup 1:20

Generator Name and Loading Address: SCD NE 8TH
Waste Profile: 115787WA

Contact Person: _____
Telephone Number: _____

Waste Type: CDL
 Contaminated Soil
 Asbestos
 Other: LF01

Address/Department of Loading: _____
Company Name: CITY TRANSFER INC. Date: 9-10-2021
Signature: [Signature] Name: _____

Dispatcher: _____ Dispatch Facility: _____
18177 Cedar Springs Lane
Arlington, Oregon 97812-6512
Phone: (541) 454-2030

Customer Inspection Upon Pickup:
Tarp in good serviceable condition: Yes No
Container in good condition: Yes No
No free standing water: Yes No
Container is empty and clean: Yes No

Circle ONE: DROP ONLY PICK UP ONLY SWAP WTL

Loading:
Start Time _____ Box # In 483030 Lanes 0 1 2 Start Time _____
End Time _____ Box # Out _____ Lanes 0 1 2 End Time _____

Transporter Name: CITY TRANSFER INC. Track/Chassis # _____
Driver Name: _____ Driver Signature: [Signature]

Remarks:



Columbia Ridge
18177 Cedar Springs Lane
Arlington, OR, 97812
Ph: (541) 454-2030

Reprint
Ticket# 727400

Customer Name SCD NE 8TH LLC SCD NE 8TH LLC Carrier 483
Ticket Date 11/12/2021 Vehicle# 483291 Volume
Payment Type Credit Account Container 483291
Manual Ticket# 1031483 Billing # 0002819
Hauling Ticket# Manifest
Destination UP/CUST PO 3535035-200
Profile 115787WA (LF01 - Contained-In PCE Contaminated Soil)
Generator 168-SCD NE 8TH LLC SCD NE 8TH LLC 10630, 10660, 10680 NE 8TH STREET BELLEVUE

Time	Scale	Operator	Inbound	Gross	101120 lb*
In 11/09/2021 06:48:10	Front Scale	jaday		Tare	55500 lb*
Out 11/12/2021 06:48:10		jaday		Net	45620 lb
Comments					22.81
					Tons

Product	LD%	Qty	UOM	Rate	Tax	Amount	Origin
1 Cont Soil Sp. W.-T 100		22.81	Tons				WA-BELLEVUE
2 EVF-P6-Environment 100							WA-BELLEVUE
3 RAIL T SPW-RAIL BY 100		22.81	Tons				WA-BELLEVUE

Driver's Signature



Columbia Ridge Landfill and Recycling Center
 a subsidiary of Waste Management
 18177 Cedar Springs Lane
 Arlington, Oregon 97122-6512
 (541) 454-2036

Bill Of Lading

Date scheduled for pickup: **9-30-21**

Time scheduled for pickup: _____

Generator Name and Loading Address

SCD NE 8th LLC
Bellevue

Contact Person:
 Telephone Number:

Waste Profile # **115787WA**

Waste Type
 CDL
 Contaminated Soil
 Asbestos
 Other _____

Acknowledgment of Loading

Company Name: _____ Date: _____
 Signature: _____ Name: _____

Dr. Scott Inc.
 1100 W. 10th Street, Portland, Oregon 97209
 405 South Street Suite
 North, Portland, OR 97209
 Phone: (503) 764-1500 or (503) 764-1511

Depot of Origin
 Columbia Ridge Landfill and Recycling Center
 18177 Cedar Springs Lane
 Arlington, Oregon 97122-6512
 Phone: (541) 454-2036

Container Inspection Upon Pickup

Tarp in good serviceable condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Container in good condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No free standing water	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Container is empty and clean	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Circle ONE: **DROP ONLY** **PICK UP ONLY** **SWAP** **WTL**

Loading
 Start Time _____ Box # **483291** _____ Unloading
 End Time _____ Box # Out _____ Times 0 1 2 Start Time _____
 End Time _____
 Transporter Name _____ Truck Chassis # _____
 Driver Name _____ Driver Signature _____

Remarks:
Replacement BOL - confirmed using waybill history & argo logs.