



## INITIAL INVESTIGATION FIELD REPORT

LUST ID: 309284

FS ID: 59359661

Site ID: 8277

SITE NAME J & J Motors Inc

### SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
15026 1st Ave S	Seattle	98148	
<hr/>			
Site Location	Closest City	County	
15026 1st Ave S	Seattle		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

### INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

### RECOMMENDATION

No Further Action:

No. Missing info.

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

### CONTAMINANT(S) (See Page 3 for details)


Soil	Yes	
Groundwater	Unknown	Gas, BTEX

### DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>NEC</i>	Date <i>4/7/11</i>
Section Manager	Date

### COMMENTS

The file has no reports and barely any information on the site. Only documents in file are copies of e-mails, several unfilled manifests, some lab results, disposal certificates, a proposal for the tank removal, and a request from Ecology (2005) of a copy of the report. What can be deducted from these is that one gas UST was removed in 1995, approx. 8.44 tons of PCS were disposed off-site for incorporation into asphalt, and that two soil samples were below MTCA for gas, BTEX, and diesel and oil were ND. No additional information in file



## INITIAL INVESTIGATION FIELD REPORT

---

LUST ID: 309284

FS ID: 59359661

Site ID: 8277

SITE NAME J & J Motors Inc

---