

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 4848	38		FS ID:	474382	255		Site ID:	100097	
SITE NAME	Hozome	een Ranger S	Station						
SITE LOCATION	INFORM	IATION							
Contact Person Name Title					Phone Number				
Mailing Address					City			Zip + 4	
48 59 56N 121 03 42W					Dia	blo		98283	
Site Location					Clos	sest City	Co	ounty	
48 59 56N 121	03 42W				Dia	blo			
Quarter-Quarter			Section		Tow	nship	Ran	ge	
Latitude:			Degree		Minu	ıte	Sec	ond	
Longitude:	Longitude:		Degree		Minute		Sec	Second	
INSPECTION INI	FORMAT	ION						· ·	
Inspection Date				l	nspection	n Time	Type of Entry N	otice	
Photographs	Yes	No		V	Veather:	Clear	Partly Cloudy	Overcast	
Videotape	Yes	No		F	Precipitat	ion	Temperature	,i	
Samples	Yes	No		V	Vind Dire	ction	Wind Speed		
RECOMMENDA	TION								
No Further Action	:						, x		
No. PCS dispos	al docum	ients are need	led.						
Release or threatened release does not pose a threat					Site Hazard Assessment				
No release or threatened release					Interim Action				
Educational Mailing					Emergency Action Plan				
Refer to another program/agency					Independent Cleanup Action				
						In Progr	ess	Completed	
		e Page 3 for	details)						
	∕es Gas, BTEX lo			ΞX					
DEPARTMENT F							······································		
Investigator						Date			
Approved by									
Unit Supervisor DEC					Date 6/3/11				
Section Manager					Date				
COMMENTS								• •	
Two USTs (gas) were re	emoved from	this site in 1	998. 0	W was	not enco	ountered in the exc	avation.	

Approx 12 cy of overexcavated PCS were disposed off-site. Confirmation samples were clean. PCS disposal documents are not available. No additional info in files.