



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2342

FS ID: 36296841

Site ID: 97430

SITE NAME Cascade Autovan Company

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
12727 412th Ave SE	North Bend	98045	
<hr/>			
Site Location	Closest City	County	
12727 412th Ave SE	North Bend		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No Videotape Yes No Samples Yes No	Weather: Clear Precipitation Wind Direction	Partly Cloudy Overcast Temperature Wind Speed

RECOMMENDATION

No Further Action:

No. Residual soil impacts above MTCA remained in place.

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	
Groundwater	Yes	Gas, BTEX, diesel.

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>NEC</i>	Date <i>4/20/14</i>
Section Manager	Date

COMMENTS

Two diesel USTs were removed from this facility in 1992. Approximately 350 cy of PCS were overexcavated and bioremediated on-site. Replacement USTs were installed within the same excavation. Residual soil impacts above MTCA as diesel (550 to 2900 ppm) remained on the north and south ends of excavation due to close proximity to a facility transformer. Monitoring wells installed later that year indicated that GW samples were below MTCA for gas, diesel and BTEX. All GW quarterly reports in file 1992 and last one on 4/1995 have been ND for TPH (418.1) and BTEX.



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2342

FS ID: 36296841

Site ID: 97430

SITE NAME Cascade Autovan Company
