




Site Vicinity Map
FSI, Monitoring Well Installation
& Groundwater Monitoring Report
8010 South 259th Street
Kent, Washington

Date: November 22, 2022
Completed By: C.Long
Reviewed By: S.Spencer
Version: ECI-001
Project No.: 0611-01-03-02


Figure No.:


01


Sheet 01 of 09





Providing Practical Environmental Compliance Solutions
Offices in: Anchorage | Tacoma | Portland













0153060

Approximate Scale in Feet

● : Soil Boring Location < CUL

GRO: Gasoline Range Organics

DRO: Diesel Range Organics

ORO: Oil Range Organics

As: Arsenic

● Monitoring Well < MTCA CUL's

● Monitoring Well > MTCA CUL's

Explanation

Cd: Cadmium

Cr: Chromium

Pb: lead

BTEX: Benzene, Toluene, Ethylbenzene, Total Xylenes

BOLD: Above laboratory reporting limit

● : Soil Boring Location > CUL

Red: Above Cleanup Level

mg/Kg: milligram per kilogram

NA: Not run for that COC

ND: Not detected above laboratory reporting limit

--- : Storm System

2021 Boring Sample Location Map

FSI, Monitoring Well Installation

& Groundwater Monitoring Report

8010 South 259th Street

Kent, Washington

Date: November 22, 2022

Completed By: C.Long

Reviewed By: S.Spencer

Version: ECI-001

Project No.: 0611-01-03-02

Figure No.: 06


Sheet 06 of 09

eci

Environmental Services

Providing Practical Environmental Compliance Solutions

Offices in: Anchorage | Tacoma | Portland





0 15 30 60
Approximate Scale in Feet

⊕ : Soil Boring Location
G: Gasoline Range Organics
D: Diesel Range Organics
HO: Heavy Oil Range Organics
- - - - : Storm System

Explanation
mg/Kg: milligram per kilogram
ug/L: microgram per liter
ND: Not detected above laboratory reporting limit

Historical Boring / Sample Location Map
FSI, Monitoring Well Installation
& Groundwater Monitoring Report
8010 South 259th Street
Kent, Washington

Date: November 22, 2022
Completed By: C.Long
Reviewed By: S.Spencer
Version: ECI-001
Project No.: 0611-01-03-02

Figure No.:
08
Sheet 08 of 09

Providing Practical Environmental Compliance Solutions
Offices in: Anchorage | Tacoma | Portland





N

0 15 30 60

Approximate Scale in Feet

⊕ : Soil Boring Location

G: Gasoline Range Organics

D: Diesel Range Organics

HO: Heavy Oil Range Organics

--- : Storm System

Explanation

mg/Kg: milligram per kilogram

ug/L: microgram per liter

ND: Not detected above laboratory reporting limit

Collective Soil Sample Map
FSI, Monitoring Well Installation
& Groundwater Monitoring Report
8010 South 259th Street
Kent, Washington

Date:	November 22, 2022	Figure No.: 09 Sheet 09 of 09
Completed By:	C.Long	
Reviewed By:	S.Spencer	
Version:	ECI-001	
Project No.:	0611-01-03-02	



Providing Practical Environmental Compliance Solutions
Offices in: Anchorage | Tacoma | Portland