Hi Jessica:

Ecology concurs with your updated monitoring well installation plan. Thanks for the update.

Mike

Michael R. (Mike) Warfel, LG, LHG, RG Site Manager, Voluntary Cleanup Program Department of Ecology Northwest Regional Office (NWRO) Physical Address: 15700 Dayton Ave N, Shoreline, WA 98133 Mailing Address: PO Box 330316, Shoreline, WA 98133-9716 Reception (24 hour) number: (206) 594-0000 Direct (Cell): (425) 324-1892 Fax: (206) 366-7810 Email: michael.warfel@ecy.wa.gov Ecology web site: https://ecology.wa.gov/

From: Jessica Smith <jsmith@aspectconsulting.com>
Sent: Wednesday, May 25, 2022 10:28 AM
To: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Cc: Meilani Lanier-Kamaha'o <mlkamahao@aspectconsulting.com>
Subject: RE: Artise Monitoring Wells

THIS EMAIL ORIGINATED FROM OUTSIDE THE WASHINGTON STATE EMAIL SYSTEM - Take caution not to open attachments or links unless you know the sender AND were expecting the attachment or the link

Hi Mike,

Great to talk to you the other day. To recap our discussion and confirm schedule: compliance monitoring well AMW-12 will be completed farther east, beyond the shoring wall, in the approximate location shown on the attached site plan. The purpose of this well is to monitoring groundwater east of the redevelopment in case groundwater impacts are redirected, which is unlikely. Monitoring well AMW-11D will also be moved west of the newly installed AMW-11S, further from the shoring wall.

The work is planned for June 3 and 4, 2022.

Let me know if you have any questions. I will let you know when the wells are complete.

Thanks, Jessica

Jessica Smith, LG | Aspect Consulting LLC | Associate Geologist | Cell: 206.423.8289

From: Jessica Smith
Sent: Tuesday, May 17, 2022 9:31 AM
To: Mike Warfel <<u>mwar461@ecy.wa.gov</u>>
Subject: Artise Monitoring Wells

Hey Mike,


We attempted to install the monitoring wells at the Artise last weekend, but had to stop the field work due to concerns that the borings could negatively impact the temporary shoring system after a soil nail was encountered in AMW-11D. I've attached a site plan showing the locations of the proposed monitoring wells and a summary of what has been completed so far. Schnitzer would like to install the wells as soon as possible so we can begin the 1-year of compliance monitoring and we are meeting today to discuss a plan to install the wells safely. My understanding from conversations with Sellen and the geotechnical engineer is that AMW-11D can be moved to the west, closer to AMW-11S, and completed safely now, but AMW-12 cannot be completed in the current proposed location until February 2023 at the earliest when the temporary shoring system is no longer needed. I would like to propose that AMW-12 be moved to the east, past the temporary shoring system in the approximate location shown on the attached site plan, so that it can be completed in the next few weeks instead of waiting until February. Do you have any concerns with that change? Give me a call if you'd like to talk through it!

Thanks, Jess

Jessica Smith, LG | Associate Geologist | Cell: 206.423.8289 Aspect Consulting LLC | 710 2nd Ave, Suite 550, Seattle 98104 | <u>www.aspectconsulting.com</u>

Bainbridge Island - Bellingham - Seattle - Wenatchee - Yakima - Portland

This email is intended solely for the addressee(s) and may contain confidential or legally privileged information. If you are not the intended recipient, please immediately alert the sender by reply email and delete this message and any attachments without storing, copying, distributing, or using the contents.



7	NE 8th St and 106th Ave NE Bellevue, Washington			
5		NOV-2020	BY: MLK / TDR	FIGURE NO.
-	CONSULTING	PROJECT NO. 190298	REVISED BY: WEG	14