



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 301297

FS ID: 32193281

Site ID: 5517

SITE NAME Kountry Korner

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
27099 Miller Bay Rd NE	Kingston	98346	
<hr/>			
Site Location	Closest City	County	
27099 Miller Bay Rd NE	Kingston		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

No release or threatened release

Educational Mailing

Refer to another program/agency

Site Hazard Assessment

Interim Action

Emergency Action Plan

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	
Groundwater	Yes	Gas, BTEX, diesel

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>[Signature]</i>	Date 5/6/11
Section Manager	Date

COMMENTS

Four USTs (gas, diesel), associated product lines, and dispensers were removed from this property in 1995. Approximately 740 tons of PCS were overexcavated and disposed off-site. Final confirmation soil samples collected after several phases of overexcavation were below MTCA for gas, BTEX, and lead. A sample from the GW observed in the excavation was below MTCA for gas (410 ppb).