



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2432

FS ID: 83974415

Site ID: 11038

SITE NAME Carnation Dairies Dist Bremerton

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number		
<i>Mailing Address</i>				
5235 Auto Center Rd	Bremerton	98312		
<i>Site Location</i>				
5235 Auto Center Rd	Bremerton			
<i>Quarter-Quarter</i>		<i>Section</i>	<i>Township</i>	<i>Range</i>
<i>Latitude:</i>	<i>Degree</i>	<i>Minute</i>	<i>Second</i>	
<i>Longitude:</i>	<i>Degree</i>	<i>Minute</i>	<i>Second</i>	

INSPECTION INFORMATION

<i>Inspection Date</i>	<i>Inspection Time</i>	<i>Type of Entry Notice</i>																	
<table style="width: 100%; border: none;"> <tr> <td style="width: 33%;"><i>Photographs</i></td> <td style="width: 33%;">Yes No</td> <td style="width: 33%;"></td> </tr> <tr> <td><i>Videotape</i></td> <td>Yes No</td> <td></td> </tr> <tr> <td><i>Samples</i></td> <td>Yes No</td> <td></td> </tr> </table>	<i>Photographs</i>	Yes No		<i>Videotape</i>	Yes No		<i>Samples</i>	Yes No		<table style="width: 100%; border: none;"> <tr> <td style="width: 50%;"><i>Weather: Clear</i></td> <td style="width: 50%;"><i>Partly Cloudy</i></td> <td style="width: 50%;"><i>Overcast</i></td> </tr> <tr> <td><i>Precipitation</i></td> <td colspan="2"><i>Temperature</i></td> </tr> <tr> <td><i>Wind Direction</i></td> <td colspan="2"><i>Wind Speed</i></td> </tr> </table>	<i>Weather: Clear</i>	<i>Partly Cloudy</i>	<i>Overcast</i>	<i>Precipitation</i>	<i>Temperature</i>		<i>Wind Direction</i>	<i>Wind Speed</i>	
<i>Photographs</i>	Yes No																		
<i>Videotape</i>	Yes No																		
<i>Samples</i>	Yes No																		
<i>Weather: Clear</i>	<i>Partly Cloudy</i>	<i>Overcast</i>																	
<i>Precipitation</i>	<i>Temperature</i>																		
<i>Wind Direction</i>	<i>Wind Speed</i>																		

RECOMMENDATION

No Further Action:

Yes

- Release or threatened release does not pose a threat*
- No release or threatened release*
- Educational Mailing*
- Refer to another program/agency*

- Site Hazard Assessment*
- Interim Action*
- Emergency Action Plan*
- Independent Cleanup Action*

In Progress *Completed*

CONTAMINANT(S) (See Page 3 for details)

<i>Soil</i>	Yes	
<i>Groundwater</i>	No	Gas, BTEX, HO

DEPARTMENT REVIEW

<i>Investigator</i>	<i>Date</i>
<i>Approved by</i>	
<i>Unit Supervisor</i> <i>AA</i>	<i>Date</i> 5/13/11
<i>Section Manager</i>	<i>Date</i>

COMMENTS

Two USTs (gas, HO), associated product lines, and dispenser were removed from two separate excavations at this property in 1989. Confirmation soil samples collected from each excavation w/o remediation and were ND or below MTCA for Gas/BTEX (gas UST) and for TPH (HO UST). No GW was observed during excavation. Stockpiled soils were used as backfill. No additional info in file.