


- Notes:


  1. Concentration contours do not reflect dissolved concentrations. Results are non-filtered.
  2. Concentration contours generated using CTech's EVS Kriging interpolation method.
  Reach=1000, Anisotropy=5, Nugget=0.
  3. April 2013 groundwater results were chosen for mapping instead of the October 2013. The rational is threefold:
  (1) the suite of wells included all wells
  (2) reporting limits tended to be more elevated in October and
  (3) concentrations of COCs in groundwater were generally higher in April than in October.
  4. December 2014 results are MW-36D, MW-36S, PAI-10, PAI-11B and PAI-12. PAI-2B is not included because it was a non-detect and it had an elevated reporting limit to 10 µg/L.
  5. Non-detects are assumed to have concentrations of half the reporting limit(RL), for contouring purposes. Map posts non-detects as < 1/2RL.
  6. Areas not shaded in the shoreline cross section are interpreted to have benzo(a)pyrene concentrations below the screening level.
  7. Benzo(a)pyrene upland groundwater screening level = 0.03 µg/L.
  8. As of 2019, NAPL was observed in the same wells called out in this figure.
  9. Wells MW-41S through MW-52D are not shown because they were installed in 2017, several years after the sampling events presented in this figure. The new wells were installed for the groundwater treatment interim action and have not been sampled for benzo(a)pyrene.
  10. Basemap: 2005 USGS aerial photograph. Does not show current conditions.
  11. Projection:NAD 1983 State Plane Washington North FIPS 4601 Feet.


Benzo(a)pyrene in **Upland Groundwater** 

Gas Works Park Site Seattle, Washington









1. Concentration contours generated using CTech's EVS Kriging interpolation method.

Reach=1000, Anisotropy=5, Nugget=0.

2. April 2013 groundwater results were chosen for mapping instead of the October 2013. The rational is threefold:

(1) the suite of wells included all wells

(2) reporting limits tended to be more elevated in October and

(3) concentrations of COCs in groundwater were generally higher in April than in October.

3. December 2014 results are MW-36D, MW-36S, PAI-2B, PAI-10, PAI-11B and PAI-12

4. Non-detects are assumed to have concentrations of half the reporting limit(RL), for contouring purposes. Map posts non-detects as < 1/2RL.

Non-detects are assumed to have concentrations of hair the reporting limit(hL), for contouring purposes, Map posts non-detects as < 1/2 kt</li>
 Areas not shaded in the shoreline cross section are interpreted to have naphthalene concentrations below the screening level.
 Naphthalene upland groundwater screening level = 9.880 μg/L
 As of 2019, NAPL was observed in the same wells called out in this figure.
 Wells MW-41S through MW-52D are not shown because they were installed in 2017, several years after the sampling events presented in this figure. The new wells were installed for the arsenic groundwater treatment interim action and have not been sampled for naphthalene.
 Basemap: 2005 USGS aerial photograph. Does not show current conditions.
 Projection: NAD 1983 State Plane Washington North FIPS 4601 Feet.


DISCLAIMER: This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. The locations of all features are approximate. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.


# Naphthalene in **Upland Groundwater**


Gas Works Park Site Seattle, Washington



Figure 5-5







1. Concentration contours generated using CTech's EVS Kriging interpolation method. Reach=1000, Anisotropy=5, Nugget=0.

2. April 2013 groundwater results were chosen for mapping instead of the October 2013. The rational is threefold:

(1) the suite of wells included all wells

(1) the suite of wells included all wells
(2) reporting limits tended to be more elevated in October and
(3) concentrations of COCs in groundwater were generally higher in April than in October.

3. December 2014 results are MW-36D, MW-36S, PAI-2B, PAI-10, PAI-11B and PAI-12

4. Non-detects are assumed to have concentrations of half the reporting limit(RL), for contouring purposes. Map posts non-detects as < 1/2RL.

Non-detects are assumed to nave concentrations or nair the reporting limit(RL), for contouring purposes, map posts non-detects as < 1/2.5 Areas not shaded in the shoreline cross section are interpreted to have benzene concentrations below the screening level.</li>
 Benzene upland groundwater screening level = 43 ug/L
 As of 2019, NAPL was observed in the same wells called out in this figure.
 Wells MW-41S through MW-52D are not shown because they were installed in 2017, several years after the sampling events presented in this figure. The new wells were installed for the arsenic groundwater treatment interim action and have not been sampled for benzene.
 Basemap: 2005 USGS aerial photograph. Does not show current conditions.
 Projection: NAD 1983 State Plane Washington North FIPS 4601 Feet.


DISCLAIMER: This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. The locations of all features are approximate. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.


### Benzene in **Upland Groundwater**


Gas Works Park Site Seattle, Washington



Figure 5-7







### Shoreline Cross Section waximum Arsenic Concentration (µg/L) < 8 Vertical Exaggeration 5:1 ≥ 8 to ≤ 80 > 80 to ≤ 800 $> 800 \text{ to} \le 8,000$ > 8,000

1. Concentration contours reflect dissolved concentrations.

2. Concentration contours generated using CTech's Earth Volumetric Studio Kriging interpolation method.

Reach=1000, Anisotropy=5, Nugget=0.

3. Groundwater results from: 2014 for PAI-10 and PAI-11; 2016 for PAI-22D, PAI-25D, PAI-27S, PAI-27D, PAI-30S and PAI-32D;

2020 for Play Area Interim Action Monitoring Wells; and October 2013 for the remaining wells. 2020 samples analyzed by method SW6010C lab filtered non-preserved.

method SW6010C lab filtered non-preserved.
Previous samples analyzed by method SW6010C field filtered preserved with HNO3.
See Section 5 for a discussion of why these data sets were selected.

4. Areas not shaded in the shoreline cross section are interpreted to have arsenic concentrations below the screening level.

5. Although arsenic is not a groundwater contaminant of concern, concentrations were screened against 8 µg/L.

6. As of 2019, NAPL was observed in the same wells called out in this figure. MW-45s contained trace NAPL at the time it was sampled in 2018.

7. Shoreline Arsenic Contaminated Groundwater Area - see Play Area Interim Action Monitoring Report (GeoEngineers 2021).

8. Basemap: 2005 USGS aerial photograph. Does not show current conditions.

9. Non-detects are assumed to have concentrations of half the reporting limit(RL), for contouring purposes.

Man nots non-detects as < 1/2R.

Map posts non-detects as < 1/2RL.

10. Projection: NAD 1983 State Plane Washington North FIPS 4601 Feet.


DISCLAIMER: This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. The locations of all features are approximate. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.


### Arsenic in **Upland Groundwater**


Gas Works Park Site Seattle, Washington





Figure 5-9






















































<u>Legend</u>

Area of Investigation Shoreline (OHWM)

COC ≤ SCO

cPAH > 0.021 mg/kg (SCO)


Diebenzofuran >0.2 mg/kg (SCO)

TPAH > 17 mg/kg (SCO)

Carbazole >0.9 mg/kg (SCO)

- 1. Basemap 2005 USGS aerial photograph. Does not show
- current conditions.
  2. Projection: NAD 1983 StatePlane Washington North FIPS 4601 Feet.

DISCLAIMER: This drawing is for information purposes. It is intended to assist in showing features discussed in an attached document. The locations of all features are approximate. GeoEngineers, Inc. cannot guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.



Limited Distribution of Dibenzofuran & Carbazole Relative to cPAH & TPAH in Surface Sediment (>SCO)

> Gas Works Park Site Seattle, Washington

GEOENGINEERS Figure 5-23



