



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

1250 West Alder Street • Union Gap, Washington 98903-0009 • (509) 575-2490

July 21, 2020

Meseret C. Ghebreslassie
Installation Restoration Program Manager
Department of the Army
Headquarters, Joint Base Lewis-McChord
1010 Liggett Avenue – Box 339500, Mail Stop 14A
Joint Base Lewis-McChord, WA 98433-9500

Subject: **Approval** – 2019 Annual Groundwater Monitoring Report Fire Training Pit (FTP)
And Tracked Vehicle Repair/Old Mobilization and Training Equipment Site
(TVR/Old MATES), Joint Base Lewis-McChord Yakima Training Center, Washington

Dear Meseret:

Thank you for the submitting the 2019 Annual Groundwater Monitoring Report Fire Training Pit (FTP) and Tracked Vehicle Repair/Old Mobilization and Training Equipment Site (TVR/Old MATES), Joint Base Lewis-McChord Yakima Training Center, Washington. This report, dated March 2020, was downloaded by Ecology on May 1, 2020, from the DoD SAFE service website.

Based on my review, I have no comments and the report is **approved**.

If you have any questions regarding, please contact me at (509) 379-0107 (cell).

Sincerely,

A handwritten signature in blue ink, appearing to read "Thomas L. Mackie".

Thomas L. Mackie, LHG
Hydrogeologist - Site Manager
Hazardous Waste and Toxics Reduction Program
Central Regional Office
Washington State Department of Ecology

ECC: Meseret C. Ghebreslassie, meseret.c.ghebreslassie.civ@mail.mil