

## STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

## **Central Region Office**

1250 West Alder St., Union Gap, WA 98903-0009 • 509-575-2490

April 27, 2023

## Sent via email

Ryan Mathews Fulcrum Environmental Consulting 406 North 2<sup>nd</sup> Street Yakima, Washington 98901

RE: Monitoring Well 101 Replacement Installation – Documentation report - Revised

Site Name: Boise Cascade Mill (aka Yakima Mill Site)

• Site Address: 805 N. 7<sup>th</sup> Street, Yakima

Facility/Site No.: 450
 Cleanup Site No.: 12095
 Agreed Order No.: DE 13959

## Dear Ryan Mathews:

The Washington State Department of Ecology (Ecology) has reviewed the revised Monitoring Well 101 Replacement Installation – Documentation report dated April 7, 2023 submitted by Fulcrum Environmental consulting to Ecology on April 18, 2023. Ecology has no additional comments and considers the report Final.

If you have any questions regarding this response, please contact me by phone at 509-225-0304 or email at John.Zinza@ecy.wa.gov.

Sincerely,

John Zinza, PE

Cleanup Project Manager Toxics Cleanup Program

Central Regional Office

cc: Allan Gebhard, Barr Engineering