



Standing water on roadway in front of property.





Standing water on left edge of driveway near the road.



Standing water in a pothole on the edge of the driveway. Damp gravel/soil made it difficult to discern if staining was present.





View of roadway in front of the subject property (left). Damp gravel/soil made it difficult to discern if staining was present.





View facing down the driveway with stained gravel. Note: white and silver vehicles are from Skagit Environmental Health and Ecology, respectively.





Additional viewpoints of same stained gravel/soil as above.





Small soil/gravel stains on driveway, (approx. 1 ft at widest part)





Small area of stained soil/gravel (approx. 1.5 ft at widest point).



Stained soil and dead vegetation on grassy area to the right of the residence.





Small (< 1 sq ft) area of staining underneath an RV parked to the right of the residence.





Dark soil staining on grassy area to the right of the residence.



Unlabeled containers. Darker soil appears to be from soil disturbance rather than staining.



Misc. trash on top of darker soil, possibly staining.





Trash with slightly darker soil around it, possibly staining.



Grassy area with small spots that appear to be staining.





Pile of trash including household batteries, electronics, and containers of caulk/lubricant.



Trash pile





Staining underneath a riding mower.



Staining observed underneath a riding mower and possibly around an open bucket.





Pile of trash with an uncovered bucket filled to the brim, propane tank, canister of starter fluid, and canister of lubricant. Couldn't discern the state of soil underneath.





Dark staining underneath a vehicle parked on grass.



Dark soil on the driveway (silver car is an Ecology SOV, not a vehicle stored on the property). Larger spot on the left appears to be damp in the center, and this area is closer to the roadway where potholes and standing water are. Could not tell if staining is contributing to the discoloration.





Miscellaneous trash pile including a paint sprayer with paint canister loaded.





Dark areas that appear to be stained soil/gravel around two Valvoline bottles (appear to be for engine oil) and an unlabeled bottle. Additional bottles of auto fluid products are in the pile of trash background.





Grassy area to the right of the property with dead grass on the natural walkway to the backyard and a few dark areas that appear to be from staining.





Grassy area with dark spots that appear to be staining.