



Port of Camas/Washougal

September 12, 1989

SEP 14 1989

Ms. Vicky Stansberry
U.S. Environmental Protection Agency
Region 10
1200 Sixth Avenue, WD-139
Seattle, Washington 98101

Mr. Thom Leifkin/Ms. Jean Witt
Storage Tank Unit
Department of Ecology
Mail Stop PV-11
Olympia, Washington 98504-8711

Chief Darrell Alder
Washougal Fire Department
1400 'A' Street
Washougal, Washington 98671

Mr. Kevin Mickel
City of Washougal
1701 'C' Street
Washougal, Washington 98671

Please be advised that the Port of Camas-Washougal has removed and disposed of tanks 7, 8, 9, 10 and 11 on the enclosed spreadsheet. Tank no. 10 was found to be a leaker, and contaminated approximately 20 cubic yards of adjacent soil. Mr. Phil Scoles is working with the Washington State Department of Ecology and the Southwest Washington Air Pollution Control Authority for the neutralization and/or disposal of this contaminated material.

Sincerely,

Sheldon Tyler
Manager

ST:pk

Enclosure

OF CAMAS-WASHOUGAL
Street
ougall, Wa. 98671

GROUND STORAGE TANK INFORMATION

Sept.12, 1989

Supercedes 6/8/89

Page 1 of 1

(Location) Address	DOE Site #	Above or under- ground	Size in Gallons	Use	Install. Date	Status	Const- ruction	Action Required	Year Action Required	Comments
(Marina) 24 A Street Washougal, Wa. 98607	010714	under	10,000	Gas	4/72	Active	Steel	Replace or Upgrade	Dec.'91	Remove & Replace 1989
(Marina) 24 A Street Washougal, Wa. 98607	010714	under	6,000	Diesel	4/72	Active	Steel	Replace or Upgrade	Dec.'91	Remove & Replace 1989
(Marina) 24 A Street Washougal, Wa. 98607	010714	under	1,000	Gas	1980	Active	Steel	Replace or Upgrade	Dec.'93	Remove & Replace 1989
(Marina) 24 A Street Washougal, Wa. 98607	010714	under	500	Diesel	1980	Active	Steel	Replace or Upgrade	Dec.'93	Remove & Replace 1989
(, port) 632 N.E.267th Av Camas,Wa.98607	010713	under	12,000	80 oct. Av.Gas	1981	Active	Steel	Leak Detection, corrosion protect. Spill/Overfill	Dec.'93	Upgrade 1990
(Airport) 632 N.E.267th Av Camas,Wa.98607	010713	under	6,000	100 oct Av.Gas	1988	Active	Fibregl. Sgl.wall	Monitor Leak Detection Spill/Overfill	Dec.'93	Upgrade 1990
(Ind.Park) 3495 Truman St. Washougal Bldg. #2		under	5,000	Diesel	1968	Inactive	Steel	Remove and Destroy	Dec.'89	Removed & Destroyed 8/20/89
(Ind.Park) 3495 Truman St. Washougal Bldg. #2		under	5,000	Gas	1968	Inactive	Steel	Remove and Destroy	Dec.'89	Removed & Destroyed 8/20/89

	(Ind.Park) 3495 Truman St. Washougal								Remove and Destroy		Removed & Destroyed
8	Bldg. #2		under	5,000	Gas	1968	Inactive	Steel		Dec.'89	8/20/89
	(Ind.Park) 531 S. 28th St. Washougal	010715							Remove and Destroy		Removed & Destroyed
9	Bldg. #4		under	500	Gas	1972 ?	Inactive	Steel		Dec.'89	8/20/89
	(Ind.Park) 531 S. 28th St. Washougal	010715							Remove and Destroy		Removed & Destroyed
10	Bldg. #4		under	1,000	Diesel	1972 ?	Inactive	Steel		Dec.'89	8/20/89
	(Ind.Park) 531 S. 28th St. Washougal	010715									Destroyed
11	Bldg. #4		above	3,000	?	?	Inactive	Steel	Destroy	N/A	8/20/89