- Proposed Sidewall Confirmation Sample
- Proposed Base Confirmation Sample
- Discrete Soil Sample
- Hand Auger
- Grab Sample

Soil Analytical Results

- Analytes detected exceeded MTCA Method A cleanup levels

Soil Management Category

- Likely Non-Hazardous Contaminated Soil
- Unknown Soil*
- Cleanup Area on South Adjacent Property
- Area Requiring Remediation
- Concrete Slab
- Site Parcel
- King County Tax Parcel

**Area beneath slab and on duplex property will be characterized using a 15-foot composite sampling grid after demolition.*

N

0 15 30 Feet

Proposed Confirmation Sampling Plan Map

Contaminated Media Management Plan
Former Phinney Substation
Seattle, Washington

Aspect Consulting	OCT-2024	BY: HRC / HMD	FIGURE NO. 1
	PROJECT NO. 210143-A-08	REVISED BY: ---/---	

Data source credits: None || Basemap Service Layer Credits: EagleView Technologies, Inc.

ArcGIS Pro: T:\projects_8\Seattle\City Light\Former Phinney Substation_210143\Former Phinney Substation_210143\Former Phinney Substation_210143.aprx || NAD 1983 HARN State Plane Washington North FIPS 4601 Feet || Date Saved: 10/4/2024 || Exported: 10/7/2024 14:52 by Nora Hoche