



LUST 5528
Rasmussen equipment
Seattle

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 5528

FS ID: 81158515

Site ID: 721

SITE NAME Rasmussen Equipment Co Inc

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
Mailing Address		City Zip + 4	
415 S Cloverdale St		Seattle 98108	
Site Location		Closest City County	
415 S Cloverdale St		Seattle	
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

No release or threatened release

Educational Mailing

Refer to another program/agency

Site Hazard Assessment

Interim Action

Emergency Action Plan

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	Gas, BTEX, diesel
Groundwater	No	

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>[Signature]</i>	Date 2/2/11
Section Manager	Date

COMMENTS

Two USTs (gas, diesel) were removed from this site in 1993. Approx 300 cy of overexcavated PCS was disposed off-site. GW was not encountered in the excavation. Confirmation samples were all below MTCA. This site appears to be cleaned up.