

Site Name = SHARP it



SHARP Report — Part 1 of 2

[Go to site contamination history](#)

• SHARP first SHARP		v2024.04.29	Ecology Info	
• SHARP rating	Low		ERTS	734648
• SHARP date	12/19/2024		CSID	17152
• EJFlagged?	✓ – No Override		FSID	24211
• LD confidence level	low		VCP	SHARP it
• Cleanup milestone	initial investigation		UST ID	SHARP it
• SHARPster	Mike Webb		LUST ID	SHARP it

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	⊘
Groundwater	D4	high	risk to off-site people	⊘
Surface water	D4	high	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	⊘
Soil	D4	high		

Location and land use info

1615 W. Ahtanum Rd, Yakima, Yakima County, 98903

Primary parcel SHARP it
Land use industrial
Responsible unit CRO

Sources reviewed

ERTS#734648

Spill summery report

Analytical report



Primary census tract	Associated census tracts
53077001300	SHARP it

Local demographics comments
no comments

Source/source area description
An above ground storage tank in a graded supply yard was struck by a stolen vehicle and the piping was broken allowing approximately half the contents of (100-150 Gallons) to drain onto a packed gravel surface.

Soil comments
no comments

Groundwater comments
no comments

Surface water comments

no comments

Sediment comments

no comments

Indoor air comments

no comments

Additional factors comments

no comments

Site history

[Go to top](#)

Site is used as a supply yard for a agricultural wind machine manufacturer.

Overflow - Site contamination and cleanup history

No overflow

Site Name = SHARP it

17152 20241219

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model

12/19/2024



Assessment scores by environmental medium

