

May 7, 2025

1413.001.10

Washington Department of Ecology
Northwest Regional Office Toxics Control Program
Attention: Ms. Tena Seeds
15700 Dayton Avenue North
Shoreline, Washington 98133

BY EMAIL ONLY

**2024 Q3 and Q4 GROUNDWATER AND SOIL VAPOR DATA REPORT
AMERICAN LINEN SUPPLY CO DEXTER AVE SITE
AGREED ORDER NO. DE 14302**

Dear Ms. Seeds:

NV5 has prepared this data submittal on behalf of BMR-Dexter LLC (“BMRD”) for the American Linen Supply Co. Dexter Ave Site (the “Site”) located at 700 Dexter Avenue North, Seattle, Washington. This submittal provides the data collected from the third quarter of 2024 through the fourth quarter of 2024, including data from interim action performance monitoring wells at the 700 Dexter Avenue North property (the “Property”) and at the Seattle Department of Transportation Mercer Parcels Site (also known as 800 Mercer), and remedial investigation (“RI”) monitoring wells. Groundwater elevation contour maps for the third and fourth quarters of 2024 are included in the Draft Interim Action Work Plan Addendum No.3, submitted to the Washington State Department of Ecology (Ecology) on March 18, 2025.

This data report was revised based on the Ecology’s comments received in March 2025. NV5 conducted the monitoring consistent with the Final Interim Action Work Plan (“IAWP”)¹, the Final Contingent Action Addendum (“CAA”) to the Final IAWP², the Final Remedial

¹ PES Environmental, Inc. 2018. *Final Interim Action Work Plan, American Linen Supply Co-Dexter Avenue Site, 700 Dexter Avenue North, Seattle, Washington*. Prepared for BMR-Dexter LLC. August.

² PES Environmental, Inc. 2019. Letter from D. Balbiani and B. O’Neal to T. Cardona (Ecology) re: *Final Contingent Action Addendum to the Final Interim Action Work Plan, Former American Linen Supply Co-Dexter Ave Site, Agreed Order No. DE 14302*. February 14.

Investigation/Feasibility Study (“RI/FS”) Work Plan,³ the Final RI/FS Work Plan Addendum,⁴ the Proposed Groundwater and Soil Vapor Monitoring Plan,⁵ and the Interim Action Work Plan Addendum No. 2.⁶ NV5 measured groundwater levels and collected groundwater samples during this period to document the chlorinated volatile organic compound (“CVOC”) concentrations in groundwater. This data submittal summarizes the field and analytical laboratory procedures, provides the tabulated data, provides CVOC time-trend plots, and includes the analytical laboratory reports and data validation review memoranda.

Construction activities were being performed on and near the Property during this monitoring period, including 700 Dexter interior build-out and redevelopment activities at 701 Dexter Avenue North.

GROUNDWATER MONITORING PROCEDURES

During quarterly groundwater monitoring, NV5 measured groundwater levels and performed groundwater sampling from wells within the RI/IA monitoring well network at the Site. Figure 1 shows the well and soil vapor probe locations. NV5 used an electronic water level probe to measure depth to groundwater in the wells, and a pressure gauge to monitor the flowing CAA wells in the Property basement. NV5 sampled the monitoring wells with a peristaltic or bladder pump depending on the depth to water in the wells. Wells were purged at pumping rates of 200 mL/min or less. Three casing volumes of water were purged from flowing Property CAA monitoring wells when the water level was above the well top of casing prior to sampling. One primary groundwater sample was collected from each monitoring well. Field quality assurance samples consisted of trip blanks, duplicate samples (one duplicate sample collected for every 20 primary groundwater samples), and equipment rinsate blanks for wells sampled with a bladder pump. All samples were shipped for analysis of VOCs by Environmental Protection Agency (“EPA”) Method 8260D. Groundwater samples from a subset of wells across the Site were also analyzed for geochemical parameters. All samples were shipped to Pace Analytical in Mount Juliet, Tennessee for analysis.

- **Third Quarter 2024:** Between September 3 to September 4, 2024, NV5 measured two rounds of groundwater levels in 103 monitoring wells within the RI/IA monitoring well network at the Property and around the Site, and in 11 monitoring wells on the Seattle DOT Mercer Parcels and at the Seattle DOT Dexter Parcel site. MW-343, MW-345, MW-144R, and MW-145R were inaccessible; MW-305 contained sediments, and the

³ PES Environmental, Inc. 2019. *Final Remedial Investigation/Feasibility Study Work Plan, American Linen Supply Co-Dexter Avenue Site, 700 Dexter Avenue North, Seattle, Washington*. Prepared for BMR-Dexter LLC. December 4.

⁴ PES Environmental, Inc. 2020. *Final Remedial Investigation/Feasibility Study Work Plan Addendum, American Linen Supply Co-Dexter Avenue Site, 700 Dexter Avenue North, Seattle, Washington*. Prepared for BMR-Dexter LLC. June 11.

⁵ PES Environmental, Inc. 2023. *2023 Groundwater and Soil Vapor Monitoring Plan, American Linen Supply Co-Dexter Avenue Site, Agreed Order No. DE 14302*. January 30.

⁶ PES Environmental, Inc. 2022. *Interim Action Work Plan Addendum No. 2, American Linen Supply Co-Dexter Avenue Site, Agreed Order No. DE 14302*. Submitted to the Washington Department of Ecology, Northwest Regional Office Toxics Cleanup Program. February 22.

depth to water was assumed to correspond to the depth at which sediment was encountered. WM-MW-02 and MW-157 contained Emulsified Vegetable Oil (EVO), with the depths listed in Table 1 representing the depth to EVO.

- Between September 4 and September 5, 2024, NV5 collected groundwater samples from 8 monitoring wells outside of the Property, including 1 Intermediate A Zone well and 7 Intermediate B Zone wells. NV5 did not sample W-MW-02 due to the presence of EVO in the well. One primary groundwater sample was collected from each monitoring well, with one duplicate sample collected from MW-346. One equipment rinsate blank and two trip blanks were also collected;
- **Fourth Quarter 2024:** Between November 4 and November 5, 2024, NV5 measured two rounds of groundwater levels in 104 monitoring wells within the RI/IA monitoring well network at the Property and around the Site, and in 11 monitoring wells on the Seattle DOT Mercer Parcels and at the Seattle DOT Dexter Parcel site. Monitoring wells MW-9 and MW-214 were inaccessible due to being paved over and parked over, respectively; and
- Between November 5 and November 22, 2024, NV5 collected groundwater samples from 123 monitoring wells outside of the Property, including 13 Shallow Zone wells, 29 Intermediate A Zone wells, 28 Intermediate B Zone wells, and 30 Deep Zone wells. Of the 24 CAA monitoring wells on the Property, NV5 sampled 23 wells during the fourth quarter 2024 event. NV5 did not sample MW-157, W-MW-02, or MW-178(basement well) due to the presence of EVO in the wells, and MW-305 was not sampled due to insufficient water. MW-112R was also not sampled as the presence of sediments made it unstable for sampling. One primary groundwater sample was collected from each monitoring well, with eight duplicate samples collected from MW108, MW-146, MW-153, MW-161, MW-168, MW-170, MW-188, and MW-346. Seven equipment rinsate blanks and eight trip blanks were submitted for analysis.

Table 11 outlines the monitoring wells historically measured for depth of water out of convenience but not included in the monitoring plan. These wells were not measured during 2024 Quarter 3 and Quarter 4.

VAPOR PROBE SAMPLING PROCEDURES

NV5 collected soil vapor samples during quarterly sampling events from shallower and deeper vadose zone soil vapor probes at the Site. Soil vapor samples were analyzed for VOCs, including tetrachloroethene (“PCE”), trichloroethene (“TCE”), cis-1,2-dichloroethene (“cDCE”), trans-1,2-dichloroethene (“tDCE”), and vinyl chloride (“VC”).

Third Quarter 2024: On September 6, 2024, NV5 collected soil vapor samples from 2 vapor probes outside the Property, including 1 Shallow Soil Zone probe and 1 Deep Soil Zone probe. One primary soil vapor sample was collected from SV01 and SV-18 each, with a duplicate sample collected from SV-18.

Fourth Quarter 2024: On November 25, 2024, NV5 collected soil vapor samples from 2 vapor probes outside the Property, including 1 Shallow Soil Zone probe and 1 Deep Soil Zone probe. One primary soil vapor sample was collected from SV01 and SV-18 each, with a duplicate sample collected from SV-18.

MONITORING RESULTS

Table 1 provides the depths to water measured during the monitoring periods in monitoring wells across the Site. Tables 2 through 9 have been updated to include field parameters and the laboratory results for the groundwater samples collected during the third through the fourth quarters of 2024 monitoring period, and Table 10 provides the laboratory results for the soil vapor samples collected during the monitoring period. Attachment A provides a well completion table that includes updated survey data and survey data for wells not monitored until after the RI. Attachment B presents CVOC time trend plots updated to include the third and fourth quarter 2024 data, and Attachment C provides the laboratory reports and data validation memoranda for the third and fourth quarter 2024 data.

The 2024 Q4 laboratory data contained some holding times that were exceeded. Specifically, VOC analysis from MW-146 and MW-994 (duplicate sample) collected on November 21, 2024 exceeded the laboratory hold time due to the need for dilution and reanalysis. This data is deemed usable but has a J qualifier. Samples from monitoring wells MW-173 through MW176, MW165 through MW168 and MW-999 (duplicate) collected between November 18 through November 19 exceeded the 48-hour holding time for nitrates. This data is used for the natural attenuation monitoring and not for regulatory compliance. These results were all non-detected. However, as sample time was exceeded a qualifier (R) was added for these samples. Technically this data is not usable for compliance analysis. Although the nitrate results were rejected, the non-detected results are similar to non-detected concentrations in past sampling events.

Please call if you have any questions or comments regarding this report.

Sincerely,

NV5

Craig J. Peterson, P.E.
Principal Environmental Engineer

cc: John Moshy, BMRD
Elizabeth Dickey, BMRD

Attachments: Table 1 – Summary of Site-Wide Groundwater Elevations
Table 2 – Groundwater Field Parameters
Table 3 – Groundwater Analytical Data for Shallow Zone Wells
Table 4 – Groundwater Analytical Data for Intermediate A Zone Wells
Table 5 – Groundwater Analytical Data for Intermediate B Zone Wells
Table 6 – Groundwater Analytical Data for Deep Zone Wells
Table 7 – Groundwater Analytical Data, Treatment Zone Monitoring Wells
Table 8 – Groundwater Geochemical Parameters
Table 9 – Dehalococcoides Data, Treatment Monitoring Zone Wells
Table 10 – Soil Vapor Analytical Results
Table 11 – Farallon Wells Excluded From the 2024 Quarter 3 and Quarter 4
Contour Maps

Figure 1 – Groundwater Monitoring Network

Attachment A – Well Completion Table
Attachment B – CVOC Time-Trend Plots
Attachment C – Laboratory Reports and Data Validation Memoranda

TABLES

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
Shallow Zone								
B-37-3	Block 37, NW quadrant	15.0 to 25.0	11.8 to 1.8	26.78	02/14/22	Farallon	8.79	17.99
					05/16/22	Farallon	7.97	18.81
					08/08/22	Farallon	8.35	18.43
					11/07/22	Farallon	8.87	17.91
					02/21/23	Farallon	8.38	18.40
					05/08/23	Farallon	7.88	18.90
					08/10/23	Farallon	9.03	17.75
					10/30/23	Farallon	8.87	17.91
B-37-4	Block 37, NE quadrant	15.0 to 25.0	12.2 to 2.2	27.20	02/14/22	Farallon	8.70	18.50
					05/16/22	Farallon	7.95	19.25
					08/08/22	Farallon	7.39	19.81
					11/07/22	Farallon	8.85	18.35
					02/21/23	Farallon	8.34	18.86
					05/08/23	Farallon	7.83	19.37
					08/10/23	Farallon	8.92	18.28
					10/30/23	Farallon	8.81	18.39
B-37-5	Block 37, center of Property	15.0 to 25.0	12.6 to 2.6	27.55	02/14/22	Farallon	9.02	18.53
					05/16/22	Farallon	8.27	19.28
					08/08/22	Farallon	8.71	18.84
					11/07/22	Farallon	9.12	18.43
					02/21/23	Farallon	8.60	18.95
					05/08/23	Farallon	8.20	19.35
					08/10/23	Farallon	9.34	18.21
					10/30/23	Farallon	9.14	18.41
B-37-6	Block 37, NE quadrant	15.0 to 25.0	12.5 to 2.5	27.54	02/14/22	Farallon	9.08	18.46
					05/16/22	Farallon	8.33	19.21
					08/08/22	Farallon	8.69	18.85
					11/07/22	Farallon	9.29	18.25
					02/21/23	Farallon	8.66	18.88
					05/08/23	Farallon	8.11	19.43
					08/10/23	Farallon	9.30	18.24
					10/30/23	Farallon	9.20	18.34
B43-FMW-1	Roy St ROW, N side (Block 43)	7.5 to 20.0	22.7 to 10.2	30.19	02/14/22	Farallon	11.21	18.98
					05/16/22	Farallon	10.54	19.65
					08/08/22	Farallon	10.56	19.63
					11/07/22	Farallon	10.84	19.35
					02/21/23	Farallon	10.92	19.27
					05/08/23	Farallon	10.81	19.38
					08/10/23	Farallon	11.58	18.61
					10/30/23	Farallon	11.56	18.63
B43-FMW-2	Mercer St ROW, N side (Block 43)	5.0 to 15.0	29.6 to 21.6	34.64	02/14/22	Farallon	13.12	21.52
					05/16/22	Farallon	12.57	22.07
					08/08/22	Farallon	13.75	20.89
					11/07/22	Farallon	12.37	22.27
					02/21/23	Farallon	12.82	21.82
					05/08/23	Farallon	13.18	21.46
					08/10/23	Farallon	14.24	20.40
					10/30/23	Farallon	13.39	21.25

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
B43-FMW-3	Roy St ROW, S side (Block 43)	10.0 to 20.0	20.0 to 10.0	29.96	02/14/22	Farallon	13.35	16.61
					05/16/22	Farallon	10.29	19.67
					08/08/22	Farallon	10.43	19.53
					11/07/22	Farallon	10.81	19.15
					02/21/23	Farallon	10.67	19.29
					05/08/23	Farallon	10.56	19.40
					08/10/23	Farallon	DRY	–
					10/30/23	Farallon	DRY	–
B43-FMW-4	Roy St ROW, S side (Block 43)	10.0 to 20.0	20.3 to 10.3	30.33	02/14/22	Farallon	11.26	19.07
					05/16/22	Farallon	10.69	19.64
					08/08/22	Farallon	10.74	19.59
					11/07/22	Farallon	11.16	19.17
					02/21/23	Farallon	10.98	19.35
					05/08/23	Farallon	10.83	19.50
					08/10/23	Farallon	11.73	18.60
					10/30/23	Farallon	11.67	18.66
B43-FMW-5	Roy St ROW, S side (Block 43)	8.0 to 18.0	24.7 to 14.7	32.67	02/14/22	Farallon	13.74	18.93
					05/16/22	Farallon	13.12	19.55
					08/08/22	Farallon	13.18	19.49
					11/07/22	Farallon	13.69	18.98
					02/21/23	Farallon	13.45	19.22
					05/08/23	Farallon	13.21	19.46
					08/10/23	Farallon	14.05	18.62
					10/30/23	Farallon	DRY	–
B43-FMW-6	Roy St ROW, N side (Block 43)	8.0 to 18.0	24.4 to 14.4	32.42	02/14/22	Farallon	13.35	19.07
					05/16/22	Farallon	12.70	19.72
					08/08/22	Farallon	12.76	19.66
					11/07/22	Farallon	13.04	19.38
					02/21/23	Farallon	13.15	19.27
					05/08/23	Farallon	13.02	19.40
					08/10/23	Farallon	13.70	18.72
					10/30/23	Farallon	13.81	18.61
BB-8A	Roy Street ROW	Unknown	–	--	01/29/09	DOF	20.60	–
					02/19/10	SES	19.05	–
					05/03/10	SES	19.34	–
					06/02/11	SES	18.18	–
					Decommissioned			–
BB-10	Dexter Ave N ROW, E side	29 to 39	–	--	09/05/97	B&V	25.91	–
					09/09/97	B&V	25.70	–
					10/17/97	B&V	25.80	–
					11/13/97	B&V	25.30	–
					12/02/97	B&V	25.30	–
					01/21/98	B&V	25.88	–
					02/27/98	B&V	25.72	–
					03/25/98	B&V	25.53	–
					04/23/98	B&V	29.54	–
					06/05/98	B&V	26.20	–
					07/01/98	B&V	26.24	–
					07/27/98	B&V	26.85	–
					08/25/98	B&V	27.27	–
					09/29/98	B&V	27.00	–
					Decommissioned			–

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
BB12A	9th Ave N ROW	Unknown	–	--	02/19/11	SES	14.40	–
					05/02/10	SES	15.81	–
DMW-1S	615 Dexter, SE quadrant	20.0 to 30.0	38.9 to 28.9	55.76	Decommissioned			
					03/21/19	HC	21.01	34.75
					03/27/19	HC	20.88	34.88
					12/05/19	HC	24.88	30.88
					03/19/20	HC	22.35	33.41
					03/26/20	HC	22.37	33.39
					05/11/20	HC	23.28	32.48
					07/13/20	HC	24.33	31.43
					11/16/20	PES	25.40	30.36
					02/01/21	HC	21.41	34.35
					06/07/21	PES	22.27	33.49
					08/16/21	PES	23.35	32.41
02/14/22	PES	19.35	36.41					
DMW-2S	615 Dexter, SE quadrant	25.0 to 35.0	31.0 to 21.0	55.74	03/19/20	HC	22.89	32.85
					05/11/20	HC	23.76	31.98
					07/13/20	HC	24.72	31.02
					11/16/20	PES	25.69	30.05
					02/01/21	HC	21.53	34.21
					06/07/21	PES	22.27	33.47
					02/14/22	PES	inaccessible	
DMW-4S	Alley S of SE quadrant of 615 Dexter	23.0 to 33.0	38.8 to 28.8	61.54	03/19/20	HC	22.28	39.26
					05/11/20	HC	22.51	39.03
					07/13/20	HC	23.11	38.43
					11/16/20	PES	23.28	38.26
					02/01/21	HC	21.48	40.06
					06/07/21	PES	24.32	37.22
					08/16/21	PES	25.83	35.71
					02/14/22	PES	21.30	40.24
DMW-5IA	Alley S of 615 Dexter	39.8 to 49.8	29.7 to 19.7	69.15	03/19/20	HC	38.71	30.44
					05/11/20	HC	39.32	29.83
					07/13/20	HC	40.37	28.78
					11/16/20	PES	41.95	27.20
					02/01/21	HC	38.25	30.90
					06/07/21	PES	38.91	30.24
					08/16/21	PES	40.08	29.07
					02/14/22	PES	36.64	32.51
DMW-6	615 Dexter, NE quadrant	34.0 to 44.0	32.3 to 22.3	66.08	03/19/20	HC	28.91	37.17
					05/11/20	HC	29.28	36.80
					07/13/20	HC	29.91	36.17
					11/16/20	PES	30.84	35.24
					02/01/21	HC	28.30	37.78
					06/07/21	PES	28.04	38.04
					08/16/21	PES	28.85	37.23
					02/14/22	PES	24.81	41.27
DMW-7S	Dexter Ave N ROW, W side	28.0 to 38.0	30.3 to 20.3	58.01	02/01/21	HC	23.59	34.42
					06/07/21	PES	24.73	33.28
					08/16/21	PES	25.80	32.21
Abandoned 2022?								

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
DMW-8S	Dexter Ave N ROW, W side	27.0 to 37.0	31.6 to 21.6	58.35	02/01/21	HC	24.46	33.89
					06/07/21	PES	25.52	32.83
					08/16/21	PES	26.53	31.82
					Abandoned 2022?			
DMW-9S	Dexter Ave N ROW, W side	23.0 to 33.0	35.9 to 25.9	58.55	02/01/21	HC	22.20	36.35
					06/07/21	PES	23.12	35.43
					08/16/21	PES	25.43	33.12
					Abandoned 2022?			
DMW-10S	601 Dexter, NE quadrant	35.0 to 55.0	24.5 to 4.5	59.24	02/01/21	HC	28.58	30.66
					06/07/21	PES	29.81	29.43
					02/14/22	PES	27.31	31.93
DMW-11S	601 Dexter, NE quadrant	30.0 to 50.0	31.2 to 11.2	60.86	02/01/21	HC	28.93	31.93
					06/07/21	PES	30.10	30.76
					02/14/22	PES	27.62	33.24
DMW-12S	615 Dexter, SE quadrant	30.0 to 50.0	36.1 to 16.1	65.67	02/01/21	HC	29.48	36.19
					06/07/21	PES	31.67	34.00
					02/14/22	PES	29.43	36.24
DMW-13S	Alley S of SW quadrant of 615 Dexter	30.0 to 50.0	36.3 to 16.3	65.02	02/01/21	HC	35.24	29.78
					06/07/21	PES	35.79	29.23
					02/14/22	PES	33.73	31.29
DMW-14S	Alley S of SW quadrant of 615 Dexter	41.0 to 51.0	29.3 to 19.3	70.15	02/01/21	HC	40.47	29.68
					06/07/21	PES	40.70	29.45
					08/16/21	PES	41.90	28.25
					02/14/22	PES	38.45	31.70
F5	Property, NW quadrant	10 to 40	29.1 to -1.0	39.00	03/20/17	PES	4.02	34.98
					03/24/17	PES	NA	
					04/14/17	PES	NA	
					04/28/17	PES	NA	
					05/05/17	PES	NA	
					05/12/17	PES	NA	
					05/19/17	PES	6.91	32.09
					06/12/17	PES	9.72	29.28
					10/11/17	PES	16.27	22.73
					03/14/19	PES	–	
					Decommissioned March 2019			
F9	Property, NE quadrant	10 to 40	28.5 to -1.5	38.76	03/20/17	PES	4.40	34.36
					03/24/17	PES	5.01	33.75
					04/14/17	PES	4.98	33.78
					04/28/17	PES	6.01	32.75
					05/05/17	PES	6.14	32.62
					05/12/17	PES	6.80	31.96
					05/19/17	PES	7.16	31.60
					06/12/17	PES	10.46	28.30
					10/11/17	PES	17.73	21.03
					03/14/19	PES	4.09	
					Decommissioned March 2019			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
F13	Property, NE quadrant	10 to 40	28.4 to -1.6	38.69	03/20/17	PES	4.34	34.35
					03/24/17	PES	4.80	33.89
					04/14/17	PES	4.68	34.01
					04/28/17	PES	5.62	33.07
					05/05/17	PES	5.90	32.79
					05/12/17	PES	6.43	32.26
					05/19/17	PES	6.99	31.70
					06/12/17	PES	9.87	28.82
					10/11/17	PES	18.58	20.11
					03/14/19	PES	3.86	
Decommissioned March 2019								
FMW-132	Block 38 West, N end	5 to 10	20.7 to 15.7	25.48	08/30/18	Farallon	7.44	18.04
					12/28/18	Farallon	6.80	18.68
					03/26/19	Farallon	7.01	18.47
FMW-133	Block 38 West, N end	6.5 to 11.5	18.8 to 13.8	24.87	08/30/18	Farallon	6.86	18.01
					12/28/18	Farallon	6.21	18.66
					03/26/19	Farallon	6.41	18.46
FMW-134	Block 38 West, S end	12 to 17	13.4 to 8.4	24.98	08/30/18	Farallon	8.66	16.32
					12/28/18	Farallon	7.80	17.18
					03/26/19	Farallon	7.51	17.47
FMW-135	Block 38 West, N end	7 to 12	18.6 to 13.6	25.29	08/30/18	Farallon	7.14	18.15
					12/28/18	Farallon	6.78	18.51
					03/26/19	Farallon	6.81	18.48
FMW-139	Block 37, SE quadrant	7.0 to 17.0	20.8 to 10.8	27.81	02/14/22	Farallon	9.85	17.96
					05/16/22	Farallon	8.42	19.39
					08/08/22	Farallon	8.98	18.83
					11/07/22	Farallon	8.65	19.16
					02/21/23	Farallon	9.38	18.43
					05/08/23	Farallon	8.57	19.24
					08/10/23	Farallon	9.54	18.27
					10/30/23	Farallon	9.48	18.33
FMW-143	9th Ave N ROW, E side	23 to 28	10 to 5	32.69	10/31/19	PES	14.88	17.81
					01/13/20	PES	15.02	17.67
					05/11/20	PES	20.47	12.22
					07/13/20	PES	21.01	11.68
					11/16/20	PES	21.19	11.50
					02/01/21	PES	17.48	15.21
					06/07/21	PES	15.68	17.01
					08/16/21	PES	15.55	17.14
					02/15/22	PES	13.25	19.44
					08/08/22	PES	12.09	20.60
					11/07/22	PES	12.89	19.80
					02/21/23	PES	12.96	19.73
					05/08/23	PES	12.65	20.04
					08/10/23	PES	13.79	18.90
					10/30/23	PES	13.76	18.93
					03/01/24	PES	12.14	20.55
					05/21/24	PES	12.75	19.94
					09/03/24	PES	13.61	18.06
					11/04/24	PES	13.60	19.09

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
FMW-154	Block 38 West	10.0 to 15.0	12.8 to 7.8	22.80	02/14/22	Farallon	6.05	16.75
					05/16/22	Farallon	5.44	17.36
					08/08/22	Farallon	5.20	17.60
					11/07/22	Farallon	5.50	17.30
					02/21/23	Farallon	5.16	17.64
					05/08/23	Farallon	5.12	17.68
					08/10/23	Farallon	5.39	17.41
					10/30/23	Farallon	5.51	17.29
FMW-155	Block 38 West	10.0 to 15.0	15.7 to 10.7	23.9	02/14/22	Farallon	6.94	16.96
					05/16/22	Farallon	6.30	17.60
					08/08/22	Farallon	6.07	17.83
					11/07/22	Farallon	6.50	17.40
					02/21/23	Farallon	6.20	17.70
					05/08/23	Farallon	5.96	17.94
					08/10/23	Farallon	6.41	17.49
					10/30/23	Farallon	6.64	17.26
FMW-156	Block 38 West	15.0 to 20.0	10.7 to 5.7	25.7	02/14/22	Farallon	8.63	17.07
					05/16/22	Farallon	8.03	17.67
					08/08/22	Farallon	7.78	17.92
					11/07/22	Farallon	8.28	17.42
					02/21/23	Farallon	7.94	17.76
					05/08/23	Farallon	7.67	18.03
					08/10/23	Farallon	8.18	17.52
					10/30/23	Farallon	8.25	17.45
G12	Property, NE quadrant	10 to 40	29.4 to -0.6	39.40	03/20/17	PES	5.29	34.11
					03/24/17	PES	5.74	33.66
					04/14/17	PES	5.89	33.51
					04/28/17	PES	7.10	32.30
					05/05/17	PES	7.18	32.22
					05/12/17	PES	7.89	31.51
					05/19/17	PES	8.32	31.08
					06/30/17	PES	13.58	25.82
					10/11/17	PES	18.68	20.72
					03/14/19	PES	5.85	33.55
					Decommissioned March 2019			
G-MW2	Property	8 to 18	–	–	07/24/01	GeoEngineers	9.93	
					01/29/09	DOF	10.76	
					06/02/11	SES	7.45	31.50
					02/07/12	Windward	8.49	30.46
					09/06/12	SES	10.53	28.47
					12/21/12	SES	9.63	29.37
					03/29/13	SES	8.56	30.44
					Decommissioned			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-1S	SDOT Mercer Parcels, NE quadrant	20.0 to 30.0	16.0 to 6.0	35.73	03/20/19	HC	16.11	19.62
					03/26/19	HC	16.21	19.52
					07/16/19	HC	16.85	18.88
					12/05/19	HC	18.89	16.84
					01/13/20	HC	22.80	12.93
					03/19/20	HC	24.53	11.20
					05/11/20	HC	26.44	9.29
					07/13/20	HC	Dry	
					11/16/20	PES	Dry	
					02/01/21	HC	20.78	14.95
					06/07/21	PES	19.43	16.30
					08/16/21	PES	19.27	16.46
					02/14/22	PES	16.62	19.11
					05/16/22	PES	15.82	19.91
					08/08/22	PES	16.14	19.59
					11/07/22	PES	17.04	18.69
					02/21/23	PES	Inaccessible	
					05/08/23	PES	15.64	20.09
					08/10/23	PES	16.99	18.74
					10/30/23	PES	16.80	18.93
					03/01/24	PES	15.03	20.70
HMW-2S	SDOT Mercer Parcels, NE quadrant	19.8 to 29.8	27.6 to 17.6	47.28	03/19/19	HC	21.68	25.60
					03/26/19	HC	24.21	23.07
					07/16/19	HC	23.98	23.30
					12/05/19	HC	25.87	21.41
					01/13/20	HC	23.45	23.83
					03/19/20	HC	24.98	22.30
					05/11/20	HC	25.82	21.46
					07/13/20	HC	26.61	20.67
					11/16/20	PES	24.08	23.20
					02/01/21	HC	21.95	25.33
					06/07/21	PES	23.49	23.79
					08/16/21	PES	24.13	23.15
					02/14/22	PES	22.03	25.25
					05/16/22	PES	22.37	24.91
					08/08/22	PES	23.20	24.08
					11/07/22	PES	23.67	23.61
					02/22/23	PES	28.05	19.23
					05/08/23	PES	27.83	19.45
					08/10/23	PES	20.71	26.57
					10/30/23	PES	28.67	18.61
					03/01/24	PES	27.75	19.53

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-9S	SDOT Mercer Parcels, SW quadrant	25.0 to 35.0	30.4 to 20.4	58.54	03/19/20	HC	33.25	25.29
					05/11/20	HC	33.61	24.93
					07/13/20	HC	33.94	24.60
					11/16/20	PES	33.44	25.10
					02/01/21	HC	31.78	26.76
					06/07/21	PES	32.66	25.88
					08/16/21	PES	33.00	25.54
					02/14/22	PES	31.52	27.02
					05/16/22	PES	31.92	26.62
					08/08/22	PES	32.78	25.76
					11/07/22	PES	33.22	25.32
					02/22/23	PES	32.29	26.25
					05/08/23	PES	32.45	26.09
					08/10/23	PES	32.98	25.56
					10/30/23	PES	32.76	25.78
					03/01/24	PES	31.36	27.18
HMW-10S	SDOT Mercer Parcels, SE quadrant	24.7 to 34.7	23.5 to 13.5	51.09	03/19/20	HC	26.37	24.72
					05/11/20	HC	27.11	23.98
					07/13/20	HC	27.83	23.26
					11/16/20	PES	28.12	22.97
					02/01/21	HC	23.91	27.18
					06/07/21	PES	26.04	25.05
					08/16/21	PES	26.41	24.68
					02/14/22	PES	24.03	27.06
					05/16/22	PES	24.40	26.69
					08/08/22	PES	25.74	25.35
					11/07/22	PES	26.13	24.96
					02/22/23	PES	24.35	26.74
					05/08/23	PES	24.70	26.39
					08/10/23	PES	26.07	25.02
					10/30/23	PES	26.40	24.69
					03/01/24	PES	23.37	27.72
HMW-11S	SDOT Mercer Parcels, SE quadrant	25.0 to 35.0	16.5 to 6.5	44.77	03/19/20	HC	35.50	9.27
					05/11/20	HC	37.15	7.62
					07/13/20	HC	37.80	6.97
					11/16/20	PES	37.54	7.23
					02/01/21	HC	32.53	12.24
					06/07/21	PES	23.40	21.37
					08/16/21	PES	21.11	23.66
					02/14/22	PES	25.48	19.29
					05/16/22	PES	25.77	19.00
					08/08/22	PES	25.83	18.94
					05/08/23	PES	24.43	20.34
					08/10/23	PES	26.42	18.35
					10/30/23	PES	26.37	18.40
					03/01/24	PES	24.97	19.80

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-17S	SDOT Mercer Parcels, NW quadrant	35.0 to 45.0	22.2 to 12.2	57.35	11/16/20	PES	28.64	28.71
					06/07/21	PES	26.37	30.98
					08/16/21	PES	27.04	30.31
					02/14/22	PES	23.77	33.58
					05/16/22	PES	29.49	27.86
					08/08/22	PES	31.37	25.98
					11/07/22	PES	31.46	25.89
					02/22/23	PES	29.83	27.52
					05/08/23	PES	30.13	27.22
					08/10/23	PES	30.94	26.41
					10/30/23	PES	31.61	25.74
					03/01/24	PES	28.73	28.62
HMW-18S	SDOT Mercer Parcels, NW quadrant	35.0 to 45.0	22.6 to 12.6	57.44	11/16/20	PES	29.28	28.16
					06/07/21	PES	27.05	30.39
					08/16/21	PES	27.65	29.79
					02/14/22	PES	24.87	32.57
					05/08/23	PES	30.37	27.07
					08/10/23	PES	31.17	26.27
					10/30/23	PES	30.89	26.55
					03/01/24	PES	34.60	22.84
HMW-19S	SDOT Mercer Parcels, NW quadrant	35.0 to 45.0	23.2 to 13.2	61.08	11/16/20	PES	33.61	27.47
					06/07/21	PES	31.77	29.31
					08/16/21	PES	32.35	28.73
					02/14/22	PES	25.91	35.17
					05/16/22	PES	33.03	28.05
					08/08/22	PES	34.86	26.22
					11/07/22	PES	35.21	25.87
					02/22/23	PES	33.80	27.28
					05/08/23	PES	30.04	31.04
					08/10/23	PES	34.82	26.26
					10/30/23	PES	34.62	26.46
					03/01/24	PES	32.66	28.42
HMW-20S	SDOT Mercer Parcels, NW quadrant	25.0 to 35.0	28.8 to 18.8	56.49	11/16/20	PES	31.71	24.78
					06/07/21	PES	30.63	25.86
					02/14/22	PES	29.54	26.95
					05/16/22	PES	–	
					05/08/23	PES	30.03	26.46
					08/10/23	PES	NM	–
					10/30/23	PES	26.20	30.29
HMW-21S	SDOT Mercer Parcels, SE quadrant	30.0 to 40.0	8.2 to -1.8	37.92	11/16/20	PES	30.41	7.51
					06/07/21	PES	22.32	15.60
					02/14/22	PES	19.40	18.52
					10/30/23	PES	19.62	18.30

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-22S	SDOT Mercer Parcels, SE quadrant	27.0 to 37.0	11.7 to 1.8	38.58	11/16/20	PES	31.37	7.21
					06/07/21	PES	23.14	15.44
					08/16/21	PES	22.90	15.68
					02/14/22	PES	20.10	18.48
					05/16/22	PES	19.68	18.90
					08/08/22	PES	19.67	18.91
					02/22/23	PES	19.65	18.93
					08/10/23	PES	20.32	18.26
					10/30/23	PES	20.29	18.29
					03/01/24	PES	NM	
J5	Property, SW quadrant	10 to 40	29.8 to -0.2	39.95	03/20/17	PES	2.16	37.79
					03/24/17	PES	2.64	37.31
					04/14/17	PES	2.71	37.24
					04/28/17	PES	3.87	36.08
					05/05/17	PES	3.71	36.24
					05/12/17	PES	4.41	35.54
					05/19/17	PES	4.88	35.07
					06/12/17	PES	8.13	31.82
					10/11/17	PES	15.15	24.80
					03/14/19	PES	–	
					Decommissioned March 2019			
J15	Property, SE quadrant	10 to 40	28.7 to -1.3	38.85	03/20/17	PES	4.90	33.95
					03/24/17	PES	5.35	33.50
					04/14/17	PES	5.55	33.30
					04/28/17	PES	6.82	32.03
					05/05/17	PES	6.82	32.03
					05/12/17	PES	6.74	32.11
					05/19/17	PES	6.24	32.61
					06/12/17	PES	11.30	27.55
					10/11/17	PES	18.29	20.56
					03/14/19	PES	5.05	33.80
					Decommissioned March 2019			
K8	Property, SW quadrant	10 to 40	29.9 to -0.1	40.39	03/20/17	PES	2.97	37.42
					03/24/17	PES	3.77	36.62
					04/14/17	PES	3.70	36.69
					04/28/17	PES	5.10	35.29
					05/05/17	PES	5.15	35.24
					05/12/17	PES	5.99	34.40
					05/19/17	PES	6.47	33.92
					06/12/17	PES	10.11	30.28
					10/11/17	PES	17.17	23.22
					03/14/19	PES	–	
					Decommissioned March 2019			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
M15	Property, SE quadrant	10 to 40	29.5 to -0.5	39.82	03/20/17	PES	5.22	34.60
					03/24/17	PES	5.75	34.07
					04/14/17	PES	5.97	33.85
					04/28/17	PES	7.24	32.58
					05/05/17	PES	7.40	32.42
					05/12/17	PES	7.93	31.89
					05/19/17	PES	8.47	31.35
					06/12/17	PES	11.53	28.29
					10/11/17	PES	18.44	21.38
					03/14/19	PES	5.05	34.77
Decommissioned March 2019								
MW-1	Block 55, N end	25.0 to 35.0	29.8 to 19.8	54.77	02/14/22	Farallon	27.18	27.59
					05/16/22	Farallon	27.25	27.52
					08/08/22	Farallon	27.21	27.56
					11/07/22	Farallon	26.06	28.71
					02/21/23	Farallon	27.14	27.63
					05/08/23	Farallon	27.01	27.76
					08/10/23	Farallon	27.66	27.11
					10/30/23	Farallon	28.16	26.61
MW-1	800 Aloha Street Street Parcel	17.5 to 37.5	—	—	06/17/93	Retec	16.10	
Decommissioned on October 12, 1993								
MW-2	Block 55, N end	30.0 to 40.0	aw	58.54	02/14/22	Farallon	30.46	28.08
					05/16/22	Farallon	30.57	27.97
					08/08/22	Farallon	30.72	27.82
					11/07/22	Farallon	31.46	27.08
					02/21/23	Farallon	30.37	28.17
					05/08/23	Farallon	30.54	28.00
					08/10/23	Farallon	31.18	27.36
					10/30/23	Farallon	31.24	27.30
MW-2	9th Avenue North ROW	27.5 to 37.5	—	—	06/17/93	Retec	15.55	
Decommissioned on October 12, 1993								
MW-3	800 Aloha Street Parcel	17.5 to 37.5	—	—	06/17/93	Retec	15.17	
Decommissioned on October 12, 1993								
MW-3	Block 55, N end	38.0 to 48.0	21.6 to 11.6	59.59	02/14/22	Farallon	30.64	28.95
					05/16/22	Farallon	31.06	28.53
					08/08/22	Farallon	31.37	28.22
					11/07/22	Farallon	32.32	27.27
					02/21/23	Farallon	30.78	28.81
					05/08/23	Farallon	31.11	28.48
					08/10/23	Farallon	32.00	27.59
					10/30/23	Farallon	32.02	27.57
MW-4	800 Aloha Street Parcel	22.5 to 32.5	—	—	06/17/93	Retec	15.80	
Decommissioned on October 12, 1993								
MW-4	Block 55, N end	30.0 to 40.0	21.16 to 11.16	52.16	02/14/22	Farallon	24.00	28.16
					05/16/22	Farallon	24.29	27.87
					08/08/22	Farallon	24.81	27.35
					11/07/22	Farallon	25.26	26.90
					02/21/23	Farallon	29.94	22.22
					05/08/23	Farallon	24.50	27.66
					08/10/23	Farallon	25.11	27.05
					10/30/23	Farallon	18.95	33.21

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-5	8th Avenue North ROW	12.5 to 22.5	–	–	06/17/93	Retec	14.57	
					Decommissioned on October 12, 1993			
MW-5	Block 55	20.0 to 30.0	37.4 to 27.4	57.41	02/14/22	Farallon	28.71	28.70
					05/16/22	Farallon	29.01	28.40
					08/08/22	Farallon	29.30	28.11
					11/07/22	Farallon	20.81	36.60
					02/21/23	Farallon	28.63	28.78
					05/08/23	Farallon	28.82	28.59
					08/10/23	Farallon	29.52	27.89
					10/30/23	Farallon	29.56	27.85
MW-6	800 Aloha Street Parcel	7 to 22	–	58.76	10/26/93	Retec	16.79	41.97
					01/25/94	Retec	17.43	41.33
					04/25/94	Retec	15.75	43.01
					09/15/94	Retec	16.61	42.15
MW-7	800 Aloha Street Parcel	9 to 18.5	–	38.20	02/07/12	Windward	14.91	23.29
				55.82	10/26/93	Retec	14.10	41.72
					01/25/94	Retec	15.30	40.52
					04/25/94	Retec	13.40	42.42
					09/15/94	Retec	14.29	41.53
				35.09	02/07/12	Windward	12.56	22.53
MW-8	800 Aloha Street Parcel	4.5 to 19	28.7 to 14.2	53.72	10/26/93	Retec	12.35	41.37
					01/25/94	Retec	13.51	40.21
					04/25/94	Retec	11.80	41.92
					09/15/94	Retec	12.49	41.23
				33.19	02/07/12	Windward	11.64	21.55
					03/20/17	PES	10.42	22.77
					03/24/17	PES	10.54	22.65
					06/12/17	PES	18.95	14.24
					03/14/19	PES	11.23	21.96
					04/22/19	PES	11.18	22.01
					07/16/19	PES	11.97	21.22
					10/21/19	PES	12.46	20.73
					01/13/20	PES	12.15	21.04
					05/11/20	PES	17.12	16.07
					07/13/20	PES	17.95	15.24
					11/16/20	PES	16.84	16.35
					02/02/21	PES	12.74	20.45
					06/01/21	PES	13.66	19.53
					08/17/21	PES	14.01	19.18
					02/15/22	PES	11.47	21.72
					05/16/22	PES	10.34	22.85
					08/08/22	PES	11.79	21.40
					11/07/22	PES	11.32	21.87
					02/21/23	PES	11.00	22.19
					05/08/23	PES	10.81	22.38
					08/10/23	PES	12.57	20.62
					10/30/23	PES	11.92	21.27
					02/28/24	PES	10.90	22.29
					05/20/24	PES	11.36	21.83
					09/03/24	PES	12.18	21.01
					11/05/24	PES	11.66	21.53

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-9	8th Ave N ROW, E side	7 to 22	34.1 to 19.1	61.35	01/25/94	Retec	15.51	45.84
				40.81	04/25/94	Retec	17.09	44.26
					09/15/94	Retec	15.50	45.85
					06/20/02	Urban	18.30	22.51
					06/02/11	SES	14.89	25.92
					02/07/12	Windward	16.39	24.42
					09/04/12	SES	16.84	23.97
					12/21/12	SES	15.94	24.87
					01/06/14	SES	13.99	26.82
					03/20/17	PES	13.33	27.48
					03/24/17	PES	13.32	27.49
					04/14/17	PES	13.59	27.22
					04/28/17	PES	15.60	25.21
					05/05/17	PES	15.68	25.13
					05/12/17	PES	16.54	24.27
					05/19/17	PES	16.78	24.03
					06/12/17	PES	19.91	20.90
					10/11/17	PES	21.80	19.01
					03/14/19	PES	13.81	27.00
					04/22/19	PES	13.93	26.88
				40.74	07/16/19	PES	15.27	25.54
					08/19/19	PES	18.32	22.49
					10/21/19	PES	20.77	19.97
					01/13/20	PES	21.58	19.16
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					08/04/20	PES	21.01	19.73
					08/17/20	PES	20.54	20.20
					09/03/20	PES	20.45	20.29
					09/21/20	PES	20.55	20.19
					11/16/20	PES	19.78	20.96
					02/01/21	PES	17.54	23.20
					06/07/21	PES	15.80	24.94
					08/16/21	PES	16.79	23.95
					02/14/22	PES	14.42	26.32
					05/16/22	PES	15.49	25.25
					08/08/22	PES	15.84	24.90
					11/07/22	PES	16.69	24.05
					02/21/23	PES	15.91	24.83
					05/08/23	PES	16.15	24.59
					08/10/23	PES	16.47	24.27
					10/30/23	PES	16.51	24.23
					03/01/24	PES	15.01	25.73
					05/20/24	PES	15.91	24.83
					09/03/24	PES	15.23	25.51
					11/04/24	PES	Inaccessible	
MW-10	800 Aloha Street Parcel	7 to 22	—	58.53	01/25/94	Retec	15.09	43.44
				37.95	04/25/94	Retec	16.64	41.89
					09/15/94	Retec	16.64	41.89
					06/20/02	Urban	16.55	41.98
					02/07/12	Windward	15.85	22.10

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-45	Block 37, SE quadrant	3.0 to 19.0	24.5 to 8.5	27.52	02/14/22	Farallon	9.57	17.95
					05/16/22	Farallon	8.25	19.27
					08/08/22	Farallon	9.26	18.26
					11/07/22	Farallon	8.32	19.20
					02/21/23	Farallon	9.36	18.16
					05/08/23	Farallon	8.74	18.78
					08/10/23	Farallon	9.74	17.78
					10/30/23	Farallon	9.49	18.03
MW-50	Block 37, SE quadrant	5.0 to 17.5	24.3 to 11.8	29.32	02/14/22	Farallon	10.23	19.09
					05/16/22	Farallon	10.54	18.78
					08/08/22	Farallon	10.80	18.52
					11/07/22	Farallon	10.89	18.43
					02/21/23	Farallon	10.69	18.63
					05/08/23	Farallon	19.13	10.19
					08/10/23	Farallon	11.15	18.17
					10/30/23	Farallon	11.05	18.27
MW-54	Block 37, SE quadrant	5.0 to 20.0	23.0 to 8.0	28.00	02/14/22	Farallon	10.18	17.82
					05/16/22	Farallon	8.80	19.20
					08/08/22	Farallon	9.05	18.95
					11/07/22	Farallon	9.18	18.82
					02/21/23	Farallon	9.69	18.31
					05/08/23	Farallon	8.79	19.21
					08/10/23	Farallon	9.70	18.30
					10/30/23	Farallon	9.69	18.31
MW121	8th Ave N ROW, E side	15 to 25	26.7 to 16.7	41.72	01/06/14	SES	18.69	23.03
					03/20/17	PES	12.25	29.47
					03/24/17	PES	11.09	30.63
					04/14/17	PES	11.24	30.48
					04/28/17	PES	11.65	30.07
					05/05/17	PES	12.36	29.36
					05/12/17	PES	11.75	29.97
					05/19/17	PES	11.61	30.11
					06/12/17	PES	14.35	27.37
					10/11/17	PES	21.67	20.05
					03/14/19	PES	10.86	30.86
					04/22/19	PES	11.58	30.14
					07/16/19	PES	17.95	23.77
					08/19/19	PES	22.95	18.77
					10/21/19	PES	24.23	17.49
					01/13/20	PES	24.22	17.50
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					07/21/20	PES	24.30	17.42
					08/04/20	PES	24.30	17.42
					08/17/20	PES	24.33	17.39
					09/03/20	PES	24.30	17.42
					09/21/20	PES	24.40	17.32
					11/17/20	PES	19.67	22.05
					02/01/21	PES	16.86	24.86
					06/07/21	PES	16.75	24.97
					08/16/21	PES	Inaccessible	
					02/14/22	PES	15.53	26.19

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW121 Continued					05/16/22	PES	16.92	24.80
					08/08/22	PES	16.89	24.83
					11/07/22	PES	18.38	23.34
					02/21/23	PES	16.23	25.49
					05/08/23	PES	16.94	24.78
					08/10/23	PES	Inaccessible	
					10/30/23	PES	Inaccessible	
					03/01/24	PES	15.63	26.09
					05/20/24	PES	17.09	24.63
					09/03/24	PES	17.68	24.04
					11/04/24	PES	12.69	29.03
MW125	Valley St ROW, ROW, N side	15 to 30	28.6 to 13.6	43.55	01/06/14	SES	24.18	19.37
					03/20/17	PES	14.40	29.15
					03/24/17	PES	14.55	29.00
					06/28/17	PES	22.20	21.35
					10/11/17	PES	26.39	17.16
					03/14/19	PES	15.59	27.96
					04/22/19	PES	14.95	28.60
					07/16/19	PES	18.30	25.25
					08/19/19	PES	25.96	17.59
					10/21/19	PES	27.26	16.29
					01/13/20	PES	27.85	15.70
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					07/21/20	PES	Inaccessible	
					08/17/20	PES	25.15	18.40
					09/03/20	PES	24.68	18.87
					09/21/20	PES	Inaccessible	
					11/16/20	PES	20.90	22.65
					02/01/21	PES	18.07	25.48
					06/07/21	PES	18.00	25.55
					08/16/21	PES	18.49	25.06
					02/14/22	PES	16.69	26.86
					05/16/22	PES	17.70	25.85
					08/08/22	PES	18.15	25.40
					11/07/22	PES	19.03	24.52
					02/21/23	PES	18.13	25.42
					05/08/23	PES	18.42	25.13
					08/10/23	PES	19.03	24.52
					10/30/23	PES	18.56	24.99
					03/01/24	PES	17.67	25.88
					05/20/24	PES	18.17	25.38
					09/04/24	PES	17.02	26.53
					11/04/24	PES	18.03	25.52
MW-154	Roy St ROW, S side	25 to 35	28.1 to 18.1	52.57	03/14/19	PES	20.81	31.76
					03/26/19	HC	21.94	30.63
					04/22/19	PES	22.40	30.17
					07/16/19	PES	27.03	25.54
					07/17/19	HC	27.02	25.55
					08/19/19	PES	28.80	23.77
					10/21/19	PES	30.16	22.41
					01/13/20	PES	29.30	23.27

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-154					03/19/20	HC	29.10	23.47
					05/11/20	PES	29.44	23.13
					07/13/20	PES	30.05	22.52
					07/21/20	PES	29.76	22.81
					08/04/20	PES	29.56	23.01
					08/17/20	PES	29.41	23.16
					09/03/20	PES	29.15	23.42
					09/21/20	PES	28.98	23.59
					11/16/20	PES	25.44	27.13
					02/01/21	PES	22.04	30.53
					06/07/21	PES	24.55	28.02
					08/16/21	PES	24.98	27.59
					02/14/22	PES	22.03	30.54
					05/16/22	PES	23.60	28.97
					08/08/22	PES	25.35	27.22
					11/07/22	PES	25.67	26.90
					02/22/23	PES	24.21	28.36
					05/08/23	PES	24.83	27.74
					08/10/23	PES	25.78	26.79
					10/30/23	PES	25.33	27.24
					03/01/24	PES	22.97	29.60
					05/20/24	PES	25.14	27.43
					09/03/24	PES	25.89	26.68
					11/04/24	PES	25.34	27.23
MW-155	Roy St ROW, S side	20 to 30	24.4 to 14.4	44.05	03/14/19	PES	16.80	27.25
					03/26/19	HC	17.20	26.85
					04/22/19	PES	17.95	26.10
					07/16/19	PES	20.94	23.11
					08/19/19	PES	22.38	21.67
					10/21/19	PES	24.54	19.51
					01/13/20	PES	22.55	21.50
					02/19/20	PES	20.38	23.67
					03/19/20	HC	23.10	20.95
					05/11/20	PES	24.31	19.74
					07/13/20	PES	25.17	18.88
					07/21/20	PES	25.05	19.00
					08/04/20	PES	24.90	19.15
					08/17/20	PES	24.74	19.31
					09/03/20	PES	24.55	19.50
					09/21/20	PES	24.53	19.52
					11/16/20	PES	22.55	21.50
					02/01/21	PES	Inaccessible	
					06/07/21	PES	Inaccessible	
					08/16/21	PES	21.03	23.02
					02/14/22	PES	17.53	26.52
					05/16/22	PES	18.52	25.53
					08/08/22	PES	19.82	24.23
					11/07/22	PES	20.78	23.27
					02/21/23	PES	18.29	25.76
					05/08/23	PES	19.20	24.85
					08/10/23	PES	20.94	23.11
					10/30/23	PES	20.62	23.43

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-155					03/01/24	PES	17.70	26.35
					05/20/24	PES	20.01	24.04
					09/03/24	PES	21.00	23.05
					11/04/24	PES	20.62	23.43
MW-159	8th Ave N ROW, E side	20 to 30	22.9 to 12.9	42.79	03/14/19	PES	14.70	28.09
					04/22/19	PES	15.67	27.12
					07/16/19	PES	20.55	22.24
					08/19/19	PES	25.60	17.19
					10/21/19	PES	29.34	13.45
					01/13/20	PES	29.35	13.44
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					07/21/20	PES	Dry	
					08/04/20	PES	28.65	14.14
					08/17/20	PES	27.30	15.49
					09/03/20	PES	26.65	16.14
					09/21/20	PES	26.31	16.48
					11/16/20	PES	22.27	20.52
					02/01/21	PES	18.91	23.88
					06/07/21	PES	19.73	23.06
					08/16/21	PES	19.86	22.93
					02/14/22	PES	17.37	25.42
					05/16/22	PES	18.22	24.57
					08/08/22	PES	18.99	23.80
					11/07/22	PES	19.89	22.90
					02/21/23	PES	18.63	24.16
					05/08/23	PES	18.84	23.95
					08/10/23	PES	20.02	22.77
					10/30/23	PES	19.39	23.40
					03/01/24	PES	18.21	24.58
					05/20/24	PES	18.99	23.80
					09/03/24	PES	19.47	23.32
					11/04/24	PES	19.17	23.62
MW-209	Valley St ROW, N side (Block 37)	5.0 to 20.0	6.9 to 21.9	26.88	02/14/22	Farallon	9.62	17.26
					05/16/22	Farallon	7.87	19.01
					08/08/22	Farallon	8.57	18.31
					11/07/22	Farallon	8.96	17.92
					02/21/23	Farallon	9.20	17.68
					05/08/23	Farallon	7.99	18.89
					08/10/23	Farallon	9.23	17.65
					10/30/23	Farallon	9.24	17.64
MW-210	Valley St ROW, N side	10 to 20	17.1 to 7.1	26.57	03/20/17	PES	–	–
					03/24/17	PES	17.75	8.82
					06/12/17	PES	10.95	15.62
					10/11/17	PES	12.71	13.86
					03/14/19	PES	8.59	17.98
					04/22/19	PES	8.71	17.86
					07/16/19	PES	8.22	18.35
					10/21/19	PES	8.62	17.95
					01/13/20	PES	8.95	17.62
					05/11/20	PES	9.30	17.27
					07/13/20	PES	9.55	17.02

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-210 Continued					11/16/20	PES	9.91	16.66
					02/01/21	PES	9.69	16.88
					06/07/21	PES	8.23	18.34
					08/16/21	PES	9.13	17.44
					02/14/22	PES	9.62	16.95
MW-210	Valley St ROW, N side (Block 37)	5.0 to 20.0	6.6 to 21.6	26.56	02/14/22	Farallon	9.08	17.48
					05/16/22	PES	7.83	18.74
					05/16/22	Farallon	7.36	19.20
					08/08/22	PES	8.08	18.49
					08/08/22	Farallon	8.11	18.45
					11/07/22	PES	8.36	18.21
					11/07/22	Farallon	8.38	18.18
					02/21/23	Farallon	8.66	17.90
					05/08/23	Farallon	7.51	19.05
					08/10/23	Farallon	8.80	17.76
					10/30/23	Farallon	8.78	17.78
					06/04/24	PES	7.22	19.34
					09/03/24	PES	8.50	18.06
					11/04/24	PES	8.36	18.20
MW-211	Valley St ROW, N side (Block 37)	5.0 to 20.0	6.5 to 21.5	26.48	02/14/22	Farallon	8.99	17.49
					05/16/22	Farallon	7.42	19.06
					08/08/22	Farallon	8.02	18.46
					11/07/22	Farallon	8.20	18.28
					02/21/23	Farallon	8.39	18.09
					05/08/23	Farallon	7.47	19.01
					08/10/23	Farallon	8.82	17.66
					10/30/23	Farallon	8.80	17.68
MW-212	Mercer St ROW, N side (Block 37)	10.0 to 25.0	4.1 to 19.1	29.09	02/14/22	Farallon	11.01	18.08
					05/16/22	Farallon	10.61	18.48
					08/08/22	Farallon	–	–
					11/07/22	Farallon	11.15	17.94
					02/21/23	Farallon	–	–
					05/08/23	Farallon	10.32	18.77
					08/10/23	Farallon	11.39	17.70
					10/30/23	Farallon	10.87	18.22
MW-213	Valley St ROW, S side (Block 37)	5.0 to 20.0	–	27.35	02/14/22	Farallon	9.36	17.99
					05/16/22	Farallon	7.95	19.40
					08/08/22	Farallon	8.76	18.59
					11/07/22	Farallon	9.07	18.28
					02/21/23	Farallon	8.90	18.45
					05/08/23	Farallon	8.12	19.23
					08/10/23	Farallon	9.54	17.81
					10/30/23	Farallon	9.31	18.04
MW-214	Valley St ROW, S side	7 to 17	20.8 to 10.8	27.32	03/20/17	PES	6.84	20.48
					03/24/17	PES	7.67	19.65
					06/12/17	PES	16.45	10.87
					10/11/17	PES	Dry	
					03/14/19	PES	8.92	18.40
					04/22/19	PES	9.03	18.29
					07/16/19	PES	8.97	18.35
					10/21/19	PES	9.54	17.78

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-214 Continued					01/13/20	PES	9.74	17.58
					05/11/20	PES	13.40	13.92
					07/13/20	PES	13.70	13.62
					11/16/20	PES	13.75	13.57
					02/01/21	PES	11.56	15.76
					06/07/21	PES	9.35	17.97
					08/16/21	PES	10.37	16.95
					02/14/22	PES	9.35	17.97
					05/16/22	PES	7.58	19.74
					08/08/22	PES	8.75	18.57
					11/07/22	PES	8.97	18.35
					02/21/23	PES	8.91	18.41
					05/08/23	PES	7.96	19.36
					08/10/23	PES	9.50	17.82
					10/30/23	PES	9.25	18.07
					03/01/24	PES	10.62	16.70
					05/21/24	PES	8.30	19.02
					09/03/24	PES	9.34	17.98
					11/04/24	PES	Inaccessible	
MW-301	Valley St ROW, S side	18.2 to 28.3	35.6 to 25.65	53.54	10/21/19	PES	Dry	
					07/13/20	PES	Inaccessible	
					07/21/20	PES	Inaccessible	
					08/04/20	PES	Dry	
					08/17/20	PES	Dry	
					09/03/20	PES	Dry	
					09/21/20	PES	Dry	
					11/16/20	PES	22.26	31.28
					02/01/21	PES	19.90	33.64
					06/07/21	PES	21.51	32.03
					08/16/21	PES	21.77	31.77
					02/14/22	PES	19.85	33.69
					05/16/22	PES	21.49	32.05
					08/08/22	PES	22.54	31.00
					11/07/22	PES	22.63	30.91
					02/21/23	PES	21.13	32.41
					05/08/23	PES	21.97	31.57
					08/10/23	PES	23.32	30.22
					10/30/23	PES	21.30	32.24
					03/01/24	PES	20.40	33.14
					05/20/24	PES	22.20	31.34
					09/03/24	PES	21.56	31.98
					11/04/24	PES	21.65	31.89
MW-305	Roy St ROW, S side	22.8 to 32.8	37.4 to 27.4	59.86	10/21/19	PES	28.17	31.69
					01/13/20	PES	27.85	32.01
					03/19/20	HC	23.83	36.03
					05/11/20	PES	25.26	34.60
					07/13/20	PES	26.44	33.42
					07/21/20	PES	26.50	33.36
					08/04/20	PES	26.75	33.11
					08/17/20	PES	26.92	32.94
					09/03/20	PES	27.31	32.55
					09/21/20	PES	28.05	31.81

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-305 Continued					11/17/20	PES	28.23	31.63
					02/01/21	PES	21.23	38.63
					06/07/21	PES	23.61	36.25
					08/16/21	PES	24.78	35.08
					02/14/22	PES	19.16	40.70
					05/16/22	PES	25.81	34.05
					11/07/22	PES	Dry	
					02/21/23	PES	Dry	
					05/08/23	PES	32.40	27.46
					08/10/23	PES	32.57	27.29
					10/30/23	PES	Not Measured	
					03/01/24	PES	20.55	39.31
					05/20/24	PES	32.34	27.52
					09/03/24	PES	32.57	27.29
					11/04/24	PES	32.60	27.26
MW-310	Alley E of Seattle Roy Aloha Shops	13.7 to 23.7	19.2 to 9.2	32.48	10/21/19	PES	13.67	18.81
					01/13/20	PES	14.71	17.77
					05/11/20	PES	19.70	12.78
					07/13/20	PES	20.56	11.92
					11/16/20	PES	19.32	13.16
					02/01/21	PES	14.17	18.31
					06/07/21	PES	12.61	19.87
					08/16/21	PES	13.25	19.23
					02/14/22	PES	9.01	23.47
					05/16/22	PES	9.21	23.27
					08/08/22	PES	10.11	22.37
					11/07/22	PES	11.30	21.18
					02/21/23	PES	9.32	23.16
					05/08/23	PES	9.44	23.04
					08/10/23	PES	11.46	21.02
					10/30/23	PES	13.91	18.57
					02/28/24	PES	9.04	23.44
					05/20/24	PES	9.99	22.49
					09/03/24	PES	11.15	21.33
					11/04/24	PES	10.86	21.62
MW-312	Alley E of Seattle Roy Aloha Shops	15.7 to 25.7	19.9 to 9.9	34.99	10/21/19	PES	15.66	19.33
					01/13/20	PES	15.97	19.02
					05/11/20	PES	22.37	12.62
					07/13/20	PES	23.34	11.65
					07/21/20	PES	23.47	11.52
					08/04/20	PES	23.71	11.28
					08/17/20	PES	23.81	11.18
					09/03/20	PES	23.94	11.05
					09/21/20	PES	Inaccessible	
					11/16/20	PES	22.85	12.14
					02/01/21	PES	14.94	20.05
					06/07/21	PES	15.74	19.25
					08/16/21	PES	16.13	18.86
					02/14/22	PES	11.25	23.74
					05/16/22	PES	11.32	23.67
					08/08/22	PES	13.01	21.98

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-312 Continued					11/07/22	PES	14.22	20.77
					02/21/23	PES	11.71	23.28
					05/08/23	PES	11.82	23.17
					08/10/23	PES	14.24	20.75
					10/30/23	PES	14.15	20.84
					02/28/24	PES	11.39	23.60
					05/20/24	PES	12.78	22.21
					09/03/24	PES	14.12	20.87
					11/04/24	PES	14.31	20.68
MW-313	Alley E of Seattle Roy Aloha Shops	19.4 to 29.4	20.4 to 10.4	39.53	10/21/19	PES	22.34	17.19
					01/13/20	PES	23.57	15.96
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					11/16/20	PES	Dry	
					02/01/21	PES	25.13	14.40
					06/07/21	PES	22.82	16.71
					08/16/21	PES	22.85	16.68
					02/14/22	PES	19.99	19.54
					05/16/22	PES	19.81	19.72
					08/08/22	PES	20.02	19.51
					11/07/22	PES	20.92	18.61
					02/21/23	PES	20.08	19.45
					05/08/23	PES	19.80	19.73
					08/10/23	PES	20.95	18.58
					10/30/23	PES	20.92	18.61
					02/28/24	PES	19.46	20.07
					05/20/24	PES	20.07	19.46
					09/03/24	PES	20.78	18.75
					11/04/24	PES	20.88	18.65
MW-320	9th Ave N ROW, W side	15.5 to 25.5	18.6 to 8.6	33.57	10/21/19	PES	15.45	18.12
					01/13/20	PES	15.62	17.95
					05/11/20	PES	21.20	12.37
					07/13/20	PES	21.96	11.61
					11/16/20	PES	22.20	11.37
					02/01/21	PES	17.62	15.95
					06/07/21	PES	16.20	17.37
					08/16/21	PES	16.14	17.43
					02/14/22	PES	13.26	20.31
					05/16/22	PES	12.86	20.71
					08/08/22	PES	13.21	20.36
					11/07/22	PES	14.19	19.38
					02/22/23	PES	13.30	20.27
					05/08/23	PES	13.06	20.51
					08/10/23	PES	14.38	19.19
					10/30/23	PES	14.38	19.19
					03/01/24	PES	12.64	20.93
					05/20/24	PES	13.36	20.21
					09/03/24	PES	14.25	19.32
					11/04/24	PES	14.33	19.24

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-332	Roy St ROW, N side	20.3 to 30.3	15.42 to 5.42	35.72	05/11/20	PES	25.58	10.14
					07/13/20	PES	26.07	9.65
					11/16/20	PES	25.97	9.75
					02/01/21	PES	21.05	14.67
					06/07/21	PES	18.95	16.77
					08/16/21	PES	18.93	16.79
					02/14/22	PES	15.67	20.05
					05/16/22	PES	15.44	20.28
					11/07/22	PES	16.54	19.18
					02/21/23	PES	15.49	20.23
					05/08/23	PES	15.24	20.48
					08/10/23	PES	16.59	19.13
					10/30/23	PES	16.84	18.88
					03/01/24	PES	15.14	20.58
					05/20/24	PES	15.33	20.39
MW-337	Lake Union Park, N end	9.7 to 19.7	17.81 to 7.81	27.51	05/11/20	PES	9.12	18.39
					07/13/20	PES	9.41	18.10
					11/16/20	PES	10.30	17.21
					02/01/21	PES	10.19	17.32
					06/07/21	PES	8.70	18.81
					08/16/21	PES	10.03	17.48
					02/14/22	PES	10.37	17.14
					05/16/22	PES	8.29	19.22
					08/08/22	PES	9.34	18.17
					11/07/22	PES	9.41	18.10
					02/21/23	PES	9.80	17.71
					05/08/23	PES	8.99	18.52
					08/10/23	PES	9.98	17.53
					10/30/23	PES	9.96	17.55
					03/01/24	PES	9.45	18.06
MW-339	Lake Union Park, S end	10.1 to 20.1	17.96 to 7.96	28.06	05/11/20	PES	9.95	18.11
					07/13/20	PES	10.26	17.80
					11/16/20	PES	10.74	17.32
					02/01/21	PES	10.20	17.86
					06/07/21	PES	9.15	18.91
					08/16/21	PES	10.56	17.50
					02/14/22	PES	10.91	17.15
					05/16/22	PES	8.56	19.50
					08/08/22	PES	9.80	18.26
					11/07/22	PES	9.04	19.02
					02/21/23	PES	10.39	17.67
					05/08/23	PES	9.22	18.84
					08/10/23	PES	10.53	17.53
					10/30/23	PES	10.38	17.68
					03/01/24	PES	9.31	18.75
					05/20/24	PES	9.11	18.95
					09/03/24	PES	10.16	17.90
					11/04/24	PES	10.26	17.80

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MWR-3	Block 37, SW quadrant	7.0 to 17.0	22.7 to 12.7	29.67	02/14/22	Farallon	10.84	18.83
					05/16/22	Farallon	10.08	19.59
					08/08/22	Farallon	10.88	18.79
					11/07/22	Farallon	10.77	18.90
					02/21/23	Farallon	10.49	19.18
					05/08/23	Farallon	10.31	19.36
					08/10/23	Farallon	11.40	18.27
					10/30/23	Farallon	11.10	18.57
MWR-6	Block 37, SE quadrant	8.0 to 18.0	21.1 to 11.1	29.12	02/14/22	Farallon	11.01	18.11
					05/16/22	Farallon	10.51	18.61
					08/08/22	Farallon	10.70	18.42
					11/07/22	Farallon	11.00	18.12
					02/21/23	Farallon	10.65	18.47
					05/08/23	Farallon	10.36	18.76
					08/10/23	Farallon	11.08	18.04
					10/30/23	Farallon	11.06	18.06
N7	Property, SW quadrant	10 to 40	41.8 to 11.8	52.44	03/20/17	PES	NA	
					03/24/17	PES	NA	
					04/14/17	PES	18.70	33.74
					04/28/17	PES	16.98	35.46
					05/05/17	PES	17.10	35.34
					05/12/17	PES	17.51	34.93
					05/19/17	PES	18.02	34.42
					06/12/17	PES	20.93	31.51
					10/11/17	PES	27.13	25.31
					03/14/19	PES	14.72	
					Decommissioned March 2019			
R-MW1	Property, NE quadrant	4 to 14	–	28.11	10/24/92	Roux	7.15	20.96
				37.78	01/29/09	DOF	10.50	17.61
					02/19/10	SES	10.35	27.43
					06/02/11	SES	7.79	29.99
					02/07/12	Windward	8.98	28.80
					09/05/12	SES	10.11	27.67
					12/21/12	SES	8.44	29.34
					03/29/13	SES	6.72	31.06
					Decommissioned			
R-MW2	Property, NE quadrant	5 to 15	36.7 to 26.7	30.86	10/24/92	Roux	10.04	20.82
				40.53	01/29/09	DOF	12.97	17.89
					02/19/10	SES	12.93	27.60
					06/02/11	SES	10.52	30.01
				41.74	02/07/12	Windward	11.61	30.13
					09/04/12	SES	12.64	29.10
					12/21/12	SES	10.84	30.90
					03/29/13	SES	9.85	31.89
					01/06/14	SES	Dry	
					03/20/17	PES	6.20	35.54
					03/24/17	PES	6.55	35.19
					04/14/17	PES	6.56	35.18
					04/28/17	PES	7.35	34.39
					05/05/17	PES	7.87	33.87
					05/12/17	PES	8.12	33.62
					05/19/17	PES	8.55	33.19

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
R-MW2 Continued					06/12/17 10/11/17 03/14/19	PES PES PES	11.26 Dry 6.39	30.48 35.35
					Decommissioned March 2019			
R-MW3	Property, NE quadrant	7 to 17	34.7 to 24.7	32.04 41.74	10/24/92 01/29/09 02/19/10 06/02/11 02/07/12 09/04/12 12/21/12 03/29/13 01/06/14 03/20/17 03/24/17 04/14/17 04/28/17 05/05/17 05/12/17 05/19/17 06/12/17 10/11/17 03/14/19	Roux DOF SES SES Windward SES SES SES PES PES PES PES PES PES PES PES PES PES	11.29 14.22 14.21 11.77 12.90 14.00 12.09 11.17 16.35 7.34 7.66 7.68 8.46 8.78 9.20 9.48 12.48 16.45 7.41	20.75 17.82 27.53 29.97 28.84 27.74 29.65 30.57 25.39 34.40 34.08 34.06 33.28 32.96 32.54 32.26 29.26 25.29 34.33
					Decommissioned March 2019			
R-MW4	Valley St ROW, S side	15 to 30	–	40.94	10/24/92	Roux	21.99	18.95
					Decommissioned before 2009			
R-MW5	Dexter Ave N ROW, E side	15 to 30	42.4 to 27.4	47.20 57.01 57.03 57.01	10/28/92 01/29/09 02/19/10 06/02/11 02/07/12 09/05/12 12/21/12 03/29/13 12/18/13 03/20/17 03/24/17 06/12/17 10/11/17 03/14/19 04/22/19 07/16/19 10/21/19 01/13/20 05/11/20 07/13/20 11/16/20 02/01/21 06/07/21 08/16/21 02/14/22 05/16/22 08/08/22	Roux DOF SES SES Windward SES SES SES SES PES	22.89 22.80 21.93 20.48 21.61 23.72 22.55 21.72 28.59 17.92 18.29 21.58 26.31 18.18 18.83 25.25 25.95 25.17 26.49 27.46 22.01 19.54 20.56 21.05 19.41 21.67 22.97	24.31 24.40 35.08 36.53 35.40 33.31 34.48 35.31 28.44 39.11 38.74 35.45 30.72 38.85 38.20 31.78 31.06 31.84 30.52 29.55 35.00 37.47 36.45 35.96 37.60 35.34 34.04

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
R-MW5					11/07/22	PES	22.30	34.71
Continued					02/21/23	PES	–	–
					05/08/23	PES	21.44	35.57
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	20.44	36.57
					03/01/24	PES	20.69	36.32
					05/20/24	PES	23.08	33.93
					09/03/24	PES	21.68	35.33
					11/04/24	PES	20.87	36.14
R-MW6	8th Ave N ROW, W side	12 to 22	33.3 to 23.3	35.39	10/28/92	Roux	17.85	17.54
				45.18	01/29/09	DOF	19.15	16.24
					02/19/10	SES	18.25	26.93
					05/03/10	SES	18.25	26.93
				45.28	06/02/11	SES	16.22	28.96
					02/07/12	Windward	14.11	31.07
					09/05/12	SES	19.38	25.90
					12/21/12	SES	15.27	30.01
					03/29/13	SES	17.18	28.10
					01/06/14	SES	22.58	22.70
					03/20/17	PES	11.49	33.79
					03/24/17	PES	11.82	33.46
					04/14/17	PES	12.37	32.91
					04/28/17	PES	13.41	31.87
					05/05/17	PES	13.60	31.68
					05/12/17	PES	13.99	31.29
					05/19/17	PES	14.21	31.07
					06/12/17	PES	17.08	28.20
					10/11/17	PES	Dry	
					03/14/19	PES	12.24	33.04
					04/22/19	PES	Inaccessible	
					07/16/19	PES	Inaccessible	
					05/11/20	PES	Inaccessible	
					07/13/20	PES	Inaccessible	
					09/21/20	PES	21.31	23.97
					10/01/20	PES	20.10	25.18
					11/16/20	PES	Inaccessible	
					02/01/21	PES	12.30	32.98
					06/07/21	PES	16.41	28.87
				44.52	08/16/21	PES	Inaccessible	
					02/14/22	PES	13.78	30.74
					05/16/22	PES	15.50	29.02
					08/08/22	PES	17.05	27.47
					11/07/22	PES	16.36	28.16
					02/21/23	PES	15.99	28.53
					05/08/23	PES	23.33	21.19
					08/10/23	PES	17.86	26.66
					10/30/23	PES	17.17	27.35
					03/01/24	PES	22.17	22.35
					05/20/24	PES	26.53	17.99
					09/03/24	PES	24.10	20.42
					11/04/24	PES	18.61	25.91

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
SCL-MW101	Alley E of Seattle Roy Aloha Shops	5 to 15	25.5 to 15.5	30.46	02/07/12	Windward	7.48	22.98
				30.02	01/06/14	SES	13.09	17.37
					03/20/17	PES	7.00	23.46
					03/24/17	PES	7.08	23.38
					06/14/17	PES	11.50	18.96
					10/11/17	PES	Dry	
					03/14/19	PES	7.64	22.82
					04/22/19	PES	7.55	22.91
					07/16/19	PES	7.90	22.56
					10/21/19	PES	8.85	21.17
					01/13/20	PES	7.87	22.15
					05/11/20	PES	12.46	17.56
					07/13/20	PES	13.95	16.07
					11/16/20	PES	11.32	18.70
					02/01/21	PES	9.57	20.45
					06/07/21	PES	9.60	20.42
					08/16/21	PES	9.89	20.13
					02/14/22	PES	7.09	22.93
					05/16/22	PES	7.22	22.80
					08/08/22	PES	7.71	22.31
					11/07/22	PES	7.86	22.16
					02/21/23	PES	7.35	22.67
					05/08/23	PES	7.38	22.64
					08/10/23	PES	8.23	21.79
					10/30/23	PES	7.94	22.08
					02/28/24	PES	7.22	22.80
					06/04/24	PES	7.44	22.58
					09/03/24	PES	8.44	21.58
					11/04/24	PES	7.97	22.05
SCL-MW102	800 Aloha Street Parcel	–	–	–	02/07/12	Windward	7.89	
SCL-MW105	Alley E of Seattle Roy Aloha Shops	20 to 30	11.1 to 1.1	31.26	02/07/12	Windward	10.46	20.80
				30.77	01/06/14	SES	13.88	17.38
					03/20/17	PES	11.40	19.86
					03/24/17	PES	10.04	21.22
					06/12/17	PES	20.45	10.81
					10/11/17	PES	23.47	7.79
					03/14/19	PES	7.97	23.29
					04/22/19	PES	7.98	23.28
					07/16/19	PES	10.87	20.39
					10/21/19	PES	10.42	20.35
					01/13/20	PES	13.00	17.77
					05/11/20	PES	16.90	13.87
					07/13/20	PES	14.63	16.14
					11/16/20	PES	16.74	14.03
					02/01/21	PES	13.48	17.29
					06/07/21	PES	11.95	18.82
					08/16/21	PES	12.28	18.49
					02/14/22	PES	10.28	20.49
					05/16/22	PES	9.97	20.80
					08/08/22	PES	10.25	20.52
					11/07/22	PES	10.88	19.89

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
SCL-MW105 Continued					02/21/23	PES	10.33	20.44
					05/08/23	PES	9.92	20.85
					08/10/23	PES	11.05	19.72
					10/30/23	PES	10.86	19.91
					02/28/24	PES	9.80	20.97
					05/20/24	PES	10.15	20.62
					09/03/24	PES	10.82	19.95
					11/04/24	PES	10.77	20.00
SCS-1	800 Aloha Street Parcel	–	–	39.55	02/07/12	Windward	17.51	22.04
SCS-2	Seattle Roy Aloha Shops, N end	11 to 21	28.2 to 18.2	39.16	02/07/12	Windward	16.56	22.60
					03/20/17	PES	15.65	23.51
					03/24/17	PES	–	
					06/12/17	PES	20.18	18.98
					03/14/19	PES	16.22	22.94
					04/22/19	PES	16.29	22.87
					07/16/19	PES	17.04	22.12
					10/21/19	PES	18.95	20.21
					01/13/20	PES	18.28	20.88
					05/11/20	PES	Dry	
					05/11/20	PES	Dry	
					07/13/20	PES	Dry	
					11/16/20	PES	Dry	
					02/02/21	PES	18.44	20.72
					06/01/21	PES	18.68	20.48
					08/17/21	PES	18.90	20.26
					02/15/22	PES	15.81	23.35
					05/16/22	PES	15.79	23.37
					08/08/22	PES	16.76	22.40
					11/07/22	PES	17.73	21.43
					02/21/23	PES	16.13	23.03
					05/08/23	PES	16.20	22.96
					08/10/23	PES	17.60	21.56
					10/30/23	PES	17.77	21.39
					02/28/24	PES	15.92	23.24
					05/20/24	PES	16.75	22.41
					09/03/24	PES	17.73	21.43
					11/05/24	PES	17.85	21.31
SCS-3	800 Aloha Street Parcel	–	–	36.73	02/07/12	Windward	14.10	22.63
SCS-4	800 Aloha Street Parcel	–	–	35.33	02/07/12	Windward	12.93	22.40
SCS-5	800 Aloha Street Parcel	–	–	39.06	02/07/12	Windward	17.81	21.25
SVE-1	Westlake Ave N, W side (Block 43)	5.0 to 17.0	23.1 to 11.1	28.05	02/14/22	Farallon	9.46	18.59
					05/16/22	Farallon	3.30	24.75
					08/08/22	Farallon	5.82	22.23
					11/07/22	Farallon	6.80	21.25
					02/21/23	Farallon	8.14	19.91
					05/08/23	Farallon	8.08	19.97
					08/10/23	Farallon	DRY	–
					10/30/23	Farallon	DRY	–

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
SVE-2	Westlake Ave N, W side (Block 43)	5.0 to 17.0	23.7 to 11.7	28.66	02/14/22	Farallon	10.29	18.37
					05/16/22	Farallon	7.90	20.76
					08/08/22	Farallon	9.57	19.09
					11/07/22	Farallon	8.44	20.22
					02/21/23	Farallon	9.08	19.58
					05/08/23	Farallon	8.88	19.78
					08/10/23	Farallon	10.81	17.85
					10/30/23	Farallon	9.49	19.17
SVE-3	Valley St ROW, S side (Block 43)	4.0 to 10.0	25.9 to 19.9	29.92	02/14/22	Farallon	Dry	–
					05/16/22	Farallon	6.08	23.84
					08/08/22	Farallon	9.87	20.05
					11/07/22	Farallon	dry	–
					02/21/23	Farallon	Dry	–
					05/08/23	Farallon	Dry	–
					08/10/23	Farallon	11.32	18.60
					10/30/23	Farallon	11.21	18.71
SVE-4	Valley St ROW, S side (Block 43)	4.0 to 16.0	24.4 to 12.4	28.36	02/14/22	Farallon	9.30	19.06
					05/16/22	Farallon	8.76	19.60
					08/08/22	Farallon	9.04	19.32
					11/07/22	Farallon	9.16	19.20
					02/21/23	Farallon	9.15	19.21
					05/08/23	Farallon	8.92	19.44
					08/10/23	Farallon	9.80	18.56
					10/30/23	Farallon	9.72	18.64
SVE-5	Valley St ROW, S side (Block 43)	4.0 to 12.0	25.3 to 17.3	29.28	02/14/22	Farallon	6.06	23.22
					05/16/22	Farallon	8.29	20.99
					08/08/22	Farallon	9.81	19.47
					11/07/22	Farallon	9.36	19.92
					02/21/23	Farallon	9.65	19.63
					05/08/23	Farallon	9.66	19.62
					08/10/23	Farallon	10.63	18.65
					10/30/23	Farallon	10.71	18.57
B-37-7	Block 37, SW quadrant	30.5 to 40.5	-0.8 to -10.8	29.71	02/14/22	Farallon	13.23	16.48
					05/16/22	Farallon	11.52	18.19
					08/08/22	Farallon	12.57	17.14
					11/07/22	Farallon	12.01	17.70
					02/21/23	Farallon	11.69	18.02
					05/08/23	Farallon	11.26	18.45
					08/10/23	Farallon	12.01	17.70
					10/30/23	Farallon	12.24	17.47
B-37-8	Block 37, SW quadrant	30.5 to 40.5	-0.6 to -10.6	29.94	02/14/22	Farallon	12.90	17.04
					05/16/22	Farallon	12.65	17.29
					08/08/22	Farallon	12.40	17.54
					11/07/22	Farallon	12.26	17.68
					02/21/23	Farallon	11.92	18.02
					05/08/23	Farallon	11.86	18.08
					08/10/23	Farallon	12.31	17.63
					10/30/23	Farallon	12.58	17.36

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b	
B-37-9	Block 37, SE quadrant	29.5 to 30.5	0.4 to -0.6	29.93	02/14/22	Farallon	12.41	17.52	
					05/16/22	Farallon	11.68	18.25	
					08/08/22	Farallon	11.42	18.51	
					11/07/22	Farallon	12.09	17.84	
					02/21/23	Farallon	11.79	18.14	
					05/08/23	Farallon	10.31	19.62	
					08/10/23	Farallon	12.09	17.84	
					10/30/23	Farallon	12.13	17.80	
BB-5	SDOT Mercer Parcels, SE quadrant	30 to 40	—	—	09/05/97	B&V	23.60		
					09/09/97	B&V	23.90		
					10/17/97	B&V	22.78		
					11/17/97	B&V	23.40		
					12/02/97	B&V	22.28		
					01/21/98	B&V	23.85		
					02/27/98	B&V	23.45		
					03/25/98	B&V	22.86		
					04/24/98	B&V	23.40		
					06/05/98	B&V	23.56		
					07/08/98	B&V	23.83		
					07/27/98	B&V	24.25		
					08/25/98	B&V	24.42		
					09/30/98	B&V	24.04		
									Decommissioned
BB-7	Valley St ROW, S side	25 to 35	—	—	06/13/97	B&V	8.80		
					06/20/97	B&V	8.40		
					06/24/97	B&V	9.70		
					11/17/97	B&V	9.44		
					12/02/97	B&V	7.78		
					01/22/98	B&V	9.83		
					02/27/98	B&V	9.01		
					03/25/98	B&V	8.98		
					04/22/98	B&V	9.18		
					06/05/98	B&V	9.39		
					07/08/98	B&V	9.14		
					07/27/98	B&V	9.55		
					08/25/98	B&V	10.50		
					09/29/98	B&V	9.83		
									Decommissioned
BB-8	Roy St ROW, S side	30 to 40	14.0 to 4.0	—	06/20/97	B&V	17.49		
					06/24/97	B&V	19.00		
					10/06/97	B&V	20.40		
					01/25/98	B&V	20.68		
					02/28/98	B&V	20.20		
					03/30/98	B&V	20.14		
					04/22/98	B&V	19.99		
					06/04/98	B&V	20.51		
					07/27/98	B&V	24.02		
					01/29/09	DOF	20.08		
					02/19/10	SES	18.66		25.59
					05/03/10	SES	19.90		24.35
					06/02/11	SES	17.64		26.61
				44.25	02/07/12	Windward	15.39	28.86	

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b	
BB-8 Continued				44.26	09/05/12	SES	20.01	24.25	
				12/21/12	SES	16.23	28.03		
				03/29/13	SES	18.70	25.56		
				43.69	01/06/14	SES	24.42	19.27	
				06/16/15	SES	18.90	24.79		
				03/20/17	PES	13.21	30.48		
				03/24/17	PES	13.26	30.43		
				06/12/17	PES	18.80	24.89		
				10/11/17	PES	23.87	19.82		
				03/14/19	PES	13.73	29.96		
				04/22/19	PES	15.36	28.33		
				07/17/19	PES	20.41	23.28		
				43.64	10/21/19	PES	26.19	17.45	
				01/13/20	PES	24.10	19.54		
				05/11/20	PES	26.62	17.02		
				07/13/20	PES	27.60	16.04		
				11/16/20	PES	20.95	22.69		
				02/01/21	PES	15.33	28.31		
				06/07/21	PES	18.35	25.29		
				08/16/21	PES	19.70	23.94		
				02/14/22	PES	14.90	28.74		
				05/16/22	PES	16.70	26.94		
				08/08/22	PES	18.68	24.96		
				11/07/22	PES	19.17	24.47		
				02/21/23	PES	—	—		
				05/08/23	PES	17.98	25.66		
				08/10/23	PES	Inaccessible	—		
				10/30/23	PES	19.18	24.46		
				03/01/24	PES	16.10	27.54		
				05/20/24	PES	19.02	24.62		
				09/03/24	PES	20.03	23.61		
				11/04/24	PES	18.89	24.75		
BB-12	9th Ave N ROW, W side	35 to 45	—	—	03/25/98	B&V	14.89		
					04/27/98	B&V	14.97		
					05/19/98	B&V	15.01		
					07/08/98	B&V	15.32		
					07/28/98	B&V	15.68		
					08/25/98	B&V	15.00		
					09/29/98	B&V	14.78		
					02/19/10	SES	16.33		17.68
					05/02/10	SES	14.52		19.49
					Decommissioned				
BB-13	Westlake Ave N ROW, W side	35 to 45	—	—	03/25/98	B&V	9.38		
					04/23/98	B&V	8.76		
					05/19/98	B&V	9.11		
					07/08/98	B&V	9.00		
					07/28/98	B&V	9.25		
					09/29/98	B&V	8.00		
					02/19/10	SES	9.50		18.15
					05/02/10	SES	9.13		18.52
					02/07/12	Windward	7.56		20.09
					Decommissioned				

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
BB-14	Valley St ROW, N side	40 to 60	–	–	03/25/98	B&V	8.38	
					04/22/98	B&V	8.24	
					05/19/98	B&V	8.29	
					07/08/98	B&V	7.42	
					07/28/98	B&V	9.03	
					08/25/98	B&V	9.49	
					09/29/98	B&V	6.14	
					Decommissioned			
DMW-31A	615 Dexter, NE quadrant	39.0 to 49.0	16.8 to 6.8	55.84	03/19/20	HC	25.39	30.45
					05/11/20	HC	25.99	29.85
					07/13/20	HC	26.68	29.16
					11/16/20	PES	26.24	29.60
					02/01/21	HC	22.90	32.94
					06/07/21	PES	23.79	32.05
					08/16/21	PES	24.43	31.41
					02/14/22	PES	20.85	34.99
					02/22/23	PES	38.10	17.74
					05/08/23	PES	NM	
					08/10/23	PES	NM	
					10/30/23	PES	NM	
					03/01/24	PES	NM	
HC-4	601 Dexter, NE quadrant	40 to 50	20.2 to 10.2	60	03/19/20	HC	31.50	28.50
					05/11/20	HC	32.21	27.79
					06/07/21	PES	31.13	28.87
					08/16/21	PES	31.70	28.30
					02/15/22	PES	29.05	30.95
FMW-136	Block 38 West, S end	30 to 40	-4.9 to -14.9	24.79	08/30/18	Farallon	8.10	16.69
					12/28/18	Farallon	7.74	17.05
					03/26/19	Farallon	7.41	17.38
FMW-142	9th Ave N ROW, E side	37.5 to 42.5	-4.6 to -9.6	32.52	10/31/19	PES	15.50	17.02
					01/13/20	PES	17.13	15.39
					04/28/20	PES	18.83	13.69
					07/13/20	PES	22.86	9.66
					11/16/20	PES	22.57	9.95
					02/01/21	PES	18.91	13.61
					06/07/21	PES	16.13	16.39
					08/16/21	PES	16.15	16.37
					02/14/22	PES	14.10	18.42
					05/16/22	PES	13.34	19.18
					08/08/22	PES	13.40	19.12
					11/07/22	PES	14.12	18.40
					02/21/23	PES	13.79	18.73
					05/08/23	PES	13.36	19.16
					08/10/23	PES	14.29	18.23
					10/30/23	PES	14.33	18.19
					03/01/24	PES	13.35	19.17
					05/21/24	PES	13.38	19.14
					09/03/24	PES	14.13	18.39
					11/04/24	PES	14.20	18.32

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
FMW-150	Block 38 West, S end	6.0 to 11.0 ³	-8.5 to -13.5 ⁴	23.3 ⁵	02/14/22	Farallon	6.50	16.80
					05/16/22	Farallon	5.95	17.35
					08/08/22	Farallon	5.57	17.73
					11/07/22	Farallon	5.92	17.38
					02/21/23	Farallon	6.02	17.28
					05/08/23	Farallon	5.51	17.79
					08/10/23	Farallon	5.88	17.42
					10/30/23	Farallon	5.97	17.33
FMW-151	Block 38 West, center of Property	6.8 to 11.8 ³	-9.3 to -14.3 ⁴	23.74	02/15/22	Farallon	7.21	16.53
					05/16/22	Farallon	6.34	17.40
					08/08/22	Farallon	6.01	17.73
					11/07/22	Farallon	7.40	16.34
					02/21/23	Farallon	5.54	18.20
					05/08/23	Farallon	5.93	17.81
					08/10/23	Farallon	6.28	17.46
					10/30/23	Farallon	6.33	17.41
FMW-152	Block 38 West, N end	6.0 to 11.0 ³	-8.5 to -13.5 ⁴	22.8 ⁵	02/14/22	Farallon	5.76	17.04
					05/16/22	Farallon	5.15	17.65
					08/08/22	Farallon	4.88	17.92
					11/07/22	Farallon	5.35	17.45
					02/21/23	Farallon	5.00	17.80
					05/08/23	Farallon	4.81	17.99
					08/10/23	Farallon	5.30	17.50
					10/30/23	Farallon	5.34	17.46
FMW-153	Block 38 West, S end	6.0 to 11.0 ³	-8.5 to -13.5 ⁴	24.72	02/15/22	Farallon	8.50	16.22
					05/16/22	Farallon	7.55	17.17
					08/08/22	Farallon	7.27	17.45
					11/07/22	Farallon	7.44	17.28
					02/21/23	Farallon	7.04	17.68
					05/08/23	Farallon	7.06	17.66
					08/10/23	Farallon	7.32	17.40
					10/30/23	Farallon	7.45	17.27
FMW-157	Block 38 West	30.0 to 40.0	-4.1 to -14.1	25.95	02/14/22	Farallon	5.87	20.08
					05/16/22	Farallon	8.28	17.67
					08/08/22	Farallon	8.04	17.91
					11/07/22	Farallon	8.53	17.42
					02/21/23	Farallon	5.16	20.79
					05/08/23	Farallon	7.95	18.00
					08/10/23	Farallon	8.43	17.52
					10/30/23	Farallon	5.59	20.36
G-MW3	Property, SE quadrant	26 to 36	–	–	07/24/01	GeoEngineers	13.05	26.72 28.55 29.04 26.41 28.60 28.41
					12/10/04	DOF	15.30	
					01/29/09	DOF	13.49	
					02/19/10	SES	12.83	
					06/02/11	SES	11.00	
					02/07/12	Windward	10.51	
					09/06/12	SES	13.14	
					12/21/12	SES	10.95	
					03/29/13	SES	11.14	
					Decommissioned			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
GEI-1	Block 37, SW quadrant	26.8 to 36.8	1.2 to -8.9	27.95	03/24/17	PES	8.63	19.32
					06/12/17	PES	21.91	6.04
					03/14/19	PES	9.64	18.31
					04/22/19	PES	9.28	18.67
					07/16/19	PES	9.59	18.36
					10/21/19	PES	10.62	17.33
					01/13/20	PES	11.37	16.58
					05/11/20	PES	15.74	12.21
					07/13/20	PES	16.09	11.86
					11/16/20	PES	15.75	12.20
					02/01/21	PES	13.03	14.92
					06/07/21	PES	10.98	16.97
					08/16/21	PES	11.29	16.66
					02/14/22	PES	9.85	18.10
					05/16/22	PES	8.89	19.06
					08/08/22	PES	9.25	18.70
					11/07/22	PES	9.61	18.34
					02/21/23	PES	18.19	9.76
					05/08/23	PES	8.85	19.10
					08/10/23	PES	9.93	18.02
					10/30/23	PES	9.79	18.16
GEI-MW-1	Block 79 East, N end	39.8 to 59.8	-9.7 to -29.7	30.30	05/11/20	PES	18.65	11.65
					07/13/20	PES	18.97	11.33
					11/16/20	PES	Inaccessible	
					02/01/21	PES	15.82	14.48
					06/07/21	PES	13.25	17.05
					08/16/21	PES	13.53	16.77
					02/14/22	PES	12.03	18.27
					05/16/22	PES	11.17	19.13
					08/08/22	PES	11.29	19.01
					11/07/22	PES	11.97	18.33
					02/21/23	PES	11.65	18.65
					05/08/23	PES	11.05	19.25
					08/10/23	PES	12.04	18.26
					10/30/23	PES	12.09	18.21
					03/01/24	PES	11.18	19.12
HMW-2IA	SDOT Mercer Parcels, NE quadrant	34.8 to 44.8	10.8 to 0.8	47.51	03/20/19	HC	18.61	28.90
					03/26/19	HC	19.11	28.40
					07/16/19	HC	24.28	23.23
					12/05/19	HC	27.83	19.68
					01/13/20	HC	25.48	22.03
					03/19/20	HC	27.29	20.22
					04/10/20	HC	27.59	19.92
					05/11/20	HC	28.27	19.24
					07/13/20	HC	28.86	18.65

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-2IA Continued					11/16/20	PES	23.31	24.20
					02/01/21	HC	19.55	27.96
					06/07/21	PES	23.32	24.19
					08/16/21	PES	23.76	23.75
					02/14/22	PES	20.11	27.40
					05/16/22	PES	20.60	26.91
					08/08/22	PES	22.80	24.71
					11/07/22	PES	22.36	25.15
					02/22/23	PES	21.09	26.42
					05/08/23	PES	21.73	25.78
					08/10/23	PES	23.53	23.98
					10/30/23	PES	22.65	24.86
					03/01/24	PES	19.67	27.84
HMW-3IA	SDOT Mercer Parcels, NW quadrant	34.8 to 44.8	20.2 to 10.2	54.75	03/19/19	HC	23.71	31.04
					03/26/19	HC	23.99	30.76
					07/16/19	HC	28.11	26.64
					12/05/19	HC	30.82	23.93
					01/13/20	HC	29.86	24.89
					03/19/20	HC	29.54	25.21
					04/10/20	HC	29.70	25.05
					05/11/20	HC	30.05	24.70
					07/13/20	HC	30.58	24.17
					11/16/20	PES	27.90	26.85
					02/01/21	HC	24.59	30.16
					06/07/21	PES	26.52	28.23
					08/16/21	PES	26.99	27.76
					02/14/22	PES	24.24	30.51
					–		26.76	27.99
					08/08/22	PES	28.40	26.35
					05/08/23	PES	34.43	20.32
					08/10/23	PES	38.64	16.11
					10/30/23	PES	38.76	15.99
					03/01/24	PES	39.58	15.17
HMW-6IA	SDOT Mercer Parcels, SW quadrant	37.5 to 47.5	21.2 to 11.2	61.27	03/19/20	HC	33.43	27.84
					05/11/20	HC	34.25	27.02
					07/13/20	HC	36.05	25.22
					11/16/20	PES	35.39	25.88
					02/01/21	HC	33.25	28.02
					06/07/21	PES	33.91	27.36
					08/16/21	PES	34.59	26.68
					02/14/22	PES	32.70	28.57
					05/16/22	PES	33.21	28.06
					08/08/22	PES	33.74	27.53
					11/07/22	PES	34.39	26.88
					02/22/23	PES	33.14	28.13
					05/08/23	PES	33.37	27.90
					08/10/23	PES	34.23	27.04
					10/30/23	PES	34.11	27.16
					03/01/24	PES	32.47	28.80

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-9IA	SDOT Mercer Parcels, SW quadrant	36.7 to 46.7	18.6 to 8.6	58.21	03/19/20	HC	34.18	24.03
					05/11/20	HC	34.48	23.73
					07/13/20	HC	34.95	23.26
					11/16/20	PES	32.91	25.30
					02/01/21	HC	30.89	27.32
					06/07/21	PES	32.22	25.99
					08/16/21	PES	32.56	25.65
					02/14/22	PES	30.71	27.50
					05/16/22	PES	31.39	26.82
					05/08/23	PES	31.95	26.26
					08/10/23	PES	32.67	25.54
					10/30/23	PES	32.27	25.94
					03/01/24	PES	30.69	27.52
HMW-20IA	SDOT Mercer Parcels, NW quadrant	41.0 to 51.0	12.8 to 2.8	56.47	11/16/20	PES	30.74	25.73
					06/07/21	PES	30.43	26.04
					02/14/22	PES	28.02	28.45
					05/16/22	PES	–	–
					05/08/23	PES	32.34	24.13
					08/10/23	PES	NM	–
MW107	8th Ave N ROW, W side	35 to 45	8.8 to -1.2	43.82	12/21/12	SES	17.28	26.54
					03/29/13	SES	18.28	25.54
					01/06/14	SES	26.74	17.08
					06/16/15	SES	17.78	26.04
					10/19/15	SES	19.88	23.94
					02/01/16	SES	12.85	30.97
					03/20/17	PES	11.80	32.02
					03/24/17	PES	12.20	31.62
					04/14/17	PES	12.31	31.51
					04/28/17	PES	14.12	29.70
					05/05/17	PES	14.34	29.48
					05/12/17	PES	14.85	28.97
					05/19/17	PES	15.03	28.79
					06/12/17	PES	18.62	25.20
					10/11/17	PES	25.10	18.72
					03/14/19	PES	12.84	30.98
					04/22/19	PES	13.35	30.47
					07/16/19	PES	21.75	22.07
					10/21/19	PES	35.69	8.13
					01/13/20	PES	31.55	12.27
					05/11/20	PES	34.30	9.52
					07/13/20	PES	34.99	8.83
					07/21/20	PES	30.10	13.72
					08/04/20	PES	27.84	15.98
					08/17/20	PES	26.56	17.26
					09/03/20	PES	25.84	17.98
					09/21/20	PES	25.32	18.50
					11/16/20	PES	Inaccessible	
					02/01/21	PES	Inaccessible	
					06/07/21	PES	Inaccessible	
					08/16/21	PES	19.36	24.46

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW107 Continued				43.01	02/14/22	PES	15.51	27.50
					05/16/22	PES	16.82	26.19
					08/08/22	PES	17.95	25.06
					11/07/22	PES	17.98	25.03
					02/21/23	PES	17.67	25.34
					05/08/23	PES	18.13	24.88
					08/10/23	PES	18.78	24.23
					10/30/23	PES	Inaccessible	
					03/01/24	PES	15.80	27.21
					05/20/24	PES	18.22	24.79
					09/03/24	PES	19.07	23.94
					11/04/24	PES	17.77	25.24
MW108	Alley E of Seattle Roy Aloha Shops	40 to 50	-7.2 to -17.2	32.78	12/21/12	SES	13.43	19.35
					03/29/13	SES	15.76	17.02
					01/06/14	SES	21.44	11.34
					06/16/15	SES	15.53	17.25
					10/19/15	SES	17.16	15.62
					02/01/16	SES	16.31	16.47
					03/20/17	PES	12.53	20.25
					03/24/17	PES	12.61	20.17
					06/12/17	PES	28.13	4.65
					10/11/17	PES	29.02	3.76
					03/14/19	PES	13.46	19.32
					04/22/19	PES	13.19	19.59
					07/16/19	PES	13.84	18.94
					10/21/19	PES	15.92	16.86
					01/13/20	PES	17.32	15.46
					05/11/20	PES	22.13	10.65
					07/13/20	PES	22.50	10.28
					11/16/20	PES	21.55	11.23
					02/01/21	PES	18.04	14.74
					06/07/21	PES	15.50	17.28
					08/16/21	PES	15.67	17.11
					02/14/22	PES	13.61	19.17
					05/16/22	PES	13.06	19.72
					08/08/22	PES	13.21	19.57
					11/07/22	PES	13.98	18.80
					02/21/23	PES	13.49	19.29
					05/08/23	PES	13.11	19.67
					08/10/23	PES	14.08	18.70
					10/30/23	PES	14.10	18.68
					02/28/24	PES	13.06	19.72
					05/20/24	PES	13.27	19.51
					09/03/24	PES	13.79	18.99
					11/04/24	PES	13.83	18.95
MW109	Alley E of Seattle Roy Aloha Shops	35 to 45	-0.0 to -10.0	34.97	12/21/12	SES	15.80	19.17
					03/29/13	SES	18.39	16.58
					01/06/14	SES	24.74	10.23
					06/16/15	SES	18.06	16.91
					10/19/15	SES	19.80	15.17
					02/01/16	SES	19.04	15.93
					03/20/17	PES	15.00	19.97

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW109 Continued				34.87	03/24/17	PES	15.00	19.97
					06/12/17	PES	31.53	3.44
					10/11/17	PES	32.17	2.80
					03/14/19	PES	15.87	19.10
					04/22/19	PES	15.62	19.35
					07/16/19	PES	16.23	18.74
					10/21/19	PES	18.14	16.83
					01/13/20	PES	19.58	15.29
					02/24/20	PES	23.01	11.86
					05/11/20	PES	24.80	10.07
					07/13/20	PES	25.28	9.59
					07/21/20	PES	25.21	9.66
					08/04/20	PES	25.25	9.62
					08/17/20	PES	25.21	9.66
					09/03/20	PES	25.22	9.65
					09/21/20	PES	Inaccessible	
					11/16/20	PES	24.59	10.28
					02/01/21	PES	20.78	14.09
					06/07/21	PES	18.14	16.73
					08/16/21	PES	18.20	16.67
					02/14/22	PES	16.03	18.84
					05/16/22	PES	15.51	19.36
					08/08/22	PES	15.61	19.26
					11/07/22	PES	16.33	18.54
					02/21/23	PES	15.87	19.00
					05/08/23	PES	15.42	19.45
					08/10/23	PES	16.45	18.42
					10/30/23	PES	16.45	18.42
					02/28/24	PES	15.40	19.47
					05/20/24	PES	11.40	23.47
					09/03/24	PES	16.20	18.67
					11/04/24	PES	16.22	18.65
MW110	Alley E of Seattle Roy Aloha Shops	35 to 45	4.7 to -5.3	39.67	12/21/12	SES	20.01	19.66
					03/29/13	SES	22.95	16.72
					01/06/14	SES	30.48	9.19
					04/22/15	SES	22.59	17.08
					06/16/15	SES	22.72	16.95
					10/19/15	SES	24.57	15.10
					02/01/16	SES	23.30	16.37
					03/20/17	PES	19.10	20.57
					03/24/17	PES	18.95	20.72
					06/12/17	PES	34.70	4.97
					10/11/17	PES	36.46	3.21
					03/14/19	PES	20.18	19.49
					04/22/19	PES	20.08	19.59
					07/16/19	PES	20.83	18.84
					10/21/19	PES	22.65	17.02
					01/13/20	PES	23.89	15.78
					05/11/20	PES	29.95	9.72
					07/13/20	PES	30.51	9.16
					07/21/20	PES	30.55	9.12
					08/04/20	PES	30.70	8.97

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW110 Continued					08/17/20	PES	30.64	9.03
					09/03/20	PES	30.67	9.00
					09/21/20	PES	Inaccessible	
					11/16/20	PES	30.04	9.63
					02/01/21	PES	25.28	14.39
					06/07/21	PES	23.00	16.67
					08/16/21	PES	23.01	16.66
					02/14/22	PES	20.28	19.39
					05/16/22	PES	20.05	19.62
					08/08/22	PES	20.18	19.49
					11/07/22	PES	21.08	18.59
					02/21/23	PES	20.42	19.25
					05/08/23	PES	19.96	19.71
					08/10/23	PES	21.10	18.57
					10/30/23	PES	21.09	18.58
					05/20/24	PES	20.30	19.37
					09/03/24	PES	20.92	18.75
					11/04/24	PES	20.98	18.69
MW114	SDOT Mercer Parcels, NW quadrant	35 to 45	10.8 to 0.8	45.84	12/21/12	SES	16.50	29.34
					03/29/13	SES	19.54	26.30
					01/06/14	SES	25.93	19.91
					Destroyed			
MW115	9th Ave N ROW, W side	35 to 45	-0.6 to -10.6	34.14	12/21/12	SES	15.26	18.88
				34.10	03/29/13	SES	18.34	15.80
					01/06/14	SES	26.08	8.06
					04/22/15	SES	16.49	17.65
					06/16/15	SES	17.72	16.42
					10/19/15	SES	19.61	14.53
					02/01/16	SES	19.14	15.00
					03/20/17	PES	14.72	19.38
					03/24/17	PES	14.70	19.40
					06/12/17	PES	32.50	1.60
					10/11/17	PES	32.58	1.52
					03/14/19	PES	15.64	18.46
					04/22/19	PES	15.42	18.68
					07/16/19	PES	15.80	18.30
					10/21/19	PES	17.34	16.76
					01/13/20	PES	19.13	14.97
					05/11/20	PES	24.84	9.26
					07/13/20	PES	25.39	8.71
					11/16/20	PES	24.97	9.13
					02/01/21	PES	21.00	13.10
					06/07/21	PES	18.00	16.10
					08/16/21	PES	17.96	16.14
					02/14/22	PES	15.82	18.28
					05/16/22	PES	15.21	18.89
					08/08/22	PES	15.24	18.86
					11/07/22	PES	15.97	18.13
					02/21/23	PES	15.56	18.54
					05/08/23	PES	15.50	18.60
					08/10/23	PES	15.93	18.17
					10/30/23	PES	15.98	18.12

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW115 Continued					03/01/24	PES	14.98	19.12
					05/20/24	PES	15.21	18.89
					09/03/24	PES	15.79	18.31
					11/04/24	PES	15.81	18.29
MW116	9th Ave N ROW, W side	35 to 45	-3.1 to -13.1	31.36	12/21/12	SES	12.24	19.12
				31.34	03/29/13	SES	14.65	16.71
					01/06/14	SES	20.30	11.06
					06/16/15	SES	14.54	16.82
					10/19/15	SES	16.07	15.29
					02/01/16	SES	15.49	15.87
					03/20/17	PES	11.95	19.39
					03/24/17	PES	11.99	19.35
					04/14/17	PES	11.99	19.35
					04/28/17	PES	20.60	10.74
					05/05/17	PES	21.35	9.99
					05/12/17	PES	22.16	9.18
					05/19/17	PES	22.46	8.88
					06/12/17	PES	27.33	4.01
					10/11/17	PES	28.26	3.08
					03/14/19	PES	12.72	18.62
					04/22/19	PES	12.41	18.93
					07/16/19	PES	12.80	18.54
					10/21/19	PES	13.30	18.04
					01/13/20	PES	15.59	15.75
					05/11/20	PES	20.55	10.79
					07/13/20	PES	20.99	10.35
					11/16/20	PES	21.41	9.93
					02/01/21	PES	18.88	12.46
					06/07/21	PES	14.66	16.68
					08/16/21	PES	14.71	16.63
					02/14/22	PES	12.65	18.69
					05/16/22	PES	12.11	19.23
					08/08/22	PES	12.18	19.16
					11/07/22	PES	13.11	18.23
					02/22/23	PES	12.50	18.84
					05/08/23	PES	12.04	19.30
					08/10/23	PES	12.09	19.25
					10/30/23	PES	13.03	18.31
					03/01/24	PES	12.04	19.30
					05/20/24	PES	12.07	19.27
					09/03/24	PES	12.83	18.51
					11/04/24	PES	12.87	18.47
MW117	Dexter Ave N ROW, E side	40 to 55	16.9 to 1.9	56.90	02/08/13	SES	27.46	29.44
					03/29/13	SES	27.81	29.09
					01/06/14	SES	30.54	26.36
					Destroyed			
MW118	Mercer St ROW, N side	40 to 50	12.9 to 2.9	52.91	03/25/13	SES	27.18	25.73
					03/29/13	SES	27.49	25.42
					01/06/14	SES	29.81	23.10
					Destroyed			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW119	9th Ave N ROW, W side	35 to 45	2.7 to -7.3	37.35	03/25/13	SES	22.21	15.14
				37.42	03/29/13	SES	22.52	14.83
					01/06/14	SES	32.12	5.23
					04/22/15	SES	21.12	16.23
					06/16/15	SES	21.12	16.23
					10/19/15	SES	23.50	13.85
					02/01/16	SES	22.99	14.36
					03/20/17	PES	17.40	20.02
					03/24/17	PES	17.45	19.97
					04/14/17	PES	17.91	19.51
					04/28/17	PES	27.14	10.28
					05/05/17	PES	28.25	9.17
					05/12/17	PES	29.25	8.17
					05/19/17	PES	29.68	7.74
					06/12/17	PES	35.73	1.69
					10/11/17	PES	39.94	-2.52
					03/14/19	PES	18.79	18.63
					03/26/19	HC	18.62	18.80
					04/22/19	PES	18.64	18.78
					07/16/19	PES	19.07	18.35
					07/17/19	HC	18.97	18.45
					07/30/19	HC	19.18	18.24
					10/21/19	PES	20.44	16.98
					11/11/19	Farallon	20.74	16.68
					01/13/20	PES	22.31	15.11
					01/14/20	Farallon	22.51	14.91
					02/18/20	Farallon	25.66	11.76
					03/19/20	HC	28.14	9.28
					03/24/20	Farallon	28.36	9.06
					05/11/20	PES	29.32	8.10
					07/13/20	PES	29.96	7.46
					11/16/20	PES	29.50	7.92
					02/01/21	PES	24.79	12.63
					06/07/21	PES	21.75	15.67
					08/16/21	PES	21.55	15.87
					02/14/22	PES	18.83	18.59
					05/16/22	PES	18.40	19.02
					08/08/22	PES	18.43	18.99
					11/07/22	PES	19.20	18.22
					02/21/23	PES	18.35	19.07
					05/08/23	PES	18.19	19.23
					08/10/23	PES	19.16	18.26
					10/30/23	PES	19.10	18.32
					03/01/24	PES	17.91	19.51
					05/20/24	PES	18.40	19.02
					09/04/24	PES	18.96	18.46
					11/04/24	PES	18.95	18.47
MW120	8th Ave N ROW, E side	40 to 50	0.0 to -10.0	40.00	01/06/14	SES	22.80	17.20
					06/16/15	SES	18.10	21.90
					10/19/15	SES	19.91	20.09
					02/01/16	SES	16.98	23.02
					03/20/17	PES	16.50	23.50

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW120 Continued				39.94	03/24/17	PES	15.24	24.76
					06/12/17	PES	23.65	16.35
					10/11/17	PES	26.99	13.01
					03/14/19	PES	16.06	23.94
					04/22/19	PES	15.79	24.21
					07/16/19	PES	17.55	22.45
					08/19/19	PES	20.17	19.83
					10/21/19	PES	22.88	17.12
					01/13/20	PES	23.57	16.37
					05/11/20	PES	26.57	13.37
					07/13/20	PES	26.52	13.42
					07/21/20	PES	25.45	14.49
					08/04/20	PES	24.39	15.55
					08/17/20	PES	23.88	16.06
					09/03/20	PES	23.55	16.39
					09/21/20	PES	23.55	16.39
					11/16/20	PES	22.07	17.87
					02/01/21	PES	19.30	20.64
					06/07/21	PES	18.34	21.60
					08/16/21	PES	18.58	21.36
					02/14/22	PES	16.58	23.36
					05/16/22	PES	16.84	23.10
					08/08/22	PES	17.19	22.75
					11/07/22	PES	Inaccessible	
					02/21/23	PES	17.32	22.62
					05/08/23	PES	17.09	22.85
					08/10/23	PES	18.02	21.92
					10/30/23	PES	17.81	22.13
					03/01/24	PES	16.30	23.64
					05/20/24	PES	17.37	22.57
					09/03/24	PES	17.35	22.59
					11/04/24	PES	17.47	22.47
MW127	8th Ave N ROW, E side	40 to 50	-1 to -11	39.04	01/06/14	SES	22.09	16.95
					08/01/19	PES	17.76	21.28
					10/21/19	PES	20.33	18.71
					01/13/20	PES	21.06	17.98
					05/11/20	PES	24.08	14.96
					07/13/20	PES	24.06	14.98
					11/16/20	PES	21.42	17.62
					02/01/21	PES	19.31	19.73
					06/07/21	PES	18.10	20.94
					08/16/21	PES	18.29	20.75
					02/14/22	PES	16.46	22.58
					05/16/22	PES	16.48	22.56
					08/08/22	PES	16.81	22.23
					11/07/22	PES	17.54	21.50
					02/21/23	PES	16.94	22.10
					05/08/23	PES	16.69	22.35
					08/10/23	PES	17.55	21.49
					10/30/23	PES	17.51	21.53
					03/01/24	PES	NM	–
					05/20/24	PES	16.78	22.26
					09/03/24	PES	16.97	22.07
					11/04/24	PES	17.11	21.93

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW131	Property, SE quadrant	45 to 55	-4.2 to -14.2	39.39	03/20/17	PES	9.73	29.66
					03/24/17	PES	10.11	29.28
					04/14/17	PES	10.31	29.08
					04/28/17	PES	12.10	27.29
					05/05/17	PES	13.10	26.29
					05/12/17	PES	12.69	26.70
					05/19/17	PES	12.84	26.55
					06/12/17	PES	15.77	23.62
					10/11/17	PES	20.75	18.64
					03/14/19	PES	8.48	30.91
				Decommissioned				
MW-142	8th Ave N ROW, E side	40 to 50	2.4 to -7.6	42.12	03/14/19	PES	15.42	26.70
					04/22/19	PES	15.75	26.37
					07/16/19	PES	20.13	21.99
					08/19/19	PES	27.21	14.91
					10/21/19	PES	29.14	12.98
					01/13/20	PES	29.58	12.54
					05/11/20	PES	32.15	9.97
					07/13/20	PES	32.26	9.86
					07/21/20	PES	29.21	12.91
					08/04/20	PES	27.42	14.70
					08/17/20	PES	26.62	15.50
					09/03/20	PES	26.05	16.07
					09/21/20	PES	25.85	16.27
					11/16/20	PES	22.44	19.68
					02/01/21	PES	19.42	22.70
					06/07/21	PES	19.63	22.49
					08/16/21	PES	19.88	22.24
					02/14/22	PES	17.41	24.71
					05/16/22	PES	17.94	24.18
					08/08/22	PES	18.66	23.46
					11/07/22	PES	19.40	22.72
					02/21/23	PES	18.61	23.51
					05/08/23	PES	18.72	23.40
					08/10/23	PES	19.63	22.49
					10/30/23	PES	19.15	22.97
					03/01/24	PES	18.10	24.02
					05/20/24	PES	18.63	23.49
					09/03/24	PES	18.86	23.26
					11/04/24	PES	18.75	23.37
MW-144	8th Ave N ROW, E side	40 to 50	3.9 to -6.1	43.50	03/14/19	PES	14.07	29.43
					04/22/19	PES	15.73	27.77
					07/16/19	PES	—	
					Decommissioned December 2019			
MW-144R	8th Ave N ROW, E side	40 to 50	2.8 to -7.3	42.46	01/13/20	PES	29.43	13.03
					05/11/20	PES	31.36	11.10
					07/13/20	PES	30.83	11.63
					07/21/20	PES	29.77	12.69
					08/04/20	PES	28.68	13.78
					08/17/20	PES	26.61	15.85
					09/03/20	PES	Inaccessible	
					09/21/20	PES	Inaccessible	
					11/16/20	PES	21.43	21.03

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-144R Continued					02/01/21	PES	18.53	23.93
					06/07/21	PES	22.48	19.98
					08/16/21	PES	19.45	23.01
					02/14/22	PES	16.28	26.18
					05/16/22	PES	17.31	25.15
					08/08/22	PES	18.40	24.06
					11/07/22	PES	18.85	23.61
					02/21/23	PES	17.69	24.77
					05/08/23	PES	18.34	24.12
					08/10/23	PES	19.36	23.10
					10/30/23	PES	18.80	23.66
					03/01/24	PES	20.17	22.29
					05/20/24	PES	18.48	23.98
					09/03/24	PES	Inaccessible	
					11/04/24	PES	22.43	20.03
MW-146	Roy St ROW, S side	40 to 50	12.9 to 2.9	52.34	03/14/19	PES	19.89	32.45
					03/26/19	HC	21.12	31.22
					04/22/19	PES	22.15	30.19
					07/16/19	PES	30.04	22.30
					07/17/19	HC	30.16	22.18
					08/19/19	PES	32.45	19.89
					10/21/19	PES	33.98	18.36
					01/13/20	PES	32.90	19.44
					03/19/20	HC	33.66	18.68
					05/11/20	PES	33.90	18.44
					07/13/20	PES	34.35	17.99
					07/21/20	PES	33.58	18.76
					08/04/20	PES	32.84	19.50
					08/17/20	PES	32.44	19.90
					09/03/20	PES	31.90	20.44
					09/21/20	PES	31.35	20.99
					11/16/20	PES	25.89	26.45
					02/01/21	PES	22.24	30.10
					06/07/21	PES	25.91	26.43
					08/16/21	PES	26.18	26.16
					02/14/22	PES	22.88	29.46
					05/16/22	PES	24.04	28.30
					08/08/22	PES	26.02	26.32
					11/07/22	PES	25.80	26.54
					02/21/23	PES	24.50	27.84
					05/08/23	PES	25.20	27.14
					08/10/23	PES	26.45	25.89
					10/30/23	PES	25.65	26.69
					03/01/24	PES	23.16	29.18
					05/20/24	PES	25.94	26.40
					09/03/24	PES	26.47	25.87
					11/04/24	PES	25.44	26.90
MW-149	Property, NE quadrant	35 to 45	0.7 to -9.3	35.22	03/14/19	PES	3.15	32.07
Decommissioned March 2019								
MW-151	Property, SW quadrant	35 to 45	4.9 to -5.1	39.38	03/14/19	PES	3.35	36.03
Decommissioned March 2019								

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-156	8th Ave N ROW, E side	40 to 50	2.0 to -8.0	41.24	01/24/19	PES	15.06	26.18
					03/14/19	PES	15.72	25.52
					04/22/19	PES	16.06	25.18
					07/16/19	PES	19.32	21.92
					08/19/19	PES	26.07	15.17
					10/21/19	PES	27.26	13.98
					01/13/20	PES	27.61	13.63
					05/11/20	PES	30.58	10.66
					07/13/20	PES	30.44	10.80
					07/21/20	PES	28.06	13.18
					08/04/20	PES	26.56	14.68
					08/17/20	PES	25.80	15.44
					09/03/20	PES	25.46	15.78
					09/21/20	PES	25.20	16.04
					11/16/20	PES	22.24	19.00
					02/01/21	PES	19.25	21.99
					06/07/21	PES	19.20	22.04
					08/16/21	PES	19.45	21.79
					02/14/22	PES	17.21	24.03
					05/16/22	PES	17.77	23.47
					08/08/22	PES	18.21	23.03
					11/07/22	PES	18.84	22.40
					02/21/23	PES	18.15	23.09
					05/08/23	PES	18.15	23.09
					08/10/23	PES	19.04	22.20
					10/30/23	PES	19.87	21.37
					03/01/24	PES	19.50	21.74
					05/20/24	PES	18.12	23.12
					09/03/24	PES	18.28	22.96
					11/04/24	PES	18.28	22.96
MW-189	Valley St ROW, S side	48.8 to 58.8	-1.2 to -11.2	47.33	10/21/19	PES	34.50	12.83
				47.99	01/13/20	PES	34.96	12.37
					05/11/20	PES	35.56	11.77
					07/13/20	PES	35.10	12.23
					07/21/20	PES	32.15	15.18
					08/04/20	PES	30.91	16.42
					08/17/20	PES	28.82	18.51
					09/03/20	PES	28.16	19.17
					09/21/20	PES	27.77	19.56
					10/01/20	PES	26.35	20.98
					11/16/20	PES	23.37	23.96
					02/01/21	PES	20.61	26.72
					06/07/21	PES	21.78	25.55
					08/16/21	PES	22.83	24.50
					02/14/22	PES	20.59	27.40
					05/16/22	PES	21.65	26.34
					08/08/22	PES	22.26	25.73
					11/07/22	PES	22.78	25.21
					02/21/23	PES	22.05	25.94
					05/08/23	PES	22.36	25.63
					08/10/23	PES	23.16	24.83
					10/30/23	PES	22.42	25.57
					03/01/24	PES	21.03	26.96
					05/20/24	PES	22.01	25.98
					09/03/24	PES	21.95	26.04
					11/04/24	PES	21.91	26.08

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-302	Dexter Ave N ROW, E side	54.3 to 64.3	3.0 to -7.0	57.03	10/21/19	PES	46.52	10.51
					01/13/20	PES	40.09	16.94
					05/11/20	PES	45.70	11.33
					07/13/20	PES	41.51	15.52
					11/16/20	PES	28.90	28.13
					02/01/21	PES	24.61	32.42
					06/07/21	PES	25.23	31.80
					08/16/21	PES	Inaccessible	
					02/14/22	PES	24.10	32.80
					05/16/22	PES	25.84	31.06
					08/08/22	PES	27.55	29.35
					11/07/22	PES	26.80	30.10
					02/21/23	PES	–	
					05/08/23	PES	25.95	30.95
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	25.73	31.17
					03/01/24	PES	25.47	31.43
					05/20/24	PES	26.33	30.57
					09/03/24	PES	26.40	30.50
					11/04/24	PES	26.01	30.89
MW-306	Roy St ROW, S side	42.8 to 52.8	17.2 to 7.2	59.48	10/21/19	PES	30.04	29.44
					01/13/20	PES	29.63	29.85
					03/19/20	HC	28.75	30.73
					05/11/20	PES	29.29	30.19
					07/13/20	PES	29.98	29.50
					07/21/20	PES	30.00	29.48
					08/04/20	PES	30.08	29.40
					08/17/20	PES	30.20	29.28
					09/03/20	PES	30.39	29.09
					09/21/20	PES	30.42	29.06
					11/16/20	PES	29.75	29.73
					02/01/21	PES	26.39	33.09
					06/07/21	PES	27.22	32.26
					08/16/21	PES	27.79	31.69
					02/14/22	PES	24.00	35.48
					05/16/22	PES	32.90	26.58
					08/08/22	PES	37.55	21.93
					11/04/22	PES	35.88	23.60
					02/21/23	PES	35.37	24.11
					05/08/23	PES	35.30	24.18
					08/10/23	PES	35.47	24.01
					10/30/23	PES	35.38	24.10
					03/01/24	PES	34.85	24.63
					05/20/24	PES	35.11	24.37
					09/03/24	PES	35.25	24.23
					11/04/24	PES	35.25	24.23
MW-308	Alley E of Seattle Roy Aloha Shops	35.1 to 45.1	-4.7 to -14.7	30.15	10/21/19	PES	13.07	17.08
					01/13/20	PES	14.32	15.83
					02/24/20	PES	17.04	13.11
					05/11/20	PES	18.70	11.45
					07/13/20	PES	19.06	11.09
					11/16/20	PES	18.25	11.90
					02/01/21	PES	15.02	15.13
					06/07/21	PES	12.65	17.50
					08/16/21	PES	12.80	17.35
					02/14/22	PES	10.89	19.26

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-308					05/16/22	PES	10.37	19.78
Continued					08/08/22	PES	10.50	19.65
					11/07/22	PES	11.22	18.93
					02/21/23	PES	10.90	19.25
					05/08/23	PES	10.34	19.81
					08/10/23	PES	11.37	18.78
					10/30/23	PES	11.30	18.85
					02/28/24	PES	10.42	19.73
					05/20/24	PES	10.41	19.74
					09/03/24	PES	11.04	19.11
					11/05/24	PES	11.23	18.92
MW-315	Mercer St ROW, N side	37.5 to 47.5	12.2 to 2.2	49.18	10/21/19	PES	27.08	22.10
					01/13/20	PES	25.80	23.38
					03/19/20	HC	27.24	21.94
					05/11/20	PES	28.12	21.06
					07/13/20	PES	28.65	20.53
					11/16/20	PES	25.28	23.90
					02/01/21	PES	22.31	26.87
					06/07/21	PES	24.80	24.38
					08/16/21	PES	25.10	24.08
					02/14/22	PES	22.22	26.96
					05/16/22	PES	22.58	26.60
					08/08/22	PES	24.06	25.12
					11/07/22	PES	24.01	25.17
					02/21/23	PES	22.61	26.57
					05/08/23	PES	23.05	26.13
					08/10/23	PES	24.58	24.60
					10/30/23	PES	23.93	25.25
					03/01/24	PES	21.74	27.44
					05/20/24	PES	24.00	25.18
					09/04/24	PES	24.43	24.75
					11/04/24	PES	23.73	25.45
MW-317	9th Ave N ROW, W side	28.2 to 38.2	3.4 to -6.6	31.35	10/21/19	PES	13.86	17.49
					01/13/20	PES	14.80	16.55
					05/11/20	PES	19.14	12.21
					07/13/20	PES	19.65	11.70
					11/16/20	PES	19.37	11.98
					02/01/21	PES	16.28	15.07
					06/07/21	PES	14.18	17.17
					08/16/21	PES	14.30	17.05
					02/14/22	PES	12.31	19.04
					05/16/22	PES	11.58	19.77
					08/08/22	PES	11.90	19.45
					11/07/22	PES	12.59	18.76
					02/22/23	PES	12.19	19.16
					05/08/23	PES	11.75	19.60
					08/10/23	PES	12.89	18.46
					10/30/23	PES	12.76	18.59
					03/01/24	PES	12.05	19.30
					05/20/24	PES	12.03	19.32
					09/03/24	PES	12.60	18.75
					11/04/24	PES	12.61	18.74

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-325	Mercer St ROW, N side	34.5 to 44.5	7.0 to -3.0	40.90	10/21/19	PES	23.69	17.21
					01/13/20	PES	25.57	15.33
					03/19/20	PES	31.64	9.26
					05/11/20	PES	33.31	7.59
					07/13/20	PES	34.03	6.87
					09/21/20	PES	34.33	6.57
					11/16/20	PES	33.78	7.12
					02/01/21	PES	28.79	12.11
					06/07/21	PES	25.55	15.35
					08/16/21	PES	25.25	15.65
					02/14/22	PES	22.14	18.76
					05/16/22	PES	21.84	19.06
					08/08/22	PES	21.91	18.99
					11/07/22	PES	22.81	18.09
					02/21/23	PES	21.60	19.30
					05/08/23	PES	21.56	19.34
					08/10/23	PES	22.51	18.39
					10/30/23	PES	22.46	18.44
					03/01/24	PES	21.18	19.72
					05/20/24	PES	21.85	19.05
					09/04/24	PES	22.35	18.55
					11/04/24	PES	22.38	18.52
MW-327	Lake Union Park, S end	24.8 to 34.8	3.6 to -6.3	28.15	10/21/19	PES	10.06	18.09
					01/13/20	PES	10.48	17.67
					05/11/20	PES	12.52	15.63
					07/13/20	PES	12.95	15.20
					09/21/20	PES	13.83	14.32
					11/16/20	PES	12.38	15.77
					02/01/21	PES	11.04	17.11
					06/07/21	PES	9.75	18.40
					08/16/21	PES	11.02	17.13
					02/14/22	PES	10.29	17.86
					05/16/22	PES	8.72	19.43
					08/08/22	PES	9.58	18.57
					11/07/22	PES	9.45	18.70
					02/21/23	PES	9.69	18.46
					05/08/23	PES	9.10	19.05
					08/10/23	PES	10.29	17.86
					10/30/23	PES	10.06	18.09
					03/01/24	PES	9.23	18.92
					05/20/24	PES	9.05	19.10
					09/03/24	PES	9.97	18.18
					11/04/24	PES	10.62	17.53
MW-330	Valley St ROW, N side	52.1 to 62.1	-0.43 to -10.43	51.67	05/11/20	PES	34.24	17.43
					07/13/20	PES	34.98	16.69
					08/17/20	PES	29.84	21.83
					09/03/20	PES	29.06	22.61
					09/21/20	PES	28.60	23.07
					11/16/20	PES	24.60	27.07
					02/01/21	PES	22.27	29.40
					06/07/21	PES	23.01	28.66
					08/16/21	PES	23.20	28.47
					02/14/22	PES	21.08	30.59
					05/16/22	PES	22.15	29.52
					11/07/22	PES	Inaccessible	
					02/21/23	PES	22.76	28.91
					05/08/23	PES	22.80	28.87

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-330 Continued					08/10/23	PES	23.62	28.05
					10/30/23	PES	22.84	28.83
					03/01/24	PES	21.65	30.02
					05/20/24	PES	22.71	28.96
					09/03/24	PES	22.52	29.15
					11/04/24	PES	22.40	29.27
MW-331	Alley E of Seattle Roy Aloha Shops	35.6 to 45.6	-5.17 to -15.17	30.43	05/11/20	PES	17.05	13.38
					07/13/20	PES	17.32	13.11
					11/16/20	PES	16.83	13.60
					02/03/21	PES	14.07	16.36
					06/07/21	PES	12.09	18.34
					08/16/21	PES	12.45	17.98
					02/14/22	PES	10.79	19.64
					05/16/22	PES	10.24	20.19
					08/08/22	PES	10.54	19.89
					11/07/22	PES	11.24	19.19
					02/21/23	PES	10.81	19.62
					05/08/23	PES	10.27	20.16
					08/10/23	PES	11.27	19.16
					10/30/23	PES	11.26	19.17
					02/28/24	PES	10.24	20.19
					05/20/24	PES	9.97	20.46
					09/03/24	PES	10.93	19.50
					11/04/24	PES	10.96	19.47
MW-333	900 Roy St, S end	33.2 to 43.2	-2.1 to -12.1	31.10	05/11/20	PES	20.26	10.84
					07/13/20	PES	20.65	10.45
					11/16/20	PES	20.34	10.76
					02/01/21	PES	17.12	13.98
					06/07/21	PES	14.57	16.53
					08/16/21	PES	14.69	16.41
					02/14/22	PES	12.82	18.28
					05/16/22	PES	12.03	19.07
					08/08/22	PES	12.09	19.01
					11/07/22	PES	12.66	18.44
					02/21/23	PES	12.40	18.70
					05/08/23	PES	Inaccessible	–
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	12.95	18.15
					03/01/24	PES	12.05	19.05
					05/20/24	PES	12.20	18.90
					09/03/24	PES	12.80	18.30
					11/04/24	PES	12.65	18.45
MW-344	SDOT Mercer Parcels, NW quadrant	39.4 to 49.4	13.6 to 3.6	52.70	06/07/21	PES	26.19	26.51
					08/16/21	PES	26.52	26.18
					02/14/22	PES	23.32	29.38
					05/16/22	PES	24.61	28.09
					08/08/22	PES	26.50	26.20
					11/07/22	PES	26.28	26.42
					02/22/23	PES	24.98	27.72
					05/08/23	PES	25.64	27.06
					08/10/23	PES	26.85	25.85
					10/30/23	PES	26.10	26.60
					03/01/24	PES	23.63	29.07
					05/20/24	PES	26.27	26.43
					09/04/24	PES	26.91	25.79
					11/04/24	PES	25.85	26.85

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
FMW-130	Block 38 West, S end	45 to 55	-22.8 to -32.8	21.86	08/30/18	Farallon	5.14	16.72
					12/28/18	Farallon	4.98	16.88
					03/26/19	Farallon	4.42	17.44
FMW-141	Alley E of Seattle Roy Aloha Shops	47.5 to 57.5	-12.1 to -22.1	35.15	10/30/19	PES	18.31	16.84
					01/13/20	PES	19.86	15.29
					05/11/20	PES	25.17	9.98
					07/13/20	PES	26.65	8.50
					07/21/20	PES	25.53	9.62
					08/04/20	PES	25.55	9.60
					08/17/20	PES	24.53	10.62
					09/03/20	PES	25.54	9.61
					09/21/20	PES	Inaccessible	
					11/16/20	PES	24.25	10.90
					02/01/21	PES	22.15	13.00
					06/07/21	PES	18.52	16.63
					08/16/21	PES	18.60	16.55
					02/14/22	PES	16.45	18.70
					05/16/22	PES	15.89	19.26
					08/08/22	PES	16.02	19.13
					11/07/22	PES	16.75	18.40
					02/21/23	PES	16.28	18.87
					05/08/23	PES	–	–
					08/10/23	PES	16.75	18.40
					10/30/23	PES	16.81	18.34
					03/01/24	PES	NM	–
					05/21/24	PES	15.85	19.30
					09/03/24	PES	16.60	18.55
					11/04/24	PES	16.67	18.48
G-MW1	Property, NW quadrant	30 to 35	–	–	07/24/01	GeoEngineers	10.54	
					01/29/09	DOF	11.25	
					02/19/10	SES	10.47	28.54
					06/03/11	SES	8.15	30.86
					02/07/12	Windward	9.34	29.67
					09/06/12	SES	11.11	27.90
					12/21/12	SES	9.04	29.97
					03/29/13	SES	10.11	28.90
HMW-11B	SDOT Mercer Parcels, NE quadrant	54.3 to 64.3	-16.0 to -26.0	38.38	Decommissioned			
					03/20/19	HC	19.29	19.09
					03/26/19	HC	19.47	18.91
					05/16/19	HC	19.22	19.16
					07/17/19	HC	19.89	18.49
					08/15/19	HC	20.25	18.13
					12/05/19	HC	21.91	16.47
					01/13/20	HC	20.79	17.59
					03/19/20	HC	28.58	9.80
					04/10/20	HC	29.39	8.99
					05/11/20	HC	29.90	8.48
					07/13/20	HC	30.57	7.81
					11/16/20	PES	30.10	8.28
					02/01/21	HC	25.55	12.83
					06/07/21	PES	22.60	15.78
					08/16/21	PES	22.52	15.86
					02/14/22	PES	19.59	18.79
					05/16/22	PES	19.26	19.12
					08/08/22	PES	19.38	19.00
					11/07/22	PES	20.04	18.34

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-1IB					02/22/23	PES	15.66	22.72
Continued					05/08/23	PES	19.02	19.36
					08/10/23	PES	20.02	18.36
					10/30/23	PES	20.00	18.38
					03/01/24	PES	18.68	19.70
HMW-2IB	SDOT Mercer Parcels, NE quadrant	52.8 to 62.8	-5.4 to -15.4	47.19	03/20/19	HC	27.50	19.69
					03/26/19	HC	27.32	19.87
					07/16/19	HC	28.29	18.90
					12/05/19	HC	30.51	16.68
					01/13/20	HC	31.02	16.17
					03/12/20	HC	36.15	11.04
					03/19/20	HC	36.33	10.86
					04/10/20	HC	37.11	10.08
					05/11/20	HC	37.68	9.51
					07/13/20	HC	38.41	8.78
					11/16/20	PES	37.62	9.57
					02/01/21	HC	33.32	13.87
					06/07/21	PES	31.03	16.16
					08/16/21	PES	30.94	16.25
					02/14/22	PES	27.87	19.32
					05/16/22	PES	27.64	19.55
					08/08/22	PES	27.71	19.48
					11/07/22	PES	28.45	18.74
					02/22/23	PES	27.63	19.56
					05/08/23	PES	27.40	19.79
					08/10/23	PES	28.47	18.72
					10/30/23	PES	28.41	18.78
					03/01/24	PES	26.85	20.34
HMW-4IA	SDOT Mercer Parcels, SW quadrant	50.0 to 60.0	8.7 to -1.3	58.53	03/19/19	HC	29.50	29.03
					03/26/19	HC	30.21	28.32
					07/17/19	HC	33.10	25.43
					12/05/19	HC	35.08	23.45
					01/13/20	HC	34.20	24.33
					03/19/20	HC	33.70	24.83
					04/10/20	HC	33.79	24.74
					05/11/20	HC	34.11	24.42
					07/13/20	HC	34.71	23.82
					02/01/21	HC	30.68	27.85
					06/07/21	PES	31.96	26.57
					02/14/22	PES	30.06	28.47
					05/16/22	PES	31.49	27.04
					08/08/22	PES	32.46	26.07
					11/07/22	PES	32.79	25.74
					02/21/23	PES	24.12	34.41
					05/08/23	PES	31.99	26.54
					08/10/23	PES	NM	–
					10/30/23	PES	NM	–
					03/01/24	PES	NM	–
HMW-5IB	SDOT Mercer Parcels, SW quadrant	49.7 to 59.7	8.7 to -1.3	60.99	03/19/20	HC	34.60	26.39
					05/11/20	HC	35.09	25.90
					07/13/20	HC	35.72	25.27
					11/16/20	PES	34.38	26.61
					02/01/21	HC	31.47	29.52
					06/07/21	PES	32.82	28.17
					08/16/21	PES	33.35	27.64
					02/14/22	PES	30.72	30.27

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-5IB Continued					05/16/22	PES	33.44	27.55
					08/08/22	PES	35.12	25.87
					02/22/23	PES	34.04	26.95
					05/08/23	PES	34.33	26.66
					08/10/23	PES	35.10	25.89
					10/30/23	PES	34.83	26.16
					03/01/24	PES	33.07	27.92
HMW-6IB	SDOT Mercer Parcels, SW quadrant	50.0 to 60.0	8.7 to -1.3	61.61	03/19/20	HC	34.87	26.74
					05/11/20	HC	35.22	26.39
					07/13/20	HC	36.01	25.60
					11/16/20	PES	36.06	25.55
					02/01/21	HC	33.86	27.75
					06/07/21	PES	34.70	26.91
					02/14/22	PES	33.21	28.40
					05/16/22	PES	34.06	27.55
					08/08/22	PES	34.78	26.83
					11/07/22	PES	35.29	26.32
					02/22/23	PES	34.06	27.55
					05/08/23	PES	34.36	27.25
					08/10/23	PES	34.23	27.38
					10/30/23	NM	NM	–
					03/01/24	PES	NM	–
HMW-7IB	SDOT Mercer Parcels, SW quadrant	49.7 to 59.7	9.0 to -1	61.38	03/19/20	HC	35.61	25.77
					05/11/20	HC	36.10	25.28
					07/13/20	HC	36.87	24.51
					11/16/20	PES	36.67	24.71
					02/01/21	HC	34.54	26.84
					06/07/21	PES	35.42	25.96
					08/16/21	PES	35.72	25.66
					02/14/22	PES	33.70	27.68
					05/16/22	PES	34.49	26.89
					08/08/22	PES	35.22	26.16
					11/07/22	PES	35.62	25.76
					02/22/23	PES	34.51	26.87
					05/08/23	PES	34.86	26.52
					08/10/23	PES	35.46	25.92
					10/30/23	PES	35.35	26.03
					03/01/24	PES	34.80	26.58
HMW-8IB	SDOT Mercer Parcels, SW quadrant	50.5 to 60.5	7.5 to -2.5	60.78	03/19/20	HC	36.69	24.09
					05/11/20	HC	37.08	23.70
					07/13/20	HC	37.62	23.16
					11/16/20	PES	35.59	25.19
					02/01/21	HC	33.26	27.52
					06/07/21	PES	34.73	26.05
					08/16/21	PES	35.07	25.71
					02/14/22	PES	32.92	27.86
					05/16/22	PES	33.98	26.80
					08/08/22	PES	38.05	22.73
					11/07/22	PES	35.26	25.52
					02/22/23	PES	34.21	26.57
					05/08/23	PES	34.53	26.25
					08/10/23	PES	35.27	25.51
					10/30/23	PES	34.94	25.84
					03/01/24	PES	NM	–

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-9IB	SDOT Mercer Parcels, SW quadrant	57.0 to 67.0	-1.6 to -11.6	57.89	03/19/20	HC	36.54	21.35
					05/11/20	HC	37.15	20.74
					07/13/20	HC	37.60	20.29
					11/16/20	PES	32.81	25.08
					02/01/21	HC	29.99	27.90
					06/07/21	PES	32.33	25.56
					08/16/21	PES	32.66	25.23
					02/14/22	PES	29.98	27.91
					05/16/22	PES	32.65	25.24
					08/08/22	PES	34.11	23.78
					11/07/22	PES	34.32	23.57
					02/22/23	PES	33.18	24.71
					05/08/23	PES	33.66	24.23
					08/10/23	PES	34.66	23.23
					10/30/23	PES	34.27	23.62
					03/01/24	PES	32.54	25.35
					05/20/24	PES	34.04	23.85
					09/04/24	PES	34.25	23.64
					11/04/24	PES	33.60	24.29
HMW-11IB	SDOT Mercer Parcels, SE quadrant	44.9 to 54.9	-5.2 to -15.2	42.91	03/19/20	HC	33.50	9.41
					05/11/20	HC	35.06	7.85
					07/13/20	HC	35.81	7.10
					11/16/20	PES	35.41	7.50
					02/01/21	HC	30.61	12.30
					06/07/21	PES	27.56	15.35
					08/16/21	PES	27.31	15.60
					02/14/22	PES	20.52	22.39
					05/16/22	PES	23.87	19.04
					08/08/22	PES	23.95	18.96
					11/07/22	PES	24.59	18.32
					02/22/23	PES	23.77	19.14
					05/08/23	PES	23.55	19.36
					08/10/23	PES	24.50	18.41
					10/30/23	PES	24.47	18.44
					03/01/24	PES	22.96	19.95
HMW-15IB	SDOT Mercer Parcels, SW quadrant	64.0 to 73.0	-5.1 to -14.1	58.33	11/16/20	PES	41.03	17.30
					02/01/21	HC	39.61	18.72
					06/07/21	PES	38.80	19.53
					08/16/21	PES	38.41	19.92
					02/14/22	PES	35.88	22.45
					05/16/22	PES	36.10	22.23
					08/08/22	PES	35.46	22.87
					11/07/22	PES	36.30	22.03
					02/21/23	PES	35.55	22.78
					05/08/23	PES	35.63	22.70
					08/10/23	PES	35.71	22.62
					10/30/23	PES	35.44	22.89
					03/01/24	PES	34.11	24.22
HMW-16IB	SDOT Mercer Parcels, NW quadrant	55.0 to 65.0	2.0 to -8.0	56.80	11/16/20	PES	34.59	22.21
					02/01/21	HC	33.08	23.72
					06/07/21	PES	33.97	22.83
					08/16/21	PES	34.38	22.42
					02/14/22	PES	32.28	24.52
					05/16/22	PES	29.87	26.93
					08/08/22	PES	31.25	25.55
					11/07/22	PES	30.85	25.95

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-16IB Continued					02/22/23	PES	28.94	27.86
					05/08/23	PES	28.96	27.84
					08/10/23	PES	30.10	26.70
					10/30/23	PES	29.62	27.18
					03/01/24	PES	27.64	29.16
MW111	Alley E of Seattle Roy Aloha Shops	70 to 80	-33.5 to -43.5	36.48	12/21/12	SES	17.45	19.03
				36.38	03/29/13	SES	20.17	16.31
					01/06/14	SES	26.54	9.94
					04/22/15	SES	20.05	16.43
					06/16/15	SES	19.90	16.58
					10/19/15	SES	21.67	14.81
					02/01/16	SES	21.25	15.23
					03/20/17	PES	18.24	18.24
					03/24/17	PES	16.82	19.66
					06/12/17	PES	25.23	11.25
					10/11/17	PES	33.74	2.74
					03/14/19	PES	18.36	18.12
					04/22/19	PES	17.44	19.04
					07/16/19	PES	17.96	18.52
					10/21/19	PES	19.57	16.91
					01/13/20	PES	21.12	15.26
					05/11/20	PES	26.42	9.96
					07/13/20	PES	26.88	9.50
					07/21/20	PES	26.96	9.42
					08/04/20	PES	26.96	9.42
					08/17/20	PES	26.95	9.43
					09/03/20	PES	26.97	9.41
					09/21/20	PES	Inaccessible	
					11/16/20	PES	26.40	9.98
					02/01/21	PES	22.77	13.61
					06/07/21	PES	19.96	16.42
					08/16/21	PES	20.00	16.38
					02/14/22	PES	17.72	18.66
					05/16/22	PES	17.26	19.12
					08/08/22	PES	17.27	19.11
					11/07/22	PES	17.90	18.48
					02/21/23	PES	17.51	18.87
					05/08/23	PES	17.10	19.28
					08/10/23	PES	18.07	18.31
					10/30/23	PES	18.11	18.27
					02/28/24	PES	17.12	19.26
					05/20/24	PES	17.55	18.83
					09/03/24	PES	17.85	18.53
					11/04/24	PES	17.88	18.50
MW112	Dexter Ave N ROW, E side	75 to 85	-17.2 to -27.2	57.49	12/21/12	SES	42.45	15.04
				57.45	03/29/13	SES	38.76	18.73
					01/06/14	SES	40.79	16.70
					06/16/15	SES	39.40	18.09
					03/20/17	PES	36.65	20.80
					03/24/17	PES	36.46	20.99
					06/12/17	PES	38.72	18.73
					10/11/17	PES	40.46	16.99
					03/14/19	PES	36.62	20.83
					04/22/19	PES	34.71	22.74
					07/16/19	PES	37.13	20.32
					10/21/19	PES	40.90	16.55

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW112				57.47	01/13/20	PES	39.66	17.81
					05/11/20	PES	42.60	14.87
					07/13/20	PES	42.51	14.96
					11/16/20	PES	40.02	17.45
					02/01/21	PES	38.03	19.44
					06/07/21	PES	37.61	19.86
					08/16/21	PES	37.49	19.98
					02/14/22	PES	35.64	21.83
					05/16/22	PES	36.43	21.04
					08/08/22	PES	37.11	20.36
					11/07/22	PES	36.72	20.75
					02/21/23	PES	–	
					05/08/23	PES	36.00	21.47
					08/10/23	PES	Inaccessible	–
MW112R	Dexter Ave N ROW, E side	75 to 85			10/30/23	PES	35.99	
					03/01/24	PES	35.20	
					05/20/24	PES	35.65	
					09/03/24	PES	35.91	
					11/04/24	PES	29.97	
MW126	Alley E of Seattle Roy Aloha Shops	85 to 95	-54.1 to -64.1	30.94	01/06/14	SES	18.08	12.86
					03/20/17	PES	12.75	18.19
					03/24/17	PES	13.35	17.59
					06/12/17	PES	24.98	5.96
					10/11/17	PES	24.24	6.70
					03/14/19	PES	12.88	18.06
					04/22/19	PES	12.62	18.32
					07/16/19	PES	12.92	18.02
					10/25/19	PES	14.09	16.85
					01/13/20	PES	15.13	15.81
					02/19/20	PES	17.50	13.44
					05/11/20	PES	18.91	12.03
					07/13/20	PES	19.32	11.62
					11/16/20	PES	19.24	11.70
					02/01/21	PES	16.95	13.99
					06/07/21	PES	14.75	16.19
					08/16/21	PES	12.70	18.24
					02/14/22	PES	12.94	18.00
					05/16/22	PES	12.45	18.49
					08/08/22	PES	12.26	18.68
					11/07/22	PES	12.78	18.16
					02/21/23	PES	12.60	18.34
					05/08/23	PES	12.18	18.76
					08/10/23	PES	12.96	17.98
					10/30/23	PES	13.10	17.84
					02/28/24	PES	12.29	18.65
					05/20/24	PES	11.77	19.17
					09/03/24	PES	12.71	18.23
					11/04/24	PES	12.69	18.25
MW130	Property, NW quadrant	70 to 80	-30.9 to -40.9	39.55	03/20/17	PES	21.21	18.34
					03/24/17	PES	22.54	17.01
					04/14/17	PES	23.35	16.20
					04/28/17	PES	23.89	15.66
					05/05/17	PES	23.30	16.25
					05/12/17	PES	23.65	15.90
					05/19/17	PES	23.81	15.74
					06/12/17	PES	24.28	15.27

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

[illegible]

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-145R Continued					08/17/20	PES	28.31	13.69
					09/03/20	PES	28.07	13.93
					09/21/20	PES	Inaccessible	
					11/16/20	PES	25.63	16.37
					02/01/21	PES	23.83	18.17
					06/07/21	PES	22.70	19.30
					08/16/21	PES	22.53	19.47
					02/14/22	PES	19.77	22.23
					05/16/22	PES	20.18	21.82
					08/08/22	PES	20.78	21.22
					11/07/22	PES	21.10	20.90
					02/21/23	PES	20.16	21.84
					05/08/23	PES	20.52	21.48
					08/10/23	PES	21.31	20.69
					10/30/23	PES	21.28	20.72
					03/01/24	PES	20.19	21.81
					05/20/24	PES	20.75	21.25
					09/03/24	PES	Inaccessible	
					11/04/24	PES	20.88	21.12
MW-147	Roy St ROW, S side	70 to 80	-17.6 to -27.6	51.85	03/14/19	PES	25.65	26.20
					03/26/19	HC	26.36	25.49
					04/22/19	PES	27.14	24.71
					07/16/19	PES	31.10	20.75
					07/17/19	HC	31.53	20.32
					10/21/19	PES	36.23	15.62
					01/13/20	PES	34.45	17.40
					03/19/20	HC	37.68	14.17
					05/11/20	PES	38.56	13.29
					07/13/20	PES	38.50	13.35
					07/21/20	PES	36.31	15.54
					08/04/20	PES	35.50	16.35
					08/17/20	PES	35.22	16.63
					09/03/20	PES	34.71	17.14
					09/21/20	PES	34.33	17.52
					11/16/20	PES	30.25	21.60
					02/01/21	PES	27.75	24.10
					06/07/21	PES	29.32	22.53
					08/16/21	PES	29.37	22.48
					02/14/22	PES	25.91	25.94
					05/16/22	PES	28.23	23.62
					08/08/22	PES	28.16	23.69
					11/07/22	PES	28.27	23.58
					02/22/23	PES	26.80	25.05
					05/08/23	PES	28.24	23.61
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	30.38	21.47
					03/01/24	PES	32.01	19.84
					05/20/24	PES	29.82	22.03
					09/03/24	PES	30.19	21.66
					11/04/24	PES	30.08	21.77
MW-148	Roy St ROW, S side	70 to 80	-25.7 to -35.7	43.91	03/14/19	PES	24.31	19.60
					03/26/19	HC	24.21	19.70
					04/22/19	PES	24.26	19.65
					07/16/19	PES	25.21	18.70
					10/21/19	PES	26.92	16.99
					01/13/20	PES	28.07	15.84

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-148 Continued					03/19/20	HC	32.80	11.11
					05/11/20	PES	33.80	10.11
					07/13/20	PES	34.47	9.44
					07/21/20	PES	34.45	9.46
					08/04/20	PES	34.50	9.41
					08/17/20	PES	34.45	9.46
					09/03/20	PES	34.43	9.48
					09/21/20	PES	34.41	9.50
					11/16/20	PES	33.50	10.41
					02/01/21	PES	Inaccessible	
					06/07/21	PES	Inaccessible	
					08/16/21	PES	27.31	16.60
					02/14/22	PES	24.53	19.38
					05/16/22	PES	24.20	19.71
					08/08/22	PES	24.40	19.51
					11/07/22	PES	25.18	18.73
					02/21/23	PES	24.35	19.56
					05/08/23	PES	24.29	19.62
					08/10/23	PES	25.30	18.61
					10/30/23	PES	25.20	18.71
					03/01/24	PES	24.04	19.87
					05/20/24	PES	24.50	19.41
					09/03/24	PES	24.97	18.94
					11/04/24	PES	25.92	17.99
MW-150	Property, NE quadrant	49 to 59	-13.3 to -23.3	35.39	03/14/19	PES	3.58	31.81
					Decommissioned March 2019			
MW-152	Property, SW quadrant	50 to 60	-10.2 to -20.2	39.11	03/14/19	PES	5.21	33.90
					Decommissioned March 2019			
MW-157	8th Ave N ROW, E side	70 to 80	-28.3 to -38.2	41.22	01/24/19	PES	14.00	27.22
					03/14/19	PES	14.94	26.28
					04/22/19	PES	15.32	25.90
					07/16/19	PES	18.86	22.36
					10/21/19	PES	28.18	13.04
					01/13/20	PES	28.77	12.45
					05/11/20	PES	31.11	10.11
					07/13/20	PES	30.92	10.30
					07/21/20	PES	27.90	13.32
					08/04/20	PES	26.35	14.87
					08/17/20	PES	25.50	15.72
					09/03/20	PES	25.09	16.13
					09/21/20	PES	24.83	16.39
					11/16/20	PES	23.56	17.66
					02/01/21	PES	22.43	18.79
					06/07/21	PES	–	
					08/16/21	PES	21.57	19.65
					02/14/22	PES	19.23	21.99
					05/16/22	PES	–	
					08/08/22	PES	19.49	21.73
					11/07/22	PES	–	
					02/21/23	PES	–	
					05/08/23	PES	19.68	21.54
					08/10/23	PES	19.85	21.37
					10/30/23	PES	Not Measured	–
					03/01/24	PES	19.75	21.47
					05/20/24	PES	20.09	21.13
					09/03/24	PES	20.22	21.00
					11/04/24	PES	20.38	20.84

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-190	Valley St ROW, S side	78.8 to 88.8	-30.2 to -40.2	48.39	10/21/19	PES	34.03	14.36
				01/13/20	PES	33.33	15.06	
				05/11/20	PES	35.32	13.07	
				07/13/20	PES	35.30	13.09	
				07/21/20	PES	34.53	13.86	
				08/04/20	PES	33.54	14.85	
				08/17/20	PES	31.01	17.38	
				09/03/20	PES	30.59	17.80	
				09/21/20	PES	30.30	18.09	
				11/16/20	PES	27.40	20.99	
				02/01/21	PES	24.36	24.03	
				06/07/21	PES	25.40	22.99	
				08/16/21	PES	27.23	21.16	
				02/14/22	PES	26.90	22.05	
				05/16/22	PES	25.95	23.00	
				08/08/22	PES	27.66	21.29	
				11/07/22	PES	27.91	21.04	
				02/21/23	PES	27.54	21.41	
				05/08/23	PES	27.94	21.01	
				08/10/23	PES	28.31	20.64	
				10/30/23	PES	28.34	20.61	
				03/01/24	PES	27.09	21.86	
				05/20/24	PES	28.04	20.91	
				09/03/24	PES	29.02	19.93	
				11/04/24	PES	29.06	19.89	
MW-303	Dexter Ave N ROW, E side	71.4 to 81.4	-13.8 to -23.8	57.28	10/21/19	PES	44.60	12.68
				01/13/20	PES	40.00	17.28	
				05/11/20	PES	42.21	15.07	
				07/13/20	PES	42.42	14.86	
				11/16/20	PES	38.75	18.53	
				02/01/21	PES	36.39	20.89	
				06/07/21	PES	37.20	20.08	
				08/16/21	PES	36.15	21.13	
				02/14/22	PES	34.45	22.82	
				05/16/22	PES	34.89	22.38	
				08/08/22	PES	35.69	21.58	
				11/07/22	PES	35.17	22.10	
				02/21/23	PES	—	—	
				05/08/23	PES	34.73	22.54	
				08/10/23	PES	Inaccessible	—	
				10/30/23	PES	34.96	22.31	
				03/01/24	PES	34.40	22.87	
				05/20/24	PES	35.30	21.97	
				09/03/24	PES	35.04	22.23	
				11/04/24	PES	34.62	22.65	
MW-307	Roy St ROW, S side	72.8 to 82.8	-12.4 to -22.4	60.21	10/21/19	PES	41.65	18.56
				01/13/20	PES	41.55	18.66	
				03/19/20	HC	43.34	16.87	
				05/11/20	PES	43.90	16.31	
				07/13/20	PES	44.69	15.52	
				07/21/20	PES	44.14	16.07	
				08/04/20	PES	44.28	15.93	
				08/17/20	PES	44.24	15.97	
				09/03/20	PES	44.47	15.74	
				09/21/20	PES	44.33	15.88	
				11/16/20	PES	43.88	16.33	

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-307 Continued					02/01/21	PES	42.38	17.83
					06/07/21	PES	41.94	18.27
					08/16/21	PES	41.66	18.55
					02/14/22	PES	39.11	21.10
					05/16/22	PES	40.85	19.36
					08/08/22	PES	41.78	18.43
					11/07/22	PES	41.07	19.14
					02/21/23	PES	13.65	46.56
					05/08/23	PES	40.91	19.30
					08/10/23	PES	41.04	19.17
					10/30/23	PES	41.21	19.00
					03/01/24	PES	40.32	19.89
					05/20/24	PES	41.27	18.94
					09/03/24	PES	40.90	19.31
					11/04/24	PES	40.76	19.45
MW-309	Alley E of Seattle Roy Aloha Shops	62.4 to 72.4	-32.0 to -42.0	29.97	10/21/19	PES	12.91	17.06
					01/13/20	PES	14.15	15.82
					05/11/20	PES	18.49	11.48
					07/13/20	PES	18.81	11.16
					11/16/20	PES	17.92	12.05
					02/01/21	PES	14.80	15.17
					06/07/21	PES	12.43	17.54
					08/16/21	PES	12.64	17.33
					02/14/22	PES	10.79	19.18
					05/16/22	PES	10.26	19.71
					08/08/22	PES	10.40	19.57
					11/07/22	PES	11.08	18.89
					02/21/23	PES	10.89	19.08
					05/08/23	PES	10.28	19.69
					08/10/23	PES	11.22	18.75
					10/30/23	PES	11.19	18.78
					02/28/24	PES	10.24	19.73
					05/20/24	PES	10.38	19.59
					09/03/24	PES	10.91	19.06
					11/04/24	PES	10.93	19.04
MW-311	Alley E of Seattle Roy Aloha Shops	62.2 to 72.2	-29.0 to -39.0	32.98	10/21/19	PES	16.45	16.53
					01/13/20	PES	17.81	15.17
					05/11/20	PES	22.42	10.56
					07/13/20	PES	22.76	10.22
					11/16/20	PES	21.29	11.69
					02/01/21	PES	17.67	15.31
					06/07/21	PES	15.30	17.68
					08/16/21	PES	15.53	17.45
					02/14/22	PES	13.50	19.48
					05/16/22	PES	13.06	19.92
					08/08/22	PES	13.25	19.73
					11/07/22	PES	13.88	19.10
					02/21/23	PES	13.52	19.46
					05/08/23	PES	13.12	19.86
					08/10/23	PES	14.08	18.90
					10/30/23	PES	11.29	21.69
					02/28/24	PES	13.03	19.95
					05/20/24	PES	13.40	19.58
					09/03/24	PES	13.71	19.27
					11/04/24	PES	13.78	19.20

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-314	Alley E of Seattle Roy Aloha Shops	67.8 to 77.8	-28.0 to -38.0	39.19	10/21/19	PES	22.34	16.85
					01/13/20	PES	23.83	15.36
					05/11/20	PES	29.54	9.65
					07/13/20	PES	30.02	9.17
					11/16/20	PES	30.49	8.70
					02/01/21	PES	25.45	13.74
					06/07/21	PES	22.80	16.39
					08/16/21	PES	22.82	16.37
					02/14/22	PES	20.40	18.79
					05/16/22	PES	19.96	19.23
					08/08/22	PES	20.80	18.39
					11/07/22	PES	20.76	18.43
					02/21/23	PES	20.31	18.88
					05/08/23	PES	19.88	19.31
					08/10/23	PES	20.90	18.29
					10/30/23	PES	20.91	18.28
					02/28/24	PES	19.69	19.50
					05/20/24	PES	20.10	19.09
MW-316	Mercer St ROW, N side	59.8 to 69.8	-10.0 to -20.0	49.44	10/21/19	PES	31.72	17.72
					01/13/20	PES	32.70	16.74
					03/19/20	HC	37.66	11.78
					05/11/20	PES	38.95	10.49
					07/13/20	PES	39.74	9.70
					09/21/20	PES	39.78	9.66
					11/16/20	PES	38.97	10.47
					02/01/21	PES	35.07	14.37
					06/07/21	PES	33.10	16.34
					08/16/21	PES	32.91	16.53
					02/14/22	PES	29.83	19.61
					05/16/22	PES	29.65	19.79
					08/08/22	PES	29.56	19.88
					11/07/22	PES	30.32	19.12
					02/21/23	PES	29.35	20.09
					05/08/23	PES	29.50	19.94
					08/10/23	PES	30.26	19.18
					10/30/23	PES	30.24	19.20
MW-318	9th Ave N ROW, W side	54.8 to 64.8	-23.1 to -33.1	31.36	10/21/19	PES	14.56	16.80
					01/13/20	PES	16.06	15.30
					05/11/20	PES	20.82	10.54
					07/13/20	PES	21.27	10.09
					11/16/20	PES	20.88	10.48
					02/01/21	PES	17.60	13.76
					06/07/21	PES	14.81	16.55
					08/16/21	PES	14.91	16.45
					02/14/22	PES	13.08	18.28
					05/16/22	PES	12.41	18.95
					08/08/22	PES	12.44	18.92
					11/07/22	PES	13.16	18.20
					02/22/23	PES	12.86	18.50
					05/08/23	PES	12.30	19.06

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-318 Continued					08/10/23	PES	13.21	18.15
					10/30/23	PES	13.27	18.09
					03/01/24	PES	12.37	18.99
					05/20/24	PES	12.41	18.95
					09/03/24	PES	13.03	18.33
					11/04/24	PES	13.10	18.26
MW-322	9th Ave N ROW, W side	54.7 to 64.7	-21.2 to -31.2	33.13	10/21/19	PES	16.41	16.72
					01/13/20	PES	18.02	15.11
					05/11/20	PES	23.22	9.91
					07/13/20	PES	23.70	9.43
					11/16/20	PES	23.41	9.72
					02/01/21	PES	19.71	13.42
					06/07/21	PES	16.76	16.37
					08/16/21	PES	16.84	16.29
					02/14/22	PES	14.92	18.21
					05/16/22	PES	14.48	18.65
					08/08/22	PES	14.28	18.85
					11/07/22	PES	15.00	18.13
					02/22/23	PES	14.63	18.50
					05/08/23	PES	14.08	19.05
					08/10/23	PES	15.01	18.12
					10/30/23	PES	15.08	18.05
					03/01/24	PES	14.20	18.93
					05/20/24	PES	14.22	18.91
					09/03/24	PES	14.83	18.30
					11/04/24	PES	14.90	18.23
MW-334	900 Roy St, S end	53.1 to 63.1	-21.88 to -31.88	31.22	05/11/20	PES	22.02	9.20
					07/13/20	PES	22.41	8.81
					11/16/20	PES	22.02	9.20
					02/01/21	PES	18.38	12.84
					06/07/21	PES	15.21	16.01
					08/16/21	PES	15.26	15.96
					02/14/22	PES	13.37	17.85
					05/16/22	PES	12.60	18.62
					08/08/22	PES	12.60	18.62
					11/07/22	PES	13.32	17.90
					02/21/23	PES	Inaccessible	–
					05/08/23	PES	Inaccessible	–
					08/10/23	PES	13.36	17.86
					10/30/23	PES	13.94	17.28
					03/01/24	PES	Inaccessible	–
					05/20/24	PES	12.55	18.67
					09/03/24	PES	13.14	18.08
					11/04/24	PES	13.16	18.06
MW-335	Mercer St ROW, N side	60.8 to 70.8	-26.54 to -36.54	34.26	05/11/20	PES	29.24	5.02
					07/13/20	PES	29.85	4.41
					11/16/20	PES	29.05	5.21
					02/01/21	PES	23.75	10.51
					06/07/21	PES	19.40	14.86
					08/16/21	PES	19.05	15.21
					02/14/22	PES	15.68	18.58
					05/16/22	PES	15.93	18.33
					08/08/22	PES	15.77	18.49
					11/07/22	PES	16.36	17.90
					02/21/23	PES	15.88	18.38
					05/08/23	PES	15.60	18.66

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-335 Continued					08/10/23	PES	16.34	17.92
					10/30/23	PES	16.43	17.83
					03/01/24	PES	15.67	18.59
					05/20/24	PES	15.36	18.90
					09/03/24	PES	16.23	18.03
					11/04/24	PES	16.18	18.08
MW-338	Lake Union Park, N end	44.4 to 54.4	-17.02 to -27.02	27.38	05/11/20	PES	15.45	11.93
					07/13/20	PES	15.77	11.61
					11/16/20	PES	15.92	11.46
					02/01/21	PES	13.24	14.14
					06/07/21	PES	10.60	16.78
					08/16/21	PES	10.97	16.41
					02/14/22	PES	9.64	17.74
					05/16/22	PES	8.66	18.72
					08/08/22	PES	8.85	18.53
					11/07/22	PES	9.49	17.89
					02/21/23	PES	9.33	18.05
					05/08/23	PES	8.65	18.73
					08/10/23	PES	9.58	17.80
					10/30/23	PES	9.67	17.71
					03/01/24	PES	9.00	18.38
					05/20/24	PES	8.51	18.87
					09/03/24	PES	9.36	18.02
					11/04/24	PES	9.39	17.99
MW-340	Lake Union Park, S end	44.4 to 54.4	-16.38 to 26.38	28.02	05/11/20	PES	17.35	10.67
					07/13/20	PES	17.65	10.37
					11/16/20	PES	17.53	10.49
					02/01/21	PES	14.54	13.48
					06/07/21	PES	11.63	16.39
					08/16/21	PES	11.94	16.08
					02/14/22	PES	10.43	17.59
					05/16/22	PES	9.39	18.63
					08/08/22	PES	9.52	18.50
					11/07/22	PES	10.25	17.77
					02/21/23	PES	10.03	17.99
					05/08/23	PES	9.55	18.47
					08/10/23	PES	9.36	18.66
					10/30/23	PES	10.34	17.68
					03/01/24	PES	10.00	18.02
					05/20/24	PES	9.30	18.72
					09/03/24	PES	10.10	17.92
					11/04/24	PES	10.05	17.97
MW-345	SDOT Mercer Parcels, NW quadrant	54.4 to 64.4	-1.6 to -11.6	52.61	06/07/21	PES	28.30	24.31
					08/16/21	PES	28.42	24.19
					02/14/22	PES	24.92	27.69
					05/16/22	PES	26.34	26.27
					08/08/22	PES	28.01	24.60
					11/07/22	PES	28.00	24.61
					02/22/23	PES	26.48	26.13
					05/08/23	PES	Inaccessible	–
					08/10/23	PES	28.02	24.59
					10/30/23	PES	27.96	24.65
					03/01/24	PES	26.07	26.54
					05/20/24	PES	27.36	25.25
					09/04/24	PES	Inaccessible	
					11/21/24	PES	27.76	24.85

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-346	SDOT Mercer Parcels, NW quadrant	53.9 to 63.9	-2.2 to -12.2	51.63	06/07/21	PES	28.91	22.72
					08/16/21	PES	29.30	22.33
					02/14/22	PES	25.95	25.68
					05/16/22	PES	26.34	25.29
					08/08/22	PES	28.58	23.05
					11/07/22	PES	28.09	23.54
					02/22/23	PES	19.00	32.63
					05/08/23	PES	27.54	24.09
					08/10/23	PES	29.05	22.58
					10/30/23	PES	28.23	23.40
					03/01/24	PES	25.70	25.93
					05/20/24	PES	28.30	23.33
					09/04/24	PES	28.74	22.89
					11/04/24	PES	27.69	23.94
MW-347	SDOT Mercer Parcels, NW quadrant	54.0 to 64.0	-1.3 to -11.3	52.70	06/07/21	PES	29.97	22.73
					08/16/21	PES	30.19	22.51
					02/14/22	PES	26.80	25.90
					05/16/22	PES	27.61	25.09
					08/08/22	PES	29.56	23.14
					11/07/22	PES	26.62	26.08
					02/22/23	PES	26.00	26.70
					05/08/23	PES	28.65	24.05
					08/10/23	PES	30.08	22.62
					10/30/23	PES	29.23	23.47
					03/01/24	PES	27.09	25.61
					05/20/24	PES	29.41	23.29
					09/04/24	PES	29.91	22.79
					11/04/24	PES	29.00	23.70
MW-348	SDOT Mercer Parcels, SW quadrant	58.6 to 68.6	-4.6 to -14.6	53.84	06/07/21	PES	31.11	22.73
					08/16/21	PES	31.44	22.40
					02/14/22	PES	28.36	25.48
					05/16/22	PES	28.87	24.97
					08/08/22	PES	30.73	23.11
					11/07/22	PES	30.55	23.29
					02/22/23	PES	26.68	27.16
					05/08/23	PES	29.82	24.02
					08/10/23	PES	31.24	22.60
					10/30/23	PES	Not Measured	
					03/01/24	PES		25.60
					05/20/24	PES		23.30
					09/04/24	PES		22.73
					11/04/24	PES	28.90	24.94
MW-349	SDOT Mercer Parcels, SW quadrant	58.6 to 68.6	-2.8 to -12.8	55.58	06/07/21	PES	31.02	24.56
					08/16/21	PES	31.25	24.33
					02/14/22	PES	28.79	26.79
					05/16/22	PES	29.92	25.66
					08/08/22	PES	32.02	23.56
					11/07/22	PES	30.03	25.55
					02/22/23	PES	25.25	30.33
					05/08/23	PES	31.99	23.59
					08/10/23	PES	32.97	22.61
					10/30/23	PES	32.69	22.89
					03/01/24	PES	30.99	24.59
					05/20/24	PES	32.56	23.02
					09/04/24	PES	32.85	22.73
					11/04/24	PES	32.41	23.17

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-350	SDOT Mercer Parcels, NW quadrant	59.4 to 69.4	-1.7 to -11.7	57.55	06/07/21	PES	35.53	22.02
					08/16/21	PES	35.50	22.05
					02/14/22	PES	33.19	24.36
					05/16/22	PES	34.09	23.46
					08/08/22	PES	35.11	22.44
					11/07/22	PES	35.13	22.42
					02/22/23	PES	34.30	23.25
					05/08/23	PES	34.63	22.92
					08/10/23	PES	35.32	22.23
					10/30/23	PES	35.11	22.44
					03/01/24	PES	33.80	23.75
					05/20/24	PES	34.85	22.70
					09/04/24	PES	35.12	22.43
					11/04/24	PES	34.97	22.58
MW-351	Roy St ROW, S side	35.4 to 45.4	2.7 to -7.3	38.1	05/08/23	PES	17.68	20.42
					08/10/23	PES	18.72	19.38
					10/30/23	PES	18.65	19.45
					03/01/24	PES	17.55	20.55
					05/20/24	PES	17.90	20.20
					09/03/24	PES	18.50	19.60
OW-1	Alley E of Block 38 West	30.0 to 45.0	-6.0 to -21.0	24.17	02/14/22	Farallon	7.42	16.75
					05/16/22	Farallon	6.67	17.50
					08/08/22	Farallon	6.34	17.83
					11/07/22	Farallon	6.72	17.45
					02/21/23	Farallon	6.39	17.78
					05/08/23	Farallon	6.26	17.91
					08/10/23	Farallon	6.66	17.51
					10/30/23	Farallon	6.78	17.39
OW-2	Alley E of Block 38 West	30.0 to 45.0	-7.0 to -22.0	22.91	02/14/22	Farallon	6.07	16.84
					05/16/22	Farallon	5.57	17.34
					08/08/22	Farallon	5.20	17.71
					11/07/22	Farallon	5.57	17.34
					02/21/23	Farallon	5.16	17.75
					05/08/23	Farallon	5.34	17.57
					08/10/23	Farallon	5.46	17.45
					10/30/23	Farallon	5.57	17.34
OW-3	Block 38 West, S end	48.0 to 63.0	-8.0 to -23.0	38.91	02/15/22	Farallon	21.88	17.03
					05/16/22	Farallon	21.12	17.79
					08/08/22	Farallon	20.79	18.12
					11/07/22	Farallon	21.18	17.73
					02/21/23	Farallon	20.66	18.25
					05/08/23	Farallon	20.85	18.06
					08/10/23	Farallon	20.89	18.02
					10/30/23	Farallon	20.99	17.92
OW-5	Block 38 West, N end	44.8 to 54.8	-11.0 to -21.0	40.44	02/14/22	Farallon	17.14	23.30
				34.57	05/16/22	Farallon	14.11	20.46
					08/08/22	Farallon	14.01	20.56
					11/07/22	Farallon	14.52	20.05
					02/21/23	Farallon	14.19	20.38
					05/08/23	Farallon	13.46	21.11
					08/10/23	Farallon	14.59	19.98
					10/30/23	Farallon	14.77	19.80

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
W-MW-01	8th Ave N ROW, W side	70 to 80	-25.1 to -35.1	44.88	02/07/12	Windward	21.22	23.66
					09/06/12	SES	23.26	21.62
					12/21/12	SES	21.82	23.06
					03/29/13	SES	23.63	21.25
					01/06/14	SES	28.96	15.92
					06/16/15	SES	24.60	20.28
					10/19/15	SES	26.86	18.02
					02/01/16	SES	25.26	19.62
					03/20/17	PES	21.02	23.86
					03/24/17	PES	21.85	23.03
					04/14/17	PES	22.11	22.77
					04/28/17	PES	25.09	19.79
					05/05/17	PES	25.33	19.55
					05/12/17	PES	25.88	19.00
					05/19/17	PES	26.09	18.79
					06/12/17	PES	29.15	15.73
					10/11/17	PES	31.50	13.38
					03/14/19	PES	21.77	23.11
					04/22/19	PES	–	
					07/16/19	PES	–	
					05/11/20	PES	–	
					07/13/20	PES	–	
					09/03/20	PES	30.18	14.70
					11/16/20	PES	27.43	17.45
					02/01/21	PES	24.80	20.08
					06/07/21	PES	25.65	19.23
				44.50	08/16/21	PES	Inaccessible	
					02/14/22	PES	22.65	22.23
					05/16/22	PES	23.03	21.85
					08/08/22	PES	23.85	21.03
					11/07/22	PES	23.83	21.05
					02/21/23	PES	22.77	22.11
					05/08/23	PES	17.05	27.83
					08/10/23	PES	24.27	20.61
					10/30/23	PES	24.10	20.78
					03/01/24	PES	15.10	29.78
					05/20/24	PES	24.20	20.68
					09/03/24	PES	19.61	25.27
					11/04/24	PES	23.58	21.30
W-MW-02	8th Ave N ROW, W side	70 to 80	-26.3 to -36.5	43.46	02/07/12	Windward	17.51	25.95
					09/05/12	SES	19.95	23.51
					12/21/12	SES	17.82	25.64
					03/29/13	SES	19.14	24.32
					01/06/14	SES	24.40	19.06
					06/16/15	SES	18.79	24.67
					10/19/15	SES	20.94	22.52
					02/01/16	SES	15.85	27.61
					03/20/17	PES	15.24	28.22
					03/24/17	PES	14.97	28.49
					04/14/17	PES	15.34	28.12
					04/28/17	PES	18.18	25.28
					05/05/17	PES	18.53	24.93
					05/12/17	PES	19.10	24.36
					05/19/17	PES	19.28	24.18
					06/12/17	PES	22.83	20.63
					10/11/17	PES	27.86	15.60

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
W-MW-02 Continued				42.89	03/14/19	PES	15.46	28.00
					04/22/19	PES	16.13	27.33
					07/16/19	PES	–	
					07/23/19	PES	21.71	21.75
					10/21/19	PES	31.93	11.53
					01/13/20	PES	–	
					05/11/20	PES	33.88	9.58
					07/13/20	PES	34.15	9.31
					07/21/20	PES	30.60	12.86
					08/04/20	PES	28.25	15.21
					08/17/20	PES	27.32	16.14
					09/03/20	PES	26.85	16.61
					09/21/20	PES	26.46	17.00
					11/16/20	PES	22.94	20.52
					02/01/21	PES	19.88	23.58
					06/07/21	PES	–	
					08/16/21	PES	–	
					02/14/22	PES	–	
					05/16/22	PES	–	
					08/08/22	PES	–	
					11/07/22	PES	–	
					02/21/23	PES	–	
					05/08/23	PES	–	
					08/10/23	PES	17.50	25.96
					10/30/23	PES	NM	–
					03/01/24	PES	18.38	25.08
					05/08/24	PES	NM	
					09/03/24	PES	19.15	24.31
					11/04/24	PES	18.73	24.73
W-MW-03	Property, NE quadrant	70 to 80	–	39.23	02/07/12	Windward	17.73	21.50
					09/06/12	SES	18.36	20.87
					12/21/12	SES	18.19	21.04
					03/29/13	SES	18.22	21.01
					Decommissioned			
W-MW-04**	Property, NE quadrant	68 to 77	–	35.53	02/07/12	Windward	14.13	22.72
					09/06/12	SES	16.73	20.37
					12/21/12	SES	16.69	20.40
					03/29/13	SES	16.90	20.21
					Decommissioned			
FMW-129	SDOT Mercer Parcels, NE quadrant	84 to 89	-45.6 to -50.6	38.31	10/19/15	SES	25.20	
					02/01/16	SES	25.25	
					04/14/17	PES	19.78	18.53
					04/28/17	PES	25.30	13.01
					05/05/17	PES	29.55	8.76
					05/12/17	PES	30.25	8.06
					05/19/17	PES	30.74	7.57
					06/12/17	PES	34.90	3.41
					03/14/19	PES	20.11	18.20
					03/26/19	HC	19.99	18.32
					05/01/19	PES	19.72	18.59
					05/16/19	HC	19.56	18.75
					07/16/19	PES	20.24	18.07
					07/17/19	HC	20.13	18.18
					07/30/19	HC	20.34	17.97
					10/21/19	PES	21.54	16.77
					01/13/20	PES	24.49	13.82

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
FMW-129 Continued					05/11/20	PES	29.20	9.11
					07/13/20	PES	29.80	8.51
					11/16/20	PES	29.57	8.74
					06/07/21	PES	–	
					08/16/21	PES	22.76	15.55
					02/14/22	PES	20.30	18.01
					05/16/22	PES	19.84	18.47
					08/08/22	PES	19.76	18.55
					11/07/22	PES	–	–
					02/21/23	PES	19.85	18.46
					05/08/23	PES	19.56	18.75
					08/10/23	PES	20.39	17.92
					10/30/23	PES	20.39	17.92
					03/01/24	PES	19.30	19.01
					05/20/24	PES	19.68	18.63
					09/04/24	PES	20.24	18.07
					11/04/24	PES	20.27	18.04
FMW-131	Block 37, SE quadrant	63 to 73	-34.7 to -44.7	27.85	03/24/17	PES	9.56	18.29
					06/12/17	PES	32.94	-5.09
					03/14/19	PES	10.26	17.59
					04/22/19	PES	9.82	18.03
					07/16/19	PES	–	
					10/21/19	PES	12.21	15.64
					01/13/20	PES	14.95	12.90
					05/11/20	PES	22.57	5.28
					07/13/20	PES	22.77	5.08
					11/16/20	PES	21.69	6.16
					02/01/21	PES	17.03	10.82
					06/07/21	PES	13.98	13.87
					08/16/21	PES	12.82	15.03
					02/14/22	PES	10.37	17.48
					05/16/22	PES	9.76	18.09
					08/08/22	PES	9.79	18.06
					11/07/22	PES	10.43	17.42
					02/21/23	PES	19.02	8.83
					05/08/23	PES	19.60	8.25
					08/10/23	PES	9.71	18.14
					10/30/23	PES	10.51	17.34
FMW-137	Alley E of Block 38 West	72 to 85	-41.9 to -54.9	30.09	11/20/18	Farallon	13.02	17.07
					12/28/18	Farallon	12.74	17.35
					03/14/19	Farallon	12.56	17.53
					05/06/19	Farallon	12.08	18.01
					07/08/19	Farallon	12.25	17.84
					11/06/19	PES	14.11	15.98
					01/13/20	PES	19.50	10.59
					05/11/20	PES	33.07	-2.98
					07/13/20	PES	33.37	-3.28
					11/16/20	PES	30.61	-0.52
					02/01/21	PES	21.52	8.57
					06/07/21	PES	15.74	14.35
					08/16/21	PES	15.28	14.81
					02/14/22	PES	12.85	17.24

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
FMW-137 Continued					05/16/22	PES	12.06	18.03
					08/08/22	PES	11.93	18.16
					11/07/22	PES	12.50	17.59
					02/21/23	PES	20.95	9.14
					05/09/23	PES	11.94	18.15
					08/10/23	PES	12.39	17.70
					10/30/23	PES	12.51	17.58
					03/01/24	PES	11.77	18.32
					05/21/24	PES	11.78	18.31
					09/03/24	PES	12.26	17.83
					11/04/24	PES	12.22	17.87
FMW-138	Alley E of Block 38 West	90 to 100	-50.0 to -60.0	40.44	11/20/18	Farallon	24.50	15.94
					12/28/18	Farallon	24.38	16.06
					03/14/19	Farallon	24.14	16.30
					05/06/19	Farallon	23.80	16.64
					07/08/19	Farallon	23.84	16.60
					02/14/22	Farallon	24.31	16.13
					05/16/22	Farallon	24.00	16.44
					08/08/22	Farallon	23.57	16.87
					11/07/22	Farallon	23.74	16.70
					02/21/23	Farallon	23.39	17.05
					05/08/23	Farallon	23.52	16.92
					08/10/23	Farallon	23.63	16.81
					10/30/23	Farallon	23.87	16.57
FMW-140	900 Roy St, S end	70 to 80	-38.0 to -48.0	31.71	10/31/19	PES	15.03	16.68
					01/13/20	PES	17.07	14.64
					05/11/20	PES	22.55	9.16
					07/13/20	PES	22.91	8.80
					11/16/20	PES	22.34	9.37
					02/01/21	PES	18.00	13.71
					06/07/21	PES	15.63	16.08
					08/16/21	PES	15.63	16.08
					02/14/22	PES	13.83	17.88
					05/16/22	PES	12.96	18.75
					08/08/22	PES	10.53	21.18
					11/07/22	PES	10.85	20.86
					02/21/23	PES	10.60	21.11
					05/08/23	PES	15.77	15.94
					08/10/23	PES	11.61	20.10
					10/30/23	PES	11.49	20.22
					03/01/24	PES	13.14	18.57
					05/21/24	PES	13.05	18.66
					09/06/24	PES	13.58	18.13
					11/04/24	PES	13.68	18.03
FMW-3D	Terry Ave N ROW, E side	59 to 69	-31.1 to -41.1	27.88	03/24/17	PES	9.58	18.30
					06/12/17	PES	30.87	-2.99
GEI-2	Block 37, NW quadrant	50.5 to 60.5	-21.1 to -31.1	29.38	Decommissioned			
					03/24/17	PES	10.96	18.42
					06/12/17	PES	37.60	-8.22
					03/14/19	PES	11.70	17.68
					04/22/19	PES	11.26	18.12
					07/16/19	PES	11.51	17.87
					10/21/19	PES	13.54	15.84
					01/13/20	PES	9.93	19.45
					05/11/20	PES	23.05	6.33
					07/13/20	PES	23.36	6.02

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
GEI-2 Continued					11/16/20	PES	22.60	6.78
					02/01/21	PES	18.06	11.32
					06/07/21	PES	14.00	15.38
					08/16/21	PES	13.92	15.46
					02/14/22	PES	12.02	17.36
					05/16/22	PES	11.24	18.14
					08/08/22	PES	11.29	18.09
					11/07/22	PES	10.77	18.61
					02/21/23	PES	20.34	9.04
					05/08/23	PES	11.06	18.32
					08/10/23	PES	11.84	17.54
					10/30/23	PES	11.91	17.47
					03/01/24	PES	11.15	18.23
					05/21/24	PES	11.02	18.36
					09/03/24	PES	11.65	17.73
					11/04/24	PES	11.71	17.67
HMW-1D	SDOT Mercer Parcels, NE quadrant	80.0 to 90.0	-41.9 to -51.9	37.99	03/20/19	HC	20.33	17.66
					03/26/19	HC	20.34	17.65
					05/16/19	HC	19.90	18.09
					07/16/19	HC	20.28	17.71
					07/17/19	HC	20.32	17.67
					07/30/19	HC	20.50	17.49
					08/15/19	HC	20.60	17.39
					12/05/19	HC	25.56	12.43
					01/13/20	HC	23.40	14.59
					03/09/20	HC	28.29	9.70
					03/19/20	HC	28.53	9.46
					04/10/20	HC	29.29	8.70
					05/11/20	HC	29.55	8.44
					07/13/20	HC	30.39	7.60
					11/16/20	PES	30.05	7.94
					02/01/21	HC	26.78	11.21
					06/07/21	PES	23.97	14.02
					08/16/21	PES	23.39	14.60
					02/14/22	PES	24.10	13.89
					05/16/22	PES	20.15	17.84
					08/08/22	PES	19.85	18.14
					11/07/22	PES	20.15	17.84
					02/21/23	PES	19.59	18.40
					05/08/23	PES	19.61	18.38
					08/10/23	PES	20.08	17.91
					10/30/23	PES	20.18	17.81
					03/01/24	PES	19.28	18.71
HMW-2D	SDOT Mercer Parcels, NE quadrant	80.0 to 90.0	-32.7 to -42.7	47.19	03/19/19	HC	27.98	19.21
					03/26/19	HC	27.26	19.93
					05/16/19	HC	27.95	19.24
					07/16/19	HC	28.66	18.53
					08/15/19	HC	29.17	18.02
					12/05/19	HC	30.52	16.67
					01/13/20	HC	30.31	16.88
					03/12/20	HC	35.94	11.25
					03/19/20	HC	36.06	11.13
					03/27/20	HC	36.04	11.15
					04/10/20	HC	36.75	10.44
					05/11/20	HC	37.18	10.01
					07/13/20	HC	37.84	9.35

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-2D Continued					11/16/20	PES	37.19	10.00
					02/01/21	HC	33.53	13.66
					06/07/21	PES	31.36	15.83
					08/16/21	PES	31.18	16.01
					02/14/22	PES	28.41	18.78
					05/16/22	PES	28.20	18.99
					08/08/22	PES	28.00	19.19
					11/07/22	PES	28.77	18.42
					02/21/23	PES	22.19	25.00
					05/08/23	PES	22.57	24.62
					08/10/23	PES	23.90	23.29
					10/30/23	PES	23.22	23.97
					03/01/24	PES	21.81	25.38
HMW-3D	SDOT Mercer Parcels, NW quadrant	80.0 to 90.0	-23.4 to -33.4	56.37	03/19/19	HC	38.90	17.47
					03/26/19	HC	38.77	17.60
					07/16/19	HC	39.11	17.26
					12/05/19	HC	39.60	16.77
					01/13/20	HC	39.62	16.75
					03/12/20	HC	41.82	14.55
					03/19/20	HC	41.86	14.51
					03/27/20	HC	42.29	14.08
					04/10/20	HC	42.43	13.94
					05/11/20	HC	42.57	13.80
					07/13/20	HC	43.31	13.06
					11/16/20	PES	43.07	13.30
					02/01/21	HC	42.15	14.22
					06/07/21	PES	41.30	15.07
					08/16/21	PES	40.85	15.52
					02/14/22	PES	39.36	17.01
					05/16/22	PES	39.00	17.37
					08/08/22	PES	38.61	17.76
					11/07/22	PES	38.60	17.77
					02/21/23	PES	27.05	29.32
					05/08/23	PES	27.64	28.73
					08/10/23	PES	28.63	27.74
					10/30/23	PES	28.20	28.17
					03/01/24	PES	34.80	21.57
HMW-6D	SDOT Mercer Parcels, SW quadrant	79.7 to 89.7	-21.1 to -31.1	61.49	03/19/20	HC	46.89	14.60
					05/11/20	HC	47.65	13.84
					07/13/20	HC	48.39	13.10
					11/16/20	PES	48.38	13.11
					02/01/21	HC	47.25	14.24
					06/07/21	PES	46.45	15.04
					08/16/21	PES	46.07	15.42
					02/14/22	PES	44.03	17.46
					05/16/22	PES	44.10	17.39
					08/08/22	PES	43.86	17.63
					11/07/22	PES	43.68	17.81
					02/22/23	PES	43.28	18.21
					05/08/23	PES	43.65	17.84
					08/10/23	PES	43.76	17.73
					10/30/23	PES	44.07	17.42
					03/01/24	PES	43.10	18.39

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-9D	SDOT Mercer Parcels, SW quadrant	79.7 to 89.7	-24.4 to -34.4	58.14	03/19/20	HC	43.55	14.59
					05/11/20	HC	44.46	13.68
					07/13/20	HC	45.17	12.97
					11/16/20	PES	44.63	13.51
					02/01/21	HC	42.95	15.19
					06/07/21	PES	42.22	15.92
					08/16/21	PES	41.88	16.26
					02/14/22	PES	39.91	18.23
					05/16/22	PES	39.56	18.58
					08/08/22	PES	43.86	14.28
					11/07/22	PES	39.39	18.75
					02/21/23	PES	38.80	19.34
					05/08/23	PES	39.20	18.94
					08/10/23	PES	39.50	18.64
					10/30/23	PES	39.59	18.55
					03/01/24	PES	38.84	19.30
HMW-10D	SDOT Mercer Parcels, SE quadrant	79.0 to 89.0	-30.8 to -40.8	51.03	03/19/20	HC	39.97	11.06
					03/25/20	HC	40.32	10.71
					05/11/20	HC	41.37	9.66
					07/13/20	HC	42.14	8.89
					11/16/20	PES	41.44	9.59
					02/01/21	HC	37.53	13.50
					06/07/21	PES	35.23	15.80
					08/16/21	PES	34.94	16.09
					02/14/22	PES	31.94	19.09
					05/16/22	PES	31.77	19.26
					08/08/22	PES	31.83	19.20
					11/07/22	PES	32.41	18.62
					02/21/23	PES	31.53	19.50
					05/08/23	PES	31.47	19.56
					08/10/23	PES	32.38	18.65
					10/30/23	PES	32.37	18.66
					03/01/24	PES	30.98	20.05
HMW-12D	SDOT Mercer Parcels, NE quadrant	82.0 to 92.0	-48.5 to -58.5	35.86	11/16/20	PES	27.09	8.77
					02/01/21	HC	23.35	12.51
					06/07/21	PES	20.33	15.53
					08/16/21	PES	20.21	15.65
					02/14/22	PES	17.79	18.07
					05/16/22	PES	17.33	18.53
					08/08/22	PES	17.23	18.63
					11/07/22	PES	17.82	18.04
					02/21/23	PES	17.27	18.59
					05/08/23	PES	17.00	18.86
					08/10/23	PES	17.84	18.02
					10/30/23	PES	17.84	18.02
					03/01/24	PES	16.88	18.98
HMW-13D	SDOT Mercer Parcels, SE quadrant	89.5 to 99.5	-44.2 to -54.2	45.08	11/16/20	PES	36.83	8.25
					02/01/21	HC	33.40	11.68
					06/07/21	PES	30.53	14.55
					08/16/21	PES	30.20	14.88
					02/14/22	PES	27.26	17.82
					05/16/22	PES	26.90	18.18
					08/08/22	PES	26.61	18.47
					11/07/22	PES	27.05	18.03
					02/21/23	PES	26.47	18.61
					05/08/23	PES	26.34	18.74

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
HMW-13D Continued					08/10/23	PES	26.98	18.10
					10/30/23	PES	27.06	18.02
					03/01/24	PES	26.17	18.91
HMW-14D	SDOT Mercer Parcels, SE quadrant	70.0 to 80.0	-23.7 to -33.7	46.11	11/16/20	PES	38.63	7.48
					02/01/21	HC	33.12	12.99
					06/07/21	PES	30.50	15.61
					08/16/21	PES	30.29	15.82
					02/14/22	PES	27.06	19.05
					05/16/22	PES	26.82	19.29
					08/08/22	PES	26.94	19.17
					11/07/22	PES	27.62	18.49
					02/21/23	PES	26.68	19.43
					05/08/23	PES	26.60	19.51
					08/10/23	PES	27.56	18.55
					10/30/23	PES	27.50	18.61
					03/01/24	PES	25.90	20.21
MW101	Property, NE quadrant	105 to 115	-65.5 to -75.5	39.49	09/06/12	SES	21.48	18.01
					12/21/12	SES	21.14	18.35
					03/29/13	SES	22.22	17.27
MW102	Valley St ROW, S side	115 to 125	-65.8 to -75.8	49.19	Decommissioned			
					09/05/12	SES	31.11	18.08
					12/21/12	SES	30.78	18.41
					03/29/13	SES	31.65	17.54
					01/06/14	SES	33.80	15.39
					10/19/15	SES	37.06	12.13
					02/01/16	SES	38.22	10.97
					03/20/17	PES	32.25	16.94
					03/24/17	PES	33.50	15.69
					04/14/17	PES	34.38	14.81
					04/28/17	PES	35.18	14.01
					05/05/17	PES	34.77	14.42
					05/12/17	PES	35.00	14.19
					05/19/17	PES	35.21	13.98
					06/12/17	PES	36.87	12.32
				49.11	10/11/17	PES	37.59	11.60
					03/14/19	PES	31.94	17.25
					04/22/19	PES	31.78	17.41
					07/16/19	PES	31.80	17.39
					10/21/19	PES	32.20	16.91
					01/13/20	PES	32.46	16.65
					05/11/20	PES	35.36	13.75
					07/13/20	PES	36.04	13.07
					07/21/20	PES	35.81	13.30
					08/04/20	PES	35.98	13.13
					08/17/20	PES	35.93	13.18
					09/03/20	PES	36.13	12.98
					09/21/20	PES	36.00	13.11
					11/16/20	PES	35.93	13.18
					49.66	02/01/21	PES	34.74
				06/07/21		PES	33.95	15.16
				08/16/21		PES	34.10	15.01
				02/14/22		PES	32.12	17.54
				05/16/22		PES	32.20	17.46
				08/08/22		PES	31.85	17.81
11/07/22	PES	31.73	17.93					

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW102					02/21/23	PES	31.44	18.22
Continued					05/08/23	PES	31.58	18.08
					08/10/23	PES	31.82	17.84
					10/30/23	PES	32.29	17.37
					03/01/24	PES	31.25	18.41
					05/20/24	PES	31.84	17.82
					09/03/24	PES	31.79	17.87
					11/04/24	PES	31.59	18.07
MW103	Alley E of Seattle Roy Aloha Shops	105.5 to 112.5	-67.6 to -77.6	35.92	09/05/12	SES	18.03	17.89
				35.86	12/21/12	SES	17.38	18.54
					03/29/13	SES	19.70	16.22
					01/06/14	SES	26.45	9.47
					06/16/15	SES	20.03	15.89
					10/19/15	SES	22.31	13.61
					02/01/16	SES	22.40	13.52
					03/20/17	PES	17.10	18.82
					03/24/17	PES	17.36	18.56
					04/14/17	PES	17.68	18.24
					04/28/17	PES	25.82	10.10
					05/05/17	PES	26.17	9.75
					05/12/17	PES	26.71	9.21
					05/19/17	PES	27.99	7.93
					06/12/17	PES	30.85	5.07
					10/11/17	PES	30.31	5.61
					03/14/19	PES	17.75	18.17
					04/22/19	PES	17.50	18.42
					07/16/19	PES	16.85	19.07
					10/21/19	PES	19.17	16.75
					01/13/20	PES	20.53	15.33
					01/30/20	PES	20.11	15.75
					05/11/20	PES	24.87	10.99
					07/13/20	PES	25.56	10.30
					07/21/20	PES	25.55	10.31
					08/04/20	PES	25.61	10.25
					08/17/20	PES	25.68	10.18
					09/03/20	PES	25.73	10.13
					09/21/20	PES	Inaccessible	
					11/16/20	PES	25.50	10.36
					02/01/21	PES	22.69	13.17
					06/07/21	PES	20.18	15.68
					08/16/21	PES	20.03	15.83
					02/14/22	PES	17.95	17.91
					05/16/22	PES	17.53	18.33
					08/08/22	PES	17.34	18.52
					11/07/22	PES	17.87	17.99
					02/21/23	PES	17.54	18.32
					05/08/23	PES	17.28	18.58
					08/10/23	PES	17.93	17.93
					10/30/23	PES	18.07	17.79
					02/28/24	PES	17.16	18.70
					05/20/24	PES	17.60	18.26
					09/03/24	PES	17.72	18.14
					11/04/24	PES	17.71	18.15

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW104	8th Ave N ROW, W side	119 to 129	-76.3 to -86.3	42.68	09/06/12	SES	24.72	17.96
					12/21/12	SES	24.31	18.37
					03/29/13	SES	25.78	16.90
					01/06/14	SES	28.87	13.81
					10/19/15	SES	30.04	12.64
					02/01/16	SES	30.90	11.78
					03/20/17	PES	25.00	17.68
					04/14/17	PES	26.58	16.10
					04/28/17	PES	30.11	12.57
					05/05/17	PES	30.71	11.97
					05/12/17	PES	30.43	12.25
					05/19/17	PES	30.60	12.08
					06/30/17	PES	33.10	9.58
					10/11/17	PES	32.69	9.99
					03/14/19	PES	25.00	17.68
					04/22/19	PES	24.86	17.82
					07/16/19	PES	25.01	17.67
					10/21/19	PES	25.62	17.06
					01/13/20	PES	–	
					05/11/20	PES	29.68	13.00
					07/13/20	PES	30.21	12.47
					08/17/20	PES	30.06	12.62
					09/03/20	PES	Inaccessible	
					09/21/20	PES	29.98	12.70
					11/16/20	PES	Inaccessible	
					02/01/21	PES	Inaccessible	
					06/07/21	PES	Inaccessible	
					08/16/21	PES	Inaccessible	
					02/14/22	PES	24.84	17.84
					05/16/22	PES	24.82	17.86
					08/08/22	PES	24.66	18.02
					11/07/22	PES	24.55	18.13
					02/21/23	PES	24.12	18.56
					05/08/23	PES	24.33	18.35
					08/10/23	PES	24.60	18.08
					10/30/23	PES	24.90	17.78
					03/01/24	PES	23.88	18.80
					05/20/24	PES	24.56	18.12
					09/03/24	PES	24.56	18.12
					11/04/24	PES	24.35	18.33
MW105	Roy St ROW, S side	130 to 140	-85.3 to -95.3	44.69	09/05/12	SES	26.85	17.84
				44.17	12/21/12	SES	26.26	18.43
					03/29/13	SES	28.47	16.22
					01/06/14	SES	32.48	11.69
					04/02/15	SES	28.56	15.61
					06/16/15	SES	28.59	15.58
					10/19/15	SES	31.15	13.02
					02/01/16	SES	31.58	12.59
					03/20/17	PES	25.86	18.31
					03/24/17	PES	26.22	17.95
					04/14/17	PES	26.71	17.46
					04/28/17	PES	34.10	10.07
					05/05/17	PES	34.40	9.77
					05/12/17	PES	34.91	9.26
					05/19/17	PES	35.39	8.78
					06/12/17	PES	38.85	5.32

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW105 Continued				44.12	10/11/17	PES	38.22	5.95
					03/14/19	PES	26.33	17.84
					04/22/19	PES	26.06	18.11
					07/17/19	PES	26.25	17.92
					10/21/19	PES	27.47	16.65
					01/13/20	PES	28.75	15.37
					05/11/20	PES	33.01	11.11
					07/13/20	PES	33.82	10.30
					11/16/20	PES	33.91	10.21
					02/01/21	PES	31.11	13.01
					06/07/21	PES	28.53	15.59
					08/16/21	PES	28.41	15.71
					02/14/22	PES	26.32	17.80
					05/16/22	PES	25.80	18.32
					08/08/22	PES	25.84	18.28
					11/07/22	PES	26.23	17.89
					02/21/23	PES	–	–
					05/08/23	PES	25.58	18.54
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	26.35	17.77
					03/01/24	PES	25.40	18.72
					05/20/24	PES	25.72	18.40
					09/03/24	PES	26.05	18.07
					11/04/24	PES	26.02	18.10
MW106	SDOT Mercer Parcels, NW quadrant	130 to 140	-78.0 to -88.0	51.99	09/05/12	SES	34.09	17.90
					03/29/13	SES	34.92	17.07
					01/06/14	SES	37.15	14.84
					10/19/15	SES	40.11	11.88
					02/01/16	SES	41.02	10.97
					04/14/17	PES	36.78	15.21
					06/30/17	PES	40.60	11.39
					03/14/19	PES	34.64	17.35
					03/26/19	HC	34.43	17.56
					04/22/19	PES	34.53	17.46
					07/16/19	PES	34.62	17.37
					07/17/19	HC	34.62	17.37
					10/21/19	PES	35.25	16.74
					01/13/20	PES	35.56	16.43
					03/19/20	HC	38.23	13.76
					05/11/20	PES	38.87	13.12
					07/13/20	PES	39.58	12.41
					11/10/20	PES	39.28	12.71
					02/01/21	PES	37.82	14.17
					06/07/21	PES	36.74	15.25
					08/16/21	PES	36.34	15.65
					02/14/22	PES	34.41	17.58
					05/16/22	PES	34.45	17.54
					08/08/22	PES	34.11	17.88
					11/07/22	PES	34.05	17.94
					02/21/23	PES	33.59	18.40
					05/08/23	PES	33.88	18.11
					08/10/23	PES	34.13	17.86
					10/30/23	PES	Not Measured	–
					03/01/23	PES	33.46	18.53
					05/20/24	PES	34.02	17.97
					09/04/24	PES	34.04	17.95
					11/04/24	PES	33.86	18.13

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW113	9th Ave N ROW, W side	70 to 80	-36.8 to -46.8	32.94	12/21/12	SES	14.15	18.79
				32.90	03/29/13	SES	16.95	15.99
					01/06/14	SES	23.35	9.59
					06/16/15	SES	16.46	16.48
					10/19/15	SES	18.24	14.70
					02/01/16	SES	17.87	15.07
					03/20/17	PES	13.60	19.30
					03/24/17	PES	13.65	19.25
					04/14/17	PES	13.80	19.10
					04/28/17	PES	24.10	8.80
					05/05/17	PES	24.94	7.96
					05/12/17	PES	25.68	7.22
					05/19/17	PES	26.01	6.89
					06/12/17	PES	31.15	1.75
					10/11/17	PES	31.00	1.90
					03/14/19	PES	14.52	18.38
					04/22/19	PES	14.21	18.69
					07/16/19	PES	14.57	18.33
				32.91	10/21/19	PES	16.19	16.72
					11/11/19	Farallon	16.41	16.50
					01/13/20	PES	17.91	15.00
					01/14/20	Farallon	18.04	14.87
					01/30/20	PES	17.05	15.86
					02/17/20	Farallon	20.79	12.12
					03/24/20	Farallon	22.72	10.19
					05/11/20	PES	25.17	7.74
					07/13/20	PES	23.67	9.24
					11/16/20	PES	23.25	9.66
					02/01/21	PES	19.60	13.31
					06/07/21	PES	16.66	16.25
					08/16/21	PES	16.69	16.22
					02/14/22	PES	14.58	18.33
					05/16/22	PES	14.07	18.84
					08/08/22	PES	14.08	18.83
					11/07/22	PES	14.78	18.13
					02/22/23	PES	14.40	18.51
					05/08/23	PES	13.85	19.06
					08/10/23	PES	14.79	18.12
					10/30/23	PES	14.84	18.07
					03/01/24	PES	14.00	18.91
					05/20/24	PES	14.05	18.86
					09/03/24	PES	14.60	18.31
					11/04/24	PES	14.66	18.25
MW122	Alley E of Seattle Roy Aloha Shops	105 to 119	-74.9 to -84.9	30.03	01/06/14	SES	17.61	12.42
					10/19/15	SES	15.59	14.44
					02/01/16	SES	15.75	14.28
					03/20/17	PES	11.62	18.41
					03/24/17	PES	11.57	18.46
					04/14/17	PES	11.76	18.27
					04/28/17	PES	19.98	10.05
					05/05/17	PES	20.43	9.60
					05/12/17	PES	20.94	9.09
					05/19/17	PES	21.30	8.73
					06/12/17	PES	25.23	4.80
					10/11/17	PES	24.93	5.10
					03/14/19	PES	11.99	18.04

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW122 Continued					04/22/19	PES	11.60	18.43
					07/16/19	PES	11.93	18.10
					10/21/19	PES	13.23	16.80
					01/13/20	PES	14.53	15.50
					01/30/20	PES	14.09	15.94
					05/11/20	PES	18.57	11.46
					07/13/20	PES	19.02	11.01
					11/16/20	PES	18.86	11.17
					02/01/21	PES	16.27	13.76
					06/07/21	PES	13.60	16.43
					08/16/21	PES	13.70	16.33
					02/14/22	PES	12.06	17.97
					05/16/22	PES	11.39	18.64
					08/08/22	PES	11.32	18.71
					11/07/22	PES	12.08	17.95
					02/21/23	PES	11.72	18.31
					05/08/23	PES	11.25	18.78
					08/10/23	PES	12.05	17.98
					10/30/23	PES	13.10	16.93
					02/28/24	PES	11.39	18.64
					05/20/24	PES	11.40	18.63
					09/03/24	PES	11.82	18.21
					11/04/24	PES	11.89	18.14
MW123	Westlake Ave N N ROW, W side	70 to 80	-42.5 to -52.5	27.51	01/06/14	SES	15.69	11.82
				27.50	03/20/17	PES	8.50	19.01
					03/24/17	PES	8.60	18.91
					06/12/17	PES	24.68	2.83
					10/11/17	PES	24.43	3.08
					03/14/19	PES	9.32	18.19
					04/22/19	PES	8.89	18.62
					07/16/19	PES	9.22	18.29
					10/21/19	PES	10.64	16.86
					01/13/20	PES	12.15	15.35
					05/11/20	PES	16.51	10.99
					07/13/20	PES	16.80	10.70
					11/16/20	PES	16.64	10.86
					02/01/21	PES	14.00	13.50
					06/07/21	PES	10.92	16.58
					08/16/21	PES	11.11	16.39
					02/14/22	PES	9.55	17.95
					05/16/22	PES	8.88	18.62
					08/08/22	PES	8.72	18.78
					11/07/22	PES	9.47	18.03
					02/21/23	PES	–	–
					05/08/23	PES	8.55	18.95
					08/10/23	PES	9.52	17.98
					10/30/23	PES	9.60	17.90
					03/01/24	PES	8.87	18.63
					05/20/24	PES	NM	–
					09/03/24	PES	9.29	18.21
					11/04/24	PES	9.34	18.16

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW124	Valley St ROW, S side	110 to 120	-53.8 to -63.8	56.24	01/06/14	SES	40.50	15.74
				56.17	03/20/17	PES	39.33	16.91
					03/24/17	PES	40.59	15.65
					04/14/17	PES	41.54	14.70
					04/28/17	PES	41.81	14.43
					05/05/17	PES	41.28	14.96
					05/12/17	PES	41.52	14.72
					05/19/17	PES	41.60	14.64
					06/12/17	PES	42.95	13.29
					10/11/17	PES	43.95	12.29
					03/14/19	PES	38.98	17.26
					04/22/19	PES	38.81	17.43
					07/16/19	PES	38.87	17.37
					10/21/19	PES	39.28	16.96
					01/13/20	PES	-	
					01/30/20	PES	42.92	13.25
					02/19/20	PES	40.76	15.41
					05/11/20	PES	41.98	14.19
					07/13/20	PES	42.86	13.31
					08/04/20	PES	42.75	13.42
					08/17/20	PES	42.79	13.38
					09/03/20	PES	42.91	13.26
					11/16/20	PES	42.79	13.38
					02/01/21	PES	Inaccessible	
					06/08/21	PES	40.93	15.24
					08/16/21	PES	Inaccessible	
				56.74	02/14/22	PES	39.20	17.54
					05/16/22	PES	39.25	17.49
					08/08/22	PES	38.98	17.76
					11/07/22	PES	38.80	17.94
					02/21/23	PES	38.47	18.27
					05/08/23	PES	38.73	18.01
					08/10/23	PES	38.90	17.84
					10/30/23	PES	39.32	17.42
					03/01/24	PES	38.30	18.44
					05/20/24	PES	38.97	17.77
MW128	Westlake Ave N ROW, E side	60 to 70	-30.8 to -40.8	–	04/22/15	SES	12.91	
				28.59	10/19/15	SES	14.15	
					02/01/16	SES	14.23	
					03/20/17	PES	10.00	18.59
					03/24/17	PES	10.04	18.55
					04/14/17	PES	10.13	18.46
					04/28/17	PES	25.30	3.29
					05/05/17	PES	26.35	2.24
					05/12/17	PES	27.06	1.53
					05/19/17	PES	27.44	1.15
					06/12/17	PES	33.41	-4.82
					10/11/17	PES	30.51	-1.92
					03/14/19	PES	10.79	17.80
					04/22/19	PES	10.43	18.16
					07/16/19	PES	10.67	17.92
					09/09/19	PES	11.12	17.47
					10/21/19	PES	12.36	16.23
					11/11/19	Farallon	12.49	16.10

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW128 Continued					01/13/20	PES	14.27	14.32
					01/30/20	PES	13.68	14.91
					02/17/20	Farallon	18.11	10.48
					05/11/20	PES	20.10	8.49
					07/13/20	PES	20.46	8.13
					11/16/20	PES	20.01	8.58
					02/01/21	PES	16.35	12.24
					06/07/21	PES	12.81	15.78
					08/16/21	PES	12.80	15.79
					02/14/22	PES	11.00	17.59
					05/16/22	PES	10.20	18.39
					08/08/22	PES	10.13	18.46
					11/07/22	PES	10.82	17.77
					02/21/23	PES	10.60	17.99
					05/08/23	PES	10.03	18.56
					08/10/23	PES	10.84	17.75
					10/30/23	PES	10.96	17.63
					03/01/24	PES	10.54	18.05
					05/20/24	PES	10.09	18.50
					09/03/24	PES	10.70	17.89
					11/04/24	PES	10.72	17.87
MW-133	Property, SW quadrant	129 to 139	-88.9 to -98.9	39.77	10/11/17	PES	27.57	12.20
					03/14/19	PES	22.62	17.15
					Decommissioned March 2019			
MW-137	Property, SW quadrant	105 to 115	-53.3 to -63.3	51.46	10/11/17	PES	39.66	11.80
					03/14/19	PES	33.99	17.47
					Decommissioned March 2019			
MW-138	Dexter Ave N ROW, E side	105 to 115	-47.6 to -57.6	57.06	10/11/17	PES	44.78	12.28
				57.03	03/14/19	PES	39.75	17.31
					04/22/19	PES	39.64	17.42
					07/19/19	PES	39.82	17.21
					10/21/19	PES	40.19	16.84
					01/13/20	PES	40.32	16.71
					05/11/20	PES	43.06	13.97
					07/13/20	PES	43.92	13.11
					11/16/20	PES	43.85	13.18
					02/01/21	PES	42.62	14.41
					06/07/21	PES	41.90	15.13
					08/16/21	PES	Inaccessible	
					02/14/22	PES	39.56	17.47
					05/16/22	PES	39.48	17.55
					08/08/22	PES	39.30	17.73
					11/07/22	PES	39.14	17.89
					02/21/23	PES	—	
					05/08/23	PES	38.97	18.06
					08/10/23	PES	Inaccessible	—
					10/30/23	PES	39.53	17.50
					03/01/24	PES	38.47	18.56
					05/20/24	PES	39.22	17.81
					09/03/24	PES	39.09	17.94
					11/04/24	PES	38.91	18.12
MW-140	Roy St ROW, N side	129.5 to 139.5	-78.9 to -88.9	50.20	10/11/17	PES	39.55	10.65
					Decommissioned 2019			
MW-141	Property, SE quadrant	95 to 105	-55.4 to 65.4	39.32	10/11/17	PES	29.40	9.92
					03/14/19	PES	21.80	17.52
					Decommissioned March 2019			

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-153	Roy St ROW, S side	120 to 130	-65.3 to -75.3	54.35	03/14/19	PES	37.27	17.08
					03/26/19	HC	36.85	17.50
					04/22/19	PES	37.12	17.23
					07/16/19	PES	37.27	17.08
					07/17/19	HC	37.11	17.24
					10/21/19	PES	37.60	16.75
					01/13/20	PES	38.80	15.55
					01/30/20	PES	38.41	15.94
					02/19/20	PES	39.41	14.94
					02/24/20	PES	39.81	14.54
					03/19/20	HC	40.14	14.21
					05/11/20	PES	40.67	13.68
					07/13/20	PES	41.55	12.80
					07/21/20	PES	41.11	13.24
					08/04/20	PES	41.31	13.04
					08/17/20	PES	41.29	13.06
					09/03/20	PES	41.37	12.98
					09/21/20	PES	41.33	13.02
					11/16/20	PES	41.39	12.96
					02/01/21	PES	40.15	14.20
					06/07/21	PES	39.39	14.96
					08/16/21	PES	38.87	15.48
					02/14/22	PES	36.90	17.45
					05/16/22	PES	36.96	17.39
					08/08/22	PES	36.51	17.84
					11/07/22	PES	36.57	17.78
					02/21/23	PES	35.94	18.41
					05/08/23	PES	36.51	17.84
					08/10/23	PES	36.63	17.72
					10/30/23	PES	36.90	17.45
					03/01/24	PES	36.61	17.74
					05/20/24	PES	36.60	17.75
					09/03/24	PES	36.44	17.91
					11/04/24	PES	36.34	18.01
MW-158A	8th Ave N ROW, E side	90 to 100	-48.2 to -58.5	41.09	01/24/19	PES	22.98	18.11
					03/14/19	PES	23.15	17.94
					04/22/19	PES	23.29	17.80
					07/16/19	PES	23.54	17.55
					10/21/19	PES	24.31	16.78
					01/13/20	PES	24.91	16.18
					01/30/20	PES	25.00	16.09
					05/11/20	PES	28.27	12.82
					07/13/20	PES	28.73	12.36
					07/21/20	PES	28.56	12.53
					08/04/20	PES	28.66	12.43
					08/17/20	PES	28.58	12.51
					09/03/20	PES	28.65	12.44
					09/21/20	PES	28.60	12.49
					11/16/20	PES	28.37	12.72
					02/01/21	PES	26.80	14.29
					06/07/21	PES	25.63	15.46
					08/16/21	PES	25.18	15.91
					02/14/22	PES	23.22	17.87
					05/16/22	PES	23.16	17.93
					08/08/22	PES	22.84	18.25
					11/07/22	PES	22.92	18.17

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-158A Continued					02/21/23	PES	22.59	18.50
					05/08/23	PES	22.73	18.36
					08/10/23	PES	23.02	18.07
					10/30/23	PES	Not Measured	
					03/01/24	PES	22.45	18.64
					05/20/24	PES	22.97	18.12
					09/03/24	PES	22.94	18.15
					11/04/24	PES	22.78	18.31
MW-160	8th Ave N ROW, W side	118 to 128	-75.4 to -85.4	42.24	03/14/19	PES	24.70	17.54
				42.03	04/22/19	PES	24.56	17.68
					07/16/19	PES	24.72	17.52
					10/21/19	PES	25.28	16.96
					01/13/20	PES	25.83	16.41
					01/30/20	PES	26.04	16.20
					02/19/20	PES	27.70	14.54
					05/11/20	PES	29.08	13.16
					07/13/20	PES	29.79	12.45
					07/21/20	PES	29.56	12.68
					08/04/20	PES	29.70	12.54
					08/17/20	PES	29.64	12.60
					09/03/20	PES	29.74	12.50
					09/21/20	PES	29.61	12.63
					11/16/20	PES	29.51	12.73
					02/01/21	PES	27.93	14.31
					06/07/21	PES	26.92	15.32
					08/16/21	PES	Inaccessible	
					02/14/22	PES	24.45	17.58
					05/16/22	PES	24.30	17.73
					08/08/22	PES	24.14	17.89
					11/07/22	PES	24.16	17.87
					11/08/22	PES	25.16	16.87
					02/21/23	PES	23.69	18.34
					05/08/23	PES	33.88	8.15
					08/10/23	PES	24.22	17.81
					10/30/23	PES	24.50	17.53
					03/01/24	PES	23.45	18.58
					05/20/24	PES	24.19	17.84
					09/03/24	PES	24.16	17.87
					11/04/24	PES	23.96	18.07
MW-161	8th Ave N ROW, W side	130 to 140	-85.6 to -95.6	43.99	03/14/19	PES	26.50	17.49
				43.84	04/22/19	PES	26.33	17.66
					07/16/19	PES	26.51	17.48
					10/21/19	PES	27.03	16.96
					01/13/20	PES	27.63	16.36
					05/11/20	PES	31.30	12.69
					07/13/20	PES	31.90	12.09
					07/13/20	PES	31.69	12.30
					08/04/20	PES	31.80	12.19
					08/17/20	PES	31.76	12.23
					09/03/20	PES	31.75	12.24
					09/21/20	PES	Inaccessible	
					11/16/20	PES	31.48	12.51
					02/01/21	PES	29.89	14.10
					06/07/21	PES	28.75	15.24
					08/16/21	PES	28.32	15.67
					02/14/22	PES	26.28	17.56

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-161 Continued					05/16/22	PES	26.12	17.72
					08/08/22	PES	25.96	17.88
					11/07/22	PES	25.95	17.89
					02/21/23	PES	25.56	18.28
					05/08/23	PES	25.80	18.04
					08/10/23	PES	26.03	17.81
					10/30/23	PES	26.30	17.54
					03/01/24	PES	25.27	18.57
					05/20/24	PES	26.02	17.82
					09/03/24	PES	26.03	17.81
					11/04/24	PES	26.81	17.03
MW-162	Property, NE quadrant	100 to 110	-61.6 to -71.6	–	03/14/19	PES	19.58	
Decommissioned March 2019								
MW-163	Property, NW quadrant	100 to 110	-61.0 to -71.0	–	03/14/19	PES	21.61	
Decommissioned March 2019								
MW-164	Property, SW quadrant	100 to 110	-59.9 to -69.9	–	03/14/19	PES	22.26	
Decommissioned March 2019								
MW-304	Dexter Ave N ROW, E side	105.2 to 115.2	-47.6 to -57.6	57.23	10/21/19	PES	40.38	16.85
				57.08	01/13/20	PES	40.48	16.75
					05/11/20	PES	43.11	14.12
					07/13/20	PES	43.97	13.26
					11/16/20	PES	Inaccessible	
					02/01/21	PES	42.76	14.47
					06/07/21	PES	42.04	15.19
					08/16/21	PES	41.50	15.73
					02/14/22	PES	39.52	17.56
					05/16/22	PES	39.59	17.49
					08/08/22	PES	39.41	17.67
					11/07/22	PES	39.24	17.84
					02/21/23	PES	–	
					05/08/23	PES	39.06	18.02
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	39.66	17.42
					03/01/24	PES	38.58	18.50
					05/20/24	PES	39.36	17.72
					09/03/24	PES	39.21	17.87
					11/04/24	PES	39.02	18.06
MW-319	9th Ave N ROW, W side	74.5 to 84.5	-42.8 to -52.8	31.31	10/21/19	PES	14.52	16.79
					01/13/20	PES	16.01	15.30
					01/30/20	PES	15.32	15.99
					02/19/20	PES	18.87	12.44
					05/11/20	PES	20.80	10.51
					07/13/20	PES	21.21	10.10
					11/16/20	PES	20.99	10.32
					02/01/21	PES	17.57	13.74
					06/07/21	PES	14.75	16.56
					08/16/21	PES	14.88	16.43
					02/14/22	PES	13.09	18.22
					05/16/22	PES	12.37	18.94
					08/08/22	PES	12.40	18.91
					11/07/22	PES	13.12	18.19
					02/22/23	PES	12.81	18.50
					05/08/23	PES	12.30	19.01
					08/10/23	PES	13.15	18.16
					10/30/23	PES	13.21	18.10
					03/01/24	PES	12.35	18.96

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-319 Continued					05/20/24	PES	12.27	19.04
					09/03/24	PES	12.95	18.36
					11/04/24	PES	12.99	18.32
MW-323	9th Ave N ROW, W side	100 to 110	-65.4 to -75.4	34.38	10/21/19	PES	17.71	16.67
					01/13/20	PES	19.20	15.18
					01/30/20	PES	18.70	15.68
					05/11/20	PES	24.04	10.34
					07/13/20	PES	24.66	9.72
					11/16/20	PES	24.48	9.90
					02/01/21	PES	21.32	13.06
					06/07/21	PES	18.53	15.85
					08/16/21	PES	18.43	15.95
					02/14/22	PES	16.31	18.07
					05/16/22	PES	15.76	18.62
					08/08/22	PES	15.70	18.68
					11/07/22	PES	16.33	18.05
					02/22/23	PES	15.95	18.43
					05/08/23	PES	15.55	18.83
					08/10/23	PES	16.30	18.08
					10/30/23	PES	16.42	17.96
					03/01/24	PES	15.64	18.74
					05/20/24	PES	15.83	18.55
					09/03/24	PES	16.17	18.21
					11/04/24	PES	16.20	18.18
MW-324	Roy St ROW, N side	66.3 to 76.3	-32.1 to -42.1	33.71	10/21/19	PES	17.09	16.62
					01/13/20	PES	18.93	14.78
					01/31/20	PES	18.13	15.58
					05/11/20	PES	24.60	9.11
					07/13/20	PES	25.11	8.60
					09/21/20	PES	25.24	8.47
					11/16/20	PES	24.81	8.90
					02/01/21	PES	20.85	12.86
					06/07/21	PES	17.69	16.02
					08/16/21	PES	17.70	16.01
					02/14/22	PES	15.66	18.05
					05/16/22	PES	14.91	18.80
					08/08/22	PES	14.94	18.77
					11/07/22	PES	15.44	18.27
					02/21/23	PES	15.28	18.43
					05/08/23	PES	14.71	19.00
					08/10/23	PES	15.71	18.00
					10/30/23	PES	15.74	17.97
					03/01/24	PES	14.87	18.84
					05/20/24	PES	14.85	18.86
					09/03/24	PES	15.52	18.19
					11/04/24	PES	15.55	18.16
MW-326	Mercer St ROW, N side	90 to 100	-48.7 to -58.7	40.97	10/21/19	PES	24.22	16.75
					01/13/20	PES	26.40	14.57
					01/30/20	PES	26.22	14.75
					03/19/20	HC	31.50	9.47
					05/11/20	PES	32.44	8.53
					07/13/20	PES	33.37	7.60
					09/21/20	PES	33.27	7.70
					11/16/20	PES	33.09	7.88
					02/01/21	PES	29.85	11.12
					06/07/21	PES	27.02	13.95

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-326 Continued					08/16/21	PES	26.50	14.47
					02/14/22	PES	23.52	17.45
					05/16/22	PES	23.18	17.79
					08/08/22	PES	22.81	18.16
					11/07/22	PES	23.14	17.83
					02/21/23	PES	22.55	18.42
					05/08/23	PES	22.71	18.26
					08/10/23	PES	23.07	17.90
					10/30/23	PES	23.20	17.77
					03/01/24	PES	26.88	14.09
					05/20/24	PES	22.76	18.21
					09/04/24	PES	22.95	18.02
					11/04/24	PES	22.82	18.15
MW-326R	Mercer St ROW, N side	90.2 to 100.2	-48.7 to -58.7	41.5	05/08/23	PES	23.11	18.39
					08/10/23	PES	23.52	17.98
					10/30/23	PES	23.64	17.86
					03/01/24	PES	NM	
					05/20/24	PES	23.19	18.31
					09/04/24	PES	22.34	19.16
					11/04/24	PES	23.25	18.25
MW-328	Lake Union Park, S end	64.5 to 74.5	-36.1 to -46.1	28.09	10/21/19	PES	11.54	16.55
					01/13/20	PES	13.21	14.88
					01/30/20	PES	12.60	15.49
					02/19/20	PES	16.50	11.59
					05/11/20	PES	18.00	10.09
					07/13/20	PES	18.35	9.74
					09/21/20	PES	19.61	8.48
					11/16/20	PES	18.20	9.89
					02/01/21	PES	15.00	13.09
					06/07/21	PES	11.88	16.21
					08/16/21	PES	12.03	16.06
					02/14/22	PES	10.44	17.65
					05/16/22	PES	9.52	18.57
					08/08/22	PES	9.55	18.54
					11/07/22	PES	10.22	17.87
					02/21/23	PES	10.04	18.05
					05/08/23	PES	9.41	18.68
					08/10/23	PES	10.30	17.79
					10/30/23	PES	10.38	17.71
					03/01/24	PES	9.72	18.37
					05/20/24	PES	9.50	18.59
					09/03/24	PES	10.09	18.00
					11/04/24	PES	10.11	17.98
MW-329	Westlake Ave N ROW, E side	98.3 to 108.3	-69.0 to -79.0	28.93	10/21/19	PES	12.67	16.26
					01/13/20	PES	14.55	14.38
					01/30/20	PES	13.96	14.97
					02/19/20	PES	18.55	10.38
					05/11/20	PES	20.35	8.58
					07/13/20	PES	20.74	8.19
					09/21/20	PES	20.85	8.08
					11/16/20	PES	20.34	8.59
					02/01/21	PES	16.60	12.33
					06/07/21	PES	13.06	15.87
					08/16/21	PES	13.13	15.80
					02/14/22	PES	11.36	17.57
					05/16/22	PES	10.52	18.41

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-329 Continued					08/08/22	PES	10.48	18.45
					11/07/22	PES	11.11	17.82
					02/21/23	PES	10.91	18.02
					05/08/23	PES	10.37	18.56
					08/10/23	PES	11.20	17.73
					10/30/23	PES	10.27	18.66
					03/01/24	PES	10.62	18.31
					05/20/24	PES	10.43	18.50
					09/03/24	PES	11.02	17.91
					11/04/24	PES	11.04	17.89
MW-336	Mercer St ROW, N side	85.3 to 95.3	-52.0 to -62.0	33.31	05/11/20	PES	29.31	4.00
					07/13/20	PES	30.00	3.31
					11/16/20	PES	29.11	4.20
					02/01/21	PES	23.57	9.74
					06/07/21	PES	18.97	14.34
					08/16/21	PES	18.48	14.83
					02/14/22	PES	16.50	16.81
					05/16/22	PES	15.17	18.14
					08/08/22	PES	14.94	18.37
					11/07/22	PES	15.47	17.84
					02/21/23	PES	14.94	18.37
					05/08/23	PES	15.02	18.29
					08/10/23	PES	15.38	17.93
					10/30/23	PES	15.50	17.81
					03/01/24	PES	14.84	18.47
					05/20/24	PES	14.94	18.37
					09/03/24	PES	15.29	18.02
					11/04/24	PES	15.25	18.06
MW-341	Lake Union Park, S end	95.2 to 105.2	-67.1 to -77.1	28.11	05/11/20	PES	18.08	10.03
					07/13/20	PES	18.43	9.68
					11/16/20	PES	18.30	9.81
					02/01/21	PES	15.05	13.06
					06/07/21	PES	11.95	16.16
					08/16/21	PES	12.07	16.04
					02/14/22	PES	10.47	17.64
					05/16/22	PES	9.58	18.53
					08/08/22	PES	9.59	18.52
					11/07/22	PES	10.28	17.83
					02/21/23	PES	10.10	18.01
					05/08/23	PES	9.60	18.51
					08/10/23	PES	10.33	17.78
					10/30/23	PES	10.44	17.67
					03/01/24	PES	9.86	18.25
					05/20/24	PES	9.55	18.56
					09/03/24	PES	10.15	17.96
					11/04/24	PES	10.18	17.93
MW-342	Valley St ROW, S side	60.1 to 70.1	-32.7 to -42.7	27.37	05/11/20	PES	17.92	9.45
					07/13/20	PES	18.22	9.15
					11/16/20	PES	18.02	9.35
					02/01/21	PES	14.81	12.56
					06/07/21	PES	11.43	15.94
					08/16/21	PES	11.54	15.83
					02/14/22	PES	10.03	17.34
					05/16/22	PES	9.09	18.28
					08/08/22	PES	9.01	18.36
					11/07/22	PES	9.79	17.59

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
MW-342 Continued					02/21/23	PES	9.95	17.42
					05/08/23	PES	8.89	18.48
					08/10/23	PES	9.75	17.62
					10/30/23	PES	9.87	17.50
					03/01/24	PES	9.30	18.07
					05/20/24	PES	8.85	18.52
					09/03/24	PES	9.59	17.78
					11/04/24	PES	9.64	17.73
MW-343	Valley St ROW, S side	99.1 to 109.1	-71.9 to -81.9	27.16	05/11/20	PES	17.63	9.53
					07/13/20	PES	17.96	9.20
					11/16/20	PES	17.76	9.40
					02/01/21	PES	Inaccessible	
					06/07/21	PES	11.55	15.61
					08/16/21	PES	11.53	15.63
					02/14/22	PES	10.03	17.13
					05/16/22	PES	9.13	18.03
					08/08/22	PES	9.02	18.14
					11/07/22	PES	9.87	17.29
					02/21/23	PES	9.54	17.62
					05/08/23	PES	8.90	18.26
					08/10/23	PES	Inaccessible	–
					10/30/23	PES	9.85	17.31
					03/01/24	PES	9.30	17.86
					05/20/24	PES	8.90	18.26
					09/03/24	PES	Inaccessible	
					11/04/24	PES	9.56	17.60
TB-18	SDOT Mercer NE quadrant	93 to 118	–	–	06/04/98	B&V Decommissioned	30.05	
M.P. A	S. Lake Union Park Retaining Wall E of MW-327	–	–	20.21	12/04/19	PES	3.39	16.82
M.P. B	S. Lake Union Park Octagonal Landing SE of footbridge	–	–	23.94	12/04/19	PES	7.05	16.89
					01/13/20	PES	7.05	16.89
					05/11/20	PES	5.28	18.66
					07/13/20	PES	5.60	18.34
					08/04/20	PES	5.93	18.01
					08/17/20	PES	5.97	17.97
					09/21/20	PES	6.15	17.79
					11/16/20	PES	6.58	17.36
					02/01/21	PES	7.09	16.85
					06/07/21	PES	5.09	18.85
					08/16/21	PES	6.35	17.59
					02/14/22	PES	7.11	16.83
					05/16/22	PES	5.19	18.75
					11/07/22	PES	–	–
					02/21/23	PES	–	–
					05/08/23	PES	8.88	15.06
					08/10/23	PES	9.45	14.49

Table 1
Summary of Groundwater Elevations
American Linen Supply Co–Dexter Avenue Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Screen Interval (ft bgs)	Screen Interval Elevation (feet)	Top of Casing Elevation (feet)	Date	Measured By	Depth to Water ^a	Groundwater Elevation ^b
M.P. B Continued					10/30/23	PES	6.57	17.37
					03/01/24	PES	10.21	13.73
					05/20/24	PES	5.15	18.79
					09/03/24	PES	6.19	17.75
					11/04/24	PES	6.63	17.31

Notes:

TOCs were surveyed relative to an established datum of 521.41 feet prior to 2012. TOCs were resurveyed by Axis Survey and Mapping of Kirkland, WA on March 16th, 2012, relative to an arbitrary benchmark of 499.89 feet above mean sea level, and by Bush, Roed & Hitchings, Inc. of Seattle, WA in multiple surveys since February 2012 using the North American Vertical Datum 1988.

^a As measured in feet below a fixed spot on the well casing rim.

^b Calculated by subtracting the depth to groundwater from the casing elevation. Groundwater elevation in angled monitoring well calculated subtracting the product of the measured depth to groundwater in the angled well by the sine of its angle.

**Monitoring well was installed at a 25 degree angle from the vertical point of penetration. Depth to groundwater measurements and sample interval account for angled length of well, not vertical depth. Groundwater elevations corrected to account for angle.

– = unknown or not applicable

ROW = right-of-way

TOC = top of casing

B&V = Black & Veach

DOF = Dalton, Olmsted & Fuglevand, Inc.

EPJ = E.P. Johnson Construction, Inc.

TD = Total Depth

PES = PES Environmental, Inc.

GeoEngineers = GeoEngineers, Inc.

Retec = Remediation Technologies, Inc.

Roux = Roux Associates

SES = SoundEarth Strategies, Inc.

Urban = Urban Redevelopment

Windward = Windward Environmental LLC

HC = Hart Crowser

⁵In feet referenced to North American Vertical Datum of 1988 (NAVD88) based on well construction detail. (Farallon table note)

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
Shallow Zone									
F13	Property, NE quadrant	03/27/17	6.80	756	15.4	3.4	0.86	-139	1.0
		06/22/17	7.00	865	20.2	–	0.27	-148	1.5
		04/05/18	6.84	491	16.6	–	0.50	67	–
		Decommissioned March 2019							
F5	Property, NW quadrant	03/28/17	6.05	1,001	10.9	5.8	0.99	-51	–
		06/22/17	6.38	1,080	19.5	–	0.80	-87	–
		Decommissioned March 2019							
F9	Property, NE quadrant	03/27/17	6.69	1,270	16.6	3.1	0.74	-151	–
		06/22/17	6.76	1,309	27.5	–	0.24	-149	–
		Decommissioned March 2019							
FMW-143	9th Ave N ROW, E side	10/31/19	6.65	892	16.8	16.1	0.35	45	0.0
		01/22/20	6.96	1,431	9.2	1.8	0.32	-39	3.5
		05/14/20	6.84	899	13.7	32.0	3.78	-34	3.5
		07/22/20	6.75	820	16.6	7.43	0.17	24	4.0
G12	Property, NE quadrant	03/27/17	7.34	1,296	20.7	–	0.41	150	1.3
		06/30/17	6.88	1,239	29.1	–	1.30	-87	–
		Decommissioned March 2019							
J5	Property, SW quadrant	03/21/17	6.95	251	15.1	4.6	0.70	-114	0.6
		06/26/17	6.94	484	19.8	–	0.42	-143	–
		04/05/18	6.85	286	14.1	–	0.50	77	–
		Decommissioned March 2019							
J15	Property, SE quadrant	03/27/17	7.42	935	14.1	–	0.48	141	2.0
		06/26/17	6.86	920	20.8	–	0.44	-99	1.5
		04/05/18	6.83	716	18.1	–	0.40	103	–
		Decommissioned March 2019							
K8	Property, SW quadrant	03/21/17	7.70	251	18.3	–	0.80	-121	0.0
		06/26/17	7.76	257	22.3	–	0.25	-4	0.0
		04/05/18	9.45	220	16.7	–	0.70	56	–
		Decommissioned March 2019							
M15	Property, SE quadrant	03/27/17	7.16	1,544	18.7	–	0.60	140	2.8
		06/26/17	6.71	1,440	25.6	–	0.70	-84	–
		04/05/18	6.90	1,034	18.0	–	0.40	86	–
		Decommissioned March 2019							
MW121	8th Ave N ROW, E side	12/26/13	6.89	1,610	–	–	4.16	-30	1.90
		03/28/17	6.63	2,608	14.4	2.9	0.99	-122	2.0
		06/20/17	8.29	2,437	19.9	–	0.52	-88	3.0
		04/05/18	6.64	2,028	17.2	–	0.60	120	–
		01/31/19	6.87	2,396	15.3	–	0.42	-3	–
		04/29/19	6.75	2,521	18.1	–	0.30	9	–
		07/19/19	6.38	2,017	18.8	–	0.46	-17	–
		11/30/20	6.50	1,838	15.9	–	0.39	-442	–
		02/05/21	6.67	1,912	15.6	4.2	1.73	48	–
		05/12/21	6.64	1,808	17.5	6.7	0.39	125	–
		08/02/21	6.63	1,853	21.6	10	0.25	124	–
		05/19/22	6.76	1,875	13.9	–	0.32	29	–
		08/04/22	6.78	1,628	18.0	–	0.60	79	–
		10/31/22	6.57	1,454	15.7	–	0.46	5	0.0
		05/16/23	8.13	1,811	16.7	–	0.17	-29	–
		11/07/23	6.71	1,051	15.6	–	1.30	-2	0.5
		05/21/24	6.64	1,652	13.0	–	2.10	200	–
		11/07/24	6.53	1,240	11.2	–	0.46	-22.2	2.2

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW125	Valley St ROW, N side	12/26/13	6.28	1,414	—	—	8.68	22	1.47
		03/22/17	6.62	1,296	14.6	3.7	1.00	-116	—
		06/28/17	6.71	984	17.1	—	1.91 ^d	-101	—
		04/06/18	6.89	831	17.5	—	0.30	-68	—
		01/21/19	6.67	912	15.8	—	0.48	122	—
		04/23/19	6.74	987	16.3	—	0.65	65	—
		07/18/19	6.90	920	18.9	—	0.40	59	—
		10/18/19	6.49	923	13.6	—	1.49	-86	2.0
		01/29/20	7.10	1,149	16.2	47.7	—	-115	2.0
		11/17/20	6.51	732	16.5	21.0	0.39	-168	—
		02/02/21	6.65	805	13.6	24.0	0.71	51	—
		05/11/21	6.66	772	16.4	5.9	0.23	-184	—
		08/02/21	6.43	759	19.6	7.2	0.31	125	—
		11/11/21	6.69	711	14.1	—	0.49	48	5.8
		02/22/22	6.76	1,895	9.1	—	0.68	-119	—
		05/19/22	6.77	736	13.4	—	0.41	-24	—
		08/09/22	6.73	650	18.3	—	0.58	-93	—
		10/31/22	6.51	587	15.0	—	0.88	25	3.0
		10/31/23	6.71	621	15.0	—	0.22	6	4.3
		11/05/24	6.37	86.5	14.4	—	0.33	-174.1	—
MW-154	Roy St ROW, S side	04/30/18	7.26	469	16.3	—	0.40	72	—
		01/21/19	7.25	523	14.4	—	0.61	99	—
		04/24/19	7.09	459	18.6	—	0.48	103	—
		07/15/19	6.96	517	20.0	—	1.21	157	—
		10/14/19	6.49	515	17.5	7.6	0.53	161	0.0
		01/21/20	6.81	965	11.1	15.1	1.61	-87	0.0
		04/30/20	6.85	652	18.5	4.0	1.06	234	0.0
		07/10/20	6.49	708	20.5	5.0	0.78	25	0.0
		11/09/20	6.94	567	14.9	24.1	5.29	27	—
		02/08/21	7.28	507	15.3	10.0	8.00	40	—
		05/10/21	7.23	469	19	7.2	4.97	-92	—
		08/17/21	6.80	494	18.1	11	6.90	4	—
		11/10/21	7.08	487	15.8	—	0.59	150	0.0
		02/18/22	7.27	872	14.8	—	4.91	-298	—
		05/02/22	7.09	671	14.9	—	5.98	211	—
		08/02/22	7.16	584	18.5	—	4.97	-15	—
		11/03/22	7.61	620	15.7	—	1.77	211	0.0
		05/12/23	7.04	583	16.5	—	0.14	-36	—
		11/10/23	6.97	619	13.5	—	1.25	-18	0.0
		06/04/24	6.59	640	15.1	—	0.35	168	—
		11/07/24	6.64	668	16.5	—	3.20	167.8	0.0
MW-155	Roy St ROW, S side	04/27/18	6.79	479	13.3	—	3.20	94	—
		01/21/19	6.52	500	12.3	—	2.43	119	—
		04/23/19	6.51	663	14.7	—	1.80	41	0.0
		07/23/19	6.26	765	14.4	—	2.06	66	—
		10/16/19	6.30	657	15.2	4.5	1.12	272	0.0
		01/20/20	5.93	819	13.7	19.9	2.00	45	0.0
		05/05/20	7.31	678	17.9	9.0	2.24	131	—
		08/03/20	6.73	686	20.1	70.1	2.45	114	0.5
		11/11/20	6.56	669	14.7	89.7	2.67	-67	—
		08/13/21	6.29	592	16.9	25	4.17	67	—
		12/02/21	6.28	563	12.5	—	4.67	207	0.0
		03/01/22	6.69	870	14.6	—	1.98	-208	—
		05/05/22	6.50	782	11.2	—	2.90	185	—
		08/03/22	6.60	774	18.7	—	2.37	-21	—
		11/04/22	7.18	995	14.8	—	0.28	181	0.0
		05/09/23	7.01	600	16.9	—	8.20	15	—
		11/10/23	7.15	848	13.6	—	1.63	56	0.0
		05/28/24	6.62	496	13.8	—	0.78	177	—
		11/11/24	6.80	898	14.2	—	1.24	-50.0	0.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-159	8th Ave N ROW, E side	04/26/18	6.92	928	18.9	—	0.70	109	—
		01/21/19	6.92	1,125	14.1	—	0.59	126	—
		04/26/19	6.83	1,279	14.5	—	0.54	79	—
		07/19/19	6.75	1,109	19.0	—	1.34	62	—
		01/29/20	6.79	1,081	14.2	4.7	0.11	-76	2.5
		11/11/20	6.78	588	12.4	4.1	0.60	-126	—
		02/08/21	6.83	625	11.1	168	0.57	-437	—
		05/11/21	6.91	625	14.4	356	0.14	-179	—
		08/05/21	6.81	477	19.5	32	0.22	101	—
		12/02/21	6.49	542	13.1	—	0.17	-105	4.5
		03/03/22	6.66	605.5	13.5	25	0.15	-700	—
		05/11/22	6.77	565	15.7	—	0.20	-104	—
		08/03/22	6.98	551	18.3	—	1.50	-75	—
		10/31/22	6.58	511	15.1	—	0.42	-24	3.5
		05/16/23	9.41	627	15.5	—	0.70	-60	—
		05/21/24	6.79	744	12.0	—	2.12	-100	—
		11/05/24	6.70	894	14.0	—	0.14	73.6	2.6
MW-214 (dry)	Valley St ROW, S side	03/30/17	7.47	467	11.0	3.6	5.91	-70	—
		06/21/17	—	—	—	—	—	—	—
		04/09/18	8.94	380	13.7	—	8.00	401	—
		10/11/19	6.91	692	16.3	10.5	0.44	122	—
		01/20/20	7.23	543	13.7	—	7.40	58	—
		04/07/20	6.62	413	11.5	—	1.03	71	0.0
		07/06/20	6.78	652	19.5	9.22	0.27	-89	0.0
MW-301	Valley St ROW, S side	11/30/20	6.33	459	16.2	20.5	2.20	-20	—
		02/05/21	6.26	442	10.8	44.9	0.99	-430	—
		05/14/21	6.33	450	14.1	63.8	0.5	-7	0.0
		08/20/21	6.18	460	15.9	14	1.23	169	0.0
		12/02/21	6.17	426	11.3	—	0.77	148	0.0
		05/10/22	5.69	496	13.6	—	0.00	94	0.2
		08/12/22	6.51	434	16.0	—	0.56	43	0.2
		10/31/22	7.15	601	13.2	—	0.47	176	0.0
		11/03/23	6.66	572	15.0	—	1.92	80	—
		11/05/24	6.12	692	15.0	—	0.47	-149.9	—
MW-305	Roy St ROW, S side	10/11/19	6.34	298	16.8	99.9	1.97	-11	0.0
		01/15/20	6.83	560	6.8	—	3.64	60	0.0
		04/28/20	6.50	480	16.0	93	4.75	89	0.0
		07/27/20	6.76	306	18.0	184	3.59	214	0.0
		11/06/20	6.54	339	15.3	329	1.87	-18	—
		05/18/21	6.62	557	16.2	123	5.19	128	—
		12/03/21	6.46	500	16.7	—	6.88	69	0.0
		05/26/22	6.75	443	16.6	—	3.29	7	—
MW-310	Alley E of Seattle Roy Aloha Shops	10/10/19	6.97	1,508	15.5	177	1.00	24	4.0
		01/14/20	6.38	1,969	10.7	4.2	0.18	-63	3.0
		04/08/20	6.48	1,503	16.9	—	0.21	-116	3.4
		08/04/20	6.83	1,489	19.4	20.7	0.27	108	3.6
		11/06/20	6.54	1,507	15.1	6.2	0.39	-145	—
		05/03/21	6.80	1,546	15.7	—	0.64	123	—
		11/04/21	6.80	1,460	14.3	—	0.51	176	3.5
		05/18/22	6.84	1,079	14.9	—	0.19	-105	—
		11/01/22	6.34	1,024	15.0	—	0.77	5	4.0
		11/07/23	6.77	1,095	14.8	—	1.27	-89	—
		11/12/24	6.84	1,349	15.0	—	0.20	-33.8	—
MW-312	Alley E of Seattle Roy Aloha Shops	10/11/19	6.84	1,670	16.4	59.6	0.49	-59	2.8
		01/21/20	6.56	1,621	14.8	2.0	0.40	-56	1.5
		04/22/20	6.66	1,703	12.6	24.7	0.64	43	3.4
		08/04/20	6.99	1,672	21.5	—	1.50	-64	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-312 (continued)		11/11/20	6.31	267	12.0	100	0.70	-92	—
		05/03/21	6.93	1,684	14.9	9.1	0.99	121	—
		11/03/21	6.45	215	15.7	—	0.38	101	2.5
		05/09/22	6.69	1,453	16.2	—	0.12	-86	—
		11/01/22	6.58	1,192	15.4	—	0.89	71	4.0
		11/07/23	6.90	1,347	14.8	—	1.21	-82	—
		11/08/24	6.76	1,409	15.8	—	0.33	-123.0	—
MW-313	Alley E of Seattle Roy Aloha Shops	10/10/19	7.06	718	17.3	66.4	0.77	131	0.5
		01/14/20	6.83	979	8.1	—	0.42	76	3.0
		05/04/21	6.66	798	14.7	114	1.08	-131	—
		11/09/21	6.55	785	15.0	—	1.14	34	0.6
		05/18/22	6.69	1,130	15.5	—	0.64	53	—
		11/01/22	7.01	1,507	15.3	—	0.21	261	0.0
		05/15/23	6.81	1,274.0	23.8	—	0.83	9	—
		11/07/23	7.09	90	15.7	—	2.10	-60	0.2
		05/22/24	6.77	1,099	16.4	—	2.33	23	—
		11/12/24	6.70	1,160	13.8	—	0.69	-60.8	—
MW-320	9th Ave N ROW, W side	10/07/19	6.65	552	17.4	21.3	0.39	253	0.0
		01/20/20	6.66	1,187	14.7	0.7	0.90	-120	4.8
		04/29/20	6.69	828	15.8	3	0.42	83	5.0
		07/28/20	6.96	751	17.8	7.08	0.96	-56	3.5
		11/12/20	6.72	630	12.6	14.7	0.50	-107	—
		05/20/21	6.70	880	14.5	4.5	0.18	-116	—
		11/16/21	6.62	418	15.5	—	1.08	72	0.0
		11/10/21	6.56	796	13.9	—	0.00	40	5.0
		06/08/22	6.77	499	15.6	—	4.14	66	—
		11/04/22	6.10	989	16.3	—	0.53	179	0.0
MW-332	Roy St ROW, N side	05/04/20	6.99	880	18.2	3.0	0.50	-50	2.5
		07/30/20	6.90	831	26.8	27.0	0.56	14	0.5
		11/12/20	6.82	616	12.3	36.8	0.57	13	—
		05/20/21	6.84	706	14.6	5.3	3.77	-77	—
		11/08/21	6.91	723	16.3	—	1.31	118	0.0
		05/31/22	6.80	893	16.2	—	0.68	18	—
		11/04/22	6.65	1,364	15.1	—	0.83	-26	0.25
		11/08/23	7.05	680	15.7	—	1.20	-34	—
		11/07/24	6.82	835	15.6	—	0.36	-74.8	—
MW-337	Lake Union Park, N end	05/07/20	6.62	548	12.7	3.9	1.18	-76	2.0
		07/23/20	6.91	449	15.4	4.0	0.12	-64	3.2
		11/10/20	6.68	330	13.1	1.6	0.18	-125	—
		05/04/21	6.77	557	12.9	—	0.06	123	—
		11/17/21	6.41	636	14.8	—	0.00	73	0.3
		05/03/22	6.78	542	11.9	—	1.08	51	—
		11/02/22	6.60	432	14.6	—	0.76	47	3.0
		11/09/23	7.50	501	13.3	—	0.16	-3	—
MW-339	Lake Union Park, S end	05/14/20	7.27	670	12.1	2.0	0.10	-69	2.0
		07/23/20	6.76	1,237	14.9	1.85	0.27	-60	1.5
		11/09/20	6.76	503	13.8	4.2	0.12	-151	—
		05/25/21	6.80	791	13.7	—	0.16	135	—
		11/10/21	6.62	376	12.2	—	0.72	93	0.2
		05/04/22	7.06	543	11.9	—	4.21	-1	—
		11/02/22	6.63	498	12.3	—	0.78	69	0.0
MW-8 (dry)	Seattle Roy Aloha Shops N end	03/20/17	6.47	1,080	14.2	11.4	1.30	-4	—
		06/27/17	—	—	—	—	—	—	—
		04/13/18	5.99	540	13.1	—	0.80	261	—
		07/18/19	6.20	692	16.9	—	0.27	224	—
		10/10/19	6.35	425	15.4	5.2	0.45	126	—
		01/16/20	5.86	322	13.0	6.9	0.40	48	—
		05/06/20	6.24	420	13.7	—	1.91	250	—
		07/14/20	6.35	494	17.6	5.8	1.99	-64	3.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-9	8th Ave N ROW, E side	12/16/13	6.72	132	—	—	0.20	263	3.41
		03/20/17	6.64	1,203	13.0	0.0	1.00	-109	—
		06/20/17	6.41	1,391	20.8	—	0.76	-93	—
		04/05/18	6.73	1,299	13.4	—	0.80	128	—
		01/21/19	6.63	1,179	12.5	—	0.71	143	—
		04/26/19	6.68	632	16.6	—	0.50	62	—
		07/16/19	6.70	1,060	17.4	—	0.22	-118	—
		10/17/19	6.27	1,190	14.4	—	0.52	-104	2.0
		11/24/20	6.50	1,120	13.9	95.4	0.38	-291	—
		02/05/21	6.39	617	14.2	8.0	0.40	42	—
		05/12/21	6.70	1,174	14.8	2.3	0.29	-159	—
		08/02/21	6.54	1,150	20.4	3.8	0.29	128	—
		11/11/21	6.61	1,006	14.8	—	0.43	175	5.8
		02/15/22	6.61	1,046	12.4	—	0.47	-247	—
		06/08/22	6.64	1,071	—	—	0.26	-13	—
		08/09/22	6.75	1,008	19.1	—	0.55	-44	—
		10/31/22	6.63	923	16.3	—	0.10	74	0.5
		05/12/23	6.75	1,084	17.8	—	0.53	-101	—
		11/06/23	6.68	1,247	15.4	—	1.15	-31	4.0
	05/21/24	6.54	1,149	13.3	—	2.03	-60	—	
	DUP	05/21/24	6.54	1,149	13.3	—	2.03	-60	—
N7	Property, SW quadrant	03/30/17	6.82	350	15.9	2.8	1.11	-74	0.0
		06/27/17	6.83	505	24.9	1.7	1.74 ^d	-4	0.3
	Decommissioned March 2019								
R-MW2	Property, NE quadrant	03/21/17	7.00	723	11.4	17.6	0.80	-161	—
		06/15/17	6.78	766	15.5	—	0.43	-161	—
		04/02/18	6.68	737	14.5	—	0.70	49	—
Decommissioned March 2019									
R-MW3	Property, NE quadrant	03/21/17	7.06	1,616	16.7	4.1	0.90	-39	—
		06/28/17	7.11	1,258	23.5	—	1.01	-132	—
		04/04/18	6.96	1,241	16.8	—	0.50	98	—
Decommissioned March 2019									
R-MW5	Dexter Ave N ROW E side	03/23/17	6.12	537	17.1	—	0.80	-37	1.0
		06/16/17	5.85	516	17.6	—	1.12	-370	—
		04/11/18	9.57 ^(a)	504	15.5	—	0.50	213	—
		01/03/19	5.96	533	14.7	—	0.81	71	—
		04/22/19	6.14	410	15.9	—	0.54	100	—
		07/16/19	6.06	378	18.8	—	0.26	52	—
		10/21/19	6.33	346	16.6	66.7	0.70	156	1.0
		01/24/20	5.97	440	12.3	9.6	0.33	25	2.5
		11/18/20	7.25	339	16.8	90.0	0.32	-388	—
		02/11/21	6.21	247	12.5	17.8	0.59	-397	—
		05/17/21	5.88	250	14.2	—	0.19	110	—
		08/03/21	6.08	275	18.9	7.1	0.85	9	—
		11/08/21	6.45	188	14.8	—	0.00	22	1
		02/24/22	6.04	252	10.3	—	0.91	-48	—
		05/17/22	6.20	415	14.2	—	0.18	63	—
		08/09/22	6.34	481	16.1	—	1.80	-6	—
		11/08/22	6.47	303	15.9	—	1.23	83	2.5
		10/30/23	6.75	371	16.5	171	4.31	-48	1.5
		11/13/24	6.22	222	16.3	—	0.39	196.7	0.5
R-MW6	8th Ave N ROW, W side	03/21/17	6.56	1,280	14.8	6.6	0.80	-39	—
		06/20/17	6.57	1,407	18.0	—	0.84	-56	1.5
		04/06/18	6.72	1,137	16.8	—	0.70	113	—
		01/25/19	6.75	1,055	14.9	—	0.33	-101	—
		04/25/19	6.77	1,295	17.5	—	0.40	18	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
R-MW6 (continued)		12/01/20	6.35	765	12.9	15.2	0.71	-42	—
		02/03/21	6.57	936	11.2	8.0	0.20	49	—
		05/17/21	5.72	1,187	15.1	—	1.30	118	—
		08/03/21	6.08	1,406	19.9	4.2	1.14	78	—
		11/29/21	7.13	1,074	15.1	—	0.08	-112	3.2
		02/23/22	6.11	1,225	9.7	—	0.69	-100	—
		05/11/22	6.32	2,045	14.0	—	0.20	-61	—
		08/03/22	6.35	1,341	18.7	—	11.8 ^d	-93	—
		11/04/22	6.09	1,429	16.0	—	0.91	110	2.0
		05/16/23	6.75	1,480	16.5	—	0.15	-54	—
		05/22/24	6.54	982	13.3	—	0.25	39	—
		11/08/24	6.41	1,299	18.6	—	0.30	-119.8	4.8
SCL-MW101	Alley E of Seattle Roy Aloha Shops	03/28/17	7.34	834	11.8	—	0.35	118	—
		06/14/17	6.35	628	17.9	—	0.12	-49	—
		04/06/18	6.61	654	14.3	—	0.30	66	—
		10/09/19	6.10	1,468	16.4	—	0.48	-78	—
		01/17/20	6.46	1,378	12.3	1.4	0.46	-59	—
		04/07/20	6.20	866	15.6	—	0.30	-79	—
		11/24/20	6.43	813	14.8	126	0.64	-112	—
		05/04/21	6.49	1,126	18.1	—	1.09	124	—
		11/11/21	6.57	1,129	16.1	—	0.45	40	2.8
		05/19/22	6.60	1,458	15.6	—	0.29	92	—
		11/03/22	6.58	1,338	16.4	—	3.31	-17	1.8
		11/11/24	6.62	1,178	16.2	—	0.20	6.7	5.0
SCL-MW105	Alley E of Seattle Roy Aloha Shops	03/28/17	7.19	1,049	12.6	—	0.50	136	—
		06/15/17	6.45	1,086	15.8	—	1.11	-95	—
		04/06/18	6.73	968	15.4	—	0.40	76	—
		10/10/19	6.50	1,289	14.2	17.8	0.57	-83	—
		01/17/20	6.53	1,552	11.1	0.8	0.33	-54	—
		04/01/20	6.33	987	15.9	14.0	0.20	-87	4.0
		07/24/20	6.62	1,108	18.3	1.0	2.28	-99	—
SCS-2	Seattle Roy Aloha Shops N end	03/20/17	6.50	947	13.0	1.6	1.00	-142	—
		06/12/17	6.41	761	17.3	—	0.59	-31	—
		04/13/18	10.72 ^(a)	199	10.5	—	0.80	215	—
		07/18/19	6.48	895	16.0	—	0.32	-97	—
		10/10/19	6.60	776	13.9	4.5	0.53	-18	—
		01/16/20	6.03	541	13.2	3.3	0.40	-25	—
SMW-3	Valley St ROW, N side	03/30/17	6.48	743	11.8	2.9	0.98	-86	—
		06/21/17	6.35	589	20.9	—	0.41	-57	—
		04/09/18	7.79 ^(a)	807	14.9	—	0.60	-18	—
		10/11/19	6.33	846	16.5	223	0.57	54	—
		01/17/20	6.54	711	12.5	9.7	0.30	-43	—
		04/09/20	6.19	698	19.0	1.3	0.17	50	4.8
		07/07/20	6.36	735	19.1	8.9	1.79	-98	6.0
Intermediate A Zone									
BB-8	Roy St ROW, S side	12/29/13	6.56	8,560	—	—	0.72	224	0.01
		03/22/17	6.74	621	14.6	—	1.80	-23	0.0
		06/14/17	6.29	649	14.5	—	1.12	188	0.0
		04/11/18	6.96	512	14.5	—	0.70	85	0.0
		01/23/19	6.80	700	12.9	—	0.76	154	0.0
		04/23/19	6.94	649	14.2	—	1.28	34	0.0
		07/17/19	6.50	640	15.9	—	0.50	-6	0.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
BB-8 (continued)		10/22/19	6.37	551	16.1	13.6	0.32	221	0.0
		01/20/20	6.70	796	14.8	0.9	1.10	45	0.0
		05/12/20	6.69	622	15.5	3.0	1.14	280	0.0
		07/27/20	6.51	638	17.4	57.3	0.40	103	0.5
		11/17/20	6.67	590	14.5	89.2	0.56	41	—
		02/11/21	6.94	456	9.4	14.0	3.78	47	—
		06/07/21	6.76	465	19.6	14.6	3.14	-77	—
		08/17/21	6.61	502	17.7	—	1.54	139	—
		11/08/21	6.92	493	15.9	4.3	2.51	93	0.0
		02/24/22	6.86	645	12.5	—	2.56	-209	—
		05/17/22	6.83	657	16.3	—	2.50	-27	—
		08/09/22	6.83	550	18.8	—	1.10	-6	—
		11/09/22	6.72	631	14.0	—	2.25	-15	0.0
		05/09/23	6.87	518	15.8	—	0.52	-24	—
		10/31/23	6.91	580	16.4	—	2.35	24	0.5
		05/22/24	6.98	744	15.1	—	0.29	-153	—
		11/13/24	7.01	923	15.6	—	0.30	-159.6	4.5
FMW-142	9th Ave N ROW, E side	10/31/19	6.22	556	12.8	10.3	0.38	-57	0.5
		01/22/20	7.22	1,113	8.7	0.9	0.44	-48	2.2
		04/28/20	6.83	725	16.5	11	0.41	69	5.0
		07/08/20	6.96	738	17.2	16.7	0.60	-25	4.4
		11/04/20	6.80	685	16.9	46.7	0.34	-109	—
		05/25/21	6.84	725	15.1	—	0.27	-182	—
		03/02/22	6.86	830	14.8	—	0.26	-436	—
		06/05/22	6.84	778	15.3	—	0.39	-84	—
		11/04/22	6.76	742	15.8	—	0.84	-161	—
		11/15/24	6.74	129.7	13.8	—	2.48	-51.2	—
GEI-1	Block 37, SW quadrant	03/24/17	6.41	1,127	12.0	24.1	0.80	-103	1.0
		06/13/17	6.65	553	14.9	—	0.56	-38	—
		04/22/19	6.35	1,099	13.3	—	0.68	-46	—
		07/16/19	6.66	908	19.2	—	0.21	-105	3.0
		10/21/19	6.65	1,285	15.1	—	0.20	-70	2.1
		01/22/20	6.83	1,108	10.8	4.7	0.40	-55	3.0
		04/29/20	6.61	639	14.8	6.5	1.05	-87	2.0
		07/30/20	6.64	854	17.8	—	1.50	-87	2.4
GEI-MW-1	Block 79 East, N end	01/23/20	6.95	1,127	14.8	17.4	0.41	-24	3.2
		04/29/20	6.90	850	19.0	5.0	0.37	-87	4.0
		08/07/20	6.86	802	21.9	18	1.11	-89	3.5
		11/10/20	6.83	609	14.0	1.4	0.30	-130	—
		05/13/21	6.77	746	17.0	—	0.21	128	—
		03/07/22	6.88	647	15.0	8.0	0.13	-664	—
		05/27/22	6.86	688	15.5	—	0.37	-116	—
		11/04/22	6.90	748	16.4	—	0.21	-9	3.8
		05/16/23	6.82	741	18.6	—	0.21	-87	—
		11/08/23	8.27	751	16.7	—	0.20	-23	—
		05/23/24	6.71	682	15.8	—	0.19	-25	—
		11/15/24	6.78	1,027	15.4	—	0.29	-131.4	—
HMW-9IA	SDOT Mercer Parcels SW quadrant	06/02/21	7.53	596	22.2	22.0	0.26	-107	0.00
		08/18/21	7.45	599	18.2	41.2	0.29	-111	0.25
HMW-20IA	SDOT Mercer Parcels NW quadrant	06/02/21	7.32	757	19.4	16.5	0.45	-19	0.50
		08/18/21	7.54	735	16.3	1.6	0.23	-94	0.0
MW107	8th Ave N ROW, W side	12/16/13	6.62	900	—	—	1.14	22	0.43
		03/27/17	7.10	1,434	13.7	—	0.50	141	2.0
		06/19/17	6.24	1,434	22.5	—	0.77	-30	1.5
		04/09/18	6.73	1,193	18.4	—	0.30	49	4.0
		01/30/19	6.99	1,299	11.0	—	0.74	127	—
		05/01/19	6.85	1,216	16.9	—	0.33	24	2.0
		07/22/19	6.64	1,187	21.5	—	2.72	-9	1.4

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW107 (continued)		10/15/19	6.93	1,263	19.9	85.3	0.38	-66	3.4
		01/28/20	7.31	1,663	16.8	9.2	—	-97	4.5
		04/03/20	6.79	1,468	15.0	10.4	2.56	-77	3.0
		07/31/20	6.93	762	19.4	27.1	0.64	52	1.2
		12/01/20	6.79	1,183	13.5	—	0.89	-36	—
		02/02/21	6.73	903	12.7	9.0	0.72	46	—
		06/02/21	6.44	1,701	16.4	—	0.22	-6	—
		08/16/21	6.56	1,832	18.4	—	0.35	-88	—
		11/29/21	6.31	1,318	15.0	—	0.17	-61	1.4
		02/23/22	6.60	1,205	11.4	—	0.82	-80	—
		05/11/22	6.70	1,316	16.0	—	0.15	-53	—
		08/03/22	6.76	1,319	21.8	—	5.40	-87	—
		10/31/22	6.68	1,370	15.8	—	5.95	-13	6.75
		02/23/23	6.52	1,144	10.3	—	0.88	-44.2	—
		05/15/23	6.75	1,624	23.1	—	0.53	-87	—
		11/03/23	6.69	1,249	17.1	—	0.73	-106	3
		02/26/24	6.86	933	10.8	—	0.48	-155	—
		05/22/24	6.89	695	13.7	—	0.41	142	—
		09/05/24	6.82	873	19.9	—	1.46	-2.7	—
		11/08/24	6.72	852	17.2	—	0.28	-114.9	5.0
MW108	Alley E of Seattle Roy Aloha Shops	12/17/13	6.36	1,570	—	—	0.50	-72	21.7
		03/28/17	6.65	1,410	13.6	2.0	0.97	-99	2.5
		06/27/17	6.72	1,252	16.3	—	4.45 ^d	-108	2.0
		04/06/18	6.69	1,026	14.6	—	0.60	136	—
		01/22/19	6.77	1,053	11.9	—	0.80	132	—
		04/29/19	6.61	1,296	14.4	—	0.42	-18	—
		07/15/19	6.55	1,217	17.7	—	0.78	-49	—
		10/10/19	6.81	1,178	15.1	14.3	1.49	3	3.3
		01/14/20	6.87	1,568	12.2	2.0	0.09	-84	4.5
		04/22/20	6.69	1,347	14.9	31.2	2.21	-96	6.6
		07/16/20	6.91	1,296	16.5	16.6	2.32	-148	7.0
		11/04/20	6.57	1,222	16.8	27.6	0.45	-114	—
		02/09/21	6.53	1,225	12.9	11.0	0.89	-451	—
		05/03/21	6.74	1,192	15.9	—	0.38	129	—
		08/04/21	6.58	1,157	20.2	4.7	0.32	111	—
		11/04/21	6.81	796	15.8	—	0.85	176	4.5
		02/15/22	6.73	1,144	12.8	—	0.41	-195	—
		05/18/22	6.72	1,087	15.3	—	0.44	-78	—
		08/10/22	6.69	860	17.1	—	0.98	-83	—
		11/01/22	6.32	835	15.0	—	0.68	7	0.0
		05/12/23	6.67	1,038	20.0	—	0.59	-64	—
		11/07/23	6.81	853	15.7	—	1.19	-79	4.0
		05/21/24	6.61	793	10.7	—	0.27	8	—
		11/12/24	6.86	1,062	15.9	—	0.20	-20.0	7.0
MW109	Alley E of Seattle Roy Aloha Shops	12/17/13	6.68	1,540	—	—	0.31	-78	16.2
		03/29/17	6.59	916	14.9	2.8	0.77	-115	1.5
		06/27/17	6.72	1,129	16.9	—	3.85 ^d	-107	1.5
		04/06/18	6.71	1,112	14.3	—	0.50	136	—
		01/23/19	6.97	1,203	15.7	—	0.59	143	—
		04/29/19	6.52	1,128	14.2	—	0.45	40	—
		07/15/19	6.57	1,214	17.5	—	0.44	-29	—
		10/15/19	6.40	1,167	15.2	16.2	0.46	-95	2.5
		01/21/20	6.48	206	14.2	4.1	4.50	60	0.0
		04/22/20	6.35	1,110	14.4	8.7	0.30	107	3.0
		07/06/20	6.11	1,037	19.1	35.5	0.31	25	6.0
		11/02/20	6.61	1,199	17.0	22.8	1.29	-48	—
		02/09/21	6.60	946	13.3	16.4	0.70	-444	—
		05/03/21	6.74	854	14.6	12.3	0.54	127	—
		08/04/21	6.35	150	19.4	8	0.25	81	—
		11/03/21	6.73	777	15.7	—	0.85	124	5.5
		02/15/22	6.74	861	14.9	—	2.02	133	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW109 (cont.)		05/09/22	6.20	901	16.7	—	0.00	-84	—
		08/10/22	6.66	65	17.5	—	1.50	160	—
		11/01/22	6.41	759	15.6	—	0.78	30	4.5
		05/15/23	6.65	879	22.4	—	0.34	-65	—
		11/07/23	6.77	787	14.9	—	1.41	-72	2.5
		05/21/24	6.62	624	15.4	—	0.27	-21	—
		11/08/24	6.62	885	15.8	—	0.28	-121.6	4.0
MW110	Alley E of Seattle Roy Aloha Shops	12/19/13	8.82	888	—	—	0.52	291	0.04
		03/23/17	6.66	1,109	13.1	0.4	1.05	-47	0.1
		06/27/17	7.13	1,010	17.2	—	1.42 ^d	57	0.0
		04/09/18	6.22	895	16.1	—	0.70	431	—
		01/23/19	6.74	1,020	14.5	—	0.41	103	—
		04/26/19	6.67	998	16.7	—	0.49	135	—
		07/15/19	6.68	965	16.2	—	0.45	160	—
		10/15/19	6.34	976	15.8	—	0.45	-19	—
		01/16/20	6.59	988	14.7	15.5	0.04	17	—
		04/22/20	6.80	1,005	13.8	30.9	1.02	10	0.0
		07/16/20	7.03	1,046	18.5	28.0	0.41	1	0.0
		11/04/20	7.08	1,028	16.6	63.8	0.36	-59	—
		02/09/21	6.66	863	13.4	107	0.83	-497	—
		05/04/21	6.71	824	18.4	116	0.48	-80	—
		08/12/21	6.60	789	25.7	132	0.39	127	—
		11/09/21	6.91	947	13.4	—	0.62	32	0.2
		02/25/22	6.75	788	14.2	—	0.52	-157	—
		05/18/22	6.74	757	16.1	—	0.41	48	—
		08/11/22	6.85	600	16.5	—	2.46	72	—
		11/01/22	7.52	873	14.7	—	0.24	199	0.0
		05/15/23	6.86	713	16.6	—	0.33	13	—
		11/07/23	7.13	71	15.4	—	0.68	-62	0.3
		05/22/24	6.74	895	15.9	—	1.98	18	—
		11/12/24	6.68	1,041	14.1	—	0.38	-94.9	0.5
MW115	9th Ave N ROW, W side	12/19/13	6.80	1,220	—	—	0.71	-61	6.69
		03/22/17	7.28	880	14.8	—	0.51	160	1.5
		06/22/17	6.85	778	20.2	—	0.39	-102	1.5
		04/11/18	6.91	860	13.1	—	0.40	89	—
		01/30/19	7.03	912	12.7	—	0.57	116	—
		07/17/19	6.68	935	16.4	—	0.37	34	—
		10/22/19	6.64	699	15.3	0.1	0.51	-140	2.0
		01/20/20	6.88	737	15.5	9.7	0.20	-35	2.0
		05/05/20	6.57	1,266	17.6	93.5	1.21	-102	2.0
		07/28/20	6.85	983	20.2	152	0.72	-58	4.5
		11/12/20	6.84	579	14.5	87.4	0.36	-121	—
		02/12/21	6.89	727	9.6	—	0.39	-16	—
		05/25/21	6.88	679	18.1	—	0.22	-171	—
		08/11/21	6.74	1,107	22.8	—	0.15	128	—
		11/18/21	6.94	608	14.5	—	0.00	62	3.5
		02/15/22	7.00	859	14.6	—	0.15	-105	—
		06/03/22	6.78	759	17.6	—	0.31	-76	—
		08/10/22	7.06	520	17.5	—	0.72	-99	—
		11/03/22	6.01	518	13.8	—	0.54	69	2
		05/18/23	6.76	727	20.7	—	0.18	-59	—
		05/24/24	7.25	651	15.4	—	0.72	20	—
		11/07/24	6.81	803	16.0	—	0.23	-74.6	—
MW116	9th Ave N ROW, W side	12/19/13	6.84	498	—	—	0.67	75	2.65
		03/21/17	7.05	814	13.3	6.2	0.80	-127	3.9
		06/16/17	6.86	749	18.7	—	0.41	-641	1.8
		04/11/18	7.11	830	13.3	—	0.40	75	—
		01/30/19	7.09	771	15.5	—	0.65	-122	2.0
		07/17/19	6.89	822	16.6	—	0.42	40	—
		10/22/19	6.86	640	15.9	2.0	0.22	158	1.3
		01/21/20	6.98	697	13.6	—	0.60	-28	1.0
		04/29/20	—	701	17.3	246	0.21	245	3.8
		07/28/20	7.05	607	25.6	416	0.75	-92	2.5

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW116 (continued)		11/12/20	6.92	680	15.1	346	0.20	-221	—
		02/11/21	7.03	652	9.7	49.0	0.34	49	—
		05/25/21	7.03	678	16.6	—	0.20	-197	—
		08/11/21	7.01	670	0.3	—	0.25	107	—
		11/18/21	7.01	631	15.1	—	0.00	61	2.8
		03/07/22	7.02	645	13.7	—	0.16	-649	—
		06/08/22	7.00	665	19.5	—	0.30	-116	—
		08/10/22	7.18	494	19.0	—	0.63	-106	—
		11/04/22	6.24	541	15.5	—	1.08	146	2.0
		05/18/23	6.93	679	22.4	—	0.25	-69	—
		11/08/23	7.11	660	16.3	—	1.28	-93	—
		05/23/24	7.03	547	18.5	—	0.27	-36	—
		11/06/24	7.00	742	16.5	—	0.28	-124.3	—
MW119	9th Ave N ROW, W side	12/19/13	9.56	579	—	—	0.34	295	18.6
		03/29/17	6.41	631	13.4	2.4	0.85	-91	2.0
		06/28/17	6.29	676	17.4	—	4.88 ^d	11	1.5
		04/05/18	6.30	517	13.1	—	0.60	119	—
		01/21/19	6.76	67	12.6	—	6.76	114	—
		04/29/19	6.33	652	15.1	—	0.42	-3	—
		07/19/19	6.34	26	16.7	—	0.61	1	—
		10/10/19	6.66	582	14.8	—	0.44	-10	3.0
		01/14/20	6.33	533	12.7	—	0.38	-308	—
		02/18/20 ^c	6.43	545	12.9	—	1.10	-58	—
		03/24/20 ^c	6.02	573	11.4	—	0.21	-7	—
		04/27/20	6.34	606	14.1	1.4	0.13	-31	3.5
		05/19/20 ^c	6.34	512	14.8	—	1.80	-50	—
		07/08/20	6.41	535	15.5	41.0	0.27	-19	5.5
		11/11/20	6.44	542	14.0	81.7	0.24	-177	—
		02/10/21	6.43	468 ^(c)	13.0	30.4	0.65	-25	—
		05/20/21	6.33	529	15.1	45.6	0.32	-102	—
		08/13/21	6.20	541	17.7	45	0.24	-71	—
		12/03/21	6.32	366	12.5	—	0.40	-97	1.8
		03/02/22	6.42	515	12.4	—	0.73	-68	—
		05/05/22	6.43	651	12.0	—	0.64	-75	—
		08/11/22	6.53	424	16.4	—	1.14	-64	—
		11/02/22	7.11	316	14.2	—	0.46	189	1.5
		05/09/23	6.38	638	14.7	—	0.10	42	—
		05/24/24	6.37	496	14.0	—	0.21	-13	—
		11/08/24	6.43	633	15.5	—	0.23	1.0	4.0
MW120	8th Ave N ROW, E side	12/19/13	6.63	743	—	—	1.30	-13	0.170
		03/28/17	7.93	622	9.5	—	0.75	123	—
		06/28/17	6.60	568	17.8	—	1.33 ^d	91	—
		04/09/18	6.96	423	15.1	—	0.40	37	0.0
		01/24/19	6.66	649	14.0	—	0.73	110	—
		05/03/19	6.46	533	14.6	—	0.36	253	—
		07/16/19	6.31	632	17.7	—	0.66	120	0.0
		10/17/19	6.08	742	15.0	—	0.51	-67	0.0
		01/17/20	6.47	1,028	13.3	12.6	0.15	-8	0.5
		04/23/20	6.40	742	15.4	15.7	4.21	103	1.2
		07/14/20	6.34	785	19.0	47.8	1.44	-36	0.0
		11/30/20	6.55	723	15.3	95.0	0.92	-24	—
		02/05/21	6.54	714	12.9	39.0	0.57	44	—
		05/12/21	6.56	682	17.6	52.9	0.29	-112	—
		08/03/21	6.47	671	18.6	27	0.42	111	—
		11/11/21	6.45	625	15.5	—	0.49	171	0.2
		02/15/22	6.62	614	13.5	—	0.44	-221	—
		05/11/22	6.62	598	17.9	—	0.41	48	—
		08/04/22	6.70	521	19.0	—	0.68	27	—
		10/31/22	6.86	473	15.9	—	0.83	15	0.0
		05/12/23	6.66	449	21.6	—	0.47	-27	—
		11/06/23	6.70	479	15.8	—	1.19	21	0.5
		05/21/24	6.62	457	14.8	—	2.18	17	—
		11/07/24	6.17	54.4	15.6	—	0.48	83.3	0.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW127	8th Ave N ROW, E side	08/01/19	6.95	440	17.2	—	0.34	164	—
		10/17/19	6.30	471	15.0	—	0.35	-83	0.0
		01/17/20	6.82	602	12.9	80.2	0.13	35	0.0
		04/23/20	6.74	476	15.0	99.9	3.95	88	0.0
		07/14/20	6.91	484	17.7	151	0.45	-76	0.0
		11/13/20	6.67	496	15.5	847	0.27	-118	—
		05/11/21	6.83	474	19.0	40.5	0.32	-148	—
		11/17/21	6.87	431	14.4	—	0.00	65	0.0
		05/20/22	6.87	450	13.6	—	0.61	51	—
		10/31/22	6.57	379	15.7	—	0.33	-7	0.0
		05/16/23	6.88	500	19.4	—	0.25	-83	—
		11/06/23	7.16	455	15.2	—	1.49	-10	—
		05/21/24	6.84	563	13.7	—	2.54	36	—
		11/12/24	6.79	513.1	15.8	—	0.28	-118.9	—
MW131	Property, SE quadrant	03/27/17	7.01	2,045	19.5	2.4	0.85	-134	1.9
		06/20/17	15.39 ^(a)	2,071	21.9	—	0.62	-86	—
		04/16/18	6.96	1,610	17.3	—	0.30	18	1.8
		10/25/18	6.66	1,546	18.9	—	0.39	-55	—
		12/12/18	6.78	1,899	14.5	—	0.44	129	—
		01/29/19	6.86	1,948	9.2	—	0.77	137	—
		03/11/19	6.70	1,849	14.0	—	1.30	-21	—
		Decommissioned March 2019							
MW-142	8th Ave N ROW, E side	04/27/18	6.96	1,349	18.9	—	0.50	133	1.5
		01/28/19	6.94	1,528	11.7	7.9	0.75	152	2.0
		04/24/19	7.00	1,541	15.6	—	0.70	121	1.2
		07/25/19	6.70	1,665	20.4	—	1.09	13	2.1
		10/16/19	6.36	1,456	15.7	—	0.85	-35	2.0
		01/22/20	6.72	2,032	16.9	37.3	0.11	-99	2.5
		04/24/20	6.74	1,789	18.8	106.0	1.20	-119	3.0
		07/30/20	6.83	1,505	20.5	18.0	1.06	-20	3.5
		11/24/20	6.61	1,490	17.1	283	0.21	-301	—
		02/08/21	6.8	1,467	14.6	6.0	0.49	38	—
		05/19/21	6.78	1,527	14.2	20.1	0.3	-132	—
		08/05/21	6.79	1,569	19.7	8.7	0.49	101	—
		11/30/21	6.67	1,685	15.7	—	0.22	-156	4.0
		02/18/22	6.70	1,712	13.2	—	0.68	-108	—
		05/26/22	6.82	1,771	15.2	—	0.42	-107	—
		08/03/22	6.81	421	19.4	—	0.59	-21	—
		10/31/22	6.78	1,511	16.3	—	1.24	7	4.5
		05/16/23	7.06	1,891	17.0	—	0.05	-74	—
		11/06/23	6.91	1,723	14.5	—	1.44	-92	3.5
		05/21/24	6.76	136	12.7	—	4.97	216	—
		11/06/24	6.51	279.1	14.3	—	0.27	-68.2	0.4
MW-144	8th Ave N ROW, E side	04/27/18	7.34	1,739	16.4	—	0.40	100	0.5
		01/28/19	7.44	1,798	13.1	5.3	0.57	125	—
		04/23/19	7.39	1,749	16.8	—	0.45	67	1.2
		Destroyed June 2019, Decommissioned December 2019							
MW-144R	8th Ave N ROW, E side	12/16/19	7.81	1,250	16.0	16.6	0.34	-131	2.0
		01/21/20	7.22	1,723	11.0	13.3	0.46	-136	3.5
		04/02/20	7.37	1,334	13.2	81.6	0.40	-32	3.0
		08/03/20	7.41	1,340	18.8	75.6	0.39	-152	2.4
		11/23/20	7.41	1,159	14.2	153	0.65	-178	0.0
		02/02/21	7.45	1,383	9.6	5.0	0.34	46	—
		02/08/21	6.80	1,467	14.6	6.0	0.49	38	—
		05/12/21	7.36	1,406	17.8	5.0	0.55	-202	—
		08/03/21	7.35	1,482	20.6	4.5	0.31	118	—
		11/29/21	7.62	1,064	18.1	—	0.00	-178	3.4

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-144R (continued)		02/23/22	7.47	1,514	9.3	—	0.78	-119	—
		05/11/22	7.46	1,558	16.6	—	0.18	-91	—
		08/23/22	7.52	1,519	19.5	—	0.05	-53	—
		11/02/22	7.38	1,592	13.1	—	0.85	-136	0.8
		05/15/23	7.36	1,697	16.8	—	0.07	-59	—
		11/08/23	7.35	1,654	14.6	—	1.63	-131	4.0
		05/22/24	7.24	1,687	13.9	—	2.09	-88	—
		11/07/24	7.07	1,403	14.0	—	0.43	-133.4	3.2
MW-146	Roy St ROW, S side	04/30/18	7.27	694	17.0	—	0.40	95	1.3
		01/22/19	7.56	621	12.1	—	0.48	122	2.0
		04/24/19	7.20	564	16.5	—	0.76	11	2.5
		07/19/19	6.76	713	16.6	—	2.60	70	1.9
		10/14/19	6.68	648	16.9	22.6	0.49	98	2.0
		01/24/20	6.85	1,019	14.7	2.8	0.04	-94	4.0
		04/30/20	7.18	827	15.8	5.2	0.23	-90	2.5
		07/09/20	7.30	805	18.6	5.0	0.26	-11	3.0
		11/10/20	7.12	665	16.1	3.2	0.30	-143	—
		02/08/21	7.14	676	15.2	—	5.93	44	—
		05/04/21	7.12	710	17.5	53.9	0.19	-265	—
		08/17/21	6.85	696	17.1	11	0.23	-73	—
		11/10/21	7.07	844	16.0	—	0.43	150	3.5
		02/18/22	7.11	973	14.3	—	0.27	-476	—
		05/03/22	6.96	937	14.5	—	0.90	-123	—
		08/03/22	7.10	775	16.6	—	5.70	-53	—
		11/03/22	6.78	1,076	15.1	—	0.33	245	3.5
		05/12/23	6.94	1,178	17.3	—	0.48	-49	—
	DUP	11/10/23	6.98	1,090	14.7	—	1.29	-79	2.5
		05/31/24	6.62	1,308	17.6	—	0.35	-192	—
		11/07/24	6.82	1,161	12.7	—	0.35	-17.6	3.4
MW-149	Property, NE quadrant	04/10/18	6.57	895	16.1	64.2 ^(b)	0.70	201	1.8
		10/25/18	6.41	814	19.3	—	0.17	-31	—
		12/13/18	6.56	1,354	16.5	—	1.79	132	0.5
		01/30/19	6.67	1,209	17.1	2.9	17.05 ^d	121	0.0
		03/13/19	6.29	1,648	17.2	—	0.12	-178	—
		Decommissioned March 2019							
MW-151	Property, SW quadrant	04/10/18	6.69	809	15.1	23.5 ^(b)	0.60	64	0.8
		10/25/18	6.26	3,599	18.5	—	0.06	-135	—
		12/14/18	6.74	2,314	11.0	—	0.13	-122	—
		01/31/19	6.86	2,151	13.0	—	0.18	21	—
		03/12/19	6.40	1,430	12.3	—	0.23	-278	—
		Decommissioned March 2019							
MW-156	8th Ave N ROW, E side	04/26/18	6.72	996	18.3	—	0.60	116	0.0
		01/24/19	6.70	1,263	16.1	78.1	0.54	131	0.0
		04/24/19	6.73	1,481	16.8	—	0.57	103	0.4
		07/22/19	7.55	1,452	20.6	—	0.13	-63	0.3
		10/17/19	6.62	1,756	17.4	9.5	0.29	-22	1.4
		01/20/20	6.60	1,739	16.7	75.4	1.02	-30	1.5
		04/24/20	6.74	1,350	15.8	50.0	1.00	105	0.0
		07/15/20	6.57	1,390	22.5	39.0	1.89	-73	2.0
		11/11/20	6.58	642	11.4	120	0.93	-17	—
		02/08/21	6.53	830	10.7	76.7	1.03	-391	—
		05/10/21	6.54	895	16.4	282	0.33	-119	—
		08/20/21	6.33	867	17.7	—	0.31	139	—
		11/18/21	6.66	724	12.1	—	0.16	63	1.5
		03/03/22	6.56	886	14.4	51	0.21	-511	—
		05/26/22	6.69	862	13.8	—	0.25	-13	—
		08/04/22	6.72	730	16.6	—	0.57	-40	—
		10/31/22	6.76	697	15.5	—	1.10	14	2.25
		05/12/23	6.77	827	17.1	—	0.63	-14	—
		11/06/23	6.62	652	14.6	—	0.23	20	0.5
		05/21/24	7.06	704	13.7	—	0.39	16	—
		11/05/24	6.57	838	14.6	—	0.10	111.9	2.8

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-189	Valley St ROW, S side	10/14/19	7.40	636	18.1	20.7	0.30	-115	0.1
		01/23/20	7.24	558	13.2	46.6	0.21	-124	0.5
		04/03/20	7.23	430	15.6	39.3	0.22	82	0.5
		08/04/20	7.44	430	18.2	113	0.18	-100	0.5
		11/17/20	7.45	436	14.5	8.3	0.47	-254	—
		02/03/21	7.61	512	11.1	20.5	0.78	-503	—
		05/14/21	7.59	564	15.4	—	0.36	-149	—
		08/11/21	7.52	615	19.6	47	0.15	-216	—
		08/20/21	7.51	590	16.7	51	0.26	-55	—
		11/30/21	7.23	709	14.8	—	0.26	133	0.8
		03/04/22	7.49	769	12.1	66.0	0.26	-578	—
		05/12/22	7.54	605	14.6	—	0.60	-118	—
		08/11/22	7.62	491	18.5	—	1.34	-72	—
		10/31/22	7.29	670	14.7	—	0.34	182	0.0
		05/12/23	7.58	486	14.5	—	0.45	-126	—
		05/23/24	7.98	431	14.1	—	0.42	119	—
		11/05/24	7.41	568.8	15.4	—	0.24	-152.6	0.0
MW-302	Dexter Ave N ROW E side	10/21/19	7.87	653	17.7	112	0.56	-170	0.5
		01/24/20	7.92	1,142	13.6	—	1.18	-130	1.0
		05/07/20	7.90	748	20.3	26.0	0.78	126	0.0
		07/28/20	7.88	763	18.9	22.0	0.34	-77	0.0
		11/17/20	7.83	572	13.9	88.2	0.74	-156	—
		05/17/21	7.86	644	15.1	195	0.48	-164	—
		11/09/21	7.78	623	12.5	—	1.69	139	0
		05/17/22	7.93	640	13.8	—	0.38	-88	—
		11/08/22	6.92	494	13.5	—	0.54	56	0
		10/30/23	7.85	568	15.7	138	4.91	-70	—
		11/13/24	7.85	564	15.1	—	0.46	-181.7	—
MW-306	Roy St ROW, S side	10/15/19	6.64	471	16.9	26.7	0.31	119	2.5
		01/16/20	7.12	810	13.4	—	0.42	4	2.6
		04/28/20	6.67	585	15.9	0.3	0.44	-88	2.0
		07/29/20	7.02	491	17.9	7.82	1.02	-19	2.5
		11/06/20	6.81	513	15.9	9.6	0.40	-126	—
		05/18/21	6.83	516	17.0	231	0.30	125	—
		12/03/21	6.46	492	15.0	—	0.31	-77	3.0
		05/26/22	7.10	473	17.0	—	0.38	-74	—
		11/04/22	7.10	567	15.5	—	0.21	180	1.5
		11/10/23	7.49	374	15.0	—	2.25	-42	—
		11/08/24	7.18	512	16.5	—	0.41	137.6	—
MW-308	Alley E of Seattle Roy Aloha Shops	10/11/19	6.51	1,185	14.9	30.1	0.48	-37	3.5
		01/16/20	6.84	1,512	13.2	2.2	0.05	-100	4.0
		04/08/20	6.77	922	14.3	—	0.35	-86	4.8
		07/06/20	6.76	1,275	18.7	12.07	1.54	-147	5.5
		11/06/20	6.53	1,013	13.3	2.5	0.33	-138	—
		05/04/21	6.70	1,233	15.4	51.1	0.57	126	—
		11/11/21	6.93	1,121	14.6	—	0.39	41	4.3
		05/19/22	7.22	1,126	14.6	—	0.29	19	—
		11/01/22	6.73	1,322	14.6	—	0.21	243	—
		05/12/23	6.64	1,179	18.1	—	1.31	-38	—
		05/21/24	6.90	774	13.9	—	0.91	1	—
		11/11/24	6.76	1,209	15.1	—	0.19	-7.7	4.5
MW-315	Mercer St ROW, N side	10/03/19	7.95	545	14.9	18.2	0.54	105	0.0
		01/16/20	8.18	846	8.8	—	0.62	-152	0.4
		04/28/20	7.86	511	14.4	21.4	0.52	-138	0.8
		07/24/20	8.22	1,195	16.3	47.8	6.45	-24	0.0
		11/02/20	7.91	546	12.7	8.6	0.62	-156	—
		05/17/21	7.75	456	16.5	90.9	0.76	-173	—
		11/05/21	7.63	511	14.1	19.0	0.45	-216	0.8
		05/09/22	7.53	478	16.5	—	0.38	35	—
		11/02/22	7.15	235	13.9	—	1.00	180	0.0
		11/08/23	8.48	149	15.3	—	4.23	-20	—
		11/11/24	7.25	315.4	13.7	—	2.33	-48.5	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-317	9th Ave N ROW, W side	10/09/19	6.07	1,011	16.8	171	0.30	-85	3.0
		01/16/20	6.49	772	14.7	3.3	0.20	-76	1.5
		04/27/20	—	743	15.5	35.0	0.27	201	2.0
		07/30/20	6.76	705	23.9	3.49	0.41	109	5.0
		11/10/20	6.58	625	13.3	0.8	0.48	-127	—
		05/19/21	6.60	821	16.9	2.3	0.05	-147	—
		11/12/21	6.62	680	14.5	—	0.55	56	5.5
		05/27/22	6.71	853	16.0	—	0.24	-123	—
		11/01/22	6.12	614	14.6	—	0.58	48	4.0
		05/16/23	6.67	832	24.0	—	0.12	-77	—
		11/08/23	6.98	871	15.6	—	1.43	-113	—
		05/21/24	6.57	988	14.1	—	0.25	-111	—
		11/06/24	6.67	948	15.6	—	0.26	-135.8	—
MW-325	Mercer St ROW, N side	10/03/19	6.68	578	15.2	23.7	0.37	242	0.0
		01/17/20	6.47	870	12.1	17.3	0.35	-12	0.0
		04/21/20	6.18	614	14.2	8.6	0.45	110	0.0
		07/23/20	6.32	1,091	16.4	82.5	1.05	109	0.0
		11/02/20	6.50	546	14.9	7.4	0.84	68	—
		02/08/21	6.52	491	11.8	38.8	1.29	-432	—
		05/17/21	6.53	530	15.8	21.7	0.3	-79	—
		08/12/21	6.35	598	15.9	8.7	0.15	2	—
		11/04/21	6.39	685	14.2	—	0.14	-103	0
		03/03/22	6.48	547	13.6	14	0.17	-443	—
		05/09/22	6.47	477	14.0	—	1.38	57	—
		08/11/22	6.55	500	15.4	—	1.31	160	—
		11/02/22	7.72	530	13.5	—	0.76	221	0.0
		05/09/23	6.95	449	15.8	—	0.37	46	—
		11/09/23	6.73	475	14.1	—	1.78	-2	—
		05/24/24	6.58	392	14.1	—	0.17	-20	—
		11/11/24	6.55	560.1	14.3	—	0.55	-120.5	—
MW-327	Lake Union Park, S end	10/02/19	6.85	479	14.2	46.0	0.57	16	3.5
		01/17/20	6.81	482	12.3	5.4	0.30	-62	2.0
		04/09/20	6.84	571	13.6	0.0	0.26	56	5.4
		07/07/20	6.34	515	15.9	12.3	—	-113	6.0
		11/09/20	6.77	560	13.5	11.2	0.17	0	—
		05/25/21	6.81	667	14.3	—	0.12	132	—
		11/10/21	6.70	475	11.5	—	0.46	-92	5.5
		05/04/22	6.83	603	13.7	—	1.81	-122	—
		11/02/22	6.89	644	12.0	—	0.12	-30	4.5
		11/09/23	7.50	501	13.3	—	0.16	-3	—
		11/14/24	6.90	680	13.1	—	0.12	-38.1	—
MW-330	Valley St ROW, N side	05/14/20	7.69	429	21.1	14	0.87	-60	0.0
		07/16/20	7.55	428	25.4	14.0	0.65	-5	1.0
		12/01/20	7.62	420	14.6	10.1	0.38	-40	—
		05/25/21	7.50	418	15.2	—	0.46	128	—
		11/11/21	7.31	399	12.7	—	0.71	165	0.5
		05/25/22	7.40	403	16.3	—	0.65	39	—
		10/31/22	7.11	472	14.9	—	0.52	172	0.0
		10/30/23	7.53	415	14.5	4	1.39	-80	—
		11/05/24	7.20	448.3	15.0	—	0.31	-185.2	—
MW-331	Alley E of Seattle Roy Aloha Shops	04/24/20	6.88	1,043	14.5	43	0.75	-450	4.5
		07/06/20	6.73	1,111	18.5	4.65	0.59	-128	7.0
		11/06/20	6.58	922	14.3	5.1	0.38	-99	—
		05/04/21	6.65	1,118	16.2	—	0.25	127	—
		11/11/21	6.64	1,066	13.4	—	0.43	175	6.2
		05/20/22	6.80	926	14.2	—	0.34	-52	—
		11/01/22	6.34	788	14.8	—	0.67	-11	4.5
		05/09/23	6.69	974	17.3	—	0.53	-102	—
		05/21/24	6.75	731	13.5	—	0.24	27	—
		11/11/24	6.81	1,001	15.5	—	0.29	11.1	5.5

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-333	900 Roy St, S end	04/29/20	6.59	1,646	17.8	5.6	1.37	-103	5.0
		07/24/20	6.37	1,569	18.7	23.0	0.30	110	6.5
		11/05/20	6.70	1,491		18.9	0.43	-309	—
		05/18/21	6.44	1,503	14.2	—	0.18	-160	—
		11/05/21	6.58	1,446	15.0	—	0.35	173	1.8
		05/31/22	6.52	1,609	18.0	—	0.44	-127	—
		11/02/22	6.45	1,222	15.3	—	1.07	244	5.0
MW-344	SDOT Mercer Parcels NW quadrant	06/01/21	7.19	567	19.5	94	0.29	-186	1.0
		08/18/21	7.28	547	19.0	—	0.21	149	1.4
		11/18/22	7.24	890	16.0	—	0.32	-9	—
		11/13/23	7.83	906	15.6	—	0.39	0	—
		11/06/24	6.82	943	16.2	—	0.33	1.3	4.0
MW-351		05/09/23	6.97	481	14.4	—	0.11	97	—
		11/09/23	6.87	466	13.6	—	1.59	-75	—
		05/24/24	7.01	415	14.0	—	1.41	-54	—
		11/08/24	6.73	467.3	15.1	—	0.21	-5.6	4.0
Intermediate B Zone									
FMW-141	Alley E of Seattle Roy Aloha Shops	10/30/19	7.33	1,124	14.0	23.0	0.39	100	0.5
		01/14/20	6.83	246	14.4	7.5	5.70	-87	1.5
		04/28/20	7.12	349	15.8	27	0.46	49	1.2
		07/22/20	7.22	1,349	19.9	58.7	1.30	-101	0.5
		11/02/20	7.30	1,112	16.7	99.5	0.85	-63	—
		05/03/21	6.79	83	14.7	21.8	2.74	126	—
		02/23/22	7.10	175	11.5	—	0.65	-328	—
		05/09/22	6.42	130	16.9	—	1.43	-5	—
		11/03/22	7.14	206	13.0	—	0.34	-11	1.0
		05/15/23	7.12	302	24.4	—	0.39	-111	—
		11/07/23	7.13	30	15.8	—	0.41	-102	—
		05/22/24	6.85	1535	16.3	—	2.23	-40	—
		11/12/24	6.88	187.3	15.1	—	1.43	-85.8	—
HMW-9IB	SDOT Mercer Parcels SW quadrant	01/26/21	7.86	655	10.1	11.0	0.83	-544	—
		06/02/21	7.58	653	29.3	19.4	0.63	-132	0.5
		08/18/21	7.59	648	20.3	6.6	0.45	-112	—
		03/31/22	7.78	575	14.2	—	0.69	-282	—
		05/24/22	6.18	2,054	15.5	—	1.16	-55	—
		08/01/22	6.22	1,309	19.0	—	22.8 ^d	-62	—
		11/09/22	6.32	1,199	13.3	—	2.48	-23	>7.5
		02/23/23	6.42	770	10.7	—	0.88	-33.3	—
		05/17/23	6.78	1,157	20.5	—	0.98	-120	—
		02/28/24	7.02	1,076	11.2	—	1.09	-11	—
		05/29/24	6.85	69	14.1	—	0.37	-171	—
		09/04/24	6.93	1,694	16.0	—	0.78	-99.9	—
		11/06/24	6.87	1,742	15.3	—	0.50	-46.2	4.5
MW111	Alley E of Seattle Roy Aloha Shops	12/17/13	7.58	498	—	—	1.19	-99	0.18
		03/23/17	7.62	447	14.0	—	1.19	-147	0.1
		06/14/17	7.29	431	19.7	—	1.15	-33	—
		04/06/18	7.75	605	15.3	—	0.60	83	—
		01/23/19	7.86	528	14.2	—	0.50	-124	—
		04/22/19	7.84	384	13.7	—	0.58	-46	—
		07/15/19	7.78	478	18.3	—	0.35	-138	—
		10/14/19	7.53	509	14.4	1.2	0.57	30	—
		01/16/20	7.56	674	14.0	143	0.10	-138	0.5
		04/23/20	7.73	632	17.0	283	0.37	-122	0.5
		07/06/20	7.52	674	21.9	204	0.56	-6	0.0
		11/02/20	7.57	666	16.3	169	0.59	-47	—
		02/09/21	7.64	611	12.4	220	0.78	-429	—
		05/03/21	7.67	444	16.9	280	0.68	-211	—
		08/04/21	7.49	517	26.3	59	0.42	93	—
		11/03/21	7.64	475	15.7	—	0.30	82	0.5
		02/15/22	7.73	465	11.6	—	0.48	-256	—
		05/18/22	7.48	379	13.8	—	0.25	4	—
		08/09/22	7.78	378	19.5	—	1.53	-139	—
		11/01/22	6.27	367	14.7	—	0.37	41	0.5
		05/15/23	7.59	428	22.8	—	0.24	-65	—
		11/07/23	8.08	115	15.5	—	0.34	-84	—
		05/22/24	7.61	434	16.8	—	1.95	-50	—
		11/08/24	7.64	494.6	12.8	—	0.46	-148.4	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)		
MW112	Dexter Ave N ROW W side	12/26/13	7.79	378	—	—	2.58	223	0.23		
		03/22/17	7.96	419	14.9	—	0.93	132	—		
		06/16/17	7.11	49	22.0	—	5.22	-457	—		
		04/12/18	7.07	41	14.8	—	1.10	35	0.0		
		12/21/18	6.88	108	13.9	—	0.77	68	—		
		04/22/19	7.52	196	17.0	—	0.38	-70	1.0		
		07/16/19	7.65	266	20.2	—	0.20	-143	0.0		
		10/21/19	6.55	152	16.7	—	0.57	-136	0.5		
		01/24/20	6.44	177	11.8	22.6	0.71	-59	2.0		
		05/07/20	7.38	218	18.9	32.0	0.53	-89	1.5		
		07/27/20	7.57	289	24.9	75.0	0.40	-122	1.6		
		11/17/20	7.59	306	14.1	32.9	0.98	-145	0.0		
		02/11/21	7.74	410	9.8	19.8	1.01	-366	—		
		05/14/21	7.79	446	16.4	—	0.44	119	—		
		08/17/21	7.72	437	19.0	—	0.61	137	—		
		11/08/21	7.76	495	16.3	275	0.55	-219	0.6		
		02/24/22	7.94	434	12.2	—	1.11	-293	—		
		05/13/22	7.96	460	18.5	—	0.79	-63	—		
		08/09/22	7.80	359	18.3	—	1.96	-152	—		
		11/08/22	6.34	147	16.6	—	0.18	104	0.5		
		05/10/23	7.52	146	16.0	—	11.19	58	—		
				Destroyed							
		MW112R	Dexter Ave N ROW W side	05/29/24	6.27	84	15.6	—	1.11	-161	—
MW126	Alley E of Seattle Roy Aloha Shops	03/28/17	7.41	397	12.8	2.0	1.37	-112	—		
		06/15/17	7.69	385	15.9	—	0.70	-64	—		
		04/06/18	7.87	353	14.3	—	0.30	99	—		
		01/22/19	7.88	432	10.7	—	1.25	115	—		
		04/29/19	7.34	427	14.7	—	0.42	7	—		
		07/18/19	7.41	357	15.9	—	0.25	14	—		
		10/15/19	6.72	396	15.1	4.7	0.38	-102	0.5		
		01/14/20	7.50	369	12.3	2.0	0.61	-171	0.5		
		04/09/20	6.97	405	12.7	1.2	0.41	31	0.0		
		07/24/20	7.17	414	19.3	1.00	0.24	-17	0.0		
		11/09/20	6.80	323	12.2	1.3	0.34	-72	—		
		02/10/21	7.09	444	12.4	28.5	1.55	-528	—		
		05/04/21	7.26	403	15.6	—	0.23	402	—		
		08/04/21	7.19	403	22.1	3.9	0.20	96	—		
		11/11/21	7.23	377	13.9	—	0.29	165	0.6		
		02/15/22	7.39	399	12.5	—	0.39	-268	—		
		05/20/22	7.36	385	14.0	—	0.52	23	—		
		08/10/22	7.40	306	16.9	—	1.00	33	—		
11/01/22	6.32	316	12.6	—	0.26	-21	0.0				
11/11/24	7.52	418	14.8	—	0.19	-30.1	1.0				
MW130	Property, NW quadrant	03/29/17	7.18	751	9.6	—	2.66	132	1.0		
		06/30/17	7.32	858	29.7	—	0.99	-70	0.0		
		05/21/18	7.69	571	26.3	—	1.07	-72	0.0		
		12/17/18	7.74	1,183	16.5	—	44.85 ^(d)	—	0.0		
		01/31/19	7.40	1,176	21.4	—	59.05 ^(d)	112	0.0		
		Decommissioned March 2019									
MW-132	Property, SE quadrant	09/25/17	8.52 ^(a)	652	27.3	39.7 ^(b)	0.70	-151	—		
		04/26/18	7.70	466	25.9	—	3.50	82	—		
		10/25/18	7.58	568	19.1	—	1.10	17	—		
		12/13/18	7.60	668	14.2	—	0.93	117	—		
		01/31/19	7.66	712	14.9	—	0.74	-40	—		
		03/11/19	7.62	592	17.2	—	0.99	-24	—		
Decommissioned March 2019											
MW-134	Property, NE quadrant	09/22/17	13.08 ^(a)	565	19.0	MAX ^(b)	0.91	-48	—		
		04/16/18	7.10	598	15.7	—	0.10	-145	0.0		
		10/25/18	7.41	748	18.3	—	0.30	157	—		
		12/12/18	7.56	649	17.0	—	0.50	-141	—		
		01/28/19	7.74	747	17.1	—	0.53	-141	—		
		03/12/19	7.06	759	16.8	—	0.38	171	—		
Decommissioned March 2019											

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-135	Property, NE quadrant	09/25/17	9.11 ^(a)	871	25.3	208 ^(b)	1.10	-25	—
		04/25/18	7.38	837	19.5	—	0.80	99	1.5
		10/25/18	7.19	1,034	17.6	—	0.77	-68	—
		12/13/18	7.41	1,341	15.4	—	0.47	124	0.8
		01/31/19	7.34	1,269	21.1	—	0.13	-157	—
		03/13/19	7.13	1,661	15.0	—	0.18	194	—
		Decommissioned March 2019							
MW-136	Property, SW quadrant	09/25/17	10.07 ^(a)	465	24.2	MAX ^(b)	0.60	-61	—
		04/16/18	7.94	447	21.9	—	0.40	-77	0.6
		10/29/18	7.57	521	20.8	—	0.62	11	—
		12/13/18	7.56	539	18.6	—	0.34	-149	—
		02/01/19	7.41	546	18.7	—	1.42	-54	—
		03/12/19	7.36	687	14.2	—	0.50	172	—
		Decommissioned March 2019							
MW-139	Property, SE quadrant	09/25/17	9.65 ^(a)	340	26.4	MAX ^(b)	0.60	-163	—
		04/25/18	7.79	432	20.3	—	0.40	89	0.8
		10/25/18	7.70	445	18.5	—	0.84	-13	—
		12/13/18	7.56	531	12.5	—	0.91	120	—
		01/28/19	7.92	534	13.4	—	1.19	-134	—
		03/11/19	7.11	703	18.4	—	0.70	-56	—
		Decommissioned March 2019							
MW-143	8th Ave N ROW, E side	04/30/18	7.83	905	15.4	—	0.60	97	0.5
		01/29/19	7.64	950	18.1	80.4	0.23	-148	0.8
		04/24/19	7.29	965	14.7	—	0.83	100	0.3
		07/19/19	7.42	835	21.3	—	0.21	-139	1.0
		10/16/19	7.12	891	16.9	—	0.88	-45	0.5
		01/22/20	7.52	1,148	13.5	22.6	0.44	-122	0.5
		04/24/20	7.52	1,020	15.0	1.0	0.62	-134	1.0
		07/29/20	7.59	850	24.9	79.7	1.12	9	0.5
		11/30/20	6.82	1,281	13.2	98.8	0.34	-285	—
		02/08/21	6.72	1,575	12.6	242	0.92	41	—
		05/19/21	6.61	1,763	15.6	101	0.07	-135	—
		08/20/21	6.40	1,871	18.4	—	0.19	156	—
		12/08/21	6.60	1,865	15.0	—	0.00	-125	6.0
		03/08/22	6.52	1,868	14.9	32	0.10	-470	—
		05/26/22	6.68	1,781	18.0	—	0.25	-120	—
		08/12/22	6.74	1,550	18.4	—	0.64	-134	—
		11/01/22	7.13	608	13.9	—	0.21	177	0.0
		05/16/23	8.33	2,194	16.9	—	0.28	-94	—
		11/07/23	7.45	1,125	15.1	—	1.69	-99	2.0
		05/24/24	6.67	1,397	14.5	—	0.18	11	—
		11/06/24	6.90	997	14.2	—	0.41	6.6	2.0
MW-145	8th Ave N ROW, E side	04/27/18	8.01	718	17.0	—	0.30	101	0.0
		01/29/19	7.60	740	17.4	94.9	0.98	-101	0.0
		04/26/19	7.89	722	16.5	—	0.36	-43	0.0
		Destroyed June 2019, Decommissioned December 2019							
MW-145R	8th Ave N ROW, E side	12/16/19	8.25	480	15.1	32.9	0.45	-106	0.0
		01/21/20	7.40	666	9.0	18.2	0.30	-187	0.0
		04/02/20	7.65	529	15.9	19.4	0.32	35	0.5
		08/03/20	7.86	547	19.3	26.1	0.69	104	1.0
		11/23/20	7.63	466	10.8	85.0	1.35	-156	—
		02/05/21	7.67	634	13.6	46.9	0.73	41	—
		05/12/21	7.70	629	18.1	28.0	0.53	-191	—
		08/23/21	7.38	638	16.7	—	0.46	159	—
		11/30/21	7.76	652	13.4	—	2.28	-145	0.5
		03/08/22	7.62	606	13.5	57	0.49	-510	—
MW-145R		05/11/22	7.53	618	14.5	—	0.51	-94	—
		08/10/22	7.75	657	17.6	—	4.90	-40	—
		11/02/22	7.55	632	11.0	—	0.72	-179	0.0
		05/15/23	7.63	646	20.5	—	0.42	11	—
		11/08/23	8.47	520	15.8	—	7.18	-13	—
		05/22/24	7.60	614	15.3	—	2.40	52	—
		11/08/24	7.48	521	14.9	—	0.41	-160.0	0.6

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-147	Roy St ROW, S side	05/01/18	7.85	911	16.8	—	0.40	79	—
		01/22/19	7.60	892	8.6	—	0.79	118	1.0
		04/23/19	7.07	685	17.3	—	0.42	-103	1.5
		07/18/19	6.85	721	17.4	—	0.46	94	2.0
		10/14/19	7.00	671	17.6	90.9	0.38	99	0.5
		01/24/20	7.66	1,031	15.7	307	9.57	-31	0.5
		04/29/20	7.16	805	20.6	73	0.62	-87	2.0
		07/09/20	7.37	833	22.1	188	0.58	-12	1.5
		11/10/20	7.16	790	13.8	41.3	0.52	-144	—
		02/09/21	7.22	719	12.2	266	1.19	46	—
		05/04/21	7.17	727	17.7	265	0.39	-213	—
		08/20/21	6.81	985	19.6	—	0.33	155	—
		11/09/21	7.38	741	15.2	—	0.75	155	1.5
		02/18/22	7.02	1,175	13.5	23	0.57	-124	—
		05/03/22	6.88	1,206	14.7	—	0.92	-129	—
		08/10/22	7.12	1,263	18.0	—	8.40	-66	—
		11/03/22	6.74	1,416	15.0	—	0.33	242	6.5
		05/12/23	7.22	843	15.9	—	0.16	18	—
		06/04/24	7.24	806	16.2	—	0.85	-183	—
		11/07/24	7.22	853	14.4	—	0.93	-35.3	1.1
MW-148	Roy St ROW, S side	05/01/18	8.06	499	13.7	—	0.40	107	0.3
		01/23/19	7.80	706	12.0	—	0.66	116	—
		04/26/19	6.94	717	13.8	—	0.43	82	0.4
		07/22/19	8.43	619	16.6	—	0.24	-143	0.5
		10/16/19	7.35	654	15.1	107	0.17	53	0.5
		01/20/20	7.44	717	13.9	35.9	0.08	-135	0.5
		04/30/20	7.74	623	18.1	207	0.53	-101	0.5
		07/15/20	7.70	593	24.7	618	0.39	-4	0.5
		11/11/20	7.72	461	13.5	360	0.38	-250	—
		08/13/21	7.57	655	19.6	161	0.29	-127	—
		12/07/21	7.64	626	13.1	—	0.99	-144	—
		02/25/22	7.71	682	12.4	—	0.9	-168	—
		05/05/22	2.61	671	12.4	—	2.51	-134	—
		08/10/22	7.76	777	17.8	—	1.25	-36	—
		11/04/22	7.22	538	14.3	—	0.40	187	0.0
		05/09/23	7.90	460	15.3	—	10.79	-110	—
		11/09/23	7.31	462	13.5	—	2.47	-60	—
		05/28/24	6.78	384	13.9	—	0.23	186	—
		11/11/24	7.48	515.8	14.0	—	0.55	-141.7	—
MW-150	Property, NE quadrant	04/10/18	7.11	845	17.5	73.5 ^(b)	0.60	315	0.0
		10/25/18	6.79	1,282	18.6	—	0.05	-114	—
		12/12/18	6.95	1,812	15.0	—	0.39	134	—
		01/29/19	6.88	1,959	15.8	—	0.15	123	—
		03/13/19	6.39	2,489	16.5	—	0.19	-214	—
		Decommissioned March 2019							
MW-152	Property, SW quadrant	04/10/18	7.45	846	15.2	15.8 ^(b)	0.60	372	0.0
		10/26/18	6.83	894	17.0	—	0.62	-85	—
		12/14/18	6.47	1,207	14.5	—	0.75	116	1.0
		01/31/19	7.26	1,632	11.6	—	9.10	125	—
		03/12/19	6.47	1,922	12.9	—	0.29	-186	—
		Decommissioned March 2019							
MW-157	8th Ave N ROW, E side	04/26/18	6.92	867	20.7	—	0.70	97	—
		01/24/19	6.86	885	14.3	—	0.71	-64	3.0
		04/24/19	6.90	1,296	17.9	—	0.31	74	3.0
		07/22/19	7.28	923	19.5	—	0.14	-118	3.0
		10/16/19	7.14	1,378	17.6	10.5	0.21	-99	0.0
		01/20/20	7.03	1,381	16.4	15.3	0.01	132	2.5
		04/24/20	7.06	1,055	15.4	331	0.27	76	1.2
		07/15/20	7.18	1,032	18.4	19.9	0.17	-137	1.5
		11/23/20	5.32	1,541	11.8	high	0.82	-237	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-190	Valley St ROW, S side	10/14/19	7.59	492	16.6	14.4	0.53	-92	0.2
		01/23/20	7.33	473	12.6	12.2	0.51	-158	0.5
		04/02/20	8.11	441	15.6	32.9	0.34	265	0.5
		08/04/20	7.89	412	20.3	18.3	0.62	91	0.5
		11/18/20	7.45	466	13.7	42.7	0.70	-277	—
		02/03/21	7.59	471	10.4	9.0	0.88	-499	—
		05/14/21	7.63	—	16.5	40.7	—	117	—
		08/11/21	7.38	476	22.2	48	0.44	11	—
		11/30/21	7.30	478	12.8	—	0.84	-79	0.0
		03/04/22	7.71	517	10.3	14	0.44	-485	—
		05/10/22	7.27	449	12.7	—	3.14	9	—
		08/11/22	7.74	374	17.0	—	1.38	-49	—
		10/31/22	7.20	565	14.9	—	0.42	177	0.0
		05/12/23	7.73	430	14.3	—	0.50	-135	—
		11/06/23	7.57	508	14.7	—	1.61	-51	0.5
		05/23/24	7.59	426	13.6	—	0.43	123	—
		11/06/24	7.42	548.2	14.4	—	0.42	-141.2	0.5
MW-303	Dexter Ave N ROW E side	10/21/19	7.88	437	16.4	50.0	0.37	-246	0.0
		01/24/20	9.34	889	—	45.9	—	-314	0.0
		05/07/20	7.67	499	16.7	75.2	0.52	-158	0.0
		07/27/20	7.94	441	25.6	70.0	0.63	-88	0.6
		11/17/20	7.94	439	15.8	69.6	4.59	-51	—
		05/18/21	7.68	415	14.2	165	0.63	-149	—
		11/09/21	7.51	455	14.5	—	0.51	-40	0.4
		05/25/22	7.83	432	15.4	—	0.61	-96	—
		11/08/22	7.77	436	13.3	—	0.34	-7	0.0
		11/13/24	7.77	481	15.0	—	0.42	-9.7	—
MW-307	Roy St ROW, S side	10/11/19	8.19	586	16.5	101	0.28	-540	0.0
		01/15/20	8.34	985	10.8	—	0.43	-126	0.0
		04/28/20	7.85	749	15.8	29.0	0.80	-174	0.25
		07/29/20	8.09	627	21.6	64.1	1.04	-27	0.5
		11/06/20	8.00	642	14.9	31.9	0.55	-204	—
		05/18/21	8.01	672	17.0	360	0.48	127	—
		12/03/21	7.78	409	13.7	—	0.92	-164	0.0
		05/26/22	8.11	634	18.6	—	0.48	-190	—
		11/04/22	6.79	708	15.6	—	0.22	257	0.0
		11/10/23	8.07	458	15.3	—	1.12	-27	—
		11/08/24	8.03	618	16.8	—	0.46	128.4	1.1
MW-309	Alley E of Seattle Roy Aloha Shops	10/14/19	7.67	626	14.6	7.2	0.64	68	0.5
		01/16/20	7.08	656	12.7	1.2	0.30	-127	0.0
		04/08/20	7.05	580	12.8	—	0.44	-128	0.0
		07/06/20	7.40	688	18.5	8.36	0.13	-165	0.5
		11/06/20	7.36	523	13.8	1.2	0.43	-157	—
		05/04/21	7.42	655	16.0	57.8	0.15	126	—
		11/11/21	7.39	597	15.0	—	0.42	50	0.5
		05/19/22	7.41	647	14.7	—	0.33	-46	—
		11/01/22	6.87	771	14.0	—	0.32	254	0.0
		05/12/23	6.69	576	19.9	—	0.74	-52	—
		05/21/24	6.78	614	13.8	—	0.23	29	—
		11/11/24	7.50	692	14.4	—	0.12	-31.8	1.0
MW-311	Alley E of Seattle Roy Aloha Shops	10/10/19	7.31	1,044	15.0	17.8	0.46	-39	0.0
		01/14/20	7.56	1,098	6.2	3.3	0.22	-140	—
		04/23/20	7.50	846	13.2	26.3	0.68	-96	0.5
		07/16/20	7.39	852	21.2	7.85	0.46	-125	1.0
		11/04/20	7.07	798	16.3	74.7	0.65	-146	—
		05/03/21	7.35	830	16.2	6.0	0.24	129	—
		11/04/21	7.47	784	15.5	—	0.36	176	0.8
		05/09/22	7.40	813	18.1	—	0.20	-31	—
		11/01/22	6.35	664	14.9	—	0.67	19	2
		05/15/23	7.46	818	22.9	—	0.47	-46	—
		11/07/23	7.56	800	14.9	—	1.16	107	—
		05/21/24	7.28	652	13.9	—	0.96	51	—
		11/12/24	7.39	883	14.9	—	0.32	-131.4	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-314	Alley E of Seattle Roy Aloha Shops	10/10/19	7.22	860	14.9	50.3	0.35	138	3.5
		01/15/20	7.18	1,428	13.7	—	0.31	31	0.9
		04/22/20	7.04	1,058	13.5	151	0.46	-96	1.5
		07/16/20	6.85	1,146	17.4	556	0.25	11	2.5
		11/04/20	6.62	1,076	17.1	467	0.35	-91	—
		05/03/21	7.08	957	16.0	163	0.23	-223	—
		12/03/21	7.08	902	14.3	—	0.96	-113	1.2
		05/18/22	7.19	902	14.6	—	0.25	-47	—
		11/01/22	7.10	946	14.8	—	0.37	188	0.0
		05/15/23	7.17	766	16.6	—	1.99	-114	—
		11/07/23	7.57	100	15.3	—	4.99	-55	1
		05/22/24	7.21	451	15.8	—	3.09	51	—
		11/12/24	7.17	469.4	14.9	—	3.28	-45.7	0.0
MW-316	Mercer St ROW, N side	10/03/19	7.77	662	15.0	88.0	0.45	203	1.0
		01/16/20	8.08	1,076	11.7	—	0.43	-89	0.4
		04/21/20	7.34	710	14.8	83.6	0.39	109	0.25
		07/24/20	7.65	713	16.8	54.2	0.46	191	0.5
		11/02/20	7.89	706	14.7	9.9	0.84	-154	—
		05/17/21	7.79	698	18.6	193	0.51	-191	—
		11/05/21	7.61	722	12.3	91	0.88	-222	0.4
		05/09/22	7.71	691	16.2	—	0.38	-48	—
		11/02/22	7.32	137	13.9	—	0.86	196	0.0
		11/08/23	8.97	274	14.7	—	9.89	-27	—
		11/11/24	7.43	388.8	13.9	—	1.37	-75.0	—
MW-318	9th Ave N ROW, W side	10/08/19	7.09	846	15.3	—	0.48	-84	4.0
		01/16/20	6.55	979	14.5	1.3	0.50	-60	2.0
		04/27/20	7.62	1,276	16.8	35.0	0.25	38	3.6
		07/30/20	6.70	1,156	18.9	16.0	1.17	-68	7.0
		11/12/20	6.56	1,204	15.7	64.3	4.62	-122	—
		05/19/21	6.61	1,183	16.7	26.1	0.20	-126	—
		11/12/21	6.64	1,095	16.0	—	0.30	57	4.8
		05/27/22	6.71	941	15.6	—	0.31	-99	—
		11/01/22	6.76	1,067	14.3	—	0.21	245	0.0
		05/16/23	6.79	1,200	19.9	—	0.08	-71	—
		11/08/23	6.96	1,172	15.2	—	1.39	-88	—
		05/22/24	6.63	1,206	16.2	—	0.13	-148	—
		11/06/24	6.66	1,181	15.9	—	0.39	-124.8	—
MW-322	9th Ave N ROW, W side	10/07/19	6.68	1,400	16.9	28.7	0.45	-66	0.0
		01/21/20	6.69	1,353	14.3	5.5	0.40	-49	1.5
		04/29/20	—	1,190	16.3	4.0	0.90	198	5.6
		07/07/20	6.74	895	16.0	12.2	0.15	-113	5.8
		11/24/20	6.67	924	15.4	16.7	0.48	-131	—
		05/19/21	6.61	1,121	16.7	9.0	0.22	-116	—
		11/09/21	6.90	1,370	12.9	—	0.00	-111	4.0
		06/08/22	6.60	1,338	17.1	—	0.43	-94	—
		11/03/22	6.78	372	14.0	—	0.20	212	4.5
		05/17/23	6.60	1,292	20.5	—	0.31	-79	—
		11/08/23	6.72	1,339	16.7	—	1.27	-79	2.5
		05/22/24	6.60	799	16.6	—	0.28	-29	—
		11/06/24	6.59	1,327	16.5	—	0.26	-114.2	3.5
MW-334	900 Roy St, S end	04/24/20	7.06	1,443	16.4	134	0.50	-96	6.0
		07/07/20	6.63	1,998	17.9	38.0	0.37	-6	5.0
		11/05/20	7.10	2,108	15.8	53.4	0.52	-271	—
		05/13/21	6.85	2,019	21.5	6.1	0.18	-150	—
		11/05/21	7.09	1,909	15.1	—	0.26	175	5.3
		05/31/22	6.92	1,983	18.2	—	0.27	-113	—
		11/03/22	6.11	1,609	15.8	—	1.40	36	2.0
		11/09/23	7.41	1,618	15.8	—	2.48	13	—
		11/07/24	6.87	2,000	16.1	—	0.31	-108.3	—
MW-335	Mercer St ROW, N side	05/01/20	6.50	688	17.8	40	0.16	64	0.8
		07/08/20	6.66	526	21.1	1.0	0.29	-3	0.0
		11/02/20	6.58	788	17.5	1.3	0.39	17	—
		02/10/21	6.55	1,140	15.0	7.0	1.17	52	—
		05/26/21	6.51	1,185	16.5	—	0.34	-113	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-335 (continued)		08/11/21	6.53	1,259	27.3	—	0.35	128	—
		11/17/21	6.58	1,165	14.9	—	0.00	65	0.3
		03/02/22	6.54	1,015	15.1	—	0.67	19	—
		05/31/22	6.56	798	18.5	—	0.30	28	—
		08/10/22	6.78	660	19.4	—	0.63	60	—
		11/03/22	6.16	626	16.6	—	0.45	16	0.0
		05/19/23	6.72	632	17.0	—	0.62	-1	—
		11/09/23	6.74	665	16.2	—	1.34	-7	0.5
		05/24/24	6.64	535	15.7	—	0.16	-27	—
		11/14/24	6.59	875	16.8	—	0.32	-145.1	0.5
MW-338	Lake Union Park, N end	05/07/20	6.42	1,320	19.6	14.8	0.42	-103	3.0
		07/23/20	6.55	896	16.3	12.0	2.73	-91	9.0
		11/10/20	6.32	856	10.7	1.0	0.26	-123	—
		05/04/21	6.40	1,155	16.1	—	1.01	120	—
		11/17/21	6.42	997	12.6	—	0.00	61	5.0
		05/04/22	6.59	1,046	13.5	—	7.22	-112	—
		11/02/22	6.50	806	11.3	—	0.80	91	3.25
		11/08/23	7.49	749	13.3	—	0.29	-4	—
		11/14/24	6.85	945	12.1	—	0.15	-10.1	—
MW-340	Lake Union Park, S end	05/12/20	6.71	1,044	16.8	6	2.73	-181	6.0
		07/17/20	6.54	968	14.8	310	1.97	-86	7.0
		11/09/20	6.46	699	12.8	3.3	0.17	-146	0.0
		05/13/21	6.42	829	14.9	—	0.14	130	0.0
		05/04/22	6.71	846	14.1	—	1.75	-91	—
		11/02/22	6.70	886	12.3	—	4.15	-17	5.5
		11/09/23	7.44	709	13.4	—	0.22	-2	—
		11/14/24	6.66	943	13.1	—	0.13	5.1	—
MW-345	SDOT Mercer Parcels NW Quadrant	06/01/21	7.93	675	22.8	82	0.51	-291	0.0
		08/18/21	8.16	650	19.8	36	0.35	138	0.0
		11/18/22	8.05	699	15.7	—	0.60	-12	—
		11/13/23	8.35	649	15.1	—	0.80	2	—
		11/21/24	7.83	853	13.8	—	1.72	99.6	—
MW-346	SDOT Mercer Parcels NW Quadrant	06/02/21	7.93	695	17.0	189	0.54	-396	0.6
		08/18/21	8.07	632	22.8	106	0.15	146	0.0
		03/31/22	8.04	614	14.3	—	0.38	-249	—
		05/24/22	7.93	603	16.0	—	0.55	-94	—
		08/02/22	7.99	538	18.4	—	1.23	-32	—
		11/10/22	8.00	595	13.4	—	2.50	-15	0.25
		02/23/23	8.18	579	9.8	—	0.80	-50.3	—
		05/16/23	8	462.0	19.9	—	1.32	-85.4	—
		11/08/23	9.05	282	14.2	—	9.00	14	—
		02/27/24	8.08	543	8.9	—	0.82	-187	—
	DUP	05/28/24	7.50	138	14.2	—	7.66	-15	—
		09/05/24	7.95	587	23.0	—	0.78	-157	—
		11/05/24	8.03	622	31.5	—	1.32	-66.5	0.5
MW-347	SDOT Mercer Parcels NW Quadrant	06/01/21	8.42	736	21.7	84	0.39	-14	0.0
		08/19/21	8.79	829	17.0	32	0.24	140	0.0
		03/31/22	8.46	606	11.7	—	0.39	-381	—
		05/26/22	7.10	591	15.2	—	3.39	-279	—
		08/02/22	7.49	569	17.9	—	0.78	-91	—
		11/10/22	7.66	555	12.5	—	1.60	-22	0.5
		02/23/23	7.98	532	5.0	—	2.29	-65.1	—
		05/17/23	7.62	390	18.3	—	1.22	-124	—
		02/27/24	6.52	92.60	8.5	—	0.83	-30.3	—
		05/29/24	5.94	156.00	15.4	—	1.64	-48.1	—
		09/04/24	7.66	518.10	22.7	—	0.72	-184.2	—
		11/06/24	7.68	549	14.7	—	0.33	87.8	0.0
MW-348	SDOT Mercer Parcels SW Quadrant	06/01/21	7.70	692	21.1	100	0.58	29	0.0
		08/19/21	7.89	625	17.9	23	0.30	147	0.0
		03/31/22	8.08	605	11.5	—	0.54	-401	—
		05/26/22	8.19	628	14.9	—	0.52	18	—
		08/01/22	8.07	642	23.7	—	0.42	-60	—
		11/10/22	6.78	4,271	11.8	—	1.85	-12	—
		03/13/23	8.20	641	9.8	—	0.99	65	—
		05/17/23	8.16	573	19.1	—	0.58	-231	—
		11/15/23	8.05	428	13.5	—	3.63	-190.1	0.1
		02/27/24	8.30	290.4	8.3	—	0.95	-46.9	—
		05/28/24	7.37	453.3	14.4	—	1.69	-213.3	—
		09/05/24	7.75	777.2	18.1	—	0.26	-281.4	—
		11/05/24	7.45	590	14.7	—	0.55	-132.6	0.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-349	SDOT Mercer Parcels SW Quadrant	06/01/21	7.53	595	19.1	37	0.28	16	0.0
		08/19/21	8.01	618	18.0	11	0.42	62	0.0
		03/30/22	7.88	642	13.6	—	0.62	-269	—
		05/26/22	6.29	1,854	15.7	—	0.39	-89	—
		08/01/22	6.49	1,178	21.7	—	9.20	-107	—
		11/08/22	6.91	1,128	11.9	—	2.77	-32	5.25
		02/23/23	7.10	1,158	11.4	—	0.59	-37.5	—
		05/16/23	7.03	963	17.1	—	1.21	-121	—
		11/13/23	7.77	700	14.2	—	0.36	1	1.5
		02/27/24	7.35	888	9.2	—	0.57	-181	—
		05/28/24	6.61	157	14.6	—	0.79	-111	—
		09/04/24	7.39	831	17.3	—	0.73	-136	—
		11/06/24	7.45	903	15.1	—	7.10	2.3	—
MW-350	SDOT Mercer Parcels NW Quadrant	06/01/21	7.91	652	23.2	161	0.28	-493	0.0
		08/18/21	7.93	572	21.7	67	0.28	-100	0.0
		11/11/22	7.83	542	13.4	—	0.75	-10	0.5
		02/24/23	7.86	564	11.7	—	0.91	-30.8	—
		05/17/23	7.87	460	26.4	—	1.70	-92	—
		11/13/23	8.51	490	14.3	—	0.99	-2	2.5
		02/28/24	7.76	676	12.6	—	0.55	-182	—
		05/29/24	7.67	99	15.4	—	5.22	-9	—
		09/05/24	7.79	727	18.0	—	0.84	-133.3	—
		11/07/24	7.67	757	15.3	—	2.00	133.3	0.5
W-MW-01	8th Ave N ROW, W side	03/30/17	7.63	536	16.7	—	0.62	111	0.3
		06/19/17	7.11	564	22.7	—	1.31	-23	—
		04/13/18	7.91	539	14.5	—	0.40	67	0.8
		10/29/18	7.50	565	16.6	—	0.67	-91	—
		12/13/18	7.36	583	17.9	—	0.34	-123	—
		01/25/19	7.46	703	12.4	MAX ^(b)	0.51	127	1.5
		03/11/19	7.36	737	15.4	—	0.36	198	—
		04/25/19	7.64	758	16.7	—	0.61	32	0.6
		07/23/19	7.75	642	19.3	—	0.17	-153	0.0
		10/15/19	7.61	900	18.8	30.6	0.21	-142	0.0
		01/27/20	7.18	834	14.6	36.8	0.28	-113	0.5
		04/03/20	7.55	648	13.2	5.9	0.36	-120	0.5
		07/31/20	7.53	658	18.5	4.50	1.11	-87	—
		11/24/20	7.72	754	12.6	39.7	0.17	-67	—
		02/03/21	7.39	984	12.5	4.0	0.12	33	—
		05/17/21	6.71	2,105	15.1	—	0.63	126	—
		08/23/21	8.16	1,738	16.8	10	0.00	13	—
		11/29/21	6.64	1,555	16.9	—	0.16	-99	4.2
		03/08/22	6.83	1,293	13.3	167	0.27	-539	—
		05/11/22	6.79	1,383	17.4	—	0.33	-87	—
		08/12/22	6.95	910	18.1	—	0.94	-130	—
		10/31/22	6.76	2,082	14.8	—	5.14	-31	4.75
		02/24/23	6.74	945	9.0	—	0.63	-67.6	—
		05/16/23	9.05	1,336	15.7	—	0.94	67	—
		02/26/24	6.84	2,261	11.8	—	0.44	-149	—
		05/22/24	6.98	1,249	14.4	—	0.41	64	—
		09/05/24	7.09	1,819	21.3	—	0.39	-67.3	—
		11/08/24	6.90	1,553	16.9	—	0.18	-115.4	5.2
W-MW-02	8th Ave N ROW, W side	12/16/13	7.05	999	—	—	0.30	-84	0.87
		03/27/17	6.53	1,239	17.8	—	0.41	135	1.8
		06/19/17	6.02	1,326	20.0	—	1.45 ^d	-11	1.5
		06/12/18	6.80	1,594	16.1	—	0.75	23	3.4
		10/26/18	6.32	1,763	19.2	—	0.41	-63	—
		12/12/18	6.51	2,025	15.7	—	0.44	125	—
		01/25/19	6.49	1,687	16.9	25.2	0.53	-52	2.0
		03/11/19	6.50	1,832	14.8	—	0.95	-9	—
		04/23/19	6.68	1,688	13.7	—	0.72	52	0.5
		07/23/19	6.61	1,740	22.3	—	0.36	-90	3.0
		10/18/19	6.65	2,030	19.1	32.7	0.24	-2	3.4
		01/28/20	7.26	2,603	16.3	—	—	-96	6.0
		04/01/20	6.66	2,140	15.7	101	0.40	652	2.5
		07/31/20	6.52	1,858	20.9	70.0	1.02	-32	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
Deep Zone									
FMW-129	SDOT Mercer Parcels NE quadrant	04/10/17	8.88	891	12.4	—	0.82	-116	0.0
		06/23/17	6.82	703	20.2	—	0.60	-31	1.0
		05/01/19	6.83	666	15.9	—	0.44	7	—
		07/16/19	6.63	669	14.6	—	0.47	97	—
		10/21/19	7.02	548	14.4	84.7	0.15	198	0.5
		01/14/20	6.44	584	12.3	52.8	0.30	70	0.0
		05/06/20	6.66	942	14.3	>1000	0.38	3	0.5
		07/10/20	6.88	826	17.7	MAX	0.24	-1	1.0
		11/10/20	6.98	834	13.7	834	0.29	-107	—
		02/10/21	7.31	97 ^(c)	13.0	18.3	1.87	152	—
		05/26/21	6.71	794	17.0	—	0.31	-137	—
		08/19/21	6.58	803	17.5	97	0.19	-37	—
		03/03/22	6.69	788	13.6	94	0.2	-437	—
		05/05/22	6.74	954	11.7	—	0.73	40	—
		08/12/22	7.46	94	16.0	—	5.62	167	—
		11/11/22	7.66	121	13.5	—	3.49	-3	0.0
		05/18/23	7.45	102	14.7	—	2.18	52	—
		05/23/24	6.88	133	14.4	—	1.20	72	—
		11/12/24	7.02	135	14.5	—	0.50	121.8	—
FMW-131	Block 37, SE quadrant	03/24/17	6.73	342	13.3	2.9	0.84	-42	0.5
		06/23/17	6.71	552	15.4	—	0.78	25	0.3
		04/22/19	6.44	224	12.6	—	0.41	-22	—
		07/01/19	—	—	—	—	—	—	—
		10/21/19	7.19	267	14.3	—	0.30	-27	0.5
		01/22/20	6.38	273	12.3	5.0	1.83	82	0.5
		04/29/20	6.41	797	16.2	95.0	0.40	-1	2.5
		07/30/20	6.86	277	15.3	2.20	0.46	42	0.0
		11/19/20	6.74	220	12.6	21.3	0.96	-298	0.0
		02/12/21	6.68	378	12.1	104	0.26	-39	—
		05/13/21	6.43	396	15.1	—	0.2	130	—
		08/19/21	6.57	384	15.0	3.1	0.19	-6	—
		02/25/22	6.32	1,004	8.9	—	0.95	-85	—
		06/09/22	6.61	431	13.8	—	0.44	35	—
		08/05/22	6.70	484	19.9	—	0.88	-28	—
		11/01/22	6.70	389	14.7	—	0.40	-13	1.25
		05/09/23	6.56	466	14.4	—	0.59	-94	—
		05/23/24	6.56	310	13.9	—	0.50	29	—
		11/14/24	6.28	561.9	15.2	—	0.33	-110.2	—
FMW-137	Alley E of Block 38 West	11/06/19	6.99	704	14.0	—	0.40	267	0.0
		01/22/20	6.62	1,001	12.0	12.4	0.48	144	0.0
		05/06/20	6.36	1,552	14.3	296	0.47	-93	2.5
		07/31/20	6.61	1,422	16.4	122	4.84	-70	2.8
		11/24/20	6.08	1,462	13.8	55.9	1.97	-44	—
		02/12/21	6.85	266	12.5	94.0	0.27	-295	—
		06/02/21	6.76	402	15.1	—	0.26	-74	—
		08/12/21	6.47	666	18.8	3.7	0.26	-1	—
		03/04/22	6.67	754	12.5	6	0.33	-567	—
		06/05/22	6.77	671	14.8	—	0.73	16	—
		08/05/22	6.78	612	16.8	—	0.67	-7	—
		11/01/22	6.73	676	14.6	—	0.57	-21	1.25
		05/19/23	6.63	641	14.1	—	0.98	-25	—
		05/24/24	6.83	195	14.1	—	1.57	49	—
		11/15/24	6.63	1,003	12.6	—	0.47	-178.0	—
FMW-140	900 Roy St, S end	10/31/19	6.34	699	15.5	83.0	0.38	-37	0.5
		01/22/20	6.77	1,666	12.4	1.6	0.32	-67	3.5
		04/28/20	6.58	1,183	15.7	115	0.51	92	4.2
		07/07/20	6.70	1,164	19.5	149	0.31	-3	6.0
		11/13/20	6.51	1,057	15.8	91.4	0.34	-179	—
		05/18/21	6.77	794	18.2	—	0.21	-174	—
		03/02/22	6.73	988	15.1	9	0.25	-389	—
		05/31/22	6.65	938	17.3	—	0.49	-96	—
		11/02/22	6.91	379	15.1	—	0.18	-43	—
		05/15/23	6.62	1,263	22.0	—	0.37	-115	—
		05/24/24	7.08	299	15.0	—	0.13	-188	—
FMW-3D	erry Ave N ROW, E side	03/24/17	6.85	302	13.7	16.9	1.06	-75	—
		06/23/17	6.81	356	19.9	—	0.48	-17	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
GEI-2	Block 37, NW quadrant	03/24/17	6.43	890	12.6	0.5	0.84	-78	0.3
		06/23/17	6.68	804	16.0	—	0.45	-80	1.0
		04/22/19	6.61	933	13.0	—	0.37	-45	—
		07/16/19	6.71	708	16.9	—	0.26	-85	1.5
		10/21/19	6.92	1,297	14.8	—	0.30	-71	2.2
		01/22/20	6.70	2,304	11.8	3.9	0.24	5	2.6
		04/29/20	6.55	1,307	14.6	180	0.40	-102	2.0
		07/30/20	6.79	898	15.9	149	0.28	-80	5.4
		11/19/20	6.64	977	13.8	2.4	0.33	-397	—
		02/12/21	6.76	1,011	10.8	—	0.68	-35	—
		05/13/21	6.55	981	14.9	—	0.29	133	—
		08/19/21	6.57	886	16.1	1.7	0.20	-61	—
		02/25/22	6.68	837	10.7	—	0.85	-85	—
		06/09/22	6.74	925	14.1	—	0.48	-58	—
		08/05/22	6.83	967	22.9	—	0.54	-95	—
		11/01/22	6.79	926	15.4	—	3.57	-22	7.0
		05/09/23	6.92	101	14.9	—	1.96	-102	—
		05/23/24	6.87	87	14.5	—	5.53	-4	—
		11/14/24	6.37	113.2	14.8	—	0.26	-88.6	—
MW102	Valley St ROW, S side	03/29/17	7.87	417	11.6	—	1.55	148	—
		06/15/17	7.89	292	16.8	—	0.69	-88	—
		04/25/18	7.89	297	19.5	—	0.40	66	1.0
		01/24/19	8.01	314	11.5	—	0.63	-124	0.0
		05/01/19	8.32	303	16.9	—	0.64	97	0.5
		07/18/19	7.40	320	20.5	—	0.12	-73	0.8
		11/14/19	7.76	295	16.9	153	2.41	202	0.0
		01/23/20	7.36	422	14.4	40	0.38	-127	0.5
		04/02/20	6.85	313	15.9	63	0.49	108	0.0
		08/04/20	7.74	311	18.2	41.9	0.42	-28	0.0
		11/18/20	7.61	302	14.7	83.6	0.65	-333	—
		02/03/21	7.76	308	12.6	95.2	1.00	-502	—
		05/14/21	7.72	318	15.3	79.6	0.67	-174	—
		08/11/21	7.76	335	18.3	55	0.49	-230	—
		11/30/21	7.46	307	13.8	—	0.80	-97	0.5
		03/07/22	7.77	306	13.4	51	0.36	-542	—
		05/10/22	7.52	314	14.1	—	0.00	-18	—
		08/12/22	7.83	280	18.0	—	0.65	-37	—
		10/31/22	7.21	371	14.6	—	0.53	180	0.0
		05/12/23	7.82	270	15.4	—	0.69	-147	—
		11/06/23	7.62	331	15.1	—	1.76	-12	—
		05/28/24	7.69	578	14.9	—	1.36	175	—
		11/06/24	7.47	354.8	15.1	—	0.31	-141.7	—
MW103	Alley E of Seattle Roy Aloha Shops	12/18/13	10.45	735	—	—	0.26	267	1.39
		03/23/17	7.49	799	13.4	—	0.91	155	0.3
		06/12/17	7.35	648	17.0	—	0.31	-88	1.8
		04/06/18	7.52	521	15.1	—	0.60	91	—
		01/23/19	9.60	359	13.8	—	0.55	126	—
		04/22/19	7.21	693	13.4	—	0.60	6	—
		07/15/19	7.14	728	17.9	—	0.54	31	—
		10/14/19	7.20	655	15.9	5.9	0.05	-57	0.5
		01/16/20	7.30	859	14.3	77.7	0.10	-120	1.0
		04/23/20	7.59	514	15.6	241	0.31	-119	1.0
		07/06/20	7.23	438	18.0	364	0.52	46	0.5
		11/02/20	7.59	425	17.4	375	0.35	-58	—
		02/10/21	7.49	433	12.5	—	0.95	-336	—
		05/03/21	7.37	561	15.6	27.7	0.34	-214	—
		08/12/21	7.03	642	22.9	—	0.43	137	—
		11/08/21	7.29	621	15.2	—	0.45	124	1.0
		02/15/22	7.41	690	14.9	—	0.14	105	—
		05/09/22	7.38	698	16.4	—	0.06	-119	—
		08/09/22	7.45	712	20.1	—	3.80	-60	—
		11/01/22	6.24	387	14.7	—	0.72	43	0.0
		05/09/23	7.34	638	18.7	—	5.80	-132	—
		11/07/23	7.72	725	15.3	—	1.44	-121	—
		05/21/24	7.15	628	15.2	—	0.16	-62	—
		11/07/24	7.18	840	15.9	—	0.32	-202.3	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW104	8th Ave N ROW, W side	12/17/13	8.49	591	—	—	0.48	245	5.03
		03/30/17	6.28	667	8.7	—	1.84	131	—
		06/30/17	7.70	383	25.5	—	0.23	-131	0.0
		04/09/18	8.47	425	20.9	—	0.20	33	0.3
		10/25/18	11.48	750	19.2	—	0.63	131	—
		12/13/18	9.33	334	19.6	—	0.20	-259	—
		02/01/19	9.65	153	20.2	MAX ^(b)	0.11	-205	0.0
		03/13/19	9.03	407	18.6	—	0.24	122	—
		04/23/19	9.10	376	18.6	—	0.21	-100	0.0
		07/22/19	9.94	373	20.8	—	0.24	138	0.0
		10/18/19	8.73	542	18.6	35.5	0.21	-133	0.0
		01/29/20	9.30	541	18.0	29.3	—	-217	0.0
		04/01/20	8.00	409	18.9	67.9	0.19	33	0.5
		07/31/20	7.64	367	20.3	32.0	0.40	7	—
		11/17/20	7.49	378	18.0	89.5	0.35	-215	—
		02/10/21	7.58	371	15.9	136	0.55	40	—
		08/23/21	7.59	363	18.3	90	0.36	-93	—
		11/29/21	7.74	376	16.6	—	1.76	154	0.5
		02/23/22	7.75	370	16.4	75	0.27	-294	—
		05/12/22	7.68	358	17.2	—	0.89	-125	—
		08/23/22	7.76	365	18.2	—	0.55	-75	—
		11/02/22	7.48	389	17.1	—	0.73	-195	0.4
		05/15/23	9.13	422	20.6	—	0.10	-10	—
		05/22/24	8.07	344	14.2	—	0.38	-227	—
		11/08/24	10.44	379.5	16.1	—	0.74	-244.2	—
MW105	Roy St ROW, S side	12/29/13	7.49	1,165	—	—	1.26	216	2.01
		04/21/17	7.47	785	17.1	105	2.34	-37	—
		06/12/17	7.37	734	17.1	—	0.70	-64	—
		04/11/18	9.48 ^(a)	469	14.4	—	1.40	42	0.8
		01/23/19	7.66	570	13.4	—	0.67	107	—
		04/23/19	7.82	580	15.3	—	0.39	-58	0.5
		07/17/19	7.53	625	17.1	—	0.32	127	—
		10/22/19	7.29	722	15.2	49	0.60	-147	1.5
		01/20/20	7.42	1,148	14.0	65	0.74	-132	1.2
		05/12/20	7.51	629	17.0	16	0.65	-77	0.5
		07/27/20	7.48	606	21.4	173	0.79	-92	1.0
		11/17/20	7.47	560	12.7	37.4	1.26	-51	—
		02/11/21	7.41	530	9.5	91.4	1.05	-391	—
		06/07/21	7.36	532	21.2	142	0.58	96	—
		08/17/21	7.17	541	17.5	68	0.39	-77	—
		11/08/21	7.37	597	14.9	123	0.60	-12	1
		02/24/22	7.46	540	12.8	—	1.1	-108	—
		05/17/22	7.52	584	18.6	—	0.61	-94	—
		08/09/22	8.09	471	16.5	—	2.02	-209	—
		11/09/22	7.24	439	12.2	—	1.34	70	0.0
		05/09/23	7.54	545	15.2	—	0.19	100	—
		10/30/23	7.40	533	16.1	2	1.85	-69	0.5
		05/22/24	6.97	188	15.2	—	0.19	-153	—
		11/13/24	7.49	602	15.2	—	0.49	-31.5	—
MW106	SDOT Mercer Parcels NW quadrant	04/14/17	9.47	726	15.1	457	2.00	2	0.0
		06/30/17	7.69	566	19.7	—	0.40	-128	0.0
		05/04/18	7.91	482	16.0	—	0.50	100	0.0
		04/26/19	7.79	507	15.6	—	0.53	-20	0.0
		07/19/19	7.51	615	17.6	—	0.50	51	0.0
		10/18/19	7.86	534	16.0	216	0.42	49	0.5
		01/14/20	7.85	961	11.4	—	0.60	13	0.0
		05/06/20	7.73	588	16.5	117	0.53	-99	0.0
		07/10/20	7.76	580	18.2	545	0.61	-14	0.5
		11/10/20	7.60	513	15.8	98.5	0.37	-167	—
		02/12/21	7.65	425	12.9	48.2	0.55	-24	—
		05/13/21	9.04 ^(a)	70	18.2	226	3.33	-117	—
		08/19/21	7.79	286	23.1	140	0.61	150	—
		02/18/22	8.04	314	13.2	—	0.54	-444	—
		05/06/22	7.15	458	15.2	—	0.37	31	—
		08/02/22	7.86	340	24.3	—	0.70	-85	—
		11/18/22	7.77	428	15.0	—	1.89	-1	—
		05/18/23	9.20	74	15.4	—	2.41	29	—
		05/29/24	8.70	106	15.0	—	0.66	-37	—
		11/06/24	8.28	167.7	14.7	—	1.04	134.8	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW113	9th Ave N ROW, W side	12/19/13	10.0	267	—	—	0.26	264	0.03
		03/22/17	6.54	1,426	15.2	2.1	1.10	-79	4.0
		06/16/17	6.52	1,145	12.9	—	0.57	-6	1.5
		04/11/18	9.44 ^(a)	946	15.0	—	0.60	63	—
		02/07/19	6.64	1,219	9.9	2.4	0.80	76	2.5
		07/17/19	6.72	667	17.4	—	1.69	241	0.3
		10/22/19	6.33	681	16.6	11.8	0.19	151	3.6
		01/14/20	6.61	1,197	13.5	—	0.50	-293	—
		02/18/20 ^c	6.63	1,261	15.1	—	0.71	-32	—
		03/24/20 ^c	6.48	994	14.5	—	0.31	-16	—
		04/27/20	6.56	1,031	16.2	1.4	0.36	-26	4.5
		05/19/20 ^c	6.50	923	16.7	—	0.57	-52	—
		07/28/20	6.54	973	16.5	—	0.28	-86	—
		11/24/20	6.56	729	15.2	34.4	0.41	-67	—
		02/10/21	7.03	96 ^(c)	13.6	14.9	5.04	215	—
		05/25/21	6.50	870	16.8	—	0.21	-141	—
		08/11/21	6.46	1,056	21.9	—	0.44	126	—
		11/18/21	6.50	960	15.2	—	0.00	67	4.5
		02/15/22	6.72	1,161	14.5	—	0.19	100	—
		06/08/22	6.57	1,206	17.6	—	0.48	-41	—
		08/10/22	6.76	980	18.4	—	0.77	-84	—
		11/03/22	6.51	955	13.4	—	1.48	31	0.25
		05/18/23	6.84	717	20.6	—	0.17	-72	—
		11/08/23	7.82	104	16.5	—	2.51	-52	—
		05/24/24	6.97	273	15.8	—	6.71	55	—
		11/07/24	6.83	257.7	15.5	—	3.30	-53.4	—
MW122	Alley E of Seattle Roy Aloha Shops	03/28/17	7.89	519	13.5	—	0.64	109	—
		06/14/17	7.72	374	16.7	—	0.46	-69	—
		04/06/18	7.93	336	14.9	—	0.60	77	—
		10/14/19	6.96	346	14.6	3.2	0.96	258	0.0
		01/17/20	7.19	362	13.7	1.2	0.20	23	—
		04/07/20	7.13	320	15.3	—	0.25	-13	0.0
		07/24/20	7.81	352	21.0	2.00	0.46	23	0.0
		11/06/20	7.50	282	13.6	17.4	0.20	-129	—
		05/03/21	7.68	345	14.8	—	0.14	112	—
		11/11/21	7.73	328	14.7	—	0.39	36	0.3
		05/18/22	7.60	360	16.3	—	0.33	-113	—
		11/01/22	6.68	416	14.3	—	0.23	240	0.0
		05/12/23	7.62	366	17.8	—	1.03	-29	—
		05/21/24	6.92	309	14.0	—	0.18	-15	—
		11/12/24	6.98	358	13.0	—	0.32	213.4	—
MW123	Westlake Ave N ROW W side	04/01/17	6.85	795	13.1	14.5	1.10	-117	—
		06/24/17	6.89	737	17.3	—	1.07	-89	—
		04/14/18	6.82	888	14.5	—	0.50	166	—
		10/18/19	6.71	947	14.3	6.0	0.36	-65	2.2
		01/22/20	6.79	687	13.8	4.7	1.89	25	4.0
		05/04/20	6.74	845	16.7	10.9	0.29	-102	3.0
		07/30/20	6.86	844	20.4	9.46	0.44	114	3.5
		11/12/20	6.73	736	14.5	—	0.34	-98	—
		05/26/21	6.77	853	17.7	—	0.26	-142	—
		03/02/22	6.93	675	14.6	—	0.17	-437	—
		06/09/22	7.01	571.2	15	—	0.23	-78	—
		11/03/22	6.06	497	14.9	—	0.80	52	2.0
		11/09/23	7.41	164	14.9	—	1.33	-38	—
		11/14/24	6.75	695	14.9	—	0.15	14.3	—
MW124	Valley St ROW, S side	12/26/13	7.84	285	—	—	1.43	217	0.39
		03/29/17	7.96	306	13.9	—	1.06	117	—
		06/15/17	7.64	292	16.5	—	0.50	9	—
		04/13/18	7.57	281	14.3	—	1.30	327	0.5
		10/11/19	6.99	398	17.8	23.1	5.01	-64	0.0
		01/30/20	8.30	450	15.6	68.0	—	-186	0.0
		04/03/20	7.39	322	15.0	408.0	0.37	114	0.0
		08/03/20	7.45	324	17.2	103	0.32	10	0.0
		11/18/20	7.50	261	13.4	82.4	0.71	-160	—
		06/08/21	7.23	322	15.6	129	0.53	-126	—
		03/07/22	7.12	358.1	12.3	59	0.45	-451	—
		05/12/22	7.48	319	16.9	162	1.20	100	—
		10/31/22	7.63	356	15.2	—	0.34	208	0.0
		05/08/23	7.42	327	16.7	—	0.15	-37	—
		11/03/23	7.69	316	14.8	—	3.54	62	—
		05/28/24	7.21	282	14.9	—	0.10	169	—
		11/05/24	7.29	346	15.4	—	0.48	-172.7	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW128	Westlake Ave N ROW E side	03/29/17	6.62	800	12.5	7.0	0.99	-88	1.8
		06/21/17	6.74	1,588	17.8	—	0.56	-79	—
		04/09/18	7.57	850	17.9	—	0.40	-45	—
		07/18/19	6.80	1,040	17.3	—	0.24	-102	—
		10/11/19	6.77	880	15.6	156	0.44	-22	4.5
		01/20/20	7.05	947	14.2	1.1	0.30	-49	2.0
		02/18/20 ^c	6.78	1175	14.2	—	0.64	-7	—
		04/27/20	6.82	941	15.1	3.5	0.12	-76	6.0
		06/29/20	7.38	810	15.6	—	0.33	-155	3.5
		11/09/20	6.85	775	14.1	93.0	0.37	-129	—
		05/25/21	6.84	758	17.7	—	0.23	-116	—
		02/25/22	6.74	838	13.3	—	0.61	-89	—
		06/08/22	6.71	850	16.6	—	0.32	-74	—
		11/01/22	6.70	878	15.5	—	0.42	-126	2.8
		05/18/23	6.93	803	17.7	—	0.68	-114	—
		11/09/23	7.39	791	15.5	—	0.81	2.3	—
		05/23/24	6.87	1,009	15.6	—	0.18	-154.4	—
		11/14/24	6.69	1,048	15.4	—	0.36	-146.4	—
MW-133	Property, SW quadrant	09/25/17	9.85 ^(a)	372	24.0	—	0.80	-157	—
		04/25/18	7.79	344	21.7	—	0.30	-25	1.3
		10/26/18	8.16	403	19.6	—	0.71	125	—
		12/12/18	7.69	362	17.3	—	0.90	-74	—
		02/01/19	7.76	362	19.4	—	0.34	-163	—
		03/13/19	6.99	413	12.1	—	0.91	181	—
		Decommissioned March 2019							
MW-137	Property, SW quadrant	09/25/17	9.22 ^(a)	342	26.0	223 ^(b)	0.60	-148	—
		04/12/18	9.29	386	22.1	—	0.10	-112	0.8
		10/26/18	7.54	469	24.2	—	8.74	141	—
		12/12/18	7.27	398	18.8	—	0.74	-117	—
		02/01/19	9.26	437	18.8	—	0.21	-171	—
		03/11/19	7.39	493	18.1	—	0.50	180	—
		Decommissioned March 2019							
MW-138	Dexter Ave N ROW E side	09/21/17	8.32 ^(a)	390	18.1	MAX ^(b)	0.52	-331	—
		04/11/18	7.89	350	17.4	—	0.20	34	0.0
		10/29/18	7.43	346	16.5	—	0.38	122	—
		12/17/18	7.82	424	15.7	—	0.49	-145	—
		01/03/19	7.33	358	16.2	—	2.41	50	0.0
		03/14/19	6.76	426	14.2	—	0.44	149	—
		04/22/19	7.47	359	17.1	—	0.34	-65	3.5
		07/19/19	7.61	366	18.9	—	0.21	-156	0.5
		10/21/19	7.36	398	16.7	—	0.54	-146	0.5
		01/27/20	7.25	509	16.6	145	0.04	-145	0.5
		05/08/20	7.29	262	19.3	—	3.54	31	0.5
		07/27/20	7.37	380	19.7	305	0.30	106	1.0
		11/18/20	7.25	339	16.8	186	0.32	-38	—
		02/11/21	7.36	350	14.3	263	0.49	47	—
		06/07/21	7.22	329	14.2	425	1.67	-147	—
		08/03/21	7.35	372	20.1	130	0.69	-131	—
		11/10/21	7.44	318	16.4	—	0.35	123	0.8
		02/24/22	7.56	384	12.1	177	0.88	-224	—
		05/25/22	7.54	367	16.8	—	0.22	-61	—
		08/09/22	7.09	187	17.3	—	2.50	177	—
		11/08/22	6.65	283	14.7	—	0.49	82	1
		05/09/23	7.44	317	16.1	—	0.38	-155	—
		05/22/24	6.50	117	6.6	—	0.22	-130	—
		11/13/24	7.36	423	16.1	—	0.62	-154.8	—
MW-140	Roy St ROW, N side	09/22/17	7.99 ^(a)	560	21.6	200 ^(b)	0.73	-209	—
		04/12/18	7.74	421	14.0	—	0.30	50	0.3
		Decommissioned							
MW-141	Property, SE quadrant	09/22/17	9.90 ^(a)	398	24.0	MAX ^(b)	0.40	-393	—
		04/12/18	7.39	337	20.9	—	0.20	38	—
		10/25/18	7.25	376	19.5	—	0.41	150	—
		12/12/18	7.20	339	17.0	—	0.92	-110	—
		01/30/19	7.35	411	20.5	—	0.28	-134	—
		03/11/19	7.29	427	16.4	—	0.55	185	—
		Decommissioned March 2019							

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-153	Roy St ROW, S side	05/01/18	8.91	369	16.5	—	0.40	87	—
		01/22/19	8.91	391	15.2	—	0.67	94	0.0
		04/24/19	8.62	327	18.0	—	0.45	93	0.0
		07/22/19	7.65	370	17.1	—	8.17	3	0.0
		11/18/19	7.45	330	17.6	90.0	0.27	228	—
		01/21/20	7.83	648	15.0	40.7	0.32	-113	0.0
		04/30/20	7.82	298	17.3	57.3	0.35	-77	0.0
		07/15/20	7.80	308	22.5	187	0.79	-10	0.0
		11/09/20	7.87	315	15.8	47.2	0.63	-134	—
		02/09/21	7.87	327	14.1	69.0	0.62	35	—
		05/10/21	7.89	336	18.9	34.6	0.7	-188	—
		08/20/21	7.97	345	19.0	60	0.35	-5	—
		12/07/21	7.99	343	14.3	—	0.95	-160	0.4
		02/25/22	7.98	368	14.8	—	0.97	-166	—
		05/02/22	7.94	349	15.9	—	4.37	112	—
		08/02/22	8.04	355	19.4	—	0.88	-30	—
		11/03/22	6.98	418	10.6	—	1.34	235	0.0
		05/12/23	7.67	372	21.5	—	0.20	-55	—
		11/10/23	7.70	351	13.8	—	1.73	-40	—
		05/31/24	7.57	399	16.7	—	0.25	-236	—
	DUP	11/07/24	7.78	379.4	16.6	—	0.38	145.8	0.0
MW-158A	8th Ave N ROW, E side	04/30/18	8.20	1,306	14.8	—	0.40	102	0.5
		01/24/19	7.91	707	13.8	MAX ^(b)	0.53	-164	0.0
		04/25/19	7.58	775	17.7	—	0.48	38	NR
		07/19/19	7.72	653	8.3	—	0.15	-144	0.0
		10/16/19	7.46	856	15.9	47.0	0.75	-79	—
		01/21/20	7.60	916	15.6	308	0.18	-168	—
		04/24/20	7.56	692	13.0	200	0.99	63	0.0
		07/15/20	7.62	681	18.4	189	0.32	-149	0.0
		11/23/20	7.64	690	7.7	389	1.78	-364	—
		02/02/21	7.71	716	11.5	285	1.00	-502	—
		05/10/21	7.73	703	18.2	262	0.61	-207	—
		08/17/21	7.69	698	18.5	—	0.51	141	—
		12/08/21	7.70	700	14.0	—	1.29	-162	0.4
		03/04/22	7.71	727	13.8	102	0.32	-607	—
		05/17/22	7.79	686	16.3	—	0.55	-43	—
		08/12/22	7.69	520	18.8	—	3.85	77	—
		11/01/22	7.28	415	14.7	—	0.19	191	0.0
		05/12/23	7.57	592	19.5	—	0.85	-142	—
		11/06/23	7.17	484	15.3	—	0.39	9	0.3
		05/21/24	7.22	408	12.2	—	4.33	-48	—
		11/05/24	7.05	552	13.7	—	1.55	146.1	0.0
MW-160	8th Ave N ROW, W side	05/21/18	7.96	323	23.2	—	0.42	-247	0.0
		01/25/19	7.57	404	18.4	MAX ^(b)	0.40	95	0.5
		05/01/19	7.71	359	24.0	—	0.32	-121	0.0
		07/23/19	7.73	341	21.8	—	0.75	115	0.5
		10/17/19	7.58	487	19.5	85.0	0.53	-111	0.8
		01/29/20	8.67	528	19.5	28.8	—	-198	0.0
		04/01/20	7.42	359	18.8	251	0.42	99	0.0
		08/03/20	7.76	344	19.6	193	0.54	122	0.5
		11/30/20	7.58	343	17.0	25	0.28	-28	—
		02/05/21	7.47	334	14.6	151	1.00	-476	—
		08/23/21	7.57	330	19.8	512	0.33	-93	—
		11/29/21	7.17	327	17.1	—	0.05	-114	0.8
		02/23/22	7.69	334	12.9	—	0.44	-219	—
		05/25/22	7.58	330	19.0	—	0.56	-43	—
		08/12/22	7.43	339	17.7	—	4.70	-32	—
		10/31/22	7.30	333	17.0	—	0.63	-163	0.8
		05/15/23	6.65	348	18.4	—	0.24	66	—
		11/03/23	7.26	352	16.6	—	0.50	-161	0.5
		05/22/24	7.50	329	14.5	—	2.82	23	—
		11/08/24	7.21	363.3	16.1	—	0.81	-107.6	—
MW-161	8th Ave N ROW, W side	05/21/18	7.59	544	21.6	—	0.48	-153	0.0
		01/25/19	7.49	661	17.9	MAX ^(b)	0.61	99	0.0
		04/29/19	7.27	662	18.4	—	0.31	24	0.0
		07/18/19	7.10	586	20.9	—	0.36	-30	0.0
		10/14/19	7.44	837	19.7	11.5	0.16	-106	0.0
		01/28/20	8.29	792	15.3	—	—	-117	0.3
		04/03/20	7.54	510	15.3	17.1	0.22	-119	0.5
		07/31/20	7.56	466	18.9	6.60	0.14	-60	0.0
		12/01/20	7.58	438	17.5	8.7	0.25	-31	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
		02/05/21	7.48	424	14.5	32.8	0.61	-507	—
		05/25/21	7.36	444	15	—	0.17	126	—
		08/23/21	7.39	449	18.2	—	0.26	157	—
		11/29/21	7.57	476	15.6	—	0.22	160	0.0
		02/23/22	7.55	498.5	13.1	—	0.18	-268	—
		05/11/22	7.42	474	15.8	—	0.29	-38	—
		08/12/22	7.55	480	19.0	—	2.40	-46	—
		10/31/22	7.32	484	17.2	—	0.52	-157	0.4
		05/15/23	6.58	503	18.2	—	0.21	74	—
		11/06/23	7.63	423	16.7	—	1.24	16	—
		05/22/24	7.30	421	14.4	—	0.43	73	—
		05/22/24	7.30	421	14.4	—	0.43	73	—
		11/08/24	7.52	519	16.5	—	0.30	-17.6	0.0
MW-162	Property, NE quadrant	02/05/19	7.68	541	12.7	7.5	0.29	110	—
		03/12/19	7.52	402	17.8	—	0.31	-82	—
		Decommissioned March 2019							
MW-163	Property, NW quadrant	02/05/19	7.67	394	15.5	4.5	3.73	-45	—
		03/12/19	7.45	392	15.6	—	0.59	145	—
		Decommissioned March 2019							
MW-164	Property, SW quadrant	02/05/19	7.63	462	14.6	10.5	0.56	-35	—
		03/12/19	7.30	686	15.4	—	0.23	149	—
		Decommissioned March 2019							
MW-304	Dexter Ave N ROW E side	10/21/19	7.91	352	17.3	91.0	0.59	-214	0.0
		01/27/20	7.96	503	16.3	172	—	-196	0.5
		05/07/20	7.54	297	18.0	221	0.59	-120	0.7
		07/27/20	7.99	330	21.0	392	1.10	-14	0.1
		05/18/21	7.37	346	13.8	315	0.56	118	—
		11/08/21	7.34	868	16.2	216	0.34	-240	0.5
		05/25/22	7.58	336	16.0	—	0.28	4	—
		11/09/22	6.50	249	11.1	—	1.66	26	0.0
		05/09/23	6.94	349	13.6	—	0.27	101	—
		10/31/23	7.60	280	16.5	—	6.32	21	—
		05/22/24	7.25	343	16.9	—	1.50	-69	—
		11/13/24	7.62	363.4	16.5	—	7.89	-49.0	—
MW-319	9th Ave N ROW, W side	10/08/19	6.90	563	15.4	22.8	0.43	193	3.5
		01/16/20	6.90	577	14.5	1.3	0.20	-69	3.0
		04/27/20	6.81	655	17.8	35.0	0.47	88	—
		07/27/20	6.60	637	21.8	6.08	0.31	109	2.5
		11/12/20	6.81	600	15.7	7.8	0.41	-149	—
		05/19/21	6.90	729	16.5	10.0	0.28	-113	—
		11/08/21	7.00	734	16.2	—	0.26	144	3.0
		05/27/22	6.90	718	15.6	—	0.29	-84	—
		11/02/22	6.91	817	11.8	—	0.31	264	2
		05/17/23	7.38	577	22.8	—	0.32	-80	—
		11/08/23	7.59	674	14.8	—	1.26	-138	—
		05/22/24	6.90	221	16.1	—	0.18	-165	—
		11/06/24	6.81	741	15.1	—	0.27	-119.6	—
MW-323	9th Ave N ROW, W side	10/09/19	6.85	489	16.7	17.6	0.35	-335	0.0
		01/20/20	7.32	786	15.2	3.4	0.50	-57	2.5
		04/23/20	—	705	15.9	13.4	0.39	221	2.4
		07/07/20	7.33	689	16.8	44.3	0.40	-25	2.8
		11/24/20	7.26	498	12.5	26.0	0.59	-143	—
		05/20/21	7.25	681	15.4	1.0	0.27	-156	—
		11/16/21	7.06	665	16.4	—	0.03	71	2.3
		06/03/22	7.15	702	15.4	—	0.40	-112	—
		11/04/22	6.04	592	15.8	—	0.50	184	2.0
		05/17/23	7.20	719	18.1	—	0.16	-78	—
		11/08/23	7.19	707	15.8	—	1.21	-85	—
		05/22/24	7.38	583	15.3	—	0.29	-63	—
		11/07/24	7.08	779	14.9	—	0.38	-175.5	—
MW-324	Roy St ROW, N side	10/02/19	8.43	1,060	16.2	89.6	0.36	162	2.0
		01/20/20	7.05	1,717	12.0	3.6	0.44	43	4.4
		04/24/20	6.79	1,492	15.9	14.0	0.22	-100	4.0
		07/07/20	6.72	1,283	17.3	15.9	0.30	4	4.0
		11/13/20	6.50	1,163	15.4	65.1	0.31	-153	—
		05/20/21	6.65	1,015	16.7	0.3	0.24	-96	—
		11/16/21	6.71	897	14.9	—	0.00	63	4.0
		05/31/22	6.55	1,076	16.8	—	0.30	-47	—
		11/03/22	6.07	999	15.1	—	1.00	45	1.0
		05/18/23	6.63	1,144	17.0	—	0.12	-59	—
		05/23/24	6.86	641	14.8	—	0.33	120	—
		11/07/24	6.80	730	16.0	—	0.29	-16.3	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-326	Mercer St ROW, N side	10/03/19	7.53	529	15.9	45.3	0.42	53	0.5
		01/17/20	7.23	875	12.5	—	0.49	47	0.8
		04/21/20	6.55	580	14.6	14.0	0.45	139	2.0
		07/23/20	6.84	1,369	16.0	9.3	0.10	-99	4.5
		11/02/20	6.99	704	15.2	6.9	0.40	-129	—
		02/09/21	6.97	752	13.0	17.0	0.31	46	—
		05/18/21	6.92	671	15.9	—	0.45	-156	—
		08/12/21	6.81	683	17.0	—	0.28	-94	—
		11/04/21	6.88	735	14.9	—	0.46	-133	0
		03/03/22	6.89	522	12.5	16	0.36	-436	—
		05/09/22	6.81	547	13.3	—	2.21	9	—
		08/11/22	7.12	383	15.8	—	1.60	129	—
		11/02/22	7.21	573	12.6	—	1.49	179	0.0
		05/15/23	7.24	630	17.3	—	0.42	-100	—
		05/09/23	6.83	503	17.1	—	0.36	23	—
		05/24/24	6.99	403	14.3	—	0.15	-57	—
MW-328	Lake Union Park, S end	10/02/19	6.82	4,785	14.6	26.6	0.41	-68	4.0
		01/17/20	6.72	1,190	12.1	5.9	0.40	-33	2.5
		04/08/20	6.53	1,154	14.1	—	0.20	-91	3.6
		07/07/20	6.83	1,014	14.2	11.5	0.26	-103	5.5
		11/09/20	6.70	1,107	12.5	9.3	0.47	-116	—
		05/25/21	6.77	1,015	14.2	—	0.19	133	—
		11/10/21	7.13	942	13.2	—	0.00	-84	4.5
		05/04/22	6.75	1,086	13.3	—	1.60	-95	—
		11/02/22	6.91	704	13.3	—	1.35	119	3.5
		05/19/23	6.86	794	13.1	—	0.54	-99	—
		11/09/23	7.41	710	13.6	—	0.30	3	—
		05/23/24	6.68	755	13.4	—	0.22	0	—
		11/14/24	6.79	1,162	13.8	—	0.29	-4.0	—
MW-329	Westlake Ave N ROW E side	10/03/19	6.92	1,012	18.6	34.8	0.38	-114	4.0
		01/20/20	7.20	1,051	14.0	—	0.30	-19	1.5
		04/27/20	7.01	951	17.9	64.1	0.70	-77	2.5
		08/03/20	7.13	913	16.5	79.5	0.31	-78	3.0
		11/09/20	6.94	877	14.3	29.9	0.47	-112	—
		05/25/21	6.96	883	17.3	—	0.28	-134	—
		02/25/22	6.90	1,003	14.2	—	0.78	-80	—
		06/09/22	7.05	908	14.2	—	0.38	-70	—
		11/01/22	6.95	1,014	15.9	—	0.41	-142	3.2
		05/18/23	7.07	840	16.2	—	0.72	-115	—
		11/09/23	7.58	835	15.0	—	0.23	-1	—
		05/23/24	7.03	1,031	15.5	—	0.61	-144	—
		11/14/24	6.91	1,074	15.2	—	0.29	-198.6	—
MW-336	Mercer St ROW, N side	05/05/20	6.92	1,126	16.4	3.0	1.88	-84	6.5
		07/08/20	6.94	990	21.3	6.0	0.45	-9	4.0
		11/02/20	6.81	940	17.6	5.9	0.37	-105	—
		02/10/21	6.86	935	15.2	—	0.26	49	—
		05/26/21	6.81	955	16.8	—	0.32	-143	—
		08/11/21	6.69	972	24.2	—	0.19	131	—
		11/17/21	6.85	913	14.9	—	0.00	55	6.5
		03/02/22	6.82	942	14.2	—	0.64	-89	—
		05/31/22	6.78	949	18.2	—	0.34	-72	—
		08/10/22	7.54	610	19.8	—	5.02	97	—
		11/03/22	6.17	623	17.8	—	3.41	19	0.0
		05/19/23	7.26	864	16.4	—	3.64	-59	—
		11/09/23	7.26	1,032	16.9	—	3.50	-9	—
		05/28/24	7.22	1,042	16.3	—	5.12	147	—
		11/14/24	7.18	1,046	16.8	—	3.79	-61.2	—
MW-326R	Mercer St ROW, N side	05/15/23	7.24	630	17.3	—	0.14	-100	—
		11/09/23	7.23	571	13.3	—	2.39	-91	—
		05/24/24	7.06	472	13.9	—	0.14	-51	—
		11/11/24	7.26	638	14.2	—	0.40	-203.4	—
MW-341	Lake Union Park, S end	05/12/20	7.44	779	14.4	12.0	0.78	-166	3.0
		07/07/20	7.14	771	14.8	18.6	0.12	-136	5.5
		11/09/20	7.63	337	11.5	11.4	0.10	-293	—
		05/25/21	7.01	762	15.5	—	0.12	132	—
		11/10/21	7.34	806	13.9	—	0.00	-126	4.3
		05/04/22	7.06	753	13.5	—	1.82	-123	—
		11/02/22	6.91	617	12.8	—	0.49	83	2.5
		05/18/23	7.16	626	15.9	—	0.48	-125	—
		11/09/23	7.60	618	13.2	—	0.25	2	—
		05/23/24	6.91	626	13.3	—	0.16	20	—
		11/14/24	6.91	1,045	13.7	—	0.15	-24.5	—

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-342	Valley St ROW, S side	05/04/20	7.40	385	14.5	9.0	0.27	-20	0.0
		07/30/20	6.60	473	16.5	17.0	0.39	123	3.5
		11/17/20	6.80	186	15.1	—	0.30	-65	—
		06/04/21	6.52	434	15.4	8.0	0.22	-113	—
		11/09/21	6.73	1,007	14.5	—	0.00	-98	1.5
		05/17/22	6.77	438	15.0	—	0.23	-24	—
		11/01/22	6.49	596	14.9	—	0.37	-134	2.8
		05/09/23	7.10	203	14.5	—	4.14	-85	—
		11/09/23	6.76	784	14.9	—	1.20	-51	—
		05/24/24	6.86	709	14.4	—	0.45	-138	—
		11/22/24	6.76	891	15.1	—	0.19	11.4	—
MW-343	Valley St ROW, S side	05/04/20	6.92	1,511	15.5	8.0	0.63	-123	6.5
		07/30/20	6.95	1,496	16.6	44.2	0.78	129	4.3
		11/24/20	6.86	1,250	13.9	430	0.62	-131	—
		06/04/21	6.86	724	15.1	8.3	0.28	-148	—
		11/09/21	7.17	776	12.5	—	0.20	-112	3.8
		05/17/22	6.85	754	14.8	—	0.27	-40	—
		11/01/22	6.74	757	15.2	—	0.40	-140	3.4
		05/09/23	7.26	420	13.8	—	1.19	-69	—
		05/24/24	6.96	812	14.3	—	1.00	-149	—
		11/22/24	6.92	874	15.1	—	0.16	-7.5	—
		Treatment Zone A Injection Wells							
IW-4A	Property, NW quadrant	03/28/18	6.49	540	17.1	—	0.50	65	—
		Decommissioned March 2019							
IW-7A	Property, NE quadrant	04/02/18	7.07	1,096	15.7	—	0.60	123	—
		Decommissioned March 2019							
IW-9A	Property, NW quadrant	03/29/18	6.58	528	16.8	—	1.40	88	—
IW-18A	Property, NE quadrant	03/30/18	6.47	928	17.7	—	0.50	117	—
		12/13/18	6.26	2,199	17.0	—	1.11	—	—
		Decommissioned March 2019							
IW-22A	Property, NE quadrant	04/02/18	6.96	1,005	18.6	—	0.60	93	—
		Decommissioned March 2019							
IW-37A	Property, SW quadrant	03/28/18	8.17	319	15.9	—	0.70	10	—
		Decommissioned March 2019							
IW-38A	Property, SW quadrant	12/14/18	6.60	1,945	15.8	—	0.26	144	—
		Decommissioned March 2019							
IW-41A	Property, SW quadrant	04/10/18	8.12	364	17.4	—	0.30	59	—
		Decommissioned March 2019							
IW-42A	Property, SW quadrant	04/10/18	7.53	590	14.2	—	0.40	73	—
		Decommissioned March 2019							
IW-45A	Property, SW quadrant	04/04/18	7.18	573	13.3	—	0.70	69	—
		Decommissioned March 2019							
IW-46A	Property, SE quadrant	03/28/18	6.78	1,564	14.7	—	0.50	89	—
		Decommissioned March 2019							
IW-48A	Property, SE quadrant	04/02/18	6.88	2,007	15.4	—	0.70	73	—
		Decommissioned March 2019							
MW-165	Property, NE quadrant	11/04/19	6.64	2,285	16.9	4.8	0.21	-177	4.0
		01/30/20	7.32	2,923	15.6	6.9	0.96	-162	4.5
		05/01/20	6.72	2,758	15.5	23.8	3.91	-75	3.0
		07/09/20	6.63	2,501	18.1	1.79	0.10	-100	6.0
		11/05/20	6.61	2,377	18.0	2.2	0.19	-244	—
		02/04/21	6.60	1,539	16.2	—	0.14	48	—
		05/06/21	6.61	1,655	15	—	0.24	-140	—
		08/10/21	6.53	1,643	17.2	—	0.19	129	—
		12/02/21	6.38	1,290	15.7	—	1.18	-661	3.4
		02/22/22	6.67	1,298	14.9	—	0.75	-150	—
		05/13/22	6.84	1,232	15.1	—	0.42	-89	—
		08/05/22	6.03	1,059	16.1	—	1.93	79	—
		10/28/22	6.51	1,247	17.3	—	0.35	-195	2.4
		05/11/23	6.49	1,874	15.2	—	0.18	-39	—
		11/01/23	6.53	1,945	17.2	—	0.89	-122	3.5
		05/28/24	6.59	1,748	15.5	—	2.13	-94	—
		11/19/24	6.38	1,905	16.9	—	0.10	73.3	7.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-169	Property, SW quadrant	11/05/19	7.68	1,295	18.9	4.3	0.18	-73	2.5
		01/23/20	7.62	2,075	13.4	5.7	0.39	-189	3.0
		05/05/20	7.31	1,685	15.8	5.7	0.38	-189	2.0
		07/10/20	7.69	1,493	17.6	10.8	0.20	-155	4.2
		11/03/20	7.49	1,610	17.9	—	0.22	-215	—
		11/30/20	7.58	343	17.0	25.0	0.28	-28	—
		02/17/21	7.77	1,457	12.0	1.0	4.37	-143	—
		05/07/21	7.80	1,333	14.1	1.5	4.85	-145	—
		08/10/21	7.53	1,317	17.3	—	0.08	-240	—
		11/19/21	7.78	1,172	15.5	—	1.00	180	3.0
		02/16/22	7.64	1,188	13.4	—	0.64	-245	—
		05/12/22	7.71	1,113	14.3	—	0.04	-124	—
		08/05/22	6.06	951	17.2	—	0.66	107	—
		10/27/22	7.64	1,025	18.1	—	0.30	—	1.4
		05/10/23	7.72	983	15.6	—	0.44	-34.7	—
		05/24/24	7.48	1,198	15.6	—	0.25	-183.5	—
		11/13/24	7.47	1,247	17.4	—	0.07	17.7	1.8
MW-173	Property, SE quadrant	11/01/19	7.30	1,279	16.5	3.0	0.27	-160	1.5
		01/28/20	9.06	1,540	14.0	10.4	0.70	-122	2.0
		05/01/20	7.47	1,036	16.2	1.5	0.17	-112	1.0
		07/09/20	7.38	1,044	17.6	1.4	0.30	-34	1.4
		11/05/20	7.31	1,006	18.1	1.3	2.38	-183	—
		02/04/21	7.16	880	13.1	9.4	1.71	-452	—
		05/05/21	7.41	916	15.1	0.3	0.74	-173	—
		08/05/21	7.23	893	17.3	93	2.38	-87	—
		12/02/21	7.48	1,048	15.9	—	0.83	179	2.0
		02/17/22	7.47	1,002	13.8	—	0.90	-234	—
		05/13/22	7.42	985	15.0	—	0.00	-129	—
		08/11/22	7.57	—	17.0	—	20.1 ^d	-27	—
		10/27/22	7.21	1,006	17.6	—	0.38	-207	1.9
		05/11/23	6.97	1,088	15.0	—	0.14	-37	—
		11/02/23	7.42	974	17.6	—	0.69	16	2.0
		05/28/24	7.54	1,199	15.5	—	2.46	-142	—
		11/18/24	7.10	1,260	17.1	—	0.53	-111.9	2.0
MW-177	Property, SW quadrant	11/06/19	6.98	1,769	15.2	4.6	0.17	-80	3.1
		01/24/20	6.71	2,491	15.5	—	1.84	-92	—
		04/01/20	6.62	1,939	16.0	28	2.54	-154	5.0
		07/10/20	6.69	1,996	17.3	25.9	0.10	-63	3.0
		11/03/20	6.86	1,300	17.0	1.5	0.33	-70	—
		02/18/21	6.98	1,155	13.4	2.5	0.64	-74	—
		05/06/21	6.96	983	14.3	—	1.13	-143	—
		08/09/21	6.94	928	16.6	—	0.45	117	—
		12/03/21	7.13	814	14.9	—	0.61	167	3.0
		02/17/22	6.89	822	14.1	—	0.15	181	—
		05/10/22	6.85	844	14.6	—	0.34	-125	—
		08/04/22	6.90	778	16.7	—	0.05	-53	—
		10/26/22	6.91	785	17.3	—	2.10	—	1.75
		05/10/23	6.77	884	15.3	—	0.42	-141	—
		11/01/23	6.88	955	17.4	—	0.21	-166	3.0
		05/23/24	7.03	928	15.7	—	2.43	-90	—
		11/12/24	6.75	1,317	17.2	—	0.04	33.9	2.8
MW-181	Property, SW quadrant	11/08/19	7.29	1,341	17.1	6.7	0.22	154	2.0
		01/27/20	6.86	2,322	14.4	9.7	0.32	-110	4.4
		04/01/20	6.41	1,422	16.3	5.4	0.13	-71	5.2
		07/08/20	6.73	1,474	17.5	41.9	0.71	-118	4.0
		11/04/20	6.91	1,629	17.4	2.5	0.23	-178	—
		02/19/21	7.30	1,454	12.5	9.2	0.73	-17	—
		05/06/21	7.18	1,330	15.6	7.5	0.11	121	—
		08/09/21	7.16	1,309	16.5	25	0.10	115	—
		11/18/21	7.20	1,216	16.4	—	1.69	163	3.8
		02/16/22	7.16	1,270	16.1	—	0.13	-348	—
		05/10/22	7.13	1,242	15.6	—	0.09	-128	—
		08/04/22	6.82	1,074	17.0	—	0.44	-7	—
		10/25/22	7.03	1,240	17.8	—	2.59	—	3.0
		05/10/23	6.86	1,280	15.6	—	0.16	-92.3	—
		11/01/23	6.99	1,281	17.2	—	1.03	-139.8	4.0
		05/23/24	6.88	1,308	15.8	—	1.91	-135.7	—
		11/11/24	6.78	1,424	17.2	—	0.06	37.1	5.1

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-185	Property, SE quadrant	10/31/19	7.05	1,944	12.8	7.4	0.48	-109	2.5
		01/29/20	6.79	3,212	15.9	2.2	0.03	-130	3.0
		04/02/20	6.82	2,168	15.1	13.1	0.25	-147	6.2
		07/08/20	6.91	1,694	17.1	11.8	1.30	-136	5.5
		11/04/20	7.20	1,175	16.6	0.8	0.07	-59	—
		02/16/21	7.37	1,167	12.8	1.6	1.15	-8	—
		05/07/21	7.29	1,127	—	1.1	0.92	-147	—
		08/03/21	7.28	973	16.5	—	0.25	76	—
		11/18/21	7.01	886	12.9	—	1.25	-91	3.8
		02/16/22	7.28	1,274	13.3	—	0.19	216	—
		05/12/22	6.97	1,297	14.4	—	0.16	-102	—
		08/05/22	7.22	1,169	16.9	—	0.11	-70	—
		10/27/22	7.14	1,140	18.0	—	0.09	—	1.75
		05/11/23	6.78	1,799	15.2	—	0.46	-144	—
		11/02/23	6.90	2,364	17.3	—	1.13	-130	2.5
		05/24/24	6.82	2,595	15.8	—	1.87	-128	—
		11/19/24	6.76	2,820	17.0	—	0.17	-35.7	4.5
Treatment Zone B Injection Wells									
IW-3B	Property, NW quadrant	03/28/18	6.65	669	16.0	—	0.70	66	—
		Decommissioned March 2019							
IW-6B	Property, SW quadrant	04/02/18	6.69	884	15.9	—	1.10	110	—
		Decommissioned March 2019							
IW-8B	Property, SW quadrant	03/30/18	7.66	471	13.6	—	0.80	111	—
		Decommissioned March 2019							
IW-17B	Property, NE quadrant	03/30/18	6.80	142	16.5	—	0.70	-6	—
		12/13/18	6.43	1,640	17.1	—	1.61	48	—
		Decommissioned March 2019							
IW-21B	Property, NE quadrant	04/02/18	7.01	1,709	17.9	—	0.50	74	—
		Decommissioned March 2019							
IW-22B	Property, NW quadrant	04/25/18	7.09	693	19.4	—	0.60	98	—
		Decommissioned March 2019							
IW-24B	Property, NE quadrant	03/30/18	6.92	1,279	17.8	—	0.70	72	—
		Decommissioned March 2019							
IW-28B	Property, NW quadrant	04/09/18	6.85 ^(a)	1,028	20.4	—	0.40	-55	—
		12/14/18	6.55	2,448	18.1	—	0.55	129	—
		Decommissioned March 2019							
IW-33B	Property, NE quadrant	04/02/18	7.03	1,425	16.7	—	0.70	87	—
		Decommissioned March 2019							
IW-37B	Property, SW quadrant	03/29/18	7.31	1,156	19.6	—	0.60	76	—
		Decommissioned March 2019							
IW-45B	Property, SE quadrant	03/28/18	7.40	949	18.0	—	0.70	64	—
		Decommissioned March 2019							
IW-47B	Property, SW quadrant	04/10/18	7.52	1,080	20.6	—	0.30	70	—
		Decommissioned March 2019							
IW-49B	Property, SE quadrant	03/28/18	6.98	1,551	15.6	—	0.60	88	—
		Decommissioned March 2019							
IW-51B	Property, SE quadrant	03/28/18	7.69	1,100	15.7	—	0.30	-151	—
		Decommissioned March 2019							
MW-166	Property, NE quadrant	11/04/19	6.64	2,204	15.5	4.7	0.20	-166	5.0
		01/30/20	7.30	2,119	17.3	9.3	—	-139	4.0
		05/01/20	6.78	2,017	17.3	9.6	0.15	-162	3.0
		07/09/20	6.95	1,340	18.6	5.81	0.21	-149	7.0
		11/05/20	6.74	1,625	17.9	4.7	0.17	-186	—
		02/04/21	6.89	1,615	15.5	2.0	0.11	50	—
		05/05/21	6.81	1,588	15.1	1.1	0.16	-138	—
		08/10/21	7.12	1,489	17.3	—	0.21	122	—
		12/02/21	6.39	1,437	15.4	—	0.54	-94	6.6
		02/22/22	6.80	1,552	16.5	—	0.22	-278	—
		05/13/22	6.79	1,529	15.2	—	0.37	-110	—
		08/05/22	6.11	1,347	17.0	—	1.41	36	—
		10/28/22	6.64	1,543	17.6	—	0.28	0	3.8
		05/11/23	6.69	1,652	15.6	—	0.32	-98	—
		11/02/23	6.71	1,455	17.2	—	0.23	7	5.5
		05/28/24	6.69	1,962	15.5	—	3.03	-35	—
		11/18/24	6.53	2,215	16.6	—	0.13	58.0	4.5

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-170	Property, SW quadrant	11/05/19	7.58	1,432	16.5	1.7	0.21	-29	1.1
		01/23/20	7.59	2,080	12.2	6.9	0.48	-157	3.0
		04/02/20	7.52	1,467	13.7	17.5	0.31	-184	4.5
		07/09/20	7.34	1,432	17.5	19.2	0.20	-182	5.5
		11/03/20	7.38	1,558	18.0	—	0.22	-203	—
		02/17/21	7.51	1,588	17.1	2.9	0.12	-117	—
		05/07/21	7.39	1,473	18	12.1	0.12	-206	—
		08/09/21	7.50	1,483	17.5	—	0.12	114	—
		11/19/21	7.53	1,419	17.0	—	0.34	170	1.5
		02/17/22	7.43	1,527	17.4	—	0.14	-327	—
		05/12/22	7.51	1,464	15.5	—	0.79	-44	—
		08/05/22	6.48	1,251	17.3	—	0.95	51	—
		10/27/22	7.47	1,482	18.3	—	0.23	—	2.6
		05/11/23	7.51	1,416	15.9	—	0.21	-39.6	—
		05/24/24	7.39	1,700	17.0	—	0.19	-149.8	—
		11/15/24	7.37	1,783	17.2	—	0.10	81.3	1.9
MW-174	Property, SE quadrant	11/01/19	6.89	1,550	15.9	2.3	0.35	-146	3.0
		01/28/20	8.71	1,196	15.0	36.4	0.62	-170	3.0
		05/01/20	7.47	855	15.4	20.3	0.20	-177	5.0
		07/09/20	7.15	768	19.3	62.7	0.20	-34	3.8
		11/05/20	6.86	1,392	18.7	1.7	0.13	-183	—
		02/04/21	6.81	1,467	14.8	4.3	1.21	-424	—
		05/05/21	7.02	1,338	16	—	0.73	-150	—
		08/05/21	7.03	1,237	17.7	—	1.54	-121	—
		12/02/21	7.07	1,712	15.2	—	0.57	187	4.0
		02/17/22	7.10	1,868	15.3	—	0.62	-158	—
		05/13/22	6.97	1,931	16.3	—	0.03	-54	—
		08/11/22	7.11	1,961	17.3	—	5.60	-77	—
		10/27/22	6.88	1,952	17.8	—	0.34	-211	3.0
		05/11/23	7.38	1,985	16.1	—	0.20	-132	—
		11/03/23	6.94	2,125	17.3	—	0.79	-118	2.2
		05/28/24	7.10	1,703	15.9	—	2.12	-133	—
		11/18/24	6.73	2,026	16.9	—	0.41	-131.5	3.0
MW-178	Property, SW quadrant	11/06/19	6.62	3,395	13.3	2.6	0.15	-67	3.5
		01/24/20	6.90	5,013	12.0	—	1.83	-149	6.0
		04/02/20	6.95	3,771	14.2	20.4	3.07	-167	6.5
		07/10/20	6.95	3,642	16.9	29.3	0.10	-101	3.5
		11/03/20	6.49	2,612	15.9	3.7	0.81	-74	—
		02/18/21	6.64	2,171	14.1	20.8	0.31	-47	—
		05/06/21	6.71	1,788	14.2	—	0.17	116	—
		08/06/21	6.71	1,679	16.6	9.2	0.31	113	—
		12/06/21	6.49	1,577	15.8	—	1.72	151	6.5
		02/17/22	6.50	1,481	14.9	—	0.25	178	—
		05/10/22	6.46	1,532	16.6	—	0.27	-124	—
		08/04/22	6.70	1,693	16.7	—	—	-56	—
		10/25/22	6.39	1,681	17.5	—	5.10	—	4.6
		05/10/23	—	—	—	—	—	—	—
		11/18/24	—	—	—	—	—	—	—
MW-182	Property, SW quadrant	11/08/19	7.03	2,831	16.7	7.2	0.15	-134	3.0
		01/27/20	6.82	3,979	15.8	—	0.23	-157	6.0
		04/01/20	6.58	2,613	18.5	14	0.08	-201	6.1
		07/08/20	6.89	2,520	17.2	8.33	0.10	-86	6.4
		11/04/20	6.55	2,719	18.5	2.7	0.24	-204	—
		02/19/21	6.55	2,282	17.9	8.9	0.38	-238	—
		05/06/21	6.59	2,165	17.8	—	0.15	-171	—
		08/09/21	6.66	2,107	17.9	17	0.21	110	—
		11/18/21	6.78	1,905	15.0	—	0.35	135	5.2
		02/16/22	6.67	2,086	17.3	—	0.12	-291	—
		05/10/22	7.66	1,001	16.6	—	0.02	-96	—
		08/04/22	7.53	1,808	17.4	—	0.45	120	—
		10/25/22	6.62	2,084	17.7	—	3.67	—	6.25
		05/10/23	6.56	2,059	16.0	—	2.54	-92.4	—
		11/02/23	6.78	2,117	17.4	—	1.08	-119.4	3.0
		05/23/24	6.72	2,102	16.7	—	1.99	-122.4	—
		11/13/24	6.50	2,200	17.1	—	0.29	-130.3	3.8

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-186	Property, SE quadrant	10/31/19	7.54	992	15.1	4.6	0.63	-64	—
		01/29/20	7.42	1,088	11.7	10.7	0.77	-158	1.5
		04/02/20	7.61	731	15.8	14.6	0.16	-228	2.6
		07/08/20	7.95	719	17.0	14.0	0.40	-122	1.2
		11/04/20	7.06	1,547	19.0	2.5	0.38	-88	—
		02/16/21	7.08	1,570	13.1	6.1	0.99	-74	—
		05/07/21	7.14	1,500	15.8	—	1.48	-137	—
		08/03/21	7.11	1,332	17.0	—	0.18	69	—
		11/18/21	7.10	1,038	12.5	—	1.78	-86	6.4
		02/16/22	6.99	1,392	14.0	—	0.56	205	—
		05/12/22	7.06	1,428	15.2	—	0.16	-119	—
		08/05/22	7.20	1,469	17.4	—	0.55	-66	—
		10/26/22	6.85	1,586	18.0	—	0.44	-170	3.0
		05/11/23	6.96	1,892.0	16.3	—	0.49	-150	—
		11/02/23	7.01	1,963	17.5	—	1.18	-126	3.5
		05/24/24	6.96	1,977	15.8	—	2.28	-108	—
		11/19/24	6.90	2,105	16.4	—	0.27	8.7	5.0
Treatment Zone C Injection Wells									
IW-1C	Property, NE quadrant	03/29/18	7.71	578	14.5	—	0.80	104	—
		Decommissioned March 2019							
IW-4C	Property, NE quadrant	04/26/18	7.91	725	17.8	—	0.70	109	—
		12/14/18	6.37	3,590	18.5	—	34.50	185	—
		Decommissioned March 2019							
IW-8C	Property, NE quadrant	04/04/18	9.13	1062	15.8	—	2.10	79	—
		Decommissioned March 2019							
IW-9C	Property, NE quadrant	04/02/18	7.36	967	18.5	—	0.80	85	—
		Decommissioned March 2019							
IW-13C	Property, SW quadrant	04/25/18	7.68	754	20.7	—	0.70	91	—
		Decommissioned March 2019							
IW-15C	Property, SW quadrant	03/30/18	7.32	1,343	19.8	—	0.30	2	—
		12/13/18	6.59	2,448	14.7	—	22.06	138	—
		Decommissioned March 2019							
IW-19C	Property, SW quadrant	03/29/18	7.59	1,122	19.3	—	0.80	98	—
		Decommissioned March 2019							
IW-20C	Property, SW quadrant	03/30/18	7.49	751	19.7	—	0.40	51	—
		Decommissioned March 2019							
MW-167	Property, NE quadrant	11/04/19	7.76	1,051	17.9	1.3	0.43	-184	0.5
		01/28/20	7.61	1,030	15.8	2.0	0.07	-214	0.5
		05/01/20	7.92	893	17.3	4.0	0.31	-187	0.0
		07/09/20	8.25	724	17.6	10.6	0.30	-129	—
		11/05/20	7.92	1,052	17.1	4.4	0.34	-236	—
		02/04/21	7.89	920	13.7	7.0	0.21	44	—
		05/05/21	7.82	901	15.3	—	0.31	121	—
		08/10/21	7.82	871	17.0	—	0.27	111	—
		12/02/21	7.63	813	16.4	—	0.32	-190	0.8
		02/22/22	7.91	857	14.7	—	0.38	-300	—
		05/13/22	7.90	818	16.3	—	0.22	-206	—
		08/05/22	6.10	717	17.4	—	0.65	100	—
		10/28/22	7.80	818	18.1	—	0.10	—	0.3
		05/11/23	7.97	683	15.6	—	0.42	-167	—
		11/01/23	7.85	872	17.3	—	0.29	-189	1.0
		05/28/24	7.93	840	6.5	—	1.88	-156	—
		11/19/24	7.51	730	15.9	—	0.36	-144.3	0.4
MW-171	Property, SW quadrant	11/08/19	8.06	583	16.3	36.8	0.17	117	1.0
		01/23/20	8.25	950	13.7	5.6	0.53	-218	0.5
		04/02/20	8.20	595	13.8	11.2	0.30	-210	1.0
		07/09/20	8.16	603	18.6	5.06	0.20	-155	1.0
		11/03/20	8.03	757	16.4	1.9	0.27	-238	—
		02/17/21	7.78	907	13.2	1.6	0.35	-243	—
		05/07/21	7.83	876	14.8	8.0	0.31	-223	—
		08/10/21	7.66	891	17.3	9.2	0.25	-139	—
		11/19/21	7.97	828	15.5	—	0.41	174	1.5
		02/17/22	7.77	922	15.0	—	0.58	-343	—
		05/12/22	7.80	877	14.6	—	0.37	-119	—
		08/04/22	6.69	773	16.9	—	0.88	144	—
		10/26/22	7.68	903	18.3	—	0.89	—	1.07
		05/11/23	6.92	930	16.2	—	0.10	79.2	—
		05/24/24	7.59	1,046	16.1	—	0.31	-126.1	—
		11/15/24	7.52	1,087	17.1	—	0.12	35.1	1.5

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-175	Property, SE quadrant	11/01/19	7.56	1,442	17.2	23.9	0.41	-151	0.0
		01/28/20	9.66	1,010	12.3	6.7	0.94	-165	0.0
		05/01/20	8.48	424	15.9	5.5	0.37	-74	0.0
		07/09/20	8.34	396	17.3	7.36	0.39	-160	0.5
		11/05/20	7.42	1,378	17.5	32.5	0.24	-85	—
		02/04/21	6.99	1,687	14.6	3.0	0.43	-456	—
		05/05/21	7.04	1,767	16.1	3.8	0.25	128	—
		08/05/21	7.02	1,605	17.4	45	0.65	-151	—
		12/02/21	7.00	1,748	16.7	—	0.38	184	4.5
		02/22/22	7.01	1,727	14.0	—	0.60	-123	—
		05/13/22	7.05	1,800	15.3	—	0.12	-77	—
		08/11/22	7.10	1,870	17.8	—	—	-84	—
		10/27/22	6.90	1,830	18.2	—	0.32	-186	3.8
		05/11/23	6.92	1,934	16.0	—	0.12	77	—
		11/02/23	6.99	1,656	17.3	—	0.19	18	4.0
		05/28/24	7.05	1,899	16.6	—	1.93	-140	—
		11/18/24	6.84	2,132	16.5	—	0.06	46.7	3.5
MW-179	Property, SW quadrant	11/06/19	6.92	2,192	14.3	5.2	0.10	139	2.0
		01/27/20	6.75	3,085	16.0	13.5	—	-146	3.5
		04/02/20	6.55	2,665	17.7	9	4.43	-170	5.5
		07/10/20	6.59	2,650	18.7	5.07	0.10	-72	5.0
		11/03/20	6.36	1,691	17.7	1.0	0.76	-80	—
		02/18/21	6.44	1,601	17.8	11.0	0.95	-28	—
		05/06/21	6.50	1,764	15.1	10.0	0.14	116	—
		08/09/21	6.53	1,844	17.1	—	0.89	111	—
		12/03/21	6.48	1,965	15.6	—	0.43	183	6.5
		02/17/22	6.28	1,943	15.6	—	0.50	188	—
		05/10/22	6.48	1,987	17.0	—	0.19	-157	—
		08/04/22	6.54	2,005	17.4	—	—	-66	—
		10/25/22	6.34	2,078	17.9	—	0.26	-175	4.0
		05/10/23	6.53	1,843	16.5	—	0.45	-151	—
		11/01/23	6.51	2,214	17.3	—	0.28	-149	1.5
		05/23/24	6.31	2,272	16.7	—	0.24	-91	—
		11/12/24	6.34	2,458	17.2	—	0.07	53.0	5.4
MW-183	Property, SW quadrant	11/08/19	8.09	303	12.8	12.6	0.38	184	0.0
		01/27/20	8.20	666	12.0	6.9	0.49	-206	0.4
		04/02/20	7.43	310	13.6	11	0.27	-190	0.0
		07/08/20	7.98	357	16.7	16.8	0.40	-163	0.5
		11/04/20	7.90	640	17.1	3.3	0.19	-69	—
		02/19/21	7.69	806	17.2	37.0	0.12	-38	—
		05/06/21	7.66	822	16.7	—	0.1	-212	—
		08/06/21	7.51	926	17.8	12	0.14	102	—
		11/18/21	7.60	925	17.0	—	0.28	139	0.6
		02/16/22	7.59	1,008	17.5	—	0.14	-329	—
		05/10/22	7.65	906	16.8	—	0.03	-111	—
		08/04/22	7.22	964	17.2	—	0.21	-2	—
		10/25/22	7.42	1,020	17.8	—	0.29	-231	0.05
		05/10/23	7.65	1,068	16.0	—	0.14	-99	—
		11/01/23	7.65	1,171	17.4	—	1.01	-151	0.5
		05/23/24	7.46	1,109	16.7	—	1.85	-134	—
		11/11/24	7.51	1,320	17.2	—	0.07	44.9	0.8
MW-187	Property, SE quadrant	11/01/19	7.22	671	9.0	8.6	0.35	-175	2.5
		01/29/20	7.82	740	13.5	1.1	0.75	-104	0.5
		04/02/20	7.34	389	12.7	23.2	0.44	-108	0.0
		07/08/20	7.55	449	16.9	5.97	0.47	-99	0.0
		11/04/20	7.82	694	16.6	2.9	0.43	-229	—
		02/16/21	7.65	922	12.4	3.0	0.55	-39	—
		05/07/21	7.64	1,035	14.3	3.2	0.39	-218	—
		08/03/21	7.68	1,012	17.3	—	0.48	44	—
		11/18/21	7.44	908	13.6	—	1.45	-125	2
		02/16/22	7.44	1,226	13.3	—	0.38	195	—
		05/12/22	7.49	1,239	16.7	—	0.42	-134	—
		08/05/22	7.53	1,383	17.4	—	3.50	-77	—
		10/26/22	7.34	1,384	18.1	—	0.48	-193	2.2
		05/11/23	7.39	1,221	15.5	—	0.41	-1,644	—
		11/02/23	7.50	1,488	17.2	—	1.11	-137	2.0
		05/24/24	7.47	1,584	16.3	—	1.91	-158	—
		11/19/24	7.39	1,796	16.5	—	0.24	-67.9	2.0

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)		
Treatment Zone D Injection Wells											
IW-1D	Property, NE quadrant	04/03/18	8.96	591	20.4	–	0.40	-228	–		
		12/13/18	6.72	2,188	13.1	–	0.28	-34	–		
		Decommissioned March 2019									
IW-3D	Property, NE quadrant	04/03/18	7.58	761	21.8	–	0.50	72	–		
		Decommissioned March 2019									
IW-4D	Property, SW quadrant	03/29/18	8.42	407	13.8	–	0.90	90	–		
		Decommissioned March 2019									
IW-6D	Property, SW quadrant	04/03/18	7.73	366	18.1	–	0.40	14	–		
		12/13/18	6.31	2,952	15.1	–	34.30	247	–		
		Decommissioned March 2019									
IW-8D	Property, SW quadrant	04/04/18	7.33	722	20.5	–	0.50	81	–		
		Decommissioned March 2019									
IW-9D	Property, SW quadrant	04/04/18	7.63	505	18.5	–	5.50	86	–		
		Decommissioned March 2019									
IW-11D	Property, NE quadrant	05/01/18	7.96	757	20.9	–	0.60	56	–		
		Decommissioned March 2019									
MW-168	Property, NE quadrant	11/04/19	7.54	649	19.4	1.4	1.68	-93	0.0		
		01/31/20	8.27	639	19.7	0.3	–	-148	0.5		
		05/01/20	7.46	557	16.1	17.4	0.44	-132	0.5		
		07/09/20	8.86	451	17.3	11.3	0.24	-207	1.0		
		11/05/20	8.60	454	16.5	5.7	0.25	-116	–		
		02/04/21	7.69	454	14.5	–	0.21	42	–		
		05/05/21	7.66	743	14.3	0.9	0.43	-199	–		
		08/10/21	7.67	767	17.9	–	0.12	113	–		
		12/02/21	7.32	771	18.3	–	0.47	-153	0.4		
		02/22/22	7.62	852	14.7	–	0.29	-291	–		
		05/13/22	7.53	834	16.4	–	0.25	98	–		
		08/05/22	7.01	650	17.5	–	0.78	87	–		
		10/28/22	7.55	867	18.2	–	0.14	–	0.6		
		05/11/23	7.62	882	16.4	–	0.13	-58.7	–		
		11/02/23	7.64	805	17.4	–	7.64	6	2		
		05/28/24	7.64	537	15.3	–	5.08	7	–		
		11/19/24	7.47	1,104	17.1	–	0.07	0.7	2.0		
		MW-172	Property, SW quadrant	11/05/19	7.65	494	21.2	0.3	1.79	269	–
				01/23/20	7.81	845	17.8	0.7	1.09	-99	0.0
				04/02/20	7.62	537	20.3	7.1	0.34	-155	0.0
				07/09/20	7.70	504	18.8	0.49	0.30	-1	0.2
				11/03/20	7.54	576	18.3	1.2	0.21	-52	–
				02/17/21	7.56	732	14.7	2.1	1.72	-106	–
				05/07/21	7.76	553	14.6	12.0	0.2	102	–
				08/10/21	7.52	656	17.8	–	0.28	-86	–
				11/19/21	7.81	572	16.7	–	0.95	172	0.1
				02/17/22	7.59	669	16.2	–	0.51	-195	–
				05/12/22	7.39	652	17.9	–	0.32	114	–
				08/05/22	7.62	609	18.6	–	0.73	147	–
10/27/22	7.50			660	19.0	–	0.08	–	0.25		
05/11/23	7.60			740	17.3	–	0.15	-44.7	–		
05/24/24	7.41			798	16.6	–	2.54	-63	–		
11/13/24	7.19			973	17.6	–	0.07	74.4	0.6		
MW-176	Property, SE quadrant			11/01/19	7.25	609	20.6	1.4	1.56	-88	0.0
				01/28/20	9.12	789	16.8	0.4	1.42	-62	0.2
				05/01/20	7.57	428	15.5	3.3	0.33	-87	0.5
				07/09/20	7.62	436	17.1	9.14	0.20	-195	2.5
				11/05/20	7.33	1,150	17.2	4.7	0.32	-86	–
				02/04/21	6.98	1,249	17.0	4.0	0.29	-460	–
				05/05/21	7.03	1,400	16.1	6.4	0.25	-187	–
				08/05/21	7.11	1,256	18.9	–	0.51	-154	–
				12/02/21	7.20	1,462	16.6	–	0.72	177	3.5
				02/22/22	7.11	1,461	17.0	–	0.50	-144	–
				05/13/22	7.10	1,523	17.5	–	0.00	-155	–
				08/11/22	7.26	1,693	17.3	–	4.50	-111	–
				10/26/22	6.99	1,570	18.7	–	0.37	-197	4.1
		05/11/23	6.98	1,651	16.9	–	0.04	-102	–		
		11/02/23	7.09	1,453	17.6	–	0.22	16	2.5		
		05/24/24	7.16	1,628	16.8	–	2.07	-123	–		
		11/18/24	6.94	1,886	17.0	–	0.11	66.0	2.8		

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
MW-180	Property, SW quadrant	11/06/19	7.15	1,752	18.1	19.3	0.19	-11	2.5
		01/24/20	6.81	2,104	16.4	—	2.97	-60	1.0
		04/01/20	6.78	1,105	17.2	9.0	1.79	-179	—
		07/10/20	6.85	875	19.0	3.79	0.10	-47	2.5
		11/03/20	6.50	1,001	17.7	1.5	0.20	-161	—
		02/18/21	6.64	1,128	14.4	1.8	0.47	-301	—
		05/06/21	6.53	1,314	15.9	4.8	0.37	119	—
		08/06/21	6.61	1,524	18.3	4.9	1.01	110	—
		12/03/21	6.57	1,539	16.0	—	0.22	167	7.0
		02/17/22	6.63	1,603	15.8	—	0.23	189	—
		05/10/22	6.58	1,741	16.4	—	0.39	-190	—
		08/04/22	6.74	1,323	16.7	—	2.99	-48	—
		10/26/22	6.48	2,096	18.1	—	6.77	—	5.75
		05/10/23	6.44	2,162	16.5	—	0.39	-157	—
		11/01/23	6.49	2,449	17.6	—	1.09	-110	3
		05/24/24	6.44	2,496	16.9	—	2.09	-88	—
		11/12/24	6.31	2,851	17.3	—	0.06	42.1	3.1
MW-184	Property, SW quadrant	11/08/19	7.83	316	17.1	0.1	1.35	229	0.0
		01/27/20	7.75	656	13.7	0.5	0.81	-95	0.3
		04/01/20	7.44	324	18.0	9	0.07	-194	4.1
		07/08/20	7.56	366	18.6	1.7	0.30	14	0.2
		11/04/20	7.64	394	19.4	2.8	0.08	-81	—
		02/19/21	7.28	875	15.4	7.7	1.00	-59	—
		05/06/21	7.70	368	15.6	4.8	0.20	112	—
		08/06/21	7.32	587	18.2	5	0.12	104	—
		11/18/21	7.38	638	16.6	—	0.78	132	0.5
		02/16/22	7.33	692	16.9	—	0.73	-239	—
		05/10/22	7.20	641	17.2	—	0.03	49	—
		08/04/22	6.79	550	17.9	—	0.79	99	—
		10/25/22	7.22	676	18.3	—	0.36	-191	0.02
		05/10/23	7.35	654	17.1	—	0.14	-91	—
		11/02/23	7.54	801	17.8	—	1.41	-85	0.5
		05/23/24	7.72	466	16.4	—	3.63	-126	—
		11/11/24	7.35	361.8	17.1	—	0.26	-105.9	0.6
MW-188	Property, SE quadrant	10/31/19	7.34	657	18.5	0.3	1.92	-21	0.5
		01/29/20	7.02	839	15.4	0.5	1.74	16	0.5
		04/02/20	7.42	499	17.8	5.0	0.13	-223	4.2
		07/08/20	7.49	514	17.9	3.65	0.30	-44	0.8
		11/04/20	7.45	581	18.4	—	0.26	-214	—
		02/16/21	7.40	636	18.7	—	0.16	-417	—
		05/07/21	7.46	696	15.2	—	0.22	119	—
		08/10/21	7.36	692	15.4	3.4	0.13	-174	—
		11/18/21	7.23	523	14.1	—	5.75	19	—
		02/16/22	7.52	666	16.9	—	0.15	201	—
		05/12/22	7.44	676	17.1	—	0.34	-93	—
		08/05/22	7.30	679	18.5	—	0.42	-50	—
		10/26/22	7.18	651	18.7	—	0.60	-165	0.09
		05/11/23	7.42	666	17.1	—	0.10	-58	—
		11/03/23	7.31	676	17.6	—	2.57	84	2.0
		05/24/24	7.36	693	17.0	—	2.16	-147	—
		11/19/24	7.33	723	17.3	—	0.13	-21.2	1.8
Treatment Zone A Perimeter Injection Wells									
PRB-A1	8th Ave N ROW, W side	09/15/20	6.89	886	19.3	112	0.28	-40	2.0
PRB-A5	8th Ave N ROW, W side	09/17/20	6.67	1,167	12.1	234	0.28	129	3.8
PRB-A11	8th Ave N ROW, W side	09/16/20	6.90	640	17.6	66	0.30	196	1.8
PRB-A14	Roy Street ROW, N side	09/17/20	7.21	865	19.0	60	0.51	33	—
PRB-A17	Roy St ROW, N side	09/15/20	7.00	694	19.5	44	0.54	128	2.6
PRB-A19	Roy St ROW, N side	09/14/20	7.13	601	19.3	83	0.53	31	3.5
PRB-A23	Roy St ROW, N side	09/14/20	6.80	808	18.3	652	0.26	140	3.2
Treatment Zone B Perimeter Injection Wells									
PRB-B1	8th Ave N ROW, W side	09/15/20	6.70	686	19.4	21	0.31	709	1.4
PRB-B4	8th Ave N ROW, W side	09/17/20	6.94	1,480	21.3	49	0.25	-87	5.5
PRB-B11	8th Ave N ROW, W side	09/16/20	7.13	1,245	17.6	19	0.58	140	1.8
PRB-B14	Roy St ROW, N side	09/14/20	7.93	1,029	18.1	41	0.35	143	0.6
PRB-B17	Roy St ROW, N side	09/15/20	8.36	745	22.3	20	0.56	-14	0.0
PRB-B19	Roy St ROW, N side	09/18/20	7.74	612	19.7	135	0.89	141	0.4
PRB-B23	Roy St ROW, N side	09/18/20	7.96	1,023	19.2	203	0.74	148	0.4

Table 2
Groundwater Field Parameters, 2017 through 2024
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Property	Sample Date	pH	Specific Conductance (mS/cm)	Temperature (°C)	Turbidity (NTUs)	Dissolved Oxygen (mg/L)	ORP (mv)	Ferrous Iron (mg/L)
Treatment Zone C Perimeter Injection Wells									
PRB-C1	8th Ave N ROW, W side	09/15/20	7.68	606	19.2	63	0.71	134	0.0
PRB-C5	8th Ave N ROW, W side	09/17/20	7.09	1,264	21.1	367	0.26	132	1.6
PRB-C11	8th Ave N ROW, W side	09/16/20	7.37	571	18.4	687	0.64	135	0.4
PRB-C14	Roy Street ROW, N side	09/17/20	7.95	721	18.7	467	0.87	752	0.4
PRB-C17	Roy St ROW, N side	09/15/20	9.50	631	22.7	1,000	0.65	124	0.4
PRB-C19	Roy St ROW, N side	09/14/20	7.73	442	19.1	155	0.38	133	0.0
PRB-C23	Roy St ROW, N side	09/14/20	8.20	728	19.0	1,000	0.42	298	0.6
Treatment Zone D Perimeter Injection Wells									
PRB-D1	8th Ave N ROW, W side	09/15/20	7.64	630	21.0	100	0.66	-20	0.0
PRB-D4	8th Ave N ROW, W side	09/17/20	6.98	1,512	23.1	98	0.48	-30	5.0
PRB-D11	8th Ave N ROW, W side	09/16/20	7.67	701	17.6	21	0.55	925	0.6
PRB-D13	Roy St ROW, N side	09/18/20	7.41	717	19.1	232	0.63	66	–
PRB-D17	Roy St ROW, N side	09/21/20	6.55	669	19.1	121	0.60	171	1.1
PRB-D20	Roy St ROW, N side	09/18/20	7.02	547	19.5	351	0.57	120	0.4
PRB-D23	Roy St ROW, N side	09/18/20	7.91	441	19.0	228	0.45	0	–

Notes:

1. – = not measured
2. ^(a) = pH meter not giving stable/reliable reading
3. ^(b) = Turbidity reading collected and read with a turbidimeter after water sample collection.
4. ^(c) = Readings collected by Farrallon
5. ^(d) = DO meter malfunction
6. MAX = Turbidity greater than instrument upper detection limit.

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC	
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Groundwater Screening Level for Soil Vapor					—		—		—		2.4		15,000		1,200		320		24		1.4		—		77		0.35	
DMW-1S (38.8 to 28.8)	615 Dexter, SE quadrant	03-25-19	HC	—	350		200 U		500 U		1.50		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		0.20 U	
		03-25-19	HC	—	300		200 U		500 U		1.80		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		1.0 U		0.20 U	
		03-18-20	HC	Peristaltic	1,800		580 J		250 U		2.90		1.6		12		1.8		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
DMW-2S (30.7 to 20.7)	615 Dexter, SE quadrant	03-18-20	HC	Peristaltic	100 U		50 U		250 U		0.200 U		0.20 U		0.20 U		0.40 U		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
DMW-4S (38.5 to 28.5)	Alley S of SE quadrant of 615 Dexter	03-19-20	HC	Peristaltic	670		790 J		250 U		0.200 U		0.26		5.5		3.0		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
DMW-5IA (29.4 to 19.4)	Alley S of 615 Dexter	03-19-20	HC	Submersible	100 U		760 J		250 U		0.200 U		0.64		0.20 U		0.40 U		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
DMW-6 (32.1 to 22.1)	615 Dexter, NE quadrant	03-18-20	HC	Submersible	100 U		50 U		250 U		0.200 U		0.20 U		0.20 U		0.40 U		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
F5 (29.1 to -1.0)	Property, NW quadrant	07-19-13	SES	Peristaltic	—		—		—		—		—		—		—		1,20,000		50		700		5.2		4.2	
		10-24-13	SES	Peristaltic	—		—		—		—		—		—		—		21,000		1,200		1,000		1,000		200 U	
		03-28-17	PES	Peristaltic	234 zJ+		—		—		0.515		0.727 U		0.158 U		0.316 U		0.199 U		0.241 J		516		4.31		90.6	
		06-22-17	PES	Peristaltic	31.6 U		—		—		0.374 J		0.708		0.158 U		0.316 U		0.199 U		0.485		10.4		0.485 J		63.9	
		Decommissioned March 2019																										
F9 (28.5 to -1.5)	Property, NE quadrant	07-19-13	SES	Peristaltic	—		—		—		—		—		—		—		1,40,000		3,400		50		8.6		78	
		06-16-15	SES	Peristaltic	—		—		—		—		—		—		—		3.7		1.8		680		12		74	
		10-19-15	SES	Peristaltic	—		—		—		—		—		—		—		15.0		6.6		840		13		75	
		02-01-16	SES	Peristaltic	—		—		—		—		—		—		—		2.9		1 U		1.3		1 U		20	
		03-27-17	PES	Peristaltic	31.6 U		—		—		0.529		2.04		0.158 U		0.316 U		0.199 U		0.153 U		0.158 J		0.539		0.118 U	
		06-22-17	PES	Peristaltic	31.6 U		—		—		0.471 J		1.70		0.158 U		0.316 U		0.199 U		0.153 U		6.10		0.485		3.57	
		Decommissioned March 2019																										
F13 (28.4 to -1.6)	Property, NE quadrant	07-19-13	SES	Peristaltic	—		—		—		—		—		—		—		2,900		280		370		100 U		49	
		10-24-13	SES	Peristaltic	—		—		—		—		—		—		—		7,300		3,100		490		50 U		10 U	
		11-18-13	SES	Peristaltic	—		—		—		—		—		—		—		67,000		6,600		3,200		85		48	
		12-12-13	SES	Peristaltic	—		—		—		—		—		—		—		50		340		670		10 U		20	
		03-07-14	SES	Peristaltic	—		—		—		—		—		—		—		84		11		10		1 U		0.36	
		06-16-15	SES	Peristaltic	—		—		—		—		—		—		—		8.4		1 U		1.8		1 U		0.31	
		10-19-15	SES	Peristaltic	—		—		—		—		—		—		—		1 U		2.0		210		2.3		4.1	
		02-02-16	SES	Peristaltic	—		—		—		—		—		—		—		3.4		1 U		1 U		1 U		0.97	
		03-27-17	PES	Peristaltic	31.6 U		—		—		0.0896 U		0.412 U		0.158 U		0.316 U		0.199 U		0.153 U		0.218 J		0.152 U		0.936	
		06-22-17	PES	Peristaltic	31.6 U		—		—		0.0896 U		0.412 U		0.158 U		0.316 U		0.199 U		0.153 U		0.194 J		0.152 U		1.32	
		04-05-18	PES	Peristaltic	31.6 U		—		—		0.0896 U		0.412 U		0.158 U		0.316 U		20.3		0.346 J		0.375 J		0.152 U		0.843	
		Decommissioned March 2019																										
FMW-1	900 Roy St, S end	11-02-22	PES	Peristaltic	—		—		—		0.0160 U		0.0500 U		0.0212 U		0.191 U		0.0280 U		0.0160 U		0.0276 U		0.0572 U		0.0273 U	
FMW-143 (10.0 to 5.0)	9th Ave N ROW, E side	07-30-19	Farallon	Unknown	—		—		—		—		—		—		—		0.20 U		0.20 U		0.20 U		0.20 U		0.20 U	
		10-31-19	PES	Peristaltic	—		—		—		0.0896 U		0.412 U		0.158 U		0.316 U		0.199 U		0.153 U		0.0933 U		0.152 U		0.118 U	
		01-22-20	PES	Peristaltic	—		—		—		0.0896 U		0.412 U		0.158 U		0.316 U		0.199 U		0.153 U		0.0933 U		0.152 U		0.118 U	
		05-14-20	PES	Bladder	—		—		—		0.0941 U		0.319 J		0.137 U		0.201 J		0.300 U		0.190 U		0.126 U		0.149 U		0.234 U	
		07-22-20	PES	Bladder	—		—		—		0.0160 U		0.146 J		0.0490 J		0.331		0.0280 U		0.0160 U		0.0276 U		0.0572 U		0.0273 U	

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE	TCE	cDCE	tDCE	VC					
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Groundwater Screening Level for Soil Vapor					—		—		—		2.4		15,000		1,200		320		24		1.4		—		77		0.35	
G12 (29.4 to -0.6)	Property, NE quadrant	07-19-13	SES	Peristaltic	—		—		—		—		—		—		—		64,000		3,100		9,200		88		130	
		10-24-13	SES	Peristaltic	—		—		—		—		—		—		—		1,700		150		100	U	100	U	20	U
		11-18-13	SES	Peristaltic	—		—		—		—		—		—		—		760		84		42		10	U	2	U
		03-27-17	PES	Peristaltic	—		—		0.243	J	0.412	U	0.158	U	0.316	U	0.199	U	0.233	J	95.9		1.97		28.4			
		06-30-17	PES	Peristaltic	—		—		0.282	J	0.412	U	0.158	U	0.316	U	0.199	U	0.323	J	115		2.94		31.5			
		Decommissioned March 2019																										
G-MW2 (31 to 21)	Property	07-24-01	GeoE	Peristaltic	—		—		0.375		48.3	E	2.01		12.88		1,76,000		237	g	129	g	1.02		0.457			
		01-29-09	DOF	Peristaltic	39,600	qp	—		20.0	U	20.0	U	20.0	U	48.9		59,000	f	210		373		1.33		0.200	U		
		06-02-11	SES	Peristaltic	59,000	xy	200		250	U	350	U	1,000	U	1,000	U	3,000	U	1,50,000		1,000	U	1,000	U	1,000	U	200	U
		09-06-12	SES	Peristaltic	—		—		0.350	U	12		1.1		4.7		1,50,000		320		260		1.4		0.2	U		
		Decommissioned																										
HMW-1S (16.0 to 6.0)	Seattle DOT Mercer Parcels, NE quadrant	03-25-19	HC	Peristaltic	100	U	—		—		1.00	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	0.2	U
		03-11-20	HC	Peristaltic	100	U	200	J	250	U	0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-2S (27.6 to 17.6)	Seattle DOT Mercer Parcels, NE quadrant	03-25-19	HC	Peristaltic	100	U	—		—		1.00	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	0.2	U
		03-12-20	HC	Peristaltic	100	U	56	J	260	U	0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-9S (30.4 to 20.4)	Seattle DOT Mercer Parcels, SW quadrant	03-17-20	HC	Submersible	100	U	61	J	250	U	0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-10S (23.5 to 13.5)	Seattle DOT Mercer Parcels, SE quadrant	03-16-20	HC	Submersible	100	U	66	J	250	U	0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-11S (16.5 to 6.5)	Seattle DOT Mercer Parcels, SE quadrant	03-11-20	HC	Submersible	100	U	620	J	250	U	0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-17S (22.2 to 12.2)	Seattle DOT Mercer Parcels, NW quadrant	09-17-20	HC	—	100	U	50	U	—		0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-18S (22.6 to 12.6)	Seattle DOT Mercer Parcels, NW quadrant	09-17-20	HC	—	100	U	50	U	—		0.200	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-19S (23.2 to 13.2)	Seattle DOT Mercer Parcels, NW quadrant	09-17-20	HC	—	170		50	U	—		0.200	U	0.20	U	0.20	U	0.60		0.20	U	0.20	U	0.20	U	0.20	U	0.20	U
HMW-20S (28.8 to 18.8)	aaaaaaa NW quadrant	09-18-20	HC	—	100	U	50	U	—		0.200	U	0.20	U	0.20	U	0.40	U	4.7		0.38		1.4		0.20	U	0.99	
HMW-21S (8.2 to -1.8)	Seattle DOT Mercer Parcels, SE quadrant	11-03-20	HC	—	—		50	U	—		—		—		—		—		—		—		—		—		—	
HMW-22S (11.8 to 1.8)	Seattle DOT Mercer Parcels, SE quadrant	11-03-20	HC	—	—		62	U	—		—		—		—		—		—		—		—		—		—	
J5 (29.8 to -0.2)	Property, SW quadrant	07-19-13	SES	Peristaltic	—		—		—		—		—		—		—		46,000		660		100	U	100	U	20	U
		10-24-13	SES	Peristaltic	—		—		—		—		—		—		—		48,000		13,000		1,400		100	U	20	U
		06-16-15	SES	Peristaltic	—		—		—		—		—		—		—		50		340		250		51		1.0	
		10-19-15	SES	Peristaltic	—		—		—		—		—		—		—		1,400		470		890		51		1.3	
		02-02-16	SES	Peristaltic	—		—		—		—		—		—		—		1,500		5		280		14		0.31	
		03-21-17	PES	Peristaltic	—		—		0.580		0.412	U	0.158	U	0.316	U	0.199	U	285		78.5		253		1.73		29.6	
		06-26-17	PES	Peristaltic	—		—		0.252	J	0.506		0.158	U	0.316	U	0.199	U	36.1		37.1		366		1.94		77.7	
		04-05-18	PES	Peristaltic	207		—		0.638		0.412	U	0.158	U	0.316	U	0.199	U	267		70.5		222		1.00		17.6	
		Decommissioned March 2019																										

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC	
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Groundwater Screening Level for Soil Vapor					—		—		—		2.4		15,000		1,200		320		24		1.4		—		77		0.35	
J15 (28.7 to -1.3)	Property, SE quadrant	07-19-13	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	4,100	220	580	6.8	20						
		10-24-13	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	10,000	50	680	100	20						
		03-07-14	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	2,200	170	120	50	10						
		06-16-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	9.0	12	310	8.8	3.1						
		10-19-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	3.6	1	5	3.0	1.7						
		02-02-16	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	—	2.4	1	35	1	0.39						
		03-27-17	PES	Peristaltic	—	—	—	0.188	J	0.495	J	0.158	U	0.316	U	0.199	U	0.153	U	43.3	1.18	6.99						
		06-26-17	PES	Peristaltic	—	—	—	0.173	J	0.459	J	0.158	U	0.316	U	0.199	U	0.153	U	39.8	1.06	6.30						
		06-26-17	PES	Peristaltic	—	—	—	0.173	J	0.551		0.158	U	0.316	U	0.199	U	0.153	U	39.3	1.03	6.73						
		04-05-18	PES	Peristaltic	41.2	J	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	12.8	0.358	J	26.3	0.709	6.07						
Decommissioned March 2019																												
K8 (29.9 to -0.1)	Property, SW quadrant	07-19-13	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	8,700	330	1,400	5.6	6.3							
		06-17-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	63	16	500	67	2							
		10-19-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	360	82	43	3.2	0.44							
		02-01-16	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	250	44	82	1.8	0.31							
		03-21-17	PES	Peristaltic	—	—	—	0.239	J	0.412	U	0.158	U	0.316	U	82.5	22.0	123	0.680	0.461	J							
		06-26-17	PES	Peristaltic	—	—	—	0.246	J	0.412	U	0.158	U	0.316	U	67.9	28.7	140	0.750	0.456	J							
		04-05-18	PES	Peristaltic	156	zJ+	—	—	0.251	J	0.412	U	0.158	U	0.316	U	229	26.3	104	0.750	1.45							
Decommissioned March 2019																												
M15 (29.5 to -0.5)	Property, SE quadrant	07-19-13	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	3,200	5	180	1.7	0.22							
		10-24-13	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	56,000	50	770	50	10							
		03-07-14	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	2,100	190	290	2.9	2.60							
		06-16-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	58	44	76	2.7	1.1							
		10-19-15	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	48	29	5	2.3	0.74							
		02-02-16	SES	Peristaltic	—	—	—	—	—	—	—	—	—	—	—	—	11	10	84	1.8	0.39							
		03-27-17	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.733	32.7	0.561	13.2							
		03-27-17	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.670	31.7	0.513	12.0							
		06-26-17	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.233	J	1.80	25.8	0.523	15.0							
		04-05-18	PES	Peristaltic	31.6	U	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.563	8.89	0.300	J						
Decommissioned March 2019																												
MW-1 (--)	800 Aloha St Parcel	03-22-93	EPJ	Bailer	5,100	500	U	1000	U	10,000	270	480	427	—	—	—	—	—	—	—	—	—	—	—	—			
		06-17-93	Retec	Unknown	—	—	—	20,000	14,000	840	6,700	—	—	—	—	—	—	—	—	—	—	—	—	—				
Decommissioned October 1993																												
MW-2 (--)	8th Ave North ROW	03-22-93	EPJ	Bailer	650	500	U	1000	U	100	42	24	67	—	—	—	—	—	—	—	—	—	—	—	—			
		06-17-93	Retec	Unknown	—	—	—	28	7.2	1	U	2	U	170	1,400	9,300	25	50										
Decommissioned October 1993																												
MW-3 (--)	800 Aloha St Parcel	03-22-93	EPJ	Bailer	27,000	500	U	1000	U	1,500	3,300	690	3,500	—	—	—	—	—	—	—	—	—	—	—	—			
		06-17-93	Retec	Unknown	—	—	—	4,800	21,000	1,900	12,300	—	—	—	—	—	—	—	—	—	—	—	—	—				
Decommissioned October 1993																												
MW-4 (--)	Seattle Roy Aloha Shops, N end	03-22-93	EPJ	Bailer	940	500	U	1000	U	82	390	39	108	—	—	—	—	—	—	—	—	—	—	—	—			
		06-17-93	Retec	Unknown	—	—	—	1	U	1	U	1	U	2	U	—	—	—	—	—	—	—	—	—				
Decommissioned October 1993																												

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)											
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29
Groundwater Screening Level for Soil Vapor					—	—	—	2.4	15,000	1,200	320	24	1.4	—	77	0.35
MW-5 (--)	8th Ave North ROW	03-22-93 06-17-93 Decommissioned October 1993	EPJ Retec Unknown	Bailer Unknown	670 —	500 U —	1000 U —	49 1 U	140 1 U	9.8 1 U	80 2 U	— —	— —	— —	— —	— —
MW-6 (31.2 to 16.2)	Seattle Roy Aloha Shops, N end	10-12-93	Retec	Unknown	1,50,000	—	—	9,100	6,800	2,600	7,300	—	—	—	—	—
		10-26-93	Retec	Unknown	1,00,000	—	—	17,000	14,000	1,400	500	—	—	—	—	—
		01-25-94	Retec	Unknown	66,000	—	—	8,800	4,600	1,500	8,100	—	—	—	—	—
		04-25-94	Retec	Unknown	1,20,000	—	—	15,000	7,200	2,600	13,300	—	—	—	—	—
		09-15-94	Retec	Unknown	56,000	—	—	15,000	2,000	1,500	7,100	—	—	—	—	—
		06-20-02	Urban	Unknown	8,500	—	—	1,900	14	250	53	—	—	—	—	—
MW-7 (26.1 to 16.1) (duplicate)	Seattle Roy Aloha Shops, N end	10-12-93	Retec	Unknown	75,000	—	—	20,000	22,000	3,000	15,000	—	—	—	—	—
		10-26-93	Retec	Unknown	74,000	—	—	8,300	7,400	50	8,300	—	—	—	—	—
		01-25-94	Retec	Unknown	53,000	—	—	1,600	2,700	1,400	5,100	—	—	—	—	—
		04-25-94	Retec	Unknown	1,40,000	—	—	3,900	7,400	3,100	14,100	—	—	—	—	—
		09-15-94	Retec	Unknown	66,000	—	—	3,400	2,700	1,900	7,700	—	—	—	—	—
		09-15-94	Retec	Unknown	77,000	—	—	3,600	3,000	2,100	8,700	—	—	—	—	—
		06-20-02	Urban	Unknown	8,400	—	—	650	37	470	150	—	—	—	—	—
		MW-8 (28.7 to 14.2) (duplicate) (duplicate)	Seattle Roy Aloha Shops, N end	10-26-93	Retec	Unknown	280	—	—	19	1	1 U	48	—	—	—
01-25-94	Retec			Unknown	230 J	—	—	13	0.7 J	1 U	4.5	—	—	—	—	—
01-25-94	Retec			Unknown	210 J	—	—	12	0.6 J	1 U	3.7	—	—	—	—	—
04-25-94	Retec			Unknown	250 U	—	—	2.2	1 U	1 U	1.7	—	—	—	—	—
09-15-94	Retec			Unknown	210 J	—	—	1 U	0.5 J	1 U	1.6 J	—	—	—	—	—
09-15-94	Retec			Unknown	250	—	—	1 U	0.5 J	1 U	1.7 J	—	—	—	—	—
06-21-02	Urban			Unknown	50 U	—	—	1 U	1 U	1 U	1 U	—	—	—	—	—
03-20-17	PES			Peristaltic	—	—	—	0.145 J	0.412 U	0.175 J	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U
04-13-18	PES			Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.570	0.153 U	0.0933 U	0.152 U	0.118 U
07-18-19	PES			Peristaltic	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U
10-10-19	PES			Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.167 J	0.0933 U	0.152 U	0.118 U
01-16-20	PES			Peristaltic	—	—	—	0.156 J	1.96	0.158 U	0.569 J	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U
05-06-20	PES			Peristaltic	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U
07-14-20	PES			Peristaltic	—	—	—	0.0160 U	0.161 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U
MW-9 (34.1 to 19.1) (duplicate)	8th Ave N ROW, E side			10-26-93	Retec	Unknown	210 J	—	—	9.5	1.3	1 U	2 U	—	—	—
		01-25-94	Retec	Unknown	250 U	—	—	5.7	1.1	1 U	2 U	—	—	—	—	—
		04-25-94	Retec	Unknown	250 U	—	—	0.001 U	1 U	1 U	2 U	—	—	—	—	—
		09-15-94	Retec	Unknown	250 U	—	—	3.50	0.6 J	1 U	2 U	—	—	—	—	—
		06-20-02	Urban	Unknown	50 U	—	—	1 U	1 U	1 U	2 U	1 U	1 U	1 U	1 U	1 U
		06-02-11	SES	Peristaltic	100 U	150 x	250 U	1.00 U	1 U	1 U	3 U	—	—	—	—	—
		09-04-12	SES	Peristaltic	—	—	—	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.61
		12-16-13	SES	Peristaltic	100 U	50 U	250 U	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U
		03-20-17	PES	Peristaltic	52.8 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.140 J	0.152 U	0.324 J
		06-20-17	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.562	0.158 U	0.316 U	0.199 U	0.153 U	0.214 J	0.152 U	0.118 U
		06-20-17	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.548	0.158 U	0.316 U	0.199 U	0.153 U	0.211 J	0.152 U	0.118 U
		04-05-18	PES	Peristaltic	32.9 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	1.58	0.153 U	0.246 J	0.152 U	0.210 J
		01-21-19	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC	
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29	
Groundwater Screening Level for Soil Vapor					—	—	—	2.4	15,000	1,200	320	24	1.4	—	77	0.35	
MW-337 (18.1 to 8.1)	Lake Union Park, N end	05-07-20	PES	Peristaltic	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U	
		07-23-20	PES	Peristaltic	—	—	—	0.0160 U	0.145 J	0.0212 U	0.191 U	0.0280 U	0.0260 J	0.0560 J	0.0572 U	0.0273 U	
		11-10-20	PES	Peristaltic	—	—	—	0.0190 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0870 J	0.0572 U	0.0273 U	
		05-04-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0490 J	0.0572 U	0.0670 J	
		11-17-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.118	0.0940	0.0276 U	0.0572 U	0.0273 U	
		05-03-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0530	0.0290 J	0.0572 U	0.0273 U	
		11-02-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.112	0.0572 U	0.0273 U	
MW-339 (duplicate) (18.2 to 8.2) (duplicate)	Lake Union Park, S end	05-14-20	PES	Peristaltic	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U	
		05-14-20	PES	Peristaltic	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U	
		07-23-20	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0280 J	0.164	0.0572 U	0.0273 U	
		11-09-20	PES	Peristaltic	—	—	—	0.0190 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.238	0.0572 U	0.0273 U	
		05-25-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.120	0.0572 U	0.0273 U	
		11-10-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0400 J	0.0572 U	0.0273 U	
		11-10-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0430 J	0.0572 U	0.0273 U	
		05-04-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
N7 (41.8 to 11.8)	Property, SW quadrant	07-19-13	SES	Peristaltic	—	—	—	—	—	—	—	640	50	18	1 U	0.2 U	
		10-19-15	SES	Peristaltic	—	—	—	—	—	—	—	2,900	99	9.9	1 U	0.2 U	
		02-02-16	SES	Peristaltic	—	—	—	—	—	—	—	230	79	1,700	2.9	0.92	
		03-30-17	PES	Peristaltic	—	—	—	0.178 J	0.412 U	0.158 U	0.316 U	280	50.4	125	0.396 J	0.310 J	
		06-27-17	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	205	85.1	153	0.955	0.386 J	
		Decommissioned March 2019															
R-MW1 (33.8 to 23.8)	Property	10-24-92	Roux	Unknown	57	1,345	6,000	1	1	0.5 U	0.5 U	5 U	5 U	—	5 U	100	
		10-24-92	DOF	Unknown	53	26,000	12,000	0.61	0.83	0.50 U	1.0 U	4.2	0.82	12.0 c	—	170	
		10-24-92	Roux	Unknown	54	290	5,000	0.58	1	0.5 U	0.5 U	2.3	2 U	14	—	140	
		01-29-09	DOF	Peristaltic	50.0 U	—	—	0.500 U	0.500 U	0.500 U	1.00 U	17.1	4.26	1.60	0.200 U	0.630	
		06-02-11	SES	Peristaltic	100 U	1,000 x	740	0.350 U	1 U	1 U	3 U	7.9	2.7	1.9	1 U	0.68	
		09-05-12	SES	Peristaltic	—	—	—	0.350 U	1 U	1 U	3 U	16	3.6	2.1	1 U	2.20	
R-MW2 (36.7 to 26.7)	Property, NE quadrant	10-24-92	Roux	Unknown	4,200	34	2,000	684	17	301	403	5 U	5 U	—	5 U	5 U	
		10-24-92	DOF	Unknown	4,000	16,000	25,000	310	0.50 U	140	180	—	—	—	—	—	
		01-29-09	DOF	Peristaltic	657	—	—	0.500 U	0.557	0.513	2.08	5.05	0.200 U	0.200 U	0.200 U	0.200 U	
		06-02-11	SES	Peristaltic	1,700	3,100	290 x	19	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U	
		09-04-12	SES	Peristaltic	—	—	—	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U	
		03-21-17	PES	Peristaltic	—	—	—	0.272 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.341 J	0.152 U	0.522	
		06-15-17	PES	Peristaltic	—	—	—	0.694	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.682	0.152 U	0.609	
		04-02-18	PES	Peristaltic	38.0 U	—	—	0.568	0.412 U	0.158 U	0.316 U	0.866	0.620	2.48	0.152 U	1.33	
Decommissioned March 2019																	

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC					
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29					
Groundwater Screening Level for Soil Vapor					—	—	—	2.4	15,000	1,200	320	24	1.4	—	77	0.35					
R-MW3 (34.7 to 24.7)	Property, NE quadrant	10-24-92	Roux	Unknown	87	3,015	1,200	0.5 U	0.5 U	0.5 U	0.5 U	5 U	5 U	—	5 U	5 U					
		10-24-92	DOF	Unknown	50 U	—	—	0.50 U	0.50 U	0.50 U	1.0 U	—	—	—	—	—					
		01-29-09	DOF	Peristaltic	50.0 U	—	—	0.500 U	0.500 U	0.500 U	1.00 U	4.26	0.200 U	0.200 U	0.200 U	0.200 U					
		06-02-11	SES	Peristaltic	100 U	240 x	250 U	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U					
		09-04-12	SES	Peristaltic	—	—	—	0.350 U	1 U	1 U	3 U	6.4	1 U	1 U	1 U	0.2 U					
		03-21-17	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	1.38	0.714	0.575	0.152 U	0.118 U					
		06-28-17	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.834	0.582	0.735	0.152 U	0.424 J					
		04-04-18	PES	Peristaltic	33.7 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	16.4	0.972	1.35	0.152 U	0.214 J					
Decommissioned March 2019																					
R-MW4 (25.9 to 10.9)	Roy St ROW	10-24-92	Roux	Unknown	410	201	1000 U	0.5 U	2	1	4	814	64	—	5 U	5 U					
		10-24-92	DOF	Unknown	640	—	—	0.5 U	1.8	0.5 U	3.1	31	2.8	2.0 U	—	2.0 U					
Decommissioned before 2009																					
R-MW5 (42.4 to 27.4)	Dexter Ave N ROW, E side	10-28-92	Roux	Unknown	93	86	1000 U	0.5 U	1	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	—	0.5 U					
		01-29-09	DOF	Peristaltic	50 U	—	—	0.500 U	0.500 U	0.500 U	1.00 U	0.800	0.200 U	0.200 U	0.200 U	0.200 U					
		06-02-11	SES	Peristaltic	100 U	50 U	250 U	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U					
		09-05-12	SES	Peristaltic	—	—	—	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U					
		12-18-13	SES	Peristaltic	100 U	50 U	250 U	0.350 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U					
		03-23-17	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.338 J	0.186 J	0.0933 U	0.152 U	0.118 U					
		06-16-17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.257 J	0.245 J	0.0933 U	0.152 U	0.118 U					
		04-11-18	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.621	0.153 U	0.0933 U	0.152 U	0.118 U					
		01-03-19	PES	Peristaltic	81.5 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.477 J	0.153 U	0.0933 U	0.152 U	0.118 U					
		04-22-19	PES	Peristaltic	31.6 U	—	—	0.0896 U	0.428 J	0.158 U	0.316 U	0.499 J	0.155 J	0.0933 U	0.152 U	0.118 U					
		07-16-19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.736	0.153 U	0.131 J	0.152 U	0.118 U					
		10-21-19	PES	Bladder	95.3 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.523	0.153 U	0.302 J	0.152 U	0.118 U					
		01-24-20	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.931	0.374 J	0.265 J	0.152 U	0.118 U					
		11-18-20	PES	Bladder	43.8 U	—	—	0.0160 U	0.205	0.0212 U	0.191 U	0.607	0.318	0.505	0.0572 U	0.0273 U					
		02-11-21	PES	Bladder	31.6 U	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.741	0.271	0.357	0.0572 U	0.0273 U					
		02-11-21	PES	Bladder	45.1 J	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.990	0.286	0.382	0.0572 U	0.0273 U					
		05-17-21	PES	Bladder	31.6 U	—	—	0.0160 U	0.147 J	0.0212 U	0.191 U	0.671	0.232	0.186	0.0572 U	0.0273 U					
		08-03-21	PES	Bladder	31.6 U	—	—	0.0290 J	0.565	0.0830 J	0.547	0.512	0.308	0.226	0.0572 U	0.0273 U					
		08-03-21	PES	Bladder	31.6 U	—	—	0.0350 J	0.561	0.0630 J	0.545	0.571	0.312	0.306	0.0572 U	0.0273 U					
		11-08-21	PES	Peristaltic	31.6 U	—	—	0.0190 J	0.178 J	0.0320 J	0.271	0.661	0.265	0.389	0.0572 U	0.0273 U					
		02-24-22	PES	Bladder	36.2 U	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.569	0.266	0.198 J	0.0572 U	0.0273 U					
		02-24-22	PES	Bladder	34.8 U	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.650	0.301	0.324 J	0.0572 U	0.0273 U					
		05-17-22	PES	Bladder	31.6 U	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.321	0.188	0.253	0.0572 U	0.0273 U					
		08-09-22	PES	Bladder	31.6 U	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.173	0.109	0.174	0.0572 U	0.0273 U					
		11-08-22	PES	Bladder	32.6 U	—	—	0.0160 U	0.0580 J	0.0212 U	0.191 U	0.515 J+	0.314 J+	0.297	0.0572 U	0.0273 U					
		10-31-23	PES	Bladder	—	—	—	0.0380 J	0.411	0.124	0.731	0.208	0.132	0.237	0.0572 U	0.0273 U					
		11-13-24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.483	0.280	0.190	0.0572 U	0.0273 U					

Table 3
Petroleum Hydrocarbons and CVOCs in Shallow Zone Groundwater
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC	
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29	
Groundwater Screening Level for Soil Vapor					–	–	–	2.4	15,000	1,200	320	24	1.4	–	77	0.35	
SCS-2 (28.2 to 18.2)	Seattle Roy Aloha Shops, N end	03-20-17	PES	Peristaltic	1,660	–	–	51.8	9.54	155	181	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		06-12-17	PES	Peristaltic	901	–	–	58.9	4.49	141	70.4	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
(duplicate)		04-13-18	PES	Peristaltic	–	–	–	44.3	5.18	37.3	47.7	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		07-18-19	PES	Peristaltic	2,190 J+	–	–	15.5	3.71	141	149	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		07-18-19	PES	Peristaltic	2,320 J+	–	–	15.0	3.37	187	131	0.199 U	0.153 U	0.0933 U	0.152 U	0.242 J	
		10-10-19	PES	Peristaltic	–	–	–	20.3	6.00	307	123	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		01-16-20	PES	Peristaltic	–	–	–	16.9	5.00 J	135	32.2	1.99 U	1.53 U	0.933 U	1.52 U	1.18 U	
Number of Analytes Measured					185	18	12	330	330	330	330	331	331	331	331	331	
Number of Analytes Detected					56	8	0	110	101	62	67	114	118	190	48	113	
Frequency of Detection					30%	44%	0%	33%	31%	19%	20%	34%	36%	57%	15%	34%	
Maximum Detection					1,50,000	790 J	–	257	16.3	307	181	285	85.1	516	4.31	90.6	
Minimum Detection					31.6 U	50.0 U	250 U	0.0160 U	0.0500 U	0.0212 U	0.1740 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
Number of Analytes Detected Above PCUL					4	4	0	24	0	0	0	42	31	28	0	88	
Frequency of Detection Above PCUL					2%	22%	0%	7%	0%	0%	0%	13%	9%	8%	0%	27%	

Notes:
PCULs and Screening Levels from Washington State Department of Ecology, Memorandum from P. Tomlinson to TCP File for American Linen Supply Co. Dexter Ave. (FSID 3573, CSID 12004) re: Development of site-specific preliminary cleanup levels, December 14, 2021.
Detections above the groundwater PCUL level are shown in **bold and highlighted in gray**.
Detections above the groundwater screening level for soil vapor are shown in **bold and highlighted in orange**.
Detections above the groundwater PCUL and screening level for soil vapor are shown in **bold highlighted in cyan**.
cDCE = cis-1,2-Dichloroethene
DOF = Dalton, Olmsted & Fuglevand, Inc.
DRO = Diesel-range organics
(duplicate) = field duplicate
EPJ = EP Johnson Construction Inc. and Environmental
GeoE = GeoEngineers, Inc.
GRO = Gasoline-range organics
HC = Hart Crowser
ORO = Oil-range organics
PCE = Perchloroethylene (tetrachloroethene)
Retec = Remediation Technologies, Inc.
Roux = Roux Associates
ROW = Right of way
SES = SoundEarth Strategies, Inc.
TCE = Trichloroethene
tDCE = trans-1,2-Dichloroethene
Urban = Urban Redevelopment LLC
VC = Vinyl chloride
Well screen elevations indicated below Sample Location in parentheses.
(--) = Well screen elevation unknown.

Laboratory and Results Notes:
Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID, NWTPH-Gx, NWTPH-Dx, or 8015-M.
VOCs analyzed by EPA Method 601, 8010S, 8015, 8020, 8021B, 8240, 8260B, 8260C, or 8260D, or by Purge and Trap Gas Chromatogram/Mass Spectrometry.
– = Not analyzed or results not available.
B = The same analyte is found in the associated blank.
c = Reported as total 1,2,-DCE (sum of cis,-1,2- and trans,1-2-DCE isomers).
E = Estimated value. The reported range exceeds the calibration range of the analysis.
f = Analyte was detected in the associated method blank. Analyte concentration in the sample is greater than 10x the concentration found in the method blank.
g = Estimated value. The reported range exceeds the calibration range of the analysis.
J = The identification of the analyte is acceptable; the reported value is an estimate.
J+ = The result is an estimated quantity, but the result may be biased high.
J- = The result is an estimated quantity, but the result may be biased low.
qp = Hydrocarbon result partly due to individual peak(s) in quantitation range.
U = Not detected at or above the laboratory method detection limit (MDL).
x = The sample chromatographic pattern does not resemble the fuel standard used for quantitation.
y = The GRO result in the sample is due to a pattern of peaks that is consistent with the chlorinated volatiles detected by the 8260C analysis.
z = No/low level gasoline/petroleum detection; result is likely elevated due to high detections of CVOCs.
Groundwater statistics are for data collected during the Remediation Investigation, 2017-2021.
Groundwater statistics for GRO exclude "z" qualified data.

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																		
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE	TCE	cDCE	tDCE	VC
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0	4.0	16	100	0.29
Soil zone - Shallow only											2.4		15,000		1,200		320		24	1.4	–	77	0.35
									WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l		
BB-5 (--)	Seattle DOT Mercer Parcels, SE quadrant	11/17/97 Decommissioned	B&V	Bailer	250	U	630	U	630	U	ND		ND		ND		ND		ND	ND	1.1	ND	ND
BB-7 (--)	Valley St ROW, N side	11/17/97 Decommissioned	B&V	Bailer	250	U	630	U	630	U	ND		ND		ND		ND		ND	ND	ND	ND	ND
BB-8 (14.0 to 4.0)	Roy St ROW, S side	06/24/97	B&V	Bailer	200	U	500	U	1000	U	1.8		1.3		1.0		1.0		11,000	1,500	4,200	14	280
		01/29/09	DOF	Unknown	499		–		–		0.694		0.500		0.500		1.00		896	258	441	2.45	1.48
		05/03/10	SES	Peristaltic	–		–		–		–		–		–		–		510	120	110	1	0.27
		06/02/11	SES	Peristaltic	130	xy	50	U	250	U	0.35		1		1		3		170	59	44	1	0.2
		09/05/12	SES	Peristaltic	–		–		–		0.35		1		1		3		200	41	28	1	0.2
		12/29/13	SES	Bladder	–		–		–		0.35		1		1		3		200	38	24	1	0.2
		06/17/15	SES	Peristaltic	–		–		–		–		–		–		–		170	40	37	10	2.0
		03/22/17	PES	Peristaltic	–		–		–		0.0896		0.412		0.158		0.316		30.4	4.95	3.10	0.152	0.118
		06/14/17	PES	Peristaltic	–		–		–		0.0896		0.412		0.158		0.316		26.0	8.57	12.6	0.155	0.118
		04/11/18	PES	Peristaltic	40.9	U	–		–		0.0896		0.412		0.158		0.316		33.7	6.13	4.64	0.152	0.118
(duplicate)		04/11/18	PES	Peristaltic	41.5	U	–		–	0.0896		0.412		0.158		0.316		46.8	8.41	6.28	0.152	0.118	
		01/23/19	PES	Peristaltic	99.6	J	–		–	0.0896		0.412		0.158		0.316		133	43.1	81.5	0.402	0.618	
		04/23/19	PES	Peristaltic	31.6	U	–		–	0.0896		0.412		0.158		0.316		48.8	9.09	7.57	0.152	0.118	
		07/17/19	PES	Bladder	112	zJ+	–		–	0.0896		0.412		0.158		0.316		169	28.9	19.3	0.262	0.118	
(duplicate)		10/22/19	PES	Bladder	176	zJ+	–		–	0.0896		0.412		0.158		0.316		135	46.6	31.8	0.398	0.162	
		10/22/19	PES	Bladder	174	zJ+	–		–	0.0896		0.412		0.158		0.316		169	48.3	30.4	0.426	0.152	
(duplicate)		01/20/20	PES	Bladder	31.6	U	–		–	0.0896		0.412		0.158		0.316		138	25.4	16.5	0.232	0.118	
		01/20/20	PES	Bladder	31.6	U	–		–	0.0896		0.412		0.158		0.316		132	24.6	16.0	0.199	0.118	
(duplicate)		05/12/20	PES	Bladder	101	zJ+	–		–	0.0941		0.682		0.137		0.387		142	30.8	17.6	0.282	0.234	
		07/27/20	PES	Bladder	–		–		–	0.0570		0.268		0.0320		0.217		165	46.8	26.3	0.531	0.0273	
		07/27/20	PES	Bladder	–		–		–	0.0660		0.470		0.0710		0.306		162	45.5	26.0	0.496	0.194	
		11/17/20	PES	Bladder	–		–		–	0.0950		0.339		0.0212		0.191		215	107	101	0.802	0.302	
(duplicate)		02/11/21	PES	Peristaltic	–		–		–	0.0490		1.58		0.242		1.28		20.1	3.83	2.19	0.0572	0.0273	
		06/07/21	PES	Bladder	–		–		–	0.0190		0.0500		0.0212		0.191		54.4	12.3	6.94	0.0980	0.0790	
		08/17/21	PES	Peristaltic	–		–		–	0.283		2.79		–		1.45		46.4	11.5	6.92	0.101	0.0273	
		11/08/21	PES	Peristaltic	–		–		–	0.0340		0.325		0.0550		0.378		38.5	7.20	3.22	0.0620	0.0273	
		02/24/22	PES	Peristaltic	–		–		–	0.0160		0.0500		0.0212		0.191		43.5	7.20	3.49	0.0572	0.0273	
		05/17/22	PES	Bladder	–		–		–	0.0160		0.0500		0.0212		0.191		37.5	6.35	3.01	0.0572	0.0273	
		08/09/22	PES	Peristaltic	–		–		–	0.0280		0.0520		0.0212		0.191		59.3	10.2	5.62	0.0690	0.0273	
		08/09/22	PES	Peristaltic	–		–		–	0.0260		0.0500		0.0212		0.191		62.4	10.9	5.94	0.0930	0.0273	
		11/09/22	PES	Peristaltic	–		–		–	0.0340		0.0500		0.0212		0.191		109	32.2	23.5	0.224	0.0273	
		05/09/23	PES	Peristaltic	–		–		–	0.0890		0.0500		0.0212		0.191		71.9	46.0	23.1	0.244	0.184	
		10/31/23	PES	Peristaltic	–		–		–	0.160		0.500		0.212		1.91		139	45.8	26.6	0.572	0.273	
		05/22/24	PES	Peristaltic	–		–		–	0.0900		0.0500		0.0212		0.191		90.4	59.1	63.4	0.398	0.109	
		11/13/24	PES	Peristaltic	–		–		–	0.0960		0.0500		0.0212		0.191		12.6	32.2	186	0.734	1.67	

Page 4 of 16

S141300110R_3526 Table 4 - GW Intermediate A.xlsm

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																				
					GRO	DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes	PCE		TCE		cDCE		tDCE		VC		
Preliminary Cleanup Level (PCUL)					800	500	500	5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Soil zone - Shallow only								2.4		15,000		1,200		320		24		1.4		–		77		0.35	
MW116 (-3.1 to -13.1)	9th Ave N ROW, W side	12/07/12	SES	Peristaltic	–	–	–	–		–		–		–		6.8		1 U		1 U		1 U		0.2 U	
		12/21/12	SES	Peristaltic	–	–	–	–		–		–		–		2.7		1 U		1 U		1 U		0.2 U	
		12/19/13	SES	Peristaltic	–	–	–	0.35	U	1	U	1	U	3	U	1	U	1	U	1	U	1	U	0.2	U
		06/25/15	SES	Peristaltic	–	–	–	–		–		–		–		1	U	1	U	1	U	1	U	0.2	U
		10/27/15	SES	Perstaltic	–	–	–	–		–		–		–		1	U	1	U	1	U	1	U	0.2	U
		02/03/16	SES	Peristaltic	–	–	–	–		–		–		–		1	U	1	U	1	U	1	U	0.2	U
		03/21/17	PES	Peristaltic	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		06/16/17	PES	Bladder	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.303	J	0.0933	U	0.152	U	0.118	U
		04/11/18	PES	Peristaltic	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01/30/19	PES	Bladder	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.655		0.152	U	0.118	U
		07/17/19	PES	Peristaltic	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		10/31/19	PES	Peristaltic	–	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01/21/20	PES	Peristaltic	–	–	–	0.0896	U	0.775		0.158	U	0.351	J	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		04/29/20	PES	Bladder	–	–	–	0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		07/28/20	PES	Bladder	–	–	–	0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		11/12/20	PES	Bladder	–	–	–	0.0160	U	0.0500	UJ	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		02/11/21	PES	Peristaltic	–	–	–	0.0370	J	1.23		0.161		0.968		0.0480	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05/25/21	PES	Peristaltic	–	–	–	0.0160	U	0.0560	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		08/11/21	PES	Bladder	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/18/21	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		03/07/22	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		06/08/22	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		08/10/22	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/04/22	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0330	U	0.0572	U	0.0273	U
		05/18/23	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/08/23	PES	Peristaltic	–	–	–	0.0160	U	0.153	J	0.0680	J	0.257	J	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05/23/24	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/06/24	PES	Peristaltic	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
MW117 (16.9 to 1.9)	Dexter Ave N ROW, E side	02/08/13	SES	Peristaltic	–	–	–	–		–		–		1 U		1 U		1.0000 U		1 U		0.2 U			
		12/18/13	SES	Peristaltic	100	U	50	U	250	U	0.35	U	1	U	1	U	3	U	1	U	1	U	0.2	U	
		Destroyed																							
MW118 (12.9 to 2.9)	Mercer St ROW, N side	03/25/13	SES	Peristaltic	–	–	–	–		–		–		1 U		1 U		1.0000 U		1 U		0.2 U			
		12/18/13	SES	Peristaltic	100	U	50	U	250	U	0.35	U	1	U	1	U	3	U	1	U	1	U	0.2	U	
		Destroyed																							

Table 4
Groundwater Petroleum Hydrocarbons and CVOs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)													
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC		
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29		
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35		
MW119 (2.7 to -7.3)	9th Ave N ROW, W side	03/25/13	SES	Peristaltic	—	—	—	—	—	—	—	—	1 U	1 U	3.3000	1 U	0.2 U	
		12/19/13	SES	Peristaltic	—	—	—	0.35 U	1 U	1 U	3 U	1 U	1 U	2.5000	1 U	0.76		
		04/21/15	SES	Peristaltic	—	—	—	—	—	—	—	34	42	50.0000	1 U	3.1		
		06/17/15	SES	Peristaltic	—	—	—	—	—	—	—	4.9	7.1	52.0000	1 U	2.7		
		10/20/15	SES	Peristaltic	—	—	—	—	—	—	—	15	22	74.0000	1 U	0.45		
		02/02/16	SES	Peristaltic	—	—	—	—	—	—	—	7.3	24	100.0000	1 U	0.45		
		03/29/17	PES	Peristaltic	—	—	—	0.139	0.412 U	0.158 U	0.316 U	5.47	10.7	42.9000	0.334 J	0.272 J		
		06/28/17	PES	Bladder	—	—	—	0.0896 U	0.726	0.158 U	0.562 J	19.0	12.4	5.9900	0.167 J	0.118 U		
		04/05/18	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	2.14	3.02	18.3000	0.203 J	0.118 U		
		01/21/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	1.24	0.153 U	0.0933 U	0.152 U	0.118 U		
		04/29/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.224 J	1.12	10.9000	0.161 J	0.118 UJ		
		07/19/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.303 J	0.153 U	0.3400 J	0.152 U	0.118 U		
		10/10/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.876	7.54	12.6000	0.159 J	0.118 U		
		11/11/19	Farallon	Unknown	—	—	—	—	—	—	—	3.70	9.50	10.0000	0.20 U	0.20 U		
		01/14/20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	5.90	5.81	9.6300	0.200 U	0.200 U		
		01/14/20	Farallon	Unknown	—	—	—	—	—	—	—	4.8	5.1	7.4000	0.20 U	0.20 U		
		02/18/20	Farallon	Unknown	—	—	—	—	—	—	—	1.3	2.5	6.6000	0.20 U	0.20 U		
		03/24/20	Farallon	Unknown	—	—	—	—	—	—	—	0.24	0.87	4.7000	0.20 U	0.20 U		
		(split)		04/27/20	PES	Peristaltic	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.595	1.62	6.8800	0.149 U	0.234 U
05/19/20	Farallon			Unknown	—	—	—	—	—	—	—	0.91	2.8	6.1000	0.20 U	0.20 U		
07/08/20	PES			Bladder	—	—	—	0.0430	0.644	0.0212 U	0.191 U	0.306	1.96	6.6700	0.163	0.0480 J		
07/28/20	Farallon			Unknown	—	—	—	—	—	—	—	0.92	2.6	7.5000	0.20 U	0.20 U		
09/17/20	Farallon			Unknown	—	—	—	—	—	—	—	0.27	1.8	7.8000	0.20 U	0.20 U		
11/11/20	PES			Bladder	—	—	—	0.0160 U	0.0500 UJ	0.0212 U	0.191 U	0.420	2.63	12.9000	0.0983 J	0.212 J+		
12/03/20	Farallon			Unknown	—	—	—	—	—	—	—	0.28	1.2	6.6000	0.20 U	0.20 U		
02/10/21	PES			Peristaltic	—	—	—	0.0470	0.0500 U	0.0212 U	0.191 U	0.0410 J	0.511	6.0500	0.0572 U	0.134		
02/10/21	Farallon			Unknown	—	—	—	—	—	—	—	0.20 U	0.46	5.0000	0.20 U	0.20 U		
05/20/21	PES			Bladder	—	—	—	0.0410	0.0710 U	0.0212 U	0.191 U	0.210	1.70	10.6000	0.165 J	0.252		
08/13/21	PES			Peristaltic	—	—	—	0.0570	0.172 J	0.0212 U	0.191 U	0.293	1.11	8.2500	0.119 J	0.440		
12/03/21	PES			Peristaltic	—	—	—	0.0410	0.151 J	0.0350 J	0.258 J	0.404	1.88	9.2500	0.0572 U	0.234		
03/02/22	PES			Peristaltic	—	—	—	0.0380 J	0.0500 U	0.0212 U	0.191 U	0.443	1.64	8.33 J+	0.0940 J	0.316		
05/05/22	PES			Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.200 J+	0.866	5.16	0.0572 U	0.0273 U		
08/11/22	PES			Peristaltic	—	—	—	0.0430	0.0500 U	0.0212 U	0.191 U	0.550	1.78	8.42	0.109 J	0.212		
11/02/22	PES			Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0920 J	5.28	64.0	0.152 J	5.65		
11/02/22	PES			Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0880 J	4.81	58.9	0.139 J	4.96		
(duplicate)				05/09/23	PES	Peristaltic	—	—	—	0.0480	0.0900 J	0.0212 U	0.191 U	0.302 J	0.0200 U	9.12	0.0612 U	0.191 U
				11/08/23	PES	Peristaltic	—	—	—	0.0330 J	0.0500 U	0.0212 U	0.191 U	2.06	4.17	9.92	0.0860 J	0.0810 J
		11/08/23	PES	Peristaltic	—	—	—	0.0360 J	0.0500 U	0.0212 U	0.191 U	2.23	4.27	10.1	0.120 J	0.0273 U		
		05/24/24	PES	Peristaltic	—	—	—	0.0240 J	0.0500 U	0.0212 U	0.191 U	0.123	0.427	3.36	0.0572 U	0.0273 U		
		11/08/24	PES	Peristaltic	—	—	—	0.0270 J	0.0500 U	0.0212 U	0.191 U	0.255	1.03	5.14	0.0630 J	0.0400 J		

Page 10 of 16

S141300110R_3526 Table 4 - GW Intermediate A.xlsm

Page 11 of 16

S141300110R_3526 Table 4 - GW Intermediate A.xlsm

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																				
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC									
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29									
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	-	77	0.35									
MW-302 (3.0 to -7.0)	Dexter Ave N ROW, E side	10/21/19	PES	Bladder	98.5	J	-	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01/24/20	PES	Bladder	31.6	U	-	0.0896	U	0.412	U	0.158	U	0.316	U	0.353	J	0.164	J	0.0933	U	0.152	U	0.118	U
		05/07/20	PES	Bladder	31.6	U	-	0.0941	U	0.308	J	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		07/28/20	PES	Bladder	-	-	-	0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		11/17/20	PES	Bladder	-	-	-	0.0480		0.743		0.0600	J	0.243	J	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05/17/21	PES	Bladder	-	-	-	0.0160	U	0.0860	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/09/21	PES	Bladder	-	-	-	0.0160	U	0.0500	U	0.153		0.892		0.0390	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05/17/22	PES	Bladder	-	-	-	0.0160	U	0.553		0.121		0.714		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/08/22	PES	Bladder	-	-	-	0.0160	U	0.174	J	0.0480	J	0.237	J	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0540	J
		10/31/23	PES	Bladder	-	-	-	0.0460		0.745		0.181		1.12		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/13/24	PES	Bladder	-	-	-	0.0160	U	0.0500	U	0.0300	J	0.214	J	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
MW-306 (17.2 to 7.2)	Roy St ROW, S side	10/15/19	PES	Bladder	31.6	U	-	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01/16/20	PES	Bladder	34.3	U	-	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		04/28/20	PES	Bladder	42.7	J	-	0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		07/29/20	PES	Bladder	-	-	-	0.0160	U	0.362		0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/06/20	PES	Bladder	-	-	-	0.0160	U	0.182	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0418	J	0.0572	U	0.0273	U
		05/18/21	PES	Bladder	-	-	-	0.0160	U	0.0550	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		12/03/21	PES	Bladder	-	-	-	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05/26/22	PES	Bladder	-	-	-	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/04/22	PES	Bladder	-	-	-	0.0160	U	0.0640	J	0.0212	U	0.191	U	0.0770	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/10/23	PES	Bladder	-	-	-	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11/08/24	PES	Bladder	-	-	-	0.0160	U	0.151	J	0.123		0.738		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
MW-308 (-4.7 to -14.7)	Alley E of Seattle Roy Aloha Shops	10/11/19	PES	Peristaltic	-	-	-	12.5		4.38		0.158	U	0.316	U	0.199	U	0.153	U	38.9		0.492	J	20.3	
		01/16/20	PES	Peristaltic	-	-	-	29.3		0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	11.9		0.411	J	16.3	
		04/08/20	PES	Peristaltic	-	-	-	21.2		0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	12.5		0.360	J	12.9	
		07/06/20	PES	Peristaltic	-	-	-	15.4		0.174	J	0.0620	J	0.191	U	0.0280	U	0.0160	U	16.0		0.608		6.98	
		11/06/20	PES	Peristaltic	-	-	-	38.4		0.480		0.115		0.516		0.0324	J	0.0160	U	6.38		0.260		2.73	
		05/04/21	PES	Peristaltic	-	-	-	20.8		0.186	J	0.104		0.332		0.0280	U	0.0160	U	3.98		0.219		11.7	
		11/11/21	PES	Peristaltic	-	-	-	8.39		0.0840	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	38.6		0.827		20.7	
		05/19/22	PES	Peristaltic	-	-	-	1.45		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	12.5		0.280		3.83	
		11/01/22	PES	Peristaltic	-	-	-	9.53		0.120	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	72.7		1.28		31.1	
		05/12/23	PES	Peristaltic	-	-	-	8.66		0.113	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	70.9		1.24		31.9	
		11/07/23	PES	Peristaltic	-	-	-	1.81		0.0500	U	0.0212	U	0.191	U	0.0360	J	0.0160	U	13.9		0.316		5.25	
		05/21/24	PES	Peristaltic	-	-	-	0.116		0.0500	U	0.0212	U	0.191	U	0.0280	J	0.0160	U	1.44		0.0720	J	0.166	
		11/11/24	PES	Peristaltic	-	-	-	7.30		0.101	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	55.4		1.11		20.5	J-

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC					
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29					
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35					
MW-315 (12.2 to 2.3) (duplicate)	Mercer St ROW, N side	10/03/19	PES	Bladder	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		01/16/20	PES	Bladder	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		04/24/20	PES	Bladder	–	–	–	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U					
		07/24/20	PES	Bladder	–	–	–	0.0430	0.632	0.0760 J	0.437	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/02/20	PES	Bladder	–	–	–	0.0160 U	0.162 J	0.0460 J	0.198 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		05/17/21	PES	Bladder	–	–	–	0.0160 U	0.167 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/05/21	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0630 J	0.393	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/05/21	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0710 J	0.404	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		05/09/22	PES	Bladder	–	–	–	0.0160 U	0.0560 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/02/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/08/23	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/11/24	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
MW-317 (3.4 to -6.6)	9th Ave N ROW, W side	10/09/19	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		01/16/20	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		04/27/20	PES	Bladder	–	–	–	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U					
		07/30/20	PES	Peristaltic	–	–	–	0.0457	1.98	0.205	1.36	0.0280 U	0.0160 U	0.0545 J	0.0572 U	0.0273 U					
		11/10/20	PES	Peristaltic	–	–	–	0.0160 U	0.836 J-	0.0212 U	0.419	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		05/19/21	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/12/21	PES	Peristaltic	–	–	–	0.0160 U	0.244	0.0900 J	0.564	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		05/27/22	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/01/22	PES	Peristaltic	–	–	–	0.0800 U	0.250 U	0.106 U	0.955 U	0.140 U	0.0800 U	0.138 U	0.286 U	0.137 U					
		05/16/23	PES	Peristaltic	–	–	–	0.1750 J	0.250 UJ	0.106 UJ	0.955 UJ	0.140 UJ	0.0800 UJ	0.138 UJ	0.286 UJ	0.137 UJ					
		11/08/23	PES	Peristaltic	–	–	–	0.0350 J	0.0560 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0760 J	0.0572 U	0.0273 U					
		05/21/24	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		11/06/24	PES	Peristaltic	–	–	–	0.0210 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
MW-325 (7.0 to -3.0)	Mercer St ROW, N side	10/03/19	PES	Bladder	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.607	0.152 U	0.118 U					
		01/17/20	PES	Bladder	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		04/21/20	PES	Bladder	–	–	–	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.696	0.149 U	0.234 U					
		07/23/20	PES	Bladder	–	–	–	0.0190 J	0.298	0.0450 J	0.256 J	0.0280 U	0.0160 U	0.262	0.0572 U	0.0273 U					
		11/02/20	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.802	0.0572 U	0.0273 U					
		02/08/21	PES	Bladder	–	–	–	0.0650	2.03	0.230	1.10	0.0280 U	0.0160 U	1.50	0.0572 U	0.0273 U					
		05/17/21	PES	Bladder	–	–	–	0.0160 U	0.0930 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.973	0.0572 U	0.0273 U					
		08/12/21	PES	Peristaltic	–	–	–	0.0160 U	0.189 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.61	0.0572 U	0.0273 U					
		11/04/21	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	2.41	0.0572 U	0.0273 U					
		03/03/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.31	0.0572 U	0.0273 U					
		05/09/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.10	0.0572 U	0.0273 U					
		08/11/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	1.22	0.284	0.869	0.0572 U	0.0273 U					
		11/02/22	PES	Bladder	–	–	–	0.0160 U	0.0950 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.12	0.0572 U	0.0273 U					
		05/09/23	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.111 J+	0.0160 U	1.13	0.0572 U	0.0273 U					
		11/09/23	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.56	0.0572 U	0.0273 U					
		05/24/24	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.26	0.0572 U	0.0273 U					
		11/11/24	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.61	0.0572 U	0.0273 U					

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	-	77	0.35				
MW-327 (3.6 to -6.3)	Lake Union Park, S end	10/02/19	PES	Bladder	-	-	-	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/17/20	PES	Peristaltic	-	-	-	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/09/20	PES	Peristaltic	-	-	-	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		07/07/20	PES	Peristaltic	-	-	-	0.0160 U	0.351	0.0212 U	0.191 U	0.260	0.267	0.0580 J	0.0572 U	0.0273 U				
		11/09/20	PES	Peristaltic	-	-	-	0.0200 J	0.173 J	0.0340 J	0.219 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/25/21	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/10/21	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/04/22	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/02/22	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/09/23	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/14/24	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0610 J	0.0572 U	0.0273 U				
MW-330 (duplicate) (-0.01 to -10.1) (duplicate)	Valley St ROW, N side	05/14/20	PES	Bladder	31.6 U	-	-	0.0941 U	0.580	0.137 U	0.278 J	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		05/14/20	PES	Bladder	31.6 U	-	-	0.0941 U	0.547	0.137 U	0.278 J	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/16/20	PES	Bladder	-	-	-	0.0500	2.49	0.0690 J	0.263	0.0625 J	0.0646	0.0583 J	0.0572 U	0.0273 U				
		12/01/20	PES	Bladder	-	-	-	0.0160 U	0.215	0.113	0.801	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		12/01/20	PES	Bladder	-	-	-	0.0200 J	0.212	0.127	0.789	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/25/21	PES	Bladder	-	-	-	0.0160 U	0.202 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/11/21	PES	Bladder	-	-	-	0.0160 U	0.0500 U	0.0300 J	0.273	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/25/22	PES	Bladder	-	-	-	0.0160 U	0.0900 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		10/31/22	PES	Bladder	-	-	-	0.0160 U	0.107 J	0.0350 J	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		10/31/23	PES	Bladder	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/05/24	PES	Bladder	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0450	0.0276 U	0.0572 U	0.0273 U				
MW-331 (-4.3 to -14.3)	Alley E of Seattle Roy Aloha Shops	04/24/20	PES	Peristaltic	-	-	-	0.226 J	0.278 U	0.257 J	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.249 J				
		07/06/20	PES	Peristaltic	-	-	-	0.0610	0.0500 U	0.0340 J	0.191 U	0.0280 U	0.0160 U	0.046 J	0.0572 U	0.306				
		11/06/20	PES	Peristaltic	-	-	-	0.0407	0.230	0.0354 J	0.219 J	0.0280 U	0.0160 U	0.0728 J	0.0572 U	0.264				
		05/04/21	PES	Peristaltic	-	-	-	0.0240 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0370 J	0.0572 U	0.339				
		11/11/21	PES	Peristaltic	-	-	-	0.0190 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.218				
		05/20/22	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/01/22	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.258				
		05/09/23	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/07/23	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.222				
		05/21/24	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.347				
		11/11/24	PES	Peristaltic	-	-	-	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				

Table 4
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate A Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)													
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC		
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29		
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35		
MW-333 (-1.5 to -11.5)	900 Roy St, S end	04/29/20	PES	Bladder	–	–	–	0.0941 U	1.08	0.189 J	0.854 J	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U		
		07/24/20	PES	Bladder	–	–	–	0.0200 J	0.253	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
		11/05/20	PES	Bladder	–	–	–	0.0160 U	0.253	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
		05/18/21	PES	Peristaltic	–	–	–	0.0160 U	0.0870 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
		11/05/21	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
		05/31/22	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
		11/02/22	PES	Peristaltic	–	–	–	0.160 U	0.500 U	0.212 U	1.91 U	0.280 U	0.160 U	0.276 U	0.572 U	0.273 U		
MW-344 (13.6 to 3.6)	Seattle DOT Mercer Parcels NW quadrant	06/01/21	PES	Bladder	–	–	–	0.0160 U	0.0700 J	0.0212 U	0.191 U	0.0920 J	0.0940	8.50	0.0572 U	9.95		
		08/18/21	PES	Bladder	–	–	–	0.0160 U	0.0740 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.654	0.0572 U	1.02		
		11/18/22	PES	Bladder	–	–	–	0.0370 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.700	620	7.92	942		
		11/13/23	PES	Bladder	–	–	–	0.400 U	1.25 U	0.530 U	4.78 U	0.700 U	0.900 J	383	5.32	241 J-		
		11/06/24	PES	Bladder	–	–	–	0.0170 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.880	257	3.19	480		
MW-351	Roy St ROW	05/09/23	PES	Peristaltic	–	–	–	0.0540	0.229	0.116	0.618	0.415	0.538	10.3	0.0572 U	0.0273 U		
		11/09/23	PES	Peristaltic	–	–	–	0.153	0.0500 U	0.0212 U	0.191 U	0.0520 J	1.04	28.0	0.151 J	0.217 J-		
		05/24/24	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0760 J	0.797	11.0	0.0572 U	0.0273 U		
		11/08/24	PES	Peristaltic	–	–	–	0.0840	0.0500 U	0.0212 U	0.191 U	0.0440 J	1.18	21.4	0.121 J	0.386		
Number of Analytes Measured					54	21	22	507	507	506	507	515	515	515	515	515		
Number of Analytes Detected					13	2	0	200	162	65	78	230	268	384	215	295		
Frequency of Detection					24%	10%	0%	39%	32%	13%	15%	45%	52%	75%	42%	57%		
Maximum Detection					669	–	–	46.6	4.5 J	4.9	6.2 J	24,500	8,050	30,800	129.0	8,610		
Minimum Detection					28.9	50 U	100 U	0.0160 U	0.0500 U	0.0212 U	0.1740 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U		
Number of Analytes Detected Above SL					0	0	0	13	0	0	0	129	146	182	1	258		
Frequency of Detection Above SL					0%	0%	0%	3%	0%	0%	0%	25%	28%	35%	0%	50%		

Notes:

PCULs and Screening Levels from Washington State Department of Ecology, Memorandum from P. Tomlinson to TCP File for American Linen Supply Co. Dexter Ave. (FSID 3573, CSID 12004) re: Development of site-specific preliminary cleanup levels, December 14, 2021.

Detections above the groundwater PCUL level are shown in **bold and highlighted in gray**.

B&V = Black & Veatch

cDCE = cis-1,2-Dichloroethene

DOF = Dalton, Olmsted & Fuglevand, Inc.

DRO = Diesel-range organics

(duplicate) = field duplicate

GeoE = GeoEngineers Inc.

GRO = Gasoline-range organics

HC = Hart Crowser

ORO = Oil-range organics

PCE = Perchloroethylene (Tetrachloroethene)

ROW = right-of-way

SES = SES Strategies, Inc.

TCE = Trichloroethene

tDCE = trans-1,2-Dichloroethene

VC = Vinyl chloride

WW = Windward

Well screen elevations indicated below Sample Location in parentheses.

(--)= unknown screen elevation.

Laboratory and Results Notes:

Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID,

or NWTPH-Gx, NWTPH-Dx, or 8015-M.

VOCs analyzed by EPA Method 601, 8010S, 8015, 8020, 8021B, 8240, 8260B, 8260C, or 8260D,

or by Purge and Trap Gas Chromatogram/Mass Spectrometry.

– = Not analyzed or results not available.

E = Estimated value. The reported range exceeds the calibration range of the analysis.

f = Analyte was detected in the associated method blank. Analyte concentration in the sample is greater than 10x the concentration found in the method blank.

g = Estimated value. The reported range exceeds the calibration range of the analysis.

ht = The analysis was performed outside the method or client-specified holding time requirement.

J = The identification of the analyte is acceptable; the reported value is an estimate.

J+ = The result is an estimated quantity, but the result may be biased high.

J- = The result is an estimated quantity, but the result may be biased low.

ND = Not detected at a concentration exceeding laboratory reporting limit; detection limit not provided.

pr = The sample was received with incorrect preservation. The value reported should be considered an estimate.

U = Not detected at or above the laboratory method detection limit (MDL).

qp = Hydrocarbon result partly due to individual peak(s) in quantitation range.

x = The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

y = The GRO result in the sample is due to a pattern of peaks that is consistent with the chlorinated volatiles detected by the 8260C analysis.

z = No/low level gasoline/petroleum detection; result is likely elevated due to high detections of CVOCs.

Groundwater statistics are for data collected during the Remediation Investigation, 2017-2021.

Groundwater statistics for GRO exclude "z" qualified data.

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l				
BB-10	Dexter Ave North ROW	11/13/97	B&V	Bailer	250 U	630 U	630 U	ND	ND	ND	ND	ND	ND	ND	ND	ND				
BB-13 (--)	Westlake Ave North ROW	06/20/05 05/02/10 Decommissioned	B&V SES	Bailer Peristaltic	250 U —	630 U —	630 U —	ND —	ND —	ND —	ND —	ND 1 U	ND 1 U	2.6 1 U	ND 1 U	1.1 0.2 U				
BB-14 (--)	North Valley St ROW	06/20/05 Decommissioned	B&V	Bailer	300 U	630 U	630 U	—	—	—	—	—	—	—	—	—				
FMW-141 (-12.1 to -22.1) (duplicate) (split)	Alley E of Seattle Roy Aloha Shops	07/26/19	Farallon	Unknown	—	—	—	—	—	—	—	30 U	2,800	6,200	30 U	820				
		10/30/19	PES	Peristaltic	—	—	—	0.230 J	0.412 U	0.158 U	0.316 U	0.199 U	2.18 J	1,200 J	7.13 J	1,760				
		10/30/19	PES	Peristaltic	—	—	—	0.212 J	0.412 U	0.158 U	0.316 U	0.199 U	12.7 J	2,250 J	10.5 J	1,710				
		11/11/19	Farallon	Unknown	—	—	—	—	—	—	—	20 U	20 U	3,500	20 U	2,900				
		01/14/20	PES	Bladder	—	—	—	0.448 U	2.06 U	0.790 U	1.58 U	0.995 U	2.91	414	1.98 J	532				
		01/14/20	Farallon	Bladder	—	—	—	—	—	—	—	4.0 U	4.0 U	250	4.0 U	380				
		02/17/20	Farallon	Unknown	—	—	—	—	—	—	—	2.0 U	2.0 U	280	2.0 U	240				
		03/24/20	Farallon	Unknown	—	—	—	—	—	—	—	10 U	10 U	1,200	10 U	820				
		04/27/20	Farallon	Unknown	—	—	—	—	—	—	—	2.0 U	6.5	440		490				
		04/28/20	PES	Bladder	—	—	—	0.471 U	1.39 U	0.685 U	0.870 U	1.50 U	3.08	1,300	4.62	468				
		05/19/20	Farallon	Unknown	—	—	—	—	—	—	—	20 U	20 U	2,400	20 U	910				
		07/22/20	PES	Bladder	—	—	—	0.320 U	1.00 U	0.424 U	3.82 U	0.560 U	2.30	790	3.19 J	561				
		07/28/20	Farallon	Unknown	—	—	—	—	—	—	—	10 U	10 U	8,100	10 U	780				
		09/17/20	Farallon	Unknown	—	—	—	—	—	—	—	4.0 U	4.0 U	600	4.0 U	620				
		11/02/20	PES	Bladder	—	—	—	0.0620	0.430	0.0212 U	0.191 U	0.0280 U	0.766	276	1.31	489				
		12/03/20	Farallon	Unknown	—	—	—	—	—	—	—	1.0 U	1.0 U	68	1.0 U	190				
		02/10/21	Farallon	Unknown	—	—	—	—	—	—	—	1.0 U	1.0 U	120	1.0 U	180				
		05/03/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0800 U	0.508	0.0280 U	0.560	5.41	0.0572 U	0.218				
		02/23/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.504	89.6 J+	0.191 J	81.7				
		05/09/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.195 J	0.0280 U	0.404	97.3	0.0572 U	50.3				
		11/03/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.316	0.848	180	0.375	130				
		05/15/23	PES	Peristaltic	—	—	—	0.0390 J	0.131 J	0.0212 UJ	0.191 UJ	0.0280 UJ	0.354 J	166 J	0.311 J	87.7 J				
		11/07/23	PES	Peristaltic	—	—	—	0.0160 U	0.0520 J	0.0212 U	0.191 U	0.0280 U	0.376	95.1	0.203	35.3				
		05/22/24	PES	Peristaltic	—	—	—	0.0230 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.250	199	0.326	17.0 J-				
		11/12/24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.240	194	0.251	92.7				
HMW-1IB (-16.0 to -26.0)	Seattle DOT Mercer Parcels, NE quadrant	03/25/19	HC	Peristaltic	100 U	200 U	500 U	1.0 U	1.0 U	1.0 U	1.0 U	20	6.7	22	1.0 U	0.2 U				
		03/10/20	HC	Unknown	100 U	60 U	300 U	0.20 U	0.20 U	0.20 U	0.40 U	13	5.6	16.0	0.20 U	0.20 U				
HMW-2IB (-5.4 to -15.4)	Seattle DOT Mercer Parcels, NE quadrant	03/25/19	HC	Peristaltic	100 U	200 U	500 U	1.0 U	3.4	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	0.2 U				
		03/12/20	HC	Submersible	100 U	51 U	260 U	0.20 U	0.20 U	0.20 U	0.40 U	0.38	0.20 U	0.59	0.20 U	0.20 U				
HMW-4IA (8.7 to -1.3)	Seattle DOT Mercer Parcels, SW quadrant	03/25/19	HC	Peristaltic	100 U	200 U	500 U	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	1.0 U	3.6				
		03/10/20	HC	Submersible	100 U	50 U	250 U	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.41				
HMW-5IB (8.7 to -1.3)	Seattle DOT Mercer Parcels, SW quadrant	03/17/20	HC	Submersible	100 U	50 U	250 U	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U				
HMW-6IB (8.7 to -1.3)	Seattle DOT Mercer Parcels,, SW quadrant	03/13/20	HC	Submersible	100 U	83 J	250 U	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U				
HMW-7IB (9.0 to -1.0)	Seattle DOT Mercer Parcels, SW quadrant	03/12/20	HC	Submersible	100 U	52 U	260 U	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
HMW-8IB (7.5 to -2.5)	Seattle DOT Mercer Parcels, SW quadrant	03/11/20	HC	Submersible	100 U	50 U	250 U	0.20 U	0.22	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U				
HMW-9IB (-1.6 to -11.6) (duplicate)	Seattle DOT Mercer Parcels, SW quadrant	03/19/20	HC	Unknown	580 J	60 J	250 U	0.20 U	0.23	0.20 U	0.40 U	660	420	9,100	8.3	1,900				
		01/26/21	PES	Bladder	—	—	—	0.0760	0.590	0.218	1.21	32.1 J+	112	3,360	4.24 J+	1,400				
		06/02/21	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	16.2	81.6	3,060	6.30 J	1,230				
		08/18/21	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	16.4	87.8	2,990	6.20 J	1,030				
		03/31/22	PES	Bladder	—	—	—	0.0560	0.178 U	0.0310 J	0.191 U	13.5 J+	79.8	3,260	5.10	1,550				
		05/24/22	PES	Bladder	—	—	—	0.0420	0.210	0.0212 U	0.191 U	1.95	11.4	2,160	11.2	850				
		05/24/22	PES	Bladder	—	—	—	0.0520	0.278	0.0212 U	0.216 J	1.61	10.7	2,100	10.8	832				
		08/01/22	PES	Bladder	—	—	—	0.400 U	1.25 U	0.530 U	4.78 U	0.700 U	2.08	2,190	8.25	1,330				
		11/09/22	PES	Bladder	—	—	—	0.400 U	1.25 U	0.530 U	4.78 U	0.700 U	0.400 U	119	3.28 J	1,220				
		02/23/23	PES	Bladder	—	—	—	0.105 J	0.735 J	0.665	2.51	0.140 U	0.0800 U	36.7	3.49	116				
		05/17/23	PES	Bladder	—	—	—	0.160 U	0.500 UJ	0.212 U	1.91 U	0.280 UJ	0.160 U	17.6 U	0.57 UJ	43.6 UJ				
		08/16/23	PES	Bladder	—	—	—	0.0260 J	0.405	0.0920 J	0.524	0.0280 U	0.620	8.86	0.680	9.18				
		11/13/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.422	2.88	0.437	0.989 J-				
		02/28/24	PES	Bladder	—	—	—	0.0270 J	0.307	0.0580 J	0.375	0.0280 U	0.308	1.76	0.189 J	0.811 J+				
		05/29/24	PES	Bladder	—	—	—	0.0160 U	0.0520 J	0.0212 U	0.191 U	0.0280 U	0.162	5.99	1.79	3.55				
		09/04/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/06/24	PES	Bladder	—	—	—	0.0260 J	0.466	0.0212 U	0.191 U	0.0280 U	0.263	3.58	0.427	3.23				
HMW-11IB (-5.2 to -15.2)	Seattle DOT Mercer Parcels, SE quadrant	03/16/20	HC	Submersible	100 U	74 J	250 U	0.20 U	0.20 U	0.20 U	0.40 U	6.9	2.5	3.6	0.20 U	0.20 U				
HMW-15IB (-5.1 to -14.1)	Seattle DOT Mercer Parcels, SW quadrant	09/16/20	HC	Unknown	100 U	50 U	—	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U				
HMW-16IB (2.0 to -8.0)	Seattle DOT Mercer Parcels, NW quadrant	09/18/20	HC	Unknown	100 U	210	—	0.20 U	0.20 U	0.20 U	0.40 U	0.20 U	0.20 U	3.3	0.20 U	15				
MW111 (-33.5 to -43.5)	Alley E of Seattle Roy Aloha Shops	12/21/12	SES	Bladder	—	—	—	—	—	—	—	110	32	37	1 U	1.8				
		12/17/13	SES	Peristaltic	—	—	—	0.35 U	1 U	1 U	3 U	1 U	1 U	4.7	1 U	17				
		04/22/15	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	1.7	1 U	18				
		06/17/15	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	1.5	1 U	20				
		10/20/15	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	1 U	1 U	8.2				
		02/02/16	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	2.3	1 U	5.8				
		03/23/17	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	1.40	0.152 U	5.22				
		06/14/17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.408 J	1.24	0.152 U	3.22				
		04/06/18	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.618	0.153 U	16.5	0.152 U	121				
		01/23/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.492 J	0.176 J	1.70	0.152 U	37.6				
		04/22/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	3.18	0.152 U	19.5 J				
		07/15/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.596	0.152 U	15.0				
		10/14/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.413 J	0.152 U	8.63				
		01/16/20	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	5.08	0.152 U	34.0				
		04/23/20	PES	Bladder	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	24.3	0.149 U	112				
		07/06/20	PES	Bladder	—	—	—	0.0210 J	2.63	0.0212 U	0.191 U	0.0280 U	0.140	27.1	0.0572 U	116				
		11/02/20	PES	Bladder	—	—	—	0.0230 J	0.225	0.0212 U	0.191 U	0.0280 U	0.161	56.2	0.0572 U	118				
		02/09/21	PES	Bladder	—	—	—	0.0420	0.955	0.103	0.606	0.320 J	0.0800 U	14.5	0.0720 J	112				
		05/03/21	PES	Bladder	—	—	—	0.0430	0.880	0.174 U	1.21	0.0280 U	0.0790	5.80	0.0572 U	44.3				
		08/04/21	PES	Peristaltic	—	—	—	0.0360 J	0.548	0.0790 J	0.480	0.0280 U	0.0460	6.18	0.0572 U	44.2				
		11/03/21	PES	Peristaltic	—	—	—	0.0260 J	0.0950 J	0.0212 U	0.207 J	0.0280 U	0.0850	8.17	0.0572 U	45.6				
		02/15/22	PES	Peristaltic	—	—	—	0.0160 U	0.0530 J	0.0212 U	0.191 U	0.0280 U	0.0480	1.87	0.0572 U	12.8				
		05/18/22	PES	Peristaltic	—	—	—	0.0160 U	0.0520 J	0.0212 U	0.191 U	0.0480 J	0.0570	0.917	0.0572 U	6.52				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
MW111 (continued)		08/09/22	PES	Peristaltic	—	—	—	0.0260 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0600	1.74	0.0572 U	15.1				
		11/01/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.639	0.0572 U	8.22				
		05/15/23	PES	Peristaltic	—	—	—	0.0160 UJ	0.0500 UJ	0.0212 UJ	0.191 UJ	0.0560 J	0.0160 UJ	0.580 J	0.0572 UJ	6.27 J				
		11/07/23	PES	Peristaltic	—	—	—	0.0220 J	0.0500 U	0.0212 U	0.191 U	0.0430 J	0.0790	0.996	0.0572 U	6.28				
		05/22/24	PES	Peristaltic	—	—	—	0.0270 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0450	1.26	0.0572 U	7.98				
		11/08/24	PES	Peristaltic	—	—	—	0.0180 J	0.0500 U	0.0212 U	0.191 U	0.0590 J	0.0460	3.35	0.0572 U	20.8				
MW112 (-17.2 to -27.2)	Dexter Ave N ROW, W side	01/00/00	SES	Bladder	—	—	—	—	—	—	—	1 U	1 U	1 U	1 U	0.2 U				
		12/26/13	SES	Bladder	—	—	—	0.35 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U				
		03/22/17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		06/16/17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/12/18	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		12/21/18	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/22/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 UJ				
		07/16/19	PES	Bladder	31.7 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		10/21/19	PES	Bladder	96.6 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/24/20	PES	Bladder	31.6 U	—	—	0.0896 U	1.24	0.158 U	0.316 U	0.248 J	0.153 U	0.0933 U	0.152 U	0.118 U				
		05/07/20	PES	Bladder	31.6 U	—	—	0.0941 U	0.390 J	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/27/20	PES	Bladder	—	—	—	0.0160 U	1.93	0.0221 J	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/17/20	PES	Bladder	—	—	—	0.0270 J	0.322	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		02/11/21	PES	Bladder	—	—	—	0.0200 J	0.112 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/14/21	PES	Bladder	—	—	—	0.0160 U	0.0600 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		08/17/21	PES	Bladder	—	—	—	0.259	2.24	0.159	0.735	0.0280 U	0.0160 U	0.0580 U	0.0572 U	0.0273 U				
		11/08/21	PES	Bladder	—	—	—	0.0270 J	0.0500 U	0.129	0.797	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		02/24/22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/13/22	PES	Bladder	—	—	—	0.0160 U	0.0570 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		08/09/22	PES	Bladder	—	—	—	0.0320 J	0.122 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/08/22	PES	Bladder	—	—	—	0.0160 UJ	0.0500 UJ	0.0212 UJ	0.191 UJ	0.0280 UJ	0.0160 UJ	0.0276 UJ	0.0572 UJ	0.0273 UJ				
		05/10/23	PES	Bladder	—	—	—	0.0160 U	0.5190	0.0920 J	0.553	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
Decommissioned August 2023																				
MW112R	Dexter Ave N ROW, W side	12/04/23	PES	Bladder	—	—	—	0.0160 U	0.197 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/29/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.016 U	0.0276 U	0.0572 U	0.0273 U				
MW126 (-54.1 to -64.1)	Alley E of Seattle Roy Aloha Shops	01/03/14	SES	Peristaltic	—	—	—	0.35 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U				
		03/28/17	PES	Peristaltic	—	—	—	0.148 J	0.563 U	0.158 U	0.316 U	0.199 U	0.153 U	0.283 J	0.152 U	0.118 U				
		06/15/17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.179 J	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/06/18	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/22/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/29/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 UJ				
		07/18/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		10/15/19	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		10/15/19	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/14/20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.162 J	0.441 J	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/09/20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		07/24/20	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/09/20	PES	Peristaltic	—	—	—	0.0210 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		02/10/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/04/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/04/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		08/04/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/11/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35				
MW-143 (-27.7 to -37.76)	8th Ave N ROW, E side	04/30/18	PES	Peristaltic	154	–	–	0.244 J	0.797	0.212 J	1.08 J	0.199 U	0.153 U	129	0.512	193				
		01/29/19	PES	Bladder	31.6 U	–	–	0.141 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.241 J	0.152 U	0.118 U				
		04/24/19	PES	Peristaltic	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		07/19/19	PES	Bladder	31.6	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.309 J	0.152 U	0.118 U				
		10/16/19	PES	Bladder	2,000 zJ+	–	–	0.211 J	0.412 U	0.158 U	0.316 U	2.35	28.0	2,510	11.0	1,180				
		01/22/20	PES	Bladder	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.171 J	0.152 U	0.254 J				
		04/24/20	PES	Bladder	88.2 U	–	–	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.135 J	0.149 U	0.234 U				
		07/29/20	PES	Bladder	–	–	–	0.0401	1.63	0.0229 J	0.191 U	0.0307 J	0.0167 J	0.0754 J	0.0572 U	0.0273 U				
		11/24/20	PES	Bladder	–	–	–	0.584	0.203	0.0610 U	0.474	0.0280 U	9.64	113	0.633	26.0				
		02/08/21	PES	Peristaltic	–	–	–	0.800 U	3.00 J	1.06 U	9.55 U	1.40 U	0.800 U	3,260	14.1	514 J				
MW-143 (continued)		05/19/21	PES	Bladder	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	1.40 U	0.800 U	4,240	21.6	1,200				
		08/20/21	PES	Bladder	–	–	–	0.106	0.302	0.0212 U	0.191 U	0.0790 J	0.138	635 J-	5.51	1,140 J-				
		12/08/21	PES	Bladder	–	–	–	0.104	0.209	0.171	0.866	0.0280 U	0.0990	339	4.41	723				
		03/08/22	PES	Bladder	–	–	–	0.142	0.268	0.0212 U	0.191 U	0.0280 U	0.146 J+	815	8.54	1,240				
		05/26/22	PES	Bladder	–	–	–	0.160 U	0.500 U	0.212 U	1.91 U	0.280 U	0.160 U	188	3.46	602				
		08/12/22	PES	Bladder	–	–	–	0.320 U	1.00 U	0.424 U	3.82 U	0.560 U	0.320 U	491	6.02	1,010				
		11/01/22	PES	Bladder	–	–	–	0.0160 U	0.128 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.100 J	0.0572 U	0.274				
		05/16/23	PES	Peristaltic	–	–	–	0.0750 J	0.183 J	0.0212 UJ	0.191 UJ	0.191 UJ	0.0160 UJ	330 J	5.04 J	524 J+				
		11/07/23	PES	Peristaltic	–	–	–	0.0160 U	0.281	0.0710 J	0.421	0.0280 U	0.111	4.12	0.126 J	3.50				
		05/24/24	PES	Peristaltic	–	–	–	0.0770	0.128 J	0.0212 U	0.191 U	0.0280 U	0.0710	307	5.72	416				
		11/06/24	PES	Peristaltic	–	–	–	0.0220 J	0.0880 J	0.0340 J	0.222 J	0.0280 U	0.0560	2.22	0.287	15.9				
MW-145 (-26.1 to -36.1)	8th Ave N ROW, E side	04/27/18	PES	Bladder	52.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.212 J	2.29	0.152 U	3.88				
		01/29/19	PES	Bladder	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.316 J	0.152 U	0.335 J				
		04/26/19	PES	Bladder	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.392 J				
Decommissioned December 2019																				
MW-145R (-27.2 to -37.2) (duplicate)	8th Ave N ROW, E side	12/16/19	PES	Bladder	140 zJ+	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.193 J	0.152 U	0.118 U				
		01/21/20	PES	Bladder	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.230 J	0.152 U	0.118 U				
		04/02/20	PES	Bladder	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.293 J	0.152 U	0.118 U				
		08/03/20	PES	Bladder	–	–	–	0.0190 J	1.45	0.0460 J	0.191 U	0.0570 J	0.0270 J	0.228	0.0572 UJ	0.0273 U				
		11/23/20	PES	Bladder	–	–	–	0.0160 U	0.0570 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.151	0.0572 U	0.0273 U				
		02/05/21	PES	Peristaltic	–	–	–	0.159	2.79	0.300	1.65	0.0280 U	0.0160 U	0.0680 J	0.0572 U	0.0273 U				
		05/12/21	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0760 J	0.0572 U	0.0273 U				
		08/23/21	PES	Bladder	–	–	–	0.0400 J	0.570	0.0460 U	0.210 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 UJ				
		08/23/21	PES	Bladder	–	–	–	0.0410	0.576	0.0470 U	0.224 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 UJ				
		11/30/21	PES	Peristaltic	–	–	–	0.0160 U	0.145 J	0.0212 U	0.263	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 UJ				
		03/08/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/11/22	PES	Bladder	–	–	–	0.0160 U	0.254	0.0380 J	0.241 J	0.0280 U	0.0160 U	0.0340 J	0.0572 U	0.0273 U				
		08/10/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/02/22	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/15/23	PES	Bladder	–	–	–	0.0160 U	0.261	0.0212 U	0.364	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/08/23	PES	Bladder	–	–	–	0.0160 U	0.0500 U	0.0940 J	0.273	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/22/24	PES	Bladder	–	–	–	0.0160 U	0.0610 J	0.0212 U	0.191 U	0.0280 U	0.016 U	0.0276 U	0.0572 U	0.0273 U				
		11/08/24	PES	Bladder	–	–	–	0.0160 J	0.0930 J	0.0560 J	0.229 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC					
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29					
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35					
MW-147 (-17.6 to -27.6) (duplicate) (split)	Roy St ROW, S side	05/01/18	PES	Bladder	484 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	19.8	83.4	399	2.09	1,150					
		01/22/19	PES	Bladder	663 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	98.2	179	1,230	2.88	738					
		04/23/19	PES	Bladder	139 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	5.13	322	1.47	499					
		07/18/19	PES	Bladder	175 zJ+	—	—	0.0896 U	0.412 U	3.16 U	6.32 U	0.199 U	4.79	219	2.49	446					
		07/18/19	PES	Bladder	170 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	4.72	286	2.12	425					
		10/14/19	PES	Bladder	513 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	3.38	597	2.91	1,410					
		01/24/20	PES	Bladder	1,200 zJ+	—	—	2.24 U	10.3 U	3.95 U	7.90 U	4.98 U	4.63 J	1,100	3.80 U	1,340					
		04/29/20	PES	Bladder	1,150 zJ+	—	—	2.35 U	6.95 U	3.43 U	4.35 U	7.50 U	5.10 J	2,410	3.90 J	3,470					
		07/09/20	PES	Bladder	—	—	—	0.0890	3.52	0.0212 U	0.191 U	4.29	12.4	2,220	11.9	6,970					
		11/10/20	PES	Bladder	2,930 zJ+	—	—	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	4.73	3,740	9.23 J	7,290					
		11/10/20	HC	Bladder	100 U	50 U	250 U	170 U	500 U	500 U	1,500 U	500 U	500 U	3,500	500 U	7,400					
		02/09/21	PES	Bladder	—	—	—	0.800 U	2.50 U	1.06 U	9.55 U	1.40 U	9.90	1,750	7.80 J	3,450 J					
		05/04/21	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	3.00 J	1,300	5.72 U	2,200					
		08/20/21	PES	Bladder	—	—	—	0.0390 J	0.108 J	0.0212 U	0.191 U	0.0280 U	0.0320 J	24.0	1.73	348 J-					
		11/09/21	PES	Bladder	—	—	—	0.0700	0.0590 J	0.124	0.737	0.0280 U	3.48	1,800	5.73	2,880					
		02/18/22	PES	Bladder	—	—	—	0.0520	0.110 U	0.0212 U	0.191 U	0.0280 U	0.426	275	2.36	383					
		05/03/22	PES	Bladder	—	—	—	0.160 U	0.500 U	0.212 U	1.91 U	0.280 U	0.250 J	121	2.31	273					
		08/10/22	PES	Bladder	—	—	—	0.0390 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.340	93.7	1.89	231					
		11/03/22	PES	Bladder	—	—	—	0.0430	0.127 U	0.0320 J	0.191 U	0.0280 U	0.116	72.7	2.06	146					
MW-148 (duplicate) (-25.7 to -35.7)	Roy St ROW, S side	05/01/18	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U					
		05/01/18	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.216 J	0.152 U	0.118 U					
		01/23/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	1.24	0.347 J	0.0933 U	0.152 U	0.118 U					
		04/26/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.277 J					
		07/22/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.415 U	0.153 U	0.0933 U	0.152 U	0.253 J					
		10/16/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.463 J					
		01/20/20	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.163 J	0.0933 U	0.152 U	0.305 J					
		04/30/20	PES	Bladder	36.8 J	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U					
		07/15/20	PES	Bladder	—	—	—	0.0160 U	1.32	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.224					
		11/11/20	PES	Bladder	—	—	—	0.0160 U	0.310 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U					
		08/13/21	PES	Peristaltic	—	—	—	0.0570	0.569	0.0640 J	0.246 J	0.0280 U	0.0160 U	0.0630 U	0.0572 U	0.516					
		12/07/21	PES	Bladder	—	—	—	0.0160 U	0.0600 U	0.0810 J	0.450	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.520					
		02/25/22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.657					
		05/05/22	PES	Bladder	—	—	—	0.0210 J	0.184 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.792					
		08/10/22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.841					
		11/04/22	PES	Bladder	—	—	—	0.0160 U	0.0850 J	0.0212 U	0.191 U	0.0400 J	0.0360 J	0.0720 J	0.0572 U	0.480					
		05/09/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.200 J	0.0280 U	0.0260 J	0.0276 U	0.0572 U	0.641					
		11/09/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.154 J-					
		05/28/24	PES	Peristaltic	—	—	—	0.0310 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.016 U	0.0276 U	0.0572 U	0.0273 U					
MW-150 (-13.3 to -23.3)	Property, NE quadrant	04/10/18	PES	Peristaltic	7,040 zJ+	—	—	22.4 U	1.63	39.5 U	79.0 U	2,500	3,200	9,710	21.1	766					
		10/25/18	PES	Peristaltic	14,600 zJ+	—	—	0.413 J	2.53	0.226 J	1.13 J	15,200	8,800	17,700	49.7	1,430					
		12/12/18	PES	Peristaltic	17,500 zJ+	—	—	0.429 J	1.04	0.158 U	0.316 U	75.6	533	32,800	242	2,040					
		01/29/19	PES	Peristaltic	11,900 zJ+	—	—	8.96 U	41.2 U	15.8 U	31.6 U	303	548	18,100	36.7 J	1,370					
		03/13/19	PES	Peristaltic	7,540 zJ+	—	—	0.165 J	0.412 U	0.185 J	0.316 U	36.0	262	15,000	50.5	479					
Decommissioned March 2019																					

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
MW-152 (-10.2 to -20.2)	Property, SW quadrant	04/10/18	PES	Peristaltic	40,600 zJ+	—	—	224 U	8.24 U	3.27 J	790 U	67,300	6,550	35,300	42.1	3,660				
		10/26/18	PES	Peristaltic	36,700 zJ+	—	—	4.48 U	20.6 U	7.90 U	15.8 U	1,960	3,150	73,000	109	4,510				
		12/14/18	PES	Peristaltic	47,300 zJ+	—	—	2.24 U	10.3 U	3.95 U	7.90 U	23,600 J+	6,870 J+	77,100 J+	134 J+	7,830 J+				
		01/31/19	PES	Peristaltic	44,300 zJ+	—	—	0.416 J	2.61 J+	0.342 J	2.10	38,300	3,920	58,400	101	9,600				
		03/12/19	PES	Peristaltic	55,900 zJ+	—	—	2.24 U	10.3 U	3.95 U	7.90 U	398 U	18,700	127,000	781	11,000				
		Decommissioned March 2019																		
MW-157 (-28.3 to -38.2)	8th Ave N ROW, E side	04/26/18	PES	Peristaltic	65.7 J	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.950	0.240 J	10.4	0.246 J	104				
		01/24/19	PES	Peristaltic	1,870 zJ+	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	1.65	4,250	14.2	674				
		04/24/19	PES	Peristaltic	3,210 zJ+	—	—	0.254 J	0.412 U	0.158 U	0.316 U	9.95 U	8.52 J	3,550	15.9	622				
		07/22/19	PES	Bladder	3,880 zJ+	—	—	0.327 J	0.412 U	0.158 U	0.316 U	19.9 U	27.6	4,530	18.4	666				
		10/16/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.561	0.158 U	0.316 U	0.199 U	0.153 U	0.188 J	0.152 U	0.118 U				
		01/20/20	PES	Bladder	1,650 zJ+	—	—	0.308 J	0.412 U	0.158 U	0.316 U	39.4	109	2,040	8.95	941				
		04/24/20	PES	Bladder	756 zJ+	—	—	1.88 U	5.56 U	2.74 U	3.48 U	6.00 U	3.80 U	1,040	8.86 J	980				
		07/15/20	PES	Bladder	—	—	—	0.480 J	1.00 U	0.424 U	3.82 U	0.560 U	3.06	888	7.20	668				
		11/23/20	PES	Bladder	—	—	—	0.740 U	1.00 U	0.424 U	3.82 U	3.04	24.7	2,770	9.98	528				
MW-190 (-30.2 to -40.2)	Valley St ROW, S side	10/14/19	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	7.78	0.152 U	0.994				
		01/23/20	PES	Bladder	31.6 U	—	—	0.150 J	1.57	0.158 U	0.344 J	0.199 U	0.153 U	0.389 J	0.152 U	0.118 U				
		04/02/20	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	2.13	0.152 U	1.81				
		08/04/20	PES	Bladder	—	—	—	0.0270 J	2.09	0.0330 J	0.191 U	0.0280 U	0.0160 U	1.74	0.0572 U	3.77 J				
		11/18/20	PES	Bladder	—	—	—	0.0160 U	0.0820 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	21.8	0.0572 U	64.9				
		02/03/21	PES	Bladder	—	—	—	0.0160 U	0.164 J	0.0450 J	0.252 J	0.0280 U	0.0160 U	12.5	0.0572 U	68.4				
		05/14/21	PES	Bladder	—	—	—	0.0160 U	0.149 U	0.0330 J	0.195 J	0.0280 U	0.0160 U	8.12	0.0572 U	32.2				
		08/11/21	PES	Peristaltic	—	—	—	0.0310 J	0.834	0.122	0.669	0.0280 U	0.0160 U	6.60	0.0572 U	34.5				
		11/30/21	PES	Bladder	—	—	—	0.0160 U	0.131 J	0.156	0.859	0.0280 U	0.0160 U	19.3	0.0572 U	56.1 J+				
		03/04/22	PES	Bladder	—	—	—	0.0160 U	0.116 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	43.3	0.0670 J	74.3				
		05/10/22	PES	Bladder	—	—	—	0.0160 U	0.527	0.0212 U	0.338	0.0280 U	0.0160 U	6.40	0.0572 U	23.3				
		08/11/22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.982	0.202	37.8	0.0572 U	54.7				
		10/31/22	PES	Bladder	—	—	—	0.0160 U	0.122 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	78.7	0.0980 J	64.4				
		05/12/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0790 J	0.0160 U	148.0	0.109 J	111.0				
		11/06/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	78.8	0.0960 J	64.8				
		05/23/24	PES	Peristaltic	—	—	—	0.0160 U	0.0510 J	0.0212 U	0.191 U	0.0280 U	0.016 U	79.5	0.105 J	58.5				
		11/06/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	2.22	0.0572 U	24.0				
MW-303 (-13.8 to -23.8)	Dexter Ave N ROW, E side	10/21/19	PES	Submersible	99.6 J	—	—	0.0896 U	1.63	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/24/20	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.313 J	0.153 J	0.0933 U	0.152 U	0.118 U				
		05/07/20	PES	Bladder	41.5 J	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/27/20	PES	Bladder	—	—	—	0.0160 U	1.56	0.0263 J	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/17/20	PES	Bladder	—	—	—	0.0160 U	0.0750 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/18/21	PES	Bladder	—	—	—	0.0160 U	0.240	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/09/21	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.144	0.749	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/25/22	PES	Bladder	—	—	—	0.0160 U	0.0680 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/08/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		10/31/23	PES	Bladder	—	—	—	0.0160 U	0.290	0.0430 J	0.331	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/13/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
MW-307 (-12.4 to -22.4)	Roy St ROW, S side	10/11/19	PES	Bladder	31.6 U	—	—	0.0896 U	1.05	0.158 U	0.316 U	0.199 U	0.153 U	0.935	0.152 U	0.289 J				
		01/15/20	PES	Bladder	31.6 U	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.172 J	0.152 U	0.118 U				
		04/28/20	PES	Bladder	146 zJ+	—	—	0.172 J	0.452 J	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/29/20	PES	Bladder	—	—	—	0.0211 J	0.780	0.0212 U	0.191 U	0.0492 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/06/20	PES	Bladder	—	—	—	0.0160 U	0.427	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/18/21	PES	Bladder	—	—	—	0.0160 U	0.272	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		12/03/21	PES	Bladder	—	—	—	0.0300 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/26/22	PES	Bladder	—	—	—	0.0160 U	0.132 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/04/22	PES	Bladder	—	—	—	1.03	0.0770 J	0.0212 U	0.191 U	0.274	0.0490	0.146	0.0572 U	0.0273 U				
		11/10/23	PES	Bladder	—	—	—	0.0760	0.264	0.100 J	0.619	0.0640 J	0.0160 J	0.0380 J	0.0572 U	0.0273 U				
		11/08/24	PES	Bladder	—	—	—	0.0160 U	0.0730 J	0.0310 J	0.211 J	0.0280 U	0.0160 U	0.0920 U	0.0572 U	0.0273 U				
MW-309 (-32.0 to -42.0)	Alley E of Seattle Roy Aloha Shops	10/14/19	PES	Peristaltic	—	—	—	0.295 J	2.01	0.158 U	0.316 U	1.11	0.497 J	1.47	0.152 U	6.37				
		01/16/20	PES	Peristaltic	—	—	—	0.585	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.487 J	0.152 U	12.6				
		04/08/20	PES	Peristaltic	—	—	—	1.92	0.412 U	0.239 J	0.316 U	0.199 U	0.153 U	0.231 J	0.152 U	12.6				
		07/06/20	PES	Peristaltic	—	—	—	0.524	0.0500 U	0.0640 J	0.191 U	0.0930 J	0.0160 U	0.170	0.0572 U	16.0				
		11/06/20	PES	Peristaltic	—	—	—	0.473	0.0500 U	0.0388 J	0.191 U	0.0726 J	0.0160 U	0.187	0.0572 U	10.5				
		05/04/21	PES	Peristaltic	—	—	—	0.252	0.0500 U	0.0212 U	0.191 U	0.0370 J	0.0160 U	0.212	0.0572 U	13.1				
		11/11/21	PES	Peristaltic	—	—	—	0.241	0.0500 U	0.0212 U	0.191 U	0.0500 J	0.0160 U	0.115	0.0572 U	14.6				
		05/19/22	PES	Peristaltic	—	—	—	0.232	0.0500 U	0.0212 U	0.191 U	0.0620 J	0.0160 U	0.239	0.0572 U	10.1				
		11/01/22	PES	Peristaltic	—	—	—	0.351	0.107 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.255	0.0572 U	13.1				
		05/12/23	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/07/23	PES	Peristaltic	—	—	—	0.274	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.261	0.0572 U	12.0				
		05/21/24	PES	Peristaltic	—	—	—	0.0780	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.016 U	0.0276 U	0.0572 U	0.651				
		11/11/24	PES	Peristaltic	—	—	—	0.187	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.111	0.0572 U	8.77 J-				
MW-311 (-29.1 to -39.1)	Alley E of Seattle Roy Aloha Shops	10/10/19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	20.4	46.1	173	0.221 J	25.1				
		01/14/20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	1.99	11.4	75.0	0.204 J	13.6				
		04/23/20	PES	Bladder	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.624	45.8	0.149 U	10.9				
		07/16/20	PES	Bladder	—	—	—	0.0650	3.39	0.0212 U	0.191 U	0.0470 J	0.334	5.24	0.144 J	24.0				
		11/04/20	PES	Bladder	—	—	—	0.0287 J	0.578	0.0319 J	0.191 U	0.169	0.524	2.66	0.0593 J	13.5				
		05/03/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0510 U	0.249 J	0.0660 J	0.361	0.981	0.0572 U	4.68				
		11/04/21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0690 J	0.287	0.418	0.0572 U	2.71				
		05/09/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.247	0.336	0.0572 U	0.346				
		11/01/22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.162	0.267	0.0572 U	1.37				
		05/15/23	PES	Peristaltic	—	—	—	0.0160 UJ	0.0730 J	0.0212 UJ	0.191 UJ	0.0280 UJ	0.107 J	0.112 J	0.0572 UJ	1.46 J				
		11/07/23	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0690	0.0650 J	0.0572 U	0.805				
		05/21/24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.108	0.160	0.0572 U	1.28				
		11/12/24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0830	0.161	0.0572 U	0.220				
MW-314 (-28.0 to -38.0) (duplicate) (duplicate)	Alley E of Seattle Roy Aloha Shops	10/10/19	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	26.1	106	491	1.63	43.6				
		01/15/20	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	22.7	98.3	596	2.12	17.9				
		01/15/20	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	19.8	88.5	569	1.85	17.9				
		04/22/20	PES	Bladder	—	—	—	0.941 U	2.78 U	1.37 U	1.74 U	3.00 U	229	3,190	14.8	410				
		07/16/20	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	4.20 J	313	4,020	22.3	442				
		11/04/20	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	13.2	807	4,240	16.4 J	360				
		05/03/21	PES	Bladder	—	—	—	0.800 U	2.50 U	1.06 U	9.55 U	1.40 U	54.5	977	3.15 J	42.9				
		12/03/21	PES	Bladder	—	—	—	0.0390 J	0.0500 U	0.0540 J	0.335	8.27	59.5	639	2.43	38.1				
		12/03/21	PES	Bladder	—	—	—	0.160 U	0.500 U	0.212 U	1.91 U	6.79	52.5	582	2.62	31.5				
		05/18/22	PES	Bladder	—	—	—	0.0290 J	0.0500 U	0.0212 U	0.191 U	7.78	63.1	800	3.08	49.1				
		11/01/22	PES	Bladder	—	—	—	0.0160 U	0.198 J	0.0212 U	0.191 U	2.85	44.7	576 J	2.77	32.0				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
MW-314 (continued)		05/15/23	PES	Bladder	—	—	—	0.0320 J	0.0500 U	0.0212 U	0.191 U	5.34	39.0	634	2.55	71.6				
		11/07/23	PES	Bladder	—	—	—	0.320 U	1.00 U	0.424 U	3.82 U	3.68	26.8	429	2.10 J	13.2				
		05/22/24	PES	Bladder	—	—	—	0.0160 U	0.0800 J	0.0212 U	0.191 U	0.0390 J	0.802	9.06	0.0900 J	0.691 J-				
		11/12/24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0600 J	0.508	4.82	0.0620 J	0.0273 U				
MW-316 (-10.0 to -20.0)	Mercer St ROW, N side	10/02/19	PES	Bladder	—	—	—	0.0896 U	0.570	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		01/16/20	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		04/21/20	PES	Bladder	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/24/20	PES	Bladder	—	—	—	0.0250 J	0.362	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/02/20	PES	Bladder	—	—	—	0.0190 J	0.120 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/17/21	PES	Bladder	—	—	—	0.0160 U	0.220	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/05/21	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.119	0.690	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		05/09/22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0340 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/02/22	PES	Bladder	—	—	—	0.0160 U	0.0830 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/08/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		11/11/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 UJ				
MW-318 (-23.1 to -33.1)	9th Ave N ROW, W side	10/08/19	PES	Bladder	—	—	—	5.75	0.495 J	0.158 U	0.316 U	0.199 U	0.153 U	6.52	0.152 U	8.65				
		01/16/20	PES	Peristaltic	—	—	—	25.4	0.519	0.158 U	0.316 U	0.199 U	0.153 U	9.86	0.152 U	31.0				
		04/27/20	PES	Bladder	—	—	—	22.6	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	2.08	0.149 U	3.84				
		07/30/20	PES	Bladder	—	—	—	5.79	0.117 J	0.0775 J	0.191 U	0.0280 U	0.0160 U	0.525 J	0.0572 UJ	0.941				
		11/12/20	PES	Bladder	—	—	—	4.20	0.224 J-	0.0212 U	0.229 J	0.0280 U	0.0160 U	0.499	0.0572 U	0.865 J+				
		05/19/21	PES	Peristaltic	—	—	—	3.97	0.108 U	0.0212 U	0.257 J	0.0280 U	0.0160 U	0.570	0.0572 U	1.56				
		11/12/21	PES	Peristaltic	—	—	—	6.15	0.0760 J	0.0212 U	0.201 J	0.0280 U	0.0160 U	0.489	0.0572 U	1.75				
		05/27/22	PES	Peristaltic	—	—	—	20.3	0.0670 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.10	0.0572 U	32.7 J+				
		11/01/22	PES	Peristaltic	—	—	—	50.1	0.189 J	0.0212 U	0.210 J	0.0280 U	0.0160 U	5.50	0.0572 U	46.1				
		05/16/23	PES	Peristaltic	—	—	—	56.1 J	0.199 J	0.0212 UJ	0.191 UJ	0.0280 UJ	0.0160 UJ	4.56 J	0.0710 J	51.1 J				
		11/08/23	PES	Peristaltic	—	—	—	42.2	0.179 J	0.0212 U	0.243 J	0.0280 U	0.0160 U	3.20	0.0610 J	18.7				
		05/22/24	PES	Peristaltic	—	—	—	54.3	0.330	0.0212 U	0.282	0.0280 U	0.016 U	2.45 J-	0.0690 J	25.4 J-				
		11/06/24	PES	Peristaltic	—	—	—	23.8	0.155 J	0.0212 U	0.191 J	0.0280 U	0.0160 U	10.2	0.0870 J	22.0				
MW-322 (-21.3 to -31.3)	9th Ave N ROW, W side	10/07/19	PES	Peristaltic	—	—	—	7.12	0.612	0.158 U	0.316 U	0.699	21.0	497	1.17	268				
		01/21/20	PES	Peristaltic	—	—	—	7.41	0.955	0.158 U	0.316 U	0.218 J	8.62	2,740	6.06	221				
		04/29/20	PES	Bladder	—	—	—	15.5 J	27.8 U	13.7 U	17.4 U	30.0 U	661	1,510	14.9 U	280				
		07/07/20	PES	Bladder	—	—	—	28.8	0.970 J	0.212 U	1.91 U	117	494	547	3.91	123				
		11/24/20	PES	Bladder	—	—	—	23.9	0.550 U	0.212 U	1.91 U	3.35	70.9	257	1.35 J	41.2				
		05/19/21	PES	Peristaltic	—	—	—	22.4	0.500 U	0.212 U	1.91 U	8.80	259	496	2.41	43.0				
		11/09/21	PES	Peristaltic	—	—	—	29.3	0.308	0.0212 U	0.191 U	1.55	137	471	2.28	136				
		06/08/22	PES	Peristaltic	—	—	—	9.54	0.690 U	0.212 U	1.91 U	0.280 U	1.45	502	1.61 J	112				
		11/03/22	PES	Peristaltic	—	—	—	11.8	0.313	0.0212 U	0.191 U	0.315	0.892	598	2.60	243				
		05/17/23	PES	Peristaltic	—	—	—	5.12 J	1.00 UJ	0.424 UJ	3.82 UJ	0.560 UJ	1.08 J	729 J	2.64 J	111 J				
		11/08/23	PES	Peristaltic	—	—	—	4.19	0.0940 J	0.0212 U	0.191 U	0.0280 U	0.512	622	3.76	43.0				
		05/22/24	PES	Peristaltic	—	—	—	2.56	0.0870 J	0.0212 U	0.191 U	0.0280 U	0.359	602	2.79	62.7 J-				
		11/06/24	PES	Peristaltic	—	—	—	3.33	0.104 J	0.0212 U	0.191 U	0.0280 U	0.204	489	2.96	69.3				

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)													
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC		
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29		
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35		
MW-346 (duplicate) (-2.2 to -12.2)	Seattle DOT Mercer Parcels NW quadrant	06/02/21	PES	Bladder	—	—	—	0.0290 J	0.206	0.0212 U	0.191 U	25.3	6.09	18.1	0.0572 U	1.90		
		06/02/21	PES	Bladder	—	—	—	0.0290 J	0.194 J	0.0212 U	0.191 U	25.1	6.16	18.3	0.0572 U	1.93		
		08/18/21	PES	Bladder	—	—	—	0.0280 J	0.0860 J	0.0212 U	0.191 U	1.58	0.646	24.7	0.0880 J	1.11		
		03/31/22	PES	Bladder	—	—	—	0.0160 U	0.124 U	0.0212 U	0.191 U	0.228 J+	1.04	3.49	0.0572 U	1.04		
		05/24/22	PES	Bladder	—	—	—	0.0160 U	0.0690 J	0.0212 U	0.191 U	0.0640 J	0.921	4.18	0.0572 U	2.08		
		08/02/22	PES	Bladder	—	—	—	0.0940	2.17	0.168	0.825	0.0280 U	0.498	3.42	0.0572 U	2.47		
		11/10/22	PES	Bladder	—	—	—	0.0160 U	0.216	0.0212 U	0.191 U	0.0280 U	0.570	2.68	0.0572 U	1.54		
		02/23/23	PES	Bladder	—	—	—	0.0160 U	0.0820 J	0.0212 U	0.191 U	0.0280 U	0.624	3.10	0.0572 U	2.04		
		02/23/23	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.794	3.25	0.0572 U	2.12		
		05/16/23	PES	Bladder	—	—	—	0.0160 U	0.448	0.0400 J	0.310	0.0370 J	0.464	2.05	0.0572 U	2.01		
		05/16/23	PES	Bladder	—	—	—	0.0160 U	0.343	0.0500 J	0.284	0.0280 U	0.432	1.97	0.0572 U	1.77		
		08/15/23	PES	Bladder	—	—	—	0.0160 U	0.336	0.0800 J	0.420	0.0280 U	0.504	2.31	0.0572 U	2.11		
		08/15/23	PES	Bladder	—	—	—	0.0160 U	0.276	0.0520 J	0.372	0.0440 J	0.574	2.36	0.0572 U	1.61		
		11/08/23	PES	Bladder	—	—	—	0.0480	0.140 J	0.0212 U	0.191 U	0.0710 J	0.319	1.82	0.0572 U	0.423		
		02/27/24	PES	Bladder	—	—	—	0.0160 U	0.102 J	0.0212 U	0.191 U	0.0800 J	0.262	0.836	0.0572 U	0.463		
		02/27/24	PES	Bladder	—	—	—	0.0160 U	0.0980 J	0.0212 U	0.191 U	0.0660 J	0.198	0.872	0.0572 U	0.492		
		05/28/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.106	0.0520	0.528	0.0572 U	0.0273 U		
		05/28/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0850 J	0.0620	0.447	0.0572 U	0.0273 U		
		09/05/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.334	1.67	0.0572 U	1.40		
		09/05/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.333	1.43	0.0572 U	0.939		
		11/05/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.284	1.36	0.0572 U	1.20		
		11/05/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.323	1.34	0.0572 U	1.16		
MW-347 (-1.3 to -11.3)	Seattle DOT Mercer Parcels NW quadrant	06/01/21	PES	Bladder	—	—	—	0.0300 J	0.346	0.0212 U	0.191 U	5.19	3.83	123	0.291	66.9		
		08/19/21	PES	Bladder	—	—	—	0.0510	0.164 J	0.0310 J	0.191 U	7.46	4.72	100	0.807	25.7		
		03/31/22	PES	Bladder	—	—	—	0.0340 J	0.121 U	0.0330 J	0.191 U	25.8 J+	50.3	290	0.998	130		
		03/31/22	PES	Bladder	—	—	—	0.0220 J	0.109 U	0.0212 U	0.191 U	27.2 J+	40.4	280	0.915	150		
		05/26/22	PES	Bladder	—	—	—	0.0160 U	0.0770 U	0.0212 U	0.191 U	0.0770 J	0.225	148	0.556	68.0		
		08/02/22	PES	Bladder	—	—	—	0.0290 J	0.497	0.0770 J	0.636	0.0280 U	0.0160 U	30.6	0.219	58.3		
		11/10/22	PES	Bladder	—	—	—	0.0160 U	0.0760 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	15.8	0.134 J	28.7		
		02/23/23	PES	Bladder	—	—	—	0.0160 U	0.327	0.183	1.05	0.0280 U	0.0160 U	3.78	0.0572 U	9.64		
		05/16/23	PES	Bladder	—	—	—	0.0160 U	0.561	0.0740 J	0.518	0.0280 U	0.189	2.70	0.0572 U	12.6		
		08/15/23	PES	Bladder	—	—	—	0.0160 U	0.0550 U	0.0212 U	0.191 U	0.0970 J	0.231	1.61	0.0572 U	10.5		
		11/10/23	PES	Bladder	—	—	—	0.0160 U	0.0530 J	0.0212 U	0.191 U	0.0280 U	0.124	0.889	0.0572 U	8.19		
		02/27/24	PES	Bladder	—	—	—	0.0160 U	0.106 J	0.0212 U	0.191 U	0.217	0.148	1.43	0.0572 U	0.670		
		05/29/24	PES	Bladder	—	—	—	0.0280 J	0.0500 U	0.0212 U	0.191 U	0.143 J+	0.476	3.46	0.0630 J	10.7		
		09/04/24	PES	Bladder	—	—	—	0.0240 J	0.608	0.237	1.49	0.0280 U	0.098	0.502	0.0572 U	5.79		
		11/06/24	PES	Bladder	—	—	—	0.0160 U	0.0790 J	0.0212 U	0.191 U	0.0280 U	0.0960	0.829	0.0572 U	6.02		

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	—	77	0.35				
MW-348 (-4.6 to -14.6) (duplicate)	Seattle DOT Mercer Parcels SW quadrant	06/01/21	PES	Bladder	—	—	—	0.0190 J	0.170 J	0.0212 U	0.191 U	12.6	8.62	104	0.107 J	55.4				
		08/19/21	PES	Bladder	—	—	—	0.0190 J	0.0680 J	0.0212 U	0.191 U	5.38	7.77	68.2	0.0572 U	45.5				
		08/19/21	PES	Bladder	—	—	—	0.0270 J	0.0680 J	0.0212 U	0.191 U	5.41	8.30	66.6	0.0660 J	45.7				
		03/31/22	PES	Bladder	—	—	—	0.0340 J	0.165 U	0.0320 J	0.191 U	14.4 J+	19.6	318	0.0790 J	252				
		05/26/22	PES	Bladder	—	—	—	0.0460	0.0950 U	0.0212 U	0.191 U	6.62	14.0	160	0.150 J	126				
		08/01/22	PES	Bladder	—	—	—	0.160 U	1.51 J	0.212 U	1.91 U	0.280 U	2.38	167	1.15 J	123				
		11/10/22	PES	Bladder	—	—	—	1.78	1.00 U	0.424 U	3.82 U	0.560 U	0.320 U	49.4	1.14 U	13.9				
		03/13/23	PES	Bladder	—	—	—	0.320 U	1.00 U	0.424 U	3.82 U	0.560 U	0.320 U	166	1.14 U	145				
		05/17/23	PES	Bladder	—	—	—	0.160 U	0.680 UJ	0.212 U	1.91 U	0.280 UJ	0.160 UJ	95.6	0.572 U	111				
		08/16/23	PES	Bladder	—	—	—	0.0240 J	0.481	0.128	0.707	0.0280 U	0.250	76.1	0.0720 J	136				
		11/14/23	PES	Bladder	—	—	—	0.0170 J	1.07	0.0260 J	0.191 U	0.0280 U	0.164	12.9	0.0572 U	117				
		02/27/24	PES	Bladder	—	—	—	0.160 U	0.500 U	0.212 U	1.91 U	0.280 U	0.160 U	7.17	0.572 U	59.9				
		05/28/24	PES	Bladder	—	—	—	0.0210 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.165	6.90	0.0572 U	17.4				
		09/05/24	PES	Bladder	—	—	—	0.0160 U	0.058 J	0.0212 U	0.191 U	0.0280 U	0.109	2.15	0.0890 J	7.17				
		11/05/24	PES	Bladder	—	—	—	0.0200 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0470	0.869	0.0572 U	2.32				
MW-349 (-2.8 to -12.8)	Seattle DOT Mercer Parcels SW quadrant	06/01/21	PES	Bladder	—	—	—	0.0160 U	2.60	0.0400 J	0.191 J	0.611	0.474	7.23	0.0572 U	11.6				
		08/19/21	PES	Bladder	—	—	—	0.0160 U	0.168 J	0.0212 U	0.191 U	0.326	0.288	5.13	0.0572 U	17.6				
		03/30/22	PES	Bladder	—	—	—	0.0290 J	0.836	0.243	1.33	0.0280 U	0.319	47.1	0.0572 U	68.0				
		05/26/22	PES	Bladder	—	—	—	0.0160 U	0.312	0.0212 U	0.191 U	0.105	0.146	23.0	0.0572 U	30.9				
		08/01/22	PES	Bladder	—	—	—	0.0380 J	1.27	0.151	0.817	0.126	0.203	12.8	0.0572 U	23.2				
		11/08/22	PES	Bladder	—	—	—	0.0160 UJ	0.702 J	0.0212 UJ	0.191 UJ	0.0430 J	0.240 J+	4.95 J	0.0572 UJ	9.84 J				
		02/23/23	PES	Bladder	—	—	—	0.0160 U	0.623	0.0212 U	0.191 U	0.0280 U	0.0160 U	2.57	0.0572 U	8.66				
		05/16/23	PES	Bladder	—	—	—	0.0160 U	0.998	0.160	0.915	0.0280 U	0.0630	1.36	0.0572 U	4.90				
		08/15/23	PES	Bladder	—	—	—	0.0160 U	0.117 U	0.0212 U	0.191 U	0.0410 J	0.0720	1.44	0.0572 U	4.30				
		11/13/23	PES	Bladder	—	—	—	0.0160 U	0.412	0.0212 U	0.191 U	0.0280 U	0.0440 U	0.993	0.0572 U	2.50 J-				
		02/27/24	PES	Bladder	—	—	—	0.0160 U	0.246	0.0490 J	0.328	0.0280 U	0.0160 U	0.518	0.0572 U	1.71				
		05/28/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0420	0.400	0.0572 U	0.449				
		09/04/24	PES	Bladder	—	—	—	0.0160 U	0.193 J	0.0990 J	0.602	0.0280 U	0.0480	0.430	0.0572 U	1.27				
		11/06/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.376	0.0572 U	0.554				
MW-350 (-1.7 to -11.7)	Seattle DOT Mercer Parcels NW quadrant	06/01/21	PES	Bladder	—	—	—	1.16	10.9	11.5	56.7	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U				
		08/18/21	PES	Bladder	—	—	—	0.123	0.840	0.690	3.42	0.0280 U	0.0160 U	0.149	0.0572 U	0.573				
		11/11/22	PES	Bladder	—	—	—	0.0160 U	0.0990 U	0.0810 J	0.331	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.672 J-				
		02/24/23	PES	Bladder	—	—	—	0.0160 U	0.0930 J	0.0212 U	0.306	0.0280 U	0.0160 U	0.0276 U	0.0572 U	1.06				
		05/17/23	PES	Bladder	—	—	—	0.022 U	0.248 UJ	0.0520 U	0.315 U	0.0280 UJ	0.0160 U	0.0276 UJ	0.0572 UJ	1.61 U				
		08/15/23	PES	Bladder	—	—	—	0.0160 U	0.172 U	0.0340 J	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	2.89				
		11/13/23	PES	Bladder	—	—	—	0.0300 J	0.116 J	0.0550	0.200 J	0.0280 U	0.0160 U	0.0276 U	0.0572 U	3.50 J-				
		02/28/24	PES	Bladder	—	—	—	0.0160 J	0.146 J	0.0450 J	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	19.7 J+				
		05/29/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.016 U	0.0276 U	0.0572 U	0.0273 U				
		09/05/24	PES	Bladder	—	—	—	0.0160 U	0.255	0.0940 J	0.495	0.0280 U	0.0160 U	0.0276 U	0.0572 U	19.0				
		11/07/24	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	33.8				
PW-1 (--)	North Valley St ROW	997 (8 hou	B&V	Bailer	250	U	630	U	630	U	ND	ND	ND	ND	ND	ND				
		1997 (Final Decommissioned	B&V	Bailer	250	U	630	U	630	U	ND	ND	ND	ND	ND	ND				

Page 13 of 14

S141300110R 3526 Table 5 - GW Intermediate B.xlsm

Table 5
Groundwater Petroleum Hydrocarbons and CVOCs in Intermediate B Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																				
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC									
Preliminary Cleanup Level					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29									
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35									
W-MW-02 (continued) (duplicate)		06/12/18	PES	Bladder	31.6	U	–	–	0.0896	U	0.829	0.158	U	0.316	U	0.199	U	0.153	U	4.72	0.279	J	4.95		
		10/26/18	PES	Peristaltic	90.2	UJ	–	–	0.0896	U	0.641	0.158	U	0.316	U	0.199	U	0.153	U	2.01	0.410	J	1.41		
		10/26/18	PES	Peristaltic	246	J+	–	–	0.0896	U	0.587	0.158	U	0.316	U	0.199	U	0.153	U	2.11	J+	0.435	J	1.80	
		12/12/18	PES	Peristaltic	158	UJ	–	–	0.0896	U	1.05	0.158	U	0.316	U	0.199	U	0.153	U	1.80	0.463	J	2.30		
		01/25/19	PES	Peristaltic	37.4	J	–	–	0.133	J	2.09	0.158	U	0.316	U	0.199	U	0.153	U	1.83	0.263	J	2.01		
		03/11/19	PES	Peristaltic	31.6	U	–	–	0.0896	U	1.12	0.158	U	0.316	U	0.199	U	0.153	U	2.41	0.316	J	2.43		
		04/23/19	PES	Peristaltic	429	zJ+	–	–	0.0896	U	0.56	0.158	U	0.316	U	0.199	U	40.1	672	2.35	81.0	J			
		07/23/19	PES	Bladder	31.6	U	–	–	0.0896	U	1.35	0.158	U	0.316	U	0.199	U	0.153	U	3.30	0.386	J	6.79		
		10/18/19	PES	Bladder	316	U	–	–	0.0896	U	1.79	0.158	U	0.316	U	0.199	U	0.153	U	2.07	0.278	J	3.56		
		01/28/20	PES	Bladder	31.6	U	–	–	0.0896	U	2.93	0.158	U	0.316	U	0.199	U	0.153	U	1.52	0.252	J	1.70		
		04/01/20	PES	Bladder	31.6	U	–	–	0.0896	U	2.51	0.158	U	0.316	U	0.199	U	0.153	U	1.44	0.166	J	1.42		
		07/31/20	PES	Bladder	–	–	–	–	0.0502		0.387	0.0212	U	0.191	U	0.0280	U	0.136	1.39	J	0.204	J	1.08		
W-MW-03 (-30.8 to -40.8)	Property	02/03/12	WW	Bladder	–	–	–	–	20	U	20	U	20	U	60	U	5,300	220	160	20	U	20	U		
		09/06/12	SES	Peristaltic	–	–	–	–	0.35	U	1	U	1	U	3	U	13	2.6	20	1	U	120			
W-MW-04 ^a (-32.5 to -41.5)	Property	02/03/12	WW	Bladder	–	–	–	–	20	U	20	U	20	U	60	U	5,400	160	54	20	U	20	U		
		09/06/12	SES	Peristaltic	–	–	–	–	0.35	U	1	U	1	U	3	U	460	440	1,900	4.0		630			
Number of Analytes Measured					93		20	18	515		515		515		515		525		525		525		525		
Number of Analytes Detected					10		4	0	165		208		84		86		148		251		373		171		
Frequency of Detection					11%		20%	0%	32%		40%		16%		17%		28%		48%		71%		33%		
Maximum Detection					580	J	–	–	56.1	J	10.9		11.5		56.7		97,200		18,700		127,000		781		
Minimum Detection					31.6	U	50	U	250	U	0.0160	U	0.0500	U	0.0212	U	0.1740	U	0.0280	U	0.0160	U	0.0276	U	
Number of Analytes Detected Above SL					0		0	0	21		0		0		0		68		91		172		7		
Frequency of Detection Above SL					0%		0%	0%	4%		0%		0%		0%		13%		17%		33%		1%		

Notes:

PCULs and Screening Levels from Washington State Department of Ecology, Memorandum from P. Tomlinson to TCP File for American Linen Supply Co. Dexter Ave. (FSID 3573, CSID 12004) re: Development of site-specific preliminary cleanup levels, December 14, 2021.

Detections above the groundwater PCUL level are shown in **bold and highlighted in gray**.

B&V = Black & Veatch

cDCE = cis-1,2-Dichloroethene

DOF = Dalton, Olmsted & Fuglevand, Inc.

DRO = Diesel-range organics

GeoE = GeoEngineers Inc.

GRO = Gasoline-range organics

HC = Hart Crowser

ORO = Oil-range organics

PCE = Perchloroethylene (Tetrachloroethene)

ROW = right-of-way

SES = SES Strategies, Inc.

TCE = Trichloroethene

tDCE = trans-1,2-Dichloroethene

VC = Vinyl chloride

WW = Windward

Well screen elevations indicated below Sample Location in parentheses.

(--) = unknown screen elevation.

a = Monitoring well was installed at a 25 degree angle from the vertical point of penetration.

Laboratory and Results Notes:

Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID, or NWTPH-Gx, NWTPH-Dx, or 8015-M.

VOCs analyzed by EPA Method 601, 8010S, 8015, 8020, 8021B, 8240, 8260B, 8260C, or 8260D, or by Purge and Trap Gas Chromatogram/Mass Spectrometry.

– = Not analyzed or results not available.

E = Estimated value. The reported range exceeds the calibration range of the analysis.

f = Analyte was detected in the associated method blank. Analyte concentration in the sample is greater than 10x the concentration found in the method blank.

g = Estimated value. The reported range exceeds the calibration range of the analysis.

ht = The analysis was performed outside the method the method or client-specified holding time requirement.

J = The identification of the analyte is acceptable; the reported value is an estimate.

J+ = The result is an estimated quantity, but the result may be biased high.

J- = The result is an estimated quantity, but the result may be biased low.

ND = Not detected at a concentration exceeding laboratory reporting limit; detection limit not provided.

pr = The sample was received with incorrect preservation. The value reported should be considered an estimate.

U = Not detected at or above the laboratory method detection limit (MDL).

qp = Hydrocarbon result partly due to individual peak(s) in quantitation range.

x = The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

y = The GRO result in the sample is due to a pattern of peaks that is consistent with the chlorinated volatiles detected by the 8260C analysis.

z = No/low level gasoline/petroleum detection; result is likely elevated due to high detections of CVOCs.

Groundwater statistics are for data collected during the Remediation Investigation, 2017-2021.

Groundwater statistics for GRO exclude "z" qualified data.

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC					
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29					
HMW-1D (-41.9 to -51.9)	Seattle DOT Mercer Parcels, NE quadrant	03-25-19	HC	Peristaltic	100	U	200	U	500	U	1.0	U	1.0	U	1.0	U	3.4	27	410	1.2	4.0
		03-09-20	HC	Submersible	140		94	J	250	U	20	U	20	U	40	U	21	110	910	20	6.0
HMW-2D (-32.7 to -42.7)	Seattle DOT Mercer Parcels, NE quadrant	03-25-19	HC	Peristaltic	100	U	200	U	500	U	1.0	U	1.0	U	1.0	U	1.0	U	1.0	U	0.2
		03-12-20	HC	Submersible	100	U	86	J	250	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	U	0.20
HMW-3D (-23.4 to -33.4)	Seattle DOT Mercer Parcels, NW quadrant	03-25-19	HC	Peristaltic	100	U	200	U	500	U	1.0	U	1.1	U	1.0	U	1.0	U	1.0	U	0.2
		03-13-20	HC	Submersible	100	U	480	J	250	U	0.20	U	0.20	U	0.40	U	0.20	U	0.20	UJ	0.20
HMW-6D (-21.1 to -31.1)	Seattle DOT Mercer Parcels, SW quadrant	03-16-20	HC	Submersible	100	U	50	U	250	U	0.42		0.64		0.20	U	0.40	U	0.20	U	0.20
HMW-9D (-24.4 to -34.4)	Seattle DOT Mercer Parcels, SW quadrant	03-17-20	HC	Submersible	100	U	230	J	250	U	0.21		0.42		0.20	U	0.89		5.1	0.20	0.97
HMW-10D (-30.8 to -40.8)	Seattle DOT Mercer Parcels, SE quadrant	03-16-20	HC	Submersible	100	U	50	U	250	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20
HMW-12D (-48.5 to -58.5)	Seattle DOT Mercer Parcels, NE quadrant	09-10-20	HC	—	100	U	50	U	—		0.20	U	0.20	U	0.20	U	0.20	U	200	J	0.22
HMW-13D (-44.2 to -54.2)	Seattle DOT Mercer Parcels, SE quadrant	09-10-20	HC	—	100	U	50	U	—		0.20	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20
HMW-14D (-23.7 to -33.7)	Seattle DOT Mercer Parcels, SE quadrant	09-16-20	HC	—	100	U	50	U	—		0.20	U	0.20	U	0.20	U	0.20	U	0.20	U	0.20
MW101 (-65.5 to -75.5)	Property, NE quadrant	07-20-12	SES	Bladder	—	—	—	—	—	—	—	U	1	U	1	U	1	U	1	U	0.2
		09-06-12	SES	Peristaltic	—	—	—	0.35	U	1.4		U	1	U	3	U	1	U	1	U	0.2
MW102 (-65.8 to -75.8)	Valley St ROW, S side	08-16-12	SES	Peristaltic	—	—	—	—	—	—	—	U	1	U	1	U	1	U	1	U	0.2
		09-05-12	SES	Bladder	—	—	—	0.35	U	1	U	1	U	3	U	1	U	1	U	1	U
(duplicate)		12-17-13	SES	Bladder	—	—	—	0.35	U	1	U	1	U	3	U	1	U	1	U	1	U
		10-27-15	SES	Bladder	—	—	—	—	—	—	—	U	1	U	1	U	1	U	1	U	0.2
		02-02-16	SES	Bladder	—	—	—	—	—	—	—	U	1	U	1	U	1	U	1	U	0.2
		03-29-17	PES	Bladder	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.289	J
		06-15-17	PES	Bladder	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		04-25-18	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.352	J	0.153	U	0.0933	U
		01-24-19	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.220	J	0.153	U	0.0933	U
		05-01-19	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		07-18-19	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		11-14-19	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		01-23-20	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		01-23-20	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		04-02-20	PES	Bladder	31.6	U	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U
		08-04-20	PES	Bladder	—	—	—	0.0160	U	1.00		0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U
		08-04-20	PES	Bladder	—	—	—	0.0160	U	0.880		0.0340	J	0.191	U	0.0280	U	0.0160	U	0.0276	U
		11-18-20	PES	Bladder	—	—	—	0.0160	U	0.0710	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U
(duplicate)		02-03-21	PES	Bladder	—	—	—	0.0160	U	0.0880	J	0.0390	J	0.282		0.0280	U	0.0160	U	0.0276	U
		05-14-21	PES	Bladder	—	—	—	0.0160	U	0.196	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U
		08-11-21	PES	Peristaltic	—	—	—	0.0350	J	0.919		0.115		0.508		0.0280	U	0.0160	U	0.0276	U
		11-30-21	PES	Bladder	—	—	—	0.0160	U	0.181	J	0.183		0.959		0.0280	U	0.0160	U	0.0276	U
		03-07-22	PES	Bladder	—	—	—	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U
		03-07-22	PES	Bladder	—	—	—	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U
		05-10-22	PES	Bladder	—	—	—	0.0160	U	0.528		0.0212	U	0.439		0.0280	U	0.0160	U	0.0276	U
		08-12-22	PES	Bladder	—	—	—	0.0160	U	0.176	U	0.0340	J	0.285		0.0280	U	0.0160	U	0.0276	U
		10-31-22	PES	Bladder	—	—	—	0.0160	U	0.174	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC	
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
MW102 (continued)		05-12-23	PES	Bladder	—	—	—	0.0160	U	0.0500	U	0.0212	U	0.194	J	0.0400	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U			
		11-06-23	PES	Bladder	—	—	—	0.0160	U	0.377		0.0212	U	0.647		0.0690	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U			
		05-28-24	PES	Bladder	—	—	—	0.330		2.13		0.330		1.94		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U			
		11-06-24	PES	Bladder	—	—	—	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0610	J	0.0160	U	0.0276	U	0.0572	U	0.0273	U			
MW103 (-67.6 to -77.6) (duplicate)	lley E of Seattle Roy Aloha Shop	07-31-12	SES	Peristaltic	—	—	—	—		—	—	—	—	—	12		25		150		10	U	79					
		09-05-12	SES	Peristaltic	—	—	—	0.35	U	1.6		1	U	3	U	8.3		22		80		1	U	110				
		09-05-12	SES	Peristaltic	—	—	—	0.35	U	1.6		1	U	3	U	8.1		22		85		1	U	120				
(duplicate)		12-18-13	SES	Peristaltic	—	—	—	0.35	U	2.4		1	U	3	U	4.3		6.1		8.6		1	U	1.2				
		12-18-13	SES	Peristaltic	—	—	—	0.35	U	2.4		1	U	3	U	4.0		5.2		7.1		1	U	0.94				
		06-17-15	SES	Peristaltic	—	—	—	—		—		—		—		1.8		1.4		1	U	1	U	0.94				
		10-20-15	SES	Peristaltic	—	—	—	—		—		—		—		3.6		1.4		1	U	1	U	1.6				
		02-02-16	SES	Peristaltic	—	—	—	—		—		—		—		1.0		1	U	1.2		1	U	0.53				
		03-29-17	PES	Peristaltic	—	—	—	0.0896	U	0.464	J	0.158	U	0.316	U	1.99	U	23.1		240		0.405	J	157				
		06-14-17	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.626		23.0		120		0.369	J	69.2				
		04-06-18	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	1.81		32.4		0.152	U	22.4				
		01-23-19	PES	Peristaltic	—	—	—	0.0896	U	1.35		0.158	U	0.316	U	0.365	J	1.48		11.4		0.152	U	6.68				
		04-22-19	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	3.09		88.0		0.209	J	32.3	J			
		07-15-19	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	2.37		118		0.232	J	55.4				
		10-14-19	PES	Peristaltic	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	91.7		0.158	J	51.8				
(duplicate)		01-16-20	PES	Bladder	—	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	40.6		0.152	U	77.9				
		04-23-20	PES	Bladder	—	—	—	0.0941	U	0.278	U	0.137	U	0														

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												VC
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE		
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29	
MW113 (continued) (split) (split) (split) (duplicate)		03-24-20	Farallon	Peristaltic	—	—	—	—	—	—	—	20 U	20 U	4,100	20 U	200	
		04-27-20	PES	Peristaltic	—	—	—	9.41 U	27.8 U	13.7 U	17.4 U	30.0 U	19.0 U	4,320	14.9 U	75.9	
		04-27-20	Farallon	Peristaltic	—	—	—	—	—	—	—	20 U	20 U	3,500	20 U	94	
		05-19-20	Farallon	Unknown	—	—	—	—	—	—	—	20 U	20 U	3,700	20 U	110	
		07-28-20	PES	Bladder	—	—	—	9.41 U	27.8 U	13.7 U	17.4 U	212	1,540	3,100	14.9 U	76.0	
		07-28-20	Farallon	Bladder	—	—	—	—	—	—	—	170	1,300	2,300	10 U	82	
		09-17-20	Farallon	Unknown	—	—	—	—	—	—	—	390	1,500	1,900	10 U	45	
		11-24-20	PES	Bladder	—	—	—	1.60 U	5.00 U	2.12 U	19.1 U	706	1,380	1,290	8.30 J	11.9	
		12-03-20	Farallon	Unknown	—	—	—	—	—	—	—	480	800	540	4.0 U	6.4	
		02-10-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	3.04	4.18	39.1	0.0780 J	0.0710 J	
		02-10-21	Farallon	Peristaltic	—	—	—	—	—	—	—	2.7	8.4	26	0.20 U	0.20 U	
		05-25-21	PES	Peristaltic	—	—	—	0.331	0.127 U	0.0212 U	0.191 U	249	944	1,380	8.60	6.91	
		08-11-21	PES	Peristaltic	—	—	—	3.38	1.25 U	0.530 U	4.78 U	87.0	617	2,180	8.75	8.65	
		11-18-21	PES	Peristaltic	—	—	—	3.73	1.25 U	0.530 U	4.78 U	70.6 J+	795	4,250	15.0	9.15	
		11-18-21	PES	Peristaltic	—	—	—	4.34	0.0950 J	0.0212 U	0.191 U	57.2	751	5,080	16.1	10.2	
		02-15-22	PES	Peristaltic	—	—	—	5.75 J	12.5 U	5.30 U	47.8 U	21.3 J	30.8	5,960	18.0 J	6.82 U	
		06-08-22	PES	Peristaltic	—	—	—	3.00	1.25 U	0.530 U	4.78 U	28.7	49.1	6,220	11.9	9.18	
		08-10-22	PES	Peristaltic	—	—	—	3.80 J	5.00 U	2.80 J	19.1 U	14.4	10.9	3,790	14.0 J	73.6	
		11-03-22	PES	Peristaltic	—	—	—	2.29	0.0500 U	0.0212 U	0.191 U	20.8	43.9	5,530	15.0	24.6	
MW122 (-75 to -89)	Iley E of Seattle Roy Aloha Shop	05-18-23	PES	Peristaltic	—	—	—	0.135 J	0.280 U	0.106 UJ	0.955 UJ	2.78 J	0.900 J	8.65 J	0.286 UJ	116 J	
		08-16-23	PES	Peristaltic	—	—	—	0.0800 U	0.121 J	0.318	1.32	1.55	1.450	22.1	0.190 J	66.1	
		11-08-23	PES	Peristaltic	—	—	—	0.0800 U	0.250 U	0.106 U	0.955 U	0.980	2.05	14.1	0.286 U	4.53	
		05-24-24	PES	Peristaltic	—	—	—	0.0210 J	0.0500 U	0.0212 U	0.191 U	2.13	6.50	58.4	0.501	0.148 J+	
		11-07-24	PES	Peristaltic	—	—	—	0.0170 J	0.0500 U	0.0212 U	0.191 U	1.97	7.30	57.2	0.441	0.0670 J	
		12-23-13	SES	Peristaltic	—	—	—	0.35 U	1 U	1 U	3 U	1 U	1 U	1 U	1 U	0.2 U	
		10-20-15	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	1 U	1 U	0.2 U	
		02-02-16	SES	Peristaltic	—	—	—	—	—	—	—	1 U	1 U	1 U	1 U	0.2 U	
		03-28-17	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		06-14-17	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.162 J	0.0933 U	0.152 U	0.118 U	
		04-06-18	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		10-14-19	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.289 J	0.153 U	0.0933 U	0.152 U	0.118 U	
		01-17-20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 UJ	
		04-07-20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U	
		07-24-20	PES	Peristaltic	—	—	—	0.0160 U	0.0880 J	0.0212 U	0.191 U	0.0540 J	0.0160 U	0.0276 U	0.0572 UJ	0.0273 U	
		11-06-20	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		05-03-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0360 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		11-11-21	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0360 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		05-18-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0370 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		11-01-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0810 J	0.0572 U	0.0273 U	
		05-12-23	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.167	0.0780	0.269	0.0572 U	0.0273 U	
		11-07-23	PES	Peristaltic	—	—	—	0.0190 J	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		05-21-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0580 J	0.0160 U	0.0276 U	0.0572 U	0.0273 U	
		11-12-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0670 J	0.0160 U	0.0400 U	0.0572 U	0.0273 U	

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC			
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
MW-140 (duplicate)	Roy St ROW, N side	09-22-17	PES	Bladder	—		—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.450	J	0.477	J	0.152	U	0.118	U
		09-22-17	PES	Bladder	—		—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.456	J	0.523		0.152	U	0.118	U
		04-12-18	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.402	J+	0.572	J+	2.47	J+	0.152	U	0.246	J+
		Decommissioned																										
MW-141	Property, SE quadrant	09-22-17	PES	Bladder	—		—		—		0.0896	U	0.941		0.158	U	0.316	U	0.199	U	0.153	U	0.345	J	0.152	U	0.457	J
		04-12-18	PES	Submersible	326	zJ+	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	71.3	J+	25.6	J+	91.6	J+	5.68	J+	7.01	J+
		10-25-18	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	3.10		0.152	U	0.118	U
		12-12-18	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	1.46		0.152	U	0.520	
		01-30-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.479	J	0.152	U	0.118	U
		03-11-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.701		0.153	U	1.30		0.152	U	0.557	
Decomissioned March 2019																												
MW-153 (-65.3 to -75.3) (duplicate)	Roy St ROW, S side	05-01-18	PES	Bladder	31.6	J	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.756		0.153	U	0.612		0.152	U	9.56	
		01-22-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	1.41		0.152	U	15.9	
		04-24-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	1.07		0.152	U	2.69	J
		04-24-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.975		0.152	U	1.66	J
		07-22-19	PES	Bladder	31.6	U	—		—		0.177	J	0.716		0.227	J	0.819	J	0.199	U	0.190	J	0.384	J	0.152	U	0.235	J
		10-15-19	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01-21-20	PES	Bladder	31.6	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		04-30-20	PES	Bladder	38.2	J	—		—		0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE	TCE	cDCE	tDCE	VC							
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
MW-161 (continued)		05-11-22	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.629		15.4		30.5		0.557		1.67	
		08-12-22	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	1.32		7.14		28.5		0.395		2.54	
(duplicate)		10-31-22	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.407		0.545		31.3		0.451		8.13	
		10-31-22	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.307		0.557		30.3		0.441		7.90	
(duplicate)		05-15-23	PES	Bladder	—		—		—		0.0160	U	0.102	J	0.0212	U	0.191	U	0.604		3.18		19.5		0.271		1.68	
		05-15-23	PES	Bladder	—		—		—		0.0160	U	0.0590	J	0.0212	U	0.191	U	0.648		3.97		22.2		0.309		2.18	
(duplicate)		11-06-23	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.227		2.11		32.5		0.465		2.73	
		11-06-23	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.202		2.17		32.1		0.469		2.75	
(duplicate)		05-22-24	PES	Peristaltic	—		—		—		0.0160	U	0.0900	J	0.0212	U	0.191	U	0.0280	U	3.13		21.5		0.223		0.340	J-
		05-22-24	PES	Peristaltic	—		—		—		0.0160	U	0.0920	J	0.0212	U	0.191	U	0.0280	U	3.18		19.9	J-	0.281		0.369	J-
(duplicate)		11-08-24	PES	Peristaltic	—		—		—		0.0160	U	0.0690	J	0.0440	J	0.287		0.392		0.986		16.1		0.322		10.3	
		11-08-24	PES	Peristaltic	—		—		—		0.0160	U	0.0640	J	0.0410	J	0.214	J	0.380		0.896		16.7		0.346		10.7	
MW-162 (-61.6 to -71.6)	Property, NE quadrant	02-05-19	PES	Bladder	—		—		—		1.00	U	1.00	U	1.00	U	1.00	U	2,800		613		1,070		9.58		128	
		03-12-19	PES	Peristaltic	690	zJ+	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	613		538		758		2.63		46.5	
		Decomissioned March 2019																										
MW-163 (duplicate) (-61.0 to -71.0)	Property, NW quadrant	02-05-19	PES	Bladder	—		—		—		1.00	U	1.00	U	1.00	U	1.00	U	218		150		42.2		1.00	U	2.95	
		02-05-19	PES	Bladder	—		—		—		1.00	U	1.00	U	1.00	U	1.00	U	220		153		40.3		1.00	U	3.45	
		03-12-19	PES	Bladder	319	zJ+	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	282		334		56.9		2.87		1.10	
Decomissioned March 2019																												
MW-164 (-59.9 to -69.9)	Property, SW quadrant	02-05-19	PES	Bladder	—		—		—		1.00	U	1.80		1.00	U	1.00	U	871		372		385		3.41		4.41	
		03-12-19	PES	Bladder	565	zJ+	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	444		327		529		4.24		7.80	
		Decomissioned March 2019																										
MW-304 (-47.6 to -57.6)	Dexter Ave N ROW, E side	10-21-19	PES	Bladder	97.9	J	—		—		0.0896	U	0.728		0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		01-27-20	PES	Bladder	42.2	U	—		—		0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U
		05-07-20	PES	Bladder	31.6	U	—		—		0.0941	U	0.278	U	0.137	U	0.174	U	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		07-27-20	PES	Bladder	—		—		—		0.0160	U	2.63		0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05-18-21	PES	Bladder	—		—		—		0.0160	U	0.357		0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11-08-21	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0800	J	0.527		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05-25-22	PES	Bladder	—		—		—		0.0160	U	0.0810	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11-09-22	PES	Bladder	—		—		—		0.0160	U	0.308		0.0520	J	0.276		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	UJ
		05-09-23	PES	Bladder	—		—		—		0.0250	J	1.03		0.288		1.68		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		10-31-23	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		05-22-24	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	UJ	0.0572	U	0.0273	UJ
		11-13-24	PES	Bladder	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)													
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC		
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29		
MW-319 (-42.8 to -52.8)	9th Ave N ROW, W side	10-08-19	PES	Bladder	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.609	8.12	53.4	0.152 U	5.76	J+	
		01-16-20	PES	Peristaltic	—	—	—	0.0896 U	0.412 U	0.158 U	0.316 U	0.414 J	11.4	63.7	0.152 U	6.78		
		04-27-20	PES	Bladder	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	10.7	54.1	0.149 U	4.52		
		07-27-20	PES	Bladder	—	—	—	0.0336 J	0.399	0.0450 J	0.207 J	0.0933 J	13.6	49.2	0.0806 J	4.77		
		11-12-20	PES	Bladder	—	—	—	0.0160 U	0.0500 UJ	0.0212 U	0.191 U	0.110	13.9	47.6	0.0572 U	4.58		
		05-19-21	PES	Peristaltic	—	—	—	0.0160 U	0.0700 U	0.0212 U	0.191 U	0.0900 J	8.52	37.4	0.104 J	4.16		
		11-08-21	PES	Peristaltic	—	—	—	0.0190 J	0.0500 U	0.0212 U	0.191 U	0.0780 J	6.72	37.0	0.100 J	4.25		
		05-27-22	PES	Peristaltic	—	—	—	0.0250 J	0.0500 U	0.0212 U	0.191 U	0.145	6.93	44.1	0.0590 J	5.19		
		11-02-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0900 J	4.72	60.8	0.138 J	5.83		
		11-02-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0890 J	5.11	59.8	0.136 J	5.60		
		05-17-23	PES	Peristaltic	—	—	—	0.159	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.490	4.17	0.0572 U	3.37		
		11-08-23	PES	Peristaltic	—	—	—	0.0360 J	0.0560 J	0.0212 U	0.191 U	0.0280 U	1.03	65.2	0.142 J	3.96		
		11-08-23	PES	Peristaltic	—	—	—	0.0410	0.0500 U	0.0212 U	0.191 U	0.0460 J	1.07	64.9	0.116 J	3.82		
		05-22-24	PES	Peristaltic	—	—	—	0.0300 J	0.0500 U	0.0212 U	0.191 U	0.252	1.21	51.4 J-	0.145 J	4.72		
		11-06-24	PES	Peristaltic	—	—	—	0.0370 J	0.0500 U	0.0212 U	0.191 U	0.0380 J	1.05	66.2	0.161 J	6.39		
MW-323 (-65.4 to -75.4)	9th Ave N ROW, W side	10-09-19	PES	Peristaltic	—	—	—	0.0896 U	4.97	0.158 U	0.316 U	0.199 U	0.891	66.5	0.152 U	13.4	J-	
		01-20-20	PES	Peristaltic	—	—	—	0.0896 U	0.549	0.158 U	0.316 U	0.199 U	0.178 J	229	0.152 U	64.9		
		04-23-20	PES	Bladder	—	—	—	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	5.11	0.149 U	4.14		
		07-07-20	PES	Bladder	—	—	—	0.0160 U	1.76	0.0212 U	0.191 U	0.0280 U	0.0300 J	2.55	0.0572 U	4.58		
		11-24-20	PES	Bladder	—	—	—	0.0160 U	0.0960 U	0.0212 U	0.191 U	0.0280 U	0.0260 J	2.68	0.0572 U	4.89		
		05-20-21	PES	Peristaltic	—	—	—	0.0160 U	0.114 U	0.0212 U	0.191 U	0.0280 U	0.0900	115	0.111 J	31.4		
		11-16-21	PES	Peristaltic	—	—	—	0.0390 J	0.320	0.0690 J	0.597	0.0280 U	0.100	384	0.304	52.2		
		06-03-22	PES	Peristaltic	—	—	—	0.400 U	1.25 U	0.530 U	4.78 U	0.700 U	0.400 U	354	1.43 U	45.5		
		11-04-22	PES	Peristaltic	—	—	—	0.0490	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0990	374	0.539	77.2		
		05-17-23	PES	Peristaltic	—	—	—	0.320 U	1.00 U	0.424 U	3.82 U	0.560 U	0.320 U	535	1.14 U	77.2		
		11-08-23	PES	Peristaltic	—	—	—	0.0540	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0800	522	0.611	50.0		
		05-22-24	PES	Peristaltic	—	—	—	0.0450	0.0800 J	0.0212 U	0.191 U	0.0280 U	0.0700	547	0.671	62.5		
		11-07-24	PES	Peristaltic	—	—	—	0.0500	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0480	527	0.517	73.1		
MW-324 (-32.1 to -42.1)	Roy St ROW, N side	10-02-19	PES	Bladder	—	—	—	0.401 J	5.45	0.158 U	0.316 U	0.199 U	0.642	1,550	3.21	61.9	J	
		01-20-20	PES	Peristaltic	—	—	—	4.48 U	20.6 U	7.90 U	15.8 U	9.95 U	7.65 U	3,170	7.60 U	113		
		04-24-20	PES	Bladder	—	—	—	4.71 U	13.9 U	6.85 U	8.70 U	15.0 U	9.50 U	8,520	16.8 J	362		
		07-07-20	PES	Bladder	—	—	—	1.25 J	2.50 U	1.06 U	9.55 U	1.400 U	0.800 U	8,410	13.6	244		
		11-13-20	PES	Bladder	—	—	—	2.51	2.50 U	1.06 U	9.55 U	1.40 U	0.800 U	7,210	13.7	184		
		05-20-21	PES	Peristaltic	—	—	—	0.800 U	2.50 U	1.06 U	9.55 U	1.40 U	1.95 J	3,470	10.5	45.6		
		11-16-21	PES	Peristaltic	—	—	—	1.60 J	2.50 U	1.06 U	9.55 U	1.40 U	0.800 U	2,240	9.00 J	29.2		
		05-31-22	PES	Peristaltic	—	—	—	2.55	2.50 U	1.06 U	9.55 U	1.40 U	0.800 U	3,200	13.7	101		
		11-03-22	PES	Peristaltic	—	—	—	1.03	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.147	1,650	6.55	74.0		
		05-18-23	PES	Peristaltic	—	—	—	1.20	1.25 U	0.530 U	4.78 U	0.700 U	0.400 U	2,090	6.93	95.3		
		11-08-23	PES	Peristaltic	—	—	—	0.654	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0930	895	4.44	40.6		
		05-23-24	PES	Peristaltic	—	—	—	0.700 J	1.25 U	0.530 U	4.78 U	0.700 U	0.400 U	931	3.97 J	47.3		
		11-07-24	PES	Peristaltic	—	—	—	0.400 U	1.25 U	0.530 U	4.78 U	2.25 J	0.400 U	1,600	8.65	38.1		

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)														
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC			
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29			
MW-326 (-48.7 to -58.7)	Mercer St ROW, N side	10-03-19	PES	Bladder	—	—	—	0.0896 U	1.31	0.158 U	0.316 U	0.769	0.297 J	6.87	0.152 U	0.118 U			
		01-17-20	PES	Bladder	—	—	—	0.113 J	0.412 U	0.158 U	0.316 U	0.834	0.470 J	9.38	0.152 U	0.118 U			
		04-21-20	PES	Bladder	—	—	—	0.108 J	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	0.971	0.149 U	0.515 J			
		07-23-20	PES	Bladder	—	—	—	0.0390 J	0.120 J	0.0212 U	0.191 U	0.0280 U	0.0430	0.277	0.0572 U	0.201			
		11-02-20	PES	Bladder	—	—	—	0.0740	0.165 J	0.0212 U	0.191 U	0.0280 U	0.0260 J	0.224	0.0572 U	0.332			
		02-09-21	PES	Bladder	—	—	—	0.0680	0.540	0.0570 J	0.427	0.183	0.263 J+	3.40	0.0572 U	0.182 J			
		05-18-21	PES	Bladder	—	—	—	0.0160 U	0.206	0.0212 U	0.191 U	0.219	0.496	3.53	0.0572 U	0.109			
		08-12-21	PES	Peristaltic	—	—	—	0.0420	0.468	0.0600 J	0.291	0.138	0.599	3.52	0.0572 U	0.206			
		11-04-21	PES	Bladder	—	—	—	0.0160 U	0.0540 J	0.0630 J	0.449	0.0850 J	0.638	4.15	0.0572 U	0.186			
		03-03-22	PES	Bladder	—	—	—	0.0160 U	0.0660 U	0.0212 U	0.191 U	0.316	1.21	8.16	0.0572 U	0.0273 U			
		05-09-22	PES	Bladder	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.200	0.860	6.59	0.0572 U	0.164			
		08-11-22	PES	Bladder	—	—	—	0.0160 U	0.0560 U	0.0212 U	0.191 U	2.26	1.74	7.63	0.0572 U	0.0273 U			
		11-02-22	PES	Bladder	—	—	—	0.0160 U	0.236	0.0212 U	0.191 U	0.114	0.774	8.75	0.0572 U	0.0273 U			
		(duplicate)	11-02-22	PES	Bladder	—	—	0.0160 U	0.185 J	0.0212 U	0.191 U	0.133	0.780	8.77	0.0572 U	0.0273 U			
		(duplicate)	05-09-23	PES	Bladder	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.175 J+	1.39	6.21	0.0572 U	0.0273 U			
		(duplicate)	05-09-23	PES	Bladder	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0890 J	1.35	6.47	0.0572 U	0.0273 U			
		05-24-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.684	5.64	0.0572 U	0.0273 U			
MW-326R (duplicate)	Mercer St	05-15-23	PES	Bladder	—	—	—	0.0160 U	0.756	0.0212 U	0.468	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.0273 U			
		11-09-23	PES	Bladder	—	—	—	0.0440	1.34	0.299	1.51	0.0280 U	0.0160 U	0.125	0.0572 U	0.0273 U			
		11-09-23	PES	Bladder	—	—	—	0.0550	1.38	0.295	1.50	0.0280 U	0.0160 U	0.131	0.0572 U	0.0273 U			
		05-24-24	PES	Peristaltic	—	—	—	0.0440	0.150 J	0.294	1.44	0.0280 UJ	0.0160 UJ	0.0890 J	0.0572 U	0.0273 U			
		11-06-24	PES	Peristaltic	—	—	—	0.6390 U	8.510	3.94	22.3	8.9600	1.0700 U	0.7930 U	0.793 U	0.511 U			
MW-328 (-36.1 to -46.1)	Lake Union Park, S end	10-02-19	PES	Bladder	—	—	—	17.0	0.535	0.158 U	0.316 U	0.199 U	0.153 U	1.26	0.152 U	23.3			
		01-17-20	PES	Peristaltic	—	—	—	17.6	0.448 J	0.158 U	0.316 U	1.66	0.153 U	1.03	0.152 U	13.1 J			
		04-08-20	PES	Peristaltic	—	—	—	9.53	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.631	0.152 U	11.1			
		07-07-20	PES	Peristaltic	—	—	—	10.3	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.03	0.0572 U	20.7			
		11-09-20	PES	Peristaltic	—	—	—	0.630	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.607	0.0572 U	7.99			
		05-25-21	PES	Peristaltic	—	—	—	6.19	0.0540 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	8.57			
		11-10-21	PES	Peristaltic	—	—	—	6.21	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.255	0.0572 U	2.03			
		05-04-22	PES	Peristaltic	—	—	—	7.53	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.336	0.0572 U	2.12			
		11-02-22	PES	Peristaltic	—	—	—	8.47	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.344	0.0572 U	2.18			
		05-19-23	PES	Peristaltic	—	—	—	6.13	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	1.74			
		11-09-23	PES	Peristaltic	—	—	—	6.74	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.195	0.0572 U	0.669 J-			
		05-23-24	PES	Peristaltic	—	—	—	1.40	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.152	0.0572 U	0.661			
		11-14-24	PES	Peristaltic	—	—	—	0.509	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.223	0.0572 U	0.459			

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC	
Preliminary Cleanup Level (PCUL)					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29	
MW-329 (duplicate) (-69.0 to -79.0)	Westlake Ave N ROW, E side	10-03-19	PES	Peristaltic	—	—	—	0.206 J	0.435 J	0.158 U	0.316 U	0.199 U	0.153 U	9.25	0.152 U	28.8	
		10-03-19	PES	Peristaltic	—	—	—	0.215 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	9.26	0.152 U	29.2	
		01-20-20	PES	Peristaltic	—	—	—	0.279 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	11.0	0.152 U	26.2	
		04-27-20	PES	Bladder	—	—	—	0.704	0.434 J	0.137 U	0.174 U	0.300 U	0.190 U	17.5	0.149 U	23.6	
		08-03-20	PES	Bladder	—	—	—	0.628	1.06	0.0290 J	0.191 U	0.0280 U	0.0160 U	14.7	0.0572 UJ	32.2	
		11-09-20	PES	Bladder	—	—	—	0.862	0.106 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	21.0	0.0572 U	23.0	
		05-25-21	PES	Peristaltic	—	—	—	0.601	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	15.2	0.0572 U	23.0	
		02-25-22	PES	Peristaltic	—	—	—	0.222	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	10.1	0.0572 U	21.8	
		06-09-22	PES	Peristaltic	—	—	—	0.260	0.0580 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	10.4	0.0572 U	22.5	
		11-01-22	PES	Peristaltic	—	—	—	0.176	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	8.51	0.0572 U	23.6	
		05-18-23	PES	Peristaltic	—	—	—	0.185	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	8.79	0.0572 U	24.5	
		11-09-23	PES	Peristaltic	—	—	—	0.172	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	8.39	0.0572 U	20.7 J-	
		05-23-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	7.80	0.0572 U	23.4	
		11-14-24	PES	Peristaltic	—	—	—	0.148	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	7.64	0.0572 U	28.5	
MW-336 (-51.6 to -61.6)	Mercer St ROW, N side	05-05-20	PES	Bladder	—	—	—	0.0941 U	0.318 J	0.137 U	0.174 U	0.300 U	0.304 J	57.1	0.149 U	6.03	
		07-08-20	PES	Bladder	—	—	—	0.0490	1.21	0.0212 U	0.191 U	0.600	6.08	61.1	0.127	7.71	
		11-02-20	PES	Bladder	—	—	—	0.215	0.301	0.0212 U	0.191 U	0.172	3.52	137	0.0910 J	5.80	
		02-10-21	PES	Bladder	—	—	—	0.0660	0.328	0.0550 J	0.225 J	0.0280 U	1.86	107	0.189 J	8.18	
		05-26-21	PES	Peristaltic	—	—	—	0.128	0.0500 U	0.0212 U	0.191 U	0.120	3.12 J+	150	0.0572 U	10.7	
		08-11-21	PES	Peristaltic	—	—	—	0.249	0.0500 U	0.0212 U	0.191 U	0.0570 J	2.68	168	0.229	20.7	
		11-17-21	PES	Peristaltic	—	—	—	0.257	0.0500 U	0.0212 U	0.191 U	0.630 J	2.05	177	0.274	8.68	
		03-02-22	PES	Peristaltic	—	—	—	0.277	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.359	223	0.330	9.98	
		05-31-22	PES	Peristaltic	—	—	—	0.230 J	0.500 U	0.212 U	1.91 U	0.280 U	0.620	263	1.03 J	7.39	
		08-10-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0320 J	0.891	23.2	0.129 J	0.0273 U	
		11-03-22	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0840 J	0.657	14.5	0.127 J	0.0273 U	
		05-19-23	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.496	3.65	0.0572 U	0.0273 U	
		11-09-23	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.468	0.198	0.102 J	0.0273 UJ	
		05-28-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.398	2.91	0.0870 J	0.0273 U	
		11-14-24	PES	Peristaltic	—	—	—	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.394	0.767	0.0572 U	0.0273 U	
MW-341 (-66.8 to -76.8)	Lake Union Park, S end	05-12-20	PES	Peristaltic	—	—	—	16.2	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	41.4	0.149 U	10.4	
		07-07-20	PES	Peristaltic	—	—	—	15.6	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0500	32.9	0.0572 U	9.86	
		11-09-20	PES	Peristaltic	—	—	—	9.87	0.167 J	0.0212 U	0.191 U	0.0740 J	0.102	25.1	0.0572 U	5.99	
		05-25-21	PES	Peristaltic	—	—	—	17.6	0.105 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	2.43	0.0572 U	26.7	
		11-10-21	PES	Peristaltic	—	—	—	14.3	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	12.2	0.0572 U	11.9	
		05-04-22	PES	Peristaltic	—	—	—	21.3	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	17.0	0.0572 U	16.6	
		11-02-22	PES	Peristaltic	—	—	—	25.7	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	6.29	0.0572 U	26.5	
		05-18-23	PES	Peristaltic	—	—	—	19.7	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	4.42	0.0572 U	23.2	
		11-09-23	PES	Peristaltic	—	—	—	20.4	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	5.42	0.0572 U	27.8 J-	
		05-23-24	PES	Peristaltic	—	—	—	19.8	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	17.7	0.0572 U	44.8	
		11-14-24	PES	Peristaltic	—	—	—	18.5	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	29.8	0.0572 U	58.0	

Table 6
Groundwater Petroleum Hydrocarbons and CVOCs in Deep Zone Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO	ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE	TCE	cDCE	tDCE	VC						
Preliminary Cleanup Level (PCUL)					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
MW-342 (-32.4 to -42.4)	Valley St ROW, S side	05-04-20	PES	Peristaltic	—		—		—		0.0941	U	0.366	J	0.137	U	0.174	U	0.300	U	0.190	U	1.34		0.149	U	1.51	
		07-30-20	PES	Peristaltic	—		—		—		0.316		1.24		0.116		0.723		0.0280	U	0.0160	U	5.56	J	0.0572	UJ	3.12	
		11-17-20	PES	Peristaltic	—		—		—		0.113		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	1.22		0.0572	U	1.87	
		06-04-21	PES	Peristaltic	—		—		—		0.526		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	6.45		0.0572	U	2.54	
		11-09-21	PES	Peristaltic	—		—		—		0.198		0.250		0.0590	J	0.412		0.0280	U	0.0160	U	2.45		0.0572	U	1.81	
		05-17-22	PES	Peristaltic	—		—		—		0.779		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	5.13		0.0572	U	10.2	
		11-01-22	PES	Peristaltic	—		—		—		0.980		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	4.60		0.0930	J	8.88	
		05-09-23	PES	Peristaltic	—		—		—		0.0290	J	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		11-09-23	PES	Peristaltic	—		—		—		1.02		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	7.68		0.0700	J	5.16	J-
		05-24-24	PES	Peristaltic	—		—		—		1.51		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	6.77		0.0690	J	4.72	
		11-22-24	PES	Peristaltic	—		—		—		1.80		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	11.0		0.0790	J	6.21	J+
MW-343 (-71.5 to -81.5)	Valley St ROW, S side	05-04-20	PES	Peristaltic	—		—		—		0.114	J	0.620		0.137	U	0.207	J	0.300	U	0.190	U	0.126	U	0.149	U	0.234	U
		07-30-20	PES	Peristaltic	—		—		—		0.0471		1.57		0.163		0.931		0.0280	U	0.0160	U	0.0276	UJ	0.0572	UJ	0.0273	U
		11-24-20	PES	Peristaltic	—		—		—		0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U
		06-04-21	PES	Peristaltic	—		—		—		0.139		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	3.17		0.0572	U	3.81	
		11-09-21	PES	Peristaltic	—		—		—		0.123		0.272		0.0560	J	0.421		0.0370	J	0.0160	U	3.00		0.0572	U	4.18	
		05-17-22	PES	Peristaltic	—		—		—		0.0940		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	2.93		0.0572	U	3.50	
		11-01-22	PES	Peristaltic	—		—		—		0.119		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	2.90		0.0572	U	4.58	
		05-09-23	PES	Peristaltic	—		—		—		0.0510		0.328		0.0680	J	0.491		0.0280	U	0.0160	U	0.214		0.0572	U	0.0273	U
		12-04-23	PES	Peristaltic	—		—		—		0.0910		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	2.88		0.0572	U	5.06	
		05-24-24	PES	Peristaltic	—		—		—		0.0750	J	0.0500	UJ	0.0212	UJ	0.191	UJ	0.0280	UJ	0.0160	UJ	2.56	J	0.0572	UJ	4.20	J
		11-22-24	PES	Peristaltic	—		—		—		0.0810		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	2.52		0.0572	U	6.48	J+
Number of Samples					97		—		—		583		583		583		583		644		644		644		644		644	
Number of Detections					14		—		—		218		188		87		100		193		255		487		171		398	
Frequency of Detection					14%		—		—		37%		32%		15%		17%		30%		40%		76%		27%		62%	
Maximum					140		—		—		44.1		8.51		136.000		150.00		2,800		1,540		10,300		32.9		1,800	
Minimum					31.6	U	50	U	250	U	0.0160	U	0.0500	U	0.0212	U	0.174	U	0.0280	U	0.0160	U	0.0276	U	0.0572	UJ	0.0273	U
Number of Samples Above SL					0		0		0		46		0		0		0		58		95		191		0		350	
Frequency of Detection Above SL					0%		—		—		8%		0%		0%		0%		9%		15%		30%		0%		54%	

Notes:

PCULs and Screening Levels from Washington State Department of Ecology, Memorandum from P. Tomlinson to TCP File for American Linen Supply Co. Dexter Ave. (FSID 3573, CSID 12004) re: Development of site-specific preliminary cleanup levels, December 14, 2021.

Detections above the groundwater PCUL level are shown in **bold and highlighted in gray**.

Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID, or NWTPH-Gx, NWTPH-Dx, or 8015-M.

VOCs analyzed by EPA Method 601, 8010S, 8015, 8020, 8021B, 8240, 8260B, 8260C, or 8260D, or by Purge and Trap Gas Chromatogram/Mass Spectrometry.

cDCE = cis-1,2-Dichloroethene
DRO = Diesel-range organics
GRO = Gasoline-range organics
HC = Hart Crowser
ORO = Oil-range organics
PCE = Perchloroethylene (Tetrachloroethene)
ROW = right-of-way
SES = SES Strategies, Inc.
TCE = Trichloroethene
tDCE = trans-1,2-Dichloroethene
VC = Vinyl chloride
Well screen elevations indicated below Sample Location in parentheses.
(--) = unknown screen elevation.

Laboratory and Results Notes:

Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID, or NWTPH-Gx, NWTPH-Dx, or 8015-M.

VOCs analyzed by EPA Method 601, 8010S, 8015, 8020, 8021B, 8240, 8260B, 8260C, or 8260D, or by Purge and Trap Gas Chromatogram/Mass Spectrometry.

— = Not analyzed or results not available.
i = The presence of the analyte indicated may be due to carryover from previous sample injections.
J = The identification of the analyte is acceptable; the reported value is an estimate.
J+ = The result is an estimated quantity, but the result may be biased high.
J- = The result is an estimated quantity, but the result may be biased low.
ND = Not detected at a concentration exceeding laboratory reporting limit; detection limit not provided.
U = Not detected at or above the laboratory method detection limit (MDL).
z = No/low level gasoline/petroleum detection; result is likely elevated due to high detections of CVOCs.

Groundwater statistics are for data collected during the Remediation Investigation, 2017-2021.
Groundwater statistics for GRO exclude "z" qualified data.

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC	
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29	
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35	
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	
Treatment Zone A Wells																	
IW-4A	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.205 J	0.589	0.158 U	0.316 U	9,470	1,100	2,010	9.77	306	
IW-7A	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.335 J	2.09	8.74	0.295 J	1.20	
IW-9A	Property Decommissioned March, 2019	03/29/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	3,230	299	510	2.36	102	
IW-18A	Property Decommissioned March, 2019	03/30/18	PES	Peristaltic	–	–	–	0.306 J	2.07	0.158 U	0.507 J	16,500	3,300	3,680	13.6	478	
IW-22A	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	3.88	0.153 U	128	6.88	232	
IW-37A	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.157 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	10.5	0.419 J	55.9	
IW-41A	Property Decommissioned March, 2019	04/10/18	PES	Peristaltic	–	–	–	1.79 U	0.412 U	3.16 U	6.32 U	37.3	28.0	510	1.89	78.2	
IW-42A	Property Decommissioned March, 2019	04/10/18	PES	Peristaltic	–	–	–	22.4 U	0.726	39.5 U	79.0 U	7,700	1,840	10,500	14.5	1,280	
IW-45A	Property Decommissioned March, 2019	04/04/18	PES	Peristaltic	–	–	–	0.202 J	0.749	0.158 U	0.361 J	9,250	7,460	18,800	14.5	2,020	
IW-46A	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.200 J	0.153 U	8.86	0.152 U	284	
IW-48A	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.425 J	0.622	1.16	1.04	16.3	
MW-165 (1.3 to -8.8)	Cluster 1	11/04/19	PES	Peristaltic	3,940	zJ+	–	0.0896 U	0.412 U	0.158 U	0.316 U	3.95	20.2	4,180	91.1	642	
		01/30/20	PES	Peristaltic	31.6	U	–	0.176 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	6.89	2.56	9.64	
		05/01/20	PES	Peristaltic	74.3	J	–	0.162 J	0.311 J	0.137 U	0.174 U	0.423 J	0.353 J	61.4	2.19	24.3	
		07/09/20	PES	Peristaltic	31.6	U	–	0.0900	0.389	0.0212 U	0.191 U	0.130	0.250	40.8	3.78	77.3	
		11/05/20	PES	Flowing	–	–	–	0.138	0.633	0.0212 U	0.191 U	0.0280 U	0.276	578	12.6	1,160	
		02/04/21	PES	Flowing	–	–	–	0.183	1.30	0.0800 J	0.369	0.0280 U	0.167	1,570	23.5	1,690	
		05/06/21	PES	Flowing	–	–	–	0.160 U	0.820 U	0.212 U	1.91 U	0.280 U	0.160 U	260	15.2	301	
		08/10/21	PES	Flowing	–	–	–	0.170	0.809	0.0460 J	0.191 U	0.0490 J	1.60 U	858	22.7	737	
		12/02/21	PES	Flowing	–	–	–	0.136	0.597	0.0212 U	0.191 U	0.0280 U	0.107	617	21.0	480	
		02/22/22	PES	Flowing	–	–	–	0.183	0.501	0.0340 J	0.191 U	0.0280 U	0.153	1,040	26.8	719	
		05/13/22	PES	Flowing	–	–	–	0.141	0.446	0.0340 J	0.191 U	0.0280 U	0.153	938	23.1	808	
		08/05/22	PES	Flowing	–	–	–	0.320 U	1.00 U	0.424 U	3.82 U	0.560 U	0.560 J	760	16.5	642	
		10/28/22	PES	Flowing	–	–	–	0.220	0.250 U	0.106 U	1.44	0.140 U	0.0800 U	858	14.9	797	
		05/11/23	PES	Flowing	–	–	–	0.114	0.413	0.0212 U	0.191 U	0.131	0.179	10.7	0.0572 U	16.0	
		11/01/23	PES	Flowing	–	–	–	0.105	0.311	0.0212 U	0.191 U	0.0280 U	0.0160 U	7.03	1.21	10.3	
		05/28/24	PES	Flowing	–	–	–	0.0840	0.116 J	0.0212 U	0.191 U	0.0280 U	0.0320 J	0.912	0.322	1.24	
		11/19/24	PES	Flowing	–	–	–	0.0990	0.115 J	0.0212 U	0.191 U	0.0280 U	0.0510	3.12	0.372	3.84	

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)											VC										
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE											
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29										
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35										
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l										
MW-169 (1.2 to -8.8)	Cluster 2	11/05/19	PES	Peristaltic	83.4	zJ+	–	–	0.13	J	0.412	U	0.158	U	0.316	U	2.72	1.15	48.8	11.9	1,500					
		01/23/20	PES	Peristaltic	158	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.995	U	1.51	J	0.665	J	6.97	275		
		05/05/20	PES	Peristaltic	158	U	–	–	0.127	J	0.388	J	0.137	U	0.493	J	0.300	U	0.190	U	0.126	U	2.20	40.5		
		07/10/20	PES	Peristaltic	2,400	zJ+	–	–	0.0830		1.01		0.105		0.834		0.0390	J	0.0490		0.194		3.06	77.9		
		11/03/20	PES	Flowing	–		–	–	0.113		0.123	J	0.0212	U	0.191	U	6.26		1.78		0.853		1.00	5.57		
		02/17/21	PES	Flowing	–		–	–	0.106		0.0570	J	0.0212	U	0.191	U	0.0280	U	0.0460		0.158		0.704	1.72		
		05/07/21	PES	Flowing	–		–	–	0.0800		0.179	U	0.0212	U	0.191	U	0.0280	U	0.0340	J	0.0680	U	0.469	0.680		
		08/10/21	PES	Flowing	–		–	–	0.100		0.0920	J	0.0212	U	0.191	U	0.0490	J	0.0160	U	0.0770	J	0.440	1.32		
		11/19/21	PES	Flowing	–		–	–	0.0750		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0610		0.127		0.657	1.89		
		02/16/22	PES	Flowing	–		–	–	0.0910		0.0500	U	0.0212	U	0.191	U	0.267		0.0340	J	0.0680	J	0.417	1.39		
		05/12/22	PES	Flowing	–		–	–	0.0780		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0370	J	0.255		0.370	5.29		
		08/05/22	PES	Flowing	–		–	–	0.103		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0380	J	0.0660	J	0.338	20.6		
		10/27/22	PES	Peristaltic	–		–	–	0.109		0.168	U	0.0670	J	0.316		0.0280	U	0.0560		0.0276	U	0.284	1.12		
		05/11/23	PES	Peristaltic	–		–	–	0.0810		0.104	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.144		0.276	4.82		
		11/03/23	PES	Peristaltic	–		–	–	0.119		0.0640	J	0.0212	U	0.191	U	0.0380	J	0.0550		0.156		0.244	4.10		
		05/24/24	PES	Peristaltic	–		–	–	0.0960		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0320	J	0.0410	J	0.153	J	0.822	
		11/13/24	PES	Peristaltic	–		–	–	0.101		0.0500	U	0.0212	U	0.191	U	13.0		1.02		3.00		0.762		47.6	
MW-173 (2.2 to -7.8)	Cluster 3	11/01/19	PES	Peristaltic	31.6	U	–	–	0.141	J	0.412	U	0.158	U	0.316	U	0.704		0.484	J	15.6		2.31		67.2	
		01/28/20	PES	Peristaltic	31.6	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.302	J	5.48		2.43		116	
		05/01/20	PES	Peristaltic	31.6	U	–	–	0.139	J	0.278	U	0.137	U	0.225	J	0.300	U	0.190	U	0.493	J	1.88		7.87	
		07/09/20	PES	Peristaltic	31.6	U	–	–	0.103		0.632		0.0212	U	0.371		0.360		0.218		0.402		2.87		26.2	
		11/05/20	PES	Flowing	–		–	–	0.179		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0865		0.616		3.30		105	
		02/04/21	PES	Flowing	–		–	–	0.242		0.191	J	0.0212	U	0.191	U	0.0280	U	0.0520		0.272		3.85		33.6	
		05/05/21	PES	Flowing	–		–	–	0.199		0.192	U	0.0212	U	0.229	J	0.0280	U	0.0530		0.142	U	2.68		15.8	
		08/05/21	PES	Flowing	–		–	–	0.176		0.171	J	0.0212	U	0.191	U	0.0280	U	0.0450		0.0860	J	1.30		0.636	
		12/02/21	PES	Flowing	–		–	–	0.199		0.164	U	0.0212	U	0.191	U	0.0280	U	0.0350	J	0.0510	J	1.06		0.292	
		02/17/22	PES	Flowing	–		–	–	0.182		0.146	U	0.0212	U	0.191	U	0.0280	U	0.0470		0.0700	J	0.588		0.236	
		05/13/22	PES	Flowing	–		–	–	0.151		0.117	J	0.0212	U	0.191	U	0.0280	U	0.0430		0.0760	J	0.474		0.253	
		08/11/22	PES	Flowing	–		–	–	0.187		0.119	U	0.0212	U	0.191	U	0.0280	U	0.0490		0.0720	J	0.370		0.143	
		10/27/22	PES	Flowing	–		–	–	0.188		0.122	J	0.0460	J	0.191	U	0.0280	U	0.0460		0.0630	J	0.556		0.629	
		05/11/23	PES	Flowing	–		–	–	0.0810		0.104	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.144		0.276		4.82	
		11/03/23	PES	Flowing	–		–	–	0.119		0.0640	J	0.0212	U	0.191	U	0.0380	J	0.0550		0.156		0.244		4.10	
		05/28/24	PES	Peristaltic	–		–	–	0.147		0.0800	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0900	J	0.0730	J	0.0670	J
		11/18/24	PES	Flowing	–		–	–	0.161		0.0960	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.247		0.104	J	0.285	

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																			
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE	TCE	cDCE	tDCE	VC			
PCUL					800		500	500	5.0		640		700		1,600		5.0	4.0	16	100	0.29			
Soil zone - Shallow only									2.4		15,000		1,200		320		24	1.4	–	77	0.35			
								WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l				
MW-177 (2.3 to -7.7)	Cluster 4	11/06/19	PES	Peristaltic	127,000	zJ+	–	–	0.744		4.14		0.579		2.77		3,180		1,710		131,000	395	J	11,000
		01/24/20	PES	Peristaltic	89,400	zJ+	–	–	4.48 U		20.6 U		7.90 U		15.8 U		26,400		7,440		99,800	265		8,440
		04/01/20	PES	Peristaltic	77,100	zJ+	–	–	448 U		2,060 U		790 U		1,580 U		27,900		6,980		123,000	760	U	9,860
		07/10/20	PES	Peristaltic	92,500	zJ+	–	–	80.0 U		250 U		106 U		955 U		29,400		6,520		76,100	345	J	9,450
		11/03/20	PES	Flowing	–		–	–	16.0 U		50.0 U		21.2 U		191 U		7,170		861		16,900	57.2	U	6,740
		02/18/21	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		10,900		2,010		12,800	50.0		6,310
		05/06/21	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		10,100		2,440		11,800	50.2		4,900
		08/09/21	PES	Flowing	–		–	–	0.440		0.590 J		0.212 U		1.91 U		6,190		1,250		6,810	31.8		3,500
		12/03/21	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		7,650		861		5,330	11.4	U	3,200
		02/17/22	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		10,500		1,800		7,920	30.4	J	2,920
		05/10/22	PES	Flowing	–		–	–	0.250		0.468		0.0780 J		0.458		7,870		1,460		6,410	29.5		2,960
		08/04/22	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		6,400		914 J+		4,980	27.4	J	4,660 J+
		10/26/22	PES	Peristaltic	–		–	–	3.20 U		33.2 J		4.24 U		38.2 U		5,450 J+		551		3,150	27.2	J	3,100
		05/10/23	PES	Flowing	–		–	–	0.155		0.282		0.0620 J		0.272		6,630		402		3,870	20.9		2,620
		11/01/23	PES	Peristaltic	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		418		61.8		2,610	12.8	J	1,170
		05/23/24	PES	Flowing	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		1,090 J+		319		1,900	11.4	U	1,090
		11/12/24	PES	Flowing	–		–	–	0.191		0.344		0.0840 J		0.386		5,730		820		2,950	15.2		1,460
MW-181 (1.5 to -8.5)	Cluster 5	11/08/19	PES	Peristaltic	23,900	zJ+	–	–	0.672 J		2.06 U		0.790 U		1.58 U		99.5 U		76.5 U		30,800	237		10,700
		01/27/20	PES	Peristaltic	9,090	zJ+	–	–	44.8 U		206 U		79.0 U		158 U		99.5 U		76.5 U		18,400	151	J	9,660
		04/01/20	PES	Peristaltic	12,200	zJ+	–	–	44.8 U		206 U		79.0 U		158 U		99.5 U		76.5 U		24,300	120	J	10,000
		07/08/20	PES	Peristaltic	15,400	zJ+	–	–	8.00 U		25.0 U		10.6 U		95.5 U		14.0 U		8.00 U		11,100	121		6,150
		11/04/20	PES	Peristaltic	–		–	–	0.336		0.188 J		0.0212 U		0.191 U		0.0280 U		0.147		1,360	58.9		6,650
		02/19/21	PES	Flowing	–		–	–	1.60 U		5.00 U		2.12 U		19.1 U		2.80 U		1.60 U		1,460	43.4		7,850
		05/06/21	PES	Peristaltic	–		–	–	1.60 U		5.00 U		2.12 U		19.1 U		23.8		1.60 U		381	23.2		6,960
		08/09/21	PES	Peristaltic	–		–	–	0.272		0.402		0.0360 J		0.191 U		0.197		0.142		775	42.1		2,170
		11/18/21	PES	Peristaltic	–		–	–	0.214		0.260		0.0510 J		0.249 J		0.0280 U		0.0940		1,530	40.8		6,870
		02/16/22	PES	Peristaltic	–		–	–	4.00 U		12.5 U		5.30 U		47.8 U		7.00 U		4.00 U		1,880	43.0	J	9,100
		05/10/22	PES	Peristaltic	–		–	–	0.160 U		0.500 U		0.212 U		1.91 U		5.29		2.26		723	34.1		10,200
		08/04/22	PES	Peristaltic	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		5.60 U		3.20 U		3,700	41.4		11,700
		10/25/22	PES	Peristaltic	–		–	–	6.60 J		40.2		4.24 U		38.2 U		5.60 U		3.20 U		5,150	31.0	J	12,200
		05/10/23	PES	Peristaltic	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		5.60 U		3.20 U		2,830	16.8	J	6,770
		11/01/23	PES	Peristaltic	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		5.60 U		3.20 U		7,530	28.4	J	6,830
		05/23/24	PES	Peristaltic	–		–	–	3.20 U		10.0 U		4.24 U		38.2 U		5.60 U		3.20 U		6,730	16.6	J	6,540
		11/11/24	PES	Peristaltic	–		–	–	0.243		0.265		0.0800 J		0.419		0.0280 U		0.0960		5,270	9.68		10,300

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																					
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE	tDCE	VC			
PCUL					800		500	500	5.0		640		700		1,600		5.0		4.0		16	100	0.29			
Soil zone - Shallow only									2.4		15,000		1,200		320		24		1.4		–	77	0.35			
								WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l				
MW-185 (1.4 to -8.7)	Cluster 6	10/31/19	PES	Flowing	446	zJ+	–	–	0.140	J	0.412	U	0.158	U	0.316	U	2.57	3.51	547	5.47	179	J+				
		01/29/20	PES	Peristaltic	31.6	U	–	–	0.228	J	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	1.09		1.52	1.66		
		04/02/20	PES	Peristaltic	31.6	U	–	–	0.192	J	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	1.18		0.729	0.512		
		07/08/20	PES	Peristaltic	56.3	U	–	–	0.127		0.545		0.0630	J	0.432		0.0570	J	0.0760	0.752	0.375		0.883			
		11/04/20	PES	Flowing	–		–	–	0.148		0.0656	J	0.0212	U	0.191	U	0.0313	J	0.0895	0.351	0.0586		J	0.900		
		02/16/21	PES	Flowing	–		–	–	0.117		0.0550	J	0.0212	U	0.191	U	0.0280	U	0.0790	0.203	0.0572		U	1.19		
		05/07/21	PES	Flowing	–		–	–	0.112		0.0640	U	0.0212	U	0.191	U	0.168		0.0870	0.257	U		0.0820	J	4.73	
		08/03/21	PES	Flowing	–		–	–	0.141		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0660	0.137	0.0572		U	2.07		
		11/18/21	PES	Flowing	–		–	–	0.119		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0710	0.360	0.0572		U	1.33		
		02/16/22	PES	Flowing	–		–	–	0.122		0.0500	U	0.0212	U	0.191	U	0.0560	J	0.0780	0.618	0.0700		J	4.89		
		05/12/22	PES	Flowing	–		–	–	0.0890		0.0500	U	0.0212	U	0.191	U	0.0410	J	0.0550	0.206	0.0572		U	2.53		
		08/05/22	PES	Peristaltic	–		–	–	0.136		0.102	J	0.0300	J	0.191	U	0.0280	U	0.125	J+	0.281		0.0930	J	0.680	
		10/27/22	PES	Peristaltic	–		–	–	0.105	J	0.250	U	0.106	U	0.955	U	0.140	U	0.0800	U	0.225		J	0.286	U	1.48
		05/11/23	PES	Peristaltic	–		–	–	0.0160	U	0.238		0.0212	U	0.191	U	0.0490	J	0.128	1.78	0.198		J	8.59		
		11/02/23	PES	Peristaltic	–		–	–	0.111		0.102	J	0.0212	U	0.191	U	0.0280	U	0.106	1.38	0.171		J	1.27		
		05/24/24	PES	Peristaltic	–		–	–	0.0720		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0710	0.655	0.0572		U	0.583		
11/19/24	PES	Peristaltic	–		–	–	0.0840		0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0300	J	0.604	0.0610	J	1.24				
Treatment Zone B Wells																										
IW-3B	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–		–	–	0.158	J	0.446	J	0.158	U	0.316	U	360	459	3,170	10.7		395				
IW-6B	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–		–	–	0.350	J	0.453	J	0.158	U	0.316	U	590	847	2,270	13.6		24.1				
IW-8B	Property Decommissioned March, 2019	03/30/18	PES	Peristaltic	–		–	–	0.0896	U	0.412	U	0.158	U	0.316	U	25.2	21.8	6.43	0.152	U	0.403	J			
IW-17B	Property Decommissioned March, 2019	03/30/18	PES	Peristaltic	–		–	–	0.838		3.71		0.451	J	2.54		60,100	11,500	51,400	228	J	3,230				
IW-21B	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–		–	–	0.0896	U	0.438	J	0.158	U	0.316	U	1.51	148	4,600	58.5		1,200				
IW-22B	Property Decommissioned March, 2019	04/25/18	PES	Peristaltic	–		–	–	1.79	U	17.7		3.16	U	6.32	U	62,600	6,000	26,600	128		9,680				
IW-24B	Property Decommissioned March, 2019	03/30/18	PES	Peristaltic	–		–	–	0.754	J+	6.26	J+	0.777	J+	4.55		48,800	20,100	48,200	274		2,040				
IW-28B	Property Decommissioned March, 2019	04/09/18	PES	Peristaltic	–		–	–	0.0896	U	0.412	U	0.158	U	0.316	U	4.71	2.42	19.4	0.174	J	3.66				
IW-33B	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–		–	–	0.560		2.30		0.158	U	0.316	U	31.6	1,800	18,200	228		2,410				
IW-37B	Property Decommissioned March, 2019	03/29/18	PES	Peristaltic	–		–	–	0.0896	U	0.412	U	0.158	U	0.316	U	1.82	0.497	J	3,240		33.0	2,420			

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)											VC				
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE					
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35				
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l				
IW-45B	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.215 J	213	7.09	150				
IW-47B	Property Decommissioned March, 2019	04/10/18	PES	Bladder	–	–	–	89.6 U	2.06 U	158 U	316 U	144	170	40,900	46.3	3,360				
IW-49B	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.307 J	0.572	974	1.49	668				
IW-51B	Property Decommissioned March, 2019	03/28/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.437 J	0.817	4.60	0.152 U	20.5				
MW-166 (-12.6 to -22.6)	Cluster 1	11/04/19	PES	Peristaltic	4,360 zJ+	–	–	0.0896 U	0.526	0.158 U	0.316 U	0.199 U	0.467 J	5,130	47	1,420				
		01/30/20	PES	Peristaltic	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	118	11.4	250				
		05/01/20	PES	Peristaltic	49.1 J	–	–	0.0941 U	0.278 U	0.137 U	0.174 U	0.300 U	0.190 U	20.4	2.03	29.5				
		07/09/20	PES	Peristaltic	31.6 U	–	–	0.0400 J	1.13	0.0510 J	0.605	0.0280 U	0.0520	21.7	1.41	42.3				
		11/05/20	PES	Peristaltic	–	–	–	0.0909	0.143 J	0.0212 U	0.191 U	0.0280 U	0.271	6,090	27.4	3,380				
		02/04/21	PES	Flowing	–	–	–	8.00 U	25.0 U	10.6 U	95.5 U	14.0 U	8.00 U	9,810	63.0 J+	3,760 J				
		05/05/21	PES	Flowing	–	–	–	3.20 U	10.0 U	4.24 U	38.2 U	5.60 U	3.20 U	7,150	42.4	2,020				
		08/10/21	PES	Flowing	–	–	–	0.116	0.0870 J	0.0212 U	0.191 U	0.0880 J	4.00 U	5,280	49.1	1,600				
		12/02/21	PES	Flowing	–	–	–	0.200 J	1.13 J	0.212 U	1.91 U	0.280 U	1.24	7,610	70.3	3,100				
		02/22/22	PES	Peristaltic	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	7.00 U	4.00 U	11,300	64.3	3,050				
		05/13/22	PES	Flowing	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	7.00 U	4.00 U	9,310	66.3	3,200				
		08/05/22	PES	Flowing	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	7.00 U	4.00 U	8,810	60.0	3,870				
		10/28/22	PES	Peristaltic	–	–	–	0.130 J	0.250 U	0.106 U	0.955 U	0.140 U	0.0800 U	12,000	49.7	4,810				
		05/11/23	PES	Peristaltic	–	–	–	0.0880	0.162 J	0.0212 U	0.191 U	0.0280 U	0.317	6,630	58.0	2,180				
		11/02/23	PES	Peristaltic	–	–	–	0.117	0.122 J	0.0550 J	0.191 U	0.289	0.401	8,910	62.7	2,770				
		05/28/24	PES	Peristaltic	–	–	–	0.104	0.0690 J	0.0212 U	0.191 U	0.0280 U	0.631	7,480	62.4	2,370				
		11/18/24	PES	Flowing	–	–	–	0.878	0.944	0.130 J	0.502 J	0.0560 U	0.778	7,900	51.9	3,060				
MW-170 (-12.8 to -22.8)	Cluster 2	11/05/19	PES	Peristaltic	22,700 zJ+	–	–	0.269 J	0.916	0.158 U	0.796 J	105	125	27,600	172	6,710				
		01/23/20	PES	Peristaltic	20,000 zJ+	–	–	2.24 U	10.3 U	3.95 U	7.90 U	7,070	5,780	21,900	136	5,920				
		04/02/20	PES	Peristaltic	17,000 zJ+	–	–	44.8 U	206 U	79.0 U	158 U	2,470	3,100	30,900	160 J	5,940				
		07/09/20	PES	Peristaltic	24,300 zJ+	–	–	0.450	2.54	0.212 U	1.91 U	2,340	3,050	32,700	211	7,520				
		11/03/20	PES	Peristaltic	–	–	–	0.290 J	0.500 U	0.212 U	1.91 U	17.6 J	18.3	9,090	160	11,500				
		02/17/21	PES	Peristaltic	–	–	–	0.320 J	0.670 J	0.700 J	2.82	0.730 J	4.90	5,450	156	14,400				
		05/07/21	PES	Peristaltic	–	–	–	8.00 U	25.0 U	10.6 U	95.5 U	14.0 U	8.00 U	3,980	178	12,000				
		08/09/21	PES	Peristaltic	–	–	–	0.230 J	0.500 U	0.212 U	1.91 U	28.0 U	16.0 U	2,630	170	8,220				
		11/19/21	PES	Peristaltic	–	–	–	16.0 U	50.0 U	21.2 U	191 U	28.0 U	16.0 U	5,440	236	13,400				
		02/17/22	PES	Peristaltic	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	42.0	16.0	5,120	179	10,300				
		05/12/22	PES	Flowing	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	464	78.8	5,960	229	11,800				
		08/05/22	PES	Flowing	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	90.8	24.0	4,770	172	12,500				
		10/27/22	PES	Peristaltic	–	–	–	0.490	0.850 U	0.570 J	1.91 U	31.0 J	3.99	2,980	180	11,700				
		05/11/23	PES	Peristaltic	–	–	–	0.125	0.220	0.0212 U	0.191 U	0.0640 J	1.78	4,650	239	12,800				

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																				
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC									
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29									
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35									
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l									
MW-170 (duplicate)		11/02/23	PES	Peristaltic	–	–	–	0.186	0.134	J	0.0212	U	0.191	U	81.8	40.5	5,760	179	11,700						
		05/24/24	PES	Peristaltic	–	–	–	3.20	U	10.0	U	4.24	U	38.2	U	19.8	J	51.4	10,200	256	11,800				
		11/15/24	PES	Peristaltic	–	–	–	0.313	0.297		0.0212	U	0.191	U	45.0	195	J	16,900	334	16,900	J				
		11/15/24	PES	Peristaltic	–	–	–	0.275	0.281		0.0212	U	0.191	U	42.3	112	J	16,800	301	11,800	J				
MW-174 (-12.3 to -22.3)	Cluster 3	11/01/19	PES	Peristaltic	31.6	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.286	J	1.07	6.85	
		01/28/20	PES	Peristaltic	531	ZJ+	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.484	J	1.05	0.529	
		05/01/20	PES	Peristaltic	51.1	J	–	–	0.0941	U	0.701		0.137	U	0.710	J	0.300	U	0.190	U	0.877		0.653	1.04	
		07/09/20	PES	Peristaltic	31.6	U	–	–	0.0160	U	0.901		0.0212	U	0.511		0.259		0.184		1.19		1.31	2.32	
		11/05/20	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.177		0.609		2.05		3.11	
		02/04/21	PES	Flowing	–	–	–	0.0160	U	0.121	J	0.0212	U	0.191	U	0.0400	J	0.0980		0.247		1.17		2.38	
		05/05/21	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.102		0.245		0.911		1.85	
		08/05/21	PES	Flowing	–	–	–	0.0220	J	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.110		0.328		0.557		29.7	
		12/02/21	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.117		0.550		0.630		105	
		02/17/22	PES	Flowing	–	–	–	0.0240	J	0.0500	U	0.0212	U	0.191	U	0.140	U	0.180	J	0.686		0.701		117	
		05/13/22	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0470	J	0.149		2.75		0.741		119	
		08/11/22	PES	Flowing	–	–	–	0.160	U	0.500	U	0.212	U	1.91	U	0.280	U	0.160	U	8.41		0.920	J	120	
		10/27/22	PES	Flowing	–	–	–	0.0260	J	0.0500	U	0.0212	U	0.191	U	2.38		0.997		22.3		1.25		157	
		05/11/23	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.140	U	0.0800	U	20.1		1.52		105	
		11/03/23	PES	Flowing	–	–	–	0.0800	U	0.250	U	0.106	U	0.955	U	0.140	U	0.0800	U	86.6		2.93		228	
		05/28/24	PES	Flowing	–	–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.287		63.8		2.19		205	J+
		11/18/24	PES	Flowing	–	–	–	0.0250	J	0.0500	U	0.0212	U	0.191	U	0.0410	J	0.459		279		4.54		374	
MW-178 (-11.7 to -21.7) (duplicate)	Cluster 4	11/06/19	PES	Peristaltic	249	ZJ+	–	–	0.0896	U	0.477	J	0.321	J	0.316	U	3.98	U	3.06	U	5.28	J	24.6	877	
		01/24/20	PES	Peristaltic	31.6	U	–	–	0.0896	U	0.412	U	0.245	J	0.383	J	0.199	U	0.153	U	0.565		9.15	2.14	
		04/02/20	PES	Peristaltic	31.7	U	–	–	0.150	J	0.412	U	0.202	J	0.316	U	0.199	U	0.153	U	1.03		4.20	2.79	
		07/10/20	PES	Peristaltic	66.6	ZJ+	–	–	0.0510		1.12		0.102		0.749		0.0280	U	0.075		0.0276	U	3.35	0.562	
		11/03/20	PES	Peristaltic	–	–	–	0.282		0.524		0.0700	J	0.414		1.41	J	0.895		54.3		44.0		15.3	
		02/18/21	PES	Peristaltic	–	–	–	0.500	J	1.00	U	0.424	U	3.82	U	2.40		0.840		2,540		34.3		1,230	
		05/06/21	PES	Peristaltic	–	–	–	0.320	U	1.00	U	0.424	U	3.82	U	10.3		0.320	U	1,620		33.6		2,680	
		08/06/21	PES	Peristaltic	–	–	–	0.445		1.24		0.152		0.756		24.1		52.6		11,500		85.5		7,110	
		12/06/21	PES	Peristaltic	–	–	–	0.800	U	2.50	U	1.06	U	9.55	U	17.3		27.6		2,240		29.2		2,620	
		02/17/22	PES	Peristaltic	–	–	–	0.800	U	2.50	U	1.06	U	9.55	U	36.3		16.9		4,230		41.5		3,360	
		05/10/22	PES	Peristaltic	–	–	–	0.800	U	2.50	U	1.06	U	9.55	U	46.9	J+	31.7		5,930		43.7		3,230	
		05/10/22	PES	Peristaltic	–	–	–	0.296		1.27		0.0212	U	0.246	J	50.8	J+	38.9		6,310		44.6		3,180	
		08/04/22	PES	Peristaltic	–	–	–	3.20	U	10.0	U	4.24	U	38.2	U	19.6	J	14.8	J+	15,600		94.4		12,700	J+
		10/25/22	PES	Peristaltic	–	–	–	3.20	U	43.8		4.24	U	38.2	U	5.60	U	3.20	U	9,440		66.4		5,850	

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)												VC			
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE					
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35				
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l				
MW-182 (-12.5 to -22.5) (duplicate)	Cluster 5	11/08/19	PES	Peristaltic	14,100 ZJ+	–	–	0.0896 U	0.519	0.344 J	0.573 J	1,570	794	19,200	89.4 J	1,560				
		01/27/20	PES	Peristaltic	2,420 ZJ+	–	–	44.8 U	206 U	79.0 U	158 U	160 J	115 J	4,500	76.0 U	1,550				
		04/01/20	PES	Peristaltic	1,760 ZJ+	–	–	4.48 U	20.6 U	7.90 U	15.8 U	1,480	169	2,600	25.0 J	2,040				
		07/08/20	PES	Peristaltic	1,000 ZJ+	–	–	0.800 U	2.50 U	1.06 U	9.55 U	126	28.0	715	16.2	1,350				
		11/04/20	PES	Peristaltic	–	–	–	0.800 U	2.51 J	1.06 U	9.55 U	208	226	84,900	281	18,900				
		02/19/21	PES	Peristaltic	–	–	–	8.00 U	25.0 U	10.6 U	95.5 U	259	99.5	87,400	269	31,100				
		05/06/21	PES	Peristaltic	–	–	–	32.0 UJ	100 UJ	42.4 UJ	382 UJ	6,650	384	68,400	226 J	31,000				
		05/06/21	PES	Peristaltic	–	–	–	0.362 J	1.05 J	0.530 J	2.99 J	8,900	469	64,900	195	30,600				
		08/09/21	PES	Peristaltic	–	–	–	0.575 J	1.85 J	0.530 U	4.78 U	70.0 U	40.0 U	26,100	118	9,620				
		11/18/21	PES	Flowing	–	–	–	40.0 U	125 U	53.0 U	478 U	1,170 J+	865	43,900	143 U	22,900				
		02/16/22	PES	Peristaltic	–	–	–	32.0 U	100 U	42.4 U	382 U	198 J	118	40,700	114 U	19,500				
		05/10/22	PES	Flowing	–	–	–	0.332	1.07	0.479	2.80	789	840	38,200	91.0	26,100				
		08/04/22	PES	Peristaltic	–	–	–	16.0 U	50.0 U	21.2 U	191 U	149	250 J+	41,700	89.0 J	46,000 J+				
		10/25/22	PES	Peristaltic	–	–	–	16.0 U	197 J	21.2 U	191 U	155 J+	180	36,600	81.0 J	24,200				
		05/10/23	PES	Flowing	–	–	–	16.0 U	50.0 U	21.2 U	191 U	60.0 J	43.0	25,100	57.2 U	15,300				
		11/02/23	PES	Flowing	–	–	–	0.160 UJ	0.760 J	0.212 UJ	1.91 UJ	39.4 J	69.0 J	32,100 J	48.7 J	15,700 J				
		05/23/24	PES	Peristaltic	–	–	–	16.0 U	50.0 U	21.2 U	191 U	102 J+	108	27,900	57.2 U	13,400				
		11/13/24	PES	Peristaltic	–	–	–	0.362	0.778	0.262	1.43	246	303	30,500	67.4	18,900				
MW-186 (-12.7 to -22.7)	Cluster 6	10/31/19	PES	Flowing	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 UJ	0.153 U	4.15	0.152 U	23.4				
		01/29/20	PES	Peristaltic	42.7 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.777	0.152 U	28.2				
		04/02/20	PES	Peristaltic	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.205 U	0.476 J	0.152 U	5.93				
		07/08/20	PES	Peristaltic	54.3 U	–	–	0.0160 U	1.91	0.107	0.688	0.0280 U	0.0850	0.101	0.0572 U	4.02				
		11/04/20	PES	Peristaltic	–	–	–	0.0379 J	0.112 J	0.0212 U	0.191 U	0.0280 U	0.177	0.552	1.06	2.26				
		02/16/21	PES	Flowing	–	–	–	0.0570	0.0770 J	0.0212 U	0.191 U	0.0280 U	0.143	0.459	1.26	6.52 J+				
		05/07/21	PES	Flowing	–	–	–	0.0440	0.0950 U	0.0212 U	0.191 U	0.179	0.123	0.393	0.892	4.67				
		08/03/21	PES	Flowing	–	–	–	0.0510	0.0990 J	0.0212 U	0.191 U	0.0280 U	0.0820	0.286	0.804	5.48				
		11/18/21	PES	Peristaltic	–	–	–	0.0460	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0850	0.259	0.731	4.57				
		02/16/22	PES	Flowing	–	–	–	0.0610	0.0650 U	0.0212 U	0.191 U	0.0280 U	0.0770	0.262	0.731	4.76				
		05/12/22	PES	Flowing	–	–	–	0.0370 J	0.0600 J	0.0212 U	0.191 U	0.0380 J	0.0980	0.664	0.717	4.69				
		08/05/22	PES	Flowing	–	–	–	0.0560	0.0600 J	0.0212 U	0.191 U	0.498	0.143 J+	0.281	0.757	7.63 J+				
		10/26/22	PES	Peristaltic	–	–	–	0.0520	0.379	0.0730 J	0.479	0.0280 U	0.0630	0.207	0.682	3.19				
		05/11/23	PES	Peristaltic	–	–	–	0.0320 J	0.245	0.0212 U	0.191 U	0.0280 U	0.0870	0.0276 U	0.628	0.0750 J				
		11/02/23	PES	Peristaltic	–	–	–	0.0440	0.165 J	0.0230 J	0.191 U	0.0280 U	0.0820	0.253	0.708	0.0273 U				
		05/24/24	PES	Flowing	–	–	–	0.0370 J	0.0770 J	0.0212 U	0.191 U	0.0280 U	0.113	0.350	0.466	0.0540 J				
		11/19/24	PES	Flowing	–	–	–	0.0450	0.0750 U	0.0212 U	0.191 U	0.0280 U	0.0350 J	0.153	0.651	0.350				

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)											
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l
Treatment Zone C Wells																
IW-1C	Property Decommissioned March, 2019	03/29/18	PES	Peristaltic	–	–	–	0.0896 U	0.524	0.158 U	0.316 U	5.07	56.5	12.7	0.152 U	1.69
IW-4C	Property Decommissioned March, 2019	04/26/18	PES	Peristaltic				0.158 J	0.918	0.158 U	0.647 J	22,300	1,860	5,080	2.17	29.7
IW-8C	Property Decommissioned March, 2019	04/04/18	PES	Peristaltic	–	–	–	0.276 J	2.77	0.206 J	1.54	27,400	1,160	4,160	9.22	169
IW-9C	Property Decommissioned March, 2019	04/02/18	PES	Peristaltic	–	–	–	0.285 J	0.690	0.158 U	0.316 U	3.15	49.7	20,400	107	3,780
IW-13C	Property Decommissioned March, 2019	04/25/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	155	111	412	0.292 J	30.0
IW-15C	Property Decommissioned March, 2019	03/30/18	PES	Bladder	–	–	–	0.896 U	4.12 U	1.58 U	3.16 U	670	166	26,800	51.3	7,350
IW-19C	Property Decommissioned March, 2019	03/29/18	PES	Peristaltic	–	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	1.12	0.192 J	103	0.305 J	168
IW-20C (dup)	Property	03/30/18	PES	Bladder	–	–	–	0.208 J	1.54	0.158 U	0.316 U	721	1,020	6,830	9.44	111
	Decommissioned March, 2019	03/30/18	PES	Bladder	–	–	–	0.198 J	1.53	0.158 U	0.316 U	678	1,020	6,690	10.2	111
MW-167 (-27.9 to -37.9)	Cluster 1	11/04/19	PES	Peristaltic	31.6 U	–	–	0.0896 U	0.567	0.158 U	0.316 U	0.326 J	0.297 J	14.6	0.599	17.3
		01/28/20	PES	Peristaltic	57.8 U	–	–	0.100 J	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	8.08	0.158 J	11.5
		05/01/20	PES	Peristaltic	68.3 J	–	–	0.0967 J	0.693	0.137 U	0.629 J	0.300 U	0.190 U	0.715	0.149 U	0.641
		07/09/20	PES	Peristaltic	31.6 U	–	–	0.0440	2.23	0.0870 J	0.926	0.0280 U	0.0670	0.473	0.0572 U	0.948
		11/05/20	PES	Peristaltic	–	–	–	0.0160 U	0.255	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.675	0.0572 U	0.897
		02/04/21	PES	Peristaltic	–	–	–	0.0340 U	0.349	0.0590 J	0.345	0.0600 J	0.0480	0.470	0.0572 U	2.22 J
		05/05/21	PES	Peristaltic	–	–	–	0.0250 J	0.544	0.0920 J	0.565	0.0280 U	0.0160 U	0.353	0.0572 U	1.06
		08/10/21	PES	Peristaltic	–	–	–	0.0920	0.777	0.0950 J	0.579	0.0280 U	0.0160 U	0.346	0.0572 U	0.223
		12/02/21	PES	Peristaltic	–	–	–	0.0160 U	0.241	0.0212 U	0.414	0.0280 U	0.0160 U	0.369	0.0572 U	0.159
		02/22/22	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.220	0.0572 U	0.144
		05/13/22	PES	Peristaltic	–	–	–	0.0160 U	0.155 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.312	0.0572 U	0.167
		08/05/22	PES	Flowing	–	–	–	0.0160 U	0.0930 J	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.211	0.0572 U	0.191
		10/28/22	PES	Peristaltic	–	–	–	0.0160 U	0.186 J	0.0212 U	0.191 U	0.192	0.0160 U	0.184	0.0572 U	0.138
		05/11/23	PES	Peristaltic	–	–	–	0.0230 J	0.293	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.0276 U	0.0572 U	0.516
		11/01/23	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0190 J	0.223	0.0572 U	0.260
		05/28/24	PES	Peristaltic	–	–	–	0.0160 U	0.0650 J	0.0212 U	0.191 U	0.0280 U	0.0380 J	0.344	0.0572 U	0.786 J+
		11/19/24	PES	Peristaltic	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.191	0.0572 U	1.14

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE	cDCE	tDCE
PCUL					800		500	500	5.0		640		700		1,600		5.0	4.0	16	100	0.29
Soil zone - Shallow only									2.4		15,000		1,200		320		24	1.4	–	77	0.35
								WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l	
MW-179 (-27.2 to -37.2)	Cluster 4	11/06/19	PES	Peristaltic	2,310	zJ+	–	–	0.0896 U	0.443 J	0.273 J	0.316 U	50.5	46.2 J	3,780	15.2 U	533				
		01/27/20	PES	Peristaltic	501	zJ+	–	–	0.0896 U	0.412 U	0.198 J	0.316 U	38.8	33.3	941	7.07	156				
		04/02/20	PES	Peristaltic	424	zJ+	–	–	1.79 U	8.24 U	3.16 U	6.32 U	62.3	45.0	817	5.99 J	152				
		07/10/20	PES	Peristaltic	924	zJ+	–	–	0.320 U	1.00 U	0.424 U	3.82 U	27.3	19.6	939	7.40	105				
		11/03/20	PES	Peristaltic	–	–	–	–	0.320 U	1.00 U	0.424 U	3.82 U	36.1 J	19.6	17,700	45.5	1,670				
		02/18/21	PES	Peristaltic	–	–	–	–	8.00 U	25.0 U	10.6 U	95.5 U	489	110	16,600	279	31,300				
		05/06/21	PES	Peristaltic	–	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	7.00 U	21.3	4,960	29.5 J	5,860				
		08/09/21	PES	Peristaltic	–	–	–	–	0.224	0.992	0.0900 J	0.543	9.16	4.00 U	790	30.6	2,860				
		12/03/21	PES	Peristaltic	–	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	13.3 J	11.3	1,810	14.3 U	6,580				
		02/17/22	PES	Peristaltic	–	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	15.9	12.6	1,400	10.2	1,600				
		05/10/22	PES	Peristaltic	–	–	–	–	0.160 U	0.650 J	0.212 U	1.91 U	11.4	8.87	654	5.71	1,940				
		08/04/22	PES	Peristaltic	–	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	7.55	4.50 J+	912	6.25 J	2,990 J+				
		10/25/22	PES	Peristaltic	–	–	–	–	0.800 U	8.20 J	1.06 U	9.55 U	10.4 J+	5.10	1,120	5.75 J	1,620				
		05/10/23	PES	Peristaltic	–	–	–	–	0.0640 J	0.229 J	0.0212 UJ	0.202 J	6.50 J	3.28 J	672 J	2.65 J	976 J				
		11/01/23	PES	Peristaltic	–	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	3.85 J	2.05	1,570	6.10 J	1,770				
		05/23/24	PES	Peristaltic	–	–	–	–	0.800 UJ	2.50 UJ	1.06 UJ	9.55 UJ	6.45 J+	1.25 J	718 J	5.25 J	1,750 J				
11/12/24	PES	Peristaltic	–	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	14.2	4.65	623	2.86 U	1,370						
MW-183 (-27.4 to -37.4)	Cluster 5	11/08/19	PES	Peristaltic	45.0	zJ+	–	–	0.0896 U	0.459 J	0.158 U	0.316 U	0.199 U	0.193 J	59.9	0.167 J	4.29				
		01/27/20	PES	Peristaltic	41.5	U	–	–	0.0896 U	0.412 U	0.158 U	0.369 J	0.237 J	0.153 U	21.8	0.152 U	15.5				
		04/02/20	PES	Peristaltic	31.6	U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 UJ	3.03	0.152 U	10.0				
		07/08/20	PES	Peristaltic	76.2	J	–	–	0.0270 J	2.39	0.128	0.844	0.0750 J	0.0630	0.893	0.0572 UJ	4.24				
		11/04/20	PES	Peristaltic	–	–	–	–	0.0160 U	0.140 J	0.0212 U	0.191 U	22.5	34.7	752	1.83	208				
		02/19/21	PES	Peristaltic	–	–	–	–	0.0510	0.131 J	0.0212 U	0.191 U	2.28	17.3	4,950	12.3	2,260				
		05/06/21	PES	Peristaltic	–	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	1.60 U	4,470	12.5 J	2,340				
		08/06/21	PES	Peristaltic	–	–	–	–	0.0680	0.347	0.0530 J	0.273	0.0280 U	2.55	3,570	9.87	3,740				
		11/18/21	PES	Peristaltic	–	–	–	–	0.0510	0.128 J	0.0212 U	0.242 J	123	8.00 U	5,430	14.1	5,110				
		02/16/22	PES	Peristaltic	–	–	–	–	4.00 U	12.5 U	5.30 U	47.8 U	7.00 U	4.00 U	4,940	14.3 U	4,410				
		05/10/22	PES	Peristaltic	–	–	–	–	0.0360 J	0.112 J	0.0212 U	0.191 U	2.80 U	18.0	3,940	7.82	4,350				
		08/04/22	PES	Peristaltic	–	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	1.60 U	3,700	11.0 J	8,160				
		10/25/22	PES	Peristaltic	–	–	–	–	1.60 U	17.8 J	2.12 U	19.1 U	2.80 U	1.60 U	3,060	9.90 J	4,350				
		05/10/23	PES	Flowing	–	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	1.60 U	321	5.72 U	1,200				
		11/01/23	PES	Peristaltic	–	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	1.60 U	193	5.72 U	1,050				
		05/23/24	PES	Peristaltic	–	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	2.80 U	1.60 U	205	5.72 U	1,030				
11/11/24	PES	Peristaltic	–	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0290 J	279	1.38	1,500						

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO	ORO	Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE	tDCE	VC					
PCUL					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Soil zone - Shallow only											2.4		15,000		1,200		320		24		1.4		—		77		0.35	
								WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		
MW-187 (27.0 to -37.0)	Cluster 6	11/01/19	PES	Peristaltic	31.6	U	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	2.34		0.152	U	2.80			
		01/29/20	PES	Peristaltic	39.3	U	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.319	J	0.152	U	0.254	J		
		04/02/20	PES	Peristaltic	31.6	U	—	—	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.234	J	0.152	U	0.118	U		
		07/08/20	PES	Peristaltic	55.6	U	—	—	0.0160	U	2.40		0.126		1.18		0.0280	U	0.0160	U	0.123		0.0572	U	0.0273	U		
		11/04/20	PES	Peristaltic	—		—	—	0.0160	U	0.298		0.0250	J	0.213	J	0.0280	U	0.0160	U	0.631		0.0572	U	0.519			
		02/16/21	PES	Peristaltic	—		—	—	0.0430		1.16		0.0870	J	0.310		0.0780	J	0.0160	U	0.241		0.0572	U	2.57	J+		
		05/07/21	PES	Peristaltic	—		—	—	0.0160	U	0.124	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.185	U	0.0572	U	1.77			
		08/03/21	PES	Peristaltic	—		—	—	0.0330	J	0.896		0.147		0.877		0.0280	U	0.0160	U	0.204		0.0572	U	1.57	J+		
		11/18/21	PES	Flowing	—		—	—	0.0160	U	0.136	J	0.0430	J	0.325		0.0280	U	0.0160	U	0.130		0.0572	U	0.823			
		02/16/22	PES	Peristaltic	—		—	—	0.0160	U	0.0650	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0770	J	0.0572	U	0.651			
		05/12/22	PES	Flowing	—		—	—	0.0160	U	0.123	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.101		0.0572	U	0.583			
		08/05/22	PES	Peristaltic	—		—	—	0.0330	J	0.317		0.0660	J	0.458		0.0280	U	0.0160	U	0.103		0.0572	U	0.617	J+		
		10/26/22	PES	Peristaltic	—		—	—	0.0160	U	0.506		0.101		0.780		0.0280	U	0.0160	U	0.125		0.0572	U	0.274			
		05/11/23	PES	Peristaltic	—		—	—	0.0160	U	0.253		0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0930	J	0.0572	U	0.156			
		11/02/23	PES	Peristaltic	—		—	—	0.0180	J	0.308		0.0670	J	0.419		0.0280	U	0.0160	U	0.0800	J	0.0572	U	0.0273	U		
05/24/24	PES	Peristaltic	—		—	—	0.0160	U	0.0700	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0750	J	0.0572	U	0.0273	U				
11/19/24	PES	Peristaltic	—		—	—	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0530	J	0.0572	U	0.0273	U				
Treatment Zone D Wells																												
IW-1D	Property Decommissioned March, 2019	04/03/18	PES	Bladder	—		—	—	0.896	U	6.74		1.58	U	3.16	U	64,100		2,830		5,920		16.0		118			
IW-3D	Property Decommissioned March, 2019	04/03/18	PES	Bladder	—		—	—	0.0896	U	1.28		0.158	U	0.409	J	4,240		4,600		9,860		16.4		37.1			
IW-4D	Property Decommissioned March, 2019	03/29/18	PES	Bladder	—		—	—	0.0896	U	0.604		0.158	U	0.316	U	2.86		0.653		5.29		0.152	U	2.56			
IW-6D	Property Decommissioned March, 2019	04/03/18	PES	Bladder	—		—	—	0.0896	U	0.412	U	0.158	U	0.316	U	16.3		0.826		2.97		0.152	U	1.27			
IW-8D	Property Decommissioned March, 2019	04/04/18	PES	Bladder	—		—	—	0.0896	U	0.412	U	0.158	U	0.384	J	6,010		4,310		3,200		39.1		631			
IW-9D	Property Decommissioned March, 2019	04/04/18	PES	Bladder	—		—	—	0.0896	U	1.12		0.158	U	0.316	U	3,610		1,510		3,380		10.0		31.6			
IW-11D	Property Decommissioned March, 2019	05/01/18	PES	Bladder	—		—	—	0.0896	U	0.643		0.158	U	0.316	U	18.9		282		1,640		2.27		34.1			

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)															
					GRO	DRO	ORO	Benzene	Toluene	Ethylbenzene	Total Xylenes	PCE	TCE	cDCE	tDCE	VC				
PCUL					800	500	500	5.0	640	700	1,600	5.0	4.0	16	100	0.29				
Soil zone - Shallow only								2.4	15,000	1,200	320	24	1.4	–	77	0.35				
								WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l	WATER µg/l				
MW-168 (-43.0 to -53.0)	Cluster 1	11/04/19	PES	Peristaltic	65.0 J	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 UJ				
		01/31/20	PES	Flowing	31.6 U	–	–	0.0896 U	0.412 U	0.158 U	0.316 U	0.199 U	0.153 U	0.0933 U	0.152 U	0.118 U				
		05/01/20	PES	Peristaltic	76.0 J	–	–	0.104 J	0.827	0.161 J	0.712 J	0.300 U	0.190 U	0.126 U	0.149 U	0.234 U				
		07/09/20	PES	Peristaltic	31.6 U	–	–	0.0160 U	2.61	0.0212 U	1.20	0.147	0.0160 U	0.175	0.0572 U	0.0273 U				
		11/05/20	PES	Peristaltic	–	–	–	0.0160 U	0.314	0.0212 U	0.191 U	0.0280 U	0.0160 U	1.92	0.0572 U	0.407				
		02/04/21	PES	Peristaltic	–	–	–	0.0200 U	0.296	0.0480 J	0.276	0.0280 U	0.0160 U	0.490	0.0572 U	0.324				
		05/05/21	PES	Peristaltic	–	–	–	0.0210 J	0.667	0.0970 J	0.602	0.0280 U	0.0320 J	1.29	0.0572 U	0.185				
		08/10/21	PES	Peristaltic	–	–	–	0.0430	0.268	0.0500 J	0.274	0.0280 U	0.0390 J	0.732	0.0650 J	0.531				
		12/02/21	PES	Peristaltic	–	–	–	0.0160 U	0.0740 J	0.0212 U	0.191 U	0.0280 U	0.0420	2.59	0.122 J	0.387				
		02/22/22	PES	Peristaltic	–	–	–	0.0160 U	0.0740 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	5.43	0.0700 J	0.932				
		05/13/22	PES	Peristaltic	–	–	–	0.0160 U	0.200 J	0.0212 U	0.194 J	0.0280 U	0.0490	9.42	0.117 J	1.68				
		08/05/22	PES	Peristaltic	–	–	–	0.0330 J	0.177 J	0.0320 J	0.191 U	0.0280 U	0.500	285	3.36	43.8				
		10/28/22	PES	Peristaltic	–	–	–	0.0190 J	0.191 J	0.0212 U	0.191 U	0.147	0.0160 U	2.93	0.0850 J	6.68				
		10/28/22	PES	Peristaltic	–	–	–	0.0160 U	0.114 J	0.0212 U	0.191 U	0.0840 J	0.0160 U	2.68	0.0870 J	6.56				
		05/11/23	PES	Peristaltic	–	–	–	0.0160 U	0.258	0.0212 U	0.191 U	0.0280 U	0.0160 U	0.536	0.0970 J	2.79				
		11/02/23	PES	Peristaltic	–	–	–	0.0160 U	0.0890 J	0.0212 U	0.191 U	0.747	0.0500	23.0 J	0.693 J	22.4 J				
		05/28/24	PES	Flowing	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	3.75	0.132 J	5.24				
		05/28/24	PES	Flowing	–	–	–	0.0160 U	0.0500 U	0.0212 U	0.191 U	0.0280 U	0.0160 U	4.55	0.151 J	6.03				
		11/19/24	PES	Peristaltic	–	–	–	0.0160 U	0.0910 J	0.0212 U	0.263	0.0280 U	0.0160 U	0.234	0.0572 U	1.58				
		11/19/24	PES	Peristaltic	–	–	–	0.0160 U	0.0980 J	0.0320 J	0.269	0.0280 U	0.0160 U	0.231	0.0572 U	1.49				
MW-172 (-42.5 to -52.5)	Cluster 2	11/05/19	PES	Flowing	4,960 zJ+	–	–	0.0896 U	0.46 J	0.158 U	0.316 U	8,810	3,280	643	22.8	2.64				
		01/23/20	PES	Flowing	10,700 zJ+	–	–	0.0896 U	1.02	0.158 U	0.550 J	31,100	10,100	623	38.1	59.0 U				
		04/02/20	PES	Peristaltic	5,310 zJ+	–	–	44.8 U	206 U	79.0 U	158 U	9,670	4,480	452	76.0 U	59.0 U				
		07/09/20	PES	Peristaltic	4,430 zJ+	–	–	0.0550	0.757	0.0212 U	0.402	6,570	4,660	668	56.9	5.57				
		11/03/20	PES	Peristaltic	–	–	–	0.0830	0.750	0.177	0.565	5,780	4,130	582	44.1	12.9				
		02/17/21	PES	Flowing	–	–	–	0.0490	0.481	0.0680 J	0.216 J	5,370	3,740	955	44.3	179				
		05/07/21	PES	Peristaltic	–	–	–	1.60 U	5.00 U	2.12 U	19.1 U	1,100	1,410	538	20.4	21.0				
		08/10/21	PES	Peristaltic	–	–	–	0.0360 J	0.378	0.0990 J	0.504	203	576	440	14.3	33.9				
		11/19/21	PES	Flowing	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	1,310	1,290	798	28.2	15.2				
		02/17/22	PES	Flowing	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	2,890	2,260	656	24.3	14.1				
		02/17/22	PES	Flowing	–	–	–	0.0340 J	0.273	0.0970 J	0.212 J	2,750	2,240	671	25.3	12.9				
		05/12/22	PES	Flowing	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	4,880	2,860	588	28.9	13.8				
		08/05/22	PES	Flowing	–	–	–	0.800 U	2.50 U	1.06 U	9.55 U	6,140	3,240	468	26.9	13.0				
		10/27/22	PES	Flowing	–	–	–	0.0400 J	0.412	0.0212 U	0.310	3,390	1,880	309	27.4	8.28				
		05/11/23	PES	Flowing	–	–	–	0.0160 U	0.203	0.0212 U	0.191 U	1,730 J+	1,810	590	29.1	9.00				
		05/24/24	PES	Flowing	–	–	–	0.400 U	1.25 U	0.530 U	4.78 U	116	526	1,270	25.3	22.6 J+				
		11/13/24	PES	Flowing	–	–	–	0.0330 J	0.173 J	0.0212 U	0.191 U	1,350	1,860	909	38.6	14.2				

Table 7
 Groundwater Analytical Data for On Property Treatment Zones
 Former American Linen Supply
 700 Dexter Avenue North
 Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC	
PCUL					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Soil zone - Shallow only											2.4		15,000		1,200		320		24		1.4		–		77		0.35	
										WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		
MW-184 (-42.5 to -52.5)	Cluster 5	11/08/19	PES	Flowing	2,310	zJ+	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	1,590	733	79.0	2.77	11.8	U						
		01/27/20	PES	Flowing	462	ZJ+	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	886	325	22.3	1.65	0.287	J						
		04/01/20	PES	Peristaltic	212	zJ+	–	–	0.896	U	4.12	U	1.58	U	3.16	U	1.99	U	1.53	U	370	1.52	U	1.18	U			
		07/08/20	PES	Peristaltic	260	zJ+	–	–	0.0160	U	1.04		0.0212	U	0.411		154	88.4	75.7	0.646		0.971						
		11/04/20	PES	Peristaltic	–		–	–	0.160	U	0.500	U	0.212	U	1.91	U	162	102	134	1.52	J	3.97						
		02/19/21	PES	Flowing	–		–	–	0.160	U	0.500	U	0.212	U	1.91	U	305	271	432	5.52		8.80						
		05/06/21	PES	Peristaltic	–		–	–	0.0800	U	0.250	U	0.106	U	0.955	U	46.2	47.2	101	0.690	J	31.4						
		08/06/21	PES	Peristaltic	–		–	–	0.0270	J	0.207		0.0212	U	0.191	U	179	171	196	3.39		25.7						
		11/18/21	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	366	280	348	6.69		21.4						
		02/16/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	370	309	361	6.54		27.4						
		05/10/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	296	216	253	5.55		36.0						
		08/04/22	PES	Flowing	–		–	–	0.160	U	0.500	U	0.212	U	1.91	U	276	189	210	4.20		55.5						
		10/25/22	PES	Flowing	–		–	–	0.160	U	1.93	J	0.212	U	1.91	U	319	J+	217	251	5.01	23.9						
		05/10/23	PES	Flowing	–		–	–	0.160	U	0.500	U	0.212	U	1.91	U	112		132	149	3.06	38.1						
		11/02/23	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	228		224	247	6.31	39.6						
05/23/24	PES	Flowing	–		–	–	0.320	U	1.00	U	0.424	U	3.82	U	87.8	J+	117	84.4	1.38	J	63.2							
11/11/24	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	49.6	J+	56.1	40.1	0.491	75.1								

Table 7
Groundwater Analytical Data for On Property Treatment Zones
Former American Linen Supply
700 Dexter Avenue North
Seattle, Washington

Sample Location	Area Location	Sample Date	Sampled By	Sampling Method	Analytical Results (micrograms per liter)																							
					GRO		DRO		ORO		Benzene		Toluene		Ethylbenzene		Total Xylenes		PCE		TCE		cDCE		tDCE		VC	
PCUL					800		500		500		5.0		640		700		1,600		5.0		4.0		16		100		0.29	
Soil zone - Shallow only											2.4		15,000		1,200		320		24		1.4		–		77		0.35	
										WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		WATER µg/l		
MW-188 (-42.2 to -52.2)	Cluster 6	10/31/19	PES	Flowing	31.6	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U		
		01/29/20	PES	Flowing	31.9	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U		
		04/02/20	PES	Peristaltic	31.6	U	–	–	0.0896	U	0.412	U	0.158	U	0.316	U	0.199	U	0.153	U	0.0933	U	0.152	U	0.118	U		
		07/08/20	PES	Peristaltic	61.9	U	–	–	0.0160	U	1.86		0.083	J	0.786		0.0280	U	0.0160	U	0.0276	U	0.0572	U	0.0273	U		
		11/04/20	PES	Peristaltic	–		–	–	0.0161	J	0.149	J	0.0212	U	0.224	J	0.0280	U	0.0160	U	0.220		0.0572	U	0.197			
		02/16/21	PES	Peristaltic	–		–	–	0.0160	U	0.352		0.0212	U	0.191	U	0.0600	J	0.0160	U	0.589		0.0572	U	5.14	J+		
		05/07/21	PES	Peristaltic	–		–	–	0.0160	U	0.130	J	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.448		0.0572	U	2.14			
		08/10/21	PES	Peristaltic	–		–	–	0.0330	J	0.337		0.0610	J	0.375		0.0280	U	0.0160	U	0.322		0.0572	U	1.17			
		11/18/21	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.162		0.0572	U	0.340			
		02/16/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.160		0.0572	U	0.357			
		05/12/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.237		0.0572	U	0.330			
		08/05/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.104		0.0310	J	0.343		0.0572	U	0.333	J+		
		10/26/22	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.104		0.0572	U	0.192			
		05/11/23	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.0750	J	0.0572	U	0.113			
		11/03/23	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0160	U	0.103		0.0572	U	0.135			
		05/24/24	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0280	U	0.0440		0.472		0.0572	U	0.324			
		(duplicate)		11/19/24	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.0430	J	0.0160	U	0.0990	J	0.0572	U	0.172	
				11/19/24	PES	Flowing	–		–	–	0.0160	U	0.0500	U	0.0212	U	0.191	U	0.183	J	0.0740		0.0830	J	0.0572	U	0.0273	U
Number of Analytes Measured					96		0		0		442		442		442		442		442		442		442		442			
Number of Analytes Detected					50		0		0		186		205		76		92		219		291		423		337		419	
Frequency of Detection					52%		0%		0%		42%		46%		17%		21%		50%		66%		96%		76%		95%	
Maximum Detection					127,000		zJ+		0		–		0		–		6.600		J		197.0		J		0.777		J+	
Minimum Detection					31.6		U		0.0		–		0		–		0.016		U		0.050		U		0.021		U	

Notes:
 Petroleum hydrocarbons analyzed by EPA Method 418.1, NWTPH-HCID, or NWTPH-Gx, NWTPH-Dx, or 8015-M.
 VOCs analyzed by EPA Method 8260C.
 cDCE = cis-1,2-dichloroethene
 DRO = diesel-range organics
 GRO = gasoline-range organics
 ORO = oil-range organics
 PCE = Perchloroethylene (tetrachloroethene)
 TCE = Trichloroethene
 tDCE = trans-1,2-Dichloroethene
 VC = Vinyl chloride
 Well screen elevations indicated below Sample Location in parentheses.

Laboratory and Results Notes:
 Detected results shown in bold, detections above the screening level highlighted in gray.
 – = Not analyzed or results not available.
 J = The identification of the analyte is acceptable; the reported value is an estimate.
 J+ = The result is an estimated quantity, the result may be biased high.
 U = Not detected at or above the laboratory method detection limit (MDL).
 z = No/low level gasoline/petroleum detection; result is likely elevated due to high detections of CVOCs.

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Shallow Zone														
F13	Property, NE quadrant	03/27/17	266	8.85	0.0227 U	68.3	10.0	24.2	1.0	23.2	0.651	510	0.296 U	0.422 U
		06/22/17	484	12.6	0.0227 U	6.13	10.9	29.3	1.5	27.8	0.806	2,610	0.296 U	0.422 U
		Decommissioned March 2019												
FMW-143	9th Ave N ROW, E side	10/31/19	405	68.4	0.0227 U	28.0	4.34	3.57	0.0	3.6	5.18	1,490	0.296 U	0.422 U
		01/22/20	375	66.1	0.0227 U	51.8	4.40	4.92	3.5	1.4	7.70	1,320	0.296 U	0.422 U
		05/14/20	333	59.4	0.0480 U	62.7	3.99	6.17	0.0	6.2	7.51	404	0.296 U	0.422 U
		07/22/20	347	48.9	0.0480 U	46.7	4.63	5.07	4.0	1.1	6.47	1,340	0.296 U	0.422 U
J5	Property, SW quadrant	03/21/17	53.4	28.0	0.0584 J	16.3	4.10	1.09	0.6	0.5	0.474	2,370	0.296 U	29.4
		06/26/17	209	45.1	0.0227 U	8.85	11.4	2.91	–	–	2.24	9,600	19.6	34.4
		Decommissioned March 2019												
J15 (dup)	Property, SE quadrant	03/27/17	476	24.2	0.0227 U	55.8	20.0	5.52	2.0	3.5	3.34	3,100	0.296 U	0.422 U
		06/26/17	486	22.0	0.0227 U	60.3	19.1	2.66	1.5	1.2	3.09	2,220	0.296 U	0.422 U
		06/26/17	543	22.1	0.0227 U	60.4	19.0	3.02	1.5	1.5	3.03	2.34	0.296 U	0.422 U
Decommissioned March 2019														
K8	Property, SW quadrant	03/21/17	70.3	10.1	0.103	27.2	5.93	0.0622 J	0.0	0.1	0.242	41.4	0.296 U	0.422 U
		06/26/17	97.5	14.7	0.307	25.8	6.45	0.0411 J	0.0	0.0	0.296	72.7	0.296 U	0.422 U
		Decommissioned March 2019												
M15 (dup)	Property, SE quadrant	03/27/17	830	11.6	0.0227 U	40.4	11.4	3.76	2.75	1.0	6.07	11,500	0.296 U	0.422 U
		03/27/17	817	11.6	0.0227 U	40.4	11.7	3.77	–	–	6.17	10,400	0.296 U	0.422 U
		06/26/17	904	11.0	0.0227 U	47.2	11.0	3.32	–	–	6.32	7,250	0.296 U	0.422 U
Decommissioned March 2019														
MW121 (dup) (dup) (dup)	8th Ave N ROW, E side	12/26/13	790	18.6	0.0250 U	200	–	2.39	1.9	0.5	6.47	346	5 U	5 U
		03/28/17	848	12.2	0.0227 U	643	17.9	33.3	2.0	31.3	13.2	479	2.04	0.422 U
		06/20/17	930	13.3	0.0227 U	61.2 J	16.5	27.1	3.0	24.1	11.0	2,140	8.88	0.422 U
		11/30/20	829	14.1	0.0480 U	184	15.3	31.0	–	–	11.5	3,100	16.4	0.422 U
		02/04/21	–	–	–	327	11.6	2.70	–	–	0.177	121	18.5	41.6
		05/12/21	–	–	–	277	13.5	22.0	–	–	8.95	1,950	8.54	0.422 U
		05/12/21	–	–	–	278	13.1	20.3	–	–	8.98	2,580	9.74	0.422 U
		08/02/21	–	–	–	280	14.7	21.4	–	–	9.20	1,320	0.296 U	0.422 U
		05/19/22	–	–	–	298	7.16	3.79	–	–	6.19	34.6	0.420 J	0.422 U
		05/19/22	–	–	–	309	7.25	4.33	–	–	6.59	36.5	0.297 J	0.422 U
		08/04/22	–	–	–	207	7.15	2.17	–	–	7.36	380	1.83	0.422 U
		08/04/22	–	–	–	195	7.64	2.90	–	–	7.82	469	2.53	0.422 U
		10/31/22	806	–	–	218	9.26	8.60	0.0	8.6	7.55	524	3.04	0.422 U
		11/07/23	635	22.1	0.860	70.9 J-	5.92	0.257	0.5	0.0	3.64	205	1.33	0.422 U
		11/07/24	893	35.2	4.6	35.4	6.96	4.64	2.2	2.4	5.33	572	1.6	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW125	Valley St ROW, N side	12/26/13	650	112	0.076	12.8	–	2.39	1.5	0.9	1.85	455	6.34	5 U
		10/18/19	481	10.9	0.0319 J	17.1	15.3	11.7	2.0	9.7	3.67	997	0.296 U	0.422 U
		01/29/20	417	10.8	0.0227 U	32.3	8.28	17.3	2.0	15.3	3.55	2,530	1.25 J	0.422 U
		11/17/20	–	–	–	0.913 J	7.62	9.91	–	–	3.37	5,490	0.296 U	0.422 U
		02/02/21	–	–	–	0.594 U	9.09	9.27	–	–	3.36	4,330	0.296 U	0.422 U
		05/11/21	–	–	–	1.06 J	8.76	12.7	–	–	3.85	6,440	0.296 U	0.422 U
		05/11/21	–	–	–	1.08 J	8.59	11.5	–	–	3.58	5,740	0.296 U	0.422 U
		08/02/21	–	–	–	0.841 J	8.86	9.02	–	–	2.92	4,450	0.296 U	0.422 U
		11/11/21	358	14.8	1.00 U	6.00 U	8.71	9.30	5.8	3.6	3.32	4,920	0.296 U	0.422 U
		03/08/22	–	–	–	1.22 J	7.70	7.81	–	–	3.31	1,180	1.25 J	0.422 U
		05/19/22	–	–	–	1.20 J	7.31	9.44	–	–	3.18	814	0.516 J	0.422 U
		08/09/22	–	–	–	1.24 J	7.75	10.2	–	–	3.23	4,050 J	1.56	0.422 U
		08/09/22	–	–	–	1.49 J	7.84	10.2	–	–	3.31	5,580 J	1.93	0.422 U
		10/31/22	366	18.6	0.0480 U	0.594 U	7.92	9.34	3.0	6.3	3.22	5,620	1.70	0.422 U
MW-154	Roy St ROW, S side	10/14/19	186	18.4	1.58	87.8	1.92	0.173	0.0	0.2	0.129	0.287 U	0.296 U	0.422 U
		01/21/20	197	19.1	3.43	88.8	3.70	0.0624 U	0.0	0.0	0.147	128	0.296 U	5.03
		04/30/20	234	22.3	3.09	74.6	1.38	1.53	0.0	1.5	0.360	0.287 U	0.296 U	0.422 U
		07/10/20	297	23.3	1.39	69.5	1.18	0.0897 J	0.0	0.1	0.0817	0.287 U	0.296 U	0.422 U
		11/09/20	152	–	–	75.8	1.24	0.440	–	–	0.0494	0.287 U	0.296 U	0.422 U
		02/08/21	–	–	–	56.3	1.83	0.407	–	–	0.0296	9.16	0.296 U	0.422 U
		05/10/21	–	–	–	49.6	1.56	0.368	–	–	0.0255	0.287 U	0.296 U	0.422 U
		08/17/21	–	–	–	62.6	2.60	0.613	–	–	0.0411	2.91 U	4.07 U	4.26 U
		11/10/21	164	27.4	1.76	51.9	1.43	0.584	0.0	0.6	0.0285	0.287 U	0.296 U	0.422 U
		02/18/22	191	–	–	44.7	1.67	0.278	–	–	0.0111	0.287 U	0.296 U	0.422 U
		05/02/22	–	–	–	44.7	1.85	0.139	–	–	0.0118	0.287 U	0.296 U	0.422 U
		08/02/22	–	–	–	56.6	1.43	0.336	–	–	0.0319	0.287 U	0.296 U	0.422 U
		11/03/22	115	44.3	6.87	59.7	1.67	0.189	0.0	0.2	0.0301	0.287 U	0.296 U	0.422 U
		11/10/23	188	47.0	4.02	65.2	2.57	0.388	0	0.4	0.114	6,950	14.3	0.422 U
		11/07/24	206	55.1	0.308	58	2.63	0.0963 J	0.0	0.1	0.704	10,900	13.9	0.422 U
MW-155	Roy St ROW, S side	10/16/19	267	16.1	4.12	94.3	3.66	0.119	0.0	0.1	0.0716	36.1	17.5	0.422 U
		01/20/20	244	13.9	4.73	77.2	3.43	0.443	0.0	0.4	0.0392	12.0	0.296 U	0.422 U
		05/05/20	258	12.3	5.07	73.3	2.75	0.700	–	–	0.0375	0.287 U	0.296 U	0.422 U
		08/03/20	251	14.8	5.06	86.5	2.43	2.99	0.5	2.5	0.821	12.3	0.296 U	0.422 U
		11/11/20	–	–	–	84.4	1.78	0.441	–	–	0.0673	106	0.296 U	0.422 U
		08/13/21	–	–	–	69.2	1.88	0.883	–	–	0.0412	36.0	0.296 U	0.422 U
		12/02/21	216	9.58	8.40 J-	53.6	2.08	0.193	0.0	0.2	0.0156	0.287 U	0.296 U	0.422 U
		03/01/22	–	–	–	128	2.10	0.249	–	–	0.167	46.2	0.296 U	0.422 U
		05/05/22	–	–	–	84.8	1.79	0.0312 J	–	–	0.0842 J	26.8	0.296 U	0.422 U
		08/03/22	–	–	–	58.0	2.12	0.133	–	–	0.0156	2.22	0.296 U	0.422 U
		11/04/22	256	14.9	2.73	138	2.11	1.54	0.0	1.5	0.491	414	1.66	0.422 U
		11/10/23	287	15.4	2.55	146	2.21	0.970	0.0	1.0	0.413	170	1.60	0.422 U
		11/11/24	276	14.9	2.6	155	2.73	0.651	0.0	0.7	0.385	241	0.296 U	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-159	8th Ave N ROW, E side	01/29/20	393	11.0	0.0227 U	32.9	4.17	3.64	2.5	1.1	3.47	6,410	44.9	0.422 U
		11/11/20	—	—	—	12.6	2.90	7.94	—	—	3.27	2,900	27.2	0.422 U
		02/08/21	—	—	—	4.88 J	4.09	6.77	—	—	2.97	20,100	70.9	0.422 U
		05/11/21	—	—	—	2.90 J	5.22	17.9	—	—	3.60	10,500	54.5	0.422 U
		08/05/21	—	—	—	1.83 J	4.45	7.87	—	—	2.43	15,200	41.5	4.26 U
		12/02/21	289	5.96	0.100 UJ	2.15	3.84	11.8	4.5	7.3	2.86	16,100	35.3	0.422 U
		03/03/22	—	—	—	1.91 U	4.26	10.2	—	—	3.50	4,030	6.63	0.422 U
		05/11/22	—	—	—	0.594 U	3.84	7.83	—	—	3.07	15,000	21.4	0.422 U
		08/03/22	—	—	—	1.22 J	4.21	9.74	—	—	3.05	6,910	12.1	0.422 U
		10/31/22	325	11.6	0.0480 U	0.594 U	5.26	6.81	3.5	3.3	3.70	12,800	21.1	0.422 U
MW-301 (dup)	Valley St ROW, S side	11/30/20	150	28.8	4.01	25.5	2.81	0.413	—	—	0.0150	10.4	0.296 U	0.422 U
		11/30/20	152	28.7	4.00	25.5	2.72	0.149	—	—	0.00685	0.287 U	0.296 U	0.422 U
		02/04/21	149	23.0	2.73 J	25.2	2.54	0.796	—	—	0.0359	0.287 U	0.296 U	0.422 U
		05/14/21	152	32.7	2.25	21.8	2.60	4.54	—	—	0.135	0.287 U	0.296 U	0.422 U
		05/14/21	149	32.9	2.25	21.8	2.54	5.07	—	—	0.143	0.287 U	0.296 U	0.422 U
		08/20/21	143	43.6	2.42	23.0	2.30	0.609	0.0	0.6	0.0339	0.287 U	0.296 U	0.422 U
		08/20/21	145	45.8	2.57	24.2	2.41	0.574	0.0	0.6	0.0344	0.287 U	0.296 U	0.422 U
		12/02/21	145	39.6	1.56 J-	17.0	2.24	0.0566 J	0.0	0.1	0.0325	0.287 U	0.296 U	0.422 U
		05/10/22	158	60.0	1.18 J-	21.3	2.67	3.52	0.2	3.3	0.236	0.287 U	0.296 U	0.422 U
		05/10/22	152	62.4	1.23 J-	21.3	2.76	2.78	0.2	2.6	0.197	0.287 U	0.296 U	0.422 U
		08/12/22	168	68.6	1.55	23.5	2.64	0.795	0.2	0.6	0.295	41.7	0.296 U	0.422 U
		08/12/22	178	63.4	1.25	23.3	2.70	0.521	0.2	0.3	0.233	35.6	0.296 U	0.422 U
MW-305	Roy St ROW, S side	10/15/19	114	18.0	1.63	28.0	3.34	2.58	0.0	2.6	0.197	0.287 U	0.296 U	0.422 U
		01/15/20	107	11.7	1.02	28.6	10.8	6.46	0.0	6.5	0.0980	0.287 U	0.296 U	0.422 U
		04/28/20	105	48.1	2.10	23.0	0.921 J	16.0	0.0	16.0	0.221	0.287 U	0.296 U	0.422 U
		07/27/20	106	14.9	1.10	21.2	0.793 U	1.18	0.0	1.2	0.0623	0.287 U	0.296 U	0.422 U
		12/03/21	61.9	31.5	7.06 J-	91.1	3.66	0.217	0.0	0.2	0.00392	0.287 U	0.296 U	0.422 U
MW-310 (dup)	Alley E of Seattle Roy Aloha Shops	10/10/19	786	10.7	0.0227 U	88.0	8.93	11.2	4.0	7.2	3.01	558	0.296 U	0.422 U
		01/14/20	763	10.6	0.0227 U	67.8	8.07	15.4	3.0	12.4	3.34	586	0.296 U	0.422 U
		04/08/20	814	10.2	0.0480 U	54.8	8.58	19.5	3.4	16.1	3.66	714	0.770 J	0.422 U
		08/04/20	791	9.82	0.0480 U	43.5	8.73	23.3	3.6	19.7	5.90	757	0.296 U	0.422 U
		08/04/20	787	9.95	0.0480 U	43.9	8.77	23.4	3.6	19.8	6.12	754	0.296 U	0.422 U
		11/03/21	837	7.71	0.176	95.5	8.77	17.1	3.5	13.6	2.62	311	0.296 U	0.422 U
		11/01/22	665	8.19	0.0480 U	45.9	5.88	14.2	4.0	10.2	1.37	538	0.296 U	0.422 U
MW-312	Alley E of Seattle Roy Aloha Shops	10/11/19	1,220	10.9	0.0227 U	5.71	14.7	5.18	2.8	2.4	0.845	768	0.296 U	0.422 U
		01/21/20	941	6.78	0.0227 U	0.0774 U	10.8	5.93	1.5	4.4	0.860	832	0.296 U	0.422 U
		04/22/20	1,010	7.27	0.0480 U	4.23 J	10.9	7.43	3.4	4.0	1.46	618	0.296 U	0.422 U
		08/04/20	1,030	7.30	0.0480 U	11.9	11.7	8.77	—	—	2.12	556	0.296 U	0.422 U
		11/03/21	143	0.763	0.100 U	1.89	3.76	3.33	2.5	0.8	0.220	208	0.296 U	0.422 U
		11/01/22	870	9.86	0.0480 U	0.612 J	6.42	4.74	4.0	0.7	0.516	2,430	0.296 U	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-313	Alley E of Seattle Roy Aloha Shops	10/10/19	378	11.6	0.199	66.3	4.39	2.15	0.5	1.7	1.59	76.2	0.296 U	0.422 U
		01/14/20	292	20.5	0.0227 U	13.3	3.17	4.00	3.0	1.0	2.37	750	0.296 U	0.422 U
		11/09/21	329	20.6	0.228 J-	67.1	2.20	8.40	0.6	7.8	1.43	113	0.296 U	0.422 U
		11/01/22	482	17.9	26.4	164	1.75	1.87	0.0	1.9	2.29	934	0.296 U	0.422 U
MW-320	9th Ave N ROW, W side	10/07/19	1,780	12.7	0.0227 U	5.08	8.51	1.60	0.0	1.6	2.37	264	0.296 U	0.422 U
		01/20/20	294	40.6	0.0227 U	30.3	7.14	7.27	4.8	2.5	3.00	1,610	0.296 U	0.422 U
		04/29/20	282	56.5	0.0480 U	67.0	4.70	5.33	5.0	0.3	3.66	158	0.296 U	0.422 U
		07/28/20	242	44.3	0.0480 U	112	3.75	3.70	3.5	0.2	3.22	52.0	0.296 U	0.422 U
		11/16/21	200	3.81	0.850	19.9	1.17	0.304	0.0	0.3	0.0563	0.287 U	0.296 U	0.422 U
		11/04/22	277	32.1	0.0480 U	369	4.58	0.177	0.0	0.2	0.568	29.4	0.296 U	0.422 U
MW-332	Roy St ROW, N side	05/04/20	252	66.4	0.0480 U	105	2.17	3.29	2.5	0.8	2.88	757	0.296 U	0.422 U
		07/30/20	255	38.8	0.175	140	2.88	3.27	0.5	2.8	2.18	843	0.296 U	0.422 U
		11/08/21	203	129	0.450	60.6	1.68	27.6	0.0	27.6	2.85	0.287 U	0.296 U	0.422 U
		11/04/22	197	301	0.129	38.9	1.22	1.08	0.3	0.8	0.866	40.1	0.296 U	0.422 U
MW-337	Lake Union Park, N end	05/07/20	229	11.0	0.0480 U	2.94 J	2.69	3.12	2.0	1.1	1.21	1,950	0.296 U	0.422 U
		07/23/20	220	9.40	0.0480 U	0.594 U	2.76	3.91	3.2	0.7	1.04	3,230	0.296 U	0.422 U
		11/17/21	255	16.2	7.14	31.8	4.28	0.378	0.3	0.1	0.466	1,270	0.296 U	0.422 U
		11/02/22	217	34.1	0.108 J	4.92 J	2.50	12.0	3.0	9.0	1.07	4,260	0.296 U	0.422 U
MW-339 (dup)	Lake Union Park, S end	05/14/20	298	14.8	0.048 U	36.8	3.01	2.81	2.0	0.8	0.866	1,380 J	0.296 U	0.422 U
		05/14/20	299	14.8	0.048 U	37.8	3.70	2.61	2.0	0.6	0.829	979 J	0.296 U	0.422 U
		07/23/20	263	8.77	0.0480 U	13.7	3.06	1.85	1.5	0.4	0.681	1,080	0.296 U	0.422 U
		11/10/21	171	11.6	1.00 U	23.0	4.96	0.567	0.2	0.4	0.206	37.4 J	0.296 U	0.422 U
		11/10/21	174	11.6	1.00 U	22.9	4.93	0.589	0.2	0.4	0.206	26.1 J	0.296 U	0.422 U
		11/02/22	317	25.5	0.518 J	35.0	3.92	1.66	0.0	1.7	0.605	22.9	0.296 U	0.422 U
MW-9 (dup)	8th Ave N ROW, E side	12/16/13	56	3.76	0.059	6.08	-	3.32	3.4	0.0	0.778	6.24	5 U	5 U
		10/17/19	612	20.0	0.0227 U	0.0774 U	4.42	21.6	2.0	19.6	3.76	1,770	8.51	0.422 U
		11/24/20	-	-	-	0.879 J	4.94	20.8	-	-	2.35	786	3.94	0.422 U
		02/04/21	-	-	-	1.79 J	3.67	23.6	-	-	1.51	644	4.07 U	4.26 U
		05/12/21	-	-	-	0.594 U	4.32	21.6	-	-	2.03	900	3.68	0.422 U
		05/12/21	-	-	-	0.594 U	4.53	22.3	-	-	2.03	915	3.64	0.422 U
		08/02/21	-	-	-	0.594 U	5.06	19.9	-	-	1.82	799	0.296 U	0.422 U
		11/11/21	507	25.7	1.12	6.00 U	4.06	19.0	5.8	13.2	1.77	652	0.296 U	0.422 U
		02/15/22	475	-	-	19.9	4.13	5.09	-	-	4.97	37.1	0.296 U	0.422 U
		06/08/22	-	-	-	25.3	4.06	8.45	-	-	2.37	329	2.15	0.422 U
		06/08/22	-	-	-	25.6	4.07	7.02	-	-	2.29	332	1.80	0.422 U
		08/09/22	-	-	-	26.6	4.72	15.6	-	-	3.02	255	1.74	0.422 U
		10/31/22	557	32.6	1.04	9.08	4.25	12.8	0.5	12.3	2.81	187	1.67	0.422 U
		11/06/23	587	63.8	1.04	56.0	4.50	17.6	-	-	3.74	128	1.53	0.422 U
N7	Property, SW quadrant	03/30/17	118	4.73	6.87	25.2	1.35	0.120	0.0	0.1	1.50	11,000	0.296 U	0.422 U
		06/27/17	235	8.76	6.29	48.4	2.71	1.45	0.3	1.2	3.31	8,430	0.296 U	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
R-MW5	Dexter Ave N ROW, E side	03/23/17	183	32.2	0.0549 J	33.0	3.94	2.94	1.0	1.9	4.24	118	0.296 U	0.422 U
		06/16/17	152	58.3	0.253	21.8	2.59	2.74	—	—	1.29	275	0.296 U	0.422 U
		10/21/19	112	41.4	0.0227 U	18.6	4.44	3.00	1.0	2.0	1.20	194	0.296 U	0.422 U
		01/24/20	107	29.4	0.0227 U	18.5	2.74	10.2	2.5	7.7	0.999	197	0.296 U	0.422 U
		11/18/20	—	—	—	8.27	2.37	6.64	—	—	1.26	182	0.296 U	0.422 U
		02/11/21	—	—	—	9.48	4.92 J	2.35	—	—	0.371	138	0.296 U	0.422 U
		02/11/21	—	—	—	9.16	1.72 J	2.07	—	—	0.363	128	0.296 U	0.422 U
		05/17/21	—	—	—	7.99	1.45	2.79	—	—	0.346	595	0.296 U	0.422 U
		08/03/21	—	—	—	8.33	2.79	1.66	—	—	0.948	3,200	0.296 U	0.422 U
		08/03/21	—	—	—	8.21	3.00	1.59	—	—	0.991	3,660	0.296 U	0.422 U
		11/08/21	93.3	13.5	0.100 UJ	8.09	1.76	1.34	1.0	0.3	0.305	2,910	0.296 U	0.422 U
		02/24/22	—	—	—	8.42	1.60	2.91 J	—	—	0.437	1,210	0.296 U	0.422 U
		02/24/22	—	—	—	8.37	1.72	2.14 J	—	—	0.406	1,240	0.296 U	0.422 U
		05/17/22	—	—	—	9.57	6.80	6.28 J	—	—	3.16 J	682	1.23 J	0.422 U
		08/09/22	—	—	—	13.8	6.80	8.25	—	—	6.02	381	1.26 J	0.422 U
		11/08/22	156	41.5	0.0480 U	15.0	5.88	7.53	2.5	5.0	4.06	332	0.296 U	0.422 U
		10/31/23	144	29.0	0.0548 U	8.94	4.81	10.7	—	—	1.86	183	0.296 U	0.422 U
		11/13/24	93.4	5.65	0.317	6.76	1.69	2.39	0.5	1.9	0.326	907	0.296 U	0.422 U
R-MW6	8th Ave N ROW, W side	03/21/17	586	5.72	0.191	119	6.28	5.02	—	—	6.24	9,410	0.296 U	0.422 U
		06/20/17	718	11.1	0.0227 U	85.7	13.6	27.0	1.5	25.5	8.28	6,980	10.7	11.2
		12/01/20	—	—	—	160	17.3	6.87	—	—	2.40	502	4.85	0.422 U
		02/03/21	—	—	—	207	2.21	1.08	—	—	0.386	881	0.296 U	0.422 U
		05/17/21	—	—	—	333	8.97	17.0	—	—	9.43	12,800	6.74	0.422 U
		08/03/21	—	—	—	318	15.2	15.5	—	—	11.2	12,400	0.296 U	0.422 U
		11/29/21	358	19.0	0.100 UJ	185	2.77	3.79	3.2	0.6	4.75	6,180	0.296 U	0.422 U
		02/23/22	—	—	—	69.6	7.85	11.7	—	—	6.35	12,700	3.37	0.422 U
		05/11/22	—	—	—	219	8.84	25.8	—	—	10.1 J	3,190	2.65	0.422 U
		08/03/22	—	—	—	60.6	10.2	27.9	—	—	9.07	10,200	5.54	0.422 U
		11/04/22	751	48.7	0.0480 U	194	10.9	22.6	2.0	20.6	8.09	7,870	8.85	0.422 U
		11/03/23	840	10.1	0.0480 U	22.9	5.77 J	15.7	—	—	4.71	14,400	17.7	0.422 U
		11/08/24	817	14.2	0.0884 U	0.637 U	9.12	46.2	4.8	41.4	10.8	6,550	6.04	0.422 U
SCL-MW101	Alley E of Seattle Roy Aloha Shops	11/11/21	551	4.63	1.00 U	162 J	6.53	19.9	2.8	17.2	1.37	138	0.296 U	0.422 U
		11/03/22	598	5.74	0.0480 U	194	7.48	9.56	1.8	7.8	1.05	33.5	0.296 U	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Intermediate A Zone														
BB-8	Roy St ROW, S side	12/29/13	270	12.6	3.68	84.6	–	0.085	0.0	0.1	0.252	5	U	5
		03/22/17	254	7.87	3.17	41.5	2.25	0.125	0.0	0.1	0.0705	0.412	J	0.296
(dup)		06/14/17	290	10.2	2.74	56.9	3.34	0.0348	J	0.0	0.0	0.0475	0.287	U
		04/11/18	258	7.43	3.41	3.98	3.24	0.145		0.0	0.1	0.0940	0.287	U
		04/11/18	262	7.42	3.17	3.98	3.14	0.0962		0.0	0.1	0.0544	0.287	U
		01/23/19	280	12.4	0.891	93.3	3.43	0.0954	J	–	–	0.0820	J	0.422
		04/23/19	227	28.1	2.77	44.4	2.71	0.315		0.0	0.3	0.0637	0.287	U
(dup)		07/17/19	240	10.4	1.94	59.0	4.36	0.691		0.0	0.7	0.0979	62.2	U
		10/22/19	245	10.3	1.98	67.3	5.09	0.678		0.0	0.7	0.376	74.8	U
		10/22/19	246	10.5	2.17	70.0	4.27	0.339		0.0	0.3	0.313	0.287	U
		01/20/20	220	12.8	3.36	76.4	4.70	0.0893	J	0.0	0.1	0.0156	46.7	U
		01/20/20	220	12.9	3.30	76.6	5.07	0.0585	J	0.0	0.1	0.0134	0.287	U
(dup)		05/12/20	210	17.9	2.98	87.3	3.09	0.533		0.0	0.5	0.0865	0.287	U
		07/27/20	217	17.9	2.96	91.7	3.38	0.685		0.5	0.2	0.297	10.8	J
		07/27/20	217	17.7	2.92	91.5	3.38	0.780		0.5	0.3	0.323	17.6	J
		11/17/20	–	–	–	123	2.47	4.91		–	–	0.971	55.5	U
		02/11/21	–	–	–	40.9	1.80	0.769		–	–	0.171	0.287	U
(dup)		06/07/21	–	–	–	41.2	1.99	1.21		–	–	0.164	0.287	U
		08/17/21	–	–	–	44.00	2.22	0.130		–	–	0.0332	2.91	U
		11/08/21	224	19.1	3.95	52.7	2.27	0.277		0.0	0.3	0.116	0.287	U
		02/24/22	–	–	–	35.5	1.61	0.0933	J	–	–	0.0518	0.287	U
		05/17/22	–	–	–	42.3	1.85	0.0281	U	–	–	0.0118	0.287	U
		08/09/22	–	–	–	40.2	2.28	0.0456	J	–	–	0.0274	0.287	U
		08/09/22	–	–	–	40.9	2.23	0.0427	J	–	–	0.0253	0.287	U
		11/09/22	207	34.1	1.05	78.7	2.37	0.228		0.0	0.2	0.0763	297	U
		10/31/23	274	31.2	0.0729	U	67.8	2.94		0.5	–	6.71	22,800	U
		11/13/24	323	26.3	0.0884	U	127	2.89		4.5	6.0	4.85	25,800	U
FMW-142	9th Ave N ROW, E side	10/31/19	276	25.5	0.0227	U	18.2	6.5	3.36	0.5	2.9	0.307	8,040	U
		01/22/20	358	24.5	0.0251	U	3.63	J	5.86	2.2	3.7	0.299	6,980	U
		04/28/20	363	23.9	0.0480	U	7.04		5.55	5.0	0.6	0.273	9,280	U
		07/08/20	373	25.4	0.0789	J	5.36		5.63	4.4	1.2	0.305	8,540	U
		11/04/22	261	83.5	0.0480	U	9.82		3.48	–	–	0.907	3,270	U
(dup)		11/06/23	1020	39.4	0.159	J	13.5	15.5	10.4	–	–	5.63	8,150	U
GEI-1	Block 37, SW quadrant	03/24/17	564	8.9	0.0227	U	0.0774	U	23.8	1.0	22.8	3.10	20,500	U
		06/13/17	304	15	0.0792	J	25.3		9.05	–	–	1.50	10,600	U
		07/16/19	529	13.4	0.0227	U	0.0774	U	17.1	3.0	14.1	2.48	16,100	U
		10/21/19	589	14.7	0.0227	U	2.76	J	16.5	2.1	14.4	2.82	21,400	U
		01/22/20	405	11.4	0.0236	U	9.33		11.3	3.0	8.3	1.88	13,900	U
		04/29/20	296	15.9	0.118		36		7.96	2.0	6.0	1.59	9,170	U
		04/29/20	287	15.8	0.181		36.2		6.57	2.0	4.6	1.31	7,980	U
		07/30/20	337	42.3	0.0480	U	53.3		9.86	2.4	7.5	1.96	8,220	U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW108	Alley E of Seattle Roy Aloha Shops	12/17/13	600	25.8	0.075	12.5	–	17.5	21.7	0.0	1.96	2,110	22.8	5 U
		03/28/17	577	22.1	0.0227 U	106	7.32	19.7	2.5	17.2	2.27	1,740	36.4	2.20
		06/27/17	679	20.6	0.0227 U	101	8.62	21.8	2.0	19.8	2.20	3,940	47.8	0.42 U
		10/10/19	570	26.1	0.0227 U	43.7	5.83	13.5	3.3	10.2	1.76	3,650	70.7	6.24
		01/14/20	586	20.8	0.0227 U	33.1	5.41	15.9	4.5	11.4	1.86	4,460	74.1	21.6
		04/22/20	744	16.0	0.048 U	2.06 J	10.8	16.7	6.6	10.1	1.94	10,500	27.3	0.422 U
		07/16/20	649	20.8	0.0480 U	50.2	8.02	15.2	7.0	8.2	1.97	8,660	50.1	0.422 U
		07/16/20	651	24.2	0.0480 U	51.5	8.11	15.6	7.0	8.6	2.05	9,770	53.7	0.422 U
		11/04/20	–	–	–	16.6	5.71	18.3	–	–	2.62	8,660	119	50.1
		02/09/21	–	–	–	25.8	5.75	15.0	–	–	2.09	3,510	64.7	21.3
		05/03/21	–	–	–	39.6	6.08	13.9	–	–	1.75	3,640	77.7	17.8
		08/04/21	–	–	–	34.5	6.38	13.2	–	–	1.81	3,970	65.1	17.6
		11/04/21	444	17.0	0.230	29.1	4.33	10.7	4.5	6.2	1.35	2,150	35.2	10.0
		02/15/22	582	–	–	33.5	4.90	12.9	–	–	1.51	1,990	24.2	6.71
		05/18/22	–	–	–	26.1	4.57	14.6	–	–	1.47	1,970	19.7	4.98
		08/10/22	–	–	–	31.1	4.54	13.1	–	–	1.56	3,590	35.0	6.27
		11/01/22	518	22.4	0.0480 U	35.0	4.22	12.1	0.0	12.1	1.56	3,350	34.2	7.87
		11/07/23	525	22.6	0.634	6.93	3.85	11	4	7.0	1.43	3800	23.7	9.88
		11/12/24	517	24.3	0.0884 U	16.9	7.74	12.5	7	5.5	1.5	6,320	47.1	16.5 J
		11/12/24	514	25.5	0.0884 U	17.5	6.25	12.4	7	5.4	1.48	6,400	50.2	24 J
MW109	Alley E of Seattle Roy Aloha Shops	12/17/13	670	16.1	0.0250 U	34.6	–	12.6	16.2	0.0	4.04	1,400	5.89	5 U
		03/29/17	498	6.90	0.0255 J	31.4	10.8	12.0	1.5	10.5	3.01	2,000	7.21	0.422 U
		06/17/17	693	13.3	0.0227 U	42.5	12.2	14.6	1.5	13.1	3.90	2,540	8.65	0.422 U
		10/15/19	628	13.7	0.0227 U	9.12	10.4	14.4	2.5	11.9	4.10	4,950	25.6	6.99
		01/21/20	143	3.77	0.127	1.51 U	2.73	0.544	0.0	0.5	0.767	886	0.296 U	0.422 U
		04/22/20	616	5.03	0.0480 U	3.41 J	10.3	12.2	3.0	9.2	3.75	3,800	21.2	0.422 U
		07/06/20	588	5.92	0.0613 J	3.74 J	8.41	12.6	6.0	6.6	3.81	3,790	22.1	0.422 U
		11/02/20	–	–	–	8.89	8.69	14.6	–	–	3.94	2,620	31.5	4.26 U
		02/09/21	–	–	–	0.696 J	6.65	9.95	–	–	3.14	4,220	16.4	0.422 U
		05/03/21	–	–	–	1.70 J	5.44	9.48	–	–	2.90	3,100	13.8	0.422 U
		08/04/21	–	–	–	2.30 J	6.28	2.06	–	–	0.523	884	4.07 U	4.26 U
		11/03/21	476	5.53	0.100 U	3.06	5.24	9.87	5.5	4.4	3.36	1,770	10.3	0.422 U
		02/15/22	–	–	–	2.04 J	5.72	9.57	–	–	2.84	2,260	7.43	0.422 U
		05/09/22	–	–	–	1.89 J	5.87	10.5	–	–	2.92	4,020	15.3	1.22 J
		08/10/22	–	–	–	1.32 J	1.19	0.181	–	–	0.0131	0.287 U	0.296 U	0.422 U
		11/01/22	497	7.52	0.105	5.22	4.29	12.3	4.5	7.8	3.18	2,190	8.63	0.422 U
		11/07/23	459	3.93	0.0881 U	2.26 J	4.5	8.08	2.5	5.6	2.84	1750	3.8	0.422 U
		11/08/24	427	4.17	0.0884 U	0.637 U	4.68	9.97	4	6.0	3.01	3,190	5.17	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)						
								Total	Ferrous	Ferric		Methane	Ethane	Ethene				
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER				
MW110	Alley E of Seattle Roy Aloha Shops	12/19/13	390	20.4	0.603	158	–	0.079			3.28	7.66	5	U	5	U		
		03/23/17	425	36.2	0.652	108	7.98	0.948	J	0.1	0.8	3.90	125	1.21	J	0.422	U	
		06/27/17	516	27.0	0.0227	160	4.91	0.115		0.0	0.1	2.13	95.5	17.4		0.422	U	
		10/15/19	465	19.3	0.0227	73.2	7.05	1.29		–	–	3.43	5,020	0.296	U	0.422	U	
		01/16/20	373	14.0	0.0227	36.2	3.01	0.32		0.0	0.3	2.89	2,590	2.58		0.422	U	
		04/22/20	472	19.8	0.0480	88.9	5.81	2.55		0.0	2.6	3.29	2,660	0.296	U	0.422	U	
		07/16/20	490	20.0	0.0480	98.7	4.64	2.68		0.0	2.7	3.16	3,000	7.68		0.422	U	
		11/04/20	–	–	–	106	3.59	1.53		–	–	1.93	2,040	0.296	U	0.422	U	
		02/09/21	–	–	–	79.6	3.08	1.17		–	–	2.79	1,660	0.296	U	0.422	U	
		05/04/21	–	–	–	76.4	3.03	5.54		–	–	2.81	2,630	5.45		0.422	U	
		08/12/21	–	–	–	72.6	3.00	2.01		–	–	2.54	2,430	7.53		0.422	U	
		11/09/21	373	15.1	0.200	89.1	2.98	5.59		0.2	5.4	2.23	3,080	16.1		0.422	U	
		02/25/22	–	–	–	80.3	2.79	1.26	J	–	–	3.09	4,620	5.97		0.422	U	
		05/18/22	–	–	–	74.3	2.53	2.34		–	–	2.85	6,540	5.88		0.422	U	
		08/11/22	–	–	–	70.9	2.42	0.210		–	–	2.77	8,590	5.85		0.422	U	
		11/01/22	356	14.1	0.142	75.0	2.48	0.161		0.0	0.2	2.83	6,950	8.24		0.422	U	
		11/07/23	428	26.4	0.0744	89.2	3.11	1.56		0.769	0.8	3.4	5600	8.8		0.422	U	
		11/12/24	428	42.4	0.0884	99.9	11.7	0.412		0.5	0.0	4.59	2,380	7.33		0.422	U	
MW114	SDOT Mercer Parcels	12/18/13	190	31.2	0.032	98.8	–	0.075		0.03	0.05	0.629	5	U	5	U	5	U
MW115	9th Ave N ROW, W side	12/19/13	580	22.1	0.0250	3.35	–	6.24	6.69	0.0	1.44	2,550	5	U	5	U		
		03/22/17	417	28.5	0.0227	35.9	7.69	5.69		1.5	4.2	1.32	215	0.296	U	0.422	U	
		06/22/17	401	33.0	0.0227	46.1	7.39	6.19		1.5	4.7	1.19	3,570	4.98		0.422	U	
		10/22/19	330	19.3	0.0227	23.6	5.51	4.53		2.0	2.5	0.930	1,500	4.04		4.17		
		01/20/20	346	19.8	0.0227	15.6	5.72	4.66		2.0	2.7	0.957	1,080	2.74		0.422	U	
		05/05/20	355	28.3	0.0480	209	6.84	11.5		2.0	9.5	1.46	1,760	0.296	U	0.422	U	
		07/28/20	407	25.0	0.0480	141	8.58	12.1		4.5	7.6	1.53	665	0.296	U	0.422	U	
		11/12/20	–	–	–	170	7.33	7.99		–	–	1.56	641	3.90		0.422	U	
		02/12/21	–	–	–	68.2	6.73	13.5		–	–	1.23	1,570	0.296	U	0.422	U	
		05/25/21	–	–	–	82.9	6.34	7.21		–	–	1.08	1,580	0.296	U	0.422	U	
		08/11/21	–	–	–	162	8.75	7.60		–	–	1.77	743	0.296	U	0.422	U	
		11/18/21	409	27.2	J	0.500	79.8	J	8.28	3.5	1.8	1.06	1,060	0.296	U	0.422	U	
		02/15/22	–	–	–	139	5.81	5.68		–	–	1.34	308	1.47		0.422	U	
		06/03/22	–	–	–	67.2	5.78	4.15		–	–	1.14	477	4.07	U	4.26	U	
		08/10/22	–	–	–	36.2	6.03	4.67		–	–	0.938	668	3.31		0.422	U	
		11/03/22	302	24.3	0.0480	21.6	4.51	4.05		2.0	2.1	1.03	523	J	6.06	0.422	U	

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW116	9th Ave N ROW, W side	12/19/13	310	26.2	0.0250 U	14.5	–	2.48	2.65	0.0	1.14	1,750	5 U	5 U
		03/21/17	432	22.0	0.0227 U	25.7	7.34	6.01	3.9	2.1	0.869	8,590	0.296 U	0.422 U
		06/16/17	377	25.1	0.0227 U	9.31	6.80	6.69	1.8	4.9	0.793	8,610	0.296 U	0.422 U
		10/22/19	361	23.6	0.0227 U	0.0774 U	5.95	3.72	1.3	2.4	0.723	7,650	0.296 U	0.422 U
		01/21/20	350	24.6	0.0227 U	0.0774 U	6.34	3.9	1.0	2.9	0.744	5,540	0.296 U	0.422 U
		04/29/20	358	23.4	0.0480 U	0.594 U	6.53	6.83	3.8	3.0	0.811	6,140	0.296 U	0.422 U
		07/28/20	314	25.4	0.0480 U	0.594 U	5.95	17.7	2.5	15.2	0.911	8,900	0.296 U	0.422 U
		11/12/20	–	–	–	1.94 J	5.90	5.95	–	–	0.790	10,100	0.296 U	0.422 U
		02/11/21	–	–	–	9.16	5.64	5.72	–	–	0.767	8,410	0.296 U	0.422 U
		05/25/21	–	–	–	8.91	5.14	4.16	–	–	0.775	6,550	0.296 U	0.422 U
		08/11/21	–	–	–	10.3	5.85	4.84	–	–	0.736	4,540	0.296 U	0.422 U
		11/18/21	303	29.1 J	0.500 U	8.40	5.87	4.03	2.8	1.3	0.757	4,140	0.296 U	0.422 U
		03/07/22	–	–	–	8.98	5.68	3.75	–	–	0.745	994	0.296 U	0.422 U
		06/08/22	–	–	–	9.61	5.48	4.59	–	–	0.815	4,280	0.746 J	0.422 U
		08/10/22	–	–	–	9.72	5.75	3.44	–	–	0.686	3,190	0.460 J	0.422 U
		11/04/22	311	32.1	0.0480 U	8.71	5.21	3.11	2.0	1.1	0.777	3,210	0.296 U	0.422 U
MW117	Dexter Ave N ROW	12/18/13	200	9.11	0.0250 U	56.3	–	1.49	2.03	0.00	0.344	5 U	5 U	5 U
MW119	9th Ave N ROW, W side	12/19/13	310	12.1	0.0250 U	3.34	–	19.4	18.6	0.8	2.55	3,450	5 U	5 U
		03/29/17	255	20.5	0.164	14.9	6.84	17.1	2.0	15.1	2.98	819	0.296 U	0.422 U
		06/28/17	360	13.7	0.0227 UJ	56.1	9.09	5.66	1.5	4.2	1.25	73.5	0.296 U	0.422 U
		10/10/19	226	18.6	0.0227 U	26.4	4.98	10.7	3.0	7.7	2.63	289	0.296 U	0.422 U
		01/14/20	237	19.0	0.0227 U	26.8	4.58	9.20	–	–	2.28	396	0.296 U	0.422 U
		04/27/20	281	14.9	0.0480 U	5.67	7.19	12.3	3.5	8.8	3.2	480	0.296 U	0.422 U
		07/08/20	213	19.9	0.0480 U	32.5	5.94	11.2	5.5	5.7	2.54	4,480	0.296 U	0.422 U
		11/11/20	–	–	–	26.7	6.43	11.1	–	–	2.51	6,170	0.296 U	0.422 U
		02/10/21	–	–	–	2.46 J	7.56	14.4	–	–	3.27	3,960	0.296 U	0.422 U
		05/20/21	–	–	–	3.83 J	5.67	13.9	–	–	3.14	7,960	0.296 U	0.422 U
		08/13/21	–	–	–	4.78 J	6.01	14.5	–	–	3.14	4,360	0.296 U	0.422 U
		12/03/21	231	12.5	0.100 UJ	7.26	6.65	12.7	1.8	11.0	2.73	8,830	0.296 U	0.422 U
		03/02/22	–	–	–	13.6	6.04	12.3	–	–	2.90	1,910	0.296 U	0.422 U
		05/05/22	–	–	–	7.73	6.19	14.7	–	–	3.62	7,820	0.296 U	0.422 U
		08/11/22	–	–	–	10.7	5.75	13.0	–	–	2.98	6,400	0.296 U	0.422 U
		11/02/22	265	22.2	0.0480 U	108	1.22	3.21	1.5	1.7	1.07	166	2.09	0.422 U
(dup)		11/02/22	265	22.2	0.0480 U	108	1.34	2.98	1.5	1.5	1.02	169	1.61	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW120	8th Ave N ROW, E side	12/19/13	290	36.5	0.0690	99.4	–	0.288	0.2	0.1	0.319	10.1	5 U	5 U
		04/09/18	151	30.2	0.237	66.9	1.08	1.40	0.0	1.4	0.194	0.287 U	0.296 U	0.422 U
		01/24/19	206	22.4	1.98	73.6	1.78	3.68	0.0	3.7	0.387	235	2.71	0.422 U
		05/03/19	217	20.5	2.01	66.2	1.66	2.31 J	–	–	0.384	157 J	0.296 U	0.422 U
(dup)		05/03/19	217	20.3	1.96	65.9	1.58	1.12 J	–	–	346	115 J	0.296 U	0.422 U
		07/16/19	211	19.9	1.76	67.1	1.7	2.85	0.0	2.9	0.391	72.4	0.296 U	0.422 U
(dup)		10/17/19	264	22.0	0.472	119	3.64	0.937	0.0	0.9	0.637	86.4 J	0.296 U	0.422 U
		10/17/19	264	22.0	0.473	120	3.68	0.930	0.0	0.9	0.637	43.9 J	0.296 U	0.422 U
		01/17/20	296	20.9	0.0227 U	125	3.05	1.59	0.5	1.1	0.707	104	2.53	0.422 U
		04/23/20	287	21.3	0.0480 U	110	3.18	2.24	1.2	1.0	0.621	34.8	0.296 U	0.422 U
		07/14/20	291	20.5	0.0480 U	106	2.30	4.40	0.0	4.4	0.731	277	0.296 U	0.422 U
(dup)		11/30/20	–	–	–	121	1.70	5.45	–	–	0.611	87.5	0.296 U	0.422 U
		11/30/20	–	–	–	122	1.93	5.09	–	–	0.628	124	3.29	0.422 U
		02/04/21	–	–	–	127	2.00	5.57	–	–	0.537	107	4.07 U	4.26 U
		05/12/21	–	–	–	128	1.79	6.73	–	–	0.492	90.8	0.296 U	0.422 U
		08/03/21	–	–	–	127	1.97	2.73	–	–	0.469	107	0.296 U	0.422 U
		11/11/21	195	21.8	1.19	112	1.22	3.76	0.2	3.6	0.454	177	0.296 U	0.422 U
		02/15/22	200	–	–	112	2.06	1.87	–	–	0.426	122	1.09 J	0.422 U
		05/11/22	–	–	–	98.4	1.26	1.75	–	–	0.385	112	1.31	0.422 U
		08/04/22	–	–	–	90.7	1.66	2.01	–	–	0.397	111	1.06 J	0.422 U
		10/31/22	189	20.7	1.42	79.6	1.58	5.00	0.0	5.0	0.407	117	1.35	0.422 U
		11/06/23	182	22.2	1.66	53.8	1.35	0.952	0.5	0.5	0.344	17.4	0.758 J	0.422 U
		11/07/24	22.4	3.64	0.506	2.83 J	1.17	0.0226 U	0	0.0	0.0204	0.287 U	0.296 U	0.422 U
MW127	8th Ave N ROW, E side	10/17/19	133	27.2	0.323	71.6	1.9	0.920	0.0	0.9	0.161	0.287 U	0.296 U	0.422 U
		01/17/20	133	24.7	0.728	74.5	2.03	4.06	0.0	4.1	0.184	69.0	0.296 U	0.422 U
		04/23/20	142	24.8	1.27	67.1	1.04	7.26	0.0	7.3	0.203	0.287 U	0.296 U	0.422 U
(dup)		07/14/20	138	23.7	1.47	62.6	0.972 J	7.52	0.0	7.5	0.217	0.287 U	0.296 U	0.422 U
		07/14/20	134	23.8	1.48	62.8	0.964 J	8.04	0.0	8.0	0.221	0.287 U	0.296 U	0.422 U
		11/17/21	140	24.9	0.820	50.5	1.25	0.0599 J	0.0	0.1	0.147	0.287 U	0.296 U	0.422 U
		10/31/22	144	26.9	0.870	53.0	1.18	0.0910 J	0.0	0.1	0.158	7.97	0.296 U	0.422 U
MW131	Property, SE quadrant	03/27/17	911	141	0.0227 U	0.0774 U	8.93	7.98	1.9	6.1	1.06	16,200	0.296 U	280
		06/20/17	1,050	122	0.0227 U	0.724 J	10.8	7.42	–	–	1.01	10,700	0.296 U	332
		04/16/18	712	114	0.0227 U	0.0774 U	44.2	7.97	1.8	6.2	1.19	29,900	329	467
		Decommissioned March 2019												

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-142	8th Ave N ROW, E side	04/27/18	794	15.6	0.0227 U	0.426 J	33.7	3.16	1.5	1.7	2.58	7,980	44.6	0.422 U
(dup)		01/28/19	784	10.1	0.0227 U	0.0774 U	27.7	2.87	2.0	0.9	2.37	3,530	17.7	0.422 U
		01/28/19	779	10.2	0.0227 U	0.0774 U	28.3	2.66	2.0	0.7	2.46	3,490	18.5	0.422 U
		04/24/19	798	9.76	0.0227 U	27.3	31.7	3.50	1.2	2.3	1.99	3,560	19.2	0.422 U
		07/25/19	792	10.6	0.0227 U	48.8	27.9	5.89	2.1	3.8	3.63	3,070	27.8	0.422 U
		10/16/19	812	14.9	0.0227 U	15.9	4.76	5.40	2.0	3.4	3.44	766	47.8	0.422 U
		01/22/20	831	18.6	0.0230 U	19.0	18.5	5.30	2.5	2.8	3.42	493	31.3	0.422 U
(dup)		04/24/20	850	17.5	0.0695 J	22.6	16.1	5.80	3.0	2.8	3.52	471	27.1	0.422 U
		07/30/20	843	20.0	0.0480 U	28.4	18.5	4.83	3.5	1.3	3.04	278	29.8	0.422 U
		11/24/20	—	—	—	45.8	18.6	7.10	—	—	3.50	871	35.5	0.422 UJ
		11/24/20	—	—	—	45.9	18.5	6.62	—	—	3.46	1,000	40.3	5.13
		02/08/21	—	—	—	16.7	45.7	3.90	—	—	3.63	2,500	31.3	0.422 U
		05/19/21	—	—	—	11.1	20.0	7.45	—	—	3.90	9,010	27.5	4.60
(dup)		08/05/21	—	—	—	37.3	18.9	8.29	—	—	3.86	5,070	28.5	4.26 U
		11/30/21	833	12.0	0.100 U	62.5	16.7	8.29	4.0	4.3	4.39	9,530	30.1	0.422 U
		02/18/22	920	—	—	62.2	15.7	9.32	—	—	4.39	3,790	11.5	1.59
		05/26/22	—	—	—	24.6	15.8	9.62	—	—	4.77	8,710	19.7	1.53
		08/03/22	—	—	—	11.1	11.0	7.72	—	—	3.79	10,600	17.6	1.81
		10/31/22	1010	30.9	0.0480 U	15.5	16.0	9.36	4.5	4.9	5.10	9,630	37.3	13.1
		10/31/22	1020	31.2	0.0480 U	16.0	15.7	9.21	4.5	4.7	5.13	9,280	37.1	12.8
		05/16/23	—	—	—	59.4 U	14.1	9.49	—	—	5.42	5,570	10.8	2.25
		11/06/23	1030	41.0	0.0480 UJ	14.4	16.7	10.7	3.5	7.2	5.64	7,970	24.4	4.38
		05/21/24	—	—	—	1.31 J	0.828 J	1.65	—	—	0.145	40.7	0.296 U	0.422 U
		11/06/24	122	8.05	2.5	2.29 U	1.49	0.623	0.4	0.2	0.177	158	1.12 J	0.422 U
MW-144	8th Ave N ROW, E side	04/27/18	740	182	0.0227 U	9.39	159	1.07	0.5	0.6	1.98	17,700	55.4	5,480
		01/28/19	735	149	0.0227 U	0.0774 U	15.1	1.98	—	—	1.66	13,700	495	1,140
		04/23/19	733	144	0.0227 U	0.0774 U	11.4	1.22	1.2	0.0	1.48	13,000	771	699
Damaged June 2019 and Decommisioned December 2019														

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-144R	8th Ave N ROW, E side	12/16/19	673	93.1	0.0227 U	11.3	46.5	2.04	2.0	0.0	1.93	8,640	16.5	305
		01/21/20	573	93.4	0.0239 U	0.0774 U	47.7	5.06	3.5	1.6	1.99	5,560	9.61	276
		04/02/20	624	96.8	0.0252 J	0.37 U	24.0	6.49	3.0	3.5	1.51	13,900	28.1	466
		08/03/20	618	97.4	0.0480 U	0.594 U	4.62	4.54	2.4	2.1	1.15	18,500	367	102
		11/23/20	—	—	—	0.594 U	3.82	5.74	—	—	1.07	20,400	414	33.8
		02/02/21	—	—	—	1.18 J	3.47	2.51	—	—	1.03	1,220	408	0.422 U
		05/12/21	—	—	—	1.63 J	3.92	1.68	—	—	1.15	11,800	389	0.422 U
		08/03/21	—	—	—	0.594 U	4.55	2.76	—	—	1.13	10,800	349	0.422 U
		11/29/21	762	88.2	0.191	0.100 U	4.88	5.39	3.4	2.0	1.47	12,700	422	0.422 U
		02/23/22	—	—	—	2.04 J	4.63	1.17	—	—	1.21	7,800	131	0.422 U
		05/11/22	—	—	—	1.13 J	4.08	1.75	—	—	1.14	3,590	45.5	0.422 U
		08/23/22	—	—	—	1.23 J	4.18	2.30	—	—	1.25	20,100	121	8.01
		11/02/22	823	101	0.0480 U	1.01 J	4.09	2.81	0.8	2.0	1.42	27,900	50.4	2.45
		05/15/23	—	—	—	0.869 J	5.83	3.43	—	—	1.46	12,000	55.8	4.26 U
		11/08/23	921	1,020	0.483 J	13.2 J	5.30	6.60	5.80	0.8	1.58	10,900 J-	111	7.07
		05/22/24	—	—	—	4.42 J	5.37	3.67	—	—	1.56	11,200	74.5	2.78
		11/07/24	952	101	0.0884 U	0.637 U	5.18	4.8	3.2	1.6	1.81	21,700	92.8	0.422 U
MW-146	Roy St ROW, S side	04/30/18	363	30.4	0.0227 U	22.3	4.47	2.65	1.3	1.4	1.26	9,240	11.9	489
		01/22/19	249	15.8	0.0227 U	32.1	3.43	1.76	2.0	0.0	0.56	2,460	1.84	107
		04/24/19	310	14.8	0.0227 U	23.3	4.95	2.87	2.5	0.4	0.770	5,090	4.00	347
		07/19/19	310	17.2	0.0227 U	23.9	3.78	2.87	1.9	1.0	0.800	6,490	0.296 U	463
		07/19/19	307	17.2	0.0227 U	24.2	3.67	2.95	1.9	1.1	0.817	5,480	0.296 U	387
		10/14/19	338	23.3	0.0227 U	20.6	3.63	2.91	2.0	0.9	0.898	6,190	0.296 U	394
		01/24/20	362	32.1	0.0227 U	15.5	3.31	3.72	4.0	0.0	1.17	888 J	3.09	728
		01/24/20	365	30.9	0.0227 U	15.3	3.30	3.22	4.0	0.0	1.12	6,280 J	3.27	672
		04/30/20	383	40.9	0.0480 U	13.7	3.55	2.91	2.5	0.4	1.1	5,020	0.296 U	511
		07/09/20	383	42.9	0.0480 U	16.6	2.92	3.08	3.0	0.1	1.14	5,990	0.296 U	463
		11/10/20	277	—	—	31.1	2.18	2.59	—	—	1.07	7,340	2.67	315
		02/08/21	—	—	—	31.5	2.17	2.97	—	—	0.952	3,330	0.296 U	239
		05/04/21	—	—	—	5.87	19.0	6.29	—	—	1.11	16,100	0.296 U	1,060
		08/17/21	—	—	—	3.18 J	11.4	7.62	—	—	1.23	8,260	334	1,810
		11/10/21	419	29.1	1.00 U	3.06	6.60	6.80	3.5	3.3	1.36	16,900	998	930
		02/18/22	508	—	—	13.4	3.57	6.15	—	—	1.33	4,870	149	180
		05/03/22	—	—	—	15.0	3.92	5.15	—	—	1.41	11,700	302	250
		08/03/22	—	—	—	12.2	3.62 J+	5.35	—	—	1.43	10,500	374	252
		11/03/22	470	38.9	0.0480 U	7.54	4.03	4.65	3.5	1.2	1.57	14,200	437	333
		05/12/23	—	—	—	12.7	6.15	6.39	—	—	1.71	21,300	366	241
		11/10/23	610	49.9	0.0789 J	7.90	5.35	10.1	2.5	7.6	1.56	17,900	340	194
		05/31/24	—	—	—	17.6 J	5.61	7.67	—	—	1.76	1,080	13.0	9.86
		05/31/24	—	—	—	15.6	5.78	7.54	—	—	1.67	10,200	116	85.9
		11/07/24	575	50.6	0.0884 U	6.4	4.52 J	7.14	3.4	3.7	1.58	23,400	307	220
		11/07/24	578	50.4	0.0884 U	6.06	8.39 J	7.28	3.4	3.9	1.58	21,100	286	206

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-149	Property, NE quadrant	04/10/18	504	44.6	0.0227 U	16.9	9.94	2.18	1.8	0.4	2.70	14,400	414	363
		12/13/18	407	7.71	0.0227 U	225	75.1	26.1	0.5	25.6	12.8	11,400	2,430	35.9
		Decommissioned March 2019												
MW-151	Property, SW quadrant	04/10/18	409	65.5	0.0870 J	2.08 J	39.2	1.38	0.8	0.6	0.536	36,500	83.3	1,440
		12/14/18	618	32.2	0.0227 U	702	335	138	–	–	11.8	18,900	68.4	68.4
		Decommissioned March 2019												
MW-156	8th Ave N ROW, E side	04/26/18	436	46.3	0.0227 U	25.0	10.7	10.2	0.0	10.2	1.13	2,250	28.4	23.8
		01/24/19	554	25.1	0.0227 U	67.6	34.3	3.42	0.0	3.4	6.59	2,470	44.8	0.422 U
		04/24/19	618	18.6	0.0227 U	145	57.3	3.81	0.4	3.4	9.01	1,720	31.2	0.422 U
		04/24/19	612	19.3	0.259 U	145	56.0	4.76	0.4	4.4	9.75	1,590	28.4	0.422 U
		07/22/19	606	45.5	0.0227 U	181	42.0	19.9	0.3	19.7	8.68	2,340	50.0	0.422 U
		10/17/19	633	46.0	0.0227 U	83.3	19.3	3.44	1.4	2.0	3.83	2,490	179	0.422 U
		01/20/20	600	48.9	0.0227 U	75.8	21.3	3.20	1.5	1.7	3.13	2,440	189	0.422 U
		04/24/20	634	54.8	0.0480 U	78.0	12.5	6.41	0.0	6.4	2.33	1,580	153	0.422 U
		07/15/20	642	55.6	0.0480 U	92.1	12.8	3.19	2.0	1.2	2.69	2,490	242	0.422 U
		11/11/20	–	–	–	118	9.96	3.36	–	–	3.23	993	19.8	0.422 U
		02/08/21	–	–	–	72.8	11.4	2.30	–	–	3.92	5,850	0.296 U	0.422 U
		05/10/21	–	–	–	38.1	12.4	17.1	–	–	4.63	21,700	60.3	0.422 U
		08/20/21	–	–	–	60.8	11.0	7.58	–	–	3.75	25,400	62.0	0.422 U
		11/18/21	317	39.8 J	0.500 U	42.7	10.4	2.56	1.5	1.1	3.36	13,100	43.1	0.422 U
		03/03/22	–	–	–	47.7	9.88	6.19	–	–	4.07	3,060 J	16.7 J	0.422 U
		03/03/22	–	–	–	46.4	9.93	5.60	–	–	3.90	2,020 J	0.296 UJ	0.422 U
		05/26/22	–	–	–	50.7	10.5	3.80 J	–	–	3.97	14,100	44.0	1.90
		08/04/22	–	–	–	51.8	8.77	3.45	–	–	3.79	14,700	56.4	1.83
		10/31/22	354	43.6	0.0480 U	49.5	8.45	4.32	2.3	2.1	3.63	19,900	65.1	3.63
		05/12/23	–	–	–	33.7	7.57	3.09	–	–	3.49	13,400	48	2.09
		11/06/23	329	59.2	0.0480 U	29.7	6.62	3.17	0.5	2.7	3.68	1,730	26.0	0.422 U
		05/21/24	–	–	–	22.8	7.28	4.82	–	–	3.91	2,920	33.6	1.14 J
		11/05/24	333	61.9	0.0884 U	19.9	5.13	2.82	2.8	0.0	3.43	2,160	27.3	1.84
MW-189	Valley St ROW, S side	10/14/19	197	17.1	0.0227 U	37.2	3.78	1.33	0.1	1.2	0.838	203	0.296 U	69.9
		01/23/20	171	13.3	0.0227 U	37.5	1.80	2.06	0.5	1.6	0.700	119	0.296 U	25.3
		04/03/20	170	12.6	0.0227 U	40.0	1.49	1.16	0.5	0.7	0.658	68.5	0.296 U	16.6
		04/03/20	169	12.7	0.0354 J	39.6	1.48	1.22	0.5	0.7	0.652	77.1	0.296 U	15.2
		08/04/20	165	12.8	0.0480 U	43.0	1.51	1.42	0.5	0.9	0.709	51.6	0.296 U	0.422 U
		11/17/20	–	–	–	42.2	1.75	0.750	–	–	0.675	89.1	0.296 U	28.9
		02/03/21	–	–	–	46.1	3.56	1.99	–	–	0.818	1,080	0.296 U	58.9
		05/14/21	–	–	–	49.3	5.56	3.27	–	–	1.34	20,800	43.7	120
		08/11/21	–	–	–	51.2	7.60	5.10	–	–	1.52	13,400	57.9	122
		11/30/21	317	17.2	0.100 U	44.4	10.8	5.84	0.8	5.0	2.02	14,300	42.2	174
		03/04/22	–	–	–	49.6	10.4	6.77	–	–	2.00	3,090	8.78	33.7
		05/12/22	–	–	–	49.3	8.62	5.68	–	–	1.59	8,600	18.0	61.7
		08/11/22	–	–	–	49.4	6.77	2.47	–	–	1.22	3,510	7.03	47.5
		10/31/22	252	20.7	0.0480 U	46.8	6.06	1.66	0.0	1.7	1.17	3,830	7.34	59.3
		11/03/23	271	19.7	0.108 J	45.4	6.28	4.27	–	–	1.34	4,310	7.79	32.5
		11/05/24	224	19.7	0.0884 U	38.8	2.84	1.1	0	1.1	0.607	998	1.48	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-302	Dexter Ave N ROW, E side	10/21/19	311	20.2	0.0227 U	26.8	8.10	2.26	0.5	1.8	0.295	129	3.74	0.422 U
		01/24/20	331	20.6	0.0227 U	22.8	1.57	1.13	1.0	0.1	0.332	590	0.296 U	0.422 U
		05/07/20	356	22.3	0.0480 U	20.8	1.71	11.1	0.0	11.1	0.518	297	0.296 U	0.422 U
		07/28/20	370	25.8	0.0480 U	22.0	1.64	1.64	0.0	1.6	0.335	299	0.296 U	0.422 U
		11/09/21	317	21.6 J	0.100 UJ	20.8	1.85	1.94	0.0	1.9	0.324	129	0.296 U	0.422 U
		11/08/22	307	26.6	0.0480 U	21.2	1.80	2.86	0.0	2.9	0.498	207	1.30	14.5
MW-306	Roy St ROW, S side	10/15/19	187	8.79	0.0227 U	80.9	2.32	3.81	2.5	1.3	0.608	0.287 U	0.296 U	0.422 U
		01/16/20	185	9.48	0.0227 U	77.5	2.97	4.09	2.6	1.5	0.550	0.287 U	0.296 U	0.422 U
		04/28/20	192	10.3	0.0480 U	75.8	3.03	2.94	0.3	2.6	0.483	0.287 U	0.296 U	0.422 U
		07/29/20	185	10.8	0.0480 U	73.9	1.11	2.93	2.5	0.4	0.509	0.287 U	0.296 U	0.422 U
		12/03/21	172	10.0	0.100 UJ	64.9	1.01	2.85	3.0	0.0	0.425	52.7	0.296 U	0.422 U
		11/04/22	178	38.8	0.369	34.3	1.02	2.49	1.5	1.0	0.460	136	0.296 U	0.422 U
MW-308	Alley E of Seattle Roy Aloha Shops	10/11/19	901	15.4	0.0227 U	95.4	6.97	16.9	3.5	13.4	2.95	2,070	19.7	0.422 U
		01/16/20	565	14.4	0.0227 U	86.0	7.85	16.0	4.0	12.0	2.65	2,780	31.5	8.93
		04/08/20	485	14.6	0.0480 U	83.2	9.49	9.39	4.8	4.6	2.53	1,870	23.9	8.43
		07/06/20	670	12.3	0.0480 U	68.6	7.40	16.9	5.5	11.4	3.08	2,630	18.9	0.422 U
		11/11/21	600	13.0	1.00 U	41.4	8.17	9.06	4.3	4.8	3.10	2,830	20.7	0.422 U
		11/01/22	651	15.3	0.0480 U	38.0	6.85	13.8	—	—	2.75	2,600	16.5	0.422 U
MW-315 (dup)	Mercer St ROW, N side	10/03/19	325	11.7	0.0227 UJ	35.0	3.02	0.850	0.0	0.9	0.306	124	0.296 U	0.422 U
		01/16/20	262	10.5	0.0227 U	37.6	4.68	1.03	0.4	0.6	0.354	77.2	0.296 U	0.422 U
		04/24/20	251	9.62	0.0480 U	37.9	1.25	2.34	0.75	1.6	0.329	57.8	0.296 U	0.422 U
		07/24/20	249	9.55	0.0480 U	38.5	1.44	3.90	0.0	3.9	0.307	32.7	0.296 U	0.422 U
		11/05/21	214	10.8	0.200 U	47.8	1.12	0.978 J	0.8	0.2	0.248	43.8 J	0.296 U	0.422 U
		11/05/21	197	10.8	0.200 U	47.9	1.28	1.40 J	0.8	0.6	0.286	71.8 J	0.296 U	0.422 U
		11/02/22	119	5.99	0.373	32.4	0.643 U	0.909	0.0	0.9	0.165	10.2	0.296 U	0.422 U
MW-317	9th Ave N ROW, W side	10/09/19	404	18.5	0.0227 U	0.0774 U	12.0	12.5	3.0	9.5	3.57	11,000	0.296 U	0.422 U
		01/16/20	394	0.0519 U	0.0227 U	0.0774 U	12.9	14.4	1.5	12.9	3.71	12,800	0.296 U	0.422 U
		04/27/20	321	26.6	0.0480 U	15.8	12.7	12.6	2.0	10.6	2.94	900	0.296 U	0.422 U
		07/30/20	332	22.3	0.0480 U	1.34 J	14.0	12.0	5.0	7.0	2.93	4,020	0.296 U	0.422 U
		11/12/21	351	32.5	1.00 U	7.90	13.5	16.0	5.5	10.5	3.96	8,570	0.296 U	0.422 U
		11/01/22	330	36.1	0.0868 J	40.3	12.0	12.9	4.0	8.9	3.48	3,200	0.296 U	0.422 U
MW-325	Mercer St ROW, N side	10/03/19	235	21.5	0.788 J	112	3.28	0.701	0.0	0.7	0.865	31.7	0.296 U	0.422 U
		01/17/20	175	20.7	1.59	93.5	4.19	0.802	0.0	0.8	0.525	4.04	0.296 U	0.422 U
		04/21/20	229	19.8	3.14	84.2	2.67	0.163	0.0	0.2	0.310	14.4	0.296 U	0.422 U
		07/23/20	207	6.99	1.97	45.7	1.55	2.04	0.0	2.0	0.220	18.5	0.296 U	0.422 U
		11/04/21	256	10.4	0.700	61.5	2.22	0.201	0.0	0.2	0.178	0.287 U	0.296 U	0.422 U
		11/02/22	181	14.5	1.38 J	61.0	1.12	1.01	0.0	1.0	0.613	1.77	0.296 U	0.422 U
MW-327	Lake Union Park, S end	10/02/19	272	18.4	0.0227 UJ	0.0774 U	4.41	12.4	3.5	8.9	0.822	18,500	0.296 U	0.422 U
		01/17/20	205	26.6	0.0227 U	0.0774 U	3.75	9.97	2.0	8.0	0.614	15,000	0.296 U	0.422 U
		04/09/20	256	21.4	0.0480 U	1.89 J	3.37	9.28	5.4	3.9	0.821	12,700	0.296 U	0.422 U
		07/07/20	316	16.6	0.0480 U	5.59	3.49	9.51	6.0	3.5	0.900	10,100	0.296 U	0.422 U
		11/10/21	311	13.4	1.00 U	0.600 U	3.88	10.5	5.5	5.0	0.892	9,540	0.296 U	0.422 U
		11/02/22	224	72.0	0.0480 U	0.594 U	3.11	11.9	4.5	7.4	0.786	12,900	0.296 U	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-330 (dup)	Valley St ROW, N side	05/14/20	156	11.3	0.0480 U	48.0	1.42	2.9	0.0	2.9	0.841	31.7 J	0.296 U	0.422 U
		05/14/20	156	11.1	0.0480 U	48.3	1.46	2.2	0.0	2.2	0.836	46.5 J	0.296 U	0.422 U
		07/16/20	164	11.0	0.0480 U	45.9	2.22	2.56	1.0	1.6	0.971	31.3	0.296 U	0.422 U
		11/11/21	144	13.4	1.00 U	43.7	1.59	2.44	0.5	1.9	0.759	31.1	0.296 U	0.422 U
		10/31/22	148	24.7	0.0516 J	51.4	1.83	1.37	0.0	1.4	1.86	22.5	0.296 U	0.422 U
MW-331	Alley E of Seattle Roy Aloha Shops	04/24/20	292	34.7	0.0480 U	243	3.36	9.66	4.5	5.2	0.809	94.1	8.18	0.422 U
		07/06/20	351	32.9	0.0480 UJ	228	3.06	17.7	7.0	10.7	0.752	83.6	0.296 U	0.422 U
		11/11/21	280	32.8 J	1.00 U	262 J	3.15	12.0	6.2	5.8	0.737	105	0.296 U	0.422 U
		11/01/22	275	34.3	0.0480 U	227	1.83	10.4	4.5	5.9	0.640	88.9	0.296 U	0.422 U
MW-333	900 Roy St, S end	04/29/20	890	33.9	0.0480 U	1.37 J	13.5	26.2	5.0	21.2	2.16	24,300	0.296 U	0.422 U
		07/24/20	835	35.1	0.0480 U	0.594 U	14.4	21.2	6.5	14.7	1.55	29,700	0.296 U	0.422 U
		11/05/21	834	35.4	0.132	0.504	13.9	21.7	1.8	20.0	1.61	16,600	0.296 U	0.422 U
		11/02/22	828	33.7	0.0480 U	0.594 U	12.5	21.7	5.0	16.7	1.94	22,000	6.07	0.422 U
MW-344	SDOT Mercer Parcels, NW quadrant	06/01/21	227	19.9	0.0480 R	57.8	0.924 U	2.06	–	–	0.641	96.5	0.296 U	0.422 U
		08/18/21	216	20.8	0.0480 U	60.4	1.20	33.3	1.4	31.9	1.16	43.0	0.296 U	0.422 U
		11/18/22	436	37.7	0.0480 U	8.43	2.99	2.81	–	–	1.75	12,500	660	1,520
Intermediate B Zone														
FMW-141 (dup)	Alley E of Seattle Roy Aloha Shops	10/30/19	596	66.9 J	0.0227 U	0.909 J	21.2	8.88	0.5	8.4	1.74	6,040	113	460 J
		10/30/19	466	44.5 J	0.0227 U	4.73 J	18.8	8.38	0.5	7.9	1.52	5,710	84.9	305 J
		01/14/20	119	10.0	0.0385 J	1.18 J	3.74	5.52	1.5	4.0	0.340	1,890	23.6	299
		04/28/20	167	16.5	0.0866 J	3.09 J	4.57	1.61	1.2	0.4	0.407	2,910	33.1	322
		07/22/20	205	23.3	0.0723 J	3.10 J	4.45	2.80	0.5	2.3	0.582	3,390	41.7	428
		11/03/22	97.7	9.45	0.115	4.40 J	4.17	0.997	1.0	0.0	0.279	620	14.1	34.8
HMW-9IB (dup)	SDOT Mercer Parcels, SW quadrant	01/26/21	290	29.8	0.0480 U	31.3	2.61	0.429	0.25	0.2	0.565	2,530	0.296 U	137
		06/02/21	294	26.0	0.0480 U	32.7	1.77	0.948	–	–	0.629	1,660	4.07 U	86.9
		08/18/21	280	27.6	0.0480 U	32.3	1.87	0.682	–	–	0.578	2,550	0.296 U	122
		05/24/22	–	83.8	0.0480 U	0.724 J	612	–	–	–	–	376	5.51	27.1
		05/24/22	–	81.5	0.0480 U	0.594 U	586	–	–	–	–	308	4.77	22.4
		08/01/22	–	50.2	0.0866 J	0.594 U	129	–	–	–	–	5,270	18.1	136
		11/09/22	442	33.8	0.0480 U	0.594 U	40.5	41.2	33	8.2	2.99	19,300	7.24	559
		02/23/23	–	37.8	0.0543 J	0.698 J	247	–	–	–	–	32,500	1.85	471
		05/17/23	–	44.7	0.048 U	0.665 J	168	–	–	–	–	37,200	2.52	209
		11/13/23	774	545	0.125	1.56 J	2.31	11.1	5	6.1	1.92	25,400	136	2.3
		02/28/24	–	60.5 J-	0.212 J	1.46 J	6.79	11.3	–	–	2.21	30,300	343	0.422 U
		05/29/24	–	–	–	0.594 U	4.72	9.22	–	–	1.43	19,400	239	0.422 U
		09/04/24	–	–	–	1.62 J	6.81	12.6	–	–	2.46	32,100	485	0.422 U
		11/06/24	903	71.6	0.232	0.637 U	6.67	11.2	4.5	6.7	2.28	34,600	488	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW111	Alley E of Seattle Roy Aloha Shops	12/17/13	170	47.3	0.025 U	4.73	–	0.168	0.2	0.0	0.135	14.7	5 U	5 U
		03/23/17	179	22.9	0.0680 J	8.25	0.918 J	0.391	0.1	0.3	0.151	136	5.75	4.17
		06/14/17	202	23.2	0.0227 U	8.97	1.20	0.298	–	–	0.142	231	7.73	6.71
		10/14/19	222	29.1	0.0227 U	7.70	1.97	0.159	–	–	0.229	324	20.9	20.1
		01/16/20	227	32.3	0.0227 U	15.7	1.56	9.04	0.5	8.5	0.415	386	30.2	20.4
		04/23/20	259	38.3	0.0480 U	26.5	1.88	22.5	0.5	22.0	0.694	447	38.7	23.3
		07/06/20	290	41.4	0.0480 U	32.8	1.65	22.1	0.0	22.1	0.668	625	51.6	25.9
		11/02/20	–	–	–	31.8	1.55	18.8	–	–	0.653	484	47.8	23.8
		02/09/21	–	–	–	25.4	1.44	4.38	–	–	0.429	452	43.5	26.1
		05/03/21	–	–	–	17.8	1.21	7.73	–	–	0.344	347	29.6	13.7
		08/04/21	–	–	–	18.4	1.50	4.17	–	–	0.315	255	21.5	4.26 U
		11/03/21	213	29.3	0.200 U	18.9	1.52	2.08	0.5	1.6	0.296	174	13.8	0.422 U
		02/15/22	198	–	–	18.0	1.32	5.31	–	–	0.304	134	9.39	2.71
		05/18/22	–	–	–	9.90	1.11	0.646	–	–	0.172	129	10.2	2.35
		08/09/22	–	–	–	15.4	1.47	1.11	–	–	0.244	205	15.9	3.55
		11/01/22	190	26.9	0.0817 J	15.7	0.677 U	0.655	0.5	0.2	0.257	182	14.4	3.63
MW112	Dexter Ave N ROW, W side	12/26/13	160	12.3	0.0640	44.9	–	0.560	0.2	0.3	0.106	5 U	5 U	5 U
		03/22/17	188	10.6	0.0227 U	45.2	1.35	0.238	–	–	0.0411	4.89	0.296 U	0.422 U
		06/16/17	240	1.15	0.162	1.26 J	5.48	2.56	–	–	0.0871	1.78	0.296 U	0.422 U
		04/12/18	16.7 J	2.09	0.398 J	1.31 J	2.80	19.5	0.0	19.5	0.421	326	0.296 U	0.422 U
		12/22/18	41.6	9.72	0.0683 J	0.342 J	5.51	22.6	–	–	0.573	373	0.296 U	0.422 U
		04/22/19	82.9	7.09	0.0227 U	7.65	6.04	4.90	1.0	3.9	0.177	281	1.12 J	1.13 J
		07/16/19	112	8.61	0.0227 U	17.1	6.12	1.28	0.0	1.3	0.154	149	3.81	0.422 U
		10/21/19	58.6	5.47	0.0227 U	1.82 J	11.1	1.70	0.5	1.2	0.169	388	5.75	0.422 U
		01/24/20	50.8	7.70	0.0227 U	0.322 J	3.41	3.56	2.0	1.6	0.220	1,670	0.296 U	35.0
		05/07/20	75.2	8.95	0.0480 U	2.62 J	2.91	3.22	1.5	1.7	0.239	752	0.296 U	0.422 U
		07/27/20	106	9.08	0.0480 U	11.0	2.86	1.68	1.6	0.1	0.213	592	0.296 U	0.422 U
		11/17/20	–	–	–	32.7	1.61	3.78	–	–	0.210	121	0.296 U	0.422 U
		02/11/21	–	–	–	32.4	1.70	1.57	–	–	0.176	93.8	0.296 U	0.422 U
		05/14/21	–	–	–	35.2	1.77	9.37	–	–	0.309	91.9	0.296 U	0.422 U
		08/17/21	–	–	–	34.2	1.52	1.60	–	–	0.170	50.1	4.07 U	4.26 U
		11/08/21	164	11.7	0.100 UJ	29.1	1.97	4.84	0.6	4.2	0.248	135	0.296 U	0.422 U
		02/24/22	–	–	–	21.3	2.40	1.45	–	–	0.184	79.5	3.28	0.422 U
		05/13/22	–	–	–	28.5	1.59	1.33	–	–	0.177	82.4	2.06	0.576 J
		08/09/22	–	–	–	19.9	3.64	1.08	–	–	0.184	123	2.69	1.95
		11/08/22	32.6	17.5	0.488	0.898 J	4.55	0.672	0.5	0.2	0.0799	49.6	0.296 U	2.37

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)			
								Total	Ferrous	Ferric		Methane	Ethane	Ethene	
				WATER	WATER	WATER	WATER	WATER				WATER	WATER	WATER	WATER
MW126 (dup)	Alley E of Seattle Roy Aloha Shops	10/15/19	210	7.54	0.0227 U	3.62 J	5.12	0.407	0.5	0.0	0.335	277	0.296 U	0.422 U	
		10/15/19	200	7.78	0.0227 U	3.89 J	5.05	0.388	0.5	0.0	0.327	317	0.296 U	0.422 U	
		01/14/20	199	7.34	0.0227 U	2.83 J	4.45	0.372	0.5	0.0	0.326	292	0.296 U	0.422 U	
		04/09/20	197	7.4	0.0480 U	2.58 J	4.28	0.257	0.0	0.3	0.289	574	3.71	0.422 U	
		07/24/20	170	6.79	0.0480 U	3.19 J	3.94	0.105	0.0	0.1	0.262	361	0.296 U	0.422 U	
		11/09/20	197	—	—	4.85 J	3.42	0.117	—	—	0.254	213	0.296 U	0.422 U	
		02/10/21	—	—	—	6.65	2.60	0.245	—	—	0.262	267	0.296 U	0.422 U	
		05/04/21	—	—	—	7.56	2.19	0.0582 J	—	—	0.195	183	0.296 U	0.422 U	
		05/04/21	—	—	—	7.51	2.11	0.0729 J	—	—	0.200	163	0.296 U	0.422 U	
		08/04/21	—	—	—	4.71 J	2.38	0.478	—	—	0.269	300	4.07 U	4.26 U	
		11/11/21	190	6.52	1.00 U	6.00 U	2.48	0.434	0.6	—	0.254	420	0.296 U	0.422 U	
		02/15/22	204	—	—	2.80 J	2.35	0.381	—	—	0.225	265	1.46	0.842 J	
		05/20/22	—	—	—	2.75 J	1.92	0.0932 J	—	—	0.101	44.4	0.301 J	0.422 U	
		08/10/22	—	—	—	2.62 J	2.57	0.0412 J	—	—	0.0370	0.287 U	0.296 U	0.422 U	
		11/01/22	203	6.77	0.0879 J	2.69 J	1.51	0.208	0.0	0.2	0.0559	115	0.296 U	0.422 U	
MW130 (dup)	Property, NW quadrant	03/29/17	276	100	0.0227 U	7.07	10.7	1.19	1.0	0.2	0.555	619	1.62	30.0	
		06/30/17	339	115	0.0227 U	6.23	1.84 J J	0.907	0.0	0.9	0.532	1,040	2.47	64.5	
		06/30/17	335	111	0.0227 U	6.16	9.68 J J	0.876	0.0	0.9	0.527	1,120	2.33	69.1	
		05/21/18	2.71 U	135	265	1.68 J	7.54	5.44	0.0	5.4	0.727	1,760	33.6	284	
		12/17/18	384	143	0.0227 U	17.3	12.6	2.26	0.0	2.3	0.490	324	8.36	166	
		Decommissioned March 2019													
MW-132	Property, SE quadrant	04/26/18	542	30.1	0.0227 U	10.6	18.6	9.59	—	—	2.04	4,640	75.9	0.422 U	
		12/13/18	260	40.4	0.0227 U	7.21	3.4	0.544	—	—	0.278	89.7	0.925 J	41.0	
		Decommissioned March 2019													
MW-134	Property, NE quadrant	04/16/18	298	38	0.0227 UJ	1.30 J	3.27	292	0.0	292	5.00	5,200	61.3	952	
		Decommissioned March 2019													
MW-135	Property, NE quadrant	04/25/18	273	118	0.0227 U	21.9	6.21	1.74	1.5	0.2	0.656	333	18.1	131	
		12/13/18	379	128	0.0227 U	61.8	18.1	4.95	0.8	4.2	1.450	2,060	56.1	327	
		Decommissioned March 2019													
MW-136	Property, SW quadrant	04/16/18	241	22.1	0.165	0.638 J	15.1	21.4	0.6	20.8	0.618	5,510	8.52	5.77	
		Decommissioned March 2019													
MW-139	Property, SE quadrant	04/25/18	212	21.9	0.0227 R	2.21 J	28.5	1.13	0.8	0.4	0.251	4.28	8.04	0.42 U	
		Decommissioned March 2019													

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-143	8th Ave N ROW, E side	04/30/18	448	66.5	0.0227 U	4.69 J	2.55	2.08	0.5	1.6	0.390	6,720	92.5	360
		01/29/19	400	58.5	0.0227 U	3.12 J	7.02	1.6	0.8	0.9	0.378	8,520	134	0.422 U
		04/24/19	393	56.2	0.0227 U	8.53	7.19	0.687	0.3	0.4	0.317	6,940	125	0.422 U
		07/19/19	403	58.2	0.140	6.91	12.7	2.07	1.0	1.1	0.398	4,790	96.5	14.4
		10/16/19	518	35.8	0.0227 U	67.7	20.9	8.54	0.5	8.0	2.09	5,780	62.6	110
		01/22/20	394	58.1	0.0229 U	2.34 J	7.53	2.02	0.5	1.5	0.410	5,090	83.6	0.422 U
		04/24/20	409	56.7	0.0480 U	1.08 J	5.57	2.19	1.0	1.2	0.405	3,720	61.4	0.422 U
		07/29/20	393	57.2	0.0480 U	0.665 J	4.48	1.39	0.5	0.9	0.428	4,040	61.3	0.422 U
		11/24/20	—	—	—	5.06	6.45	7.11	—	—	0.654	10,600	190	10.9
		02/08/21	—	—	—	44.3	32.5	20.6	—	—	3.95	19,500	417	0.422 U
		05/19/21	—	—	—	5.27	38.2	32.4	—	—	7.46	19,100	363	283
		08/20/21	—	—	—	1.75 J	37.8	30.6	—	—	6.99	24,300	390	1,080
		12/08/21	964	70.3	1.48	3.08	35.6	30.1	6.0	24.1	6.26	25,300	517	867
		03/08/22	—	—	—	1.79 J	39.2	30.9	—	—	5.10	23,000	197	284
		05/26/22	—	—	—	2.93 J	33.2	40.1	—	—	6.50	21,000	478	483
		08/12/22	—	—	—	1.91 J	41.9	29.7	—	—	5.68	28,600	817	680
		11/01/22	339	25.4	2.80	15.7	2.63	2.48	0.0	2.5	0.398	1,280	3.10	3.06
		05/16/23	—	—	—	0.966 J	47.4 J	36.6	—	—	11.1	11,300 J	237 J	255 J
		11/07/23	613	57.3	0.0828 U	5.27	10.9	2.52	2	0.5	1.76	664	14.1	17.1
		05/24/24	—	—	—	1.15 J	42.1	32.8	—	—	8.98	8,180	194	251
		11/06/24	645	57.8	0.155	4.72 U	13.9	5.49	2	3.5	2.67	1,280	26.4	29.2
MW-145	8th Ave N ROW, E side	04/27/18	272	74.4	0.238	71.0	8.09 J	42.9	0.0	42.9	0.912	2,050	0.296 U	18.5
		01/29/19	255	43.5	0.219	55.4	4.80	4.85	0.0	4.9	0.193	276	0.296 U	0.422 U
		04/26/19	287	44.7	0.0227 U	73.9	5.29	5.73	0.0	5.7	0.318	455	1.73	5.24
		Damaged June 2019 and Decommissioned Decemberr 2019												
MW-145R (dup)	8th Ave N ROW, E side	12/16/19	258	20.1	0.0227 U	16.6	4.12	1.22	0.0	1.2	0.256	272	0.296 U	0.422 U
		01/21/20	233	20.1	0.0249 U	3.17 J	5.32	1.32	0.0	1.3	0.305	449	1.72	0.422 U
		04/02/20	260	20.1	0.0227 U	1.07 J	6.87	1.39	0.5	0.9	0.342	2,050	5.34	0.422 U
		08/03/20	266	29.3	0.0480 U	1.24 J	2.27	1.54	1.0	0.5	0.362	8,550	5.59	0.422 U
		11/23/20	—	—	—	26.9	2.89	4.61	—	—	0.361	1,610	0.296 U	0.422 U
		02/04/21	—	—	—	26.7	1.95	1.23	—	—	0.310	1,380	4.07 U	4.26 U
		05/12/21	—	—	—	27.3	1.90	2.80	—	—	0.327	1,620	0.296 U	0.422 U
		08/23/21	—	—	—	24.2	1.99	0.884	—	—	0.198	1,810	0.296 U	0.422 U
		08/23/21	—	—	—	24.9	1.94	0.723	—	—	0.160	1,380	0.296 U	0.422 U
		11/30/21	265	24.4	0.100 U	25.3	1.65	4.97	0.5	4.5	0.404	1,740	0.296 U	0.422 U
		03/08/22	—	—	—	27.2	1.86	1.07	—	—	0.314	3,080	1.45	0.602 J
		05/11/22	—	—	—	28.4	1.90	0.576	—	—	0.286	2,360	2.15	0.704 J
		08/10/22	—	—	—	27.1	2.25	1.68	—	—	0.320	2,510	5.28	2.13
		11/02/22	279	27.7	0.0480 U	26.5	2.05	0.451	0.0	0.5	0.317	1,610	4.52	1.81
		05/15/23	—	—	—	26.3	2.33	0.268	—	—	0.277	345	4.07 U	4.26 U
		11/08/23	294	28.5	0.0867 J	25.1	2.42	0.510	0.594	—	0.315	1,350	4.03	0.422 U
		05/22/24	—	—	—	28.4	2.04	0.287	—	—	0.279	1,050	2.36	0.422 U
		11/08/24	301	28	0.0884 U	24.3	3.21	0.342	0.6	0.0	0.296	1,600	4.68	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-147 (dup)	Roy St ROW, S side	05/01/18	302	40.8	0.0227 U	183	21.3	17.1	—	—	0.564	5,060	10.7	144
		01/22/19	302	56.2	0.0227 U	43.2	5.2	6.01	1.0	5.0	0.646	4,210	2.10	100
		04/23/19	346	26.9	0.0227 U	28.1	13.7	4.39	1.5	2.9	0.787	8,110	0.296 U	158
		07/18/19	307	19.3	0.0227 U	30.0	9.56	3.80 J	2.0	1.8	0.750	5,450	0.296 U	191
		07/18/19	310	18.8	0.0890 J	29.4	11.7	2.40 J	2.0	0.4	0.724	5,830	0.296 U	202
		10/14/19	339	23.2	0.0227 U	28.0	6.70	9.37	0.5	8.9	0.919	7,830	2.94	457
		01/24/20	351	28.3	0.0227 U	25.6	3.34	13.5	0.5	13.0	0.995	1,550	0.296 U	172
		04/29/20	370	33.9	0.0480 U	22.4	3.47	8.66	2.0	6.7	1.01	3,780	0.296 U	468
		07/09/20	401	43.3	0.0480 U	14.0	3.29	13.3	1.5	11.8	1.04	5,490	4.65	641
		11/10/20	343	—	—	16.6	3.04	5.85	—	—	0.890	8,350	3.95	552
		02/09/21	—	—	—	36.8	4.33	2.44	—	—	0.659	4,050	0.296 U	302
		05/04/21	—	—	—	1.35 J	18.7	8.90	—	—	0.910	5,960	0.296 U	785
		08/20/21	—	—	—	0.826 J	57.3	7.13	—	—	1.17	17,500	446	1,420
		11/09/21	339	52.4	0.200 UJ	4.69	4.77	7.71	1.5	6.2	0.865	4,170	72.0	764
		02/18/22	583	—	—	18.6	3.60	10.9	—	—	1.43	3,320	36.6	121
		05/03/22	—	—	—	5.59	4.84	14.2	—	—	1.74	14,600	208	296
		08/10/22	—	—	—	4.00 J	5.80	9.78	—	—	1.64	14,900	196	280
		11/03/22	656	44.2	0.0480 U	1.48 J	6.17	6.37	6.5	0	1.70	18,000	427	275
		05/12/23	—	—	—	19.9	11.8	1.37	—	—	0.567	3,800	48.2	135
		11/10/23	264	71.3	0.0722 J	25.2	7.02	4.69	0.3	4	0.354	1,660	17.5	93.6
		06/04/24	—	—	—	26.8	4.90	3.95	—	—	0.417	2,370	15.2	91.7
		11/07/24	329	67.2 J	0.0884 U	21.6	4.86	4.76	1.1	4	0.634	5,090	47.2	117
MW-148 (dup)	Roy St ROW, S side	05/01/18	170	22.2	0.0227 U	95.5	2.46	12.0	0.3	11.8	0.439	1,210	0.296 U	0.422 U
		05/01/18	162	22.5	0.0227 U	96.1	2.53	11.2	0.3	11.0	0.379	1,140	0.296 U	0.422 U
		01/23/19	151	17.7	0.0227 U	154	4.04	10.1	—	—	0.594	1,390	0.296 U	2.84
		04/26/19	161	17.1	0.0227 U	175	5.19	2.91	0.4	2.5	0.420	1,600	0.296 U	3.65
		07/22/19	160	17.0	0.0227 U	173	3.51	5.44	0.5	4.9	0.534	1,940	0.296 U	4.66
		10/16/19	163	18.0	0.0326 J	198	4.48	2.24	0.5	1.7	0.498	2,050	6.03	0.422 U
		01/20/20	158	16.4	0.0227 U	117	5.22	1.75	0.5	1.3	0.380	1,090	3.20	5.65
		04/30/20	160	16.5	0.0480 U	149	2.84	30.3	0.5	29.8	0.774	1,270	0.296 U	0.422 U
		07/15/20	162	16.3	0.0480 U	127	2.36	7.72	0.5	7.2	0.517	1,320	13.1	0.422 U
		11/11/20	—	—	—	60.0	1.02	4.27	—	—	0.341	544	0.296 U	0.422 U
		08/13/21	—	—	—	152	1.69	4.87	—	—	0.488	1,380	0.296 U	0.422 U
		12/07/21	157	15.5	0.500 U	137	1.66	3.84	—	—	0.433	1,210	0.296 U	0.422 U
		02/25/22	—	—	—	139	1.87	10.2	—	—	0.576	679	1.16 J	2.82
		05/05/22	—	—	—	177	2.05	3.07	—	—	0.581	1,250	1.66	3.69
		08/10/22	—	—	—	173	2.66	18.5	—	—	0.702	1,400	2.12	4.51
		11/04/22	157	16.4	0.186	80.8	1.67	0.421	0.0	0.4	0.325	427	2.49	22.3
MW-152	Property, SW quadrant	04/10/18	312	128	0.0227 U	15.0	13.2	0.210	0.0	0.2	0.386	1,590	41.1	1,830
		12/14/18	299	181	0.0227 U	31.6	16.9	3.82	1.0	2.8	1.46	3,710	32.2	2,050
Decommissioned March 2019														

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-157	8th Ave N ROW, E side	04/26/18	201	27.8	0.0227 U	4.51 J	2.86	1.02	–		0.209	111	0.779 J	36.6
		01/24/19	421	43.2	0.0227 U	24.1	12.9	5.25	3.0	2.3	1.17	4,970	37.4	124
		04/24/19	513	34.1	0.0227 U	95.0	39.5	9.40	3.0	6.4	2.13	5,510	36.0	119
		07/22/19	464	43.7	0.0227 U	46.7	14.9	11.4	3.0	8.4	1.73	5,090	45.8	56.2
		10/16/19	408	22.8	0.441	5.72	7.17	1.68	0.0	1.7	0.403	4,670	78.6	0.422 U
		01/20/20	467	42.1	0.0227 U	53.2	20.0	6.27	2.5	3.8	1.72	4,250	58.4	91.0
		04/24/20	498	39.9	0.0480 U	47.6	16.4	13.1	1.2	11.9	1.86	4,700	62.9	109
		07/15/20	491	40.7	0.0480 U	45.5	13.7	4.86	1.5	3.4	1.54	6,000	94.2	149
		11/23/20	–	–	–	20.0	3580	14.2	–	–	1.89	2,730	37.0	46.8
MW-190	Valley St ROW, S side	10/14/19	172	12.8	0.0227 U	20.3	10.3	1.85	0.2	1.7	0.406	428	6.87	0.422 U
		01/23/20	173	10.5	0.0227 U	4.06 J	4.46	1.49	0.5	1.0	0.273	656	0.296 U	0.422 U
		04/02/20	180	23.9	0.0227 U	22.3	2.05	2.24	0.5	1.7	0.420	318	0.296 U	0.422 U
		08/04/20	174	14.7	0.0480 U	23.3	1.87	0.957	0.5	0.5	0.507	230	0.296 U	0.422 U
		11/18/20	–	–	–	51.9	3.08	1.60	–	–	1.01	96	0.296 U	37.6
		02/03/21	–	–	–	42.8	4.42	2.03	–	–	0.951	755	0.296 U	48.9
		05/14/21	–	–	–	37.9	3.42	4.55	–	–	1.08	1,450	0.296 U	28.2
		08/11/21	–	–	–	43.7	3.64	2.26	–	–	0.993	701	0.296 U	31.4
		11/30/21	190	11.9	0.100 U	39.6	4.02	1.96	0.0	2.0	0.860	2,710	0.296 U	44.6
		03/04/22	–	–	–	40.9	4.82	1.69	–	–	0.871	1,530	1.34	18.6
		05/10/22	–	–	–	41.9	3.05	0.958	–	–	0.859	799	1.32	9.09
		08/11/22	–	–	–	43.6	4.60	1.66	–	–	0.767	3,010	3.75	10.4
		10/31/22	174	17.3	0.0480 U	40.2	5.82	1.75	0.0	1.8	0.861	6,190	8.53	26.9
		11/06/23	227	15.9	0.0887 J	36.4	6.44	2.34	–	–	0.872	4,110	28.4	30.4
		11/06/24	237	15.6	0.0884 U	34.9	5.05	2.08	0.5	1.6	0.842	7,810	42.5	55
MW-303	Dexter Ave N ROW, E side	10/21/19	144	15.2	0.0227 U	62.2	4.76	3.06	0.0	3.1	0.289	95.7	6.17	0.422 U
		01/24/20	162	14.8	0.0227 U	29.8	3.54	1.32	0.0	1.3	0.285	137	0.296 U	0.422 U
		05/07/20	156	14.2	0.0480 U	43.5	1.66	4.49	0.0	4.5	0.371	177	0.296 U	0.422 U
		07/27/20	158	14.7	0.0480 U	49.0	1.69	1.48	0.6	0.9	0.298	157	0.296 U	0.422 U
		11/09/21	163	14.8	0.132 J-	55.0	1.42	1.59	0.4	1.2	0.333	93.9	0.296 U	0.422 U
		11/08/22	142	15.7	0.151	60.0	1.40	1.97	0.0	2.0	0.328	67.6	0.296 U	0.422 U
MW-307	Roy St ROW, S side	10/11/19	276	14.6	0.0227 U	69.1	4.12	1.03	0.0	1.0	0.149	26.6 J+	13.0	7.90
		01/15/20	266	15.1	0.0227 U	64.7	7.87	1.99	0.0	2.0	0.198	12.6	2.79	0.422 U
		04/28/20	274	14.8	0.0480 U	72.0	3.56	1.19	0.25	0.9	0.172	25.0	0.296 U	0.422 U
		07/29/20	265	14.7	2.20	73.0	1.90	1.22	0.5	0.7	0.169	69.5	0.296 U	0.422 U
		12/03/21	257	9.87	0.100 UJ	62.7	1.73	1.61	0.0	1.6	0.161	20.4	0.296 U	0.422 U
		11/04/22	272	13.1	0.158	25.5	8.03	0.163	0.0	0.2	0.137	14.3	1.71	8.25
MW-309	Alley E of Seattle Roy Aloha Shops	10/14/19	228	15.1	0.0227 U	86.5	2.95	0.511	0.5	0.0	0.435	105	0.296 U	0.422 U
		01/16/20	264	17.7	0.0227 U	69.9	1.66	0.451	0.0	0.5	0.621	158	2.06	0.422 U
		04/08/20	275	18.7	0.0480 U	72.2	1.61	0.721	0.0	0.7	0.680	144	0.296 U	0.422 U
		07/06/20	283	18.9	0.0480 U	70.9	1.67	0.938	0.5	0.4	0.683	233	0.296 U	0.422 U
		11/11/21	250	18.2	1.00 U	58.8	1.91	0.649	0.5	0.1	0.709	253	0.296 U	0.422 U
		11/01/22	294	16.0	0.547	49.2	2.04	0.699	0.0	0.7	0.659	435	1.65	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-311	Alley E of Seattle Roy Aloha Shops	10/10/19	394	45.9	0.0227 U	35.0	5.31	0.349	0.0	0.3	0.738	856	40.8	10.4
		01/14/20	385	43.4	0.0227 U	14.2	5.99	0.306	—	—	0.793	534	22.7	7.10
		04/23/20	385	44.1	0.0480 U	9.65	7.58	1.99	0.5	1.5	0.745	491	14.8	0.422 U
		07/16/20	409	43.7	0.0480 U	8.36	7.88	5.48	1.0	4.5	0.791	633	14.2	0.422 U
		11/04/21	382	44.1	0.136	19.2	3.02	0.766	0.8	0.0	0.496	97.0	0.296 U	0.422 U
		11/01/22	367	48.7	0.107	27.7	1.70	0.543	2.0	0.0	0.310	111	7.11	3.79
MW-314 (dup) (dup)	Alley E of Seattle Roy Aloha Shops	10/10/19	253	24.4	0.0227 U	264	2.84	2.42	3.5	0.0	1.11	377	18.6	0.422 U
		01/15/20	231	18.9	0.0227 U	309	2.44	11.7	0.9	10.8	1.27	290	7.67 J	0.422 U
		01/15/20	233	19.4	0.0227 U	304	2.44	12.0	0.9	11.1	1.30	303	0.296 UJ	0.422 U
		04/22/20	378	35.1	0.0480 U	190	7.12	12.1	1.5	10.6	1.02	2,750	35.2	154
		07/16/20	510	42.8	0.0480 U	94.8	14.0	6.53	2.5	4.0	1.16	4,290	70.8	178
		12/03/21	199	14.1	0.100 UJ	244	2.25	12.3 J	1.2	11.1	0.857	439	0.296 UJ	0.422 UJ
		12/03/21	198	14.1	0.100 UJ	245	2.29	8.77 J	1.2	7.6	0.831	492	6.43 J	5.86 J
		11/01/22	210	17.7	0.0480 U	270	2.02	1.26	0.0	1.3	0.660	848	7.60	3.90
		11/07/23	226	13.9	0.0850 J	238	2.14	3.72	3.40	0.3	0.678	1,200	5.42	2.20
		11/12/24	170	11.9	0.525	56.7	1.66	0.106	0	0.1	0.0196	0.287 U	0.296 U	0.422 U
MW-316	Mercer St ROW, N side	10/02/19	384	16.9	0.0227 UJ	41.8	3.78	2.58	1.0	1.6	0.328	143	0.296 U	0.422 U
		01/16/20	331	16.9	0.0227 U	41.6	5.63	6.15	0.4	5.8	0.359	145	0.296 U	0.422 U
		04/21/20	325	16.4	0.0480 U	58.2	1.76	3.54	0.25	3.3	0.318	350	0.296 U	0.422 U
		07/24/20	335	15.0	0.0480 U	47.9	1.87	1.95	0.5	1.5	0.258	179	0.296 U	0.422 U
		11/05/21	332	15.6	0.200 U	45.6	1.77	2.40	0.4	2.0	0.264	35.6	0.296 U	0.422 U
		11/02/22	193	8.98	0.362	25.0	0.931 U	1.23	0.0	1.2	0.160	36.2	0.296 U	0.422 U
MW-318	9th Ave N ROW, W side	10/08/19	339	24.1	0.0227 U	119	6.73	11.7	4.0	7.7	2.33	355	12.8	0.422 U
		01/16/20	387	22.6	0.0227 U	118	4.09	16.0	2.0	14.0	2.94	2,230	18.2	0.422 U
		04/27/20	676	14.5	0.0480 U	5.12	7.87	14.9	3.6	11.3	3.55	6,720	13.9	0.422 U
		07/30/20	652	12.1	0.0480 U	7.79	9.46	13.5	7.0	6.5	3.03	5,380	0.296 U	0.422 U
		11/12/21	616	15.0	1.00 U	22.0	8.14	14.0	4.8	9.3	3.73	4,550	18.1	0.422 U
		11/01/22	394	20.4	0.185	105	3.35	10.6	0.0	10.6	2.83	850	8.88	2.62
MW-322	9th Ave N ROW, W side	10/07/19	841	30.4	0.0227 U	21.1	19.4	43.9	0.0	43.9	4.26	3,090	59.1	20.8
		01/21/20	676	31.1	0.0227 U	17.8	17.1	19.5	1.5	18.0	1.87	3,620	107	0.422 U
		04/29/20	547	30.4	0.0480 U	69.9	5.49	14.6	5.6	9.0	2.32	2,360	86.6	22.2
		07/07/20	355	22.5	0.0480 U	97.0	3.71	12.8	5.8	7.0	1.99	2,240	42.6	0.422 U
		11/09/21	719	19.2	0.100 UJ	3.45	10.8	17.8	4.0	13.8	3.47	6,440	26.7	21.3
		11/03/22	730	22.7	0.0480 U	18.0	13.5	19.2	4.5	14.7	3.28	3,540	71.5	53.9
		11/08/23	732	20.9	0.0503 J	28.7	13.4	16.9	17.4	0.0	1.98	1,600	39.3	7.54
		11/06/24	655	21.6	0.0884 U	29.5	11.7	17.7	3.5	14.2	1.87	2,030	46.8	11.9
MW-334	900 Roy St, S end	04/24/20	864	17.8	0.0480 U	2.48 J	6.69	13.8	6.0	7.8	0.840	23,300	0.296 U	0.422 U
		07/07/20	1,280	23.5	0.0480 U	1.21 J	9.92	16.2	5.0	11.2	0.701	32,500	0.296 U	0.422 U
		11/05/21	1,260	22.7	0.126	0.433	10.6	9.51	5.3	4.3	0.464	18,400	0.296 U	0.422 U
		11/03/22	1,240	26.2	0.0480 U	0.594 U	8.91	10.3	2.0	8.3	0.612	22,300	4.35	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-335	Mercer St ROW, N side	05/01/20	293	17.4	0.0480 U	54.1	2.90	1.31	0.8	0.5	0.721	73.7	0.296 U	0.422 U
		07/08/20	192	20.7	0.0480 U	59.4	2.02	0.171	0.0	0.2	0.594	46.3	0.296 U	0.422 U
		11/17/21	556	31.6	0.500 U	72.7	9.35	0.0711 J	0.3	—	2.06	1,440	21.6	0.422 U
		11/03/22	280	24.3	0.0480 U	86.7	2.52	0.135	0.0	0.1	1.17	338	3.60	0.422 U
		11/09/23	287	30.9	0.0480 U	57.0	2.79	0.147	—	—	1.03	317	2.79	0.422 U
		11/14/24	335	31.7	0.0884 U	80.1	3.3	0.214	0.5	0.0	1.14	389	16.2	0.422 U
MW-338	Lake Union Park, N end	05/07/20	604	12.4	0.0480 U	2.19 J	7.16	16.4	3.0	13.4	1.62	16,700	0.296 U	0.422 U
		07/23/20	464	11.6	0.0480 U	1.11 J	7.83	13.8	9.0	4.8	1.02	22,700	0.296 U	0.422 U
		11/17/21	566	12.3	0.500 U	0.417	9.65	19.4	5.0	14.4	1.48	25,200	0.296 U	0.422 U
		11/02/22	607	13.1	0.0480 UJ	0.594 U	8.20	24.4	3.3	21.2	1.72	25,800	6.02	0.422 U
MW-340	Lake Union Park, S end	05/12/20	545	12.8	0.0480 U	2.31 J	6.54	14.2	6.0	8.2	1.90	19,600	0.296 U	0.422 U
		07/17/20	533	12.9	0.0480 U	0.663 J	5.31	13.8	7.0	6.8	1.85	24,700	0.296 U	0.422 U
		11/10/21	425	14.5	1.00 U	0.600 U	5.13	12.6	5.0	7.6	1.72	21,600	0.296 U	0.422 U
		11/02/22	467	14.6	0.724 J	2.57 J	5.10	14.7	5.5	9.2	1.72	16,000	3.62	0.422 U
MW-345	SDOT Mercer Parcels, NW quadrant	06/01/21	233	50.5	0.0647 J	55.7	2.74	0.961	—	—	0.125	241	7.26	9.64
		08/18/21	239	46.0	0.0480 U	47.9	1.73	1.15	0.0	1.2	0.174	251	2.54	3.81
		11/18/22	289	44.3	0.0480 U	41.0	1.81	1.40	—	—	0.215	1,710	20.3	289
MW-346 (dup)	SDOT Mercer Parcels, NW quadrant	06/02/21	189	54.1	0.0480 U	96.4	5.57	6.57	—	—	0.227	166	14.7	10.9 J
		06/02/21	193	54.1	0.0480 U	96.2	5.73	6.52	—	—	0.228	141	11.2 J	8.86 J
		08/18/21	221	45.0	0.0480 U	48.7	1.83	3.16	0.0	3.2	0.184	189	7.36	5.08
		05/24/22	—	35.5	0.0480 U	81.2	2.07	—	—	—	—	72.0	0.296 U	0.988 J
		08/02/22	—	34.1	0.0480 U	83.6	1.61	—	—	—	—	116	0.563 J	2.34
		11/10/22	193	35.0	0.0677 J	81.3	1.17	8.20	0.3	8.0	0.301	96.6	0.296 U	2.21
		02/23/23	—	35.1	0.133	73.3	1.76	—	—	—	—	86.3	0.296 U	3.83
		02/23/23	—	35.3	0.138	73.9	1.60	—	—	—	—	88.8	0.296 U	4.24
		05/16/23	—	32.2	0.0546 J	73.3	1.62	—	—	—	—	89.5	0.296 U	3.51
		05/16/23	—	32.5	0.0535 J	76.5	1.65	—	—	—	—	103	0.296 U	3.46
		11/08/23	126	15.7	0.31	43.8	1.47	1.72	1.08	0.6	0.107	40.2	0.296 U	1.25 J
		02/27/24	—	20.9	0.868 J-	63.5	1.78	2.63	—	—	0.166	120	0.296 U	1.19 J
		02/27/24	—	22.3	0.889 J-	64.2 J-	1.59	3.04	—	—	0.179	114	0.296 U	0.718 J
		05/28/24	—	—	—	16.2	0.941 J+	0.675	—	—	0.0193	0.287 U	0.296 U	0.422 U
		05/28/24	—	—	—	16.1	1.13 J+	0.642	—	—	0.0188	0.287 U	0.296 U	0.422 U
		09/05/24	—	—	—	68.4	1.35	1.97 J	—	—	0.184	791 J	0.296 U	3.46
		09/05/24	—	—	—	68.5	1.37	1.15 J	—	—	0.183	460 J	0.296 U	2.86
		11/05/24	192	28.4	0.0884 U	84.5	1.68	0.71	0.5	0.2	0.157	634	0.296 U	2.87 J
		11/05/24	191	28.4	0.0884 U	84.1	1.85	0.549	0.5	0.0	0.155	529	1.73	4.25 J

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-347	SDOT Mercer Parcels, NW quadrant	06/01/21	226	60.4	0.0480 R	85.7	2.74	2.02	–	–	0.109	55.3	19.8	34.8
		08/19/21	309	34.7	0.0480 U	93.6	2.53	1.22	0.0	1.2	0.0704	75.9	29.3	43.4
		05/26/22	–	33.7	0.0480 R	12.8	53.5	–	–	–	–	176	3.17	12.3
		08/02/22	–	33.7	0.108	5.45	21.2	–	–	–	–	2,320	2.38	12.1
		11/10/22	248	32.8	0.0480 U	4.72 J	11.6	1.38	0.5	0.9	0.153	7,090	1.50	11.5
		02/23/23	–	32.1	0.114	13.9	2.25	–	–	–	–	4,590	1.64	7.09
		05/16/23	–	31.1	0.048 U	26.1	2.07	–	–	–	–	3,020	1.76	10.4
		11/10/23	210	31.4	0.078 J	33.4	1.68	0.634	–	–	0.116	1420	3.66	11.4
		02/27/24	–	2.6	0.857 J-	20.9	1.83	0.186	–	–	0.0189	94.5	1.25 J	1.91
		05/29/24	–	–	–	15.3	1.81	0.205	–	–	0.0891	8,170	99.1	71.0
		09/04/24	–	–	–	39.6	1.35	0.636	–	–	0.13	811	5.91	11.4
		11/06/24	207	32	0.0884 U	42	1.33	0.347	0	0.3	0.118	554	2.5	9.25
MW-348 (dup)	SDOT Mercer Parcels, SW quadrant	06/01/21	233	57.3	0.0865 J	66.9	2.09	2.05	–	–	0.114	166	0.296 U	13.1
		08/19/21	237	39.8	0.0480 U	52.5	1.87	0.507 J	0.0	0.5	0.103	117	0.296 U	9.34
		08/19/21	238	40.2	0.0480 U	53.1	1.88	0.878 J	0.0	0.9	0.107	126	0.296 U	10.2
		05/26/22	–	40.6	0.0546 J-	60.0	1.84	–	–	–	–	310	0.296 U	20.0
		08/01/22	–	39.7	0.116	56.5	1.23	–	–	–	–	306	1.06 J	23.2
		11/10/22	1,440	117	0.593	0.649 J	2,180	465	–	–	4.71	5,390	3.80	3.01
		03/13/23	–	41.9	0.0480 U	32.6	4.18	–	–	–	–	237	1.71	23.4
		05/17/23	–	38.0	0.048 U	26.0	3.01	–	–	–	–	22,000	3.59	32.1
		11/14/23	174	17.2	0.15 J	32.5	5.31	2.32	0.1	2.2	0.097	8900	1.68	95.8
		02/27/24	–	21.2	0.213	13.3	8.48	8.78	–	–	0.244	33,100	6.18	270
		05/28/24	–	–	–	60.7	10.0	1.22	–	–	0.0771	30,400	6.35	82.3
		09/05/24	–	–	–	8.94	14.8	0.983	–	–	0.164	36,000	22.3	327
		11/05/24	228	16.1	0.0884 U	66.4 J	22.4	2.54	0	2.5	0.166	26,300	16.2	118
MW-349	SDOT Mercer Parcels, SW quadrant	06/01/21	233	33.7	0.0480 R	57.1	2.75	0.722	–	–	0.116	184	0.296 U	0.422 U
		08/19/21	253	33.3	0.0480 U	45.8	1.95	0.196	0.0	0.2	0.136	245	0.296 U	8.43
		05/26/22	–	78.2	0.0597 J-	0.594 U	621	–	–	–	–	926	4.29	15.8
		08/01/22	–	56.3	0.0480 U	0.594 U	25.4	–	–	–	–	13,500	4.02	12.9
		11/08/22	568	45.5	0.0480 U	2.28 J	63.8	9.41	5.3	4.2	1.08	27,100	0.296 U	3.25
		02/23/23	–	42.5	0.048 U	2.27 J	9.58	–	–	–	–	33,700	0.296 U	5.85
		11/13/23	478	35.8	0.126	10.1	3.64	2.55	1.5	1.1	0.392	20800	1.42	5.15
		02/27/24	–	29.2	0.223	7.97	3.74	2.03	–	–	0.355	21,700	3.33	6.87
		05/28/24	–	–	–	5.98	2.63	0.907	–	–	0.0350	5,720	0.296 U	3.76
		09/04/24	–	–	–	8.79	2.16	1.94	–	–	0.417	0.287 U	0.296 U	0.422 U
		11/06/24	437	33	0.0884 U	9.89	2.36	3.98	0	4.0	0.426	5,940	1.21 J	1.6

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-350	SDOT Mercer Parcels, NW quadrant	06/01/21	264	23.2	0.0480 R	59.8	2.52	2.93	—	—	0.191	145	16.0	9.41
		08/18/21	274	13.7	0.0480 U	21.0	2.19	1.54	0.0	1.5	0.318	166	0.296 U	0.422 U
		11/11/22	250	14.8	0.0480 U	40.4	1.20	2.51	0.5	2.0	0.566	298	1.60	1.52
		02/24/23	—	15.2	0.048 U	41.2	1.95	—	—	—	—	1,370	0.296 U	5.23
		05/17/23	—	15.0	0.048 U	39.5	1.33	—	—	—	—	2,160	4.17	11.5
		11/13/23	317	15.6	0.0791 U	34.5	1.74	5.38	2.5	2.9	0.658	2500	14.7	22.4
		02/28/24	—	17.1	0.17	27.6	1.60	2.30	—	—	0.724	5,550	56.1	53.7
		05/29/24	—	—	—	1.98 J	0.462 J	0.685	—	—	0.0380	0.287 U	0.296 U	0.422 U
		09/05/24	—	—	—	28.4	1.83	1.21	—	—	0.694	5,450	63.6	63.3
		11/07/24	374	21.4	0.0884 U	27.8	2.23	1.14	0.5	0.6	0.764	6,970	108	98
W-MW-01	8th Ave N ROW, W side	03/30/17	211	23.8	0.023 U	29.0	1.84	18.2	0.3	18.0	0.542	367	0.757 J	1.27 J
		06/19/17	250	27.6	0.0727 J	28.3	3.00	9.48	—	—	0.321	461	0.296 U	0.42 U
		04/13/18	214	26.8	0.0227 U	61.4	2.95	20.4	0.8	19.6	0.717	702	5.81	7.55
		01/25/19	235	31.7	0.0227 UJ	56.9	7.93	11.1	1.5	9.6	0.552	291	2.43	3.41
		07/23/19	242	33.2	0.0227 U	78.9	2.73	0.614	0.0	0.6	0.323	327	3.96	7.04
		10/15/19	239	31.6	0.0227 U	73.8	2.49	1.16	0.0	1.2	0.320	384	0.296 U	0.422 U
		01/27/20	216	27.6	0.0227 U	66.4	2.31	0.990	0.5	0.5	0.380	292	0.296 U	0.422 U
		04/03/20	231	28.2	0.0227 U	66.3	2.08	0.389	0.5	0.0	0.288	296	0.296 U	0.422 U
		07/31/20	232	29.5	0.168	71.4	2.44	0.498 J+	—	—	0.224	232	0.296 U	0.422 U
		11/24/20	—	—	—	33.3	19.9	3.68	—	—	0.501	1,120	0.296 U	0.422 U
		02/03/21	—	—	—	19.3	64.9	1.16	—	—	0.788	2,430	0.296 U	0.422 U
		05/17/21	—	—	—	0.600 J	27.8	10.4	—	—	3.36	67,000	0.296 U	0.422 U
		08/23/21	—	—	—	4.32 J	5.07	6.16	—	—	2.19	46,100	0.296 U	0.422 U
		11/29/21	1,190	24.4	0.100 U	3.99	6.38	18.2	4.2	14.0	3.54	31,300	0.296 U	0.422 U
		03/08/22	—	—	—	18.3	3.58	20.7	—	—	1.81	24,500	0.296 U	0.422 U
		05/11/22	—	—	—	12.0	4.15	12.6	—	—	2.39	28,100	0.296 U	0.422 U
		08/12/22	—	—	—	24.8	3.43 J+	3.05	—	—	1.11	28,300	1.42	1.63
		08/12/22	—	—	—	25.2	3.42 J+	3.00	—	—	1.11	26,100	1.39	1.44
		10/31/22	1,440	28.1	0.0480 U	0.948 J	8.73	17.3	4.8	12.6	4.34	31,600	0.296 U	0.422 U
		05/16/23	—	—	—	9.78 J	5.68 J	7.67	—	—	2.29	37,500 J	4.91 J	4.87 J
11/06/23	1,280	27.5	0.0480 U	3.33 J	12.2	14.0	—	—	3.56	27,100	4.46	2.75		
11/08/24	1,070	28.2	0.0884 U	0.637 U	9.63	6.29	5.2	1.1	2.54	13,300	5.83	0.422 U		
W-MW-02	8th Ave N ROW, W side	12/16/13	240	105	0.025 U	101	—	0.672	0.9	0.0	0.676	8.91	5 U	5 U
		03/27/17	455	142	0.0227 UJ	0.0774 U	204	47.5	1.8	45.8	4.12	6,740	0.296 U	8.32
		06/19/17	520	103	0.0227 UJ	0.0774 U	116	33.7	1.5	32.2	2.98	16,900	0.296 U	3.71
		06/12/18	854	77.9	0.0227 R	0.0774 U	97.7	21.1	3.4	17.7	3.45	23,800	14.3	57.9
		01/25/19	876	91	0.0665 J	0.0774 U	33.7	20.8	2.0	18.8	3.71	11,300	0.67 J	0.422 U
		04/23/19	799	86.7	0.0227 U	0.0774 U	26.1	13.4	0.5	12.9	3.43	10,600	45.2	37.4
		07/23/19	965	98.4	0.0227 U	3.24 J	43.4	13.6	3.0	10.6	3.47	25,700	0.296 U	15.0
		10/18/19	1,230	89.5	0.0227 U	0.0774 U	37.6	20.5	3.4	17.1	3.82	32,100	42.0	4.22 U
		01/28/20	1,160	89.7	0.0227 U	0.0774 U	34.3	21.9	6.0	15.9	3.76	19,900	87.0	0.422 U
		04/01/20	1,140	82.4	0.0263 J	0.280 U	33.7	16	2.5	13.5	3.30	22,800	79.6	0.422 U
		07/31/20	1,070	77.4	0.0480 U	0.594 U	29.3	15.6	—	—	2.85	22,600	76.9	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Deep Zone														
FMW-129 (dup)	SDOT Mercer Parcels, NE quadrant	04/10/17	308	44.2	0.0227 U	124	2.74	0.365	0.0	0.4	0.402	279	26.8	0.422 U
		06/23/17	296	36.1	0.0914 J	95.5	1.70	9.92	1.0	8.9	0.412	276	14.7	0.422 U
		07/16/19	221	23.7	0.771	86.8	2.23	4.6	—	—	0.415	40.5	6.45	0.422 U
		10/21/19	209	23.6	0.639	82.4	1.52	18.9	0.5	18.4	0.648	53.5	5.31	0.422 U
		01/14/20	201	22.6	0.787	82.4	1.42	3.33	0.0	3.3	0.291	17.1	4.75	0.422 U
		05/06/20	313	35.6	0.0480 U	92.7	2.22	77.9	0.5	77.4	1.04	160	13.6	0.422 U
		07/10/20	346	37.5	0.0480 U	85.8	2.21	12.9	1.0	11.9	0.511	195	13.6	0.422 U
		11/10/20	—	—	—	81.2	1.61	9.18	—	—	0.438	267	22.3	0.422 U
		02/10/21	—	—	—	4.17 J	1.33	0.152	—	—	0.0145	0.287 U	0.296 U	0.422 U
		05/26/21	—	—	—	114	1.69	12.4	—	—	0.493	316	36.1	0.422 U
		05/26/21	—	—	—	126	1.68	10.2	—	—	0.469	351	39.4	0.422 U
		08/19/21	—	—	—	133	1.96	9.55	—	—	0.465	222	27.0	0.422 U
		05/05/22	—	—	—	140	2.23	0.924	—	—	0.455	481	20.0	0.422 U
		08/12/22	—	—	—	4.84 J	1.19	0.0763 J	—	—	0.0140	6.68	0.517 J	0.422 U
		11/11/22	48.3	2.72	0.806	5.12	1.26	0.115	0.0	0.1	0.0152	0.287 U	0.296 U	0.422 U
FMW-131	Block 37, SE quadrant	03/24/17	166	6.12	0.0227 U	0.738	2.18	0.598	0.5	0.1	1.03	159	1.19 J	0.422 U
		06/23/17	273	28.1	0.109	29.2	1.56	2.39	0.3	2.1	1.26	87.4	0.296 U	0.422 U
		10/21/19	108	6.00	0.0227 U	2.56 J	1.91	0.608	0.5	0.1	0.589	45.6	0.296 U	0.422 U
		01/22/20	160	7.02	0.0227 U	0.695 J	2.35	0.422	0.5	0.0	0.967	1,270	0.296 U	0.422 U
		04/29/20	375	13.1	0.0480 U	0.594 U	5.07	0.416	2.5	0.0	4.19	11,800	0.296 U	0.422 U
		07/30/20	133	7.13	0.0480 U	3.42 J	2.81	0.365	0.0	0.4	1.06	2,310	0.296 U	0.422 U
		11/01/22	198	10.3	0.0480 U	1.36 J	2.49	1.55	1.3	0.3	1.64	212	1.39	0.422 U
FMW-137	Alley E of Block 38 West	11/06/19	408	24.3	0.0331 J	37.0	3.20	0.400	0.0	0.4	2.67	0.287 U	0.296 U	0.422 U
		01/22/20	302	20.7	0.452	36.9	2.21	0.269	0.0	0.3	1.73	7.37	0.296 U	0.422 U
		05/06/20	699	44.4	0.0480 U	7.18	5.80	34.6	2.5	32.1	2.42	21.8	0.296 U	0.422 U
		07/31/20	721	63.4	0.0480 U	3.81 J	5.55	20.2	2.8	17.4	2.67	29.2 J	0.296 U	0.422 U
		11/01/22	343	25.0	0.0656 J	10.3	2.70	1.29	1.3	0.0	2.77	186	1.37	0.422 U
FMW-140	900 Roy St, S end	10/31/19	396	17.6	0.0227 U	2.99 J	16.8	0.213	0.5	0.0	1.02	2,440	75.1	81.1
		01/22/20	518	28.3	0.0228 U	76.3	6.09	20.6	3.5	17.1	2.09	5,080	105	39.3
		04/28/20	587	26.8	0.0480 U	47.2	7.94	22.0	4.2	17.8	2.56	4,640	40.3	36.3
		07/07/20	560	29.2	0.0480 U	70.5	6.72	17.7	6.0	11.7	2.61	5,150	81.6	33
		11/02/22	182	7.96	0.0480 U	4.64 J	7.58	7.64	—	—	2.54	6,390	0.296 U	0.422 U
GEI-2	Block 37, NW quadrant	03/24/17	420	12.5	0.0227 U	0.0774 U	8.14	24.0	0.3	23.8	0.898	15.1	0.296 U	0.422 U
		06/23/17	458	23.0	0.0227 U	0.0774 U	6.84	14.9	1.0	13.9	0.483	10,500	23.8	42.5
		07/16/19	340	27.1	0.0227 U	36.1	6.60	7.51	1.5	6.0	0.432	4,550	15.0	11.5
		10/21/19	512	24.8	0.0227 U	47.8	343	13.2	2.2	11.0	0.496	10,000	59.2	27.5
		01/22/20	414	281	0.0228 U	64.7	3.79	7.98	2.6	5.4	4.30	5,080	3.88	0.422 U
		04/29/20	622	18.5	0.0480 U	1.88 J	4.63	19.9	2.0	17.9	0.906	56.8	0.296 U	0.422 U
		07/30/20	474	18.0	0.0480 U	0.594 U	3.83	12.1	5.4	6.7	0.542	12,300	10.8	65.7
		11/01/22	502	18.8	0.0480 U	0.594 U	4.07	12.1	7.0	5.1	0.570	12,900	13.4	33.9

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW102	Valley St ROW, S side	04/25/18	160	4.99	0.0315 J	0.880 J	1.94	9.60	1.0	8.6	0.414	0.561	0.296 U	0.422 U
		01/24/19	162	5.19	0.0553 J	1.74 J	4.36	6.46	0.0	6.5	0.363	172	0.296 U	0.422 U
		05/01/19	173	5.39	0.0227 U	0.318 J	3.75	11.9	0.5	11.4	0.405	255	1.07 J	0.422 U
		07/18/19	167	5.58	0.0227 U	1.83 J	4.76	7.16	0.8	6.4	0.353	290	0.296 U	0.422 U
		11/14/19	176	8.17	0.161	2.57 J	4.19	4.01	0.0	4.0	0.329	224	0.296 U	0.422 U
		01/23/20	162	5.73	0.0227 U	3.07 J	2.31	1.76	0.5	1.3	0.268	117	0.296 U	0.422 U
		01/23/20	161	5.62	0.0227 U	2.93 J	2.34	1.31	0.5	0.8	0.259	154	0.296 U	0.422 U
		04/02/20	165	5.52	0.0300 J	4.02 J	1.15	3.02	0.0	3.0	0.246	10.1	0.296 U	0.422 U
		08/04/20	152	5.57	0.0480 U	3.74 J	1.51	1.83	0.0	1.8	0.220	13.6	0.296 U	0.422 U
		08/04/20	151	5.56	0.0480 U	3.73 J	1.18	1.41	0.0	1.4	0.215	22.2	0.296 U	0.422 U
		11/18/20	—	—	—	3.72 J	1.07	3.64	—	—	0.255	15.5	0.296 U	0.422 U
		02/03/21	—	—	—	3.75 J	1.32	2.96	—	—	0.200	17.4	0.296 U	0.422 U
		05/14/21	—	—	—	2.23 J	1.36	4.77	—	—	0.285	69.0	0.296 U	0.422 U
		08/11/21	—	—	—	2.48 J	1.61	4.53	—	—	0.264	91.5	0.296 U	0.422 U
		11/30/21	154	4.77	0.100 U	2.09	1.16	1.66	0.5	1.2	0.243	301	0.296 U	0.422 U
		03/07/22	—	—	—	2.24 J	1.57	4.29	—	—	0.240	51.2	0.296 U	0.422 U
		03/07/22	—	—	—	2.31 J	1.53	4.41	—	—	0.249	49.0	0.296 U	0.422 U
		05/10/22	—	—	—	2.63 J	1.62	3.79	—	—	0.195	264	0.296 U	0.422 U
		08/12/22	—	—	—	1.95 J	1.13	2.56	—	—	0.314	321	0.296 U	0.422 U
		10/31/22	142	5.07	0.0751 J	2.45 J	1.50	0.212	0.0	0.2	0.0402	2.66	0.296 U	0.422 U
MW103	Alley E of Seattle Roy Aloha Shops	12/18/13	380	48.8	0.025 U	0.99	—	1.14	1.4	0.0	1.10	67.5	9.14	13.5
		03/23/17	337	48.4	0.0227 U	36.3	1.97	1.68	0.3	1.4	1.09	433	82.5	34.1
		06/14/17	339	34.7	0.0227 U	28.1	2.58	4.56	—	—	0.936	863	84.6	43.1
		10/14/19	302	27.4	0.0227 U	25.0	1.55	0.948	0.5	0.4	0.870	166	17.7	13.8
		01/16/20	296	28.6	0.0227 U	25	1.75	7.45	1.0	6.5	1.02	284	29.1	34.3
		04/23/20	252	17.2	0.0480 U	13.3	2.77	13.5	1.0	12.5	0.814	267	10.1	0.422 U
		04/23/20	258	17.1	0.0480 U	13.5	2.44	11.3	1.0	10.3	0.786	314	12.3	0.422 U
		07/06/20	229	11.1	0.0480 U	8.30	2.10	24.4	0.5	23.9	0.864	246	0.296 U	0.422 U
		11/02/20	—	—	—	5.77	1.59	24.6	—	—	0.888	164	4.07 U	4.26 U
		02/10/21	—	—	—	9.20	1.18	9.69	—	—	0.592	65.2	0.296 U	0.422 U
		05/03/21	—	—	—	19.6	1.48	2.57	—	—	0.732	157	16.4	4.02
		08/12/21	—	—	—	25.4	1.75	0.936	—	—	0.833	205	23.4	7.61 J
		08/12/21	—	—	—	25.4	1.88	1.12	—	—	0.829	221	25.0	0.422 U
		11/08/21	305	30.2	0.200 U	25.9	1.50	0.884	1.0	—	0.802	171	26.4	9.95
		02/15/22	—	—	—	28.0	1.97	1.32	—	—	0.853	103	9.86	7.64
		05/09/22	—	—	—	30.4	1.63	2.65	—	—	0.951	272	28.3	24.3
		08/09/22	—	—	—	29.1	1.86	0.756	—	—	0.941	229	23.1	24.5
		11/01/22	311	36.1	0.107	27.9	0.960 U	0.881	0.0	0.9	1.01	277	20.6	28.1

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW104 <														

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW106	SDOT Mercer Parcels, NW quadrant	04/14/17	309	28.7	0.0227 U	17.9	5.93	14.1	0.0	14.1	1.08	79.5	0.296 U	2.62
		06/30/17	305	27.3	0.0227 U	18.0	10.0	4.96	0.0	5.0	0.779	38.7	0.296 U	0.442 U
		05/04/18	283	25.0	0.0227 U	10.4	1.74	0.164	0.0	0.2	0.496	77.8	0.296 U	10.8
		04/26/19	267	23.6	0.0227 U	15.9	3.32	3.42	0.0	3.4	0.695	42.1	0.296 U	0.422 U
		07/19/19	266	24.4	0.0227 U	15.0	2.23	13.7	0.0	13.7	0.972	39.5	0.296 U	0.422 U
		10/18/19	276	25.8	0.0227 U	17.0	2.32	2.64	0.5	2.1	0.792	47.2	0.296 U	0.422 U
		01/14/20	278	25.9	0.0227 U	17.0	2.82	12.6	0.0	12.6	1.02	39.8	0.296 U	0.422 U
		05/06/20	272	23.9	0.0480 U	15.3	2.52	9.99	0.0	10.0	0.904	27.3	0.296 U	0.422 U
		05/06/20	276	23.7	0.0480 U	15.2	2.45	8.02	0.0	8.0	0.856	26.4	0.296 U	0.422 U
		07/10/20	286	23.6	0.0480 U	15.6	1.97	6.51	0.5	6.0	0.943	47.5	0.296 U	0.422 U
		11/10/20	238	—	—	17.4	1.29	5.07	—	—	0.696	22.4	0.296 U	0.422 U
		11/10/20	232	—	—	17.3	1.24	4.13	—	—	0.666	24.3	0.296 U	0.422 U
		02/12/21	—	—	—	16.1	1.17	2.94	—	—	0.583	93.5	0.296 U	0.422 U
		02/12/21	—	—	—	16.2	1.15	2.88	—	—	0.583	88.8	0.296 U	0.422 U
		05/13/21	—	—	—	3.80 J	0.536 J	11.1	—	—	0.408	150	0.296 U	0.422 U
		08/19/21	—	—	—	13.1	1.19	9.70	—	—	0.641	77.9	0.296 U	0.422 U
		12/06/21	116	4.61	0.100 U	7.14	0.970 U	15.1	0.0	15.1	0.481	89.9	0.296 U	0.422 U
		02/18/22	172	—	—	11.2	1.06	10.8	—	—	0.546	37.3	0.296 U	0.422 U
		05/06/22	—	—	—	14.6	1.27	1.51	—	—	0.678	59.6	0.296 U	0.422 U
		08/02/22	—	—	—	9.67	5.73	4.45	—	—	0.707	87.0	0.296 U	0.652 J
		11/18/22	225	16.0	0.0480 U	14.3	1.18	11.5	—	—	1.02	50.1	0.296 U	0.422 U
MW113	9th Ave N ROW, W side	12/19/13	96	23.5	0.280	17.4	—	0.119	0.0	0.1	0.0248	5 U	5 U	5 U
		03/22/17	594	65.5	0.0295 J	55.4	27.0	7.46	4.0	3.5	0.757	3.53	0.296 U	0.422 U
		06/16/17	587	57.5	0.0227 U	41.9	18.0	14.4	1.5	12.9	0.990	6,520	147	0.422 U
		02/07/19	551	43.9	0.0389 J	33.3	18.8	6.1	2.5	3.6	0.659	4,050	39.9	6.30
		07/17/19	139	152	0.992	15.1	2.38	0.786	0.3	0.5	0.0799	1,130	9.87	27.2
		10/22/19	561	70.4	0.146	22.1	15.8	3.38	3.6	0.0	0.426	2,330	16.3	115
		01/14/20	583	66.9	0.0227 U	24.5	16.3	6.14	—	—	0.716	17,700	73.5	673
		04/27/20	456	46.0	0.0921 J	51.2	9.77	6.64	4.5	2.1	0.743	3,760	60.0	0.422 U
		07/28/20	396	39.2	0.0480 U	64.2	7.85	5.91	—	—	0.599	3,060	59.4	16.6
		11/24/20	—	—	—	110	3.02	5.16	—	—	0.420	575	13.0	0.422 U
		02/10/21	—	—	—	4.61 J	1.09	0.049 J	—	—	0.0129	0.287 U	0.296 U	0.422 U
		05/25/21	—	—	—	99.0	3.27	11.9	—	—	0.442	1,870	34.9	0.422 U
		08/11/21	—	—	—	67.5	6.49	6.87	—	—	0.567	4,220	61.1	0.422 U
		11/18/21	452	30.4 J	0.500 U	58.5	6.48	5.44	4.5	0.9	0.542	2,740	63.2	0.422 U
		11/18/21	440	30.4 J	0.500 U	58.5	6.43	5.63	4.5	1.1	0.546	2,120	50.7	0.422 U
		02/15/22	—	—	—	80.2	21.8	12.1	—	—	0.808	817	25.3	0.422 U
		06/08/22	—	—	—	79.1	15.3	15.3	—	—	1.10	1,690	56.5	4.44
		08/10/22	—	—	—	52.7	16.9	8.35	—	—	0.683	2,620	60.3	34.5
		11/03/22	526	67.6	0.0480 U	68.6	14.0	8.94	0.3	8.7	0.898	1,360	46.5	10.8

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW122	Alley E of Seattle Roy Aloha Shops	10/14/19	182	7.8	0.0584 J	5.82	1.19	0.348	0.0	0.3	0.212	0.287 U	0.296 U	0.422 U
		01/17/20	177	7.56	0.0227 U	6.07	1.21	0.152	–	–	0.477	149	0.296 U	0.422 U
		04/07/20	172	6.73	0.0480 U	4.92 J	1.37	0.0655 J	0.0	0.1	0.205	0.287 U	0.296 U	0.422 U
		07/24/20	173	6.06	0.0480 U	4.37 J	1.34	0.247	0.0	0.2	0.376	7.78	0.296 U	0.422 U
		11/11/21	178	6.45	1.00 U	6.00 U	1.69	0.337	0.3	0.1	0.457	44.3	0.296 U	0.422 U
		11/01/22	187	7.61	0.0480 U	3.26 J	1.49	0.203	0.0	0.2	0.533	81.5	4.98	2.39
MW123 (dup)	Westlake Ave N ROW, W side	10/18/19	409	22.9	0.0227 U	5.61	5.56	5.14	2.2	2.9	1.86	4,380	0.296 U	0.422 U
		10/18/19	409	22.9	0.0227 U	5.61	5.56	5.14	2.2	2.9	1.86	4,380	0.296 U	0.422 U
		01/22/20	382	24.3	0.0238 U	33.5	5.43	4.58	4.0	0.6	1.82	2,360	4.18	0.422 U
		05/05/20	337	31	0.0480 U	23.0	4.77	3.46	3.0	0.5	1.4	2,740	0.296 U	0.422 U
		07/30/20	424	22.7	0.0480 U	7.32	5.43	3.95	3.5	0.5	1.71	12,200	0.296 U	0.422 U
		11/03/22	346	22.3	0.0480 U	1.77 J	4.53	3.95	2.0	2.0	1.73	5,740	7.36	0.422 U
MW124	Valley St ROW, S side	12/26/13	160	5.96	1.22	0.730	–	1.46	0.4	1.1	0.125	5 U	5 U	5 U
		04/13/18	162	4.47	0.0227 U	0.46 J	2.45	20.1	0.5	19.6	0.757	24.6	0.296 U	0.422 U
		10/11/19	152	6.26	0.0227 U	5.92	3.78	2.24	0.0	2.2	0.301	12.3 U	0.296 U	0.422 U
		01/30/20	232	5.40	0.0668 J	2.12 J	2.69	5.46	0.0	5.5	0.347	70.8	0.296 U	0.422 U
		04/03/20	163	4.61	0.0269 J	0.894 J	1.87	6.36 J	0.0	6.4	0.468	42.2	0.296 U	0.422 U
		08/03/20	167	4.60	0.0480 U	0.594 U	1.96	1.34	0.0	1.3	0.322	30.0	0.296 U	0.422 U
		10/31/22	165	4.64	0.0778 J	0.594 U	2.24	0.131	0.0	0.1	0.282	9.47	0.296 U	0.422 U
MW128 (dup)	Westlake Ave N ROW, E side	03/29/17	387	15.9	0.0227 U	0.0774 U	4.84	10.5	1.8	8.7	0.227	12,600	13.2	64.8
		06/21/17	1,050	24.6	0.0227 U	0.0774 U	7.81	23.0	–	–	0.704	19,600	33.4	45.1
		07/18/19	601	22.3	0.0227 U	4.34 J	6.94	12.4	–	–	0.409	15,500	16.4	68.3
		10/11/19	746	22.6	0.0227 U	20.9 J	4.2	7.95	4.5	3.5	0.207	13,100	8.49 J	23.5 J
		10/11/19	828	21.4	0.0227 U	14.0 J	4.42	8.74	4.5	4.2	0.218	10,100	2.96 UJ	4.22 UJ
		01/20/20	541	23.1	0.0227 U	1.11 U	6.92	12.1	2.0	10.1	0.450	10,800	8.84	40.8
		04/27/20	497	18.6	0.0480 U	1.24 J	5.07	10.5	6.0	4.5	0.385	14,200	10.4	59.2
		06/29/20	515	18.2	0.0480 U	0.594 U	4.10	10.4 J	3.5	6.9	0.400 J	16,900	8.59	69.8
		11/01/22	480	18.2	0.0480 U	0.594 U	3.94	10.0	2.8	7.2	0.333	13,300	10.9	32.8
MW-133	Property, SW quadrant	04/25/18	173	9.91	0.287	1.43 J	2.84	4.80	1.3	3.6	0.297	549	5.77	17.4
		Decommissioned March 2019												
MW-137	Property, SW quadrant	04/12/18	213	109.0	0.0227 R	10.8	2.90	218	0.8	217.3	4.41	1,600	0.296 U	4.47
		Decommissioned March 2019												

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-138	Dexter Ave N ROW, E side	04/11/18	143	13.8	0.0227 U	45.9	4.89 J	21.5	0.0	21.5	0.725	83.1	0.296 U	0.422 U
		01/03/19	125	14.1	0.0227 U	47.5	3.90	2.19	0.0	2.2	0.375	61.3	0.621 J	0.573 J
		04/22/19	139	14.2	0.0227 U	42.7	5.70	13.2	–	–	0.509	164	0.296 U	1.43
		07/19/19	133	14.9	0.0227 U	53.4	1.40	11.7	0.5	11.2	0.560	74.2	0.296 U	0.422 U
		10/21/19	129	14.2	0.0227 U	51.9	1.10	3.83	0.5	3.3	0.504	101	0.296 U	0.422 U
		01/27/20	137	14.1	0.0227 U	48.6	2.2	21.9	0.5	21.4	0.711	564	0.296 U	0.422 U
		05/08/20	101	10.3	0.048 U	36	1.14	45	0.5	44.5	0.895	398	0.296 U	0.422 U
		07/27/20	122	13.8	0.0480 U	56.8	1.14	4.16	1.0	3.2	0.488	23.1	0.296 U	0.422 U
		11/18/20	–	–	–	45.9	0.948 J	4.63	–	–	0.452	17	0.296 U	0.422 U
		02/11/21	–	–	–	48.9	1.02	9.10	–	–	0.460	26.7	0.296 U	0.422 U
		06/07/21	–	–	–	41.8	0.921 U	14.2	–	–	0.424	42.0	0.296 U	0.422 U
		08/03/21	–	–	–	57.6	1.11	18.0	–	–	0.605	40.3	0.296 U	0.422 U
		11/10/21	115	11.8	1.00 U	44.0	1.03	29.3	0.8	28.5	0.857	53.2	0.296 U	0.422 U
		02/24/22	–	–	–	55.1	0.598 J	26.6	–	–	0.857	27.3	0.296 U	0.422 U
		05/25/22	–	–	–	65.1	0.848 U	22.5	–	–	0.792	47.3	0.741 J	0.728 J
		08/09/22	–	–	–	7.12	1.70	0.0708 J	–	–	0.0379	0.287 U	0.296 U	0.422 U
		11/08/22	115	8.38	0.0480 U	6.81	1.81	0.971	1.0	0.0	0.331	321	1.73	0.422 U
MW-140	Roy St ROW, N side	04/12/18	249	15.5	0.0227 R	5.73	2.40	15.0	0.3	14.7	0.795	261	0.296 U	0.422 U
		Decommissioned												
MW-141	Property, SE quadrant	04/12/18	179	9.64	0.0227 R	7.49	4.30	4.61	–	–	0.556	2,690	3.29	0.869 J
		Decommissioned March 2019												
MW-153	Roy St ROW, S side	05/01/18	148	24	0.0227 U	23.7	1.26	1.01	–	–	0.187	74.3	0.296 U	0.422 U
		01/22/19	156	9.91	0.0227 U	13.2	1.92	3.01	0.0	3.0	0.299	387	0.296 U	4.89
		04/24/19	174	9.4	0.0227 U	9.23	3.86	3.60 J	0.0	3.6	0.385	412	0.296 U	1.79
		04/24/19	170	9.16	0.0227 U	8.91	4.62	1.59 J	0.0	1.6	0.305	434	0.296 U	0.422 U
		07/22/19	160	8.31	0.0227 U	6.78	1.84	1.67	0.0	1.7	0.325	27	0.296 U	0.422 U
		10/15/19	174	10.5	0.0227 U	8.29	2.32	6.77	–	–	0.420	20.2	0.296 U	0.422 U
		01/21/20	166	10.7	0.0248 U	8.49	2.72	0.799	0.0	0.8	0.317	8.66	0.296 U	0.422 U
		04/30/20	140	7.3	0.0480 U	6.23	0.843 J	7.79	0.0	7.8	0.420	0.287 U	0.296 U	0.422 U
		07/15/20	150	7.49	0.0509 J	6.67	0.957 J	2.42	0.0	2.4	0.597	39.7	0.296 U	0.422 U
		11/09/20	142	–	–	11.2	0.956 J	2.68	–	–	0.327	32.7	0.296 U	0.422 U
		02/09/21	–	–	–	11.0	0.955 J	0.382	–	–	0.313	103	0.296 U	0.422 U
		02/09/21	–	–	–	10.8	0.907 J	0.560	–	–	0.315	105	0.296 U	0.422 U
		05/10/21	–	–	–	9.43	1.15	8.36	–	–	0.474	113	0.296 U	4.17
		08/20/21	–	–	–	8.81	1.14	3.65	–	–	0.351	106	0.296 U	0.422 U
		12/07/21	161	8.82	0.0690 J	8.69	1.28	6.82	0.4	6.4	0.414	174	0.296 U	8.20
		02/25/22	–	–	–	8.48	0.904 J	2.89	–	–	0.380	146	1.88	9.65
		05/02/22	–	–	–	8.50	1.39	8.80	–	–	0.436	173	1.20 J	9.40
		08/02/22	–	–	–	7.62	1.09	11.4	–	–	0.836	65.6	0.639 J	2.46
		11/03/22	159	10.4	0.0635 J	8.92	1.94	0.503	0.0	0.5	0.332	278	3.66	9.27

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)			
								Total	Ferrous	Ferric		Methane	Ethane	Ethene	
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER	
MW-158A	8th Ave N ROW, E side	04/30/18	345	113	0.446	278	54.8	55.4	0.5	54.9	1.04	352	15.7	11.0	
		01/24/19	329	29.7	0.0227 U	26.8	7.95	181	0.0	181	3.07	196	2.52	8.12	
		04/25/19	345	26.7	0.0227 U	21.1	8.11	12.4 J	—	—	0.393 J	177	0.296 U	4.74	
		07/19/19	330	26.9	0.0227 U	19.8	4.64	69.2	0.0	69.2	1.37	222	0.296 U	5.86	
		10/16/19	327	24.5	0.0330 J	20.4	4.46	5.46	—	—	0.350	115	20.1	7.24	
		01/21/20	319	25.3	0.0255 U	19.8	1.19	4.54	—	—	0.326	187	2.06	9.78	
		04/24/20	333	23.9	0.0480 U	13.0	3.14	6.38	0.0	6.4	0.326	88.4	0.296 U	9.01	
		07/15/20	323	24.0	0.0480 U	16.6	2.99	7.46	0.0	7.5	0.422	91.2	0.296 U	0.422 U	
		11/23/20	—	—	—	12.7	5.49	9.60	—	—	0.412	1,110	0.296 U	0.422 U	
		02/02/21	—	—	—	19.2	4.82	12.0	—	—	0.697	1,070	0.296 U	0.422 U	
		05/10/21	—	—	—	16.7	3.82	17.3	—	—	0.551	1,180	0.296 U	0.422 U	
		08/17/21	—	—	—	15.6	3.26	10.2	—	—	0.647	1,020	4.07 U	4.26 U	
		12/08/21	317	25.2	0.100 U	15.7	3.30	12.2	0.4	11.8	0.540	1,010	0.296 U	0.422 U	
		(dup)	12/08/21	320	25.0	0.500 U	16.0	2.89	12.2	0.4	11.8	0.537	866	0.296 U	0.422 U
		03/04/22	—	—	—	15.9	2.80	10.1	—	—	0.474	243	0.580 J	0.466 J	
		05/17/22	—	—	—	16.7	2.77	15.4	—	—	0.609	642	1.28 J	1.32	
		08/12/22	—	—	—	16.8	1.79	0.125	—	—	0.0232	11.9	0.296 U	0.422 U	
11/01/22	327	24.8	0.0555 J	15.4	2.67	2.33	0.0	2.3	0.404	1,660	2.72	2.87			
MW-160	8th Ave N ROW, W side	05/21/18	186	10.7	0.0703 J	2.68 J	1.47	12.3	0.0	12.3	0.400	129	14.5	4.75	
		01/25/19	134	10.7	0.0227 U	1.87 J	3.98	59.1	0.5	58.6	1.22	766	11.7	0.422 U	
		05/01/19	197	10.5	0.0227 U	1.26 J	3.79	4.60	0.0	4.6	0.387	1,070	4.41	0.422 U	
		07/23/19	182	8.28	0.0227 U	2.64 J	1.95	2.68	0.5	2.2	0.408	535	0.296 U	0.422 U	
		10/17/19	183	8.21	0.0227 U	2.06 J	2.31	10.5	0.8	9.7	0.522	537	0.296 U	0.422 U	
		01/29/20	172	8.94	0.0227 U	2.30 J	6.59	0.769	0.0	0.8	0.324	294	6.02	0.422 U	
		04/01/20	182	7.59	0.0249 J	3.29 J	3.41	20.7	0.0	20.7	0.569	621	2.24	0.422 U	
		08/03/20	173	6.84	0.0480 U	3.08 J	1.71	2.26	0.5	1.8	0.474	817	0.296 U	0.422 U	
		11/30/20	—	—	—	3.65 J	1.66	0.937	—	—	0.453	318	0.296 U	0.422 U	
		02/04/21	—	—	—	3.12 J	1.68	2.37	—	—	0.404	305	4.07 U	4.26 U	
		05/12/21	—	—	—	2.77 J	1.59	18.5	—	—	0.677	407	0.296 U	0.422 U	
		08/23/21	—	—	—	2.68 J	1.29	21.8	—	—	0.661	288	0.296 U	0.422 U	
		11/29/21	167	6.37	0.100 UJ	2.34	1.07	15.9	0.8	15.1	0.528	304	0.296 U	0.422 U	
		02/23/22	—	—	—	2.44 J	1.24	8.18	—	—	0.425	119	0.296 U	0.422 U	
		05/25/22	—	—	—	2.41 J	1.07	29.4	—	—	0.796	165	0.296 U	0.422 U	
		08/12/22	—	—	—	2.25 J	1.13	1.35	—	—	0.316	424	0.296 U	1.65	
		10/31/22	174	6.66	0.0480 U	1.96 J	1.03	3.91	0.8	3.1	0.420	408	0.296 U	0.422 U	

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

[illegible]

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-326 (dup)	Mercer St ROW, N side	10/03/19	209	17.1	0.0227 UJ	89.7	12.9	2.63	0.5	2.1	0.347	99.4	25.0	8.23
		01/17/20	211	17.9	0.0227 U	63.6	2.79	1.3	0.8	0.5	0.488	13.3	2.01	0.422 U
		04/21/20	242	20.4	0.0480 U	50.8	1.07	4.02	2.0	2.0	0.485	16.5	0.296 U	0.422 U
		07/23/20	271	23.1	0.0480 U	49.9	1.29	6.53	4.5	2.0	0.470	20.9	0.296 U	0.422 U
		11/04/21	268	24.4	0.200 U	53.1	1.72	4.73	0.0	4.7	0.494	0.287 U	0.296 U	0.422 U
		11/02/22	188	16.0	0.219 J	62.7	0.470 U	0.440	0.0	0.4	0.427	1.84	0.296 U	0.422 U
		11/02/22	194	15.9	0.0480 J	63.6	0.384 U	0.454	0.0	0.5	0.428	2.18	0.296 U	0.422 U
MW-328	Lake Union Park, S end	10/02/19	683	17.7	0.0227 UJ	0.787 J	8.75	20.3	4.0	16.3	0.755	23,700	0.296 U	36.8
		01/17/20	672	17.7	0.0227 U	0.0774 U	5.00	16.2	2.5	13.7	0.397	23,800	3.99	32.9
		04/08/20	708	17	0.0480 U	0.594 U	3.90	13.7	3.6	10.1	0.348	22,900	7.44	28.4
		07/07/20	574	15.1	0.0480 U	0.594 U	3.69	9.97	5.5	4.5	0.243	25,300	12.6	0.422 U
		11/10/21	458	12.0	1.00 U	3.71	4.64	6.98	4.5	2.5	0.201	16,600	0.296 U	0.422 U
		11/02/22	509	14.0	0.0480 UJ	0.594 U	4.42	9.31	3.5	5.8	0.253	22,600	17.0	15.1
MW-329 (dup)	Westlake Ave N ROW, E side	10/03/19	581	56.1	0.0227 UJ	11.4	4.82	7.71	4.0	3.7	2.21	591	19.9	0.422 U
		10/03/19	589	56.1	0.0227 UJ	11.4	5.05	8.06	4.0	4.1	2.26	716	23.4	0.422 U
		01/20/20	506	52.6	0.0227 U	14.8	4.61	4.83	1.5	3.3	2.30	1,020	25.9	0.422 U
		04/27/20	457	39	0.0480 U	14.4	3.50	11.1	2.5	8.6	2.14	955	24.2	0.422 U
		08/03/20	447	35.5	0.0480 U	14.0	3.59	7.75	3.0	4.8	2.13	630	15.7	0.422 U
		11/01/22	499	48.3	0.0480 U	18.9	3.83	4.01	3.2	0.8	2.21	404	21.4	2.58
MW-336	Mercer St ROW, N side	05/05/20	511	37.5	0.0480 U	74.3	3.58	10.5	6.5	4.0	0.596	271	0.296 U	0.422 U
		07/08/20	465	36.4	0.0480 U	72.1	2.68	7.72	4.0	3.7	0.462	343	7.16	0.422 U
		11/17/21	419	35.9	0.500 U	58.6	4.11	6.74	6.5	0.2	0.555	480	17.8	0.422 U
		11/03/22	256	39.6	0.830	60.4	1.70	0.0281 U	0.0	0.0	0.00101 J	1.56 J	0.296 U	0.422 U
MW-341	Lake Union Park, S end	05/12/20	378	19.1	0.0480 U	16.5	4.91	9.23	3.0	6.2	0.819	1,450	11.1	0.422 U
		07/07/20	404	19.8	0.0480 U	7.30	3.91	6.95	5.5	1.5	0.889	2,790	6.33	0.422 U
		11/10/21	386	19.8	1.00 U	8.98	3.07	6.74	4.3	2.5	0.723	3,370	0.296 U	0.422 U
		11/02/22	387	21.1	0.162 J	31.5	2.70	7.61	2.5	5.1	0.552	872	6.26	10.5
MW-342	Valley St ROW, S side	05/04/20	174	14.2	0.351	9.65	2.68	1.13	0.0	1.1	0.438	1,040	0.296 U	0.422 U
		07/30/20	227	8.07	0.0480 U	0.594 U	4.82	10.2	3.5	6.7	0.934	11,400	0.296 U	0.422 U
		11/09/21	559	24.0	0.0750 J-	0.275 J	8.03	27.3	1.5	25.8	2.52	18,400	0.296 U	0.422 U
		11/01/22	302	18.4	0.0480 U	0.594 U	2.61	4.87	2.8	2.1	0.436	12,000	6.62	18.0
MW-343	Valley St ROW, S side	05/04/20	695	108	0.0480 U	2.93 J	4.30	14.8	6.5	8.3	6.30	70.4	0.296 U	0.422 U
		07/30/20	697	109	0.0480 U	2.43 J	3.95	11.7	4.3	7.5	6.23	68.5	0.296 U	0.422 U
		11/09/21	363	29.7	0.200 UJ	0.594	3.12	6.73	3.8	3.0	2.21	2,630	0.296 U	0.422 U
		11/01/22	388	32.1	0.0480 U	0.594 U	2.94	5.82	3.4	2.4	2.11	2,130	4.33	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Perimeter Injection Zone A														
PRB-A1	8th Ave N ROW, W side	09/15/20	373	27.6	0.0480 U	63.4	8.92	12.7	2.0	10.7	1.65	2,350	26.4	17.1
PRB-A11 (dup)	8th Ave N ROW, W side	09/16/20	271	30.5	0.0480 U	37.4 J	5.62	7.35 J	–	–	0.905	1,170 J	56.2 J	27.6 J
		09/16/20	252	31.1	0.0480 U	34.2 J	5.67	4.79 J	1.8	3.0	0.823	1,710 J	69.7 J	37.1 J
PRB-A14	Roy Street ROW, N side	09/17/20	234	26.2	0.0480 U	201	2.48	2.63	–	–	0.565	419	0.296 U	27.6
PRB-A17	Roy St ROW, N side	09/15/20	284	26.5	0.0480 U	57.6	2.37	5.32	2.6	2.7	2.12	3,010	0.296 U	69.9
PRB-A19	Roy St ROW, N side	09/14/20	236	26.4	0.0480 U	34.2	2.06	5.21	3.5	1.7	0.735	6,380	0.296 U	0.422 U
PRB-A23	Roy St ROW, N side	09/14/20	382	28.9	0.0480 U	4.31 J	29.7	13.3	3.2	10.1	2.33	25,400	589	259
PRB-A5	8th Ave N ROW, W side	09/17/20	543	20	0.0480 U	75.4	14.2	9.04	3.8	5.2	2.09	12,900	65.6	70.3
Perimeter Injection Zone B														
PRB-B1	8th Ave N ROW, W side	09/15/20	245	21	0.0480 U	90.7	8.30	5.14	1.4	3.7	1.74	558	7.5	0.422 U
PRB-B4	8th Ave N ROW, W side	09/17/20	696	58.7	0.0480 U	44.3	30.7	22.2	5.5	16.7	1.91	29,100	609	671
PRB-B11	8th Ave N ROW, W side	09/16/20	450	53.8	0.0480 U	189	4.77	5.40	1.8	3.6	0.812	1,480	277	211
PRB-B14	Roy St ROW, N side	09/14/20	408	67.1	0.0480 U	61.3	7.36	2.44	0.6	1.8	0.723	5,080	65	650
PRB-B17	Roy St ROW, N side	09/15/20	144	99.5	0.0480 U	79.4	6.39	2.11	0.0	2.1	0.462	906	0.296 U	0.422 U
PRB-B19	Roy St ROW, N side	09/18/20	255	30.9	0.0480 U	26.6	5.33	4.26	0.4	3.9	0.680	54.7	0.296 U	0.422 U
PRB-B23	Roy St ROW, N side	09/18/20	433	45.3	0.0480 U	62.0	37.0	4.45	0.4	4.1	0.416	10,800	0.296 U	2,010
Perimeter Injection Zone C														
PRB-C1	8th Ave N ROW, W side	09/15/20	271	31.9	0.0480 U	6.28	3.10	2.84	0.0	2.8	0.299	855	0.296 U	8.18
PRB-C5	8th Ave N ROW, W side	09/17/20	590	31.1	0.0480 U	60.5	16.0	4.92	1.6	3.3	0.778	11,200	58.1	112
PRB-C11	8th Ave N ROW, W side	09/16/20	235	23	0.0480 U	45.2	1.99	13.6	0.4	13.2	0.545	763	3.36	7.63
PRB-C14	Roy Street ROW, N side	09/17/20	227	47.2	0.0480 U	88.3	3.06	6.24	0.4	5.8	0.240	266	0.296 U	8.29
PRB-C17	Roy St ROW, N side	09/15/20	95.7	92.4	0.0480 U	85.8	18.1	15.4	0.4	15.0	1.07	1,260	0.296 U	8.21
PRB-C19	Roy St ROW, N side	09/14/20	184	16.3	0.0480 U	18.5	1.30	2.37	0.0	2.4	0.219	319	0.296 U	0.422 U
PRB-C23	Roy St ROW, N side	09/14/20	266	33.6	0.0480 U	71.9	5.19	4.14	0.6	3.5	0.378	2,980	0.296 U	0.422 U
Perimeter Injection Zone D														
PRB-D1	8th Ave N ROW, W side	09/15/20	277	22.5	0.0480 U	26.0	2.49	5.26	0.0	5.3	0.493	835	0.296 U	0.422 U
PRB-D4	8th Ave N ROW, W side	09/17/20	713	56.7	0.0480 U	48.0	32.7	19.1	5.0	14.1	1.96	19,800	343	468
PRB-D11	8th Ave N ROW, W side	09/16/20	238	24.7	0.0480 U	112	3.97	2.80	–	–	0.749	2,350	0.296 U	15.2
PRB-D13	Roy St ROW, N side	09/18/20	200	22.8	0.0480 U	149	2.11	15.3	–	–	0.756	453	0.296 U	0.422 U
PRB-D17	Roy St ROW, N side	09/21/20	261	39	0.0480 UJ	20.0	6.53	8.34	1.1	7.2	1.06	10,500	9.58	671
PRB-D20	Roy St ROW, N side	09/18/20	230	25.7	0.0480 U	25.7	4.98	4.41	0.4	4.0	1.41	420	0.296 U	0.422 U
PRB-D23 (dup)	Roy St ROW, N side	09/18/20	173	27.9	0.0503 J	6.65	2.53	17.4 J	–	–	0.395	48.4	0.296 U	0.422 U
		09/18/20	176	28.5	0.0480 U	6.43	2.96	9.58 J	–	–	0.268	2.87 U	16.3	170

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Treatment Zone A														
MW-165	Property, NE quadrant	11/04/19	1,060	51.2	0.0227 U	57.2	121	60.6	4.0	56.6	5.26	12,000	370	151
		01/30/20	1,340	41.1	0.0227 U	12.9	88.7	48.1	4.5	43.6	7.47	21,000	221	69.4
		05/01/20	1,350	84.8	0.0480 U	1.72 J	100	50.7	3.0	47.7	7.36	2,590	84.5	0.422 U
		07/09/20	1,410	80.8	0.0480 U	7.66	89.2	41.3	6.0	35.3	7.57	20,000	476	139
		11/05/20	—	—	—	2.64 J	83.2	44.7	—	—	6.92	28,200	529	499
		11/05/20	—	—	—	2.65 J	83.3	44.6	—	—	7.03	29,500	549	532
		05/06/21	—	—	—	0.594 U	40.1	26.6	—	—	4.86	25,900	571	1,240
		12/02/21	651	55.4	0.100 UJ	0.198	29.5	20.1	3.4	16.7	3.61	34,900	859	590
		05/13/22	—	—	—	0.594 U	23.1	17.8	—	—	3.16	27,300	488	406
		10/28/22	610	56.7	0.0480 U	5.35	25.4	18.4	2.4	16.0	3.41	33,300	712	446
		05/11/23	—	—	—	0.594 U	26.2	25.3	—	—	5.52	27,700	527	38.9
		11/01/23	1,010	89.4	0.0714 J	0.594 U	26.2	25.7	3.5	22.2	5.93	25,700	378	6.89
		05/28/24	—	—	—	1.79 J	26.8	25.9	—	—	5.49	29,700	266	3.79
		11/19/24	903	71.9	0.0884 R	0.637 U	23.1	25.2	7	18.2	5.68	24,500	188	5.63
MW-169	Property, SW quadrant	11/05/19	577	149	0.0227 U	0.333 J	19.9	6.15	2.5	3.7	0.832	19,600	299	883
		01/23/20	584	145	0.0227 U	1.85 J	17.2	9.29	3.0	6.3	0.978	25,600	396	1,110
		05/05/20	601	147	0.225	0.594 U	19.2	5.10	2.0	3.1	0.821	18,700	336	1,180
		07/10/20	627	149	0.0480 U	0.594 U	16.9	11.3	4.2	7.1	0.883	21,600	393	866
		11/03/20	—	—	—	31.5	32.5	5.75	—	—	1.05	21,100	352	139
		05/07/21	—	—	—	9.36	19.7	4.22	—	—	1.36	7,940	68.6	25.8
		11/19/21	553	99.2	0.405 J	8.38	19.7	4.25	3.0	1.3	1.12	20,900	46.8	27.8
		10/27/22	449	85.0	0.0480 U	0.596 J	15.2 J+	2.71	1.4	1.3	0.748	30,500	198	0.422 U
		05/11/23	—	—	—	1.22 J	14.4	7.08	—	—	0.811	22,000	164	3.37
		11/03/23	486	86.4	0.0756 J	0.824 J	13.3	7.41	—	—	0.889	33,100	171	5.19
		05/24/24	—	—	—	1.04 J	14.2	4.03	—	—	0.785	29,500	204	55.0
		11/13/24	549	92.4	0.128	0.637 U	14.8	3.7	1.8	1.9	0.851	26,900	219	43.3
MW-173	Property, SE quadrant	11/01/19	472	51.7	0.0227 U	60.6	14.8	2.86	1.5	1.4	0.38	7,530	38.2	124
		01/28/20	442	38.9	0.0227 U	36.0	16.4	3.08	2.0	1.1	0.685	22.2	65.1	126
		05/01/20	484	46.6	0.0480 U	7.09	20.5	1.32	1.0	0.3	0.835	17,700	71.6	117
		07/09/20	524	48.9	0.0480 U	4.94 J	17.2	1.55	1.4	0.2	1.04	20,300	173	135
		12/02/21	444	42.2	0.100 UJ	0.275	13.2	2.92	2.0	0.9	1.82	6,270	174	41.6
		10/27/22	515	46.0	0.0480 U	0.594 U	11.9	3.02	1.9	1.1	2.07	29,400	613	104
		05/11/23	—	—	—	1.61 J	12.7	3.22	—	—	2.3	28,800	833	303
		11/02/23	613	49.7	0.0480 U	0.594 U	12.3	4.02	2.75	1.3	2.55	25,400	619	94.9
		05/28/24	—	—	—	0.734 J	16.1	6.23	—	—	2.39	30,500	795	59.6
		11/18/24	683	51.2	0.0884 R	0.637 U	14.8 J	4.1	2	2.1	2.29	28,600	664	62.3

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-177	Property, SW quadrant	11/06/19	589	285	0.0227 U	96.2	56.3	32.2	3.1	29.1	4.13	22,500	17.8	4,000
		01/24/20	511	241	0.0227 U	67.4	14.2	20.2	—	—	3.15	3,010	102	3,640
		04/01/20	588	282	0.0227 U	60.7	26.7	19.8	5.0	14.8	3.21	21,300	122	2,410
		07/10/20	670	254	0.0480 U	90.4	30.3	17.5	3.0	14.5	3.17	25,700	129	2,080
		11/03/20	—	—	—	55.4	17.4	6.26	—	—	1.32	28,400	472	2,990
		05/06/21	—	—	—	21.4	11.3	6.31	—	—	0.895	30,100	561	2,540
		12/03/21	306	69.2	0.100 UJ	16.4	9.66	4.48	3.0	1.5	0.736	19,400	345	1,130
		10/26/22	320	69.0	0.0480 U	10.3	8.33	3.62	1.8	1.9	0.666	29,100	731	1,880
		05/10/23	—	—	—	1.24 J	81.3	2.38	—	—	0.905	23,100	488	958
		11/01/23	441	78.6	0.119	0.594 U	10.1	6.79	—	—	0.764	27,400	661	1,430
		05/23/24	—	—	—	1.46 J	0.796 J	6.08	—	—	0.706	24,900	481	856
		11/12/24	581	92.4	0.0884 U	1.4 J	10.1	5.84	2.8	3.0	0.952	20,000	339	630
MW-181 (dup)	Property, SW quadrant	11/08/19	605	161	0.0227 U	0.449 J	26.5	3.74	2.0	1.7	1.09	14,300	18.7	2,870
		01/27/20	586	169	0.0227 U	0.749 U	46.4	11.4	4.4	7.0	1.87	17,500	7.62	2,370
		04/01/20	553	185	0.0274 J	0.337 U	22.4	9.12	5.2	3.9	1.45	17,700	24.3	2,620
		07/08/20	581	161	0.0480 U	0.594 U	21.8	10.1	4.0	6.1	1.36	22,700	29.4	2,140
		11/04/20	—	—	—	13.0	36.3	12.9	—	—	1.51	29,900	29.1	3,720
		11/04/20	—	—	—	11.6	36.00	13.2	—	—	1.55	28,500	36.5	3,810
		05/06/21	—	—	—	1.42 J	32.7	7.46	—	—	1.35	34,400	178	7,110
		11/18/21	499	123 J	0.500 U	3.32	36.6	10.1	3.8	6.3	1.44	25,500	250	3,890
		10/25/22	553	95.7	0.234 J	1.36 J	28.8	12.1	3.0	9.1	1.66	25,300	282	3,550
		05/10/23	—	—	—	0.594 U	33.5	13.5	—	—	1.62	31,600	311	3,290
		11/01/23	640	95.1	0.120 J	0.594 U	32.7	15.8	—	—	1.86	19,600	230	1,230
		05/23/24	—	—	—	1.87 J	31.0	13.3	—	—	1.59	85.2	0.296 U	2.44
		11/11/24	639	97.2	0.0884 U	0.637 U	34	13.8	5.1	8.7	1.61	29,100	410	2,860
MW-185	Property, SE quadrant	10/31/19	731	116	0.0227 U	38.1	51.4	9.91	2.5	7.4	1.63	10,300	9.69	232
		01/29/20	1,120	150	0.0227 U	0.112 J	38.7	18.5	3.0	15.5	3.42	37,000	213	0.422 U
		04/02/20	1,190	157	0.0227 U	0.273 U	20	25.2	6.2	19.0	3.41	23,300	227	0.422 U
		07/08/20	762	109	0.0480 U	0.594 U	18.7	13.1	5.5	7.6	1.64	28,500	288	0.422 U
		11/18/21	450	98.0 J	0.500 U	1.58 J	11.1	4.00	3.8	0.2	0.716	19,800	115	20.8
		10/27/22	526	79.9	0.0480 U	0.721 J	11.3	4.85	1.8	3.1	0.767	30,400	198	22.1
		05/11/23	—	—	—	0.594 U	57.9	35.7	—	—	2.88	23,700	92.1	24.7
		11/02/23	1,250	143	0.0480 U	0.594 U	14.5	26.5	—	—	2.64	17,100	58.9	6.17
		05/24/24	—	—	—	2.52 J	26.0	22.2	—	—	2.69	14,500	45.8	4.34
		11/19/24	1,400	157	0.0884 R	0.637 U	22.7	18.8	4.5	14.3	2.51	19,700	81.1	15.3

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Treatment Zone B														
MW-166	Property, NE quadrant	11/04/19	948	93.8	0.0227 U	13.6	122	54.5	5.0	49.5	2.11	14,300	67.6	2,500
(dup)		01/30/20	871	77.3	0.0863 J	0.0774 U	95.7	41.5	4.0	37.5	2.06	22,800	772	987
		05/01/20	893	87.3	0.0480 U	0.594 U	45.5	34.3	3.0	31.3	1.92	19,200	608	162
		07/09/20	701	55.3	0.0480 U	0.594 U	18.8	18.7	7.0	11.7	1.35	39,200	431	132
		07/09/20	717	55.8	0.0480 U	0.594 U	19.3	18.9	7.0	11.9	1.34	30,000	505	158
		11/05/20	—	—	—	4.67 J	42.2	36.6	—	—	2.03	34,500	940	1,890
		05/05/21	—	—	—	9.62	46.4	32.3	—	—	1.46	17,100	641	1,570
		12/02/21	688	76.0	1.72 J-	12.2	46.4	33.8	6.6	27.2	1.29	24,100	748	2,330
		05/13/22	—	—	—	10.7	42.9	32.9	—	—	1.14	18,900	399	1,450
		10/28/22	757	89.5	0.0480 U	18.1	46.7	33.9	3.8	30.1	1.58	30,100	480	1,930
		05/11/23	—	—	—	9.71	48.8	33.4	—	—	1.1	24,100	467	1,450
		11/02/23	909	101	0.0480 U	9.48	47.4	40.8	28.7	12.1	1.33	31,000	542	1,260
		05/28/24	—	—	—	10.4	52.0	42.6	—	—	1.24	26,800	529	1,140
		11/18/24	1,010	74 J	0.0884 R	8.55	57.1	41.6	4.5	37.1	1.21	27,300	630	1,170
MW-170	Property, SW quadrant	11/05/19	506	178	0.0227 U	112	22.9	1.87	1.1	0.8	0.947	10,000	62	1,120
(dup)		01/23/20	484	162	0.0227 U	60.9	19.6	8.24	3.0	5.2	1.03	7,530	42.7	868
		04/02/20	488	174	0.0227 U	41.1	16.7	10.8	4.5	6.3	1.05	9,400	44.8	986
		07/09/20	481	186	0.0480 U	16.9	13.2	12.1	5.5	6.6	1.22	13,000	31.5	1,120
		11/03/20	—	—	—	49.7	19.3	4.32	—	—	1.04	14,800	44.0	2,390
		05/07/21	—	—	—	16.9	14.6	2.57	—	—	1.02	31,400	52.0	1,990
		11/19/21	546	163	1.00 R	14.8	15.4	3.80	1.5	2.3	1.21	29,900	17.4	661
		05/12/22	—	—	—	9.53	14.5	2.74	—	—	1.09	13,100	29.9	814
		10/27/22	601	162	0.0480 U	3.03 J	16.5	4.09	2.6	1.5	1.19	21,800	146	2,160
		05/11/23	—	—	—	3.89 J	15.5	4.89	—	—	1.37	23,500	148	2,060
		11/02/23	611	175	0.0480 U	4.54 J	15.5	3.17	—	—	1.39	27,500	39.0	870
		05/24/24	—	—	—	7.34	15.9	2.64	—	—	1.43	23,600	22.6	552
		11/15/24	621	193	0.0884 U	7.69	23.2	2.97	1.9	1.1	1.55	32,800	42.4	909
		11/15/24	611	198	0.0884 U	7.58	18.4	2.83	1.9	0.9	1.59	32,000	41.9	900
MW-174	Property, SE quadrant	11/01/19	593	99.3	0.0227 U	17.8	15.3	9.63	3.0	6.6	1.73	21,600	214	165
		01/28/20	328	29.7	0.0227 U	11.1	5.28	9.95	3.0	7.0	0.710	1,720	111	0.422 U
		05/01/20	409	30.3	0.0480 U	1.79 J	4.7	18.1	5.0	13.1	0.800	16,800	86.5	0.422 U
		07/09/20	384	26.3	0.0480 U	8.34	3.94	6.28	3.8	2.5	0.761	16,700	82.3	0.422 U
		12/02/21	837	68.7	0.178 J-	5.42	16.9	9.04	4.0	5.0	2.77	4,840	34.0	7.99
		10/27/22	1,090	86.4	0.0480 U	3.69 J	29.1	14.7	3.0	11.7	3.68	28,200	196	57.6
		05/11/23	—	—	—	6.52	31.2	14.1	—	—	3.6	28,900	194	58.2
		11/03/23	1,150	98.2	0.0910 J	2.72 J	30.9	16.4	—	—	4.09	29,100	180	58.6
		05/28/24	—	—	—	3.59 J	32.9	16.4	—	—	3.48	34,200	244	66.7
		11/18/24	1,080	107	0.0884 R	2.8 J	37.9	17.4	3	14.4	3.9	33,000	302	109

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-178	Property, SW quadrant	11/06/19	1,740	170	0.0227 U	0.387 U	827	39.3	3.5	35.8	8.53	17,600	71.9	7,880
		01/24/20	1,810	178	0.0401 J	0.0774 U	43.8	65.8	6.0	59.8	7.47	2,240	784	114
		04/02/20	1,890	185	0.0376 J	0.0774 U	84.2	57.2	6.5	50.7	4.61	7,150	417	39.6
		07/10/20	2,040	201	0.0480 U	0.594 U	68.3	58.8	3.5	55.3	2.49	22,200	679	0.422 U
		11/03/20	—	—	—	0.737 J	59.5	26.2	—	—	3.78	26,500	382	495
		05/06/21	—	—	—	0.594 U	26.6	14.8	—	—	2.72	27,400	544	2,160
		12/06/21	721	96.9	0.100 U	0.145	24.1	12.6	6.5	6.1	2.44	25,200	194	594
		05/10/22	—	—	—	0.864 J	24.7	13.5	—	—	2.25	11,700 J	150	370
		10/25/22	754	134	0.0480 U	3.92 J	20.1	16.2	4.6	11.6	2.82	20,200	472	1,220
(dup)	Property, SW quadrant	11/08/19	1,610	146	0.0389 J	3.44 J	198	86.8	3.0	83.8	7.64	12,600	22.2	4,150
		01/27/20	1,310	128	0.0227 U	29.6	293	72.7	6.0	66.7	8.11	17,500	5.57	4,990
		04/01/20	1,290	137	0.0227 U	22.3	75.7	61.4	6.1	55.3	6.80	16,800	337	2,400
		07/08/20	1,250	158	0.0480 U	19.9	123	60.6	6.4	54.2	5.82	27,700	375	1,710
		11/04/20	—	—	—	0.594 U	144	39.0	—	—	5.90	38,900	89.6	8,010
		05/06/21	—	—	—	0.675 J	79.2	25.9	—	—	3.91	24,000	140	8,580
		05/06/21	—	—	—	0.654 J	84.8	23.6	—	—	3.94	27,000	140	8,250
		11/18/21	620	395 J	0.500 U	3.36	69.3	20.3	5.2	15.1	3.43	21,800	256	3,390
		05/10/22	—	—	—	0.594 U	61.2	19.2	—	—	3.12	19,900	294	3,400
		10/25/22	632	345	0.300	2.34 J	47.9	20.5	6.3	14.3	3.27	31,200	282	5,090
		05/10/23	—	—	—	0.594 U	41.3	19.8	—	—	3.03	30,500	383	4,290
		11/02/23	692	412	0.0480 U	1.01 J	33.0	22.7	—	—	3.13	30,900	293	3,530
		05/23/24	—	—	—	1.24 J	30.6	17.8	—	—	2.93	27,300	231	2,920
		11/13/24	702	365	0.0884 U	0.795 J	28	18.8	3.8	15.0	3.1	26,700	272	2,960
MW-186	Property, SE quadrant	10/31/19	320	62.9	0.0227 U	31.4	5.29	0.501	—	—	0.280	1,030	5.78	18.4
		01/29/20	249	58.8	0.0227 U	21.2	5.85	1.65	1.5	0.2	0.226	1,790	9.35	26.6
		04/02/20	322	60.1	0.0325 J	18.2	6.25	6.13	2.6	3.5	0.298	3,710	21.2	23.7
		07/08/20	298	54.4	0.0480 U	9.56	4.91	3.57	1.2	2.4	0.260	2,770	17.9	20.4
		11/18/21	645	101 J	0.500 U	1.49 J	12.6	8.30	6.4	1.9	1.50	32,800	260	109
		10/26/22	781	94.6	0.0480 U	0.594 U	10.2	10.8	3.0	7.8	1.73	32,900	300	37.4
		05/11/23	—	—	—	0.594 U	16.6	15.4	—	—	2.26	37,400	186	3.18
		11/02/23	1,110	113	0.0480 U	0.594 U	10.3	10.0	—	—	1.89	24,700	256	3.98
		05/24/24	—	—	—	2.69 J	11.5	10.9	—	—	2.00	29,400	311	0.422 U
		11/19/24	1,030	99.7	0.0884 U	0.637 U	13.3	7.72	5	2.7	1.91	21,900	228	11

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Treatment Zone C														
MW-167	Property, NE quadrant	11/04/19	347	38.1	0.0227 U	61.9	19.6	0.849	0.5	0.3	0.345	8,580	25.7	121
		01/28/20	347	38.7	0.0227 U	1.43 J	8.74	0.365	0.5	0.0	0.213	6,210	35.2	69.1
		05/01/20	366	38.7	0.0480 U	0.594 U	9.21	0.717	0.0	0.7	0.187	5,780	62.9	0.422 U
		07/09/20	356	33.5	0.0480 U	0.879 J	7.42	14.3	—	—	0.239	10,500	93.0	0.422 U
		12/02/21	353	28.5	0.100 UJ	36.9	12.5	4.65	0.8	3.9	0.414	5,720	90.8	0.422 U
		10/28/22	392	33.8	0.0480 U	16.9	10.2	2.35	0.3	2.1	0.569	5,840	90.9	1.42
		05/11/23	—	—	—	10.4	10.2	2.26	—	—	0.604	7,350	121	4.0
		11/01/23	441	37.1	0.0864 J	5.13	10.1	2.55	—	—	0.743	9,510	156	5.45
		05/28/24	—	—	—	5.83	10.4	3.07	—	—	0.876	10,900	163	13.7
		11/19/24	456	36.6	0.0884 R	4.07 J	11.9	3.25	0.4	2.9	0.89	9,820	212	15.5
MW-171	Property, SW quadrant	11/05/19	258	42.1	0.0936 J	22.0	10.2	3.63	1.0	2.6	0.190	231	0.296 U	10.8
		01/23/20	262	29.0	0.0227 U	9.02	4.99	9.73	0.5	9.2	0.200	580	0.296 U	19.5
		04/02/20	271	31.2	0.0227 U	5.27	5.33	13.1	1.0	12.1	0.195	896	5.34	57.0
		07/09/20	276	30.3	0.0480 U	9.59	3.76	4.18	1.0	3.2	0.176	963	14.1	72.3
		11/03/20	—	—	—	12.9	8.64	2.40	—	—	0.203	1,560	60.8	177
		05/07/21	—	—	—	32.9	8.03	5.33	—	—	0.420	3,200	33.1	529
		11/19/21	308	87.1	0.500 R	17.0	6.92	3.98	1.5	2.5	0.515	863	10.8	126
		05/12/22	—	—	—	14.3	5.73	4.11	—	—	0.496	1,080	8.35	104
		10/26/22	326	102	0.0480 U	12.0	7.08	2.66	1.1	1.6	0.548	4,890	26.4	424
		05/11/23	—	—	—	13.7	7.15	1.69	—	—	0.566	5,360	21.7	443
		11/01/23	350	110	0.0767 J	11.6	6.97	3.68	—	—	0.682	6,720	20.8	551
		05/24/24	—	—	—	12.0	6.95	1.68	—	—	0.585	6,610	20.4	706
		11/15/24	336	116	0.0884 U	11.5	6.37	2	1.5	0.5	0.645	9,070	21	921
MW-175	Property, SE quadrant	11/01/19	351	66.3	0.0227 U	224	32.1	0.800	0.0	0.8	0.178	1,670	16.4	323
		01/28/20	180	19.1	0.0227 U	1.88 J	13.4	0.916	0.0	0.9	0.0503	3,030	13.6	24.7
		05/01/20	199	16.2	0.0480 U	0.594 U	8.71	1.40	0.0	1.4	0.0531	4,030	0.296 U	0.422 U
		07/09/20	205	11.9	0.0480 U	0.594 U	4.26	1.48	0.5	1.0	0.0569	4,720	16.3	0.422 U
		12/02/21	819	72.2	0.100 UJ	0.144	11.8	5.57	4.5	1.1	1.86	5,050	110	0.422 U
		10/27/22	1,000	82.8	0.0480 U	0.594 U	18.8	15.9	3.8	12.1	2.84	32,200	567	0.422 U
		05/11/23	—	—	—	0.594 U	19.5	10.3	—	—	2.71	24,400	404	0.422 U
		11/02/23	1,100	88.0	0.0728 U	0.594 U	20.7	17.6	13.9	3.7	3.04	31,800	528	0.422 U
		05/28/24	—	—	—	1.83 J	26.7	14.4	—	—	3.29	35,500	462	0.422 U
		11/18/24	1,030	97.6	0.0884 R	0.637 U	29.7	12.6	3.5	9.1	3.11	30,200	512	62.4

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-179	Property, SW quadrant	11/06/19	1,180	121	0.0227 U	89.1	145	21.6	2.0	19.6	9.13	29,400	0.296 U	222
		01/27/20	1,270	121	0.0227 U	8.17	118	47.6	3.5	44.1	10.2	30,100	0.296 U	88.0
		04/02/20	1,400	122	0.0227 U	10.1	73.2	40.6	5.5	35.1	8.35	17,800	10.2	60.9
		07/10/20	1,420	149	0.0480 U	32.9	68.5	36.2	5.0	31.2	7.68	22,200	4.30	0.422 U
		11/03/20	—	—	—	13.2	31.2	10.6	—	—	2.64	25,600	4.77	121
		05/06/21	—	—	—	0.594 U	57.8	9.20	—	—	2.19	28,800	20.0	675
		12/03/21	777	202	0.100 UJ	0.100 U	28.1	15.1	6.5	8.6	2.78	21,000	19.8	360
		05/10/22	—	—	—	0.701 J	22.5	14.1	—	—	2.67	4,030	4.59	63.9
		10/25/22	886	228	0.0480 U	4.20 J	16.8	28.4	4.0	24.4	2.98	17,300	16.0	206
		05/10/23	—	—	—	0.594 U	20.5	6.7	—	—	3.02	14,300	19.5	137
		11/01/23	983	213	0.0846 J	0.594 U	15.6	20.0	—	—	2.93	16,500	21.1	233
		05/23/24	—	—	—	2.35 J	16.6	34.9	—	—	2.65	608	0.296 U	7.71
		11/12/24	1,040	238	0.0884 U	0.637 U	20.6	17.6	5.4	12.2	2.98	20,800	23.2	185
MW-183	Property, SW quadrant	11/08/19	162	13.0	0.0227 U	0.297 J	7.95	2.46	0.0	2.5	0.119	933	8.02	7.25
		01/27/20	151	13.3	0.0693 J	0.612 U	10.4	2.14	0.4	1.7	0.114	2,470	0.296 U	15.2
		04/02/20	174	11.3	0.0254 J	0.653 J	6.87	3.87	0.0	3.9	0.137	3,360	3.91	14.8
		07/08/20	175	11.8	0.0480 U	5.13	2.96	5.11	0.5	4.6	0.141	3,890	0.296 U	15.6
		11/04/20	—	—	—	41.2	9.81	2.72	—	—	0.739	11,000	4.75	40.4
		05/06/21	—	—	—	35.6	12.3	2.60	—	—	1.48	11,700	0.296 U	466
		11/18/21	341	95.3 J	0.500 U	22.4	16.0	5.01	0.6	4.4	1.88	20,400	13.4	1,100
		05/10/22	—	—	—	21.6	12.1	3.04	—	—	1.48	23,600	7.83	386
		10/25/22	345	95.3	0.0480 U	20.1	9.81	3.49	0.1	3.4	1.51	29,100	8.44	469
		05/10/23	—	—	—	19.8	11	3.06	—	—	1.36	29,800	0.296 U	379
		11/01/23	585	75.5	0.0890 J	16.2	10.5	2.51	—	—	1.55	32,600	4.79	437
		05/23/24	—	—	—	19.0	10.7	2.65	—	—	1.33	36,600	5.04	353
		11/11/24	622	84.1	0.0884 U	15.3	14.2	3.26	0.8	2.5	1.55	32,200	4.92	419
MW-187	Property, SE quadrant	11/01/19	193	24.5	0.0227 U	21.6	27.5	5.52	2.5	3.0	0.140	33.6	0.296 U	0.422 U
		01/29/20	179	18.6	0.0237 J	11.4	2.82	1.59	0.5	1.1	0.132	291	0.296 U	0.422 U
		04/02/20	201	18.5	0.0308 J	14.9	3.00	2.72	0.0	2.7	0.117	167	0.296 U	0.422 U
		07/08/20	201	17.1	0.0480 U	13.6	2.30	0.206	0.0	0.2	0.114	67.6	0.296 U	0.422 U
		11/18/21	524	75.3 J	0.500 U	9.70	7.16	2.69	2.0	0.7	0.602	10,400	239	19.4
		10/26/22	696	80.8	0.0480 U	0.594 U	7.33	4.32	2.2	2.1	0.868	13,100	375	0.422 U
		05/11/23	—	—	—	0.644 J	8.7	4.3	—	—	1.08	20,100	385	2.22
		11/02/23	805	87.1	0.0496 U	0.594 U	7.10	3.47	—	—	1.05	23,300	398	0.422 U
		05/24/24	—	—	—	2.53 J	7.04	3.66	—	—	1.10	17,500	413	0.422 U
		11/19/24	857	94.1	0.0884 UJ	1.28 J	8.38	4.1	2	2.1	1.12	22,300	442	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
Treatment Zone D														
MW-168	Property, NE quadrant	11/04/19	221	11.8	0.0227 U	12.1	2.44	0.378	0.0	0.4	0.254	0.287 U	0.296 U	0.422 U
		01/31/20	204	10.9	0.0227 U	11.0	2.19	0.301	0.5	0.0	0.286	108	0.296 U	0.422 U
		05/01/20	223	12.3	0.0480 U	11.3	3.46	2.55	0.5	2.1	0.276	598	0.296 U	0.422 U
		07/09/20	256	12.0	0.0480 U	0.594 U	2.16	7.06	1.0	6.1	0.319	1,600	0.296 U	18.1
		12/02/21	370	27.9	0.130 J-	5.92	7.10	1.91	0.4	1.5	0.940	16,100	270	0.422 U
(dup)		10/28/22	434	35.9	0.206	4.28 J	10.3	2.82	0.6	2.2	1.18	12,800	276	32.7
		10/28/22	439	36.4	0.171	4.26 J	10.3	2.71	0.6	2.1	1.16	13,100	264	31.8
		05/11/23	–	–	–	2.0 J	11.7	8.93	–	–	1.27	12,700	306	44.3
(dup)		11/02/23	503	43.0	0.593 J	1.57 J	11.7	5.78	2.63	3.2	1.12	16,900	332	17.5
		11/02/23	499	42.1	0.0480 UJ	1.34 J	11.6	5.59	2.83	2.8	1.15	16,800	332	17.3
(dup)		05/28/24	–	–	–	0.986 J	13.8	8.83	–	–	1.18	17,200	279	3.12
		05/28/24	–	–	–	0.959 J	14.2	8.61	–	–	1.18	17,100	264	2.83
(dup)		11/19/24	510	42.9	0.0884 R	1.29 J	13.6	13.4 J	2	11.4	1.52	16,800	325	2.27 J
		11/19/24	517	42.5	0.0884 R	1.37 J	13.7	7.4 J	2	5.4	1.48	13,400	260	4.83 J
MW-172	Property, SW quadrant	11/05/19	231	31.0	0.0227 U	22.1	3.31	0.131	–	–	0.392	18.1	0.296 U	0.422 U
		01/23/20	198	26.2	0.0227 U	26.8	4.93	0.355	0.0	0.4	1.03	301	7.66	19.4
		04/02/20	201	22.6	0.0315 J	41.8	8.49	4.78	0.0	4.8	2.58	34.7	0.296 U	0.422 U
		07/09/20	204	21.3	0.0480 U	34.3	6.99	4.88	0.2	4.7	2.05	256	0.296 U	0.422 U
		11/03/20	–	–	–	33.9	8.82	1.82	–	–	1.90	893	16.5	21.3
		05/07/21	–	–	–	23.6	4.91	5.67	–	–	0.850	4,770	0.296 U	0.422 U
		11/19/21	249	20.2	0.137 J-	25.2	6.70	0.534 J	0.1	0.4	1.58	2,570	0.296 U	0.422 U
		05/12/22	–	–	–	32.8	6.84	0.707	–	–	2.02	4,630	3.09	1.50
		10/27/22	294	25.9	0.0480 U	29.9	7.79 J+	0.514	0.3	0.3	2.22	5,210	0.296 U	0.422 U
		05/11/23	–	–	–	30.3	10.2	1.14	–	–	2.93	8,530	6.35	1.98
		11/02/23	407	26.9	0.0594 U	28.2	12.8	1.14	0.296	0.8	4.62	8,800	17.9	0.860 J
		05/24/24	–	–	–	24.0	6.86	3.58	–	–	1.80	11,100	17.1	11.5
		11/13/24	438	34.5	0.0884 U	32.5	14.2	2.23	0.6	1.6	4.62	7,550	77.9	2.46
MW-176	Property, SE quadrant	11/01/19	358	12.3	0.0227 U	15.2	1.65	0.351	0.0	0.4	0.310	20.4	0.296 U	0.422 U
		05/24/24	–	–	–	1.68 J	20.2	10.8	–	–	2.54	28,000	441	0.422 U
(dup)		01/28/20	186	11.5	0.0227 U	14.4	1.55	0.256	0.2	0.1	0.310	21.7	0.296 U	0.422 U
		01/28/20	184	11.4	0.0227 U	14.7	1.62	0.258	0.2	0.1	0.301	18.8	0.296 U	0.422 U
		05/01/20	198	11.3	0.0480 U	13.8	1.79	0.802	0.5	0.3	0.310	28.8	0.296 U	0.422 U
		07/09/20	207	11.0	0.0480 U	10.3	1.57	6.74	2.5	4.2	0.341	71.8	0.296 U	0.422 U
		12/02/21	625	57.5	0.100 UJ	0.988	9.53	5.04	3.5	1.5	1.59	6,220	123	11.8
		10/27/22	840	68.6	0.0480 U	0.594 U	16.4	11.4	4.1	7.3	2.29	28,900	590	30.1
		05/11/23	–	–	–	2.79 J	16.8	12.0	–	–	2.36	26,300	407	2.5
		11/02/23	919	76.6	0.0514 U	0.657 J	17.6	14.2	11.4	2.8	2.62	32,900	489	6.67
		11/18/24	887	78.9 J-	0.0884 R	0.637 U	23.1	11.6	2.75	8.9	2.69	27,800	536	44.6

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER
MW-180	Property, SW quadrant	11/06/19	940	50.8	0.0227 U	86.8	193	17.7	2.5	15.2	15.7	6,310	0.296 U	49.2
		01/24/20	623	46.9	0.0227 U	97.8	37.5	17.2	1.0	16.2	9.14	2,300	6.29	103
		04/01/20	489	34.6	0.0287 J	68.3	40.9	19.6	—	—	5.00	12,700	2.65	0.422 U
		07/10/20	397	31.8	0.0480 U	63.1	23.1	20.1	2.5	17.6	3.17	13,600	0.296 U	0.422 U
		11/03/20	—	—	—	55.5	25.3	14.1	—	—	3.53	21,700	6.99	33.2
		05/06/21	—	—	—	40.4	29.1	15.8	—	—	4.09	20,600	8.59	41.2
		12/03/21	755	44.6	0.100 UJ	23.3	28.1	20.9	7.0	13.9	5.52	23,000	36.5	98.3
		05/10/22	—	—	—	24.5	27.7	18.7	—	—	6.08	12,500	28.1	83.4
		10/26/22	1,150	74.6	0.0480 U	24.1	34.7	23.7	5.8	18.0	8.18	14,700	39.1	99.8
		05/10/23	—	—	—	14.0	33.2	19.7	—	—	8.57	20,200	213	210
		11/01/23	1,340	167	0.0659 J	27.0	29.7	26.5	—	—	7.81	24,500	159	109
		05/24/24	—	—	—	23.6	29.5	17.7	—	—	7.24	14,600	89.0	71.8
		11/12/24	1,340	193	0.0884 U	23	38.8	19.2	3.1	16.1	7.74	18,500	207	80.7
MW-184	Property, SW quadrant	11/08/19	156	10.8	0.0284 J	14.3	1.08	0.0836 J	0.0	0.1	0.268	8.35	0.296 U	0.422 U
		01/27/20	141	8.94	0.065 J	13.4	1.35	0.256	0.3	0.0	0.332	0.287 U	0.296 U	0.422 U
		04/01/20	152	8.68	0.0277 J	6.06	1.52	4.90	4.1	0.8	0.364	9.82	0.296 U	5.11
		07/08/20	160	10.9	0.0480 U	18.4	1.94	0.392	0.2	0.2	0.581	1,310	0.296 U	0.422 U
		11/04/20	—	—	—	28.5	3.92	2.89	—	—	2.28	4,380	0.296 U	0.422 U
		05/06/21	—	—	—	14.8	2.31	1.87	—	—	0.522	690	0.296 U	14.3
		11/18/21	298	19.9 J	0.500 U	34.3	12.7	1.35	0.5	0.9	3.83	1,480	0.296 U	0.422 U
		05/10/22	—	—	—	29.9	11.1	1.14	—	—	3.50	1,610	4.63	6.02
		10/25/22	303	23.7	0.132	29.7	9.49	1.16	0.0	1.1	3.72	1,720	7.45	6.31
		05/10/23	—	—	—	21.0	10.4	21.4	—	—	2.89	1,920	12.7	23.9
		11/02/23	395	29.6	0.0558 U	32.6	14.6	2.09	—	—	4.72	1,930	12.4	15.4
		05/23/24	—	—	—	11.7	5.04	1.78	—	—	1.35	3,020	7.59	67.6
		11/11/24	207	22	0.0884 U	7.5	3.8	0.543	0.6	0.0	0.668	3,800	4.35	99.7
MW-188 (dup)	Property, SE quadrant	10/31/19	196	22.0	0.0231 J	38.7	1.41	0.325	0.5	0.0	0.387	0.287 U	0.296 U	0.422 U
		01/29/20	187	23.9	0.0227 U	31.7	1.31	0.668	0.5	0.2	0.460	102	0.296 U	0.422 U
		04/02/20	198	25.4	0.0227 U	31.8	1.03	4.98	4.2	0.8	0.476	204	0.296 U	0.422 U
		07/08/20	204	22.5	0.0480 U	36.2	0.958 J	2.39	0.8	1.6	0.444	66.1	0.296 U	0.422 U
		11/18/21	277	39.6 J	0.500 U	23.6	2.52	1.22	—	—	0.521	4,050	78.4	0.422 U
		10/26/22	264	41.4	0.0480 U	24.4	1.97	1.19	0.1	1.1	0.579	927	24.1	0.422 U
		05/11/23	—	—	—	23.9	3.95	1.94	—	—	0.578	599	19.2	0.422 U
		11/03/23	298	42.5	0.0780 J	20.4	2.05	2.03	—	—	0.667	883	23.3	0.422 U
		05/24/24	—	—	—	16.8	10.1	6.42	—	—	0.644	1,520	36.2	1.49
		11/19/24	270	42.9	0.0884 UJ	23.3	1.91	1.75	1.8	0.0	0.598	366	11.1	0.422 U
		11/19/24	269	41.9	0.0884 UJ	22.7	2.01	1.72	1.8	0.0	0.599	319	9.37	0.422 U

Table 8
Groundwater Natural Attenuation Parameters
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Description Location Description	Sample Date	Alkalinity (mg CaCO ₃ /L)	Chloride (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)	TOC (mg/L)	Iron (mg/L)			Total Manganese (mg/L)	Dissolved Gases (µg/L)		
								Total	Ferrous	Ferric		Methane	Ethane	Ethene
				WATER	WATER	WATER	WATER	WATER			WATER	WATER	WATER	WATER

Notes:

Alkalinity analyzed by EPA Method 2320.
Anions analyzed by EPA Method 9056A.
Total Organic Carbon (TOC) analyzed by EPA Method 9060A.
Metals Analyzed by EPA Method 6020B.
Ferrous Iron measured during field sampling using a Hach field kit.
Dissolved gases analyzed by EPA Method RSK175.
Ferric iron = total iron minus ferrous iron; if total iron < ferrous iron, ferric iron is reported as zero ("0").
mgCaCO₃/L= milligrams of calcium carbonate per liter
mg/L = milligrams per liter
ug/L = micrograms per liter
Samples prior to 2017 were collected by SoundEarth Strategies (SES).
U = Not detected at or above the laboratory method detection limit (MDL).
Detected results shown in bold.
J = The identification of the analyte is acceptable; the reported value is an estimate.
J+ = The identification of the analyte is acceptable; the reported value is an estimate, but the result may be biased high.
R = The data is unusable. The sample result is rejected due to serious deficiencies in meeting QC criteria. The analyte may or may not be present in the sample.
– = Not sampled or results not available.
Beginning October 2020, select locations were sampled for an abbreviated analyte list (Sulfate, TOC, Total Iron, Total Manganese, Methane, Ethane, and Ethene).

Table 9
Dehalococcoides Data, Treatment Zone Monitoring Wells
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Location	Treatment Zone	Sample Date	Dehalococcoides (Dhc)		VC Reductase (vcrA)		BAV1 VC Reductase (bvcA)		TCE Reductase (tceA)	
			Percent Population ^a	Enumeration Per Liter ^b	Percent Population ^c	Enumeration Per Liter	Percent Population ^c	Enumeration Per Liter	Percent Population ^c	Enumeration Per Liter
Well Cluster 1 (Plume Wells)										
MW-166 (-12.6 to -22.6)	B	08/10/21	0.2 - 0.6 %	2E+06	0.3 - 0.9 %	2E+06	0.03 - 0.1 %	3E+05	0.006 - 0.02 %	5E+04
Well Cluster 2 (Source Area Wells)										
MW-170 (-12.8 to -22.8)	B	08/09/21	0.8 - 2 %	8E+06	0.6 - 2 %	6E+06	0.4 - 1 %	4E+06	0.4 - 1 %	4E+06
Well Cluster 4 (Source Area Wells)										
MW-177 (2.3 to -7.7)	A	08/09/21	14 - 35 %	3E+08	4 - 11 %	8E+07	16 - 40 %	4E+08	1 - 3 %	2E+07
MW-179 (-27.2 to -37.2)	C	08/09/21	8 - 23 %	9E+08	1 - 4 %	2E+08	0.3 - 0.8 %	3E+07	12 - 32 %	1E+09
Well Cluster 5 (Plume Wells)										
MW-181 (1.5 to -8.5)	A	08/09/21	7 - 20 %	2E+08	5 - 15 %	1E+08	5 - 15 %	1E+08	5 - 14 %	1E+08
MW-182 (-12.5 to -22.5)	B	08/09/21	10 - 26 %	4E+08	7 - 19 %	3E+08	8 - 21 %	3E+08	5 - 14 %	2E+08

Notes:

a = Percent *Dehalococcoides* (Dhc) in microbial population. This value is calculated by dividing the number of Dhc 16S ribosomal ribonucleic acid (rRNA) gene copies by the total number of bacteria as estimated by the mass of DNA extracted from the sample. Range represent normal variation in Dhc enumeration.

b = Based on quantification of Dhc 16s rRNA gene copies. Dhc are generally reported to contain one 16s rRNA gene copy per cell; therefore, this number is of interpreted to represent the number of Dhc cells present in the sample.

10⁵-10⁶ Dhc gene copies per liter: indicates the sample contains moderate concentrations of Dhc which may, or may not, be associated with observable dechlorination activity.

1 x 10⁷ Dhc gene copies per liter (or above): indicates that the sample contains high concentrations of Dhc often associated with significant dechlorination rates.

c = Percent of functional gene in microbial population. This value is calculated by dividing the functional gene copies quantified by the total number of estimate prokaryotes in the sample (based on the total quantity of DNA extracted from the sample). A value of 100% would suggest that all microbes in the sample contain the gene.

Well screen elevations (feet relative to the North American Vertical Datum of 1988 (NAVD88)) shown in parentheses.

No data was collected in 2024.

Table 10
Soil Vapor Analytical Results
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Probe	Location Description	Sample Name	Sample Date	Analytical Results (micrograms per cubic meter)											
				Benzene		PCE		TCE		cDCE		tDCE		VC	
Screening Level				11		320		11		–		610		9.5	
SV01 (30.4 to 29.9) (duplicate)	8th Ave N	SV01-20130311	03-11-13	–		1.5		0.16	U	0.31		0.580	U	0.710	
		SV01-092518	09-25-18	1.28	U	2.72	UJ	2.14	U	1.59	U	1.59	U	1.02	U
		SV01-092518-D	09-25-18	1.28	U	137	J	2.14	U	1.59	U	1.59	U	1.02	U
(duplicate)		SV01-020619	02-06-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV01-042919	04-29-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV01-042919-D	04-29-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
(duplicate)		SV-01-071919	07-19-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV-01-071919-D	07-19-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV01-110119	11-01-19	0.719		1.36	UJ	1.07	U	0.793	U	0.793	U	0.511	U
(duplicate)		SV01-110119-D	11-01-19	0.639	U	2.75	J	1.07	U	0.793	U	0.793	U	0.511	U
		SV01-012720	01-27-20	0.776		1.36	U	1.07	U	0.793	U	0.793	U	0.511	U
		SV01-012720-D	01-27-20	0.639	U	1.36	U	1.07	U	0.793	U	0.793	U	0.511	U
(duplicate)		SV01-040120	04-01-20	–		1.66		1.07	U	0.793	U	0.793	U	0.511	U
		SV01-040120-D	04-01-20	–		1.36	U	1.07	U	0.793	U	0.793	U	0.511	U
		SV01-071520	07-15-20	0.639	U	1.79		1.07	U	0.793	U	0.793	U	0.511	U
		SV-01-110820	11-08-20	0.639	U	1.55		1.07	U	0.793	U	0.793	U	0.511	U
		SV01-020721	02-07-21	7.54		1.36	U	1.07	U	1.09		0.793	U	180	
		SV01-051221	05-12-21	12.2		2.76		1.07	U	8.60		0.793	U	409	
(duplicate)		SV-907-051121	05-12-21	14.5		2.97		1.19		9.99		0.816		473	
		SV01-081421	08-14-21	29.1	J	12.8	J	1.07	U	33.0	J	2.54	J	478	J
		SV-908-081221	08-12-21	29.2	J	15.8	J	1.07	U	33.1	J	2.60	J	445	J
(duplicate)		SV01-121721	12-17-21	18.8		8.15		1.07	U	23.2		1.65		160	
		SV01-030822	03-08-22	13.9		4.28		1.07	U	13.3		0.959		55.5	
		SV01-050422	05-04-22	15.3		4.79		1.07		11.8		1.03		28.9	
		SV-01-082222	08-22-22	28.0		6.42		1.07	U	25.2		2.01		50.6	
		SV01-111022	11-10-22	16.5		5.90		1.07	U	21.8		1.72		28.6	
		SV01-022323	02-23-23	0.639	U	3.22		1.07	U	0.793	U	0.793	U	0.511	U
(duplicate)		SV01-080923	08-09-23	0.639	U	7.60	J	1.07	U	0.793	U	0.793	U	0.511	U
		SV-910-080923	08-09-23	0.639	U	13.5	J	1.07	U	0.793	U	0.793	U	0.511	U
		SV01-111623	11-16-23	0.639	U	4.15		1.07	U	0.793	U	0.793	U	0.511	
		SV01-031924	03-19-24	0.639	U	3.20		1.07	U	0.793	U	0.793	U	0.511	U
		SV01-061224	06-12-24	0.639	U	2.60		1.07	U	0.793	U	0.793	U	0.511	U
		SV01-090624	09-06-24	1.74		6.59		1.07	U	0.793	U	0.793	U	0.511	U
		SV01-112524	11-25-24	0.639	U	4.30		1.07	U	0.793	U	0.793	U	0.511	U
SV02 (32.1 to 31.6)	8th Ave N	SV02-20130311	03-11-13	–		2.3		0.170	U	0.12	U	0.61	U	0.0400	U
		SV02-092518	09-25-18	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV02-020619	02-06-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV02-042919	04-29-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV-02-071919	07-19-19	1.28	U	31.3		2.14	U	1.59	U	1.59	U	1.02	U
		SV02-110119	11-01-19	0.639	U	14.5		1.07	U	0.793	U	0.793	U	0.511	U
		SV02-071720	07-17-20	1.01		9.51		1.07	U	0.793	U	0.793	U	0.511	U
SV03 (31.8 to 31.3)	8th Ave N	SV03-20130311	03-11-13	–		4.6		0.390		0.12	U	0.58	U	0.0370	U
		SV03-092518	09-25-18	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV03-020619	02-06-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
		SV03-042919	04-29-19	1.28	U	2.72	U	2.14	U	1.59	U	1.59	U	1.02	U
SV-04 (38.6 to 38.1)	Roy St	SV-04-071620	07-16-20	0.639	U	31.8		1.07	U	0.793	U	0.793	U	0.511	U
		SV-04-111020	11-10-20	0.639	U	21.8		1.07	U	0.793	U	0.793	U	0.511	U
		SV-04-081221	08-12-21	0.639	U	44.9		1.07	U	0.793	U	0.793	U	0.511	U
SV-05 (31.6 to 31.1)	Roy St	SV-05-071620	07-16-20	3.71		34.5		1.07	U	0.793	U	0.793	U	0.511	U
		SV-05-111020	11-10-20	1.24		55.2		1.07	U	0.793	U	0.793	U	0.511	U
		SV-05-081221	08-12-21	0.639	U	97.1		1.07	U	0.793	U	0.793	U	0.511	U
SV-06 (47.9 to 47.4)	Roy St	SV-06-071620	07-16-20	0.639	U	105		1.07	U	0.793	U	0.793	U	0.511	U
		SV-06-111020	11-10-20	0.639	U	79.4		1.07	U	0.793	U	0.793	U	0.511	U
		SV-06-020321	02-03-21	1.01		58.3		1.07	U	0.793	U	0.793	U	0.511	U
		SV-06-050621	05-06-21	0.639	U	61.8		1.07	U	0.793	U	0.793	U	0.511	U

Table 10
Soil Vapor Analytical Results
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Probe	Location Description	Sample Name	Sample Date	Analytical Results (micrograms per cubic meter)											
				Benzene		PCE		TCE		cDCE		tDCE		VC	
Screening Level				11		320		11		-		610		9.5	
SV-07 (duplicate) (38.9 to 38.4)	Roy St	SV-07-071620	07-16-20	6.07		43.5		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-901-071620	07-16-20	5.81		42.5		1.18		0.793 U		0.793 U		0.511 U	
		SV-07-111020	11-10-20	0.639 U		51.6		1.32		0.793 U		0.793 U		0.511 U	
		SV-07-020321	02-03-21	0.974		30.3		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-07-050621	05-06-21	0.639 U		26.4		1.07 U		0.793 U		0.793 U		0.511 U	
SV-08 (31.4 to 30.9)	8th Ave N	SV-08-071420	07-14-20	0.639 U		2.91		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-110220	11-02-20	0.639 U		14.6		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-020321	02-03-21	0.639 U		6.26		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-050521	05-05-21	0.754		7.06		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-030722	03-07-22	0.639 U		6.05		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-080923	08-09-23	0.639 U		30.4		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-08-061124	06-11-24	0.645		8.01		1.07 U		0.793 U		0.793 U		0.511 U	
SV-09 (duplicate) (35.3 to 34.8) (duplicate)	8th Ave N	SV-09-071420	07-14-20	0.639 U		20.2		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-900-071420	07-14-20	0.639 U		28.3		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-09-110220	11-02-20	0.639 U		9.30		17.4		0.793 U		0.793 U		0.511 U	
		SV-09-020321	02-03-21	0.639 U		6.99		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-904-020321	02-03-21	0.639 U		6.93		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-09-050521	05-05-21	0.639 U		12.6		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-09-030722	03-07-22	0.639 U		6.52		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-09-080923	08-09-23	0.639 U		45.4		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-09-061124	06-11-24	0.639 U		16.4		1.07 U		0.793 U		0.793 U		0.511 U	
SV-10 (46.3 to 45.8)	Valley St	SV-10-071620	07-16-20	0.891		7.13		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-10-110820	11-08-20	0.639 U		5.17		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-10-020521	02-05-21	0.639 U		1.89		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-10-050521	05-05-21	0.639 U		3.27		1.07 U		0.793 U		0.793 U		0.511 U	
SV-11 (37.4 to 36.9) (duplicate)	Valley St	SV-11-071620	07-16-20	0.639 U		55.8		1.43		0.793 U		0.793 U		0.511 U	
		SV-11-110820	11-08-20	0.719		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-902-110820	11-08-20	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-11-020621	02-06-21	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-11-050521	05-05-21	0.639 U		3.03		1.07 U		0.793 U		0.793 U		0.511 U	
SV-12 (39.1 to 38.6)	Valley St	SV-12-071620	07-16-20	0.811		7.40		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-12-110820	11-08-20	0.639 U		3.19		2.14		1.20		0.793 U		0.511 U	
		SV-12-020521	02-05-21	0.639 U		1.72		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-12-050221	05-02-21	0.639 U		2.41		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-12-030322	03-03-22	0.639 U		1.88		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-12-080923	08-09-23	17.9		4.84		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-12-061224	06-12-24	0.639 U		8.55		1.07 U		0.793 U		0.793 U		0.511 U	
SV-13 (32.9 to 32.4)	Valley St	SV-13-071620	07-16-20	0.639 U		3.23		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-110820	11-08-20	0.639 U		3.46		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-020521	02-05-21	0.639 U		2.62		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-081221	08-12-21	0.639 U		3.86		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-030722	03-07-22	0.639 U		2.71		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-080923	08-09-23	0.639 U		3.90		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-13-061224	06-12-24	0.639 U		1.36		1.07 U		0.793 U		0.793 U		0.511 U	
SV-14 (35.4 to 34.9)	Roy St	SV-14-071620	07-16-20	0.639 U		3.61		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-14-120220	12-02-20	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-14-020321	02-03-21	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-14-050421	05-04-21	0.639 U		1.42		1.07 U		0.793 U		0.793 U		0.511 U	
SV-15 (28.5 to 28.0)	Roy St	SV-15-071620	07-16-20	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-15-120220	12-02-20	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-15-020321	02-03-21	0.898		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-15-050421	05-04-21	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		31.7	
		SV-15-081221	08-12-21	0.639 U		1.36 U		1.07 U		0.793 U		0.793 U		0.511 U	
SV-16 (37.5 to 37.0)	8th Ave N	SV-16-071520	07-15-20	0.639 U		6.86		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-16-111920	11-19-20	0.639 U		4.20		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-16-020721	02-07-21	0.639 U		2.83		1.07 U		0.793 U		0.793 U		0.511 U	
		SV-16-051021	05-10-21	0.639 U		153		12.8		1.17		1.29		0.511 U	
		SV-16-081321	08-13-21	0.639 U		5.86		1.07 U		0.793 U		0.793 U		0.511 U	

Table 10
Soil Vapor Analytical Results
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Probe	Location Description	Sample Name	Sample Date	Analytical Results (micrograms per cubic meter)											
				Benzene		PCE		TCE		cDCE		tDCE		VC	
Screening Level				11		320		11		-		610		9.5	
SV-17 (36.6 to 36.1)	8th Ave N	SV-17-071620	07-16-20	0.639	U	4.80	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-110220	11-02-20	0.639	U	6.65	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-020721	02-07-21	7.03		1.51	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-050621	05-06-21	0.639	U	1.79	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-030722	03-07-22	0.664		1.74	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-111623	11-16-23	0.639	U	5.08	1.07	U	0.793	U	0.793	U	0.511	U	
		SV-17-061224	06-12-24	0.639	U	1.75	1.07	U	0.793	U	0.793	U	0.511	U	
SV-18 (36.6 to 36.1) (duplicate) (															

Table 10
Soil Vapor Analytical Results
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Sample Probe	Location Description	Sample Name	Sample Date	Analytical Results (micrograms per cubic meter)					
				Benzene	PCE	TCE	cDCE	tDCE	VC
Screening Level				11	320	11	–	610	9.5
SV-24 (23.8 to 23.3)	Alley Between 8th & 9th	SV-24-071420	07-14-20	0.639 U	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-24-110920	11-09-20	0.639 U	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-24-020321	02-03-21	273 J	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-24-050421	05-04-21	0.639 U	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-24-111623	11-16-23	0.639 U	8.96 J	1.07 U	0.793 U	0.793 U	0.511 U
		SV-24-061024	06-10-24	1.82 J	5.45 J	1.07 U	0.793 U	0.793 U	0.511 U
SV-25 (52.7 to 52.2) (duplicate)	Dexter Ave N	SV-25-071520	07-15-20	1.49	215	1.07 U	0.793 U	0.793 U	0.511 U
		SV-25-110920	11-09-20	1.01	14.8 J	1.07 U	0.793 U	0.793 U	0.511 U
		SV-903-110920	11-09-20	0.818	54.0 J	1.07 U	0.793 U	0.793 U	0.511 U
		SV-25-020621	02-06-21	0.639 U	73.3	1.07 U	0.793 U	0.793 U	0.511 U
		SV-25-050521	05-05-21	0.639 U	121	1.07 U	0.793 U	0.793 U	0.511 U
SV-26 (46.7 to 46.2)	Dexter Ave N	SV-26-071520	07-15-20	4.57	66.9	2.61	0.793 U	0.793 U	0.511 U
		SV-26-111120	11-11-20	0.639 U	105	2.37	0.793 U	0.793 U	0.511 U
		SV-26-050621	05-06-21	0.639 U	51.6	1.07 U	0.793 U	0.793 U	0.511 U
SV-27 (44.1 to 43.6) (duplicate)	Dexter Ave N	SV-27-071520	07-15-20	0.639 U	95.7	1.07 U	0.793 U	0.793 U	0.511 U
		SV-27-110920	11-09-20	0.661	87.6	1.07 U	0.793 U	0.793 U	0.511 U
		SV-27-020621	02-06-21	0.901 J	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-905-020621	02-06-21	4.25 J	1.36 U	1.07 U	0.793 U	0.793 U	0.511 U
		SV-27-050521	05-05-21	0.639 U	65.9	1.07 U	0.793 U	0.793 U	0.511 U
SV-28 (53.1 to 52.6)	Dexter Ave N	SV-28-071720	07-17-20	0.639 U	31.6	1.07 U	0.793 U	0.793 U	0.511 U
		SV-28-110920	11-09-20	0.639 U	79.4	1.07 U	0.793 U	0.793 U	0.511 U
		SV-28-020621	02-06-21	0.639 U	36.0	1.07 U	0.793 U	0.793 U	0.511 U
		SV-28-050521	05-05-21	0.639 U	55.7	1.07 U	0.793 U	0.793 U	0.511 U

Notes:

Laboratory analyses conducted by Air Toxics Ltd. of Folsom, CA (2013 samples) and ESC/Pace Analytical of Mount Juliet, TN (2018-2021 samples).

VOCs analyzed by U.S. Environmental Protection Agency Method TO-15 or Modified TO-15 Selective Ion.

Screen Elevation is shown beneath Probe Location in parentheses. Screen Elevation is relative to NAVD88 Vertical Datum. Survey data is from 06/16/2020-07/31/2020.

Screening levels based on CLARC, July 2021, Vapor Intrusion Method B table, Sub-Slab Soil Gas Screening Levels (if available), or Method B

Indoor Air Cleanup Levels with a 10x vapor attenuation factor if a sub-slab cleanup level is not available.

– = Screening level not established.

U = Not detected at a concentration exceeding the laboratory reporting limit.

Detected results shown in **bold**, detections exceeding MTCA Method B sub-slab screening levels shown in **bold and highlighted in gray**.

PCE = Perchloroethylene (Tetrachloroethene)

TCE = Trichloroethene

cDCE = cis-1,2-Dichloroethene

tDCE = trans-1,2-Dichloroethene

VC = Vinyl chloride

(duplicate) = Field duplicate. Samples collected concurrently.

Table 11
Farallon Wells Excluded From the 2024 Quarter 3 and Quarter 4 Contour Maps
American Linen Supply Co Dexter Ave Site
700 Dexter Avenue North
Seattle, Washington

Shallow			Intermediate A			Intermediate B			Deep		
X-coordinates	Y-coordinates	Well Location	X-coordinates	Y-coordinates	Well Location	X-coordinates	Y-coordinates	Well Location	X-coordinates	Y-coordinates	Well Location
1269503.455	231645.6208	MW-45	1269414.236	231121.3122	FMW-150	1269433.501	231253.1744	OW-1	N/A	N/A	N/A
1269499.135	231564.4861	MW-50	1269388.103	231210.1119	FMW-151	1269429.926	231122.0727	OW-2			
1269563.379	231642.4492	MW-54	1269353.91	231326.74	FMW-152	1269314.71	231013.84	OW-3			
1269362.515	231643.1221	MWR-3	1269352.62	231043	FMW-153	1269324.75	231369.61	OW-5			
1269561.305	231566.9737	MWR-6	1269341.77	231556.91	B-37-7						
1269551.763	231637.8439	FMW-139	1269448.08	231558.97	B-37-8						
1269137.925	231878.6866	B43-FMW-1	1268586.161	231391.7096	MW-4						
1269102.034	231531.7733	B43-FMW-2	1269437.13	231346.24	FMW-157						
1269138.789	231803.7262	B43-FMW-3	1269554.298	231544.625	B-37-9						
1269119.723	231794.9535	B43-FMW-4									
1269064.155	231770.1212	B43-FMW-5									
1269078.31	231840.3822	B43-FMW-6									
1269224.39	231813.92	SVE-1									
1269237.63	231787.92	SVE-2									
1269143.72	231805.3	SVE-3									
1269199.12	231831.54	SVE-4									
1269167.892	231816.653	SVE-5									
1268584.205	231261.5012	MW-1									
1268485.636	231262.231	MW-2									
1268390.52	231361.9265	MW-3									
1268469.64	231378.29	MW-5									
1269456.65	231826.6093	B-37-3									
1269554.931	231824.7241	B-37-4									
1269446.845	231715.7181	B-37-5									
1269561.875	231753.5438	B-37-6									

Note:

These wells are not included in the NV5 groundwater monitoring plan.

FIGURES

