

2025 Second Quarter Progress Report and First Quarter Groundwater Performance Monitoring Report

SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal) Cleanup Site ID 4426 Consent Decree No. 00-2-05714-8SEA

July 2025

Submitted to:

Washington State Department of Ecology Northwest Regional Office 15700 Dayton Avenue North Shoreline, Washington 98133

Prepared for:

TLP Management Services LLC 1670 Broadway Suite 3100 Denver, Colorado 80202

Prepared by:

TechSolve Environmental, Inc. 7518 NE 169th Street Kenmore, Washington 98028 www.techsolveinc.com



2025 Second Quarter Progress Report and First Quarter Groundwater Performance Monitoring Report

SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal) Cleanup Site ID 4426 Consent Decree No. 00-2-05714-8SEA

Erik I. Lottsfeldt, LG

Project Manager, WA Licensed Geologist

TechSolve Environmental, Inc.

Like Whileld

A 21 Geologic ERIK I. LOTTSFELDT

Larry E. Roberts, LG, LHG

Principal, WA Licensed Geologist/Hydrogeologist

TechSolve Environmental, Inc.

Tany & Robert






TABLE OF CONTENTS

EXECUT	TIVE SUMMARY	ES -1
1 IN	TRODUCTION	1-1
2 RE	MEDIATION SYSTEM OPERATIONS	2-1
2.1	Waterfront System Operations	2-1
2.1	I.1 Recovery Well Monitoring	
2.2	Inland System Operations	2-4
2.3		
3 SU	MMARY OF GROUNDWATER PERFORMANCE MONITORING PROGRAM	3-1
4 SU	MMARY OF DATA VALIDATION	4-1
5 AD	DDITIONAL ACTIVITIES	5-1
5.1	Periodic EPA Five-Year Review	
5.2	MW-3 Decommissioning	5-1
5.3	Waterfront Piezometer Sampling	
6 RE	FERENCES	6-1

TABLES

- 1. Waterfront Groundwater System Petroleum Hydrocarbon Recovery Rates
- 2. Groundwater/LNAPL Recovery Well Performance Monitoring
- 3. Groundwater Performance Monitoring Schedule
- 4. Groundwater Performance Monitoring Groundwater Elevations
- 5. Summary of Analytical Results for Groundwater TPH-G, TPH-D, TPH-O, and Benzene
- 6. Summary of Free Product Measurement Results for Groundwater
- 7. Summary of Data Validation Results

FIGURES

- 1. Site Location Map
- 2. Plant 1 First Quarter 2025 Groundwater Monitoring Analytical Results & Contours

TechSolve Environmental

i

ACRONYMS AND ABBREVIATIONS

AG&M **ARCADIS Geraghty & Miller** ARCO Atlantic Richfield Company

ΒP British Petroleum West Coast Products Company

Cleanup Action Plan CAP

CCR **Construction Completion Report**

CUL cleanup level

Ecology Washington State Department of Ecology

EDR Engineering Design Report

GPM gallons per minute

Groundwater Compliance Monitoring and Contingency Program **GWCMCP**

indicator hazardous substance IHS

KCDNRP King County Department of Natural Resources and Parks

light non-aqueous phase liquid LNAPL **0&M** operation and maintenance

POC point of compliance

RI/FS Remedial Investigation/Feasibility Study

SVE soil vapor extraction

TechSolv Consulting Group, Inc. (predecessor of TechSolve Environmental, Inc.) TechSolv

TechSolve TechSolve Environmental, Inc. TPH total petroleum hydrocarbons

TPH-D total petroleum hydrocarbons as diesel TPH-G total petroleum hydrocarbons as gasoline total petroleum hydrocarbons as oil TPH-O

VRU vapor recovery unit

WAC Washington Administrative Code



EXECUTIVE SUMMARY

This report summarizes the operation of remediation systems during the second quarter of 2025 (April through June) and groundwater monitoring conducted in the first quarter of 2025 (January through March) at the SeaPort Seattle Terminal (the Site). The Site is located on Harbor Island at 1652 SW Lander Street in Seattle, Washington.

There were no anomalous conditions noted in the remediation systems or during groundwater monitoring conducted during the second quarter. Groundwater in one monitoring well, GM-14S, contained concentrations of two dissolved-phase Indicator Hazardous Substances (IHSs) above the cleanup levels (CULs) during the first quarter groundwater performance monitoring. The elevated concentrations of benzene and total petroleum hydrocarbons as gasoline detected in Well GM-14S are similar to concentrations previously reported. Concentrations of IHSs in all other wells were below the CULs.

In accordance with Washington State Department of Ecology (Ecology) Consent Decree No. 00-2-05714-8SEA (Ecology 2000), the 2025 third quarter progress report and second quarter groundwater monitoring report will be the next report submitted to Ecology. That report will be submitted to Ecology by October 15, 2025.



ES-1

1 INTRODUCTION

TechSolve Environmental, Inc. (TechSolve) is submitting this report on behalf of TLP Management Services LLC to summarize the operation and maintenance of the waterfront remediation system during the second quarter 2025 (April through June) and groundwater monitoring conducted in the first quarter 2025 (January through March) for the SeaPort Seattle Terminal (the Site) (Figure 1). The Site is located on Harbor Island at 1652 SW Lander Street in Seattle, Washington, and is the location of the former Atlantic Richfield Company (ARCO)/British Petroleum West Coast Products Company (BP) Terminal site. These two summary reports are combined based upon an Ecology recommendation (Ecology 2004a). This progress report satisfies reporting requirements pursuant to Ecology Consent Decree No. 00-2-05714-8SEA (Ecology 2000).



2 REMEDIATION SYSTEM OPERATIONS

Remediation systems were installed and completed at the Site in accordance with specifications of the Engineering Design Report (EDR) prepared by TechSolv Consulting Group, Inc. (TechSolv), predecessor of TechSolve Environmental, Inc., and ARCADIS Geraghty & Miller (AG&M) (TechSolv and AG&M 2000), and the Site Cleanup Action Plan (CAP) (Ecology 1999). A waterfront groundwater/light non-aqueous phase liquid (LNAPL) remediation system has operated at the Site since 1992 (including an interim system and the final system) to remove free-phase LNAPL and dissolved-phase petroleum hydrocarbons from groundwater at Plant 1 (Figure 1), as further detailed below.

2.1 Waterfront System Operations

Installation, startup, and testing of the final waterfront remediation system was completed in 2002 and 2003. An interim recovery system was installed along the waterfront in 1992 and operated until the installation of the final system. Standard operation of the final system began once testing demonstrated that the system operated as designed. System construction, operation, and maintenance (O&M) are detailed in the Construction Completion Report (CCR) (TechSolv 2003a) and in the Final O&M Manual (TechSolv 2003b), which were approved by Ecology (Ecology 2004b). The O&M Manual is updated as practices or procedures change or as systems are altered. Operation of various portions of the remediation systems have been ongoing since startup and have been modified/revised as needed, as discussed in the following sections.

O&M activities are conducted on the recovery systems to ensure they operate as designed and in accordance with applicable operating limits. These activities include, but are not limited to:

- weekly checks of groundwater recovery system pumping rates;
- weekly inspections of system components and waste storage containers for integrity per the requirements of Washington Administrative Code (WAC) 173-303-320;
- monthly sampling of recovered groundwater influent and effluent streams to ensure compliance with King County Department of Natural Resources and Parks (KCDNRP) Discharge Permit 7592-07 for sample site A43262;
- monthly monitoring and calculation of system LNAPL recovery rates; and
- monthly sampling of system flow rates and hydrocarbon concentrations.

Additional maintenance activities are conducted as needed to maintain system operational integrity and to ensure discharges are within permitted ranges.



Operation of waterfront air sparging and soil vapor extraction (SVE) systems were discontinued in May 2008, as the bulk of available hydrocarbons had been recovered (TechSolv 2009). The results of monitoring showed that operation of these portions of the recovery system have achieved their objectives of recovering LNAPL to the maximum extent practicable and improving groundwater quality along the waterfront.

Combined LNAPL recovery (free-phase, residual, and dissolved-phase) from final SVE and groundwater/LNAPL recovery systems is approximately 14,560 gallons (October 2002 to June 2025) (Table 1). The interim systems, operated from 1992 through 2002, recovered an additional 15,223 gallons of LNAPL, for a total combined LNAPL recovery of 29,783 gallons. The majority of LNAPL recovered by final remediation systems was from enhanced biodegradation, calculated from carbon dioxide concentrations in SVE vapor.

The data collected from the groundwater/LNAPL recovery system (Table 1) show that influent concentrations of dissolved benzene, diesel, and gasoline in recovered groundwater (i.e., untreated water pumped from recovery wells that are screened in the shallow groundwater) have decreased over time. During 2025, influent concentrations of dissolved benzene and gasoline were all below the surface water cleanup levels (CULs), influent sampling for diesel was discontinued in 2009. The data included in Table 1 also show that measurable volumes of recovered free-phase LNAPL have not been generated since 2008, which was the last time sufficient LNAPL was recovered to warrant offsite shipment. These data correlate with the absence of recoverable free-phase LNAPL in the system recovery wells, other than slight and medium sheens detected in two of the recovery wells (RW-2 and RW-4). The monitoring results indicate that the recovery system has captured the available free-phase LNAPL, and that operation of the recovery system should be discontinued and the efforts for continued protection of the waterfront should be focused on groundwater monitoring of the waterfront wells (TechSolve 2022d).

Effluent discharges from the groundwater/LNAPL recovery system to the sanitary sewer have been within KCDNRP's permitted ranges in 2025 (Table 1). Average monthly effluent flow rates ranged from 0.32 to 0.46 gallons per minute (GPM) in 2025. These rates are below KCDNRP's maximum permitted flow of 15,000 gallons per day (10.4 GPM) and are consistent with past rates that have decreased over time.

Maintenance and repair of the remediation systems and wells are conducted to maintain integrity, effective operation, capture, and hydraulic control along the waterfront. Notable activities conducted in the second quarter of 2025 included the following:

- cleanout and service of treatment system process equipment, and
- piping and system back flushing and preventative maintenance to maintain conveyance piping and pumping from the recovery wells.
- annual ultrasonic thickness (UT) testing of the recovery system piping and manifold.



The data collected indicate that the system continues to operate as designed and in accordance with permit requirements.

2.1.1 Recovery Well Monitoring

Monitoring of the recovery wells for free-phase LNAPL, sheen, and concentrations of dissolved-phase Indicator Hazardous Substances (IHSs) is voluntary (e.g. not required by the Consent Decree) and is conducted semi-annually. The latest sampling was conducted in the second quarter 2025 (Table 2). This monitoring has shown that no recoverable LNAPL remains and that dissolved-phase IHSs in shallow groundwater are not likely to cause exceedances of IHS CULs at the deeper points of compliance (POCs) monitoring wells. These POCs are located along the waterfront and the monitoring wells are screened at depths where the groundwater and surface water exchange is occurring (i.e., below the base of the subsurface waterfront barriers of sheet piling and seawalls), as detailed in the Remedial Investigation/Feasibility Study (RI/FS) completed in 1997 (Geraghty & Miller, 1994, 1996, and 1997). The next round of recovery well sampling is scheduled to be completed in the fourth quarter of 2025, and the results will be presented in the subsequent quarterly progress report to be submitted in January 2026.

Recovery well monitoring for LNAPL conducted in June 2025 (Table 2) showed no measurable LNAPL (<0.01 feet) in any of the ten recovery wells (Figure 2). No sheen on groundwater was detectable in seven of the ten recovery wells. A medium sheen was detected in well RW-4. A slight sheen was detected in wells RW-2 and GM-11S. Monitoring of shallow groundwater for dissolved-phase IHSs showed concentrations in eight of the ten recovery wells were below the IHS CULs for benzene and for total petroleum hydrocarbons (TPH) as gasoline (TPH-G). Concentrations in all wells were below the IHS CULs for diesel (TPH-D) and for oil (TPH-O). Groundwater from one well, GM-11S, exceeded the TPH-G CUL. Groundwater from one well, RW-4, exceeded the benzene CUL. These data have been consistent over the past several years and are also consistent with the results of the Waterfront Probing Investigation (TechSolve 2020). The investigation showed that no recoverable LNAPL remains present and that dissolved phase IHSs in shallow groundwater are not likely to cause exceedances of IHS CULs at the deeper POCs.

The trends in monitoring results from waterfront recovery wells and from compliance monitoring wells, which are discussed in Section 3, support the conclusion that the cleanup objectives for the Site have been achieved, as detailed in the Annual Site Reports since 2019 (TechSolve 2020, 2021, 2022c, 2023a, 2024, and 2025). The data included in these reports document attainment of the Site cleanup objectives and show that moving to compliance monitoring exclusively is appropriate and consistent with the Consent Decree. Discussions with Ecology to further evaluate this transition are ongoing and additional monitoring of waterfront temporary piezometers is currently being conducted to support this monitoring transition, per Ecology's request (Ecology 2023).



2.2 Inland System Operations

An inland SVE system operated from 2008 through 2014 to improve soil and groundwater conditions along the southern boundary of Plant 1. The SVE system was decommissioned in 2018 following completion of the cleanup goals and has been discussed in the Annual Site Reports cited in the previous section. The in-ground SVE piping and control manifold for this system remain onsite as a contingency in case operation of the system is warranted in the future.

Groundwater monitoring data collected along Plant 1's southern boundary indicate the system improved groundwater conditions in this area of the Site, as discussed in previous progress reports as well as the Annual Site Report (TechSolve 2025).

2.3 Containment Boom Monitoring

Oil sorbent booms have been maintained on the West Duwamish Waterway adjacent to Plant 1 to contain oil sheens that have historically appeared on surface water. The boom locations have been adjusted periodically with Ecology's concurrence as the sheens have been markedly reduced over time. One boom, the Northern Warehouse Boom, is currently maintained in the waterway adjacent to the warehouse (Figure 2). Boom locations have been selected to best contain occasional sheens historically observed on the West Duwamish Waterway directly adjacent to the Site. The boom and the waterway are monitored by TechSolve weekly, at a minimum, for boom integrity and for the presence of oil sheens and augmented by surveillance made by Terminal personnel. Booms are replaced as necessary based on their condition. The Northern Warehouse Boom was replaced on May 27, 2025.

No sheens on surface water have been observed within the Northern Warehouse Boom during the second quarter of 2025. Use of the Southern Warehouse Boom was discontinued in the second quarter of 2022, following notification to Ecology (TechSolve 2022b), as no sheen had been observed in that area since August 2019. No sheen was observed near the northwest corner of the Site during this monitoring period as well. The Southern Warehouse Boom will be reinstalled and maintained if sheens attributable to the SeaPort Seattle Terminal are detected at this location in the future. Waterway sheen monitoring results will continue to be evaluated throughout the remainder of 2025 and into 2026, per Ecology's request (Ecology 2023). Boom monitoring and maintenance will be conducted until Ecology concurs that the performance standard for boom maintenance established by the Groundwater Compliance Monitoring and Contingency Program (GWCMCP) (TechSolv 1999) has been met.



3 SUMMARY OF GROUNDWATER PERFORMANCE MONITORING PROGRAM

The first quarter 2025 groundwater monitoring was conducted in accordance with requirements of the Consent Decree (Ecology 2000), CAP (Ecology 1999), and GWCMCP (TechSolv 1999). The monitoring also includes revisions requested by Ecology that are included in the EDR (TechSolv and AG&M 2000) and detailed below. The current groundwater monitoring schedule is summarized in Table 3. Monitoring well locations for Plant 1 are shown on Figure 2. The first quarter groundwater monitoring was conducted on March 18 and 19, 2025.

Wells monitored on a semi-annual basis are sampled in the first and third quarter, which typically correspond with seasonal groundwater highs and lows, respectively. As such, wells AR-03, GM-14S, GM-15S, GM-16S, GM-17S, GM-24S, AMW-01, AMW-02, AMW-03, AMW-04, AMW-05, MW-1-T9, MW-2-T9, and MW-3-T9 were sampled in the first quarter of 2025. These wells will next be sampled in the third quarter of 2025.

Overall, first quarter 2025 groundwater elevations (Table 4) were higher than elevations measured in the second and third quarters of 2024 and similar to the fourth quarter of 2024. These data indicate that the seasonal groundwater high occurred in late 2024 to early 2025, corresponding with historical trends showing groundwater elevations rising to seasonal highs in the winter and spring months and falling to seasonal lows in the summer and autumn months.

Groundwater monitoring samples collected for the first quarter 2025 were submitted to OnSite Environmental, Inc., Redmond, Washington (Ecology Accreditation #C591) for laboratory analysis of IHSs identified in the CAP. The IHSs include TPH-G, TPH-D, TPH-O, and benzene.

Petroleum hydrocarbon monitoring results for the first quarter 2025 are included in Table 5 and Figure 2. The only detections of an IHS above a CUL were in well GM-14S, which had exceedances for TPH-G and benzene. Concentrations from all other samples analyzed were below associated CULs. The benzene and TPH-G concentrations detected in Well GM-14S are similar to concentrations previously detected. Further evaluations of data trends will be presented in the 2025 Annual Site Report, in accordance with Consent Decree requirements.

Three wells (GM-11S, GM-12S, and GM-13S) have been examined monthly for the presence of free phase LNAPL and sheens (Table 6). Historically, gauging for LNAPL at Plant 1 was conducted at four wells; however, gauging of Well GM-14S was discontinued in 2004, with concurrence from Ecology (Ecology 2004c), and converted to a monitoring well in 2007, as it has been free of LNAPL since 1999.

No measurable LNAPL was detected in Wells GM-11S, GM-12S, and GM-13S during the first and second quarters of 2025. A slight sheen was detected in GM-11S in May and June of 2025. Historical sheen monitoring data and trend analysis were presented in the 2024 Annual Site Report (TechSolve 2025). Overall, LNAPL and sheen monitoring indicate that these wells meet the



2nd Quarter Progress Report and 1st Quarter Groundwater Monitoring Report SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal) July 2025

GWCMCP LNAPL performance standard of no measurable LNAPL. These three wells will continue to be gauged for sheen and LNAPL for the remainder of 2025, until Ecology concurs that the GWCMCP LNAPL performance standard has been met.



4 SUMMARY OF DATA VALIDATION

Laboratory analytical results were reported with associated laboratory quality assurance/quality control (QA/QC) data. Analytical reports were reviewed, and the data were validated. During this quarter, the TPH-G and TPH-D results for GM-24S were qualified as J (estimated value), as noted in Table 7. These results do not affect our interpretation of the Site data. All laboratory reports are retained by TechSolve.



5 ADDITIONAL ACTIVITIES

5.1 Periodic EPA Five-Year Review

As part of the periodic EPA five-year review for the Harbor Island Superfund Site, Ecology requested (Ecology, 2025a) an updated Mann-Kendall trend analysis of select wells and analytes at the Site, similar to what EPA has presented in the past. The table below summarizes the results.

Mann-Kendall Trend Analysis (2020-2024), TF-OU2, BP (SeaPort Midstream Partners)

Well	Constituent	# Data Daints	Min May	Trand Tast	Confidence
weii	Constituent	# Data Points	Min-Max	Trend Test	Confidence
			Concentration	Result	Factor
			(μg/L)		
A N 4) A / O 2	Dan1	20	0.5 +- 200	Dannasina	05.00/
AMW-02	Benzene ¹	20	0.5 to 200	Decreasing	95.0%
GM-14S	Benzene ¹	20	0.5 to 1900	Increasing	95.0%
MW-3-T9	Benzene ¹	10	0.5 to 17	No Trend	95.0%
GM-14S	TPH-G ²	20	280 to 3000	No Trend	95.0%
GM-24S	TPH-G ²	20	190 to 2300	No Trend	95.0%
GM-15S	TPH-G ²	10	50 to 300	No Trend	95.0%
GM-16S	TPH-G ²	10	50 to 140	No Trend	95.0%
AR-03	TPH-G ²	10	5 to 740	No Trend	95.0%
MW-1-T9	TPH-G ²	10	87 to 480	No Trend	95.0%
MW-2-T9	TPH-G ²	10	56 to 760	No Trend	95.0%
MW-3-T9	TPH-G ²	10	410 to 740	No Trend	95.0%

¹Benzene cleanup level = 71 μg/L

The EPA five-year review report is traditionally published in the third quarter following the period of review (2020-2024), in this case likely September 2025.

Also as part of the five-year review, a site walk-through was arranged by Ecology to tour the facility on March 27, 2025, with representatives of the EPA as well as Terminal and TechSolve staff.

5.2 MW-3 Decommissioning

Facility improvements to add a new vapor recovery unit (VRU) associated with upgraded biodiesel handling capabilities required an existing monitoring well, MW-3, to be decommissioned due to its location within the foundation footprint of the new VRU. MW-3 was decommissioned in accordance with Washington well construction standards (WAC 173-160-381) with Ecology's



²TPH-G cleanup level = 1,000 μg/L


approval (Ecology, 2025b) on May 8, 2025. MW-3 was installed prior to the RI/FS and was never used as part of the monitoring well network for either groundwater quality or elevation monitoring and therefore will not be replaced unless requested by Ecology. The former location of MW-3 is depicted on Figure 2: Plant 1 First Quarter 2025 GW Monitoring Analytical Results & Contours.

5.3 Waterfront Piezometer Sampling

Discussions are ongoing with Ecology to determine a clear path forward towards discontinuing active remediation, implementing final confirmation monitoring, and achieving Site closure. Shallow groundwater analytical data requested by Ecology (Ecology, 2023) was collected quarterly in 2024 from the eleven temporary piezometers that exist in the warehouse and loading rack areas to assess this option. The piezometers were sampled for dissolved-phase IHSs (benzene, TPH-G, TPH-D, and TPH-O), as well as MNA parameters (methane, total sulfate, total nitrate, total chloride, alkalinity, manganese, hardness, and ferrous iron). The results of these activities will be presented to Ecology in an upcoming summary report. Recommendations may include a temporary discontinuation of the active remediation system with additional groundwater monitoring to assess the potential for IHS rebound.



6 REFERENCES





2022c. 2021 Annual Site Report, Site: Former BP Harbor Island Terminal, 1652 SW Lander Street, Seattle, Washington. April 2022.
Street, Seattle, Washington. April 2022.
2022d. Petition for Waterfront Groundwater/LNAPL Recovery System Shutdown, Site: Former BP Harbor Island Terminal. October 2022.
2023a. 2022 Annual Site Report, Site: Seaport Seattle Terminal (Former ARCO/BP Harbor Island Terminal), 1625 SW Lander Street, Seattle, Washington. April 2023.
2024. 2023 Annual Site Report, Site: Seaport Seattle Terminal (Former ARCO/BP Harbor Island Terminal), 1625 SW Lander Street, Seattle, Washington. April 2024.
2025. 2024 Annual Site Report, Site: Seaport Seattle Terminal (Former ARCO/BP Harbor Island Terminal), 1625 SW Lander Street, Seattle, Washington. April 2025.
Washington State Department of Ecology (Ecology). 1999. Cleanup Action Plan (CAP), ARCC Terminal 21T, Seattle, Washington. November 19, 1999.
2000. Consent Decree No. 00-2-05714-8SEA. March 24, 2000.
2004a. Annual Site Review Meeting with Roger Nye, Project Manager, Northwest Regional Office. Personal communication to Ralph Moran (BP) and Larry Roberts and Scott Larsen (TechSolv Consulting Group, Inc.). April 14, 2004.
2004b. Letter from Roger K. Nye, Northwest Regional Office, to Ralph Moran (BP). June 8, 2004.
2004c. Email from Roger K. Nye, Northwest Regional Office, to Larry Roberts (TechSolv Consulting Group, Inc.) RE: proposal approval. June 15, 2004.
2023. Verbal discussion between Vance Atkins (Ecology), Larry Roberts (TechSolve Environmental, Inc.), and Doug Hall (TLP Management Services). Onsite terminal walk-through/meeting. July 12, 2023.
2025a. Email from Vance Atkins (Ecology) to Larry Roberts (TechSolve Environmental, Inc.) RE: Trend Analysis. March 6, 2025, 4:46:45 PM.
2025b. Letter from Vance Atkins, Northwest Regional Office, to Erik Lottsfeldt (TechSolve Environmental, Inc.), April 21, 2025.



TABLES

- 1. Waterfront Groundwater System Petroleum Hydrocarbon Recovery Rates
- 2. Groundwater/LNAPL Recovery Well Performance Monitoring
- 3. Groundwater Performance Monitoring Schedule
- 4. Groundwater Performance Monitoring Groundwater Elevations
- 5. Summary of Analytical Results for Groundwater TPH-G, TPH-D, TPH-O, and Benzene
- 6. Summary of Free Product Measurement Results for Groundwater
- 7. Summary of Data Validation Results



Table 1. Waterfront Groundwater System Petroleum Hydrocarbon Recovery Rates Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

GROUNDWATER SYSTEM EFFICIENCIES

	·		Influent	Effluent	%	Influent	Effluent	%	Influent	Effluent	%	Influent	Effluent	%	Influent	Effluent	%	Influent	Effluent	%	Influent	Effluent	%
	SAMPLE DATE	UNITS	Benzene	Benzene	Reduction	Diesel	Diesel	Reduction	Ethylbenzene	Ethylbenzene	Reduction	Gasoline	Gasoline	Reduction	Oil	Oil	Reduction	Toluene	Toluene	Reduction	Xylenes	Xylenes	Reduction
	2002 Averages	μg/L	225.3	14.3	91%	7,315	7,020	NA	55.2	6.2	75%	1,770	336	82%	831	804	NA	17.0	2.5	88%	88.8	9.9	87%
	2003 Averages	μg/L	137.7	19.5	76%	4,945	4,648	NA	44.5	12.9	69%	1,854	678	62%	760	763	NA	42.7	5.4	61%	154.1	50.3	68%
	2004 Averages	μg/L	93.5	3.2	82%	10,285	9,342	NA	76.8	4.7	79%	4,383	840	59%	762	1,026	NA	116.6	2.2	82%	356.6	23.0	75%
	2005 Averages	μg/L	76.7	14.5	84%	4,162	5,987	NA	170.8	45.4	81%	10,090	3,229	70%	864	750	NA	566.9	121.0	84%	1,327.7	367.9	78%
	2006 Averages	μg/L	38.9	1.2	89%	11,263	2,174	NA	42.1	0.9	90%	4,944	202	94%	665	666	NA	55.6	8.0	77%	485.1	5.2	96%
	2007 Averages	μg/L	8.8	1.5	60%	1,223	906	NA	6.6	0.8	56%	407	115	63%	598	598	NA	1.0	0.5	21%	19.8	1.9	50%
	2008 Averages	μg/L	10.0	1.1	70%	540	468	NA	5.5	0.7	39%	279	76	61%	505	504	NA	0.7	0.5	40%	10.6	1.6	65%
	2009 Averages	μg/L	5.2	1.0	48%	369	561	NA	4.1	1.6	31%	407	182	46%	497	489	NA	0.8	0.7	44%	15.2	7.4	33%
	2010 Averages	μg/L	3.9	0.7	76%		2,193	NA	6.8	1.7	78%	915	336	65%		410	NA	0.9	0.9	NA	26.3	6.7	69%
	2011 Averages	μg/L	3.2	0.5	80%	1	1,714	NA	2.4	1.0	53%	439	89	69%	1	492	NA	1.0	1.0	NA	7.1	3.0	29%
	2012 Averages	μg/L	3.6	1.3	48%	1	2,787	NA	1.9	1.2	37%	362	144	61%	1	636	NA	1.0	1.0	NA	5.7	3.4	48%
	2013 Averages	μg/L	1.0	0.5	45%		1,333	NA	1.1	0.5	49%	356	124	57%		433	NA	0.5	0.5	NA	2.4	1.0	78%
	2014 Averages	μg/L	1.7	0.3	61%		1,699	NA	0.6	0.3	46%	539	122	79%		236	NA	0.5	0.3	NA	1.5	0.5	61%
	2015 Averages	μg/L	2.3	0.4	66%		5,175	NA	1.6	0.4	60%	1,146	406	64%		396	NA	0.5	0.4	NA	2.8	0.5	74%
	2016 Averages	μg/L	2.2	0.6	76%		2,292	NA	2.3	0.5	81%	1,282	582	50%		248	NA	0.4	0.4	NA	2.9	1.0	62%
	2017 Averages	μg/L	1.9	0.4	74%		4,325	NA	1.0	0.4	63%	1,421	641	56%		349	NA	0.5	0.4	NA	1.0	0.7	55%
	2018 Averages	μg/L	1.1	0.7	60%		1,673	NA	0.7	0.7	7%	359	136	62%		346	NA	0.5	0.5	NA	1.3	0.9	30%
	2019 Averages	μg/L	0.5	0.4	50%		1,539	NA	0.7	0.7	NA	231	68	60%		584	NA	0.7	0.7	NA	2.0	2.0	NA
	2020 Averages	μg/L	0.7	0.5	NA		588	NA	1.0	1.0	NA	100	51	65%		750	NA	1.0	1.0	NA	3.0	3.0	NA
	2021 Averages	μg/L	1.6	0.5	NA		756	NA	1.0	1.0	NA	110	50	NA		750	NA	1.0	1.0	NA	3.3	3.0	NA
	2022 Averages	μg/L	1.0	0.5	NA		378	NA	1.0	1.0	NA	95	50	NA		750	NA	1.0	1.0	NA	3.0	3.0	NA
	2023 Averages	μg/L	0.9	0.5	NA		482	NA	1.0	1.0	NA	86	50	NA		750	NA	1.0	1.0	NA	3.0	3.0	NA
	2024 Averages	μg/L	1.4	0.5	NA		1056	NA	1.0	1.0	NA	74	50	NA		693	NA	1.0	1.0	NA	1.2	1.2	NA
	1/30/2025	μg/L	0.6	0.5	15%	1	980	NA	1.0	1.0	NA	89	50	44%	1	750	NA	1.0	1.0	NA	1.0	1.0	NA
	2/20/2025	μg/L	0.5	0.5	0%		310	NA	1.0	1.0	NA	50	50	0%		750	NA	1.0	1.0	NA	1.0	1.0	NA
	3/25/2025	μg/L	0.5	0.5	0%		250	NA	1.0	1.0	NA	50	50	0%		750	NA	1.0	1.0	NA	1.0	1.0	NA
	4/24/2025	μg/L	0.5	0.5	0%		370	NA	1.0	1.0	NA	50	50	0%		750	NA	1.0	1.0	NA	1.0	1.0	NA
1	5/22/2025	μg/L	0.5	0.5	0%	l	250	NA	1.0	1.0	NA	50	50	0%	l	750	NA	1.0	1.0	NA	1.0	1.0	NA
	6/19/2025	μg/L	0.5	0.5	0%		250	NA	1.0	1.0	NA	50	50	0%		750	NA	1.0	1.0	NA	1.0	1.0	NA
——	2025 Averages	μg/L	0.5	0.5	NA		401.7	NA	1	1	NA	57	50	NA	40.000 #	750	NA	1	1	NA	1	1	NA
	SURFACE WATER CLEAR		71 μg/L			10,000 μg/L			NA			1,000 µg/L			10,000 μg/L			NA			NA		
	KCDNR DISCHA	ARGE LIMITS		70 µg/L		l	100,000 µg/L		ı	1.700 ua/L		I	NA		l	100,000 µg/L			1,400 µg/L			2,200 µg/L	

IETRO	DISCHA	ARGE	DATA

	Maximum permitted GPM:	TOTALS: 10.4	33,930,444 gal Gallons Gas, Diesel, 8	13.4	963.1 156.6	1667.2 238.9	184.0 24.1	34.8	14.8	101.3 Recovered:	419.57
2025 Totals and Averages	1/0	0.32	76,420	0.000	0.050	0.778	0.495	0.001	0.001	0.001	0.18
June-25	28 170	0.17	6,690	0.0000	0.00	0.01	0.04	0.0001	0.0001	0.0001	0.01
May-25		0.16	6,310	0.0000	0.00	0.02	0.04	0.0001	0.0001	0.0001	0.01
April-25		0.34	14,570	0.0001	0.01	0.04	0.09	0.0001	0.0001	0.0001	0.02
March-25		0.32	15,130	0.0001	0.01	0.04	0.09	0.0001	0.0001	0.0001	0.02
February-25		0.46	13,970	0.0001	0.01	0.08	0.09	0.0001	0.0001	0.0001	0.02
January-25		0.46	19,750	0.0001	0.02	0.60	0.14	0.0002	0.0002	0.0002	0.11
2024 Totals and Averages		0.72	379,000	0.003	0.29	3.49	2.35	0.003	0.003	0.006	0.86
2023 Totals and Averages		0.91	495,900	0.005	0.42	1.87	3.10	0.004	0.004	0.012	0.74
2022 Totals and Averages		0.90	486,520	0.004	0.37	1.64	3.04	0.004	0.004	0.012	0.69
2021 Totals and Averages		1.01	510,230	800.0	0.47	3.72	3.19	0.004	0.004	0.014	1.03
2020 Totals and Averages		1.06	572,320	0.003	0.46	2.70	3.58	0.005	0.005	0.014	0.93
2019 Totals and Averages		1.26	611,500	0.002	1.30	8.72	2.89	0.003	0.003	0.009	1.84
2018 Totals and Averages		1.20	641,740	0.006	2.16	9.61	1.79	0.002	0.004	0.007	1.96
2017 Totals and Averages	364	1.65	866,030	0.014	11.96	33.39	2.62	0.004	0.01	0.01	7.07
2016 Totals and Averages	370	1.90	999,770	0.022	13.87	22.12	2.06	0.004	0.03	0.03	5.70
2015 Totals and Averages	358	1.71	874,680	0.015	6.56	36.53	2.92	0.004	0.01	0.02	6.68
2014 Totals and Averages	332	1.62	761,480	0.010	3.43	10.95	1.55	0.003	0.00	0.01	2.33
2013 Totals and Averages	365	1.33	700,450	0.014	2.26	8.80	3.43	0.003	0.01	0.02	2.08
2012 Totals and Averages	371	1.89	948,600	0.034	3.97	25.92	3.47	0.01	0.02	0.04	4.81
2011 Totals and Averages	356	1.90	949,880	0.026	5.13	17.55	3.54	0.01	0.03	0.13	3.81
2010 Totals and Averages	372	2.17	1,185,127	0.037	8.62	18.84	4.26	0.01	0.05	0.19	4.66
2009 Totals and Averages	369	2.98	1,569,390	0.07	5.75	7.81	6.40	0.01	0.06	0.22	2.89
2008 Totals and Averages	363	3.19	1,645,810	0.14	3.95	7.21	6.95	0.01	0.08	0.15	2.59
2007 Totals and Averages	360	3.17	1,599,607	0.15	9.08	18.30	8.40	0.02	0.11	0.48	5.20
2006 Totals and Averages		6.40	3,220,733	0.80	192.72	663.65	19.09	2.85	1.89	20.04	128.92
2005 Totals and Averages		11.17	5,827,144	3.43	447.43	155.78	41.55	25.29	7.69	59.98	100.52
2004 Totals and Averages		9.58	4,570,461	3.54	175.70	419.25	28.95	5.35	3.16	14.66	92.43
2003 Totals and Averages		8.03	4,114,867	4.43	62.20	169.14	26.05	1.18	1.47	5.05	37.76
2002 Totals and Averages	- U	4.18	322,785	0.62	4.99	19.42	2.30	0.05	0.13	0.22	3.90
Observation Date		(GPM)	(gallons, GW)	Removed	Removed	Removed	Removed	Removed	Removed	Recovered	(dissolve
	Days since last monitoring	Average flow	Observation dates	Benzene	Gasoline	Pounds of Diesel	Oil	Toluene	Ethylbenzene	Xylenes	and Oil
			Total Flow Between	Pounds of	Pounds of		Pounds of	Pounds of	Pounds of	Pounds of	Total Gallo Gas. Dies

Oil Water Separator Data	
Observation Date	Monthly free LNAPL Recovery (gal)
February-03	19.6
April-03	6.9
May-03	2.5
July-03	2
December-03	20
January-04	25
June-04	35
August-04	50
September-04	8
November-04	10
December-04	3.5
January-05	0
February-05	35
July-05	110
February-06	5
March-06	2
December-06	30
March-08	30
Total Gallons free LNAPL R	Recovered: 395

TOTAL PETROLEUM RECOVERY Total lbs. Dissolved Gas, Diesel, and Oil Recovered in Groundwater (2002-Present) 2,814 lbs Total Gallons Dissolved Gas, Diesel, and Oil Recovered in Groundwater (2002-Present)* 420 gal Total Gallons LNAPL Recovered by Final Recovery System (2002-Present) Total Gallons LNAPL Recovered by Interim Recovery System (1992-2002) Total Gallons of TPH Vapor Recovered by Final SVE System (2003-2008)** 395 gal 9,312 gal 2,334 gal Total Gallons of TPH Vapor Recovered by Interim SVE System (1996-2002)** 1,248 gal Total Gallons TPH Recovered from Final SVE System due to Biodegradation (2003-2008)*** 11,411 gal Total Gallons TPH Recovered from Interim SVE System due to Biodegradation (1996-2002)*** 4,664 gal 14,560 gal Total Gallons Recovered by Final Recovery Systems (2002-Present) Total Gallons Recovered by Interim Recovery Systems (1992-2002) Total Gallons of Petroleum Removed (1992-Present) 15,223 gal

Definitions

gal - gallons GPM - Gallons per minute

NA - Not available or could not be calculated due to non-detection

LNAPL - Light non-aqueous phase liquid (oil)

SVE - Soil vapor extraction

TPH - Total petroleum hydrocarbons

μg/L - micrograms per liter GW - Groundwater

LNAPL recovery is recorded periodically when sufficient product has been accumulated to be transported off-site for disposal.

Influent diesel and oil samples are no longer analyzed. Influent and effluent samples are collected before and after, respectively, a diffused air stripper, which does not remove diesel or oil.

Effluent sample data are representative of the outflow water to King County Metro sanitary sewer.

The average µg/L of the preceding month and the month of reference are used to calculate pounds of compound removed.

Data presented in italicized text represent non-detections. The listed italicized value is the laboratory reporting limit

If influent concentrations are below the laboratories reporting limit, the percent reduction is calculated using the reporting limit. The actual percent reduction is ≥ the reported value.

* Calculation of lbs. of Recovered Product:

To convert μ g/L to lbs./gallon - (μ g/L)x(3.785l/gal)=ug/gal, (ug/gal)x(ug/(2.2046x10-9lbs))=lbs./gal

lbs./gal of chemical constituent x total gallons recovered =lbs. of chemical recovered

Density of Gasoline utilized for conversions from pounds to gallons is 6.15 lbs./gal Density of Diesel utilized for conversions from pounds to gallons 6.98 lbs./gal

Density of Oil utilized for conversions from pounds to gallons 7.63 lbs./gal

Benzene, toluene, ethylbenzene, and xylenes volumes are not included in the Total Gallons calculations, as they are assumed to be included in TPH as gasoline.

** *** SVE Recovery Calculations for TPH and Biodegradation, which are maintained in separate tables.

C = Average Influent TPH concentration (ppmv) Q = Influent Flow Rate (SCFM)

Mc = Molecular wt. of Carbon Dioxide = 44

Mg = Molecular wt. of Gasoline = 87

Density of Gasoline for conversions is 6.15 lbs./gal

** TPH recovered by SVE system was calculated in lbs./hr. = C x Q x Mg x 1.583 x 10^{-7} 1.583 x 10^{-7} is a constant and is derived as follows:

 10^{-6} ppmv x 60min/1hr x 1 lb. Mole/379 cu.ft. SVE TPH recovery calculations are based on TPH concentrations in the SVE stream. SVE hrs. of operation, and SVE measured flow rates.

Table 2. Groundwater/LNAPL Recovery Well Performance Monitoring

June 2025

Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

Well	Date	Measurable LNAPL (>0.01')	Sheen on Groundwater (None, SS, MS, HS)	TPH-G NWTPH-Gx (mg/L)	TPH-D NWTPH-Dx (mg/L)	TPH-O NWTPH-Dx (mg/L)	Benzene EPA 8021 (μg/L)
RW-1	6/24/2025	No	NS	0.097	ND	ND	ND
RW-2	6/24/2025	No	SS	0.24	3.4	ND	8.9
RW-4	6/24/2025	No	MS	0.81	8.5	ND	72
RW-5	6/24/2025	No	NS	ND	0.27	ND	ND
RW-6	6/24/2025	No	NS	ND	ND	ND	ND
RW-7	6/24/2025	No	NS	ND	ND	ND	ND
RW-8	6/24/2025	No	NS	ND	0.40	ND	ND
RW-9	6/24/2025	No	NS	ND	1.8	ND	ND
RW-10	6/24/2025	No	NS	ND	ND	ND	ND
GM-11S	6/25/2025	No	SS	1.4	8.4	1.6	0.57
Cleanup Leve	el	No (<0.01')	No Sheen*	1*	10*	10*	71*
Method Repo	rting Limit			0.05	0.25	0.75	0.5

Notes

Definitions:

EPA 8021 EPA method of analysis for volatile organic compounds in water.

mg/L Milligrams per liter. μ g/L Micrograms per liter.

ND Constituent not detected above reporting limit. A less than sign (<) preceeding a value indicates a ND at the listed value.

TPH Total petroleum hydrocarbons.

TPH-D Total petroleum hydrocarbons as diesel.

TPH-G Total petroleum hydrocarbons as gasoline.

TPH-O Total petroleum hydrocarbons as oil.

NWTPH-Dx Northwest TPH method for analysis of diesel in water - extended.

NWTPH-Gx Northwest TPH method for analysis of gasoline in water - extended.

SS Slight sheen observed on groundwater.

MS Meduim sheen observed on groundwater.

HS Heavy sheen observed on groundwater.

^{*} Listed cleanup levels and values in **bold** that exceed these levels are applicable at points of compliance (POCs).

Recovery wells are not POCs for parameters with a " * " and values above listed cleanup levels are not recognized as exceedances.

Table 3. Groundwater Performance Monitoring Schedule

Site: SeaPort Seattle Terminal (Former ARCO/ BP Harbor Island Terminal)

Analyses Conducted by Quarter

Well	First Quarter	Second Quarter	Third Quarter	Fourth Quarter
Plant 1	1 list Quarter	Occoria Quarter	Tillia Quartor	1 outil Quarter
1 Idill 1	Benzene, TPH-G,		Benzene, TPH-G,	
MW-1-T9	TPH-D, TPH-O	(1)	TPH-D, TPH-O	(1)
	Benzene, TPH-G,	(.)	Benzene, TPH-G,	(· /
MW-2-T9	TPH-D, TPH-O	(1)	TPH-D, TPH-O	(1)
	Benzene, TPH-G,	` ,	Benzene, TPH-G,	` ,
MW-3-T9	TPH-D, TPH-O	(1)	TPH-D, TPH-O	(1)
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,
GM-14S	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O
	Benzene, TPH-G,		Benzene, TPH-G,	
GM-15S	TPH-D, TPH-O	(1)	TPH-D, TPH-O	(1)
	Benzene, TPH-G,		Benzene, TPH-G,	
GM-16S	TPH-D, TPH-O		TPH-D, TPH-O	
	Benzene, TPH-G,		Benzene, TPH-G,	
GM-17S	TPH-D, TPH-O		TPH-D, TPH-O	
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,
GM-24S	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O
	Benzene, TPH-G,		Benzene, TPH-G,	_
AR-03	TPH-D, TPH-O	(1)	TPH-D, TPH-O	(1)
				Benzene, TPH-G,
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	TPH-D, TPH-O,
AMW-01	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	cPAHs
				Benzene, TPH-G,
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	TPH-D, TPH-O,
AMW-02	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	cPAHs
				Benzene, TPH-G,
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	TPH-D, TPH-O,
AMW-03	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	cPAHs
				Benzene, TPH-G,
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	TPH-D, TPH-O,
AMW-04	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	cPAHs
				Benzene, TPH-G,
	Benzene, TPH-G,	Benzene, TPH-G,	Benzene, TPH-G,	TPH-D, TPH-O,
AMW-05	TPH-D, TPH-O	TPH-D, TPH-O	TPH-D, TPH-O	cPAHs
Plant 2				

Plant 2

All Plant 2 monitoring has been discontinued.

Notes: Field Duplicate and QA/QC samples collected from wells highlighted in bold.

TPH-G - Gasoline Range organics utilizing NWTPH-Gx method

TPH-D - Diesel Range Organics utilizing NWTPH-Dx

TPH-O - Extended Range Organics (Motor Oil) utilizing NWTPH-Dx

Benzene is analyzed for utilizing EPA 8021 or 8260B.

cPAHs - Carcinogenic Polycyclic Aromatic Hydrocarbons utilizing EPA 8270SIM Field Parameters (pH, Temperature, Conductivity, Turbidity, Water Level, & Product Level) are recorded from all wells sampled

(1) - If a groundwater cleanup level exceedance occurs in first or third quarter in any of these highlighted wells, all (1) wells will be sampled the following quarter. Wells exceeding cleanup levels will continue quarterly monitoring until four consecutive quarters below cleanup level are achieved.

Table 4. Groundwater Performance Monitoring Groundwater Elevations
First Quarter 2025
Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

Well	Date	TOC Elevation (ft NAVD88)	Depth to Water (ft below TOC)	Groundwater Elevation (ft NAVD88)
Plant 1				
GM-14S	3/19/2025	11.77	3.52	8.25
GM-15S	3/18/2025	12.32	4.56	7.76
GM-16S	3/19/2025	11.99	4.04	7.95
GM-17S	3/19/2025	12.56	3.72	8.84
GM-24S	3/19/2025	11.11	2.48	8.63
AR-03	3/18/2025	12.49	5.26	7.23
AMW-01	3/18/2025	12.17	5.68	6.49
AMW-02	3/18/2025	15.36	7.74	7.62
AMW-03	3/18/2025	15.29	7.62	7.67
AMW-04	3/18/2025	11.42	7.76	3.66
AMW-05	3/18/2025	11.05	6.28	4.77
MW-1-T9	3/19/2025	12.21	5.01	7.20
MW-2-T9	3/19/2025	12.37	4.75	7.62
MW-3-T9	3/19/2025	11.87	4.41	7.46

Definitions:

ft Feet

NA Not available. Well elevations have not been surveyed.

NAVD88 North American Vertical Datum of 1988

TOC Top of casing

Table 5. Summary of Analytical Results for Groundwater - TPH-G, TPH-D, TPH-O, and Benzene

First Quarter 2025

Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

Well	Date	TPH-G NWTPH-Gx (μg/L)	TPH-D NWTPH-Dx (μg/L)	TPH-O NWTPH-Dx (μg/L)	Benzene EPA 8260 (μg/L)
Plant 1	0/40/0005			5	
GM-14S	3/19/2025	1,100	790	ND	920
GM-15S	3/18/2025	ND	ND	ND	ND
GM-16S	3/19/2025	ND	300	ND	ND
GM-17S	3/19/2025	ND	ND	ND	ND
GM-24S	3/19/2025	520 J	340 J	ND	ND
AR-03	3/18/2025	86	860	ND	ND
AMW-01	3/18/2025	ND	ND	ND	ND
AMW-02	3/18/2025	ND	ND	ND	ND
AMW-03	3/18/2025	ND	ND	ND	ND
AMW-04	3/18/2025	ND	ND	ND	ND
AMW-05	3/18/2025	ND	ND	ND	ND
MW-1-T9	3/19/2025	ND	ND	ND	ND
MW-2-T9	3/19/2025	78	ND	ND	ND
MW-3-T9	3/19/2025	720	250	ND	0.84
Cleanup Level		1,000	10,000	10,000	71
Method Reportin	g Limit	50	250	750	0.5

Notes:

Values in **bold** exceed the cleanup level.

Definitions:

EPA 8260	EPA method of analysis for volatile organic compounds in water.
μg/L	Micrograms per liter.

ND Constituent not detected above listed method reporting limit.

TPH Total petroleum hydrocarbons.

TPH-D Total petroleum hydrocarbons as diesel.
TPH-G Total petroleum hydrocarbons as gasoline.

TPH-O Total petroleum hydrocarbons as oil.

NWTPH-Dx Northwest TPH method for analysis of diesel in water - extended.

NWTPH-Gx Northwest TPH method for analysis of gasoline in water - extended.

J Estimated value.

UJ Not detected at an estimated value.

Table 6. Summary of Free Product Measurement Results for Groundwater 2025 Monitoring Data
Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

Well	Date	Free Product (feet)
Plant 1		
GM-11S	1/30/2025	None
GM-11S	2/20/2025	None
GM-11S	3/27/2025	None
GM-11S	4/24/2025	None
GM-11S	5/22/2025	Slight Sheen
GM-11S	6/19/2025	Slight Sheen
GM-12S	1/30/2025	None
GM-12S	2/20/2025	None
GM-12S	3/27/2025	None
GM-12S	4/24/2025	None
GM-12S	5/22/2025	None
GM-12S	6/19/2025	None
GM-13S	1/30/2025	None
GM-13S	2/20/2025	None
GM-13S	3/27/2025	None
GM-13S	4/24/2025	None
GM-13S	5/22/2025	None
GM-13S	6/19/2025	None
Cleanup Level		No Sheen

Notes: Values in **bold** exceed the cleanup level.

Table 7. Summary of Data Validation Results
Groundwater Performance Monitoring

First Quarter 2025

Site: SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)

Sample ID	Constituent	Qualifier	Reason
P1-GWGM-24S-125	Gasoline	J	Field duplicate RPD exceeds acceptance criteria.
P1-GWGM-224S-125	Gasoline	J	Field duplicate RPD exceeds acceptance criteria.
P1-GWGM-24S-125	Diesel	J	Field duplicate RPD exceeds acceptance criteria.
P1-GWGM-224S-125	Diesel	J	Field duplicate RPD exceeds acceptance criteria.

Definitions:

J The associated result is qualified as an estimated value.


RPD Relative Percent Difference

UJ The associated result is qualified as undetected at an approximate quantitation limit.


FIGURES

- 1. Site Location Map
- 2. Plant 1 First Quarter 2025 Groundwater Monitoring Analytical Results & Contours





AREA PLAN



SITE PLAN



Site Location Map

SeaPort Seattle Terminal (Former ARCO/BP Harbor Island Terminal)
1652 Southwest Lander Street
Seattle, WA 98134

