

INITIAL INVESTIGATION

SITE NAME: Chempro Kent
ADDRESS: 20245 77 th Ave S., Kent
INSP. DATE: 5/7/91
INSP. NAME: John Stormon

An initial investigation was conducted at Chempro Kent on 5/7/91 by John Stormon. Richard Lee, the plant manager, told me that the tanks were removed and that all the contaminated soil was excavated and removed from the site. All remediation work on site is complete, the excavation has been backfilled and the cleanup report was forwarded to the UST unit in Olympia. A copy of the final cleanup report will be sent the NWRO in Bellevue as soon as copies of the photographs can be made.

STATUS: Tanks removed / Cleanup Complete awaiting Report

PHOTO No. 7

CHEMPRO KENT

DATE: 5/7/91

TIME: _____

TAKEN BY: STORMON

WITNESS: _____

FILM: 9404

CAMERA: E111304



DESCRIPTION:

ASPHALT PATCH

OVER TANK EXCAVATION,

WEST SIDE OF OFFICE

COMMENTS:

PHOTO No. _____

DATE: _____

TIME: _____

TAKEN BY: _____

WITNESS: _____

FILM: _____

CAMERA: _____

DESCRIPTION:

COMMENTS:
