SHARP Report — Part 1 of 2



• SHARP first SHARP		v2024.04.29	Ecology	/ Info
 SHARP rating 	Low		ERTS	none
• SHARP date	08/26/2025		CSID	788
• EJFlagged?	🛇 - No Override		FSID	2065
 LD confidence level 	medium		VCP	none
 Cleanup milestone 	periodic review		UST ID	none
• SHARPster	Chris DeBoer		LUST ID	none

This sec	ction is	blank i	f this is	the f	irst SHARP
11113 366	JUUII IS	Dialini	เนแจเจ	uic i	

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	B2	low	multiple chemical types	~
Groundwater	C1	high	risk to off-site people	\Diamond
Surface water	D4	low	climate change impacts	✓
Sediment	D4	medium	plant/animal tissue data	\Diamond
Soil	C1	medium		

Location and land use info

1400 N 4th St, Renton, King County, 98057

Primary parcel 7223000010

Land use industrial

Responsible unit NWRO

Sources reviewed

Haley Aldrich, 2023 Groundwater and Surface Water Monitoring, PACCAR Renton Site, June 18, 2024

Dalton, Olmsted & Fuglevant, Inc. Confirmational Monintoring and Inspection Plans, Former PACCAR Defense Systems Site, November 1997

HartCrowser, Remedial Investigation Report, PACCAR Site, September 1, 1989



	SHARP
Associated census tracts	
mments	

Source/source area description	
Sources of contamination at the Site include industrial fill; Dies and solvents in above-and below-ground storage tanks, transforce contamination was identified on property and groundwater contamination.	ormers, and galvenizing operations. Soil
Soil comments	
no comments	
lio comments	

no comments

Groundwater comments



	7.10.1
Surface water comments	
The site's Consent Decree considers stormwater at the site as surface water.	
Sediment comments	
no comments	
Indoor air comments	
no comments	
Additional factors comments	
no comments	



	Site history <u>Go to top</u>
	Industrial operations at the property resulting in contamination included rail car and tank manufacturing and
occupied by a truck manufacturing facility.	were conducted from 1907 to 1988. Those facilities were decomissioned in 1988 and the property is currently
	occupied by a truck manufacturing facility.



Overflow - Site contamination and cleanup history	
lditional parcels: 0823059170, 0886610070	

788 Pacific Car & Foundry Co 20250826

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 08/26/2025



