

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP	v2024.04.29	Ecology I	nfo
 SHARP rating 	Low	ERTS	none
 SHARP date 	09/25/2025	CSID	1325
EJFlagged?	🛇 - No Override	FSID	2194
 LD confidence level 	medium	VCP	none
 Cleanup milestone 	post-cleanup controls & monitoring	UST ID	none
• SHARPster	John Rapp	LUST ID	none

This section is	blank if	this is the	first SHARP
-----------------	----------	-------------	-------------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	0
Groundwater	C3	medium	risk to off-site people	\otimes
Surface water	D4	medium	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	\otimes
Soil	C2	medium		

Location and land use info

Sources reviewed

1401 and 1451 Northwest 46th Street, Seattle, King County,

Primary parcel SHARP it
Land use commercial
Responsible unit NWRO

Wesmar Final Cleanup Action Report
Revised Cleanup Action Plan
Wesmar Company, Inc. Final RI, FS, and Proposed Cleanup Action



wesinal Company, inc.	SHARP
Primary census tract	Associated census tracts
4700	
Local demographics co	mments
A zero was applied to all EJScr	een parameters because the EJScreen website was not available at the time of
rating	
Source/source area des	•
The historical use of the Property as a wood treatment facility for the City of Seattle. The historical presence of	
numerous railways located or 45th Street is considered a	or adjacent to the Property. A rail line running along the north side of Northwest
	the Property. The heavy industrial activities historically conducted in the North
15	gulated fill material beneath the Property and vicinity.
billion area. The age of armes	Guidea in material beneath the Froperty and vienney.
Soil comments	
no comments	
ino comments	
0	
Groundwater comments	3
no comments	



Surface water comments
no comments
Sediment comments
no comments
Indoor air comments
no comments
Additional factors comments
no comments



Site history Go to top

Based on information reviewed in the course of this investigation, it appears that the original grade of the Property was approximately 11.5 feet below the current surrounding street grade. By 1889, the ROWs surrounding the Property had been deeded to the City of Seattle. By 1903, the grade of the Property and surrounding streets had been raised to the current foundation grade of the former Wesmar Building, which was constructed in 1905, when Pacific Coast Pipe Co. and City Electric Light and Waterworks occupied the Property. The surrounding streets were raised to their current elevation during a subsequent regrading event that occurred in 1913. In 1917, the eastern portion of the Property was used for the storage of pipes treated by the Pacific Coast Pipe Co. The pipe treatment facility appeared to operate on the Property until 1947, when Durabilt Luggage Co. constructed the former ColorTech building, and in 1950, R.D. Bodle Fruit and Vegetable Cannery operated on the Property. The most recent occupants, Wesmar and Colortech, occupied the Property between 1979 and 2007.



Overflow -	Site contamination and cleanup history
No overflow	

1325 Wesmar Company, Inc. 20250925

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 09/25/2025



