



• SHARP first SHARP		v2024.04.29	Ecology Info	
• SHARP rating	Low		ERTS	647106, 601862
• SHARP date	09/24/2025		CSID	4944
• EJFlagged?	SHARP it		FSID	543
• LD confidence level	low		VCP	NA
• Cleanup milestone	cleanup completion/NFA		UST ID	503227
• SHARPster	John Mefford		LUST ID	5334

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	medium	multiple chemical types	⊗
Groundwater	D4	high	risk to off-site people	⊗
Surface water	D4	high	climate change impacts	⊗
Sediment	D4	high	plant/animal tissue data	⊗
Soil	D4	high		

Location and land use info	
1802 S. 1st St., Yakima, Yakima County, 98903	
Primary parcel	191331-11012
Land use	commercial
Responsible unit	CRO

Sources reviewed
Tidricks Quality Transmission Remedial Investigation, PLSA, May 26, 2015



Primary census tract	Associated census tracts
53077001400	NA

Local demographics comments
no comments

Source/source area description
<p>The release(s) occurred from a waste oil UST and from two drywells. These two drywells were in operation for at least 20 years. Petroleum hydrocarbons, including waste oil, and their associated constituents were initially believed to have impacted soil and groundwater.</p>

Soil comments
no comments

Groundwater comments
no comments



Surface water comments
no comments

Sediment comments
no comments

Indoor air comments
no comments

Additional factors comments
no comments

Site history

[Go to top](#)

Ecology received a complaint of oil dumping at the facility in 1992. At that time, the facility was associated with Carlos Motors. Prior to that time, from the 1960s through 1978, the facility was part of a car dealership. Beginning in 1993, Tidrick's Quality Transmission occupied the property. In 1994, a cleanup action was performed which consisted of removal of the three USTs and excavation of petroleum-contaminated soils near the waste oil UST and the two drywells. Subsequent sampling showed that the MTCA cleanup standards were met.



Overflow - Site contamination and cleanup history

No overflow



Assessment scores by environmental medium

