



GEOLOGIC LOG
B1




GEOLOGIC LOG
B2




(NOTE: REFUSAL AT 30')


GEOLOGIC LOG B3




GEOLOGIC LOG B4




GEOLOGIC LOG
B5




GEOLOGIC LOG
B6




GEOLOGIC LOG B7




GEOLOGIC LOG B8




GEOLOGIC LOG
B9




GEOLOGIC LOG
B10




GEOLOGIC LOG
B11




GEOLOGIC LOG
B12




GEOLOGIC LOG B13




GEOLOGIC LOG
B14




GEOLOGIC LOG B15




GEOLOGIC LOG B16



GEOLOGIC LOG
B17



GEOLOGIC LOG
B18



GEOLOGIC LOG
B19

