

























TRUCK CITY TRUCK STOP

Photos from film #1403

Pic #	Date	Description
2	7/27/92	Pumping all liquid from the tanks prior to removal.
3	7/27/92	Drain line from fill cap drains to east.
4	7/27/92	Drain line from fill cap. (same as pic. #3)
5	7/28/92	South tank nest / Tanks exposed ready for inerting.
6	7/28/92	Removing overburden from north tank nest.
7 & 8	7/28/92	New power pole being installed to allow excavation of contaminated soil.
9	7/28/92	North tank nest ready for inerting.
10&11	7/28/92	Inerting tanks.
12&13	7/29/92	Removing first tank.
14	7/29/92	Tank #2.
15	7/29/92	Three tanks from south excavation.
16&17	7/29/92	First tank north tank nest.
18	7/29/92	Second tank north tank nest.
19	7/29/92	Third tank north tank nest.
20	7/29/92	North tank excavation.
21	7/29/92	Removing old power pole.
22	7/29/92	Excavation of contaminated soil.
23	7/29/92	Cutting tanks to allow cleaning for safe transport.
24	7/30/92	North excavation continues to grow.