

**Photo No. 1**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
View of old  
greenhouses  
from the driveway.



**Photo No. 2**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Overgrown old  
greenhouses.



**Photo No. 3**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island

**Comments:**  
King County  
Landmark sign  
showing years of  
operation -  
1888-1989.



**Photo No. 4**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island

**Comments:**  
Large tank,  
probably for water  
storage.



**Photo No. 5**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Dirt pile surrounded  
by blackberries. No  
odor.



**Photo No. 6**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Old water  
reservoir, with  
wetland plants grow-  
ing in it.



**Photo No. 7**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island

**Comments:**  
Old buildings  
being used as  
residences, with  
raised-bed  
vegetable  
garden  
in-between.



**Photo No. 8**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
More overgrown  
greenhouses.



**Photo No. 9**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Debris pile in  
back of property.



**Photo No. 10**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Old abandoned  
truck and  
greenhouse.



**Photo No. 11**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island

**Comments:**  
Drum in back  
of property.  
Small area of petroleum  
stained soil.



**Photo No. 12**  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island

**Comments:**  
Tank in back  
of property.  
Contents unknown.



**Photo No.** 13  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Pile of dug-up  
soil. No odor.



**Photo No.** 14  
**Date:** 10-16-97  
**Taken by:**  
J. Polayes  
**Witness:**

**Location:**  
Harrington-Beall  
Greenhouses  
Vashon Island  
**Comments:**  
Greenhouses  
viewed from the  
street.

