

## Pasco School District No. 1 High School Site

## **Toxics Cleanup Program**

# Review of Environmental Cleanup Document Available for Comment

The Pasco School District No. 1 High School site is located at 1108 N. 10<sup>th</sup> Avenue in Pasco, Franklin County, Washington (see Map on page 2). Petroleum contamination was found in soil at the site and cleanup actions were conducted. Ecology continues to monitor the effectiveness of the cleanup actions and developed a report called a Periodic Review.

Ecology conducts a "Periodic Review" at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment.

#### You are Invited to Comment

You are invited to review and comment on the Periodic Review which contains information about the site, the cleanup that was conducted, and the results of the monitoring conducted since cleanup began.

 Send your comments about the Periodic Review to Patti Carter at Ecology for consideration. Comments will be accepted September 15 through October 14, 2014. The shaded box at the right has details about where to review documents and submit comments.

## **Site Overview**

The Pasco High School was built in the early 1950s in a residential neighborhood of Pasco, Washington. Several expansions of the school have taken place along with a renovation in 1993.

A tank containing heating oil for the school was stored under an asphalt parking lot. The tank provided fuel for boilers that heated school buildings. The tank was removed in 2006. During the removal of the tank, petroleum contamination was found in soil.

Environmental investigations were conducted to evaluate the extent of contamination. Soil and groundwater were sampled and a limited amount of contaminated soil was found. Contaminated soil was removed and replaced with clean fill.

Some contaminated soil remains because it was located about 25 feet under the ground, and removing the soil could impact building structures. Groundwater was not impacted. An Environmental Covenant was placed on the property to limit how it may be used and to further protect the cleanup work done.

## September 2014

## **Comments Accepted**

#### September 15 through October 14, 2014

For **ADA** accommodations or documents in an alternate format call Carol Bergin 509/329-3546, 711 (relay service), or 877-833-6341 (TTY).

Para asistencia en Español

Gregory Bohn 509/454-4174

#### Submit Comments to

Patti Carter, Site Manager WA Department of Ecology Toxics Cleanup Program 4601 N. Monroe, Spokane WA 99205 509/329-3522 patti.carter@ecy.wa.gov

#### **Public Involvement Coordinator**

Carol Bergin See Ecology address above 509/329-3546 carol.bergin@ecy.wa.gov

#### **Document Review Locations**

#### WA Department of Ecology

Kari Johnson, Public Disclosure 4601 N. Monroe Spokane, WA 99205 Call for an appointment 509/329-3415

#### **Ecology's Toxics Cleanup Website**


https://fortress.wa.gov/ecy/gsp/ Sitepage.aspx?csid=353

Facility Site ID No. 14758414 Cleanup Site ID No. 353

## **What Happens Next?**

Ecology will review, consider, and respond to all comments received by **October 14, 2014.** 

Modifications to the delisting may be made if appropriate. If no modifications are made, the Periodic Review will become final.



## Site Map Pasco School District No. 1 Pasco High School

Publication Number: 14-09-028