

Maralco is a bankrupt, abandoned facility. It was a secondary aluminum smelter. Recycled aluminum cans were the primary feedstock. About 20,000 cubic yards of slag from the process, called black cross, remains at the facility. Bark operation in background. Date about 1993.





View of the east side of the building. The BNSF tracks have a spur going into the facility. Date about 1993.

