

**Location:** Brian Road site

**Photo #:** 1

**Date:** 3/28/05

**Time:** 9:30 am

**Taken by:** Steve Brown

**Witness:** Grant H.

**Film:** Digital

**Camera:** Sony Mavica



**Description:** 55 gallon drums found in overgrown brush. Counted 17, all appear full, contents unknown; possibly primer or industrial adhesive.

**Location:** same

**Photo #:** 2,3

**Date:** 3/28/05

**Time:** 9:30 am

**Taken by:** Steve Brown

**Witness:** Grant H.

**Film:** Digital

**Camera:** Sony Mavica



**Description:** Contents? of blue drum solidified, no odor. Lower photo of sticks and branches stuck to top of drum, black sticky substance on lid smells like model airplane glue.

Location: Brian Lane Site

Photo #: 1,2,3,4

Date: 3/18/05

Time: 12:30 pm

Taken by: Steve Brown

Witness: \_\_\_\_\_

Film: Digital

Camera: Sony Mavica



Description: Clockwise from upper left, MSW debris, tire pile, decaying structure, tractor trailer cab.

Location: same

Photo #: 5

Date: 3/18/05

Time: 12:30 pm

Taken by: Steve Brown

Witness: \_\_\_\_\_

Film: Digital

Camera: Sony Mavica



Description: MSW debris uncovered by recent landclearing activity. Photo taken in same area as Photo1.