

INITIAL INVESTIGATION FIELD REPORT

ERTS: direct list Parcel(s): 0320123063 County: Pierce

SITE INFORMATION

Site Name (e.g., Co. name over door): OPLC Tacoma Junction Facility	Site Address (including City and Zip+4): 2660 Frank Albert RD Fife, WA 98424	Site Phone:						
Site Contact and Title:	4): Site Contact Phone:							
Site Owner: Olympic Pipe Line CO c/o BP America INC	Site Owner Address (including City and Zip+4 POB 5015 Buena Park, CA 90622-5015	Site Owner Phone:						
Site Owner Contact:	Site Owner Contact Address (including City an	nd Zip+4): Owner Contact Phone:						
Alternate Site Name(s):	Comments:	Comments:						
Previous Site Owner(s):	Previous Site Owner(s): Comments:							
INSPECTION INFORMATION Inspection Conducted? Dat	al Degrees): 47.232616 mal Degrees): -122.368171 e/Time: Entry Notice: And	nounced Unannounced U						
Yes No No Photographs taken?	Yes 🛛 No 🗌							
Samples collected?	Yes No If Yes, be sure to incl	lude a figure/sketch showing sample locations.						
RECOMMENDATION								
No Further Action (Check appropria	LIST on Confirmed and Suspected Contaminated Sites List:							
Release or threatened release does	not pose a threat	Contaminated Sites List.						
No release or threatened release								
Refer to program/agency (Name:_								
COMPLAINT (Brief Summary of E	pleted (i.e., contamination removed) RTS Complaint):							
•	ered during facility upgrade project activities.							
CURRENT SITE STATUS (Brief S	ummary of why Site is recommended for <u>Listing</u> of	or <u>NFA</u>):						
	ntaminated soil was removed, analysis of soil sam carbon concentrations in excess of MTCA Method							
I recommend this site be listed on the	Confirmed and Suspected Contaminated Sites L	ist.						
Investigator: Robin Munroe		Date Submitted: 2 Dec 2015						

OBSERVATIONS

Description (please be sure to include the following: site observations, site features and cover, chronology of events, sources/past practices likely responsible for contamination, presence of water supply wells and other potential exposure pathways, etc.):

The site is an operating Olympic Pipe Line Company (OPLC) facility that has been in operation since 1965.

In August 2015 OPLC personnel detected petroleum odors and soil staining during excavation for a facility upgrade project. OPLC contracted Antea Group to collect soil and water samples for analysis to confirm the presence of petroleum hydrocarbons.

Sampling and laboratory analysis cited here are from the Antea Group Site Discovery and Independent Remedial Action Report, October 12, 2015.

Initial soil and water samples were collected from a trench excavation and from water that had ponded and accumulated within the affected area. Laboratory analysis indicated total petroleum hydrocarbons levels in excess of MCTA Method A Cleanup Levels.

Following the completion of the upgrade project the excavation was expanded laterally in all directions. Soil samples were collected from the sidewalls of the excavation limit. Field screening with a photoionization detector (PID) indicated the need for further soil removal.

The excavation was expanded to the maximum extent possible but the presence of onsite structures and increased water volume threatening sidewall stability prevented the removal of all impacted soil.

All soil excavated during the upgrade project was stockpiled and contained onsite pending additional soil removal for remedial action. A total of 302.49 tons of petroleum impacted soils and 1,200 gallons of water were transported to appropriate hazardous waste disposal facilities.

Laboratory analytical results of sidewall samples collected from the final limits of the excavation indicated petroleum hydrocarbon concentrations in the form of **TPH-G**, **TPH-D**, **benzene**, **ethylbenzene**, **and/or xylenes** in excess of the respective MTCA Method A Cleanup Levels remain at the limits of the excavation.

Based on the analytical results of soil samples taken at the site, it is confirmed that total petroleum hydrocarbons, benzene, ethylbenzene, and/or xylenes exist in concentrations exceeding MTCA Method A Cleanup Levels.

I recommend this site be listed on the Confirmed and Suspected Contaminated Sites List.

(fill in contaminant matrix below with appropriate status choice from the key below the table)

			VATER	VATER		5	
CONTAMINANT GROUP	CONTAMINANT	SOIL	SROUNDIWATER	SURFACE WATER	AIR	BEDROCK	DESCRIPTION
			5	ns			Compounds containing phenols (Examples: phenol; 4-
	Phenolic Compounds						methylphenol; 2-methylphenol)
	Non-Halogenated Solvents	RA .ca					Organic solvents, typically volatile or semi-volatile, not containing halogens, i.e., Chlorine, Iodine, Bromine or Fluorine. (Examples include acetone, benzene, toluene, ethylbenzene & xylenes [BTEX], methyl ethyl ketone, ethyl acetate, methanol, ethanol, isopropranol, formic acid, acetic acid, Stoddard solvent and naphtha)
	Polynuclear Aromatic Hydrocarbons (PAH)						Hydrocarbons composed of two or more benzene rings.
Non-Halogenated Organics	Tributyltin						The main active ingredients in biocides used to control a broad spectrum of organisms. Found in antifouling marine paint, antifungal action in textiles and industrial water systems. (Examples: Tributyltin; monobutyltin; dibutyltin)
	Methyl tertiary-butyl ether Benzene	Rica					MTBE is a volatile oxygen-containing organic compound that was formerly used as a gasoline additive to promote complete combustion and help reduce air pollution. Benzene
	Other Non-Halogenated Organics	A s					Other Non-Halogenated Organics (Example: Phthalates)
	Petroleum Diesel	CA					Petroleum Diesel
	Petroleum Gasoline	ĊΑ					Petroleum Gasoline
	Petroleum Other						Crude oil and any fraction thereof. Petroleum products that are not specifically Gasoline or Diesel.
Halogenated Organics (see notes at bottom)	PBDE						Polybrominated di-phenyl ether
	Other Halogenated Organics						Other organic compounds with halogens (chlorine, fluorine, bromine, iodine). Search HSDB (http://toxnet.nlm.nih.gov/cgibin/sis/htmlgen?HSDB) and look at the Chemical/Physical Properties, and Molecular Formula. If there is a CI, I, Br, F in the formula, it is halogenated. (Examples: Hexachlorobutadiene; hexachlorobenzene; pentachlorophenol)
	Halogenated solvents						Solvents containing halogens (Halogen is typically chlorine, but can also be fluorine, bromine, iodine), and their breakdown products (Examples: Trichloroethylene; Tetrachloroethylene (aka Perchloroethylene); TCE; TCA; trans and cis 1,2 dichloroethylene; vinyl chloride)
	Polychlorinated Biphenyls (PCB)						Any of a family of industrial compounds produced by chlorination of biphenyl, noted primarily as an environmental pollutant that accumulates in animal tissue with resultant pathogenic and teratogenic effects
	Dioxin/dibenzofuran compounds (see notes at bottom)						A family of more than 70 compounds of chlorinated dioxins or furans. (Examples: Dioxin; Furan; Dioxin TEQ; PCDD; PCDF; TCDD; TCDF; OCDD; OCDF). Do not use for 'dibenzofuran', which is a non-chlorinated compound that is detected using the semivolatile organics analysis 8270
	Metals - Other						Metals other than arsenic, lead, or mercury. (Examples: cadmium, antimony, zinc, copper, silver)
Metals	Lead			L			Lead
	Mercury						Mercury
- KLACOS, GOOGLO BARRON AND AND AND AND AND AND AND AND AND AN	Arsenic						Arsenic
Pesticides ,	Non-halogenated pesticides						Pesticides without halogens (Examples: parathion, malathion, diazinon, phosmet, carbaryl (sevin), fenoxycarb, aldicarb)
	Halogenated pesticides						Pesticides with halogens (Examples: DDT; DDE; Chlordane; Heptachlor; alpha-beta and delta BHC; Aldrin; Endosulfan, dieldrin, endrin)
	Radioactive Wastes						Wastes that emit more than background levels of radiation.
Other Contaminants	Conventional Contaminants, Organic						Unspecified organic matter that imposes an oxygen demand during its decomposition (Example: Total Organic Carbon)

CONTAMINANT GROUP	CONTAMINANT	SOIL	GROUNDWATER	SURFACE WATER	AIR	BEDROCK	DESCRIPTION
	Conventional Contaminants, Inorganic						Non-metallic inorganic substances or indicator parameters that may indicate the existence of contamination if present at unusual levels (Examples: Sulfides, ammonia)
	Asbestos						All forms of Asbestos. Asbestos fibers have been used in products such as building materials, friction products and heat-resistant materials.
	Other Deleterious Substances						Other contaminants or substances that cause subtle or unexpected harm to sediments (Examples: Wood debris; garbage (e.g., dumped in sediments))
	Benthic Failures						Failures of the benthic analysis standards from the Sediment Management Standards.
	Bioassay Failures						For sediments, a failure to meet bloassay criteria from the Sediment Management Standards. For soils, a failure to meet TEE bloassay criteria for plant, animal or soil blota toxicity.
	Unexploded Ordinance						Weapons that failed to detonate or discarded shells containing volatile material.
	Other Reactive Wastes						Other Reactive Wastes (Examples: phosphorous, lithium metal, sodium metal)
Reactive Wastes	Corrosive Wastes					2	Corrosive wastes are acidic or alkaline (basic) wastes that can readily corrode or dissolve materials they come into contact with. Wastes that are highly corrosive as defined by the Dangerous Waste Regulation (WAC 173-303-090(6)). (Examples: Hydrochloric acid; sulfuric acid; caustic soda)

Status choices for contaminants	
Contaminant Status	Definition
B - Below Cleanup Levels (Confirmed)	The contaminant was tested and found to be below cleanup levels. (Generally, we would not enter each and every contaminant that was tested; for example if an SVOC analysis was done we would not enter each SVOC with a status of "below". We would use this for contaminants that were believed likely to be present but were found to be below standards when tested
S - Suspected	The contaminant is suspected to be present; based on some knowledge about the history of the site, knowledge of regional contaminants, or based on other contaminants known to be present
C - Confirmed Above Cleanup Levels	The contaminant is confirmed to be present above any cleanup level. For example - above MTCA method A, B, or C; above Sediment Quality Standards; or above a presumed site-specific cleanup level (such as human health criteria for a sediment contaminant).
RA - Remediated - Above	The contaminant was remediated, but remains on site above the cleanup standards (for example - capped area).
RB - Remediated - Below	The contaminant was remediated, and no area of the site contains this contaminant above cleanup standards (for example - complete removal of contaminated soils).

Halogenated chemicals and solvents: Any chemical compound with chloro, bromo, iodo or fluoro is halogenated; those with eight or fewer carbons are generally solvents (e.g. halogenated methane, ethane, propane, butane, pentane, hexane, heptane or octane) and may also be used for or

Dibenzodioxins and dibenzofurans are normalized to a combined equivalent toxicity based on 2,3,7,8-tetrachloro-p-dibenzodioxin as set out in Ch. 173-340-708(8)(d) and in the Evaluating the Toxicity and Assessing the Carcinogenic Risk of Environmental Mixtures using Toxicity Equivalency Factors Focus Sheet (https://fortress.wa.gov/ecy/clarc/FocusSheets/tef.pdf). Results may be

FOR ECOLOGY USE ONLY (For Listin	ng Sites):
How did the Site come to be known:	☐ Site Discovery (received a report): (Date Report Received) ☐ ERTS Complaint ☐ Other (please explain):
Does an Early Notice Letter need to be s If No, please explain why:	
NAICS Code (if known): Otherwise, briefly explain how	property is/was used (i.e., gas station, dry cleaner, paint shop, vacant land, etc.):
Site Unit(s) to be created (Unit Type):	☐ Upland (includes VCP & LUST) ☐ Sediment
If multiple Units needed, please o	explain why:
Cleanup Process Type (for the Unit):	☐ No Process ☐ Independent Action ☐ Ecology-supervised or conducted
Site Status: Awaiting Cleanup Cleanup Started No Further Action Req	☐ Construction Complete – Performance Monitoring ☐ Cleanup Complete – Active O&M/Monitoring quired
Site Manager (Default: Southwest Region	on): Southwest Region
Specific confirmed contaminants include:	: Facility/Site ID No. (if known):
in Soil	를 통해 있는 경험 등록 기계를 가고 있는 것이다.
in Groundwater	홍현 1일 등 경우를 받고 있을 것을 받는 것이 되었다. 그 이 그리는 그는 그는 그를 보고 있는 것이 되었다. 경우 1일 등 1일
in Other (specify)	matrix:

COUNTY ASSESSOR INFO:

Please attach to this report a copy of the tax parcel/ownership information for each parcel associated with the site, as well as a parcel map illustrating the parcel boundary and location.