



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

February 10, 2016

TO: TCP File (Snohomish County Fire District 1 Damson)

FROM: Donna Musa
Ecology NWRO Initial Investigations Coordinator

SUBJECT: Initial Investigation: No Further Action (NFA) Determination
Snohomish County Fire District 1 Damson
20510 Damson Rd
Lynnwood, WA 98036
Parcel ID # 00373002800504
Facility Site ID: 52295357
Cleanup Site ID: 12979
UST ID: 290

Ecology has determined that no further action is necessary (at the Initial Investigation stage) due to independent remediation.

Ecology reviewed the following document:

- Memorandum: UST Closure and Remediation Report – Snohomish County Fire Station #22, 20510 Damson Road, Lynnwood, WA. Aspect Consulting, Seattle, WA. October 28, 2015.

The above document provides sufficient evidence that this cleanup was conducted to MTCA Method A cleanup levels for unrestricted land use.

Additional information about Ecology's review of this site cleanup may be accessed here: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=12979>.

To view the documentation Ecology has available electronically, on the right-hand side of the page, click on [View Electronic Documents](#).