




**LEGEND**

-  Limits of Excavation
-  Limits of Clay Membrane Panels and HDPE "Sheet Drain" for Vapor Dissipation
-  Contaminated Soil


**Earth Solutions NW LLC**  
 Technical Engineering, Construction Monitoring  
 and Environmental Sciences

Cross Section of West Excavation Sidewall  
 Potlatch Village  
 Kirkland, Washington

Drwn. GLS	Date 11/14/2014	Proj. No. 2880.07
Checked TWS	Date Nov. 2014	Plate 1




**Earth Solutions NW LLC**  
 Technical Engineering, Construction Monitoring  
 and Environmental Sciences

**Cross Section A of West Excavation Sidewall**  
**Potala Village**  
**Kirkland, Washington**

Drwn. GLS	Date 11/17/2014	Proj. No. 2880.07
Checked TWS	Date Nov. 2014	Plate 2