INITIAL INVESTIGATION FIELD REPORT Check this box if you have ERTS #(s): attached any documents to 063000004850 Parcel #(s): this form (using the County: Clallam paperclip icon on the left). 55168441 FSID #: DEPARTMENT OF ECOLOGY CSID #: UST #: 3425 SITE INFORMATION Site Name (Name over door): Site Address (including City, State and Zip); Phone Email 220 Tumwater Truck Route, Lots 15, 16, & 17 Former Pettit Oil Kardlock Port Angeles, WA 98362 Site Contact, Title, Business: Site Contact Address (including City, State and Zip): Phone (206) 292-2078 Tom Colligan 601 Union Street, Suite 600 Email Floyd | Snider Seattle, WA 98101 Site Owner, Title, Business: Site Owner Address (including City, State and Zip): Phone (360) 417-3424 Email Karen Goschen, Executive Director 338 W. First Street Port of Port Angeles Port Angeles, WA 98362 kareng@portofpa.com Site Owner Contact, Title, Business: Site Owner Contact Address (including City, State and Zip): Phone (360) 417-3452 Email Jesse Waknitz, Environmental Manager, 338 W. First Street Port of Port Angeles Port Angeles, WA 98362 jessew@portofpa.com Previous Site Owner(s): Additional Info (for any Site Information Item): Alternate Site Name(s): Bauman Olympic, Inc.; D&D Distributors Latitude (Decimal Degrees): Longitude (Decimal Degrees): -123.445737 Please check this box if there is relevant inspection information, such as data or INSPECTION INFORMATION photos, in an existing site report for this site. Date/Time: 7/28/2016 Inspection Conducted? Entry Notice: Announced X Unannounced Yes 🔯 No 🗌 Yes Photographs taken? No × Note: Attach photographs or upload to PIMS Samples collected? Yes I No × Note: Attach record with media, location, depth, etc. RECOMMENDATION LIST on Confirmed and Suspected No Further Action (Check appropriate box below): Contaminated Sites List: 図 Release or threatened release does not pose a threat No release or threatened release Refer to program/agency (Name: Independent Cleanup Action Completed (contamination removed) COMPLAINT (Brief Summary of ERTS Complaint): Site Discovery. Port of Port Angeles submitted a Floyd/Snider memorandum on June 3, 2016, Re: Former Pettit Oil Karklock/Shell Bulk Plant Property Soil And Groundwater Sampling, dated June 3. 2016. CURRENT SITE STATUS (Brief Summary of why Site is recommended for Listing or NFA): Port of Port Angeles conducted independent sampling on this parcel and submitted sampling results showing releases of gasoline- and diesel-range petroleum hydrocarbons in soil and groundwater.

Investigator: Connie Groven Date Submitted: 10/12/2016

DBSERVATIONS Please check this box if you included information on the Supplemental Page at end of report.
Description (If site visit made, please be sure to include the following: site observations, site features and cover, chronology of events, sources/past practices likely responsible for contamination, presence of water supply wells and other potential exposure pathways, etc.):
This site is currently used for parking. In 1999 five underground storage tanks (USTs) containing gas and diesel, and their associated fueling equipment were removed from the site. During the UST decommissioning, approximately 2,400 tons of petroleum contaminated soil (PCS) was removed from the site for disposal. Groundwater was encountered at 12 feet bgs.
Four borings were completed at the site. Soil sample results indicated remaining PCS at the northern property boundary and likely extending into the alleyway. This location is down gradient of the former USTs.
Soil samples from boring SB09 indicates remaining petroleum contaminated soil (PCS) from gasoline and diesel at a depth of 14 to 16 feet. A grab groundwater sample, collected from the same boring indicates levels of contaminants of concern above their respective MTCA Method A Cleanup Levels, including 1400 ug/L gasoline and 71,000 ug/L diesel.
Given the remaining contamination at the site, I recommend the site be listed on the Confirmed and Suspected Contaminated Sites List as a site awaiting additional cleanup.
,
·
Documents reviewed:
Floyd/Snider. 2016. Former Pettit Oil Kardlock/Shell Bulk Plant Property Soil And Groundwater Sampling Memo. June 3.

CONTAMINANT	GONTAMINANT	7108	MATER	FACE TER	A/P	OENT.	DESCRIPTION
GROUP		8	GROUNDWAT	SURI	A	SEDIMENT	
	Phenolic Compounds						Compounds containing phenols (Examples: phenol; 4-methylphenol; 2-methylphenol)
	Non-Halogenated Solvents						Organic solvents, typically volatile or semi-volatile, not containing any halogens. To determine if a product has halogens, search HSDB (http://toxnet.nlm.nih.gov/cgi-bin/sis/htmlgen?HSDB) and look at the Chemical/Physical Properties, and Molecular Formula. If there is not a Ci, I, Br, F in the formula, it's not halogenated. (Examples: acetone, benzene, toluene, xylenes, methyl ethyl ketone, ethyl acetate, methanol, ethanol, isopropranol, formic acid, acetic acid, stoddard solvent, Naptha). Use this when TEX contaminants are present independently of gasoline.
Non-	Polynuclear Aromatic Hydrocarbons (PAH)						Hydrocarbons composed of two or more benzene rings.
Halogenated Organics	TributyItin						The main active ingredients in blocides used to control a broad spectrum of organisms. Found in antifouling marine paint, antifungal action in textiles and industrial water systems. (Examples: Tributyltin; monobutyltin; dibutyltin)
	Methyl tertiary-butyl ether						MTBE is a volatile oxygen-containing organic compound that was formerly used as a gasoline additive to promote complete combustion and help reduce air pollution.
	Benzene	В	В				Benzene
	Other Non-Halogenated Organics	В	В				TEX
	Petroleum Diesel	С	С				Petroleum Diesel
	Petroleum Gasoline	С	С				Petroleum Gasoline
	Petroleum Other	В	S				Oil-range organics
	PBDE						Polybrominated di-phenyl ether
	Other Halogenated Organics						Other organic compounds with halogens (chlorine, fluorine, bromine, iodine). search HSDB (http://toxnet.nlm.nih.gov/cgi-bin/sis/htmlgen?HSDB) and look at the Chemical/Physical Properties, and Molecular Formula. If there is a CI, I, Br, F in the formula, it is halogenated. (Examples: Hexachlorobutadiene; hexachlorobenzene; pentachlorophenol)
Halogenated Organics (see	Halogenated solvents						PCE, chloroform, EDB, EDC, MTBE
notes at bottom)	Polychlorinated Biphenyls (PCB)						Any of a family of industrial compounds produced by chlorination of biphenyl, noted primarily as an environmental pollutant that accumulates in animal tissue with resultant pathogenic and teratogenic effects
	Dioxin/dibenzofuran compounds (see notes at bottom)						A family of more than 70 compounds of chlorinated dioxins or furans. (Examples: Dioxin; Furan; Dioxin TEQ; PCDD; PCDF; TCDD; TCDF; OCDD; OCDF). Do not use for 'dibenzofuran', which is a non-chlorinated compound that is detected using the semivolatile organics analysis 8270
Metals	Metals - Other						Cr, Se, Ag, Ba, Cd
	Lead						Lead
	Mercury						Mercury
	Arsenic	Talkala a karawa	and the second			- <u> </u>	Arsenic
Pesticides	Non-halogenated pesticides						Pesticides without halogens (Examples: parathion, malathion, diazinon, phosmet, carbaryl (sevin), fenoxycarb, aldicarb)
	Halogenated pesticides						Pesticides with halogens (Examples: DDT; DDE; Chlordane; Heptachlor; alpha-beta and delta BHC; Aldrin; Endosulfan, dieldrin, endrin)

٠. .

CONTAMINANT GROUP	CONTAMINANT	7/0S	GROUNDWATER SURFACE WATER	AR	SEDMONT	DESCRIPTION
Other Contaminants	Radioactive Wastes					Wastes that emit more than background levels of radiation.
	Conventional Contaminants, Organic					Unspecified organic matter that imposes an oxygen demand during its decomposition (Example: Total Organic Carbon)
	Conventional Contaminants, Inorganic					Non-metallic inorganic substances or indicator parameters that may indicate the existence of contamination if present at unusual levels (Examples: Sulfides, ammonia)
	Asbestos					All forms of Asbestos. Asbestos fibers have been used in products such as building materials, friction products and heat-resistant materials.
	Other Deleterious Substances					Other contaminants or substances that cause subtle or unexpected harm to sediments (Examples: Wood debris; garbage (e.g., dumped in sediments))
	Benthic Failures					Failures of the benthic analysis standards from the Sediment Management Standards.
	Bioassay Failures					For sediments, a failure to meet bioassay criteria from the Sediment Management Standards. For soils, a failure to meet TEE bioassay criteria for plant, animal or soil biota toxicity.
Reactive Wastes	Unexploded Ordinance					Weapons that failed to detonate or discarded shells containing volatile material.
	Other Reactive Wastes					Other Reactive Wastes (Examples: phosphorous, lithium metal, sodium metal)
	Corrosive Wastes					Corrosive wastes are acidic or alkaline (basic) wastes that can readily corrode or dissolve materials they come into contact with. Wastes that are highly corrosive as defined by the Dangerous Waste Regulation (WAC 173-303-090(6)). (Examples: Hydrochloric acid; sulfuric acid; caustic soda)

(fill in contaminant matrix below with appropriate status choice from the key below the table)

Status choices for contaminants	
Contaminant Status	Definition
B— Below Cleanup Levels (Confirmed)	The contaminant was tested and found to be below cleanup levels. (Generally, we would not enter each and every contaminant that was tested; for example if an SVOC analysis was done we would not enter each SVOC with a status of "below". We would use this for contaminants that were believed likely to be present but were found to be below standards when tested
S— Suspected	The contaminant is suspected to be present; based on some knowledge about the history of the site, knowledge of regional contaminants, or based on other contaminants known to be present
C— Confirmed Above Cleanup Levels	The contaminant is confirmed to be present above any cleanup level. For example—above MTCA method A, B, or C; above Sediment Quality Standards; or above a presumed site-specific cleanup level (such as human health criteria for a sediment contaminant).
RA— Remediated - Above	The contaminant was remediated, but remains on site above the cleanup standards (for example—capped area).
RB— Remediated - Below	The contaminant was remediated, and no area of the site contains this contaminant above cleanup standards (for example— complete removal of contaminated soils).

Halogenated chemicals and solvents: Any chemical compound with chloro, bromo, iodo or fluoro is halogenated; those with eight or fewer carbons are generally solvents (e.g. halogenated methane, ethane, propane, butane, pentane, hexane, heptane or octane) and may also be used for or registered as pesticides or fumigants. Most are dangerous wastes, either listed or categorical. Organic compounds with more carbons are almost always halogenated pesticides or a contaminant or derivative. Referral to the HSDB is recommended if you are unfamiliar with a chemical name or compound, as it contains useful information about synonyms, uses, trade names, waste codes, and other regulatory information about most toxic or potentially toxic chemicals.

Dibenzodioxins and dibenzofurans are normalized to a combined equivalent toxicity based on 2,3,7,8-tetrachloro-p-dibenzodioxin as set out in WAC 173-340-708(8)(d) and in the Evaluating the Toxicity and Assessing the Carcinogenic Risk of Environmental Mixtures using Toxicity Equivalency Factors Focus Sheet (https://fortress.wa.gov/ecy/clarc/FocusSheets/tef.pdf). Results may be reported as individual compounds and isomers (usually lab results), or as a toxic equivalency value (reports).

FOR ECOLOGY II REVIEWER USE ON	LY (For Listing Sites):				
How did the Site come to be known:	☑ Site Discovery (received a report): 7/13/2016 (Date Report Received) ☐ ERTS Complaint ☐ Other (please explain):				
Does an Early Notice Letter need to If No, please explain why:	oe sent: ⊠ Yes □ No				
NAICS Code (if known): Otherwise, briefly explain how prope Former Kardlock Station, Currently used for	erty is/was used (i.e., gas station, dry cleaner, paint shop, vacant land, etc.):				
Site Unit(s) to be created (Unit Type): If multiple Units needed, please explai					
Cleanup Process Type (for the Unit):	☐ No Process ☐ Independent Action ☐ Voluntary Cleanup Program ☐ Ecology-supervised or conducted ☐ Federal-supervised or conducted				
Site Status: ☑ Awaiting Cleanup ☐ Cleanup Started ☐ No Further Action Rec	☐ Construction Complete – Performance Monitoring ☐ Cleanup Complete – Active O&M/Monitoring uired				
Site Manager (Default:); (Connie Groven				
Specific confirmed contaminants inclu	rde: Facility/Site ID No. (if known):				
Gasoline and <u>dlesel</u> in Soil	Cleanup Site ID No. (if known):				
Gasoline and diesel in Groundwater	경영화 경영화 경영화 경영화 시간 등 경영화 시간 등 경영화 경영화 경영화 경영화 기간 등 기간				
in Other (specify i	terre in the second of the sec				

COUNTY ASSESSOR INFO: Please attach to this report a copy of the tax parcel/ownership information for each parcel associated with the site, as well as a parcel map illustrating the parcel boundary and location.

Additional or Supplemental Information from Observations Page