


EXPLANATION

- RA10-1 Remediation Area and Number
- MW-106S Soil Sample Location Where Cleanup level Exceeded



Weyerhaeuser East Site
 Everett, Washington
**EAST SITE
 LOCATION OF CLEANUP LEVEL
 EXCEEDANCES**