## ERTS # 662453

Initial Rep	oort			External	Reference #	#			
Caller Informa	ation			Where did it happe	<u>en</u>				
	First	Last		Berth			Anchorage		
Name	Jerry	Jackson		Location Name	American	Linen Tacoi	ma		
Busines Name	J2Environment			Street Address	2011 Sout	h Tacoma V	Nay		
Street Address				Other Address					
Other Address				City/Place	TACOMA		State WA	Zip 98	3409
City E-mail		State WA	Zip Confidential_FL	County - Region WIRA #			SWRO	FS ID	14562825
Phon	ne Ext	Туре		Waterway			Ту	pe	
	) 342-4848	Busines	29	Latitude		47.2325	Longitude		122.46392
(000)	042 4040	Busines	55	Topo Quad 1:24:000	ТАСОМА				
What happen	ed	Spills Pro	ogram Oil Spill? N	Direction/Landmark (n	nile post, cro	oss roads, t	ownship/range	e)	
Incident Date	1/26/2016 Re	eceived Date	12/28/2015 12:00						
Medium	SOIL								
Material PETROLEUM - OIL OTHER				Primary Potentially Responsible Party Information					
	Quantity	Unit		First		Last			
				Name					
Source		STORAGE TA	NK	Business Name Alsc	0				
				Street Address 505	East South1	Femple			
Cause	LEAKING UNDE	RGROUND STC	ORAGE TANK	Other Address					
Activity	STORING			City Salt	Lake City	:	State UT	Zip 84	102
· · · · · · · · · · · · · · · · · · ·	SOIL CONTAMIN	NATION		Phone (801	) 328-8831	Ext	Тур	be Busin	ess
Vessel Name				E-mail					
Hull Num	ıber								
Additional Co	ntact Informatio	<u>on</u>							
Name		Phone	Ext	Туре					
More Informa		on found at the a	itas Contomination is	from potroloum	aliouad the	ro oro throa	tonko on oito	000	1
				from petroleum. It is to bil ) and a third unknown		ne are three	; latiks on site.	Une	
Reports are b	eing sent to Ecolog	уу							
UST id 7054									
			Entry Pe	erson BROOKS, NANN	IETTE		Entry Dat	e 1/26/2	2016

#### **Department of Ecology - Environmental Report Tracking System**

## ERTS # 662453

# Referral

				Referral #	204421
Referral Method	Person Referred to	Willoughby, Mark		Primary	
C E-mail ERTS number	Phone	(360) 407-6179	Fax		
<ul> <li>E-mail ettachment</li> </ul>	E-mail	marw461@ecy.wa.gov			
	Program/Organization	TOXICS CLEANUP			
O Print	Address				
<ul> <li>Telephone</li> </ul>	City	Bellevue	WA		
	Region/Location	SWRO			
	Referral Date	1/26/2016			

### ERTS # 662453

# Followup

Inspector Information	Where did it happen	Followup #1				
Referral # 204421	Berth Anchorage					
Lead Inspector Willoughby, Mark	Location Name American Linen Tacoma					
Program/Organization TOXICS CLEANUP	Street Address 2011 South Tacoma Way					
* Region/Location SWRO	Other Address	7. 00.100				
# of Ecology Staff Overtime	City/Place TACOMA State WA	Zip 98409-				
Action Start Date	End Date County PIERCE Region SWRO	FS ID 14562825				
REFERRAL 1/26/2016	2/8/2016 WRIA #					
What happened Spills Program Oil Spill?	N Latitude 47.2325 Longitude	122.46392				
Incident Date 1/26/2016	Topo Quad 1:24,000 TACOMA					
Medium SOIL	Direction/Landmark (mile post, cross roads, towr	ship/range)				
Material						
PETROLEUM - OIL OTHER						
Quantity Unit Est.	Detentially Deep south to Desta lafe south					
Potentially Responsible Party Information						
Source Regulated?	Check if the primary PRP provided noti					
Source Regulated?	Primary 🗹 First I Name	_ast				
Cause	Business Name Alsco					
LEAKING UNDERGROUND STORAGE TANK	Street Address 505 East SouthTemple					
	Other Address					
	City Salt Lake City State UT	Zip 84102-				
Activity	Phone (801) 328-8831 Ext Ty	pe Business				
STORING	E-mail					
Impact						
SOIL CONTAMINATION						
Vessel						
Narrative						
	nt from J2 Environmental LLC. The assessment was done to	investigate three				
	cleaners. Soil and ground water samples were taken. No					
Phase II Limited and Targeted Subsurface Investigation c levels for TPH DRO & Heavy oil.	conduted by Aerotech on 10/28/15 show three soil samples	exceeding MTCA				
J2 Environmental will conduct additional soil and groundwa	ater samping. Referred site to site manager.					
	-					
Vessel Emergency	Entry Person: Willoughby, Mark En	ntry Date 2/8/2016				